

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2346
SCHOOL NAME: McKay School
ADDRESS OF SCHOOL: 6901 S. Fairfield
CITY: Chicago, IL, 60629

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/11/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 732
IDPH INSPECTOR LICENSE NUMBER: 100-09106
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier
IDPH MP LICENSE NUMBER: 100-00440
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

McKay School

6901 S. Fairfield
Chicago, IL, 60629

Unit: 24451
Building ID: 4760

IDPH ID Number: 14-016-2990-2346

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 13, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24451 Region: 05 IDPH ID:14-016-2990-2346

School: McKay School Building ID: 4760

Address: 6901 S. Fairfield
Chicago, IL, 60629

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/05/2019

Inspector: Michael Hasier Inspector IDPH License: 100-09106
Management Planner: Shawn Brown Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Shawn Brown
100-00440

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 13, 2019

RE: McKay School, Unit 24451
6901 S. Fairfield
Chicago, IL, 60629

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at McKay School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at McKay School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: McKay School
Address: 6901 S. Fairfield
IDPH ID: 14-016-2990-2346
Contact:

Unit: 24451
Chicago, IL, 60629
Building ID: 4760
Phone:

Region: 05

2. Description of Facility

Original Construction: 1950
Total Square Footage: 78300
Current Occupancy: 732

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:
Date: 8/13/2019

6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:
Date: 09/05/2019

7. Review Date:09/05/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the McKay School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4760:

B. The following new homogenous areas have been identified for Building 4760:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Tan Floor Tile
03	9 X 9 White Vinyl Floor Tile-NOT OBSERVED
04	9x9 Beige Floor Tile-NOT OBSERVED
06A	12x12 Off-White w/Gray Specks Vinyl Floor Tile Mastic
13B	9x9 Beige Floor Tile Mastic-VFT NOT OBSERVED
14A	Mastic under 12 X 12 Beige/White Tile
17	12x12 Beige/White Floor Tile
18	Black Baseboard
19	Black Baseboard Mastic
20	12x12 Grey Floor Tile-NOT OBSERVED
22	Carpet Mastic
23	Drywall
24	Drywall Compound
25	Plaster
26	2x4 Acoustical Ceiling Tile
27A	Sheet Flooring
27B	Sheet Flooring Mastic
28	12X12 Tan/White Marble Floor Tile
28M	12x12 Tan/White Marble Floor Tile Mastic
29	9x9 Tan w/Black Streaks Floor Tile
29M	9x9 Tan w/Black Streaks Floor Tile Mastic
30	9x20 Black Edge Tile
30M	9"x20" Black Edge Tile Mastic
31	9 X 9 Off-White Floor Tile
31M	9" x 9" Off-White Floor Tile Mastic
32	9x9 Gray/Tan Floor Tile
32M	9"x9" Gray/Tan Floor Tile Mastic
6	12x12 Off-White w/Gray Specks Vinyl Floor Tile
K	Boiler Gaskets
L	Foil Wrap on Duct Work
M	Fiberglass Pipe Insulation Wrap
N	Fiberglass Pipe Insulation Joints
O	Cementious Pipe Fittings

The following areas were deemed to be inaccessible:

05	9x9 Dark Brown w/White Specks Vinyl Floor Tile
06A	12x12 Off-White w/Gray Specks Vinyl Floor Tile

	Mastic
13A	9x9 White Vinyl Floor Tile Mastic-VFT NOT OBSERVED
13C	9x9 Dark Brown w/White Specks Floor Tile Mastic
14A	Mastic under 12 X 12 Beige/White Tile
14B	12x12 Tan Floor Tile Mastic
19	Black Baseboard Mastic
21	Orange Linoleum Mastic
22	Carpet Mastic
26	2x4 Acoustical Ceiling Tile
27B	Sheet Flooring Mastic
28M	12x12 Tan/White Marble Floor Tile Mastic
29M	9x9 Tan w/Black Streaks Floor Tile Mastic
30M	9"x20" Black Edge Tile Mastic
31M	9" x 9" Off-White Floor Tile Mastic
32M	9"x9" Gray/Tan Floor Tile Mastic
C	Boiler Breeching

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The McKay School Building 4760 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School McKay School Unit 24451 Building ID 4760

Address 6901 S. Fairfield Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	9X9 Black Floor Tile ABATED			2nd & 3rd Floor Corridors	ABATED	MISC								
01B	9x9 Red Floor Tile ABATED			2nd & 3rd Floor Corridors	ABATED	MISC								
02	12x12 Tan Floor Tile	3,730	SF	1st Floor Corridor, Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	9 X 9 White Vinyl Floor Tile-NOT OBSERVED			Rooms 103 & 105	ASSUMED	MISC		None						Low
04	9x9 Beige Floor Tile-NOT OBSERVED			Office (Under Carpet)	ASSUMED	MISC								
05	9x9 Dark Brown w/White Specks Vinyl Floor Tile	250	SF	Engineer's Office	CHR	MISC	N	LOC	10		No	ACBM with the potential for damage	3	LOW
06A	12x12 Off-White w/Gray Specks Vinyl Floor Tile Mastic	8,000	SF	2nd & 3rd Floor Corridors & Rooms 103, 203, 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Orange Linoleum	2,100	SF	Rooms 202, 203, 209, 211, 102, 110 (Old 1st Floor Lounge)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13A	9x9 White Vinyl Floor Tile Mastic-VFT NOT OBSERVED	625	SF	Rooms 103 & 105	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13B	9x9 Beige Floor Tile Mastic-VFT NOT OBSERVED			Office (Under Carpet)	ASSUMED	MISC								
13C	9x9 Dark Brown w/White Specks Floor Tile Mastic	250	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	Mastic under 12 X 12 Beige/White Tile	1,500	SF	Rooms 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	12x12 Tan Floor Tile Mastic	3,730	SF	1st Floor Corridor and Room 108	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14C	12x12 Gray Floor Tile Mastic-NOT OBSERVED			Room 101	CHR	MISC								
17	12x12 Beige/White Floor Tile	1,500	SF	Room 209 and 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Black Baseboard	400	LF	Rooms 202, 203, 209, & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Black Baseboard Mastic	400	LF	Rooms 202, 203, 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12x12 Grey Floor Tile-NOT OBSERVED			Room 101	ASSUMED	MISC								
21	Orange Linoleum Mastic	1,020	SF	Room 100 & 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Carpet Mastic	250	SF	School Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Drywall	1,200	SF	Rooms 103 & 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School McKay School Unit 24451 Building ID 4760

Address 6901 S. Fairfield Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
24	Drywall Compound	1,200	SF	Rooms 103 & 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Plaster	4,800	SF	Auditorium	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2x4 Acoustical Ceiling Tile	17,000	SF	All Rooms (Except 202), Corridors, Auditorium, Bathrooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
27A	Sheet Flooring	1,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27B	Sheet Flooring Mastic	1,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12X12 Tan/White Marble Floor Tile	1,395	SF	Rooms 105, 111 & 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28M	12x12 Tan/White Marble Floor Tile Mastic	1,375	SF	Rooms 105, 111 & 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	9x9 Tan w/Black Streaks Floor Tile	100	SF	Room 111 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29M	9x9 Tan w/Black Streaks Floor Tile Mastic	100	SF	Room 111 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	9x20 Black Edge Tile	10	SF	Room 111 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	9"x20" Black Edge Tile Mastic	10	SF	Room 111 Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	9 X 9 Off-White Floor Tile	625	SF	Room 105	ASSUMED	MISC	N	LOC	33		No	ACBM with the potential for damage	5	LOW
31M	9" x 9" Off-White Floor Tile Mastic	625	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	9x9 Gray/Tan Floor Tile	20	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32M	9"x9" Gray/Tan Floor Tile Mastic	20	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	12x12 Off-White w/Gray Specks Vinyl Floor Tile	8,000	SF	2nd & 3rd Floor Corridors, and Rooms 103, 203, 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	200	LF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cardboard Pipe Insulation	300	LF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Boiler Breeching	200	SF	Boiler Room	CHR	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School McKay School Unit 24451 Building ID 4760

Address 6901 S. Fairfield Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
E	Cardboard Pipe Joints-NOT OBSERVED			Boiler Room	CHR	TSI								
H	Aircell Pipe Joints-NOT OBSERVED			Boiler Room	CHR	TSI								
K	Boiler Gaskets	25	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Foil Wrap on Duct Work	840	LF	Boiler Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Fiberglass Pipe Insulation Wrap	60	LF	Fan Room 1 & 2	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
N	Fiberglass Pipe Insulation Joints	50	LF	Fan Room 1 & 2	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Cementious Pipe Fittings	50	LF	Boiler Room- Boiler Header & Return	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Fittings on Fiberglass Pipe Runs	45	SF	Unexcavated Tunnel	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School McKay School Unit 24451 Building ID 4760

Address 6901 S. Fairfield Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/13/2019
Inspector Name Michael Hasier
100-09106 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	
01B	
02	
03	Not Observed Multiple Years
04	Not Observed Multiple Years
05	Damage located in Engineer's Office
06A	
08	
13A	VFT Not Observed Multiple Years
13B	VFT Not Observed Multiple Years
13C	
14A	
14B	
14C	Not Observed Multiple Years
17	
18	
19	
20	Not Observed Multiple Years
21	
22	
23	
24	
25	

Chicago Public Schools

School McKay School Unit 24451 Building ID 4760

Address 6901 S. Fairfield Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
26	
27A	
27B	
28	
28M	
29	
29M	
30	
30M	
31	33 SF of Damage located in Room 105
31M	
32	
32M	
6	
A	
B	
C	
E	Not Observed Multiple Years
H	Not Observed Multiple Years
K	
L	
M	
N	
O	
P	

Chicago Public Schools

School McKay School **Unit** 24451 **Building ID** 4760

Address 6901 S. Fairfield **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School McKay School
Address 6901 S. Fairfield

Unit 24451
Chicago, IL, 60629

Building ID 4760
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	9X9 Black Floor Tile ABATED			2nd & 3rd Floor Corridors	Abated	MISC					
01B	9x9 Red Floor Tile ABATED			2nd & 3rd Floor Corridors	Abated	MISC					
02	12x12 Tan Floor Tile	3,730	SF	1st Floor Corridor, Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	9 X 9 White Vinyl Floor Tile-NOT OBSERVED			Rooms 103 & 105	Assumed	MISC					
04	9x9 Beige Floor Tile-NOT OBSERVED			Office (Under Carpet)	Assumed	MISC					
05	9x9 Dark Brown w/White Specks Vinyl Floor Tile	250	SF	Engineer's Office	Chrysotile	MISC	No	10	SF	6 ACBM with the potential for damage	Remove
06A	12x12 Off-White w/Gray Specks Vinyl Floor Tile Mastic	8,000	SF	2nd & 3rd Floor Corridors & Rooms 103, 203, 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Orange Linoleum	2,100	SF	Rooms 202, 203, 209, 211, 102, 110 (Old 1st Floor Lounge)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	9x9 White Vinyl Floor Tile Mastic-VFT NOT OBSERVED	625	SF	Rooms 103 & 105	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13B	9x9 Beige Floor Tile Mastic-VFT NOT OBSERVED			Office (Under Carpet)	Assumed	MISC					
13C	9x9 Dark Brown w/White Specks Floor Tile Mastic	250	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	Mastic under 12 X 12 Beige/White Tile	1,500	SF	Rooms 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	12x12 Tan Floor Tile Mastic	3,730	SF	1st Floor Corridor and Room 108	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14C	12x12 Gray Floor Tile Mastic-NOT OBSERVED			Room 101	Chrysotile	MISC					
17	12x12 Beige/White Floor Tile	1,500	SF	Room 209 and 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Black Baseboard	400	LF	Rooms 202, 203, 209, & 211	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Black Baseboard Mastic	400	LF	Rooms 202, 203, 209 & 211	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 Grey Floor Tile-NOT OBSERVED			Room 101	Assumed	MISC					
21	Orange Linoleum Mastic	1,020	SF	Room 100 & 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Carpet Mastic	250	SF	School Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Drywall	1,200	SF	Rooms 103 & 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Drywall Compound	1,200	SF	Rooms 103 & 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Plaster	4,800	SF	Auditorium	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2x4 Acoustical Ceiling Tile	17,000	SF	All Rooms (Except 202), Corridors, Auditorium, Bathrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27A	Sheet Flooring	1,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27B	Sheet Flooring Mastic	1,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12X12 Tan/White Marble Floor Tile	1,395	SF	Rooms 105, 111 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	12x12 Tan/White Marble Floor Tile Mastic	1,375	SF	Rooms 105, 111 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9x9 Tan w/Black Streaks Floor Tile	100	SF	Room 111 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School McKay School
Address 6901 S. Fairfield

Unit 24451
Chicago, IL, 60629

Building ID 4760
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29M	9x9 Tan w/Black Streaks Floor Tile Mastic	100	SF	Room 111 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	9x20 Black Edge Tile	10	SF	Room 111 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	9"x20" Black Edge Tile Mastic	10	SF	Room 111 Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	9 X 9 Off-White Floor Tile	625	SF	Room 105	Assumed	MISC	No	33	SF	6 ACBM with the potential for damage	Remove
31M	9" x 9" Off-White Floor Tile Mastic	625	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	9x9 Gray/Tan Floor Tile	20	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32M	9"x9" Gray/Tan Floor Tile Mastic	20	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12x12 Off-White w/Gray Specks Vinyl Floor Tile	8,000	SF	2nd & 3rd Floor Corridors, and Rooms 103, 203, 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	200	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Insulation	300	LF	Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Boiler Breeching	200	SF	Boiler Room	Chrysotile	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Joints-NOT OBSERVED			Boiler Room	Chrysotile	TSI					
H	Aircell Pipe Joints-NOT OBSERVED			Boiler Room	Chrysotile	TSI					
K	Boiler Gaskets	25	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Foil Wrap on Duct Work	840	LF	Boiler Room	Assumed	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Fiberglass Pipe Insulation Wrap	60	LF	Fan Room 1 & 2	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Fiberglass Pipe Insulation Joints	50	LF	Fan Room 1 & 2	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Cementious Pipe Fittings	50	LF	Boiler Room- Boiler Header & Return	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Fittings on Fiberglass Pipe Runs	45	SF	Unexcavated Tunnel	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School McKay School
Address 6901 S. Fairfield

Unit 24451
 Chicago, IL, 60629

Building ID 4760
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
 174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/05/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	
01B	
02	
03	
04	
05	
06A	
08	
13A	
13B	

Chicago Public Schools

School McKay School
Address 6901 S. Fairfield

Unit 24451
Chicago, IL, 60629

Building ID 4760
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13C	
14A	
14B	
14C	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27A	
27B	
28	
28M	
29	
29M	
30	
30M	
31	
31M	
32	
32M	

Chicago Public Schools

School McKay School
Address 6901 S. Fairfield

Unit 24451
Chicago, IL, 60629

Building ID 4760
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
6	
A	
B	
C	
E	
H	
K	
L	
M	
N	
O	
P	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9X9 Black Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9X9 Black Floor Tile ABATED**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Red Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Red Floor Tile ABATED**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor, Room 108**
MATERIAL QUANTITY: **3730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**
MATERIAL LOCATION: **1st Floor Corridor, Room 108**
MATERIAL QUANTITY: **3730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9 X 9 White Vinyl Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 103 & 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____

Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **9 X 9 White Vinyl Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Rooms 103 & 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office (Under Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9x9 Beige Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Office (Under Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/White Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in Engineer's Office**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/White Specks Vinyl Floor Tile**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray Specks Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors & Rooms 103, 203, 209 & 211**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray Specks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors & Rooms 103, 203, 209 & 211**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Orange Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 202, 203, 209, 211, 102, 110 (Old 1st Floor Lounge)**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Orange Linoleum**
MATERIAL LOCATION: **Rooms 202, 203, 209, 211, 102, 110 (Old 1st Floor Lounge)**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9x9 White Vinyl Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9x9 White Vinyl Floor Tile Mastic-VFT NOT OBSERVED**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **9x9 Beige Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office (Under Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **13B**

MATERIAL DESCRIPTION: **9x9 Beige Floor Tile Mastic-VFT NOT OBSERVED**

MATERIAL LOCATION: **Office (Under Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Mastic under 12 X 12 Beige/White Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 209 & 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Mastic under 12 X 12 Beige/White Tile**
MATERIAL LOCATION: **Rooms 209 & 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Corridor and Room 108**
MATERIAL QUANTITY: **3730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Corridor and Room 108**
MATERIAL QUANTITY: **3730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14C**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **14C**

MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic-NOT OBSERVED**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Beige/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 209 and 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Beige/White Floor Tile**
MATERIAL LOCATION: **Room 209 and 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 202, 203, 209, & 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Rooms 202, 203, 209, & 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 202, 203, 209 & 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Rooms 202, 203, 209 & 211**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12x12 Grey Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Orange Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100 & 202**
MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Orange Linoleum Mastic**
MATERIAL LOCATION: **Room 100 & 202**
MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **School Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **School Office**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Rooms 103 & 105**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2x4 Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Rooms (Except 202), Corridors, Auditorium, Bathrooms**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2x4 Acoustical Ceiling Tile**
MATERIAL LOCATION: **All Rooms (Except 202), Corridors, Auditorium, Bathrooms**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **Sheet Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **Sheet Flooring**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27B**
MATERIAL DESCRIPTION: **Sheet Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **27B**
MATERIAL DESCRIPTION: **Sheet Flooring Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12X12 Tan/White Marble Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 111 & 113**
MATERIAL QUANTITY: **1395** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12X12 Tan/White Marble Floor Tile**
MATERIAL LOCATION: **Rooms 105, 111 & 113**
MATERIAL QUANTITY: **1395** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12x12 Tan/White Marble Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 111 & 113**
MATERIAL QUANTITY: **1375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12x12 Tan/White Marble Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105, 111 & 113**
MATERIAL QUANTITY: **1375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29M**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **29M**
MATERIAL DESCRIPTION: **9x9 Tan w/Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9x20 Black Edge Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **9x20 Black Edge Tile**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **9"x20" Black Edge Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **30M**
MATERIAL DESCRIPTION: **9"x20" Black Edge Tile Mastic**
MATERIAL LOCATION: **Room 111 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9 X 9 Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **33** DAMAGE UNITS: **SF**
COMMENTS: **33 SF of Damage located in Room 105**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **9 X 9 Off-White Floor Tile**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **33** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31M**
MATERIAL DESCRIPTION: **9" x 9" Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **31M**
MATERIAL DESCRIPTION: **9" x 9" Off-White Floor Tile Mastic**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9x9 Gray/Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **9x9 Gray/Tan Floor Tile**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32M**
MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **32M**
MATERIAL DESCRIPTION: **9"x9" Gray/Tan Floor Tile Mastic**
MATERIAL LOCATION: **Room 105**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray Specks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, and Rooms 103, 203, 209 & 211**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12x12 Off-White w/Gray Specks Vinyl Floor Tile**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, and Rooms 103, 203, 209 & 211**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Cardboard Pipe Joints-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____

Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Joints-NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell Pipe Joints-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Pipe Joints-NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUILDING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Foil Wrap on Duct Work**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Foil Wrap on Duct Work**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Wrap**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room 1 & 2**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Wrap**
MATERIAL LOCATION: **Fan Room 1 & 2**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room 1 & 2**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/13/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation Joints**
MATERIAL LOCATION: **Fan Room 1 & 2**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Cementious Pipe Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room- Boiler Header & Return**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Cementious Pipe Fittings**
MATERIAL LOCATION: **Boiler Room- Boiler Header & Return**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**
SCHOOL NAME: **McKay School** INSPECTION DATE: **8/13/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Unexcavated Tunnel**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/13/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24451** BUIDLING ID: **4760**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **McKay School** REVIEW DATE: **9/5/2019**
ADDRESS: **6901 S. Fairfield** IDPH LICENSE NO: **100-09106**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Runs**
MATERIAL LOCATION: **Unexcavated Tunnel**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B


Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019
Course Dates:
05/01/2020
Expires:
1905BIR02
Certificate Number:



Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	3/1/2020
INSPECTOR	5/1/2020

ID NUMBER	ISSUED	EXPIRES
100 - 09106	5/8/2019	05/15/2020

MICHAEL S HASIER
444 OLD BARN RD., APT. B
BARRINGTON, IL 60010

Environmental Health



PROJECT MANAGER 3/1/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
371 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081

Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health



Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 02950		ISSUED 3/6/2019	EXPIRES 05/15/2020
KEITH CLOUGH 524 HOMELAND RD MATTESON, IL 60443		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	4/9/2019
Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed