

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-5680  
SCHOOL NAME: Hanson Park Branch @ St. Stanislaus  
ADDRESS OF SCHOOL: 2318 North Lorel Avenue  
CITY: Chicago, IL, 60639

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/9/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1409  
IDPH INSPECTOR LICENSE NUMBER: 100-18350  
IDPH LICENSED INSPECTOR NAME(Please Print): Joseph Hennigan  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Hanson Park Branch @ St. Stanislaus**

2318 North Lorel Avenue  
Chicago, IL, 60639

Unit: 24461  
Building ID: 4770stans

IDPH ID Number: 14-016-2990-5680

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 4, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 24461            Region: 02            IDPH ID:14-016-2990-5680

School: Hanson Park Branch @ St. Stanislaus            Building ID: 4770stans

Address: 2318 North Lorel Avenue

Chicago, IL, 60639

Building Contact: Pena, Jeremy

Contact Phone:312 545 9563

Current Building Owners: Chicago Public Schools

Review Date: 10/23/2019

Inspector: Joseph Hennigan

Inspector IDPH License: 100-18350

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 04, 2019

RE: Hanson Park Branch @ St. Stanislaus, Unit 24461  
2318 North Lorel Avenue  
Chicago, IL, 60639

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Hanson Park Branch @ St. Stanislaus, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hanson Park Branch @ St. Stanislaus, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Hanson Park Branch @ St. Stanislaus Unit: 24461 Region: 02  
Address: 2318 North Lorel Avenue Chicago, IL, 60639  
IDPH ID: 14-016-2990-5680 Building ID: 4770stans  
Contact: Pena, Jeremy Phone: 312 545 9563

### 2. Description of Facility

Original Construction: 0 Additional Construction:  
Total Square Footage: 32476 No of Floors: 2  
Current Occupancy: 1409

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Joseph Hennigan

Inspector IDPH license # 100-18350  
Signature:  
Date: 10/4/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342  
Signature:  
Date: 10/23/2019

### 7. Review Date:10/23/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hanson Park Branch @ St. Stanislaus. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4770stans:

05

Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 4770stans:

- 29                      12" x 12" Tan with Dark Brown Streaks VFT
- 29M                    12" x 12" Tan with Dark Brown Streaks VFT Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|     |   |
|-----|---|
| 01  | Tank Insulation   |
| 02  | MJP on Fiberglass Pipe Runs                               |
| 03  | Paperwrap Pipe Insulation                                 |
| 04  | MJP on Paperwrap Pipe Insulation                          |
| 05  | Aircell Pipe Insulation                                   |
| 06  | MJP on Aircell Pipe Runs                                  |
| 07  | Boiler Breeching  |
| 08  | 9"x9" Maroon Floor Tile                                   |
| 08A | 9"x9" Maroon Floor Tile Mastic                            |
| 09  | 9"x9" Brown Floor Tile                                    |
| 09A | 9"x9" Brown Floor Tile Mastic                             |
| 10  | Black Border Floor Tile                                   |
| 10A | Black Border Floor Tile Mastic                            |
| 11  | 9"x9" Green Floor Tile                                    |
| 11A | 9"x9" Green Floor Tile Mastic                             |
| 12  | 12"x12" Beige Streaked Floor Tile                         |
| 12A | 12"x12" Beige Streaked Floor Tile Mastic                  |
| 13  | 9"x9" White Floor Tile                                    |
| 13A | 1'x1' White Grooved Ceiling Tile                          |
| 15  | Light Brown Floor Tile                                    |
| 15A | Light Brown Floor Tile Mastic                             |
| 16  | 12"x12" White Floor Tile                                  |
| 16A | 12"x12" White Floor Tile Mastic                           |
| 17  | 12"x12" Tan With Brown Streaks Floor Tile                 |
| 17A | 12"x12" Tan With Brown Streaks Floor Tile Mastic          |
| 18  | 12"x12" Black w/ White Specks Floor Tile                  |
| 18A | 12"x12" Black w/ White Specks Floor Tile Mastic           |
| 19  | 12"x12" Purple Streaked Floor Tile                        |
| 19A | 12"x12" Purple Streaked Floor Tile Mastic                 |
| 20  | Hard Coat Plaster   |
| 21  | 1'x1' White Smooth Ceiling Tile                           |
| 22  | Terrazzo floor beige & multi-color specks                 |
| 23  | Linoleum white with gray specks                           |
| 24  | Linoleum white with gray specks MASTIC                    |
| 25  | 12"x12" Dark Brown with light brown streaks VFT           |
| 26  | 12"x12" Dark Brown with light brown streaks VFT<br>MASTIC |
| 27  | 9"x9" Black w/white streaks VFT                           |
| 28  | 9"x9" Black w/white streaks VFT MASTIC                    |
| 29  | 12" x 12" Tan with Dark Brown Streaks VFT                 |
| 29M | 12" x 12" Tan with Dark Brown Streaks VFT Mastic          |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joseph Hennigan, IDPH License # 100-18350. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Hanson Park Branch @ St. Stanislaus Building 4770stans Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus Unit 24461 Building ID 4770stans

Address 2318 North Lorel Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description             | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category   | Damage Reason | Disturbance Potential |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| 01    | Tank Insulation                  | 150               | LF             | Boiler Room + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | Any remaining friable ACBM or friable suspect ACBM                      |               | LOW                   |
| 02    | MJP on Fiberglass Pipe Runs      | 100               | FITTING        | Boiler Room + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | Any remaining friable ACBM or friable suspect ACBM                      |               | LOW                   |
| 03    | Paperwrap Pipe Insulation        | 500               | LF             | Boiler Room + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | Any remaining friable ACBM or friable suspect ACBM                      |               | LOW                   |
| 04    | MJP on Paperwrap Pipe Insulation | 50                | FITTING        | Boiler Room + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 05    | Aircell Pipe Insulation          | 400               | LF             | Boiler Rm + Coal Rm, 1st Floor Hallway, West Entry, 1st Floor Corridor, 2nd Floor Corridor by Northeast Stairs | ASSUMED       | TSI               | Y       | LOC         | 1               |              | Yes                           | Damaged or significantly damaged friable thermal system insulating ACBM | 5             | HIGH                  |
| 06    | MJP on Aircell Pipe Runs         | 40                | FITTING        | Boiler Rm + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 07    | Boiler Breeching                 | 75                | LF             | Boiler Room + Coal Room  | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 08    | 9"x9" Maroon Floor Tile          | 2,500             | SF             | Throughout 1st and 2nd Floor, 1st and 2nd Floor Hallways, Stair Landings                                       | ASSUMED       | MISC              | N       | DIST        | 10              |              | No                            | ACBM with potential for significant damage                              | 5             | MODERATE              |
| 08A   | 9"x9" Maroon Floor Tile Mastic   | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings   | ASSUMED       | MISC              | N       | NONE        | 10              |              | No                            | ACBM with potential for significant damage                              |               | MODERATE              |
| 09    | 9"x9" Brown Floor Tile           | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 09A   | 9"x9" Brown Floor Tile Mastic    | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 10    | Black Border Floor Tile          | 700               | SF             | Perimeter 1st and 2nd Floor Hallways, Stair Landings   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 10A   | Black Border Floor Tile Mastic   | 700               | SF             | Perimeter 1st and 2nd Floor Hallways, Stair Landings   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 11    | 9"x9" Green Floor Tile           | 9,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013,  | ASSUMED       | MISC              | N       | NONE        | 5               |              | No                            | ACBM with potential for significant damage                              |               | LOW                   |

# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus Unit 24461 Building ID 4770stans

Address 2318 North Lorel Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                            | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |  |                   |                | 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room   |               |                   |         |             |                 |              |                               |  |               |                       |
| 11A   | 9"x9" Green Floor Tile Mastic                    | 9,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room | ASSUMED       | MISC              | N       | NONE        | 5               |              | No                            | ACBM with potential for significant damage |               | MODERATE              |
| 12    | 12"x12" Beige Streaked Floor Tile                | 4,500             | SF             | Rooms 103, 107, 204, Lunchroom, Main Office Area  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 12A   | 12"x12" Beige Streaked Floor Tile Mastic         | 4,500             | SF             | Rooms 103, 107, 204, Lunchroom, Main Office Area  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 13    | 9"x9" White Floor Tile                           | 8,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, Library and Computer Room                       | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 13A   | 1'x1' White Grooved Ceiling Tile                 | 30,000            | SF             | 1st & 2nd Floor Classrooms, Main Office, Lunchroom  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 15    | Light Brown Floor Tile                           | 400               | SF             | North Stairs by Lunchroom   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 15A   | Light Brown Floor Tile Mastic                    | 400               | SF             | North Stairs by Lunchroom   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 16    | 12"x12" White Floor Tile                         | 500               | SF             | 2nd Floor Room 200 & Restroom   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 16A   | 12"x12" White Floor Tile Mastic                  | 500               | SF             | 2nd Floor Room 200 & Restroom   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 17    | 12"x12" Tan With Brown Streaks Floor Tile        | 260               | SF             | 2nd Floor Kitchen, 1st floor kitchen storage room   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 17A   | 12"x12" Tan With Brown Streaks Floor Tile Mastic | 260               | SF             | 2nd Floor Kitchen, 1st floor kitchen storage room   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 18    | 12"x12" Black w/ White Specks Floor Tile         | 300               | SF             | 2nd Floor Hall by Kitchen   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |

# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus Unit 24461 Building ID 4770stans

Address 2318 North Lorel Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                            | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 18A   | 12"x12" Black w/ White Specks Floor Tile Mastic        | 300               | SF             | 2nd Floor Hall by Kitchen   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 19    | 12"x12" Purple Streaked Floor Tile                     | 275               | SF             | 2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 2nd and 1st fl corridor - replacement patches  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 19A   | 12"x12" Purple Streaked Floor Tile Mastic              | 275               | SF             | 2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 1st and 2nd fl corridors - replacement patches | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 20    | Hard Coat Plaster                                      | 60,000            | SF             | Throughout Building, 1st and 2nd fl corridors, classrooms, Southwest corner stairwell                     | ASSUMED       | SURFACE           | N       | LOC         | 100             |              | No                            | ACBM with potential for significant damage |               | LOW                   |
| 21    | 1'x1' White Smooth Ceiling Tile                        | 400               | SF             | Main Entry Across From Main Office  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 22    | Terrazzo floor beige & multi-color specks              | 600               | SF             | Main entry doorway vestibule  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 23    | Linoleum white with gray specks                        | 900               | SF             | 1st floor boys and girls bathrooms  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 24    | Linoleum white with gray specks MASTIC                 | 900               | SF             | 1st floor boys and girls washrooms  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 25    | 12"x12" Dark Brown with light brown streaks VFT        | 150               | SF             | Replacement Tiles - 1st and 2nd fl. corridor and N.S.E. W. Stairwell landings and center stairwell        | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 26    | 12"x12" Dark Brown with light brown streaks VFT MASTIC | 150               | SF             | Replacement Tiles - 1st and 2nd fl. corridor and N. S. E. W. stairwell landings and center stairwell      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 27    | 9"x9" Black w/white streaks VFT                        | 100               | SF             | 1st fl pump room next to NW stairs  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 28    | 9"x9" Black w/white streaks VFT MASTIC                 | 100               | SF             | 1st fl pump room next to NW stairs  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage         |               | LOW                   |
| 29    | 12" x 12" Tan with Dark Brown Streaks                  | 100               | SF             | 1st Floor Photo   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the                              |               | LOW                   |

# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus Unit 24461 Building ID 4770stans

Address 2318 North Lorel Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA No | Material Description                                | Material Quantity | Material Units | Material Location    | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       | VFT   |                   |                | Room                 |               |                   |         |             |                 |              |                               | potential for damage               |               |                       |
| 29M   | 12" x 12" Tan with Dark Brown Streaks<br>VFT Mastic | 100               | SF             | 1st Floor Photo Room | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage |               | LOW                   |



# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus Unit 24461 Building ID 4770stans  
Address 2318 North Lorel Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>10/4/2019</b>                |
| Inspector Name <b>Joseph Hennigan</b>             |
| <b>100-18350</b> <b>5/15/2020</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments:                                  |
|------------|--|
| 01         | Repairs Completed + Some replacement with fiberglass |
| 02         | Repairs Completed + Some replacement with fiberglass |
| 03         | Repairs Completed + Some replacement with fiberglass |
| 04         | Repairs Completed + Some replacement with fiberglass |
| 05         | Previous Damage Repaired New Damage Noted            |
| 06         | Previous Damaged has been repaired                   |
| 07         | Major Repairs + Some replacement with fiberglass     |
| 08         | Damage still exists throughout (Chipping)            |
| 08A        |  |
| 09         |  |
| 09A        |  |
| 10         |  |
| 10A        |  |
| 11         |  |
| 11A        |  |
| 12         |  |
| 12A        |  |
| 13         |  |
| 13A        |  |
| 15         |  |
| 15A        |  |
| 16         |  |
| 16A        |  |

# Chicago Public Schools

**School** Hanson Park Branch @ St. Stanislaus **Unit** 24461 **Building ID** 4770stans  
**Address** 2318 North Lorel Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 17         |                     |
| 17A        |                     |
| 18         |                     |
| 18A        |                     |
| 19         |                     |
| 19A        |                     |
| 20         |                     |
| 21         |                     |
| 22         |                     |
| 23         |                     |
| 24         |                     |
| 25         |                     |
| 26         |                     |
| 27         |                     |
| 28         |                     |
| 29         |                     |
| 29M        |                     |

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Hanson Park Branch @ St. Stanislaus

**Unit** 24461

**Building ID** 4770stans

**Address** 2318 North Lorel Avenue

Chicago, IL, 60639

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category   | Response        |
|-----------|----------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 01        | Tank Insulation                  | 150               | LF             | Boiler Room + Coal Room   | Assumed       | TSI               | Yes     | 0               | LF           | 7 Any remaining friable ACBM or friable suspect ACBM                      | Follow O&M Plan |
| 02        | MJP on Fiberglass Pipe Runs      | 100               | FITTING        | Boiler Room + Coal Room   | Assumed       | TSI               | Yes     | 0               | FITTING      | 7 Any remaining friable ACBM or friable suspect ACBM                      | Follow O&M Plan |
| 03        | Paperwrap Pipe Insulation        | 500               | LF             | Boiler Room + Coal Room   | Assumed       | TSI               | Yes     | 0               | LF           | 7 Any remaining friable ACBM or friable suspect ACBM                      | Follow O&M Plan |
| 04        | MJP on Paperwrap Pipe Insulation | 50                | FITTING        | Boiler Room + Coal Room   | Assumed       | TSI               | Yes     | 0               | FITTING      | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 05        | Aircell Pipe Insulation          | 400               | LF             | Boiler Rm + Coal Rm, 1st Floor Hallway, West Entry, 1st Floor Corridor, 2nd Floor Corridor by Northeast Stairs  | Assumed       | TSI               | Yes     | 1               | LF           | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair          |
| 06        | MJP on Aircell Pipe Runs         | 40                | FITTING        | Boiler Rm + Coal Room   | Assumed       | TSI               | Yes     | 0               | FITTING      | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 07        | Boiler Breeching                 | 75                | LF             | Boiler Room + Coal Room   | Assumed       | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 08        | 9"x9" Maroon Floor Tile          | 2,500             | SF             | Throughout 1st and 2nd Floor, 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 10              | SF           | 5 ACBM with potential for significant damage                              | Follow O&M Plan |
| 08A       | 9"x9" Maroon Floor Tile Mastic   | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 10              | SF           | 5 ACBM with potential for significant damage                              | Follow O&M Plan |
| 09        | 9"x9" Brown Floor Tile           | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 09A       | 9"x9" Brown Floor Tile Mastic    | 2,500             | SF             | 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 10        | Black Border Floor Tile          | 700               | SF             | Perimeter 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 10A       | Black Border Floor Tile Mastic   | 700               | SF             | Perimeter 1st and 2nd Floor Hallways, Stair Landings  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 11        | 9"x9" Green Floor Tile           | 9,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room | Assumed       | MISC              | No      | 5               | SF           | 5 ACBM with potential for significant damage                              | Follow O&M Plan |
| 11A       | 9"x9" Green Floor Tile Mastic    | 9,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room | Assumed       | MISC              | No      | 5               | SF           | 5 ACBM with potential for significant damage                              | Follow O&M Plan |

# Chicago Public Schools

**School** Hanson Park Branch @ St. Stanislaus

**Unit** 24461

**Building ID** 4770stans

**Address** 2318 North Lorel Avenue

Chicago, IL, 60639

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description                             | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                              | Response        |
|-----------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 12        | 12"x12" Beige Streaked Floor Tile                | 4,500             | SF             | Rooms 103, 107, 204, Lunchroom, Main Office Area  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 12A       | 12"x12" Beige Streaked Floor Tile Mastic         | 4,500             | SF             | Rooms 103, 107, 204, Lunchroom, Main Office Area  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 13        | 9"x9" White Floor Tile                           | 8,000             | SF             | Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, Library and Computer Room | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 13A       | 1'x1' White Grooved Ceiling Tile                 | 30,000            | SF             | 1st & 2nd Floor Classrooms, Main Office, Lunchroom  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 15        | Light Brown Floor Tile                           | 400               | SF             | North Stairs by Lunchroom   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 15A       | Light Brown Floor Tile Mastic                    | 400               | SF             | North Stairs by Lunchroom   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 16        | 12"x12" White Floor Tile                         | 500               | SF             | 2nd Floor Room 200 & Restroom   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 16A       | 12"x12" White Floor Tile Mastic                  | 500               | SF             | 2nd Floor Room 200 & Restroom   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 17        | 12"x12" Tan With Brown Streaks Floor Tile        | 260               | SF             | 2nd Floor Kitchen, 1st floor kitchen storage room   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 17A       | 12"x12" Tan With Brown Streaks Floor Tile Mastic | 260               | SF             | 2nd Floor Kitchen, 1st floor kitchen storage room   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 18        | 12"x12" Black w/ White Specks Floor Tile         | 300               | SF             | 2nd Floor Hall by Kitchen   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 18A       | 12"x12" Black w/ White Specks Floor Tile Mastic  | 300               | SF             | 2nd Floor Hall by Kitchen   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 19        | 12"x12" Purple Streaked Floor Tile               | 275               | SF             | 2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 2nd and 1st fl corridor - replacement patches                            | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 19A       | 12"x12" Purple Streaked Floor Tile Mastic        | 275               | SF             | 2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 1st and 2nd fl corridors - replacement patches                           | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 20        | Hard Coat Plaster                                | 60,000            | SF             | Throughout Building, 1st and 2nd fl corridors, classrooms, Southwest corner stairwell   | Assumed       | SURFACE           | No      | 100             | SF           | 5 ACBM with potential for significant damage | Follow O&M Plan |
| 21        | 1'x1' White Smooth Ceiling Tile                  | 400               | SF             | Main Entry Across From Main Office  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 22        | Terrazzo floor beige & multi-color specks        | 600               | SF             | Main entry doorway vestibule  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 23        | Linoleum white with gray specks                  | 900               | SF             | 1st floor boys and girls bathrooms  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 24        | Linoleum white with gray specks MASTIC           | 900               | SF             | 1st floor boys and girls washrooms  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |
| 25        | 12"x12" Dark Brown with light brown streaks VFT  | 150               | SF             | Replacement Tiles - 1st and 2nd fl.   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage         | Follow O&M Plan |

# Chicago Public Schools

School Hanson Park Branch @ St. Stanislaus

Unit 24461

Building ID 4770stans

Address 2318 North Lorel Avenue

Chicago, IL, 60639

Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description                                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|-----------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|           |  |                   |                | corridor and N.S.E.W. Stairwell landings and center stairwell                                       |               |                   |         |                 |              |                                      |                 |
| 26        | 12"x12" Dark Brown with light brown streaks VFT MASTIC | 150               | SF             | Replacement Tiles - 1st and 2nd fl corridor and N. S. E. W. stairwell landings and center stairwell | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27        | 9"x9" Black w/white streaks VFT                        | 100               | SF             | 1st fl pump room next to NW stairs  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28        | 9"x9" Black w/white streaks VFT MASTIC                 | 100               | SF             | 1st fl pump room next to NW stairs  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29        | 12" x 12" Tan with Dark Brown Streaks VFT              | 100               | SF             | 1st Floor Photo Room  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29M       | 12" x 12" Tan with Dark Brown Streaks VFT Mastic       | 100               | SF             | 1st Floor Photo Room  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Hanson Park Branch @ St. Stanislaus

**Unit** 24461

**Building ID** 4770stans

**Address** 2318 North Lorel Avenue

Chicago, IL, 60639

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

|                                    |            |
|------------------------------------|------------|
| Review Date                        | 10/23/2019 |
| Manager Planner Name               | Jigar Shah |
| 100-07342                          | 5/15/2020  |
| Manager IDPH License No/Expiration |            |

| HA Number | Management Comments         |
|-----------|-----------------------------|
| 01        |                             |
| 02        |                             |
| 03        |                             |
| 04        |                             |
| 05        | Isolate Area, Repair ACM    |
| 06        | Repaired in 2018            |
| 07        |                             |
| 08        | replace damaged VFT         |
| 08A       |                             |
| 09        |                             |
| 09A       |                             |
| 10        |                             |
| 10A       |                             |
| 11        | replace damaged floor tiles |
| 11A       |                             |
| 12        |                             |
| 12A       |                             |
| 13        |                             |
| 13A       |                             |
| 15        |                             |
| 15A       |                             |
| 16        |                             |

# Chicago Public Schools

**School** Hanson Park Branch @ St. Stanislaus

**Unit** 24461

**Building ID** 4770stans

**Address** 2318 North Lorel Avenue

Chicago, IL, 60639

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments           |
|-----------|-------------------------------|
| 16A       |                               |
| 17        |                               |
| 17A       |                               |
| 18        |                               |
| 18A       |                               |
| 19        |                               |
| 19A       |                               |
| 20        | Repair Damaged Plaster if ACM |
| 21        |                               |
| 22        |                               |
| 23        |                               |
| 24        |                               |
| 25        |                               |
| 26        |                               |
| 27        |                               |
| 28        |                               |
| 29        |                               |
| 29M       |                               |



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room + Coal Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS: **Repairs Completed + Some replacement with fiberglass**

Inspector's Signature: \_\_\_\_\_

Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Tank Insulation**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**  
COMMENTS: **Repairs Completed + Some replacement with fiberglass**

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Runs**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Repairs Completed + Some replacement with fiberglass**

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room + Coal Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

COMMENTS: **Repairs Completed + Some replacement with fiberglass**

Inspector's Signature: \_\_\_\_\_

Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **MJP on Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage Deterioration**  
DISTURBANCE POTENTIAL: **HIGH**  
MATERIAL LOCATION: **Boiler Rm + Coal Rm, 1st Floor Hallway, West Entry, 1st Floor Corridor, 2nd Floor Corridor by Northeast Stairs**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**  
COMMENTS: **Previous Damage Repaired New Damage Noted**

Inspector's Signature: \_\_\_\_\_ Date: **10/04/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Boiler Rm + Coal Rm, 1st Floor Hallway, West Entry, 1st Floor Corridor, 2nd Floor Corridor by Northeast Stairs**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Isolate Area, Repair ACM

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Runs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Rm + Coal Room**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

COMMENTS: **Previous Damaged has been repaired**

Inspector's Signature: \_\_\_\_\_

Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Runs**  
MATERIAL LOCATION: **Boiler Rm + Coal Room**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repaired in 2018

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Boiler Breeching**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Major Repairs + Some replacement with fiberglass**

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Boiler Breaching**  
MATERIAL LOCATION: **Boiler Room + Coal Room**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Water**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1st and 2nd Floor, 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**  
COMMENTS: **Damage still exists throughout (Chipping)**

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile**  
MATERIAL LOCATION: **Throughout 1st and 2nd Floor, 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

replace damaged VFT

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **08A**  
MATERIAL DESCRIPTION: **9"x9" Maroon Floor Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24461**    BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus**    INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue**    IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Black Border Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Perimeter 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Black Border Floor Tile**  
MATERIAL LOCATION: **Perimeter 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Border Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Perimeter 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Black Border Floor Tile Mastic**  
MATERIAL LOCATION: **Perimeter 1st and 2nd Floor Hallways, Stair Landings**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/04/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile**  
MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

replace damaged floor tiles

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, East and West Stairs, Library and Computer Room**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 103, 107, 204, Lunchroom, Main Office Area**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile**  
MATERIAL LOCATION: **Rooms 103, 107, 204, Lunchroom, Main Office Area**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 103, 107, 204, Lunchroom, Main Office Area**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 103, 107, 204, Lunchroom, Main Office Area**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, Library and Computer Room**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9"x9" White Floor Tile**  
MATERIAL LOCATION: **Rooms 104, 105, 005, 106, 006, 012, 206, 304, 205, 013, 301, 102, 202, 103, 204, 201, 011, 207, 303, 108, Library and Computer Room**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24461**    BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus**    INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue**    IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **1'x1' White Grooved Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Classrooms, Main Office, Lunchroom**  
MATERIAL QUANTITY: **30000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **1'x1' White Grooved Ceiling Tile**  
MATERIAL LOCATION: **1st & 2nd Floor Classrooms, Main Office, Lunchroom**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Stairs by Lunchroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Light Brown Floor Tile**  
MATERIAL LOCATION: **North Stairs by Lunchroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North Stairs by Lunchroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **North Stairs by Lunchroom**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Room 200 & Restroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile**  
MATERIAL LOCATION: **2nd Floor Room 200 & Restroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Room 200 & Restroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Room 200 & Restroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" Tan With Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Kitchen, 1st floor kitchen storage room**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12"x12" Tan With Brown Streaks Floor Tile**  
MATERIAL LOCATION: **2nd Floor Kitchen, 1st floor kitchen storage room**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12"x12" Tan With Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Kitchen, 1st floor kitchen storage room**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12"x12" Tan With Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Kitchen, 1st floor kitchen storage room**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Hall by Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks Floor Tile**  
MATERIAL LOCATION: **2nd Floor Hall by Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Hall by Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Hall by Kitchen**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" Purple Streaked Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 2nd and 1st fl corridor  
- replacement patches**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12"x12" Purple Streaked Floor Tile**  
MATERIAL LOCATION: **2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 2nd and 1st fl corridor - replacement patches**  
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12"x12" Purple Streaked Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 1st and 2nd fl corridors - replacment patches**  
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12"x12" Purple Streaked Floor Tile Mastic**  
MATERIAL LOCATION: **2nd Floor Kitchen and Stairway by 2nd Floor Computer Room, 1st and 2nd fl corridors - replacement patches**  
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building, 1st and 2nd fl corridors, classrooms, Southwest corner stairwell**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout Building, 1st and 2nd fl corridors, classrooms, Southwest corner stairwell**  
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair Damaged Plaster if ACM

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'x1' White Smooth Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Entry Across From Main Office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **1'x1' White Smooth Ceiling Tile**  
MATERIAL LOCATION: **Main Entry Across From Main Office**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Terrazzo floor beige & multi-color specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main entry doorway vestibule**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Terrazzo floor beige & multi-color specks**  
MATERIAL LOCATION: **Main entry doorway vestibule**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Linoleum white with gray specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor boys and girls bathrooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Linoleum white with gray specks**  
MATERIAL LOCATION: **1st floor boys and girls bathrooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Linoleum white with gray specks MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor boys and girls washrooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Linoleum white with gray specks MASTIC**  
MATERIAL LOCATION: **1st floor boys and girls washrooms**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown with light brown streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Replacement Tiles - 1st and 2nd fl. corridor and N.S.E.W. Stairwell landings and center stairwell**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown with light brown streaks VFT**  
MATERIAL LOCATION: **Replacement Tiles - 1st and 2nd fl. corridor and N.S.E.W. Stairwell landings and center stairwell**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown with light brown streaks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Replacement Tiles - 1st and 2nd fl corridor and N. S. E. W. stairwell landings and center stairwell**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown with light brown streaks VFT MASTIC**  
MATERIAL LOCATION: **Replacement Tiles - 1st and 2nd fl corridor and N. S. E. W. stairwell landings and center stairwell**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **9"x9" Black w/white streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st fl pump room next to NW stairs**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **9"x9" Black w/white streaks VFT**  
MATERIAL LOCATION: **1st fl pump room next to NW stairs**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9"x9" Black w/white streaks VFT MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st fl pump room next to NW stairs**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24461** BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus** REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue** IDPH LICENSE NO: **100-18350**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9"x9" Black w/white streaks VFT MASTIC**  
MATERIAL LOCATION: **1st fl pump room next to NW stairs**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/23/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24461**    BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus**    INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29M**  
MATERIAL DESCRIPTION: **12" x 12" Tan with Dark Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **1st Floor Photo Room**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24461**      BUILDING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @  
St. Stanislaus**      REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **29M**  
MATERIAL DESCRIPTION: **12" x 12" Tan with Dark Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **1st Floor Photo Room**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24461**    BUIDLING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Joseph Hennigan**  
SCHOOL NAME: **Hanson Park Branch @ St. Stanislaus**    INSPECTION DATE: **10/4/2019**  
ADDRESS: **2318 North Lorel Avenue**    IDPH LICENSE NO: **100-18350**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Tan with Dark Brown Streaks VFT**  
MATERIAL LOCATION: **1st Floor Photo Room**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/04/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24461**      BUILDING ID: **4770stans**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Hanson Park Branch @  
St. Stanislaus**      REVIEW DATE: **10/23/2019**  
ADDRESS: **2318 North Lorel Avenue**      IDPH LICENSE NO: **100-18350**

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" Tan with Dark Brown Streaks VFT**  
MATERIAL LOCATION: **1st Floor Photo Room**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/23/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.idph.illinois.gov

4/18/2016

**JOSEPH L HENNIGAN**  
855 W ADAMS, SUITE 200  
CHICAGO, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE  |  |  | ENDORSEMENTS                                 | TC EXPIRES |
|--|--|--|--|------------|
| <br><b>ASBESTOS PROFESSIONAL LICENSE</b><br>ID NUMBER: 100 - 10350<br>ISSUED: 4/18/2016<br>EXPIRES: 05/15/2017<br><b>JOSEPH L HENNIGAN</b><br>855 W ADAMS, SUITE 200<br>CHICAGO, IL 60607<br>Environmental Health |  |  | INSPECTOR                                    | 2/13/2017  |
|   |  |  | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL | 2/6/2017   |
| <b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid training course certificate.   |  |  |  |            |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| FRONT OF LICENSE   |   |                              | BACK OF LICENSE   |                   |
|--|---|------------------------------|---|-------------------|
|             | <b>ASBESTOS PROFESSIONAL LICENSE</b>  |                              | <b>ENDORSEMENTS</b>   | <b>TC EXPIRES</b> |
| <b>ID NUMBER</b><br>100 - 18350  | <b>ISSUED</b><br>5/9/2018   | <b>EXPIRES</b><br>05/15/2019 | INSPECTOR   | 2/10/2019         |
| <b>JOSEPH L HENNIGAN</b><br>2942 W VAN BUREN ST<br>CHICAGO, IL 60612<br>Environmental Health |  |                              | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL  | 2/3/2019          |
|  |   |                              | <b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid<br>training course certificate. |                   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

*Nicholas J. Peneff*

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR15

Certificate Number:



*N. Penneff*

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSEPH L HENNIGAN**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 18350

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| FRONT OF LICENSE   |                                      |   | BACK OF LICENSE   |                   |
|--|--------------------------------------|---|---|-------------------|
|             | <b>ASBESTOS PROFESSIONAL LICENSE</b> |   | <b>ENDORSEMENTS</b>   | <b>TC EXPIRES</b> |
| ID NUMBER<br>100 - 18350   | ISSUED<br>4/19/2019                  | EXPIRES<br>05/15/2020   | INSPECTOR   | 2/9/2020          |
| <b>JOSEPH L HENNIGAN</b><br>2942 W VAN BUREN ST<br>CHICAGO, IL 60612<br>Environmental Health |                                      |  | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL  | 2/2/2020          |
|  |                                      |   | <b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid<br>training course certificate. |                   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that JOSEPH L. HENNIGAN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR15

Certificate Number:

*Nicholas J. Peneff*

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE   |  |  | ENDORSEMENTS  | TC EXPIRES |
|---|--|--|---|------------|
|  |  |  | INSPECTOR   | 2/28/2020  |
| ID NUMBER   | ISSUED   | EXPIRES  | PROJECT DESIGNER  | 3/15/2020  |
| 100 - 07342   | 4/19/2019  | 05/15/2020   | MANAGEMENT PLANNER  | 2/28/2020  |
| <b>JIGAR M SHAH</b>   |  |  | PROJECT MANAGER   | 2/22/2020  |
| 2942 W VAN BUREN ST   |  |  | AIR SAMPLING PROFESSIONAL   |            |
| CHICAGO, IL 60612   |  |  | <b>Alteration of this license shall result in legal action</b>                      |            |
| Environmental Health  |  |  | This license issued under authority of the State of Illinois                        |            |
|   |  |  | Department of Public Health   |            |
|   |  |  | This license is valid only when accompanied by a valid training course certificate. |            |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |