

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2391  
SCHOOL NAME: Palmer School  
ADDRESS OF SCHOOL: 5051 N Kenneth Avenue  
CITY: Chicago, IL, 60630

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/17/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 733  
IDPH INSPECTOR LICENSE NUMBER: 100-05183  
IDPH LICENSED INSPECTOR NAME(Please Print): Delores Fitzpatrick  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Palmer School**

5051 N Kenneth Avenue  
Chicago, IL, 60630

Unit: 24821  
Building ID: 5260

IDPH ID Number: 14-016-2990-2391

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 22, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 24821            Region: 01            IDPH ID:14-016-2990-2391

School: Palmer School            Building ID: 5260

Address: 5051 N Kenneth Avenue

Chicago, IL, 60630

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 11/19/2019

Inspector: Delores Fitzpatrick

Inspector IDPH License: 100-05183

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 22, 2019

RE: Palmer School, Unit 24821  
5051 N Kenneth Avenue  
Chicago, IL, 60630

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Palmer School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Palmer School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Palmer School Unit: 24821 Region: 01  
Address: 5051 N Kenneth Avenue Chicago, IL, 60630  
IDPH ID: 14-016-2990-2391 Building ID: 5260  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 733

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Delores Fitzpatrick

Inspector IDPH license # 100-05183  
Signature:  
Date: 10/22/2019

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019  
Signature:  
Date: 11/19/2019

### 7. Review Date:11/19/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 10/1/2019  
Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Palmer School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5260:

B. The following new homogenous areas have been identified for Building 5260:

- 22A Wood Floor
- 23A Wood Floor

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	Cardboard Pipe Insulation
20	12"x12" Beige VFT
21	12"x12" Beige VFT Mastic
22A	Wood Floor
23A	Wood Floor
24	12"x12" Tan w/ White & Brown Streaks VFT
25	12"x12" Tan w/ White & Brown Streaks VFT Mastic
26	12"x12" White VFT
27	12"x12" White VFT Mastic
29	MJP E/F/V on Fiberglass Pipe Insulation
32	12"x12" Gray VFT
33M	12"x12" Gray VFT Mastic
34	Gray Vinyl Baseboard
35M	Gray Vinyl Baseboard Mastic
36	2'x4' Ceiling Tile
37	Drywall
38	Drywall Joint Compound
39	Vermont Asbestos Fiber Repair NOT OBSERVED
40	Breaching Insulation
41	Pink Insulation
42	Spray-on White Duct Insulation
43	Ornamental Plaster
44	Firedoor
45	Terrazzo
46	2'x2' Tectum Ceiling Tile
47	12"x12" Tan w/white and brown streaks VFT
47A	12"x12" Tan w/white and brown streaks Mastic
48	12"x12" White w/gray speckles VFT
48A	12"x12" White w/gray speckles mastic
49	White Linolium
49A	White Linoleum Mastic
50	Textured Ceiling
51	Drywall System
52	2'x2' Ceiling Tile
53	Fire Doors
54	Pink Insulation
55	12" X 12" Light blue with blue specks VFT (Over HA's 47, 47A, 48 & 48A)
55A	12" X 12" Light blue with blue specks VFT Mastic (Over HA's 47, 47A, 48 & 48A)
56	Tan marble linoleum over existing floor (Over HA's

56A	49 & 49A) Tan marble linoleum over existing floor Mastic (Over HA's 49 & 49A)
57	Carpet Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Delores Fitzpatrick, IDPH License # 100-05183. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Palmer School Building 5260 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Ceramic - NOT OBSERVED			1st Floor Lunchroom and Kitchen - 1912 - NOT OBSERVED		MISC		None						Moderate
04	Cardboard Pipe Insulation	2,000	LF	Throughout 1926	ASSUMED	TSI	Y	NONE	0			ACBM with the potential for damage		LOW
05	Hard Plaster			Throughout 1926	NO_ACBM		N							LOW
10	Green Pipe Insulation (Oil and Chilled Water)	5,000	LF	On Chilled Water Piping and Oil Piping Throughout Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Beige VFT	4,500	SF	1st and 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office; Store Room next to Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
21	12"x12" Beige VFT Mastic	4,500	SF	1st & 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	9"x9" Gray VFT	150	SF	Rooms 109 and 110 and the Store Room - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
22A	Wood Floor	250	SF	Rooms 109 and 110	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
23	9"x9" Gray VFT Mastic	150	SF	Rooms 109 and 110 and the Storeroom - 1926	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23A	Wood Floor	50	SF	Storage Rooms Behind Class Rooms 109 & 110	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		
24	12"x12" Tan w/ White & Brown Streaks VFT	830	SF	Room 217, Room Across From Room 112 and Room Across from Room 212 - 1926	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		MODERATE
25	12"x12" Tan w/ White & Brown Streaks VFT Mastic	830	SF	Room 217, the Room Across From Room 112 and the Room across from Room 212 - 1926	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
26	12"x12" White VFT	400	SF	Teacher's Lounge (105) - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27	12"x12" White VFT Mastic	400	SF	Teacher's Lounge (105) - 1926	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	MJP E/F/V on Mag Block Pipe Insulation	40	LF	Boiler Room and the Tunnel Connecting To the Main Building - 1926	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
29	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Boiler Room, Mechanical Areas, Boy's and Girl's Washroom/Pipe Chases, 1st and 2nd Floor Janitor's Closets - 1926	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
32	12"x12" Gray VFT	8,500	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33M	12"x12" Gray VFT Mastic	8,500	SF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Gray Vinyl Baseboard	1,200	LF	Throughout - 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
35M	Gray Vinyl Baseboard Mastic	1,200	LF	Throughout 1998	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	2'x4' Ceiling Tile	8,500	SF	Throughout 1998	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
37	Drywall	8,500	SF	Throughout 1998	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
38	Drywall Joint Compound	800	LF	Throughout 1998	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
39	Vermont Asbestos Fiber Repair NOT OBSERVED	200		Crawl Space/Unfinished Pipe Space NOT OBSERVED	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		MODERATE
40	Breaching Insulation	150	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0			ACBM with the potential for damage		LOW
41	Pink Insulation	12,200	SF	Attic	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
42	Spray-on White Duct Insulation	12,200	SF	Attic	ASSUMED	TSI	Y	NONE	0			ACBM with the potential for damage		LOW
43	Ornamental Plaster	800	SF	Auditorium, Stage and Balcony	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
44	Firedoor	3	EA	Balcony Projector Room	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
45	Terrazzo	2,000	SF	1st & 2nd floor	ASSUMED	MISC	N	NONE	0			ACBM with the		LOW

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors; Stairwells; Rms 213 & 215 (Throughout Building)								potential for damage		
46	2'x2' Tectum Ceiling Tile	3,000	SF	Gymnasium	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	12"x12" Tan w/white and brown streaks VFT	1,100	SF	Modular Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
47A	12"x12" Tan w/white and brown streaks Mastic	1,100	SF	Modular Hallway	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
48	12"x12" White w/gray speckles VFT	5,000	SF	Rooms 140-147	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
48A	12"x12" White w/gray speckles mastic	5,000	SF	Rooms 140-147	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
49	White Linolium	580	SF	Boy's and Girl's Washroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
49A	White Linoleum Mastic	580	SF	Boy's and Girl's Washroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
50	Textured Ceiling	580	SF	Boy's and Girl's Washroom	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
51	Drywall System	5,000	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
52	2'x2' Ceiling Tile	4,500	SF	Throughout Building	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
53	Fire Doors	16	EA	Hallway Entrances and Rooms 140-147	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
54	Pink Insulation	8,000	SF	Attic	ASSUMED	MISC	Y	NONE	0			ACBM with the potential for damage		LOW
55	12" X 12" Light blue with blue specks VFT (Over HA's 47, 47A, 48 & 48A)	6,100	SF	Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55A	12" X 12" Light blue with blue specks VFT Mastic (Over HA's 47, 47A, 48 & 48A)	6,100	SF	Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Tan marble linoleum over existing floor (Over HA's 49 & 49A)	580	SF	Modular washrooms (Over HA's 49 & 49A)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56A	Tan marble linoleum over existing floor Mastic (Over HA's 49 & 49A)	580	SF	Modular washrooms (Over HA's 49 & 49A)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
57	Carpet Mastic	700	SF	Main Office & Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Cardboard Pipe Insulation	240	LF	Throughout 1926 (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Aircell Duct Wrap	2,500	SF	Main and NE Unexcavated Areas - 1926	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Floor Debris NOT OBSERVED	1,000	SF	All Unexcavated Areas - 1926 NOT OBSERVED	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Aircell Pipe Insulation	2,000	LF	Throughout 1926 - See Hatching Maps	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Mag Block Pipe Insulation	550	LF	Boiler Room and the Tunnel Connecting to Main Building - 1926	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	Boiler Insulation #1	50	SF	Boiler Room - 1926	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Boiler Insulation #2	50	SF	Boiler Room - 1926	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	MJP E/F/V on Aircell Pipe Insulation	200	LF	Throughout 1926 - See Hatching Maps	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/22/2019</b>
Inspector Name <b>Delores Fitzpatrick</b>
<b>100-05183</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
04	
05	
10	
20	
21	
22	
22A	
23	
23A	
24	
25	
26	
27	
28	
29	
32	
33M	
34	
35M	
36	
37	
38	

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
39	
40	
41	
42	
43	
44	
45	
46	
47	
47A	
48	
48A	
49	
49A	
50	
51	
52	
53	
54	
55	
55A	
56	
56A	
57	
F	
G	
H	
J	
K	

# Chicago Public Schools

School Palmer School Unit 24821 Building ID 5260

Address 5051 N Kenneth Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
L	
M	
O	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Ceramic - NOT OBSERVED			1st Floor Lunchroom and Kitchen - 1912 - NOT OBSERVED		MISC					
04	Cardboard Pipe Insulation	2,000	LF	Throughout 1926	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05	Hard Plaster			Throughout 1926	No ACBM		No				
10	Green Pipe Insulation (Oil and Chilled Water)	5,000	LF	On Chilled Water Piping and Oil Piping Throughout Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Beige VFT	4,500	SF	1st and 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office; Store Room next to Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Beige VFT Mastic	4,500	SF	1st & 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9"x9" Gray VFT	150	SF	Rooms 109 and 110 and the Store Room - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22A	Wood Floor	250	SF	Rooms 109 and 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9"x9" Gray VFT Mastic	150	SF	Rooms 109 and 110 and the Storeroom - 1926	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	Wood Floor	50	SF	Storage Rooms Behind Class Rooms 109 & 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Tan w/ White & Brown Streaks VFT	830	SF	Room 217, Room Across From Room 112 and Room Across from Room 212 - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Tan w/ White & Brown Streaks VFT Mastic	830	SF	Room 217, the Room Across From Room 112 and the Room across from Room 212 - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" White VFT	400	SF	Teacher's Lounge (105) - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" White VFT Mastic	400	SF	Teacher's Lounge (105) - 1926	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	MJP E/F/V on Mag Block Pipe Insulation	40	LF	Boiler Room and the Tunnel Connecting To the Main Building - 1926	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
29	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Boiler Room, Mechanical Areas, Boy's and Girl's Washroom/Pipe Chases, 1st and 2nd Floor Janitor's Closets - 1926	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Gray VFT	8,500	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33M	12"x12" Gray VFT Mastic	8,500	SF	Throughout - 1998	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Gray Vinyl Baseboard	1,200	LF	Throughout - 1998	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
35M	Gray Vinyl Baseboard Mastic	1,200	LF	Throughout 1998	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	2'x4' Ceiling Tile	8,500	SF	Throughout 1998	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Drywall	8,500	SF	Throughout 1998	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Drywall Joint Compound	800	LF	Throughout 1998	Assumed	MISC	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
39	Vermont Asbestos Fiber Repair NOT OBSERVED	200		Crawl Space/Unfinished Pipe Space NOT OBSERVED	Assumed	MISC	Yes	0		6 ACBM with the potential for damage	Follow O&M Plan
40	Breaching Insulation	150	SF	Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Pink Insulation	12,200	SF	Attic	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Spray-on White Duct Insulation	12,200	SF	Attic	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Ornamental Plaster	800	SF	Auditorium, Stage and Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Firedoor	3	EA	Balcony Projector Room	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
45	Terrazzo	2,000	SF	1st & 2nd floor Corridors; Stairwells; Rms 213 & 215 (Throughout Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2'x2' Tectum Ceiling Tile	3,000	SF	Gymnasium	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12"x12" Tan w/white and brown streaks VFT	1,100	SF	Modular Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12"x12" Tan w/white and brown streaks Mastic	1,100	SF	Modular Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" White w/gray speckles VFT	5,000	SF	Rooms 140-147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	12"x12" White w/gray speckles mastic	5,000	SF	Rooms 140-147	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	White Linolium	580	SF	Boy's and Girl's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	White Linoleum Mastic	580	SF	Boy's and Girl's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Textured Ceiling	580	SF	Boy's and Girl's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Drywall System	5,000	SF	Throughout Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	2'x2' Ceiling Tile	4,500	SF	Throughout Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Fire Doors	16	EA	Hallway Entrances and Rooms 140-147	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
54	Pink Insulation	8,000	SF	Attic	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" X 12" Light blue with blue specks VFT (Over HA's 47, 47A, 48 & 48A)	6,100	SF	Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12" X 12" Light blue with blue specks VFT Mastic (Over HA's 47, 47A, 48 & 48A)	6,100	SF	Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Tan marble linoleum over existing floor (Over HA's 49 & 49A)	580	SF	Modular washrooms (Over HA's 49 & 49A)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	Tan marble linoleum over existing floor Mastic (Over HA's 49 & 49A)	580	SF	Modular washrooms (Over HA's 49 & 49A)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Carpet Mastic	700	SF	Main Office & Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
 Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
F	MJP E/F/V on Cardboard Pipe Insulation	240	LF	Throughout 1926 (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Aircell Duct Wrap	2,500	SF	Main and NE Unexcavated Areas - 1926	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Floor Debris NOT OBSERVED	1,000	SF	All Unexcavated Areas - 1926 NOT OBSERVED	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Aircell Pipe Insulation	2,000	LF	Throughout 1926 - See Hatching Maps	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Mag Block Pipe Insulation	550	LF	Boiler Room and the Tunnel Connecting to Main Building - 1926	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Boiler Insulation #1	50	SF	Boiler Room - 1926	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Boiler Insulation #2	50	SF	Boiler Room - 1926	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP E/F/V on Aircell Pipe Insulation	200	LF	Throughout 1926 - See Hatching Maps	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
 Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Management Planner's Comments Summarized at the End of the Report*

Review Date	11/19/2019
Manager Planner Name	Arturo Saenz
100-04019	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
04	
05	
10	
20	
21	
22	
22A	
23	
23A	
24	
25	
26	
27	
28	
29	
32	
33M	
34	
35M	
36	
37	
38	

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
39	
40	
41	
42	
43	
44	
45	
46	
47	
47A	
48	
48A	
49	
49A	
50	
51	
52	
53	
54	
55	
55A	
56	
56A	
57	
F	
G	

# Chicago Public Schools

**School** Palmer School  
**Address** 5051 N Kenneth Avenue

**Unit** 24821  
Chicago, IL, 60630

**Building ID** 5260  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
H	
J	
K	
L	
M	
O	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Ceramic - NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st Floor Lunchroom and Kitchen - 1912 - NOT OBSERVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Ceramic - NOT OBSERVED**

MATERIAL LOCATION: **1st Floor Lunchroom and Kitchen - 1912 - NOT OBSERVED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24821**    BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School**    INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue**    IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1926**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1926**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 1926**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Throughout 1926**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Green Pipe Insulation (Oil and Chilled Water)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **On Chilled Water Piping and Oil Piping Throughout Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Green Pipe Insulation (Oil and Chilled Water)**  
MATERIAL LOCATION: **On Chilled Water Piping and Oil Piping Throughout Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12"x12" Beige VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office; Store Room next to Main Office - 1926**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **12"x12" Beige VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office; Store Room next to Main Office - 1926**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office - 1926**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12"x12" Beige VFT Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridor, Rooms 106, 113-115 and 215 and the Main Office - 1926**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 109 and 110 and the Store Room - 1926**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT**  
MATERIAL LOCATION: **Rooms 109 and 110 and the Store Room - 1926**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 109 and 110 and the Storeroom - 1926**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic**  
MATERIAL LOCATION: **Rooms 109 and 110 and the Storeroom - 1926**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White & Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 217, Room Across From Room 112 and Room Across from Room 212 - 1926**

MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White & Brown Streaks VFT**  
MATERIAL LOCATION: **Room 217, Room Across From Room 112 and Room Across from Room 212 - 1926**  
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White & Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 217, the Room Across From Room 112 and the Room across from Room 212 - 1926**

MATERIAL QUANTITY: **830**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Tan w/ White & Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 217, the Room Across From Room 112 and the Room across from Room 212 - 1926**  
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Teacher's Lounge (105) - 1926**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12"x12" White VFT**  
MATERIAL LOCATION: **Teacher's Lounge (105) - 1926**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teacher's Lounge (105) - 1926**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**  
MATERIAL LOCATION: **Teacher's Lounge (105) - 1926**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room and the Tunnel Connecting To the Main Building - 1926**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room and the Tunnel Connecting To the Main Building - 1926**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room, Mechanical Areas, Boy's and Girl's Washroom/Pipe Chases, 1st and 2nd Floor Janitor's Closets - 1926**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room, Mechanical Areas, Boy's and Girl's Washroom/Pipe Chases, 1st and 2nd Floor Janitor's Closets - 1926**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33M**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **33M**  
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout - 1998**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35M**  
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **35M**  
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Mastic**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Drywall Joint Compound**  
MATERIAL LOCATION: **Throughout 1998**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Vermont Asbestos Fiber Repair NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Crawl Space/Unfinished Pipe Space NOT OBSERVED**  
MATERIAL QUANTITY: **200** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Vermont Asbestos Fiber Repair NOT OBSERVED**  
MATERIAL LOCATION: **Crawl Space/Unfinished Pipe Space NOT OBSERVED**  
MATERIAL QUANTITY: **200** MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Breaching Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Breaching Insulation**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Pink Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Pink Insulation**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Spray-on White Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Spray-on White Duct Insulation**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ornamental Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Stage and Balcony**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ornamental Plaster**  
MATERIAL LOCATION: **Auditorium, Stage and Balcony**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Firedoor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Balcony Projector Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Firedoor**  
MATERIAL LOCATION: **Balcony Projector Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd floor Corridors; Stairwells; Rms 213 & 215 (Throughout Building)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **1st & 2nd floor Corridors; Stairwells; Rms 213 & 215 (Throughout Building)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **2'x2' Tectum Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gymnasium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **2'x2' Tectum Ceiling Tile**  
MATERIAL LOCATION: **Gymnasium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12"x12" Tan w/white and brown streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Hallway**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12"x12" Tan w/white and brown streaks VFT**  
MATERIAL LOCATION: **Modular Hallway**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/white and brown streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular Hallway**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12"x12" Tan w/white and brown streaks Mastic**  
MATERIAL LOCATION: **Modular Hallway**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" White w/gray speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 140-147**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" White w/gray speckles VFT**  
MATERIAL LOCATION: **Rooms 140-147**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12"x12" White w/gray speckles mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 140-147**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12"x12" White w/gray speckles mastic**  
MATERIAL LOCATION: **Rooms 140-147**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **White Linolium**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **White Linolium**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24821**    BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School**    INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue**    IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **White Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **White Linoleum Mastic**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Textured Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Textured Ceiling**  
MATERIAL LOCATION: **Boy's and Girl's Washroom**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Drywall System**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hallway Entrances and Rooms 140-147**  
MATERIAL QUANTITY: **16** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Fire Doors**  
MATERIAL LOCATION: **Hallway Entrances and Rooms 140-147**  
MATERIAL QUANTITY: **16** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Pink Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Pink Insulation**  
MATERIAL LOCATION: **Attic**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" X 12" Light blue with blue specks VFT (Over HA's 47, 47A, 48 & 48A)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Modular all classrooms and corridors  
(Over HA's 47, 47A, 48 & 48A)**

MATERIAL QUANTITY: **6100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" X 12" Light blue with blue specks VFT (Over HA's 47, 47A, 48 & 48A)**  
MATERIAL LOCATION: **Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55A**  
MATERIAL DESCRIPTION: **12" X 12" Light blue with blue specks VFT Mastic (Over HA's 47, 47A, 48 & 48A)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Modular all classrooms and corridors  
(Over HA's 47, 47A, 48 & 48A)**

MATERIAL QUANTITY: **6100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **55A**  
MATERIAL DESCRIPTION: **12" X 12" Light blue with blue specks VFT Mastic (Over HA's 47, 47A, 48 & 48A)**  
MATERIAL LOCATION: **Modular all classrooms and corridors (Over HA's 47, 47A, 48 & 48A)**  
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Tan marble linoleum over existing floor (Over HA's 49 & 49A)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Modular washrooms (Over HA's 49 & 49A)**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Tan marble linoleum over existing floor (Over HA's 49 & 49A)**  
MATERIAL LOCATION: **Modular washrooms (Over HA's 49 & 49A)**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56A**  
MATERIAL DESCRIPTION: **Tan marble linoleum over existing floor Mastic (Over HA's 49 & 49A)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Modular washrooms (Over HA's 49 & 49A)**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **56A**  
MATERIAL DESCRIPTION: **Tan marble linoleum over existing floor Mastic (Over HA's 49 & 49A)**  
MATERIAL LOCATION: **Modular washrooms (Over HA's 49 & 49A)**  
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office & Room 206**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Main Office & Room 206**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1926 (See Hatching Maps)**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1926 (See Hatching Maps)**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main and NE Unexcavated Areas - 1926**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Aircell Duct Wrap**  
MATERIAL LOCATION: **Main and NE Unexcavated Areas - 1926**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Floor Debris NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Unexcavated Areas - 1926 NOT OBSERVED**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Floor Debris NOT OBSERVED**  
MATERIAL LOCATION: **All Unexcavated Areas - 1926 NOT OBSERVED**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1926 - See Hatching Maps**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1926 - See Hatching Maps**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room and the Tunnel Connecting to Main Building - 1926**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room and the Tunnel Connecting to Main Building - 1926**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Boiler Insulation #1**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1926**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Boiler Insulation #1**  
MATERIAL LOCATION: **Boiler Room - 1926**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Boiler Insulation #2**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1926**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Boiler Insulation #2**  
MATERIAL LOCATION: **Boiler Room - 1926**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School** INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1926 - See Hatching Maps**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUIDLING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout 1926 - See Hatching Maps**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24821** BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School** REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue** IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Wood Floor**  
MATERIAL LOCATION: **Rooms 109 and 110**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24821**    BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Delores Fitzpatrick**  
SCHOOL NAME: **Palmer School**    INSPECTION DATE: **10/22/2019**  
ADDRESS: **5051 N Kenneth Avenue**    IDPH LICENSE NO: **100-05183**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **Wood Floor**  
MATERIAL LOCATION: **Storage Rooms Behind Class Rooms 109 & 110**  
MATERIAL QUANTITY: **50**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY:    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24821**      BUILDING ID: **5260**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Palmer School**      REVIEW DATE: **11/19/2019**  
ADDRESS: **5051 N Kenneth Avenue**      IDPH LICENSE NO: **100-05183**

HOMOGENEOUS AREA: **23A**  
MATERIAL DESCRIPTION: **Wood Floor**  
MATERIAL LOCATION: **Storage Rooms Behind Class Rooms 109 & 110**  
MATERIAL QUANTITY: **50**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/19/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DELORES FITZPATRICK  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/16/2013 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



*N. Kennedy*

02/16/2013

Course Dates:

02/16/2014

Expires:

1302BIR20

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penoff

Doctor of Public Health

FORM # A-010



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**DELORES FITZPATRICK**  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS          PROFESSIONAL          LICENSE</b>		<b>ENDORSEMENTS</b>  INSPECTOR  PROJECT MANAGER AIR SAMPLING PROFESSIONAL	<b>TC EXPIRES</b>  2/10/2019  2/3/2019
<b>ID NUMBER</b> 100 - 05183	<b>ISSUED</b> 5/9/2018	<b>EXPIRES</b> 05/15/2019			
<b>DELORES FITZPATRICK</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health					
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that DELORES FITZPATRICK  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR11

Certificate Number:

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**DELORES FITZPATRICK**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 05183	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020		INSPECTOR	2/9/2020
<b>DELORES FITZPATRICK</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**DELORES FITZPATRICK**  
855 WEST ADAMS, SUITE 200  
CHICAGO, IL 60607

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 05183

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License			Back of License	
			<b>ASBESTOS PROFESSIONAL LICENSE</b>	
<b>ID NUMBER</b> TC0 - 05183	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017	<b>ENDORSEMENTS</b> INSPECTOR	<b>TC EXPIRES</b> 2/13/2017
<b>DELORES FITZPATRICK</b> 855 WEST ADAMS, SUITE 200 CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/6/2017
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHA*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280693

---

Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 04019	4/30/2019	05/15/2020

**ARTURO SAENZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612  
Environmental Health



<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
---------------------	-------------------

INSPECTOR	2/28/2020
MANAGEMENT PLANNER	2/28/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed