

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2773
SCHOOL NAME: Garvey School
ADDRESS OF SCHOOL: 10309 S. Morgan Avenue
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/21/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 250
IDPH INSPECTOR LICENSE NUMBER: 100-11102
IDPH LICENSED INSPECTOR NAME(Please Print): Elmer Spraggins II
IDPH MP LICENSE NUMBER: 100-09786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Garvey School

10309 S. Morgan Avenue
Chicago, IL, 60643

Unit: 24951
Building ID: 5420

IDPH ID Number: 14-016-2990-2773

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 6, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24951 Region: 06 IDPH ID:14-016-2990-2773

School: Garvey School Building ID: 5420

Address: 10309 S. Morgan Avenue

Chicago, IL, 60643

Building Contact: Hefner, Scott

Contact Phone:847 452 3593

Current Building Owners: Chicago Public Schools

Review Date: 09/05/2019

Inspector: Elmer Spraggins II

Inspector IDPH License: 100-11102

Management Planner: John Fenn

Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

John Fenn
100-09786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 06, 2019

RE: Garvey School, Unit 24951
10309 S. Morgan Avenue
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Garvey School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Garvey School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Garvey School Unit: 24951 Region: 06
Address: 10309 S. Morgan Avenue Chicago, IL, 60643
IDPH ID: 14-016-2990-2773 Building ID: 5420
Contact: Hefner, Scott Phone: 847 452 3593

2. Description of Facility

Original Construction: 1974 Additional Construction:
Total Square Footage: 55354 No of Floors: 3
Current Occupancy: 250

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Elmer Spraggins II

Inspector IDPH license # 100-11102

Signature:
Date: 8/6/2019

6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:
Date: 09/05/2019

7. Review Date:09/05/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Garvey School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5420:

10

Mudded Pipe Joints

B. The following new homogenous areas have been identified for Building 5420:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

08	Insulation in Fire Rated Doors
09	Mudded Pipe Runs
10	Mudded Pipe Joints
11	12x12 Gray Streaked Floor Tile
12	12x12 Gray Streaked Floor Tile Mastic
13	Gray Terrazzo Flooring
14	Brown Terrazzo Flooring
15	Blue Ceramic Tile Grout
16	Blue Ceramic Tile Adhesive
17	Tan Ceramic Tile Grout
18	Tan Ceramic Tile Adhesive
19	12x12 White w/Maroon Specks Floor Tile
19A	12x12 White w/Maroon Specks Floor Tile Mastic
20	Aqua Mosaic Ceramic Tile Grout
21	Aqua Mosaic Ceramic Tile Adhesive
22	Brown Mosaic Ceramic Tile Grout
23	Brown Mosaic Ceramic Tile Adhesive
24	Pink Mosaic Ceramic Tile Grout
25	Pink Mosaic Ceramic Tile Adhesive
26	12x12 Dark Gray Ceramic Tile Grout
27	12x12 Dark Gray Ceramic Tile Adhesive
28	Sink Undercoating
29	Plaster Ceiling
30	Gray Carpet Adhesive
CM-1	Blue Carpet Mastic
CM-2	Purple Carpet Mastic
FT-8	12x12 Gray Patterned Floor Tile
FTM-8	12x12 Gray Patterned Floor Tile Mastic

The following areas were deemed to be inaccessible:

05	12x12 White Patterned Floor Tile Mastic
08	Insulation in Fire Rated Doors
12	12x12 Gray Streaked Floor Tile Mastic
16	Blue Ceramic Tile Adhesive
18	Tan Ceramic Tile Adhesive
19A	12x12 White w/Maroon Specks Floor Tile Mastic
21	Aqua Mosaic Ceramic Tile Adhesive
23	Brown Mosaic Ceramic Tile Adhesive
25	Pink Mosaic Ceramic Tile Adhesive

27	12x12 Dark Gray Ceramic Tile Adhesive
29	Plaster Ceiling
30	Gray Carpet Adhesive
CM-1	Blue Carpet Mastic
CM-2	Purple Carpet Mastic
FTM-1	12x12 Beige Patterned Floor Tile Mastic
FTM-2	12x12 Brown w/White Patterned Floor Tile Mastic
FTM-3	12x12 White w/Red Patterned Floor Tile Mastic
FTM-4	12x12 White w/Caramel Pattern Floor Tile Mastic
FTM-5	12x12 Tan w/White Patterned Floor Tile Mastic
FTM-6	12x12 White w/Black Pattern Floor Tile Mastic
FTM-7	12x12 Grey w/White Pattern Floor Tile Mastic
FTM-8	12x12 Gray Patterned Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Elmer Spraggins II, IDPH License # 100-11102. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Garvey School Building 5420 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Garvey School Unit 24951 Building ID 5420

Address 10309 S. Morgan Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Spray-On Fireproofing			Throughout Facility above Drop In Ceiling Panels	NO_ACBM	SURFACE								
03	2x4 Drop-In Ceiling Panels w/Red Backing			Throughout Facility	NO_ACBM	MISC								
04	12x12 White Patterned Floor Tile	1,500	SF	Front 1/2 of Office, 102, 208, and 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12x12 White Patterned Floor Tile Mastic	3,500	SF	Front 1/2 of Office, 102, 208, and 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Vinyl Baseboard			Library, Rooms 102 and 104	NO_ACBM	MISC								
07	Vinyl Baseboard Mastic			Library, Rooms 102 and 104	NO_ACBM	MISC								
08	Insulation in Fire Rated Doors	560	SF	Exterior Doors and Gym	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Mudded Pipe Runs	30	LF	2nd Floor Utility Room & Pump Room	ASSUMED	TSI	Y	LOC	13		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
10	Mudded Pipe Joints	25	LF	Throughout Facility Including Pump Room	ASSUMED	TSI	Y	LOC	15		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
11	12x12 Gray Streaked Floor Tile	12,000	SF	Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
12	12x12 Gray Streaked Floor Tile Mastic	12,000	SF	Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Gray Terrazzo Flooring	2,280	SF	Stairways, Kitchen, Lobby, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Brown Terrazzo Flooring	80	SF	Border in Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Blue Ceramic Tile Grout	290	SF	3rd Floor Girls'	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Garvey School Unit 24951 Building ID 5420

Address 10309 S. Morgan Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Washroom								potential for damage		
16	Blue Ceramic Tile Adhesive	290	SF	3rd Floor Girls' Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Tan Ceramic Tile Grout	190	SF	3rd Floor Boys' Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Tan Ceramic Tile Adhesive	190	SF	3rd Floor Boys' Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 White w/Maroon Specks Floor Tile	2,640	SF	Rooms 301, 303, 305 and 313	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19A	12x12 White w/Maroon Specks Floor Tile Mastic	2,640	SF	Rooms 301, 303, 305 and 313	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Aqua Mosaic Ceramic Tile Grout	580	SF	1st & 2nd Floor Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Aqua Mosaic Ceramic Tile Adhesive	580	SF	1st & 2nd Floor Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Brown Mosaic Ceramic Tile Grout	370	SF	1st & 2nd Floor Boys' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Brown Mosaic Ceramic Tile Adhesive	370	SF	1st & 2nd Floor Boys' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Pink Mosaic Ceramic Tile Grout	70	SF	Gym Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Pink Mosaic Ceramic Tile Adhesive	70	SF	Gym Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Dark Gray Ceramic Tile Grout	150	SF	Entrance 1 & 2 Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Dark Gray Ceramic Tile Adhesive	150	SF	Entrance 1 & 2 Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Sink Undercoating	4	SF	Rooms 102 and 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Plaster Ceiling	6,000	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Gray Carpet Adhesive	290	SF	Counsellor's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-1	Blue Carpet Mastic	675	SF	Engineer's Office, Rooms 107, 215, 304, 307, MDF Room, 3rd Floor Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CM-2	Purple Carpet Mastic	650	SF	Back Half of Main Office, Principal's Office, and Room 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-1	12x12 Beige Patterned Floor Tile	800	SF	Room 302	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Garvey School Unit 24951 Building ID 5420

Address 10309 S. Morgan Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
FT-2	12x12 Brown w/White Patterned Floor Tile	800	SF	Room 206	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-3	12x12 White w/Red Patterned Floor Tile	1,320	SF	Room 309 and 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-4	12x12 White w/Caramel Pattern Floor Tile	1,400	SF	Room 104 and 211	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-5	12x12 Tan w/White Patterned Floor Tile	4,050	SF	Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms	CHR	MISC	N	LOC	25		No	ACBM with the potential for damage	5	MODERATE
FT-6	12x12 White w/Black Pattern Floor Tile	6,500	SF	Rooms 109, Hall, 205, 207, 209, and 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-7	12x12 Grey w/White Pattern Floor Tile	675	SF	Room 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-8	12x12 Gray Patterned Floor Tile	6,700	SF	3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302, 1st Floor Corridors, Lunchroom 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-1	12x12 Beige Patterned Floor Tile Mastic	800	SF	Room 302	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-2	12x12 Brown w/White Patterned Floor Tile Mastic	1,650	SF	Room 206	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-3	12x12 White w/Red Patterned Floor Tile Mastic	1,320	SF	Rooms 309 and 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	12x12 White w/Caramel Pattern Floor Tile Mastic	1,400	SF	Rooms 104 and 211	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	12x12 Tan w/White Patterned Floor Tile Mastic	4,050	SF	Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-6	12x12 White w/Black Pattern Floor Tile Mastic	6,500	SF	Rooms 109, Hall, 205, 207, 209, and 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-7	12x12 Grey w/White Pattern Floor Tile Mastic	675	SF	Room 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-8	12x12 Gray Patterned Floor Tile Mastic	6,700	SF	3rd Floor Corridor,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Garvey School Unit 24951 Building ID 5420

Address 10309 S. Morgan Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/6/2019
Inspector Name <u>Elmer Spraggins II</u>
<u>100-11102</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
03	
04	
05	
06	
07	
08	
09	Damage at 1st Floor Water Heater & 2nd Floor Water Heater in Janitor's Break Room
10	Damage in 1st Floor Domestic Water Room at back of Gym
11	
12	
13	
14	
15	
16	
17	
18	
19	
19A	
20	
21	
22	
23	

Chicago Public Schools

School Garvey School Unit 24951 Building ID 5420

Address 10309 S. Morgan Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
24	
25	
26	
27	
28	
29	
30	
CM-1	
CM-2	
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	Damage in Room 103, cracks
FT-6	
FT-7	
FT-8	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
WC-1	
WG-1	

Chicago Public Schools

School Garvey School **Unit** 24951 **Building ID** 5420

Address 10309 S. Morgan Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Spray-On Fireproofing			Throughout Facility above Drop In Ceiling Panels	No ACBM	SURFACE					
03	2x4 Drop-In Ceiling Panels w/Red Backing			Throughout Facility	No ACBM	MISC					
04	12x12 White Patterned Floor Tile	1,500	SF	Front 1/2 of Office, 102, 208, and 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12x12 White Patterned Floor Tile Mastic	3,500	SF	Front 1/2 of Office, 102, 208, and 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Vinyl Baseboard			Library, Rooms 102 and 104	No ACBM	MISC					
07	Vinyl Baseboard Mastic			Library, Rooms 102 and 104	No ACBM	MISC					
08	Insulation in Fire Rated Doors	560	SF	Exterior Doors and Gym	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Mudded Pipe Runs	30	LF	2nd Floor Utility Room & Pump Room	Assumed	TSI	Yes	13	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
10	Mudded Pipe Joints	25	LF	Throughout Facility Including Pump Room	Assumed	TSI	Yes	15	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
11	12x12 Gray Streaked Floor Tile	12,000	SF	Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12x12 Gray Streaked Floor Tile Mastic	12,000	SF	Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Gray Terrazzo Flooring	2,280	SF	Stairways, Kitchen, Lobby, and 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Brown Terrazzo Flooring	80	SF	Border in Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Blue Ceramic Tile Grout	290	SF	3rd Floor Girls' Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Blue Ceramic Tile Adhesive	290	SF	3rd Floor Girls' Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Tan Ceramic Tile Grout	190	SF	3rd Floor Boys' Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Tan Ceramic Tile Adhesive	190	SF	3rd Floor Boys' Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 White w/Maroon Specks Floor Tile	2,640	SF	Rooms 301, 303, 305 and 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 White w/Maroon Specks Floor Tile Mastic	2,640	SF	Rooms 301, 303, 305 and 313	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Aqua Mosaic Ceramic Tile Grout	580	SF	1st & 2nd Floor Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Aqua Mosaic Ceramic Tile Adhesive	580	SF	1st & 2nd Floor Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Brown Mosaic Ceramic Tile Grout	370	SF	1st & 2nd Floor Boys' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Brown Mosaic Ceramic Tile Adhesive	370	SF	1st & 2nd Floor Boys' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Pink Mosaic Ceramic Tile Grout	70	SF	Gym Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25	Pink Mosaic Ceramic Tile Adhesive	70	SF	Gym Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Dark Gray Ceramic Tile Grout	150	SF	Entrance 1 & 2 Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Dark Gray Ceramic Tile Adhesive	150	SF	Entrance 1 & 2 Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Sink Undercoating	4	SF	Rooms 102 and 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Plaster Ceiling	6,000	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Gray Carpet Adhesive	290	SF	Counselor's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-1	Blue Carpet Mastic	675	SF	Engineer's Office, Rooms 107, 215, 304, 307, MDF Room, 3rd Floor Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CM-2	Purple Carpet Mastic	650	SF	Back Half of Main Office, Principal's Office, and Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 Beige Patterned Floor Tile	800	SF	Room 302	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 Brown w/White Patterned Floor Tile	800	SF	Room 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-3	12x12 White w/Red Patterned Floor Tile	1,320	SF	Room 309 and 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-4	12x12 White w/Caramel Pattern Floor Tile	1,400	SF	Room 104 and 211	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-5	12x12 Tan w/White Patterned Floor Tile	4,050	SF	Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms	Chrysotile	MISC	No	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-6	12x12 White w/Black Pattern Floor Tile	6,500	SF	Rooms 109, Hall, 205, 207, 209, and 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-7	12x12 Grey w/White Pattern Floor Tile	675	SF	Room 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-8	12x12 Gray Patterned Floor Tile	6,700	SF	3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Beige Patterned Floor Tile Mastic	800	SF	Room 302	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-2	12x12 Brown w/White Patterned Floor Tile Mastic	1,650	SF	Room 206	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	12x12 White w/Red Patterned Floor Tile Mastic	1,320	SF	Rooms 309 and 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-4	12x12 White w/Caramel Pattern Floor Tile Mastic	1,400	SF	Rooms 104 and 211	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-5	12x12 Tan w/White Patterned Floor Tile Mastic	4,050	SF	Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-6	12x12 White w/Black Pattern Floor Tile Mastic	6,500	SF	Rooms 109, Hall, 205, 207, 209, and 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
 Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
FTM-7	12x12 Grey w/White Pattern Floor Tile Mastic	675	SF	Room 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-8	12x12 Gray Patterned Floor Tile Mastic	6,700	SF	3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
WC-1	Window Caulk ABATED			Throughout Facility (Abated)	Abated	MISC					
WG-1	Window Glazing ABATED			Throughout Facility	Abated	MISC					

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
 Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
 174 N. Brandon Drive Glendale Heights, IL, 60139
 Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/05/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
19A	
20	
21	
22	
23	
24	
25	

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
 Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
 174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
26	
27	
28	
29	
30	
CM-1	
CM-2	
FT-1	
FT-2	
FT-3	
FT-4	
FT-5	
FT-6	
FT-7	
FT-8	
FTM-1	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-6	
FTM-7	
FTM-8	
WC-1	
WG-1	

Chicago Public Schools

School Garvey School
Address 10309 S. Morgan Avenue

Unit 24951
Chicago, IL, 60643

Building ID 5420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Spray-On Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility above Drop In Ceiling Panels**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Spray-On Fireproofing**
MATERIAL LOCATION: **Throughout Facility above Drop In Ceiling Panels**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **2x4 Drop-In Ceiling Panels w/Red Backing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **2x4 Drop-In Ceiling Panels w/Red Backing**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12x12 White Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Front 1/2 of Office, 102, 208, and 310**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12x12 White Patterned Floor Tile**
MATERIAL LOCATION: **Front 1/2 of Office, 102, 208, and 310**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 White Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Front 1/2 of Office, 102, 208, and 310**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 White Patterned Floor Tile Mastic**
MATERIAL LOCATION: **Front 1/2 of Office, 102, 208, and 310**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library, Rooms 102 and 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
MATERIAL LOCATION: **Library, Rooms 102 and 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library, Rooms 102 and 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Library, Rooms 102 and 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Exterior Doors and Gym**
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**
MATERIAL LOCATION: **Exterior Doors and Gym**
MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Pipe Runs**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Utility Room & Pump Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **13** DAMAGE UNITS: **LF**
COMMENTS: **Damage at 1st Floor Water Heater & 2nd Floor Water Heater in Janitor's Break Room**

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Pipe Runs**
MATERIAL LOCATION: **2nd Floor Utility Room & Pump Room**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **13** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Mudded Pipe Joints**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility Including Pump Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**
COMMENTS: **Damage in 1st Floor Domestic Water Room at back of Gym**

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Mudded Pipe Joints**
MATERIAL LOCATION: **Throughout Facility Including Pump Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 Gray Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 Gray Streaked Floor Tile**
MATERIAL LOCATION: **Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12x12 Gray Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12x12 Gray Streaked Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 104, 107, 304, 306, 312 and 313, 1st, 2nd and 3rd floor Hallways, Lunchroom, 2nd Floor Teacher's Lounge and Teacher's Restrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Gray Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairways, Kitchen, Lobby, and 1st Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Gray Terrazzo Flooring**
MATERIAL LOCATION: **Stairways, Kitchen, Lobby, and 1st Floor Corridor**
MATERIAL QUANTITY: **2280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Brown Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Border in Lobby**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Brown Terrazzo Flooring**
MATERIAL LOCATION: **Border in Lobby**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Girls' Washroom**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
MATERIAL LOCATION: **3rd Floor Girls' Washroom**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Girls' Washroom**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Adhesive**
MATERIAL LOCATION: **3rd Floor Girls' Washroom**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Boys' Washroom**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**
MATERIAL LOCATION: **3rd Floor Boys' Washroom**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Boys' Washroom**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Adhesive**
MATERIAL LOCATION: **3rd Floor Boys' Washroom**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 White w/Maroon Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 301, 303, 305 and 313**
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 White w/Maroon Specks Floor Tile**
MATERIAL LOCATION: **Rooms 301, 303, 305 and 313**
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12x12 White w/Maroon Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 301, 303, 305 and 313**
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **12x12 White w/Maroon Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 301, 303, 305 and 313**
MATERIAL QUANTITY: **2640** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Aqua Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Girls' Washrooms**
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Aqua Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1st & 2nd Floor Girls' Washrooms**
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Aqua Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Girls' Washrooms**
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Aqua Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st & 2nd Floor Girls' Washrooms**
MATERIAL QUANTITY: **580** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Boys' Washrooms**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1st & 2nd Floor Boys' Washrooms**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Boys' Washrooms**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1st & 2nd Floor Boys' Washrooms**
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Pink Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Vestibule**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Pink Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **Gym Vestibule**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Pink Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Vestibule**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Pink Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **Gym Vestibule**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Dark Gray Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance 1 & 2 Vestibules**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Dark Gray Ceramic Tile Grout**
MATERIAL LOCATION: **Entrance 1 & 2 Vestibules**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Dark Gray Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrance 1 & 2 Vestibules**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Dark Gray Ceramic Tile Adhesive**
MATERIAL LOCATION: **Entrance 1 & 2 Vestibules**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102 and 104**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Rooms 102 and 104**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Plaster Ceiling**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Counsellor's Office**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
MATERIAL LOCATION: **Counsellor's Office**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office, Rooms 107, 215, 304, 307, MDF Room, 3rd Floor Teacher's Lounge**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **CM-1**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Engineer's Office, Rooms 107, 215, 304, 307, MDF Room, 3rd Floor Teacher's Lounge**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Back Half of Main Office, Principal's Office, and Room 109**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **CM-2**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
MATERIAL LOCATION: **Back Half of Main Office, Principal's Office, and Room 109**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 Beige Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 Beige Patterned Floor Tile**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 Brown w/White Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-2**
MATERIAL DESCRIPTION: **12x12 Brown w/White Patterned Floor Tile**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-3**
MATERIAL DESCRIPTION: **12x12 White w/Red Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 309 and 311**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-3**
MATERIAL DESCRIPTION: **12x12 White w/Red Patterned Floor Tile**
MATERIAL LOCATION: **Room 309 and 311**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-4**
MATERIAL DESCRIPTION: **12x12 White w/Caramel Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 104 and 211**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-4**
MATERIAL DESCRIPTION: **12x12 White w/Caramel Pattern Floor Tile**
MATERIAL LOCATION: **Room 104 and 211**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-5**
MATERIAL DESCRIPTION: **12x12 Tan w/White Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**
COMMENTS: **Damage in Room 103, cracks**

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-5**
MATERIAL DESCRIPTION: **12x12 Tan w/White Patterned Floor Tile**
MATERIAL LOCATION: **Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-6**
MATERIAL DESCRIPTION: **12x12 White w/Black Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 109, Hall, 205, 207, 209, and 202**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-6**
MATERIAL DESCRIPTION: **12x12 White w/Black Pattern Floor Tile**
MATERIAL LOCATION: **Rooms 109, Hall, 205, 207, 209, and 202**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-7**
MATERIAL DESCRIPTION: **12x12 Grey w/White Pattern Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 204**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-7**
MATERIAL DESCRIPTION: **12x12 Grey w/White Pattern Floor Tile**
MATERIAL LOCATION: **Room 204**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-8**
MATERIAL DESCRIPTION: **12x12 Gray Patterned Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109**

MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FT-8**
MATERIAL DESCRIPTION: **12x12 Gray Patterned Floor Tile**
MATERIAL LOCATION: **3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109**
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 Beige Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **12x12 Beige Patterned Floor Tile Mastic**
MATERIAL LOCATION: **Room 302**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 Brown w/White Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-2**
MATERIAL DESCRIPTION: **12x12 Brown w/White Patterned Floor Tile Mastic**
MATERIAL LOCATION: **Room 206**
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**
MATERIAL DESCRIPTION: **12x12 White w/Red Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 309 and 311**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-3**
MATERIAL DESCRIPTION: **12x12 White w/Red Patterned Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 309 and 311**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-4**
MATERIAL DESCRIPTION: **12x12 White w/Caramel Pattern Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 104 and 211**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-4**
MATERIAL DESCRIPTION: **12x12 White w/Caramel Pattern Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 104 and 211**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**
MATERIAL DESCRIPTION: **12x12 Tan w/White Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms**

MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-5**
MATERIAL DESCRIPTION: **12x12 Tan w/White Patterned Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101, 103, 201, 203, 314, Engineer's Office and 1st, 2nd & 3rd Floor Storage Rooms**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-6**
MATERIAL DESCRIPTION: **12x12 White w/Black Pattern Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 109, Hall, 205, 207, 209, and 202**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-6**
MATERIAL DESCRIPTION: **12x12 White w/Black Pattern Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 109, Hall, 205, 207, 209, and 202**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-7**
MATERIAL DESCRIPTION: **12x12 Grey w/White Pattern Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 204**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-7**
MATERIAL DESCRIPTION: **12x12 Grey w/White Pattern Floor Tile Mastic**
MATERIAL LOCATION: **Room 204**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-8**
MATERIAL DESCRIPTION: **12x12 Gray Patterned Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109**

MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUILDING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **FTM-8**
MATERIAL DESCRIPTION: **12x12 Gray Patterned Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Corridor, Teachers Lounge and Restroom, Electric Closet, 308, 302. 1st Floor Corridors, Lunchroom 109**
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WC-1**
MATERIAL DESCRIPTION: **Window Caulk ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **WC-1**
MATERIAL DESCRIPTION: **Window Caulk ABATED**
MATERIAL LOCATION: **Throughout Facility (Abated)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Garvey School** INSPECTION DATE: **8/6/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **WG-1**
MATERIAL DESCRIPTION: **Window Glazing ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24951** BUIDLING ID: **5420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Garvey School** REVIEW DATE: **9/5/2019**
ADDRESS: **10309 S. Morgan Avenue** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **WG-1**
MATERIAL DESCRIPTION: **Window Glazing ABATED**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ELMER SPRAGGINS II
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI06

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
275 Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081

Fax: 312-421-2921

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	1/30/2020
100 - 11102	4/16/2019	05/15/2020		PROJECT MANAGER	3/29/2020
ELMER SPRAGGINS II				AIR SAMPLING PROFESSIONAL	
12823 S GREEN				Alteration of this license shall result in legal action	
CHICAGO, IL 60643				This license issued under authority of the State of Illinois	
Environmental Health				Department of Public Health	
				This license is valid only when accompanied by a valid training course certificate.	

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035


Kathy DeSalvo, Director

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

JOHN H FENN

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed