

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2417  
SCHOOL NAME: Ray School  
ADDRESS OF SCHOOL: 5631 S. Kimbark  
CITY: Chicago, IL, 60637

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/23/2016

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 677  
IDPH INSPECTOR LICENSE NUMBER: 100-11070  
IDPH LICENSED INSPECTOR NAME(Please Print): Mallory Jones  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Ray School**

5631 S. Kimbark  
Chicago, IL, 60637

Unit: 25071  
Building ID: 5560

IDPH ID Number: 14-016-2990-2417

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

May 16, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 25071            Region: 04            IDPH ID:14-016-2990-2417

School: Ray School            Building ID: 5560

Address: 5631 S. Kimbark

Chicago, IL, 60637

Building Contact: Baffoe, Michael

Contact Phone:312 929 7292

Current Building Owners: Chicago Public Schools

Review Date: 06/03/2019

Inspector: Mallory Jones

Inspector IDPH License: 100-11070

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 16, 2019

RE: Ray School, Unit 25071  
5631 S. Kimbark  
Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Ray School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Ray School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Ray School Unit: 25071 Region: 04  
Address: 5631 S. Kimbark Chicago, IL, 60637  
IDPH ID: 14-016-2990-2417 Building ID: 5560  
Contact: Baffoe, Michael Phone: 312 929 7292

### 2. Description of Facility

Original Construction: 1893 Additional Construction: 1915,1996  
Total Square Footage: 84500 No of Floors: 4  
Current Occupancy: 677

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Chicago, Il, 60607  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Mallory Jones

Inspector IDPH license # 100-11070

Signature:  
Date: 5/16/2019

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:  
Date: 06/03/2019

### 7. Review Date:06/03/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ray School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5560:

E	cardboard pipe covering
F	cardboard pipe fittings
S	Cementious Pipe Fittings
T	Pipe Insulation

B. The following new homogenous areas have been identified for Building 5560:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Hard Plaster
02A	12x12 beige w/tan streaks floor tile
02B	12x12 black floor tile
02C	12x12 white floor tile
02D	12x12 beige streaked floor tile
02E	12x12 orange floor tile
10	wallboard
11B	12x12 black floor tile mastic
16	brown vinyl baseboard
17	brown vinyl baseboard mastic
18	drywall compound
19A	12x12 green floor tile
19B	12x12 green floor tile mastic
21	ceiling plaster
22	12"x12" Light Blue VFT
23	12"x12" Light Blue VFT Mastic
24	12"x12" Dark Blue VFT
25	12"x12" Dark Blue VFT Mastic
26	Lab Table Tops
27	12"x12" Light Green VFT
28	12"x12" Light Green VFT Mastic
29	12"x12" Dark Green VFT
30	12"x12" Dark Green VFT Mastic
S	Cementitious Pipe Fittings
T	Pipe Insulation
V	Cementitious Pipe Fittings
W	Pipe Insulation
X	Material behind metal ceiling and walls

The following areas were deemed to be inaccessible:

11A	12x12 beige w/tan streaks floor tile mastic
11B	12x12 black floor tile mastic
11F	12x12 tan floor tile mastic
17	brown vinyl baseboard mastic
18	drywall compound
19B	12x12 green floor tile mastic
23	12"x12" Light Blue VFT Mastic
25	12"x12" Dark Blue VFT Mastic
28	12"x12" Light Green VFT Mastic

30	12"x12" Dark Green VFT Mastic
E	cardboard pipe covering
F	cardboard pipe fittings
H	aircell pipe joints
K	water meter packing
S	Cementious Pipe Fittings
T	Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Ray School Building 5560 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Plaster	40,000	SF	Throughout 1893 Construction	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	12x12 beige w/tan streaks floor tile	1,550	SF	basement art room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02B	12x12 black floor tile	300	SF	room 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02C	12x12 white floor tile	300	SF	room 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02D	12x12 beige streaked floor tile	430	SF	1st, 2nd, 3rd floor corridors (patches)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02E	12x12 orange floor tile			1st floor corridor - outside boys toilet	ASSUMED	MISC								
02F	12x12 tan floor tile	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	9x9 black floor tile			main office - principal's office, bathroom, vault	CHR	MISC								
03B	9x9 white floor tile			main office - principal's office, bathroom & vault	CHR	MISC								
03C	9x9 green floor tile			engineer's toilet	CHR	MISC								
05	linoleum			basement ladie's room	NO_ACBM	MISC								
08	12x12 floor tile- ABATED			1955 building (demolished)	ABATED	MISC								
09	9x9 floor tile- ABATED			1955 building (demolished)	ABATED	MISC								
10	wallboard	450	SF	basement art room, fire pump room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11A	12x12 beige w/tan streaks floor tile mastic	1,550	SF	basement - art room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11B	12x12 black floor tile mastic	1,000	SF	room 306	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11C	12x12 white floor tile mastic			room 306	NO_ACBM	MISC								
11D	12x12 beige streaked floor tile mastic			1st, 2nd, 3rd floor corridors (patches)	CHR	MISC								
11E	12x12 orange floor tile mastic			1st floor corridor - outside boys toilet	CHR	MISC								
11F	12x12 tan floor tile mastic	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				102,105,107, engineer'sn office										
12A	9x9 black floor tile mastic (Abated)			main office - principal's office, washroom, vault	ABATED	MISC								
12B	9x9 white floor tile mastic (Abated)			main office - principal's office, bathroom & vault	ABATED	MISC								
12C	9x9 green floor tile mastic			engineer's toilet	ABATED	MISC								
13	linoleum mastic			basement ladie's room	NO_ACBM	MISC								
14	12x12 floor tile mastic- ABATED			1955 building- (building demolished)	ABATED	MISC								
15	9x9 floor tile mastic- ABATED			1955 building- (building demolished)	ABATED	MISC								
16	brown vinyl baseboard	200	LF	basement art room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	brown vinyl baseboard mastic	200	LF	basement art room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	drywall compound	200	SF	basement art room	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
19A	12x12 green floor tile	800	SF	Staff lounge - kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19B	12x12 green floor tile mastic	800	SF	Staff lounge - kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Hard Plaster			Auditorium	NO_ACBM	SURFACE								
21	ceiling plaster	10,160	SF	throughout basement	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Light Blue VFT	6,700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Light Blue VFT Mastic	6,700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Dark Blue VFT	2,400	SF	Basement, 1st, 2nd, 3rd Floor Corridors,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				demolished)										
R	aircell pipe joints- ABATED			1955 addition- (building demolished)	ABATED	MISC								
S	Cementitious Pipe Fittings	10	LF	Girls and Boys bathrooms - pipe chases	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
T	Pipe Insulation	30	LF	Girls and Boys bathrooms - pipe chases	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
U	incinerator brick			boiler room	NO_ACBM	TSI		None						
V	Cementitious Pipe Fittings			Engineer's Storage and Fire Pump Room	ASSUMED	TSI		None						Low
W	Pipe Insulation			Engineer's Storage and Fire Pump Room	ASSUMED	TSI		None						Low
X	Material behind metal ceiling and walls			Auditorium Fan Room	ASSUMED	SURFACE		None						Low



# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>5/16/2019</b>
Inspector Name <b>Mallory Jones</b>
<b>100-11070</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02A	
02B	
02C	
02D	
02E	
02F	
03A	
03B	
03C	
05	
08	
09	
10	
11A	
11B	
11C	
11D	
11E	
11F	
12A	
12B	
12C	

# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
13	
14	
15	
16	
17	
18	
19A	
19B	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
A	
E	
F	
G	
H	
I	
K	
O	
P	
Q	

# Chicago Public Schools

School Ray School Unit 25071 Building ID 5560

Address 5631 S. Kimbark Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
R	
S	
T	
U	
V	
W	
X	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Ray School  
Address 5631 S. Kimbark

Unit 25071  
Chicago, IL, 60637

Building ID 5560  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Plaster	40,000	SF	Throughout 1893 Construction	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	12x12 beige w/tan streaks floor tile	1,550	SF	basement art room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02B	12x12 black floor tile	300	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12x12 white floor tile	300	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12x12 beige streaked floor tile	430	SF	1st, 2nd, 3rd floor corridors (patches)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	12x12 orange floor tile			1st floor corridor - outside boys toilet	Assumed	MISC					
02F	12x12 tan floor tile	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	9x9 black floor tile			main office - principal's office, bathroom, vault	Chrysotile	MISC					
03B	9x9 white floor tile			main office - principal's office, bathroom & vault	Chrysotile	MISC					
03C	9x9 green floor tile			engineer's toilet	Chrysotile	MISC					
05	linoleum			basement ladie's room	No ACBM	MISC					
08	12x12 floor tile- ABATED			1955 building (demolished)	Abated	MISC					
09	9x9 floor tile- ABATED			1955 building (demolished)	Abated	MISC					
10	wallboard	450	SF	basement art room, fire pump room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12x12 beige w/tan streaks floor tile mastic	1,550	SF	basement - art room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11B	12x12 black floor tile mastic	1,000	SF	room 306	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11C	12x12 white floor tile mastic			room 306	No ACBM	MISC					
11D	12x12 beige streaked floor tile mastic			1st, 2nd, 3rd floor corridors (patches)	Chrysotile	MISC					
11E	12x12 orange floor tile mastic			1st floor corridor - outside boys toilet	Chrysotile	MISC					
11F	12x12 tan floor tile mastic	4,770	SF	Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, engineer'sn office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	9x9 black floor tile mastic (Abated)			main office - principal's office, washroom, vault	Abated	MISC					
12B	9x9 white floor tile mastic (Abated)			main office - principal's office, bathroom & vault	Abated	MISC					
12C	9x9 green floor tile mastic			engineer's toilet	Abated	MISC					
13	linoleum mastic			basement ladie's room	No ACBM	MISC					
14	12x12 floor tile mastic- ABATED			1955 building- (building demolished)	Abated	MISC					
15	9x9 floor tile mastic- ABATED			1955 building- (building demolished)	Abated	MISC					

# Chicago Public Schools

School Ray School  
Address 5631 S. Kimbark

Unit 25071  
Chicago, IL, 60637

Building ID 5560  
Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
16	brown vinyl baseboard	200	LF	basement art room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17	brown vinyl baseboard mastic	200	LF	basement art room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
18	drywall compound	200	SF	basement art room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12x12 green floor tile	800	SF	Staff lounge - kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19B	12x12 green floor tile mastic	800	SF	Staff lounge - kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Hard Plaster			Auditorium	No ACBM	SURFACE					
21	ceiling plaster	10,160	SF	throughout basement	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Light Blue VFT	6,700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Light Blue VFT Mastic	6,700	SF	Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Dark Blue VFT	2,400	SF	Basement, 1st, 2nd, 3rd Floor Corridors, Adjust. Office,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Dark Blue VFT Mastic	2,400	SF	Basement, 1st, 2nd, 3rd Floor Corridors, Adjust. Office,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Lab Table Tops	432	SF	Room 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" Light Green VFT	3,200	SF	1st Floor Corridor, Storage Room, Principles Office.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Light Green VFT Mastic	3,200	SF	1st Floor Corridor, Storage Room, Principles Office.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Dark Green VFT	3,200	SF	1st Floor Corridor and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Dark Green VFT Mastic	3,200	SF	1st Floor Corridor and Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	mag block boiler insulation- ABATED			boiler room- material abated and boiler removed in 1994	Abated	MISC					
E	cardboard pipe covering	40	SF	attic - tank	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	cardboard pipe fittings	3	LF	attic - tank	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	aircell pipe insulation			original (1893) building air chamber	Abated	TSI					
H	aircell pipe joints	6	FITTING	basement teachers lounge	Chrysotile	TSI	Yes	1	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
I	preform pipe covering- ABATED			1893 building	Abated	MISC					

# Chicago Public Schools

**School** Ray School  
**Address** 5631 S. Kimbark

**Unit** 25071  
 Chicago, IL, 60637

**Building ID** 5560  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
K	water meter packing	5	FITTING	basement fire pump room, Basement Teacher's Lounge	Amosite	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	cardboard pipe covering- ABATED			1955 addition- (building demolished)	Abated	MISC					
P	cardboard pipe joint- ABATED			1955 addition- (building demolished)	Abated	MISC					
Q	aircell pipe insulation- ABATED			1955 building addition- (building demolished)	Abated	MISC					
R	aircell pipe joints- ABATED			1955 addition- (building demolished)	Abated	MISC					
S	Cementious Pipe Fittings	10	LF	Girls and Boys bathrooms - pipe chases	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
T	Pipe Insulation	30	LF	Girls and Boys bathrooms - pipe chases	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	incinerator brick			boiler room	No ACBM	TSI					
V	Cementitious Pipe Fittings			Engineer's Storage and Fire Pump Room	Assumed	TSI					
W	Pipe Insulation			Engineer's Storage and Fire Pump Room	Assumed	TSI					
X	Material behind metal ceiling and walls			Auditorium Fan Room	Assumed	SURFACE					

# Chicago Public Schools

**School** Ray School  
**Address** 5631 S. Kimbark

**Unit** 25071  
 Chicago, IL, 60637

**Building ID** 5560  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	06/03/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02A	
02B	
02C	
02D	
02E	
02F	
03A	
03B	
03C	
05	
08	
09	
10	
11A	
11B	
11C	
11D	
11E	



# Chicago Public Schools

**School** Ray School  
**Address** 5631 S. Kimbark

**Unit** 25071  
Chicago, IL, 60637

**Building ID** 5560  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
11F	
12A	
12B	
12C	
13	
14	
15	
16	
17	
18	
19A	
19B	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
A	
E	
F	

# Chicago Public Schools

**School** Ray School  
**Address** 5631 S. Kimbark

**Unit** 25071  
Chicago, IL, 60637

**Building ID** 5560  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
G	
H	Repair damaged material
I	
K	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1893 Construction**  
MATERIAL QUANTITY: **40000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Plaster**  
MATERIAL LOCATION: **Throughout 1893 Construction**  
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 beige w/tan streaks floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **1550**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02A**  
MATERIAL DESCRIPTION: **12x12 beige w/tan streaks floor tile**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 black floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02B**  
MATERIAL DESCRIPTION: **12x12 black floor tile**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02C**  
MATERIAL DESCRIPTION: **12x12 white floor tile**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 beige streaked floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches)**  
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02D**  
MATERIAL DESCRIPTION: **12x12 beige streaked floor tile**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches)**  
MATERIAL QUANTITY: **430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02E**  
MATERIAL DESCRIPTION: **12x12 orange floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor - outside boys toilet**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02E**

MATERIAL DESCRIPTION: **12x12 orange floor tile**

MATERIAL LOCATION: **1st floor corridor - outside boys toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02F**  
MATERIAL DESCRIPTION: **12x12 tan floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office**  
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02F**  
MATERIAL DESCRIPTION: **12x12 tan floor tile**  
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102, 105, 107, eng office**  
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**  
MATERIAL DESCRIPTION: **9x9 black floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom, vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **03A**

MATERIAL DESCRIPTION: **9x9 black floor tile**

MATERIAL LOCATION: **main office - principal's office, bathroom, vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **9x9 white floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom & vault**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **03B**  
MATERIAL DESCRIPTION: **9x9 white floor tile**  
MATERIAL LOCATION: **main office - principal's office, bathroom & vault**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03C**  
MATERIAL DESCRIPTION: **9x9 green floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **03C**

MATERIAL DESCRIPTION: **9x9 green floor tile**

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **linoleum**

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **12x12 floor tile- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12x12 floor tile- ABATED**

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **9x9 floor tile- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9x9 floor tile- ABATED**

MATERIAL LOCATION: **1955 building (demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **wallboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement art room, fire pump room**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **wallboard**  
MATERIAL LOCATION: **basement art room, fire pump room**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12x12 beige w/tan streaks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement - art room**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12x12 beige w/tan streaks floor tile mastic**  
MATERIAL LOCATION: **basement - art room**  
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **12x12 black floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **12x12 black floor tile mastic**  
MATERIAL LOCATION: **room 306**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **12x12 white floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11C**

MATERIAL DESCRIPTION: **12x12 white floor tile mastic**

MATERIAL LOCATION: **room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **12x12 beige streaked floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **12x12 beige streaked floor tile mastic**  
MATERIAL LOCATION: **1st, 2nd, 3rd floor corridors (patches)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**  
MATERIAL DESCRIPTION: **12x12 orange floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st floor corridor - outside boys toilet**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11E**

MATERIAL DESCRIPTION: **12x12 orange floor tile mastic**

MATERIAL LOCATION: **1st floor corridor - outside boys toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11F**  
MATERIAL DESCRIPTION: **12x12 tan floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office**  
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **11F**  
MATERIAL DESCRIPTION: **12x12 tan floor tile mastic**  
MATERIAL LOCATION: **Classrooms 303, 305, 310, 311, 313, 203, 205, 208, 101, 102,105,107, engineer'sn office**  
MATERIAL QUANTITY: **4770** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **9x9 black floor tile mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, washroom, vault**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **9x9 black floor tile mastic (Abated)**

MATERIAL LOCATION: **main office - principal's office, washroom, vault**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9x9 white floor tile mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **main office - principal's office, bathroom & vault**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9x9 white floor tile mastic (Abated)**  
MATERIAL LOCATION: **main office - principal's office, bathroom & vault**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **9x9 green floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **12C**

MATERIAL DESCRIPTION: **9x9 green floor tile mastic**

MATERIAL LOCATION: **engineer's toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **linoleum mastic**

MATERIAL LOCATION: **basement ladie's room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12x12 floor tile mastic- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12x12 floor tile mastic- ABATED**

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 floor tile mastic- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9x9 floor tile mastic- ABATED**

MATERIAL LOCATION: **1955 building- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **brown vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **brown vinyl baseboard**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **brown vinyl baseboard mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **brown vinyl baseboard mastic**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **drywall compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **drywall compound**  
MATERIAL LOCATION: **basement art room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 green floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff lounge - kitchen**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **12x12 green floor tile**  
MATERIAL LOCATION: **Staff lounge - kitchen**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19B**  
MATERIAL DESCRIPTION: **12x12 green floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Staff lounge - kitchen**  
MATERIAL QUANTITY: **800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **19B**  
MATERIAL DESCRIPTION: **12x12 green floor tile mastic**  
MATERIAL LOCATION: **Staff lounge - kitchen**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Hard Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **ceiling plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **throughout basement**  
MATERIAL QUANTITY: **10160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **ceiling plaster**  
MATERIAL LOCATION: **throughout basement**  
MATERIAL QUANTITY: **10160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**  
MATERIAL LOCATION: **Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,**  
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,**  
MATERIAL QUANTITY: **6700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Light Blue VFT Mastic**

MATERIAL LOCATION: **Basement Storage, Boys Restroom, Lunchroom, Corridor, Girls Playroom, Room 312,**

MATERIAL QUANTITY: **6700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT**  
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT Mastic**  
MATERIAL LOCATION: **Basement,1st,2nd,3rd Floor Corridors, Adjust. Office,**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Lab Table Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 309**  
MATERIAL QUANTITY: **432**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: **432**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Light Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" Light Green VFT**

MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12"x12" Light Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Light Green VFT Mastic**

MATERIAL LOCATION: **1st Floor Corridor, Storage Room, Principles Office.**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12"x12" Dark Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Office**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12"x12" Dark Green VFT**  
MATERIAL LOCATION: **1st Floor Corridor and Office**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" Dark Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor and Office**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" Dark Green VFT Mastic**  
MATERIAL LOCATION: **1st Floor Corridor and Office**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **mag block boiler insulation- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room- material abated and boiler removed in 1994**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **mag block boiler insulation- ABATED**

MATERIAL LOCATION: **boiler room- material abated and boiler removed in 1994**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **cardboard pipe covering**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **attic - tank**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **cardboard pipe covering**  
MATERIAL LOCATION: **attic - tank**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **cardboard pipe fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **attic - tank**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **cardboard pipe fittings**  
MATERIAL LOCATION: **attic - tank**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **original (1893) building air chamber**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **aircell pipe insulation**

MATERIAL LOCATION: **original (1893) building air chamber**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **aircell pipe joints**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement teachers lounge**  
MATERIAL QUANTITY: **6** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **1** DAMAGE UNITS: **FITTING**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **aircell pipe joints**

MATERIAL LOCATION: **basement teachers lounge**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **1**

DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair damaged material

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **preform pipe covering- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1893 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **preform pipe covering- ABATED**

MATERIAL LOCATION: **1893 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **water meter packing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **basement fire pump room, Basement Teacher's Lounge**  
MATERIAL QUANTITY: **5**    MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **water meter packing**  
MATERIAL LOCATION: **basement fire pump room, Basement Teacher's Lounge**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **cardboard pipe covering- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **cardboard pipe covering- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **cardboard pipe joint- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **cardboard pipe joint- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **aircell pipe insulation- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 building addition- (building demolished)**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **aircell pipe insulation- ABATED**

MATERIAL LOCATION: **1955 building addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **aircell pipe joints- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **aircell pipe joints- ABATED**

MATERIAL LOCATION: **1955 addition- (building demolished)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Cementious Pipe Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Cementious Pipe Fittings**  
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/16/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
MATERIAL LOCATION: **Girls and Boys bathrooms - pipe chases**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **incinerator brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **incinerator brick**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **Cementitous Pipe Fittings**

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25071**    BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School**    INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark**    IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUILDING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: **Pipe Insulation**

MATERIAL LOCATION: **Engineer's Storage and Fire Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Ray School** INSPECTION DATE: **5/16/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Material behind metal ceiling and walls**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Auditorium Fan Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/16/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25071** BUIDLING ID: **5560**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Ray School** REVIEW DATE: **6/3/2019**  
ADDRESS: **5631 S. Kimbark** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **Material behind metal ceiling and walls**

MATERIAL LOCATION: **Auditorium Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **06/03/2019**



# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2019 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---



2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384

  
Kathy DeSalvo, Director





**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19466**

ISSUED  
**4/12/2019**

EXPIRES  
**05/15/2020**

**EVAN I CHRISTIAN**  
3024 N RACINE AVE, APT 2  
CHICAGO, IL 60657



Environmental Health

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019

Expiration Date: 1/7/2020

Certificate Number: MPR1901070063




---

Kathy DeSalvo, Director



# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed