

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2423
SCHOOL NAME: Revere School
ADDRESS OF SCHOOL: 1010 E. 72nd St.
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/26/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 239
IDPH INSPECTOR LICENSE NUMBER: 100-03613
IDPH LICENSED INSPECTOR NAME(Please Print): Daniel Juneau
IDPH MP LICENSE NUMBER: 100-01784
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Revere School

1010 E. 72nd St.
Chicago, IL, 60619

Unit: 25121
Building ID: 5610

IDPH ID Number: 14-016-2990-2423

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 24, 2019

RE: Revere School, Unit 25121
1010 E. 72nd St.
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Revere School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Revere School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Revere School Unit: 25121 Region: 05
Address: 1010 E. 72nd St. Chicago, IL, 60619
IDPH ID: 14-016-2990-2423 Building ID: 5610
Contact: Smith, Jimmie Phone: 312 523-6273

2. Description of Facility

Original Construction: 1939 Additional Construction: 1903,1962
Total Square Footage: 8072 No of Floors: 1
Current Occupancy: 239

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Daniel Juneau

Inspector IDPH license # 100-03613

Signature:
Date: 6/24/2019

6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784

Signature:
Date: 07/24/2019

7. Review Date:07/24/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Revere School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5610:

B. The following new homogenous areas have been identified for Building 5610:

39	Ceramic Flooring
40	Beige Terrazzo
41	Beige Terrazzo
42	12x12 Beige w/Streaks Floor Tile and Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

02	12x12 Beige Floor Tile
04	Hardcoat Plaster
09	12x12 Beige Floor Tile
10	Hardcoat Plaster
12	2x4 Ceiling Tile
13	Fire Doors
14	Fire Doors
16	12x12 Grey Floor Tile
18	12x12 Purple Floor Tile
19	12x12 Purple Floor Tile Mastic
20	12x12 Pink Floor Tile
23	12x12 Beige Floor Tile Mastic
24	12x12 Tan Floor Tile
26	12x12 Grey Floor Tile
39	Ceramic Flooring
40	Beige Terrazzo
41	Beige Terrazzo
42	12x12 Beige w/Streaks Floor Tile and Mastic
E	Univents
F	Concealed Boiler Insulation under Metal Jackets and Gaskets
J	Fiberglass Fittings
M	Aircell Duct Insulation
O	Duct Expansion Joint
Q	Duct Insulation Jacket
T	Aircell Pipe Insulation

The following areas were deemed to be inaccessible:

13	Fire Doors
14	Fire Doors
19	12x12 Purple Floor Tile Mastic
29	9x9 Brown Floor Tile Mastic
F	Concealed Boiler Insulation under Metal Jackets and Gaskets
H	Aircell Pipe Insulation
P	Pre-Form Pipe Insulation
Q	Duct Insulation Jacket
R	Aircell Joint Insulation
S	Preform Pipe Joint Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Daniel Juneau, IDPH License # 100-03613. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Revere School Building 5610 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	9x9 Floor Tile ABATED			1961 Building- Material Removed	ABATED	MISC								
02	12x12 Beige Floor Tile	15,000	SF	1961 Building- Classroom/Storage Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	Carpeting ABATED			1961 Building- Material Removed	ABATED	MISC								
04	Hardcoat Plaster	40,000	SF	1961 Building	ASSUMED	SURFACE	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
05	Old Spray-On Insulation ABATED			1961 Building	ABATED	MISC								
06	New Spray-On Ceiling Insulation			1961 Building	NO_ACBM	MISC								
07	Hardcoat Plaster			1938 Building- Gym	NO_ACBM	MISC		None						
08	9x9 Brown Floor Tile and Mastic	390	SF	1902 Building- Classroom 200 (formerly Teachers' Room)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12x12 Beige Floor Tile	10,000	SF	1902 Building- Throughout Classrooms, & Room 201	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Hardcoat Plaster	49,000	SF	1902 Building	ASSUMED	MISC	N	LOC	2		No	ACBM with the potential for damage		MODERATE
11	Canvas Wall Covering ABATED			1902 Building- Material Removed	ABATED	MISC								
12	2x4 Ceiling Tile	7,000	SF	1902 Building- Kitchen, and Throughout 1961 Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
13	Fire Doors	8	EA	1938 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Fire Doors	6	EA	1902 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Light Grey Floor Tile Mastic			1961 Building- Classrooms, Storage Rooms	NO_ACBM	MISC								
16	12x12 Grey Floor Tile	1,700	SF	1961 Building- Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Grey Floor Tile Mastic			1961 Building- Corridors	NO_ACBM	MISC		None						
18	12x12 Purple Floor Tile	360	SF	1961 Building- Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12x12 Purple Floor Tile Mastic	360	SF	1961 Building- Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	12x12 Pink Floor Tile	600	SF	1961 Building- Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12x12 Pink Floor Tile Mastic			1961 Building- Classrooms	NO_ACBM	MISC		None						
23	12x12 Beige Floor Tile Mastic	10,000	SF	1902 Building- Throughout Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	12x12 Tan Floor Tile	3,500	SF	1938 Building- Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12x12 Tan Floor Tile Mastic			1938 Building- Auditorium	NO_ACBM	MISC		None						
26	12x12 Grey Floor Tile	2,200	SF	1961 Building- Main Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Grey Floor Tile Mastic			1938 Building- Main Corridors	NO_ACBM	MISC		None						
28	9x9 Brown Floor Tile	150	SF	1938 Building- Gym Storage Room	CHR	MISC	N	LOC	0		No	ACBM with the potential for damage		LOW
29	9x9 Brown Floor Tile Mastic	150	SF	1938 Building- Gym Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Brown Carpet Mastic			1961 Building- Main Office Area, Room 219 & Room 221D	NO_ACBM	MISC		None						
31	Purple Carpet Mastic			1961 Building- 1st Floor Classrooms	NO_ACBM	MISC		None						
32	Drywall			1902 Building- Pump Room and Corridors	NO_ACBM	MISC		None						
33	Drywall Compound			1902 Building- Pump Room	NO_ACBM	MISC		None						
34	Drywall			1938 Building- Main Corridor	NO_ACBM	MISC		None						
36	Stucco Ceiling Plaster			Main Corridor	NO_ACBM	MISC								
37	Stucco Ceiling Plaster			1902 Building- Corridors & Classrooms	NO_ACBM	MISC		None						
38	Transite Table Tops			1902 Building- Classroom 203	NO_ACBM	MISC		None						
39	Ceramic Flooring			1961 Building- Student Bathrooms and Entry Vestibule by Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Beige Terrazzo	800	SF	1961 Building- Stairwells, Gym Entry/Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
41	Beige Terrazzo	500	SF	1902 Building-Basement Serving Area, Lunchroom Manager's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 Beige w/Streaks Floor Tile and Mastic	180	SF	1902 Building-Basement Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Fiberglass Duct Wrap			1961 Building-Mechanical Room	NOT_TEST ED	TSI		None						Low
B	Duct Expansion Joint			1961 Building-Mechanical Room	NO_ACBM	TSI		None						
C	Fiberglass Insulation				NOT_TEST ED	TSI								
E	Univents	38	EA	1961 Building	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
F	Concealed Boiler Insulation under Metal Jackets and Gaskets	600	SF	1902 Building-Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
G	Tank Insulation ABATED			1902 Building-Pump Room	ABATED	TSI								
H	Aircell Pipe Insulation	100	LF	1902 Building- Fan Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Fiberglass Insulation			1902 Building-Pump Room	NOT_TEST ED	TSI								
J	Fiberglass Fittings	50	JOINTS	1902 Building - Basement B20 Fan Room	ASSUMED	TSI	Y	LOC	2		No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Cardboard Insulation ABATED			1902 Building-Boiler Room	ABATED	TSI								
L	Cardboard Joint Insulation ABATED			1902 Building	ABATED	TSI								
M	Aircell Duct Insulation	150	SF	1902 Building- Fan Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
N	Hot Water Tank Insulation ABATED			1902 Building- Tank Room	ABATED	TSI								
O	Duct Expansion Joint	300	SF	1902 Building- Fan Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
P	Pre-Form Pipe Insulation	75	LF	Coal Room- 02	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Duct Insulation Jacket	300	LF	Crawlspace below Auditorium Stage	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
R	Aircell Joint Insulation	7	LF	1902 Building-Boiler/Pump Room	CHR	TSI	Y	LOC	1		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
S	Preform Pipe Joint Insulation	10	LF	1902 Building- Coal Room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
T	Aircell Pipe Insulation	40	LF	1902 Building - Pump Room, B19B Storage, Basement Hall	ASSUMED	TSI	Y	LOC	15		No	Damaged or significantly damaged friable thermal system insulating ACBM		LOW

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 6/24/2019
Inspector Name Daniel Juneau
100-03613 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	Room ID changed to 200. Mastic added
09	
10	2 SF of Damage in Basement Electrical Room
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
23	
24	

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
25	
26	
27	
28	3 - 4 missing tiles in Gym Storage
29	
30	Carpet also in 219 & 221D
31	
32	
33	
34	
36	
37	
38	
39	
40	
41	
42	
A	Not A Suspect Material
B	
C	Not A Suspect Material
E	
F	
G	
H	
I	Not A Suspect Material
J	1 Damaged Elbow Basement Engine Room, North Cal Piping- 2 in Control Room at Heat Exchange
K	
L	

Chicago Public Schools

School Revere School Unit 25121 Building ID 5610

Address 1010 E. 72nd St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
M	
N	
O	
P	
Q	Aircell Duct IM beneath Fiberglass Overwrap. Damaged, Restrict Access
R	1 Damaged fitting- B19B
S	
T	15 LF of Damage in Crawlspace

Table II

Management Planner's Review

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	9x9 Floor Tile ABATED			1961 Building- Material Removed	Abated	MISC					
02	12x12 Beige Floor Tile	15,000	SF	1961 Building- Classroom/Storage Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Carpeting ABATED			1961 Building- Material Removed	Abated	MISC					
04	Hardcoat Plaster	40,000	SF	1961 Building	Assumed	SURFACE	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	Old Spray-On Insulation ABATED			1961 Building	Abated	MISC					
06	New Spray-On Ceiling Insulation			1961 Building	No ACBM	MISC					
07	Hardcoat Plaster			1938 Building- Gym	No ACBM	MISC					
08	9x9 Brown Floor Tile and Mastic	390	SF	1902 Building- Classroom 200 (formerly Teachers' Room)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 Beige Floor Tile	10,000	SF	1902 Building- Throughout Classrooms, & Room 201	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Hardcoat Plaster	49,000	SF	1902 Building	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Canvas Wall Covering ABATED			1902 Building- Material Removed	Abated	MISC					
12	2x4 Ceiling Tile	7,000	SF	1902 Building- Kitchen, and Throughout 1961 Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	Fire Doors	8	EA	1938 Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
14	Fire Doors	6	EA	1902 Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
15	Light Grey Floor Tile Mastic			1961 Building- Classrooms, Storage Rooms	No ACBM	MISC					
16	12x12 Grey Floor Tile	1,700	SF	1961 Building- Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Grey Floor Tile Mastic			1961 Building- Corridors	No ACBM	MISC					
18	12x12 Purple Floor Tile	360	SF	1961 Building- Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12x12 Purple Floor Tile Mastic	360	SF	1961 Building- Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12x12 Pink Floor Tile	600	SF	1961 Building- Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12x12 Pink Floor Tile Mastic			1961 Building- Classrooms	No ACBM	MISC					
23	12x12 Beige Floor Tile Mastic	10,000	SF	1902 Building- Throughout Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Tan Floor Tile	3,500	SF	1938 Building- Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 Tan Floor Tile Mastic			1938 Building- Auditorium	No ACBM	MISC					
26	12x12 Grey Floor Tile	2,200	SF	1961 Building- Main Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Grey Floor Tile Mastic			1938 Building- Main Corridors	No ACBM	MISC					
28	9x9 Brown Floor Tile	150	SF	1938 Building- Gym Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9x9 Brown Floor Tile Mastic	150	SF	1938 Building- Gym Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	Brown Carpet Mastic			1961 Building- Main Office Area, Room 219 & Room 221D	No ACBM	MISC					
31	Purple Carpet Mastic			1961 Building- 1st Floor Classrooms	No ACBM	MISC					
32	Drywall			1902 Building- Pump Room and Corridors	No ACBM	MISC					
33	Drywall Compound			1902 Building- Pump Room	No ACBM	MISC					
34	Drywall			1938 Building- Main Corridor	No ACBM	MISC					
36	Stucco Ceiling Plaster			Main Corridor	No ACBM	MISC					
37	Stucco Ceiling Plaster			1902 Building- Corridors & Classrooms	No ACBM	MISC					
38	Transite Table Tops			1902 Building- Classroom 203	No ACBM	MISC					
39	Ceramic Flooring			1961 Building- Student Bathrooms and Entry Vestibule by Gym	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
40	Beige Terrazzo	800	SF	1961 Building- Stairwells, Gym Entry/Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Beige Terrazzo	500	SF	1902 Building- Basement Serving Area, Lunchroom Manager's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Beige w/Streaks Floor Tile and Mastic	180	SF	1902 Building- Basement Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Fiberglass Duct Wrap			1961 Building- Mechanical Room	Not Tested	TSI					
B	Duct Expansion Joint			1961 Building- Mechanical Room	No ACBM	TSI					
C	Fiberglass Insulation				Not Tested	TSI					
E	Univents	38	EA	1961 Building	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
F	Concealed Boiler Insulation under Metal Jackets and Gaskets	600	SF	1902 Building- Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G	Tank Insulation ABATED			1902 Building- Pump Room	Abated	TSI					
H	Aircell Pipe Insulation	100	LF	1902 Building- Fan Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Fiberglass Insulation			1902 Building- Pump Room	Not Tested	TSI					
J	Fiberglass Fittings	50	JOINTS	1902 Building - Basement B20 Fan Room	Assumed	TSI	Yes	2	JOINTS	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Cardboard Insulation ABATED			1902 Building- Boiler Room	Abated	TSI					
L	Cardboard Joint Insulation ABATED			1902 Building	Abated	TSI					
M	Aircell Duct Insulation	150	SF	1902 Building- Fan Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
 Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
N	Hot Water Tank Insulation ABATED			1902 Building- Tank Room	Abated	TSI					
O	Duct Expansion Joint	300	SF	1902 Building- Fan Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P	Pre-Form Pipe Insulation	75	LF	Coal Room- 02	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Duct Insulation Jacket	300	LF	Crawlspace below Auditorium Stage	Assumed	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Aircell Joint Insulation	7	LF	1902 Building- Boiler/Pump Room	Chrysotile	TSI	Yes	1	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Preform Pipe Joint Insulation	10	LF	1902 Building- Coal Room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T	Aircell Pipe Insulation	40	LF	1902 Building - Pump Room, B19B Storage, Basement Hall	Assumed	TSI	Yes	15	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
 Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	07/24/2019
Manager Planner Name	Steven Geneser
100-01784	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	Repair Damage
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
23	
24	

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
 Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
27	
28	Replace Missing Tiles in Gym Storage Room
29	
30	
31	
32	
33	
34	
36	
37	
38	
39	
40	
41	
42	
A	
B	
C	
E	
F	
G	
H	
I	
J	Repair Damaged Elbows

Chicago Public Schools

School Revere School
Address 1010 E. 72nd St.

Unit 25121
Chicago, IL, 60619

Building ID 5610
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
K	
L	
M	
N	
O	
P	
Q	Remove Aircell Duct
R	Repair Damaged Fitting
S	
T	Repair Damage in Crawlspace

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Material Removed**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED**

MATERIAL LOCATION: **1961 Building- Material Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Classroom/Storage Rooms**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
MATERIAL LOCATION: **1961 Building- Classroom/Storage Rooms**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **Carpeting ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Material Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Carpeting ABATED**

MATERIAL LOCATION: **1961 Building- Material Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **1961 Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Old Spray-On Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Old Spray-On Insulation ABATED**

MATERIAL LOCATION: **1961 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **New Spray-On Ceiling Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **New Spray-On Ceiling Insulation**

MATERIAL LOCATION: **1961 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **1938 Building- Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Classroom 200 (formerly Teachers' Room)**
MATERIAL QUANTITY: **390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Room ID changed to 200. Mastic added**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile and Mastic**
MATERIAL LOCATION: **1902 Building- Classroom 200 (formerly Teachers' Room)**
MATERIAL QUANTITY: **390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Throughout Classrooms, & Room 201**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**
MATERIAL LOCATION: **1902 Building- Throughout Classrooms, & Room 201**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1902 Building**
MATERIAL QUANTITY: **49000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS: **2 SF of Damage in Basement Electrical Room**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **1902 Building**
MATERIAL QUANTITY: **49000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:
Repair Damage

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Canvas Wall Covering ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Material Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Canvas Wall Covering ABATED**

MATERIAL LOCATION: **1902 Building- Material Removed**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Kitchen, and Throughout 1961 Building**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**
MATERIAL LOCATION: **1902 Building- Kitchen, and Throughout 1961 Building**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **1938 Building**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **1902 Building**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Light Grey Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **1961 Building- Classrooms, Storage Rooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Light Grey Floor Tile Mastic**

MATERIAL LOCATION: **1961 Building- Classrooms, Storage Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**

MATERIAL LOCATION: **1961 Building- Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12x12 Purple Floor Tile Mastic**
MATERIAL LOCATION: **1961 Building- Corridors**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 Pink Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Classrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12x12 Pink Floor Tile**
MATERIAL LOCATION: **1961 Building- Classrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12x12 Pink Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12x12 Pink Floor Tile Mastic**

MATERIAL LOCATION: **1961 Building- Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Throughout Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**
MATERIAL LOCATION: **1902 Building- Throughout Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building- Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**
MATERIAL LOCATION: **1938 Building- Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**

MATERIAL LOCATION: **1938 Building- Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building- Main Corridor**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**
MATERIAL LOCATION: **1961 Building- Main Corridor**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Main Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**

MATERIAL LOCATION: **1938 Building- Main Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building- Gym Storage Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **3 - 4 missing tiles in Gym Storage**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
MATERIAL LOCATION: **1938 Building- Gym Storage Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Replace Missing Tiles in Gym Storage Room

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1938 Building- Gym Storage Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**
MATERIAL LOCATION: **1938 Building- Gym Storage Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Main Office Area, Room 219 & Room 221D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Carpet also in 219 & 221D**

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **1961 Building- Main Office Area, Room 219 & Room 221D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- 1st Floor Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **1961 Building- 1st Floor Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Pump Room and Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1902 Building- Pump Room and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1938 Building- Main Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1938 Building- Main Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**

MATERIAL LOCATION: **Main Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Corridors & Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**

MATERIAL LOCATION: **1902 Building- Corridors & Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Transite Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **1902 Building- Classroom 203**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Transite Table Tops**

MATERIAL LOCATION: **1902 Building- Classroom 203**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Duct Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1961 Building- Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not A Suspect Material**

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Duct Wrap**

MATERIAL LOCATION: **1961 Building- Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Duct Expansion Joint**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1961 Building- Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Duct Expansion Joint**
MATERIAL LOCATION: **1961 Building- Mechanical Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not A Suspect Material**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fiberglass Insulation**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Univents**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1961 Building**
MATERIAL QUANTITY: **38** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Univents**
MATERIAL LOCATION: **1961 Building**
MATERIAL QUANTITY: **38** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Concealed Boiler Insulation under Metal Jackets and Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Boiler Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Concealed Boiler Insulation under Metal Jackets and Gaskets**
MATERIAL LOCATION: **1902 Building- Boiler Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Tank Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not A Suspect Material**

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Fiberglass Insulation**

MATERIAL LOCATION: **1902 Building- Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Fiberglass Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building - Basement B20 Fan Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **JOINTS**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **JOINTS**

COMMENTS: **1 Damaged Elbow Basement Engine Room, North Cal Piping- 2 in Control Room at Heat Exchange**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Fiberglass Fittings**
MATERIAL LOCATION: **1902 Building - Basement B20 Fan Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **JOINTS**
DAMAGE QUANTITY: **2** DAMAGE UNITS: **JOINTS**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged Elbows

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Cardboard Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Cardboard Insulation ABATED**

MATERIAL LOCATION: **1902 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Cardboard Joint Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Cardboard Joint Insulation ABATED**

MATERIAL LOCATION: **1902 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Hot Water Tank Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 Building- Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Hot Water Tank Insulation ABATED**

MATERIAL LOCATION: **1902 Building- Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Duct Expansion Joint**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Duct Expansion Joint**
MATERIAL LOCATION: **1902 Building- Fan Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Coal Room- 02**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation**
MATERIAL LOCATION: **Coal Room- 02**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Duct Insulation Jacket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Crawlspace below Auditorium Stage**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Aircell Duct IM beneath Fiberglass Overwrap. Damaged, Restrict Access**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Duct Insulation Jacket**
MATERIAL LOCATION: **Crawlspace below Auditorium Stage**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove Aircell Duct

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Aircell Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Boiler/Pump Room**
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**
COMMENTS: **1 Damaged fitting- B19B**

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **Aircell Joint Insulation**
MATERIAL LOCATION: **1902 Building- Boiler/Pump Room**
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damaged Fitting

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Preform Pipe Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902 Building- Coal Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 06/24/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Preform Pipe Joint Insulation**
MATERIAL LOCATION: **1902 Building- Coal Room**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1902 Building - Pump Room, B19B Storage, Basement Hall**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

COMMENTS: **15 LF of Damage in Crawlspace**

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUIDLING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **1902 Building - Pump Room, B19B Storage, Basement Hall**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair Damage in Crawlspace

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Beige Terrazzo**
MATERIAL LOCATION: **1961 Building- Stairwells, Gym Entry/Foyer**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Beige Terrazzo**
MATERIAL LOCATION: **1961 Building- Stairwells, Gym Entry/Foyer**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Ceramic Flooring**
MATERIAL LOCATION: **1961 Building- Student Bathrooms and Entry Vestibule by Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Ceramic Flooring**
MATERIAL LOCATION: **1961 Building- Student Bathrooms and Entry Vestibule by Gym**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Beige Terrazzo**
MATERIAL LOCATION: **1902 Building- Basement Serving Area, Lunchroom Manager's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Beige Terrazzo**
MATERIAL LOCATION: **1902 Building- Basement Serving Area, Lunchroom Manager's Office**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **07/24/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Revere School** INSPECTION DATE: **6/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12x12 Beige w/Streaks Floor Tile and Mastic**
MATERIAL LOCATION: **1902 Building- Basement Engineer's Office**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **06/24/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25121** BUILDING ID: **5610**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Revere School** REVIEW DATE: **7/24/2019**
ADDRESS: **1010 E. 72nd St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12x12 Beige w/Streaks Floor Tile and Mastic**
MATERIAL LOCATION: **1902 Building- Basement Engineer's Office**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **07/24/2019**

APPENDIX B

Inspector and Management Planner Licenses

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: BIR1811203167

Kathy DeSalvo, Director

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: MPR1811203186



Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
4/17/2019

EXPIRES
05/15/2020

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016
Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/20/2019

MANAGEMENT PLANNER

11/20/2019

PROJECT MANAGER

11/6/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed