

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2428  
SCHOOL NAME: Ruggles School  
ADDRESS OF SCHOOL: 7831 S. Prairie  
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 413  
IDPH INSPECTOR LICENSE NUMBER: 100-09106  
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier  
IDPH MP LICENSE NUMBER: 100-00746  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Ruggles School**

7831 S. Prairie  
Chicago, IL, 60619

Unit: 25181  
Building ID: 5660

IDPH ID Number: 14-016-2990-2428

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 25, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                  Unit: 25181                  Region: 05                  IDPH ID:14-016-2990-2428

School: Ruggles School                  Building ID: 5660

Address: 7831 S. Prairie  
Chicago, IL, 60619

Building Contact: Jackson, David                  Contact Phone:1-773-359-7447

Current Building Owners: Chicago Public Schools

Review Date: 10/24/2019

Inspector: Michael Hasier                  Inspector IDPH License: 100-09106  
Management Planner: Amy Williams                  Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Amy Williams  
100-00746

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 25, 2019

RE: Ruggles School, Unit 25181  
7831 S. Prairie  
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Ruggles School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Ruggles School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Ruggles School Unit: 25181 Region: 05  
Address: 7831 S. Prairie Chicago, IL, 60619  
IDPH ID: 14-016-2990-2428 Building ID: 5660  
Contact: Jackson, David Phone: 1-773-359-7447

### 2. Description of Facility

Original Construction: 1925 Additional Construction: 1956  
Total Square Footage: 88210 No of Floors: 2  
Current Occupancy: 413

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:  
Date: 9/25/2019

### 6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:  
Date: 10/24/2019

### 7. Review Date: 10/24/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ruggles School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5660:

23	Fire Brick Mortar
45	Ceiling Plaster

B. The following new homogenous areas have been identified for Building 5660:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

12	12" Light Brown Floor Tile
13	12" Blue Floor Tile
15	12" Gray Floor Tile
16	Duct Jacket
16A	9 x 9 Brown/Orange Floor Tile Mastic - Not Observed
18	Baseboard
19	Baseboard Mastic
20	Baseboard
21	Baseboard Mastic
22	Insulation on Incinerator Door
23	Fire Brick Mortar
24	Fire Door
25	12" Beige Floor Tile
26	12" Beige Floor Tile Mastic
27	12" Beige Floor Tile
31	12" Blue Floor Tile Mastic
34	12" Light Brown Floor Tile
35	12" Light Brown Floor Tile Mastic
36	12" Brown Floor Tile
38	Dark Blue Carpet Mastic
39	Beige Linoleum
40	Beige Linoleum Mastic
41	Blue Carpet Mastic - Not Observed
42	2' Tectum Ceiling Tiles
43	12x12 Black and White Floor Tile - Not Observed
44	2x4 Ceiling Tiles
45	Ceiling Plaster
46	12x12 Beige Floor Tile
47	12"x12" Red w/Dark Streaks Vinyl Floor Tile
47A	12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic
48	12"x12" Black and Green Vinyl Floor Tile
48A	12"x12" Black and Green Vinyl Floor Tile Mastic
49	12"x12" Off-White Vinyl Floor Tile
49A	12"x12" Off-White Vinyl Floor Tile Mastic
50	Red Multicolor Carpet Mastic
O	Pre-form Pipe Insulation
S	Fittings on Pre-form Insulation
T	Boiler Gasket
U	White Coating on Bottom of Sink
V	Black Coating on Bottom of Sink

The following areas were deemed to be inaccessible:

19	Baseboard Mastic
21	Baseboard Mastic
22	Insulation on Incinerator Door
23	Fire Brick Mortar
24	Fire Door
26	12" Beige Floor Tile Mastic
28	12" Beige Floor Tile Mastic
29	9" Tan Floor Tile Mastic
30	12" Light Brown Floor Tile Mastic
31	12" Blue Floor Tile Mastic
32	12" Tan Floor Tile Mastic
33	12" Gray Floor Tile Mastic
35	12" Light Brown Floor Tile Mastic
37	12" Brown Floor Tile Mastic
38	Dark Blue Carpet Mastic
40	Beige Linoleum Mastic
47A	12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic
48A	12"x12" Black and Green Vinyl Floor Tile Mastic
49A	12"x12" Off-White Vinyl Floor Tile Mastic
50	Red Multicolor Carpet Mastic
C	Paperwrap Pipe Insulation
D	Fittings on Paperwrap Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	8/21/2018
	8/21/2018
	7/8/2019
	7/8/2019

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Ruggles School Building 5660 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05B	9 x 9 White Floor Tile Streaked VAT ABATED			1963 Building- Main Office, Principal's Office, Nurse's Toilet	ABATED	MISC								
11	9" Tan Floor Tile	150	SF	1956 Building- Storage Room and Closet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12" Light Brown Floor Tile	50	SF	1956 Building- Northeast Corridor, 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12" Blue Floor Tile	750	SF	Pre-Kindergarten- Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12" Tan Floor Tile	420	SF	1956 Building- 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12" Gray Floor Tile	3,000	SF	1956 Building- Room 201, 202, 203, 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Duct Jacket	300	SF	1926 Building- North Section Basement	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
16A	9 x 9 Brown/Orange Floor Tile Mastic - Not Observed			1926 Building- Room 205	ASSUMED	MISC								
18	Baseboard	560	LF	1926 Building- Rooms 211, 213, and 2nd Floor Teachers' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Baseboard Mastic	560	LF	1926 Building- Rooms 211, 213 and 2nd floor Teachers' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Baseboard	660	LF	Rooms 200, 202, 203 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Baseboard Mastic	660	LF	Room 200, 202, 203 & 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Insulation on Incinerator Door	10	SF	1926 Building- Boiler Room (Door Welded Shut)	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
23	Fire Brick Mortar	240	SF	1926 Building- Boiler Room	ASSUMED	TSI	N	NONE	0		Yes	ACBM with the potential for damage		LOW
24	Fire Door	2	SF	Boiler Room Tunnel	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12" Beige Floor Tile	1,320	SF	1924 Building- 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12" Beige Floor Tile Mastic	1,320	SF	1926 Building- 2nd	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor								potential for damage		
27	12" Beige Floor Tile	1,150	SF	1956 Building- 1st Floor Corridor and Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12" Beige Floor Tile Mastic	1,150	SF	1956 Building- 1st Floor Corridor and Room 200	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	9" Tan Floor Tile Mastic	150	SF	1956 Building- Kitchen Office and Storeroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12" Light Brown Floor Tile Mastic	50	LF	1956 Building- 1st Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12" Blue Floor Tile Mastic	750	SF	1956 Building- Kindergarten Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12" Tan Floor Tile Mastic	420	SF	1956 Building- 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12" Gray Floor Tile Mastic	3,000	SF	1956 Building- Rooms 201, 202, 203, 204	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12" Light Brown Floor Tile	270	SF	1926 Building- 1st and 2nd Floors, Southwest Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12" Light Brown Floor Tile Mastic	270	SF	1926 Building- 1st and 2nd Floor Southwest Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" Brown Floor Tile	1,000	SF	1926 Building- Room 216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	12" Brown Floor Tile Mastic	1,000	SF	1926 Building- Room 216	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Dark Blue Carpet Mastic	750	SF	1956 Building- Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Beige Linoleum	40	SF	1956 Building- Room 101, Storeroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Beige Linoleum Mastic	40	SF	Building 1956- Room 101, Storeroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Blue Carpet Mastic - Not Observed			1926 Building- 1st & 2nd Floor Classrooms	ASSUMED	MISC								
42	2' Tectum Ceiling Tiles	1,800	SF	1926 Building- Gymnasium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12x12 Black and White Floor Tile - Not			1956 Building-	ASSUMED	MISC		NONE						LOW

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Observed			Storage Room and Closet										
44	2x4 Ceiling Tiles	75,000	SF	1924 Building-Throughout	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
45	Ceiling Plaster	80,000	SF	1956 Building- All 2nd Floor	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
46	12x12 Beige Floor Tile	750	SF	1956 Building-Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12"x12" Red w/Dark Streaks Vinyl Floor Tile	600	SF	Room 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47A	12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic	600	SF	Room 109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12"x12" Black and Green Vinyl Floor Tile	100	SF	Lunchroom Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48A	12"x12" Black and Green Vinyl Floor Tile Mastic	100	SF	Lunchroom Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12"x12" Off-White Vinyl Floor Tile	100	SF	Lunchroom Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49A	12"x12" Off-White Vinyl Floor Tile Mastic	100	SF	Lunchroom Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Red Multicolor Carpet Mastic	100	SF	Principal's Office, Office in Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Paperwrap Pipe Insulation	153	LF	1926 Building-Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway	CHR	TSI	Y	DIST	8		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D	Fittings on Paperwrap Insulation	18	EA	1926 Building-Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Tank Insulation- ABATED			1926 Building-Boiler Room	ABATED	TSI								
F	Tank Packing- ABATED			1926 Building-Boiler Room	ABATED	TSI								
J	Aircell Pipe Insulation	600	LF	1926 Building-Throughout Building, Air Plenums (Not Decks), and	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Unexcavated Areas										
O	Pre-form Pipe Insulation	100	LF	1926 Building-Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Aircell Pipe Insulation	400	LF	Throughout Building & Unexcavated Areas	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Fittings Aircell	90	LF	Throughout Building & Unexcavated Areas	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
R	Fittings on Aircell	40	LF	1956 Building-Throughout Building & Unexcavated Area	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
S	Fittings on Pre-form Insulation	10	LF	1926 Building-Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
T	Boiler Gasket	25	LF	1926 Building-Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
U	White Coating on Bottom of Sink	40	SF	Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
V	Black Coating on Bottom of Sink	40	SF	Room 204	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/25/2019</b>
Inspector Name <b>Michael Hasier</b>
<b>100-09106</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
05B	
11	
12	
13	
14	
15	
16	
16A	Not Observed 2019- Now Wood Floor
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
47A	
48	
48A	
49	
49A	
50	
C	
D	
E	
F	
J	300 LF hot water pipe abated from Boiler Rm to 1956 RR's in 2018; debris clean up
O	
P	Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partially HA P; debris & soil clean up

# Chicago Public Schools

School Ruggles School Unit 25181 Building ID 5660

Address 7831 S. Prairie Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
Q	Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partial abatement & debris & soil clean up
R	Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partial abatement
S	
T	
U	
V	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05B	9 x 9 White Floor Tile Streaked VAT ABATED			1963 Building- Main Office, Principal's Office, Nurse's Toilet	Abated	MISC					
11	9" Tan Floor Tile	150	SF	1956 Building- Storage Room and Closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" Light Brown Floor Tile	50	SF	1956 Building- Northeast Corridor, 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12" Blue Floor Tile	750	SF	Pre-Kindergarten- Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12" Tan Floor Tile	420	SF	1956 Building- 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" Gray Floor Tile	3,000	SF	1956 Building- Room 201, 202, 203, 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Duct Jacket	300	SF	1926 Building- North Section Basement	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
16A	9 x 9 Brown/Orange Floor Tile Mastic - Not Observed			1926 Building- Room 205	Assumed	MISC					
18	Baseboard	560	LF	1926 Building- Rooms 211, 213, and 2nd Floor Teachers' Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Baseboard Mastic	560	LF	1926 Building- Rooms 211, 213 and 2nd floor Teachers' Restroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Baseboard	660	LF	Rooms 200, 202, 203 & 204	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21	Baseboard Mastic	660	LF	Room 200, 202, 203 & 204	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Insulation on Incinerator Door	10	SF	1926 Building- Boiler Room (Door Welded Shut)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
23	Fire Brick Mortar	240	SF	1926 Building- Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Fire Door	2	SF	Boiler Room Tunnel	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" Beige Floor Tile	1,320	SF	1924 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" Beige Floor Tile Mastic	1,320	SF	1926 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" Beige Floor Tile	1,150	SF	1956 Building- 1st Floor Corridor and Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" Beige Floor Tile Mastic	1,150	SF	1956 Building- 1st Floor Corridor and Room 200	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	9" Tan Floor Tile Mastic	150	SF	1956 Building- Kitchen Office and Storeroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" Light Brown Floor Tile Mastic	50	LF	1956 Building- 1st Floor Corridor	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" Blue Floor Tile Mastic	750	SF	1956 Building- Kindergarten Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12" Tan Floor Tile Mastic	420	SF	1956 Building- 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" Gray Floor Tile Mastic	3,000	SF	1956 Building- Rooms 201, 202, 203, 204	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" Light Brown Floor Tile	270	SF	1926 Building- 1st and 2nd Floors, Southwest Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" Light Brown Floor Tile Mastic	270	SF	1926 Building- 1st and 2nd Floor Southwest Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" Brown Floor Tile	1,000	SF	1926 Building- Room 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" Brown Floor Tile Mastic	1,000	SF	1926 Building- Room 216	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Dark Blue Carpet Mastic	750	SF	1956 Building- Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Beige Linoleum	40	SF	1956 Building- Room 101, Storeroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Beige Linoleum Mastic	40	SF	Building 1956- Room 101, Storeroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Blue Carpet Mastic - Not Observed			1926 Building- 1st & 2nd Floor Classrooms	Assumed	MISC					
42	2' Tectum Ceiling Tiles	1,800	SF	1926 Building- Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Black and White Floor Tile - Not Observed			1956 Building- Storage Room and Closet	Assumed	MISC					
44	2x4 Ceiling Tiles	75,000	SF	1924 Building- Throughout	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
45	Ceiling Plaster	80,000	SF	1956 Building- All 2nd Floor	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Beige Floor Tile	750	SF	1956 Building- Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12"x12" Red w/Dark Streaks Vinyl Floor Tile	600	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic	600	SF	Room 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" Black and Green Vinyl Floor Tile	100	SF	Lunchroom Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	12"x12" Black and Green Vinyl Floor Tile Mastic	100	SF	Lunchroom Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"x12" Off-White Vinyl Floor Tile	100	SF	Lunchroom Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	12"x12" Off-White Vinyl Floor Tile Mastic	100	SF	Lunchroom Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Red Multicolor Carpet Mastic	100	SF	Principal's Office, Office in Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Paperwrap Pipe Insulation	153	LF	1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway	Chrysotile	TSI	Yes	8	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D	Fittings on Paperwrap Insulation	18	EA	1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever	Chrysotile	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
 Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Tunnel Walkway							
E	Tank Insulation- ABATED			1926 Building- Boiler Room	Abated	TSI					
F	Tank Packing- ABATED			1926 Building- Boiler Room	Abated	TSI					
J	Aircell Pipe Insulation	600	LF	1926 Building- Throughout Building, Air Plenums (Not Decks), and Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Pre-form Pipe Insulation	100	LF	1926 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Aircell Pipe Insulation	400	LF	Throughout Building & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Fittings Aircell	90	LF	Throughout Building & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
R	Fittings on Aircell	40	LF	1956 Building- Throughout Building & Unexcavated Area	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Fittings on Pre-form Insulation	10	LF	1926 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
T	Boiler Gasket	25	LF	1926 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	White Coating on Bottom of Sink	40	SF	Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
V	Black Coating on Bottom of Sink	40	SF	Room 204	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
 Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/24/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
05B	
11	
12	
13	
14	
15	
16	
16A	
18	
19	
20	
21	
22	
23	
24	
25	
26	



# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
 Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
47A	
48	
48A	
49	
49A	

# Chicago Public Schools

**School** Ruggles School  
**Address** 7831 S. Prairie

**Unit** 25181  
Chicago, IL, 60619

**Building ID** 5660  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
50	
C	
D	
E	
F	
J	
O	
P	
Q	
R	
S	
T	
U	
V	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **9 x 9 White Floor Tile Streaked VAT ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1963 Building- Main Office, Principal's Office, Nurse's Toilet**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **05B**  
MATERIAL DESCRIPTION: **9 x 9 White Floor Tile Streaked VAT ABATED**  
MATERIAL LOCATION: **1963 Building- Main Office, Principal's Office, Nurse's Toilet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Storage Room and Closet**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **9" Tan Floor Tile**  
MATERIAL LOCATION: **1956 Building- Storage Room and Closet**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Northeast Corridor, 1st Floor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile**  
MATERIAL LOCATION: **1956 Building- Northeast Corridor, 1st Floor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Pre-Kindergarten- Room 101**  
MATERIAL QUANTITY: **750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12" Blue Floor Tile**  
MATERIAL LOCATION: **Pre-Kindergarten- Room 101**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile**  
MATERIAL LOCATION: **1956 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12" Gray Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Room 201, 202, 203, 204**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **12" Gray Floor Tile**  
MATERIAL LOCATION: **1956 Building- Room 201, 202, 203, 204**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Duct Jacket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- North Section Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Duct Jacket**  
MATERIAL LOCATION: **1926 Building- North Section Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **9 x 9 Brown/Orange Floor Tile Mastic - Not Observed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Now Wood Floor**

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **9 x 9 Brown/Orange Floor Tile Mastic - Not Observed**

MATERIAL LOCATION: **1926 Building- Room 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Rooms 211, 213, and 2nd Floor Teachers' Restroom**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **1926 Building- Rooms 211, 213, and 2nd Floor Teachers' Restroom**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Rooms 211, 213 and 2nd floor Teachers' Restroom**  
MATERIAL QUANTITY: **560**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **1926 Building- Rooms 211, 213 and 2nd floor Teachers' Restroom**  
MATERIAL QUANTITY: **560** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 200, 202, 203 & 204**  
MATERIAL QUANTITY: **660**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Rooms 200, 202, 203 & 204**  
MATERIAL QUANTITY: **660** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 200, 202, 203 & 204**  
MATERIAL QUANTITY: **660** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Baseboard Mastic**  
MATERIAL LOCATION: **Room 200, 202, 203 & 204**  
MATERIAL QUANTITY: **660** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Insulation on Incinerator Door**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room (Door Welded Shut)**  
MATERIAL QUANTITY: **10**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Insulation on Incinerator Door**  
MATERIAL LOCATION: **1926 Building- Boiler Room (Door Welded Shut)**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Fire Brick Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Fire Brick Mortar**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Fire Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room Tunnel**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Fire Door**  
MATERIAL LOCATION: **Boiler Room Tunnel**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1924 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
MATERIAL LOCATION: **1924 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1926 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor and Room 200**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor and Room 200**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor and Room 200**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor and Room 200**  
MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Kitchen Office and Storeroom**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- Kitchen Office and Storeroom**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- 1st Floor Corridor**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Kindergarten Room 101**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" Blue Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- Kindergarten Room 101**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12" Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" Gray Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Rooms 201, 202, 203, 204**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" Gray Floor Tile Mastic**  
MATERIAL LOCATION: **1956 Building- Rooms 201, 202, 203, 204**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- 1st and 2nd Floors, Southwest Corridor**  
MATERIAL QUANTITY: **270**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile**  
MATERIAL LOCATION: **1926 Building- 1st and 2nd Floors, Southwest Corridor**  
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- 1st and 2nd Floor Southwest Corridor**  
MATERIAL QUANTITY: **270**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12" Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1926 Building- 1st and 2nd Floor Southwest Corridor**  
MATERIAL QUANTITY: **270** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **12" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Dark Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Room 101**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Dark Blue Carpet Mastic**  
MATERIAL LOCATION: **1956 Building- Room 101**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Room 101, Storeroom**  
MATERIAL QUANTITY: **40**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
MATERIAL LOCATION: **1956 Building- Room 101, Storeroom**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building 1956- Room 101, Storeroom**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Beige Linoleum Mastic**  
MATERIAL LOCATION: **Building 1956- Room 101, Storeroom**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic - Not Observed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **1926 Building- 1st & 2nd Floor Classrooms**  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Blue Carpet Mastic - Not Observed**

MATERIAL LOCATION: **1926 Building- 1st & 2nd Floor Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUILDING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **2' Tectum Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Gymnasium**  
MATERIAL QUANTITY: **1800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **2' Tectum Ceiling Tiles**  
MATERIAL LOCATION: **1926 Building- Gymnasium**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Black and White Floor Tile - Not Observed**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1956 Building- Storage Room and Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12x12 Black and White Floor Tile - Not Observed**

MATERIAL LOCATION: **1956 Building- Storage Room and Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **2x4 Celiing Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1924 Building- Throughout**  
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **2x4 Celiing Tiles**  
MATERIAL LOCATION: **1924 Building- Throughout**  
MATERIAL QUANTITY: **75000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Ceiling Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- All 2nd Floor**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Ceiling Plaster**  
MATERIAL LOCATION: **1956 Building- All 2nd Floor**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Room 200**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1956 Building- Room 200**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12"x12" Red w/Dark Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **12"x12" Red w/Dark Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **12"x12" Red w/Dark Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 109**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Black and Green Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **12"x12" Black and Green Vinyl Floor Tile**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12"x12" Black and Green Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **12"x12" Black and Green Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12"x12" Off-White Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **12"x12" Off-White Vinyl Floor Tile**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **12"x12" Off-White Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **12"x12" Off-White Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Lunchroom Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25181**    BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Red Multicolor Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Principal's Office, Office in Gym**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Red Multicolor Carpet Mastic**  
MATERIAL LOCATION: **Principal's Office, Office in Gym**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway**  
MATERIAL QUANTITY: **153** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway**  
MATERIAL QUANTITY: **153** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Fittings on Paperwrap Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway**

MATERIAL QUANTITY: **18** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Fittings on Paperwrap Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room and Pipe Chase, Unexcavated Areas, Dever Tunnel Walkway**  
MATERIAL QUANTITY: **18** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Tank Insulation- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Tank Insulation- ABATED**

MATERIAL LOCATION: **1926 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Tank Packing- ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Tank Packing- ABATED**

MATERIAL LOCATION: **1926 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1926 Building- Throughout Building, Air Plenums (Not Decks), and Unexcavated Areas**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS: **300 LF hot water pipe abated from Boiler Rm to 1956 RR's in 2018; debris clean up**

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1926 Building- Throughout Building, Air Plenums (Not Decks), and Unexcavated Areas**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Pre-form Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Pre-form Pipe Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Building & Unexcavated Areas**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partially HA P; debris & soil clean up**

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout Building & Unexcavated Areas**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Fittings Aircell**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Building & Unexcavated Areas**  
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partial abatement & debris & soil clean up**

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Fittings Aircell**  
MATERIAL LOCATION: **Throughout Building & Unexcavated Areas**  
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Fittings on Aircell**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1956 Building- Throughout Building & Unexcavated Area**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Hot Water Pipe ACM Insulation ABATED from the Boiler Room to 1956 RR's - partial abatement**

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Fittings on Aircell**  
MATERIAL LOCATION: **1956 Building- Throughout Building & Unexcavated Area**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Fittings on Pre-form Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Fittings on Pre-form Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **1926 Building- Boiler Room**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **White Coating on Bottom of Sink**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **White Coating on Bottom of Sink**  
MATERIAL LOCATION: **Room 101**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Ruggles School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Black Coating on Bottom of Sink**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25181** BUIDLING ID: **5660**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Ruggles School** REVIEW DATE: **10/24/2019**  
ADDRESS: **7831 S. Prairie** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Black Coating on Bottom of Sink**  
MATERIAL LOCATION: **Room 204**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/24/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---


# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019  
Course Dates:  
05/01/2020  
Expires:  
1905BIR02  
Certificate Number:



Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	3/1/2020
INSPECTOR	5/1/2020

ID NUMBER	ISSUED	EXPIRES
100 - 09106	5/8/2019	05/15/2020

**MICHAEL S HASIER**  
444 OLD BARN RD., APT. B  
BARRINGTON, IL 60010

Environmental Health



PROJECT MANAGER 3/1/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



**Reliable  
Environmental  
Solutions, Inc.** **RES**

*This is to certify that* **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

**COURSE LENGTH: 4 HOURS**

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

*William S. Williams*

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2539 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

*Does hereby certify*


**William Williams**

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least  
70% for re-accreditation under AHERA (Title II)*

**Asbestos Management Planner Refresher**


**Class Date:** 02/15/2019  
**Examination Date:** 02/15/2019  
**STC Certificate Number:** STC-20190215-000527AMPR  
**Certification Expiration:** 02/15/2020

  
David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

4/21/2019

100 - 00746

4/11/2019

05/15/2020

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

**AMY J WILLIAMS**

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed