

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2435
SCHOOL NAME: Sawyer School
ADDRESS OF SCHOOL: 5248 S. Sawyer Ave
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1286
IDPH INSPECTOR LICENSE NUMBER: 100-19716
IDPH LICENSED INSPECTOR NAME(Please Print): Imani Robinson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sawyer School

5248 S. Sawyer Ave
Chicago, IL, 60632

Unit: 25231
Building ID: 5710

IDPH ID Number: 14-016-2990-2435

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

May 17, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25231 Region: 04 IDPH ID:14-016-2990-2435

School: Sawyer School Building ID: 5710

Address: 5248 S. Sawyer Ave
Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 06/09/2019

Inspector: Imani Robinson Inspector IDPH License: 100-19716
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 17, 2019

RE: Sawyer School, Unit 25231
5248 S. Sawyer Ave
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Sawyer School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Sawyer School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sawyer School
Address: 5248 S. Sawyer Ave
IDPH ID: 14-016-2990-2435
Contact:
Unit: 25231
Chicago, IL, 60632
Building ID: 5710
Phone:
Region: 04

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 1286
Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602
Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, Il, 60607
Phone: (312) 762-2900
Fax: (312) 782-5145

5. Inspector

Inspector Name: Imani Robinson

Inspector IDPH license # 100-19716
Signature:
Date: 5/17/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466
Signature:
Date: 06/09/2019

7. Review Date:06/09/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sawyer School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5710:

14	9" x 9" Beige Floor Tile Mastic
2	9" x 9" Beige Floor Tile
23	12" x 12" Beige Floor Tile
24	12" x 12" Brown Floor Tile Mastic
3	12" x 12" Brown Floor Tile
A	Aircell Pipe Insulation

B. The following new homogenous areas have been identified for Building 5710:

- | | |
|----|-----------------------------------|
| 23 | 12" x 12" Beige Floor Tile |
| 24 | 12" x 12" Brown Floor Tile Mastic |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	9" x 9" Green Floor Tile Mastic
11	12" x 12" Beige Floor Tile Mastic
12	9" x 9" Green Floor Tiles
13	12" x 12" Beige Floor Tile
14	9" x 9" Beige Floor Tile Mastic
15	9" x 9" Multi-Color Floor Tile
16	9" x 9" Multi-Color Floor Tile Mastic
17	12" x 12" Light Gray and Beige Floor Tile
18	12" x 12" Light Gray and Beige Floor Tile Mastic
19	Blue Carpet Adhesive - REMOVED
2	9" x 9" Beige Floor Tile
20	12" x 12" Lt. Beige w/ Dk. Beige & White Specks Floor Tile
21	12" x 12" Beige w/ Dk. Beige & White Specks Floor Tile
22	Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)
23	12" x 12" Beige Floor Tile
24	12" x 12" Brown Floor Tile Mastic
3	12" x 12" Brown Floor Tile
5	Linoleum
6	Fire Doors
8	12" x 12" Floor Tile Mastic
9	Linoleum Adhesive
A	Aircell Pipe Insulation
B	Aircell Pipe Insulation Joints
C	Cardboard Pipe Insulation
E	Aircell Duct Wrap
H	Boiler Gaskets
I	Boiler Covering
J	Tank Covering
K	Aircell Pipe Insulation
L	Aircell Pipe Insulation Joints
M	Cardboard Pipe Insulation
N	Cardboard Joints
O	Fiberglass Joints
P	Incinerator Insulation - REMOVED
Q	12x12 Blue Mix Floor Tile
R	12x12 Blue Mix Floor Tile Mastic
S	12x12 Yellow Mix Floor Tile
T	12x12 Yellow Mix Floor Tile Mastic
U	12x12 Beige Mix Floor Tile

V	12x12 Beige Mix Floor Tile Mastic
W	12x12 Brown Mix Floor Tile
X	12x12 Brown Mix Floor Tile Mastic
Y	9x9 Dark Brown w/Beige Streaks Floor Tile
Z	9x9 Dark Brown w/Beige Streaks Floor Tile Mastic

The following areas were deemed to be inaccessible:

10	9" x 9" Green Floor Tile Mastic
11	12" x 12" Beige Floor Tile Mastic
14	9" x 9" Beige Floor Tile Mastic
2	9" x 9" Beige Floor Tile
22	Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)
24	12" x 12" Brown Floor Tile Mastic
6	Fire Doors
8	12" x 12" Floor Tile Mastic
9	Linoleum Adhesive
C	Cardboard Pipe Insulation
R	12x12 Blue Mix Floor Tile Mastic
T	12x12 Yellow Mix Floor Tile Mastic
V	12x12 Beige Mix Floor Tile Mastic
X	12x12 Brown Mix Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Imani Robinson, IDPH License # 100-19716. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sawyer School Building 5710 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Hard Coat			1918 Building	NO_ACBM	MISC								
10	9" x 9" Green Floor Tile Mastic	800	SF	Throughout 1918 Building, Rm. 102	ASSUMED	MISC	N	LOC	800		No	ACBM with the potential for damage	3	LOW
11	12" x 12" Beige Floor Tile Mastic	10,000	SF	Throughout 1918 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9" x 9" Green Floor Tiles	800	SF	Throughout 1918 Building, Rm. 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12" x 12" Beige Floor Tile	10,000	SF	Throughout 1918 Building	ASSUMED	MISC	N	LOC	50		No	ACBM with the potential for damage	2	LOW
14	9" x 9" Beige Floor Tile Mastic	1,700	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	LOC	600		Yes	ACBM with the potential for damage	3	LOW
15	9" x 9" Multi-Color Floor Tile			Room 207	ASSUMED	MISC								
16	9" x 9" Multi-Color Floor Tile Mastic			Room 207	ASSUMED	MISC								
17	12" x 12" Light Gray and Beige Floor Tile	800	SF	Room 202	ASSUMED	MISC	N	LOC	10		No	ACBM with the potential for damage	5	MODERATE
18	12" x 12" Light Gray and Beige Floor Tile Mastic			Room 202	ASSUMED	MISC								
19	Blue Carpet Adhesive - REMOVED			Library (Basement)	ASSUMED	MISC								
2	9" x 9" Beige Floor Tile	1,700	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	DIST	600		Yes	ACBM with the potential for damage	3	LOW
20	12" x 12" Lt. Beige w/ Dk. Beige & White Specks Floor Tile	400	SF	Rm. 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12" x 12" Beige w/ Dk. Beige & White Specks Floor Tile	400	SF	Rm. 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)	800	SF	Rm. 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12" x 12" Beige Floor Tile	500	SF	Rm. 110	ASSUMED	MISC	N	DIST	500		Yes	ACBM with the potential for damage	3	HIGH
24	12" x 12" Brown Floor Tile Mastic	500	SF	Rm. 110	ASSUMED	MISC	N	DIST	500		Yes	ACBM with the potential for damage	3	LOW
3	12" x 12" Brown Floor Tile	10,000	SF	Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203	ASSUMED	MISC	N	DIST	10,000		Yes	ACBM with the potential for damage	5	MODERATE
4	2' x 4' Drop Ceiling			Main Office and Library	NO_ACBM	MISC								
5	Linoleum	900	SF	Office and Room 211, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	Fire Doors	21	SF	1900 Building - Basement (across from room B3)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
8	12" x 12" Floor Tile Mastic	10,000	SF	Throughout 1900 Building - Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	Linoleum Adhesive	900	SF	Office and room 211, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	750	LF	Throughout 1918 Building	ASSUMED	TSI	Y	LOC	1		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
B	Aircell Pipe Insulation Joints	75	LF	Throughout 1918 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Cardboard Pipe Insulation	150	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Cardboard Pipe Insulation Joints	15	LF	Throughout 1900 Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell Duct Wrap			Boy's Play Room 1900 Building	ASSUMED	TSI								
G	Fiberglass Joints			Throughout 1918 Building	CHR	TSI								
H	Boiler Gaskets	15	SF	Boiler Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Boiler Covering	750	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
J	Tank Covering	600	SF	Engine and Tank Room	ASSUMED	TSI	Y	LOC	4		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
K	Aircell Pipe Insulation	750	LF	Throughout 1900 Building	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Aircell Pipe Insulation Joints	75	LF	Throughout 1900 Building	ASSUMED	TSI	Y	DIST	4		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
M	Cardboard Pipe Insulation			Throughout 1918 Building	ASSUMED	TSI								
N	Cardboard Joints			Throughout 1918 Building	ASSUMED	TSI								
O	Fiberglass Joints	30	LF	Throughout 1900	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable		MODERATE

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 5/17/2019
Inspector Name Imani Robinson
100-19716 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	All of Rm. 104 damaged
15	Not observed 2019
16	Not observed 2019
17	
18	Not observed 2019
19	
2	All of Rm. 104 damaged
20	
21	
22	
23	
24	
3	Damage located in room 301-304 and 306
4	
5	
6	
8	
9	

Chicago Public Schools

School Sawyer School Unit 25231 Building ID 5710

Address 5248 S. Sawyer Ave Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
A	Damage in mechanical room
B	
C	
D	
E	Not observed 2019
G	Not observed 2019
H	
I	
J	New water tank and boiler with no cover
K	
L	
M	Not observed 2019
N	Not observed 2019
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	
Z	Not observed 2019

Chicago Public Schools

School Sawyer School **Unit** 25231 **Building ID** 5710

Address 5248 S. Sawyer Ave **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard Coat			1918 Building	No ACBM	MISC					
10	9" x 9" Green Floor Tile Mastic	800	SF	Throughout 1918 Building, Rm. 102	Assumed	MISC	No	800	SF	6 ACBM with the potential for damage	Remove
11	12" x 12" Beige Floor Tile Mastic	10,000	SF	Throughout 1918 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Remove
12	9" x 9" Green Floor Tiles	800	SF	Throughout 1918 Building, Rm. 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12" x 12" Beige Floor Tile	10,000	SF	Throughout 1918 Building	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Repair
14	9" x 9" Beige Floor Tile Mastic	1,700	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	600	SF	6 ACBM with the potential for damage	Remove
15	9" x 9" Multi-Color Floor Tile			Room 207	Assumed	MISC					
16	9" x 9" Multi-Color Floor Tile Mastic			Room 207	Assumed	MISC					
17	12" x 12" Light Gray and Beige Floor Tile	800	SF	Room 202	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Remove
18	12" x 12" Light Gray and Beige Floor Tile Mastic			Room 202	Assumed	MISC					
19	Blue Carpet Adhesive - REMOVED			Library (Basement)	Assumed	MISC					
2	9" x 9" Beige Floor Tile	1,700	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	600	SF	6 ACBM with the potential for damage	Remove
20	12" x 12" Lt. Beige w/ Dk. Beige & White Specks Floor Tile	400	SF	Rm. 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" Beige w/ Dk. Beige & White Specks Floor Tile	400	SF	Rm. 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)	800	SF	Rm. 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Beige Floor Tile	500	SF	Rm. 110	Assumed	MISC	No	500	SF	6 ACBM with the potential for damage	Remove
24	12" x 12" Brown Floor Tile Mastic	500	SF	Rm. 110	Assumed	MISC	No	500	SF	6 ACBM with the potential for damage	Remove
3	12" x 12" Brown Floor Tile	10,000	SF	Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203	Assumed	MISC	No	10,000	SF	6 ACBM with the potential for damage	Remove
4	2' x 4' Drop Ceiling			Main Office and Library	No ACBM	MISC					
5	Linoleum	900	SF	Office and Room 211, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Fire Doors	21	SF	1900 Building- Basement (across from room B3)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	12" x 12" Floor Tile Mastic	10,000	SF	Throughout 1900 Building - Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Linoleum Adhesive	900	SF	Office and room 211, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	750	LF	Throughout 1918 Building	Assumed	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
B	Aircell Pipe Insulation Joints	75	LF	Throughout 1918 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Cardboard Pipe Insulation	150	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
D	Cardboard Pipe Insulation Joints	15	LF	Throughout 1900 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell Duct Wrap			Boy's Play Room 1900 Building	Assumed	TSI					
G	Fiberglass Joints			Throughout 1918 Building	Chrysotile	TSI					
H	Boiler Gaskets	15	SF	Boiler Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Boiler Covering	750	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Tank Covering	600	SF	Engine and Tank Room	Assumed	TSI	Yes	4	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
K	Aircell Pipe Insulation	750	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Aircell Pipe Insulation Joints	75	LF	Throughout 1900 Building	Assumed	TSI	Yes	4	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
M	Cardboard Pipe Insulation			Throughout 1918 Building	Assumed	TSI					Follow O&M Plan
N	Cardboard Joints			Throughout 1918 Building	Assumed	TSI					Follow O&M Plan
O	Fiberglass Joints	30	LF	Throughout 1900 Building	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Incinerator Insulation - REMOVED			Boiler Room	Assumed	TSI					
Q	12x12 Blue Mix Floor Tile	1,000	SF	1900 BLDG- Rm B-1, Rm. 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
R	12x12 Blue Mix Floor Tile Mastic	1,000	SF	1900 BLDG-Rm B-1, Rm. 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S	12x12 Yellow Mix Floor Tile	1,000	SF	1900 BLDG- Rm B-1, Rm. 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
T	12x12 Yellow Mix Floor Tile Mastic	1,000	SF	1900 BLDG-Rm B-1, Rm. 305	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
U	12x12 Beige Mix Floor Tile	500	SF	1918 BLDG Rm 206, 208	Assumed	MISC	No	60	SF	5 ACBM with potential for significant damage	Repair
V	12x12 Beige Mix Floor Tile Mastic	500	SF	1918 BLDG Rm 206, 208	Assumed	MISC	No	500	SF	6 ACBM with the potential for damage	Repair
W	12x12 Brown Mix Floor Tile	500	SF	1918 BLDG- Rm 206, 208	Assumed	MISC	No	60	SF	6 ACBM with the potential for damage	Repair
X	12x12 Brown Mix Floor Tile Mastic	500	SF	1918 BLDG- Rm 206, 208	Assumed	MISC	No	60	SF	6 ACBM with the potential for damage	Repair
Y	9x9 Dark Brown w/Beige Streaks Floor Tile		SF	1900 BLDG - Rm 007 by Lunchroom	Assumed	MISC	No	500	SF	6 ACBM with the potential for damage	Remove
Z	9x9 Dark Brown w/Beige Streaks Floor Tile Mastic			1900 BLDG Rm 007 by Lunchroom	Assumed	MISC					Repair

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	06/09/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic throughout 1918 building
11	See HA10
12	
13	Sample the damaged floor tile and associated mastic if positive for acbm remove or repair and replace damaged floor tile and associated mastic throughout the 1918 bldg.
14	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 104 and continue O&M

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
15	
16	
17	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 202 and continue O&M
18	
19	
2	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 104 and continue O&M
20	
21	
22	
23	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 110
24	See HA 23
3	Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in rooms 301-304 & 306
4	
5	
6	
8	
9	
A	
B	
C	
D	
E	
G	

Chicago Public Schools

School Sawyer School
Address 5248 S. Sawyer Ave

Unit 25231
 Chicago, IL, 60632

Building ID 5710
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
H	
I	
J	Sample material to determine asbestos content. Repair all TSI damaged ACBM
K	
L	Sample material to determine asbestos content. Repair all TSI damaged ACBM
M	
N	
O	
P	
Q	
R	
S	
T	
U	Sample material to determine asbestos content. Repair and/or remove all damaged TSI damaged ACBM
V	See Ha U
W	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
X	See HA W
Y	Sample material to determine asbestos content. Repair and/or remove all damaged ACBM
Z	See HA Y

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Hard Coat**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard Coat**

MATERIAL LOCATION: **1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building, Rm. 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **800** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1918 Building, Rm. 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **800** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic throughout 1918 building

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

See HA10

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building, Rm. 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tiles**
MATERIAL LOCATION: **Throughout 1918 Building, Rm. 102**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove or repair and replace damaged floor tile and associated mastic throughout the 1918 bldg.

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS: **All of Rm. 104 damaged**

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 104 and continue O&M

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9" x 9" Multi-Color Floor Tile Mastic**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 202 and continue O&M

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Light Gray and Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (Basement)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive - REMOVED**

MATERIAL LOCATION: **Library (Basement)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS: **All of Rm. 104 damaged**

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 104 and continue O&M

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Lt. Beige w/ Dk. Beige & White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm. 207**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12" x 12" Lt. Beige w/ Dk. Beige & White Specks Floor Tile**
MATERIAL LOCATION: **Rm. 207**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dk. Beige & White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rm. 207**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dk. Beige & White Specks Floor Tile**

MATERIAL LOCATION: **Rm. 207**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm. 207**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige and Lt. Beige Floor Tiles (HA's 20 & 21)**
MATERIAL LOCATION: **Rm. 207**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10000** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in room 301-304 and 306**

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms 301, 302, 303, 304, 306, 203**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10000** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in rooms 301-304 & 306

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **2' x 4' Drop Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **2' x 4' Drop Ceiling**

MATERIAL LOCATION: **Main Office and Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office and Room 211, 311**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Office and Room 211, 311**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 Building- Basement (across from room B3)**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **1900 Building- Basement (across from room B3)**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 1900 Building - Classrooms**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office and room 211, 311**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Linoleum Adhesive**
MATERIAL LOCATION: **Office and room 211, 311**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**
COMMENTS: **Damage in mechanical room**

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
MATERIAL LOCATION: **Throughout 1918 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Duct Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Play Room 1900 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Duct Wrap**

MATERIAL LOCATION: **Boy's Play Room 1900 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fiberglass Joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Fiberglass Joints**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Boiler Covering**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Boiler Covering**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank Covering**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engine and Tank Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**
COMMENTS: **New water tank and boiler with no cover**

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Tank Covering**
MATERIAL LOCATION: **Engine and Tank Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample material to determine asbestos content. Repair all TSI damaged ACBM

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation Joints**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Sample material to determine asbestos content. Repair all TSI damaged ACBM

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Cardboard Joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard Joints**

MATERIAL LOCATION: **Throughout 1918 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Fiberglass Joints**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1900 Building**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Fiberglass Joints**

MATERIAL LOCATION: **Throughout 1900 Building**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Incinerator Insulation - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Incinerator Insulation - REMOVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **12x12 Blue Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG- Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **12x12 Blue Mix Floor Tile**
MATERIAL LOCATION: **1900 BLDG- Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12x12 Blue Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG-Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **R**
MATERIAL DESCRIPTION: **12x12 Blue Mix Floor Tile Mastic**
MATERIAL LOCATION: **1900 BLDG-Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12x12 Yellow Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG- Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **12x12 Yellow Mix Floor Tile**
MATERIAL LOCATION: **1900 BLDG- Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12x12 Yellow Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG-Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **T**
MATERIAL DESCRIPTION: **12x12 Yellow Mix Floor Tile Mastic**
MATERIAL LOCATION: **1900 BLDG-Rm B-1, Rm. 305**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **12x12 Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1918 BLDG Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **U**
MATERIAL DESCRIPTION: **12x12 Beige Mix Floor Tile**
MATERIAL LOCATION: **1918 BLDG Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged TSI damaged ACBM

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**
MATERIAL DESCRIPTION: **12x12 Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1918 BLDG Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **V**
MATERIAL DESCRIPTION: **12x12 Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **1918 BLDG Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

See Ha U

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**
MATERIAL DESCRIPTION: **12x12 Brown Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1918 BLDG- Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **W**
MATERIAL DESCRIPTION: **12x12 Brown Mix Floor Tile**
MATERIAL LOCATION: **1918 BLDG- Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **12x12 Brown Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1918 BLDG- Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **12x12 Brown Mix Floor Tile Mastic**
MATERIAL LOCATION: **1918 BLDG- Rm 206, 208**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

See HA W

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1900 BLDG - Rm 007 by Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **Y**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/Beige Streaks Floor Tile**
MATERIAL LOCATION: **1900 BLDG - Rm 007 by Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Sample material to determine asbestos content. Repair and/or remove all damaged ACBM

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Z**
MATERIAL DESCRIPTION: **9x9 Dark Brown w/Beige Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1900 BLDG Rm 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **Z**

MATERIAL DESCRIPTION: **9x9 Dark Brown w/Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1900 BLDG Rm 007 by Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

See HA Y

Management Planner's Signature: _____ Date: **06/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rm. 110**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **HIGH** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **500** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **05/17/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rm. 110**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample the damaged floor tile and associated mastic if positive for acbm remove and replace damaged floor tile and associated mastic in room 110

Management Planner's Signature: _____ Date: 06/09/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUIDLING ID: **5710**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Imani Robinson**
SCHOOL NAME: **Sawyer School** INSPECTION DATE: **5/17/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rm. 110**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **500** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Date: 05/17/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25231** BUILDING ID: **5710**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Sawyer School** REVIEW DATE: **6/9/2019**
ADDRESS: **5248 S. Sawyer Ave** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rm. 110**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

See HA 23

Management Planner's Signature: _____ Date: **06/09/2019**

APPENDIX B

Inspector and Management Planner Licenses

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657



Environmental Health

ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063


Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed