

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2456
SCHOOL NAME: Shoesmith School
ADDRESS OF SCHOOL: 1330 E. 50th St.
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/22/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 372
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-01934
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Randy Livingston

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Shoesmith School

1330 E. 50th St.
Chicago, IL, 60615

Unit: 25371
Building ID: 5920

IDPH ID Number: 14-016-2990-2456

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

December 19, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25371 Region: 04 IDPH ID:14-016-2990-2456

School: Shoesmith School Building ID: 5920

Address: 1330 E. 50th St.

Chicago, IL, 60615

Building Contact: Lyons, Terence

Contact Phone:773 653 6644

Current Building Owners: Chicago Public Schools

Review Date: 12/23/2019

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Randy Livingston

Management Planner IDPH License: 100-01934

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Randy Livingston
100-01934

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: December 19, 2019

RE: Shoesmith School, Unit 25371
1330 E. 50th St.
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Shoesmith School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Shoesmith School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Shoesmith School	Unit: 25371	Region: 04
Address:	1330 E. 50th St.	Chicago, IL, 60615	
IDPH ID:	14-016-2990-2456	Building ID: 5920	
Contact:	Lyons, Terence	Phone: 773 653 6644	

2. Description of Facility

Original Construction: 1961	Additional Construction:
Total Square Footage: 36887	No of Floors: 2
Current Occupancy: 372	

3. LEA Designated Person

Contact: Robert Christlieb	Phone: (773) 553-3197
Address: 42 West Madison Street	
Chicago, IL 60602	

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates	
Contact: Doug McCormick	
Address 600 West Van Buren St., Ste 500	
Chicago, IL, 60607	
Phone: (312) 762-2900	Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 12/19/2019

6. Management Planner

Management Planner Name: Randy Livingston

Management Planner IDPH license # 100-01934

Signature:
Date: 12/23/2019

7. Review Date:12/23/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Shoesmith School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5920:

20	Vibration Collar
25	12" X 12" White w/Blue Speckles Floor Tile
31	1'x1' White Sm.Fissured w/RPHCeilingTile (Patching)

B. The following new homogenous areas have been identified for Building 5920:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	Baseboards
12	Baseboard Mastic
14	12' x 12" Grayish Speckled Floor Tile
15	12' x 12" Grayish Speckled Floor Tile Mastic
17	Blue/Gray Mixed Carpet Mastic - REMOVED
20	Vibration Collar
21	Vault Door Insulation
22	Interior Fire Doors Insulation
23	Incinerator Brick
24	Incinerator Brick Mortar
25	12" X 12" White w/Blue Speckles Floor Tile
26	12" X 12" Blue Floor Tile
27	12" X 12" Purple Floor Tile
28	Mastic Associated with 12" x 12" Floor Tile
29	1' x 1' Off White RPH Ceiling Tile
3	Hard Plaster
30	1' x 1' Off White RPH Ceiling Tile Adhesive
31	1'x1' White Sm.Fissured w/RPHCeilingTile (Patching)
32	1'x1' White Lg.Fissured w/RPHCeilingTile (Patching)
33	1'x1' White Med.Fissuredw/RPHCeilingTile (Patching)
34	Chalk/Marker Board Adhesive
35	2' x 2' Off-white Ceiling Tiles
36	2' x 2' Off-white Ceiling Tile Mastic
37	Pipe Insulation
38	1' X 1' Small Fissured Ceiling Tile
39	1' X 1' Large fissured Ceiling Tiles
4	Drywall
40	Sink Undercoating
41	Stair Tread Covering
42	Stair Tread Covering Mastic
43	4" Black vinyl Baseboard
44	4" Black vinyl Baseboard Mastic
45	Chalk Board Adhesive
46	Marker Board Adhesive
47	12" X 12" Beige w/Brown Specks Floor Tile
48	12" X 12" Beige w/Brown Specks Floor Tile Mastic
49	5" Beige Base Boards
50	5" Beige Base Board Mastic
51	4' X 8' Ceiling Panels

52	Insulation In Metal Walls
53	Yellow Rolled Flooring
54	Yellow Rolled Flooring Adhesive
55	Interior Wall Panels
56	2' x 4' inlay ceiling tile
7A	12" x 12" Tan Floor Tile
7B	12" x 12" Light Brown Floor Tile
9	Ceramic Tile Grout
F	Insulation Board
G	Vibration Damper

The following areas were deemed to be inaccessible:

15	12' x 12" Grayish Speckled Floor Tile Mastic
21	Vault Door Insulation
28	Mastic Associated with 12" x 12" Floor Tile
30	1' x 1' Off White RPH Ceiling Tile Adhesive
34	Chalk/Marker Board Adhesive
36	2' x 2' Off-white Ceiling Tile Mastic
42	Stair Tread Covering Mastic
44	4" Black vinyl Baseboard Mastic
45	Chalk Board Adhesive
46	Marker Board Adhesive
48	12" X 12" Beige w/Brown Specks Floor Tile Mastic
50	5" Beige Base Board Mastic
52	Insulation In Metal Walls
54	Yellow Rolled Flooring Adhesive
55	Interior Wall Panels
56	2' x 4' inlay ceiling tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Shoesmith School Building 5920 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Shoesmith School Unit 25371 Building ID 5920

Address 1330 E. 50th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
11	Baseboards			Material Not Present	ASSUMED	MISC								
12	Baseboard Mastic	0		Material Not Present	ASSUMED	MISC								
14	12" x 12" Grayish Speckled Floor Tile	50	SF	Boiler Room Entrance, Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12" x 12" Grayish Speckled Floor Tile Mastic	50	SF	Boiler Room Entrance, Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Interior Door Caulk			Throughout Building at Entrance Doors	CHR	MISC								
17	Blue/Gray Mixed Carpet Mastic - REMOVED			1st Floor Teacher's Resource Room, Room 206 & Counselor's Office	ASSUMED	MISC								
18	12" x 12" Light Peach Speckled Floor Tile - ABATED			1st Floor Men's Washroom	ABATED									
19	12" x 12" Light Peach Speckled Floor Tile Mastic - ABATED			1st Floor Men's Washroom	ABATED									
20	Vibration Collar	3	SF	Kitchen Store Room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
21	Vault Door Insulation	28	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Interior Fire Doors Insulation			Boiler Room	ASSUMED	MISC								
23	Incinerator Brick			Incinerator Room	ASSUMED	MISC		None						
24	Incinerator Brick Mortar			Incinerator Room	ASSUMED	MISC								
25	12" X 12" White w/Blue Speckles Floor Tile	6,350	SF	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings	ASSUMED	MISC	N	DIST	45		Yes	ACBM with potential for significant damage	5	LOW
26	12" X 12" Blue Floor Tile	15,170	SF	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12" X 12" Purple Floor Tile	2,008	SF	1st & 2nd Floor Corridors and Stair Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Mastic Associated with 12" x 12" Floor Tile	21,400	SF	Throughout School (HA 25-27)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	1' x 1' Off White RPH Ceiling Tile	21,400	SF	Throughout School	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Shoesmith School Unit 25371 Building ID 5920

Address 1330 E. 50th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
3	Hard Plaster	540	SF	Kitchen	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
30	1' x 1' Off White RPH Ceiling Tile Adhesive	21,400	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	1'x1' White Sm.Fissured w/RPHCeilingTile (Patching)	130	SF	Rooms 108, 106, 104 and the 2nd Floor North Stairwell and Hallway, Teachers Lounge	ASSUMED	MISC	Y	DIST	35		Yes	Damaged or significantly damaged friable misc. ACBM	10	LOW
32	1'x1' White Lg.Fissured w/RPHCeilingTile (Patching)	283	SF	2nd Floor North Stairwell, 104, 106, 203, 206, 208, and Corridors, Teachers Lounge and Janitors clos	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
33	1'x1' White Med. Fissuredw/RPHCeilingTile(Patching)	150	SF	Rooms 103-106 and the 1st Floor Janitor's Closet	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Chalk/Marker Board Adhesive	2,560	SF	1st and 2nd Floor Classrooms, Teachers Lounge and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	2' x 2' Off-white Ceiling Tiles	2,900	SF	Gym	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
36	2' x 2' Off-white Ceiling Tile Mastic	2,900	SF	Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Pipe Insulation			Pipe Chase in Washrooms	ASSUMED	TSI								
38	1' X 1' Small Fissured Ceiling Tile	850	SF	101, 103-108, 206, 1st and 2nd Fl Coridors, Teachers Lounge and Janitor's Closet	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
39	1' X 1' Large fissured Ceiling Tiles	253	SF	104, 106, 1st Fl Coridor, 203, 206, 208	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
4	Drywall	240	SF	Mechanical and Electrical Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Sink Undercoating	4	SF	206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Stair Tread Covering	416	SF	All Stairways and Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Stair Tread Covering Mastic	416	SF	All Stairways and	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Shoesmith School Unit 25371 Building ID 5920

Address 1330 E. 50th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
43	4" Black vinyl Baseboard	308	LF	Stage Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	ASSUMED	MISC	N	NONE	0		No	potential for damage ACBM with the potential for damage		LOW
44	4" Black vinyl Baseboard Mastic	308	LF	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Chalk Board Adhesive	1,040	SF	100, 102, 104-109, Teachers Lounge and 203-208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Marker Board Adhesive	960	SF	100, 102, 104-109, 203-208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" X 12" Beige w/Brown Specks Floor Tile	1,260	SF	Classrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12" X 12" Beige w/Brown Specks Floor Tile Mastic	1,260	SF	Classrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	5" Beige Base Boards	200	LF	Classrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	5" Beige Base Board Mastic	200	LF	Classrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	4' X 8' Ceiling Panels	1,518	SF	All ceilings in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Insulation In Metal Walls	1,780	SF	Exterior walls in the mobile trailer unit	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
53	Yellow Rolled Flooring	192	SF	Entrances and Washrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Yellow Rolled Flooring Adhesive	192	SF	Entrances and Washrooms in the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Interior Wall Panels	760	SF	Interior walls of the mobile trailer unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	2' x 4' inlay ceiling tile	1,180	SF	Lunchroom	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
6	9" x 9" Floor Tile	0		Throughout Building	ABATED									
6A	9" x 9" Grey Floor Tile	0		Center Stairwell & Room 207 & Outside Room 202, Incinerator Room,	ABATED	MISC								

Chicago Public Schools

School Shoesmith School **Unit** 25371 **Building ID** 5920

Address 1330 E. 50th St. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Engineer's Office, Corridors										
6B	9" x 9" White Floor Tile	0		Throughout Corridors & Locker Room	ABATED	MISC								
6C	9" x 9" Black Floor Tile	0		Throughout Corridors & Locker Room	ABATED	MISC								
6D	9" x 9" Tan w/Spots Floor Tile	0		Rooms 204, 208, & 107, Lunchroom P. E., Lunchroom NW	ABATED	MISC								
6E	9" x 9" Pink Floor Tile	0		Room 100	ABATED	MISC								
6F	9" x 9" Blue Floor Tile - Abated			Room 100	ABATED	MISC								
6G	9" x 9" Brown w/Spots Floor Tile - Abated			Main Office Area, Rooms 203 & 205	ABATED	MISC								
6H	9" x 9" Brown Striped Floor Tile - Abated			Lunchroom, Rooms 103, 203, 204, 205 & 208	ABATED	MISC								
6I	9" x 9" Grey w/Spots Floor Tile - Abated			Rooms 104, 105, 107, 108 & 207	ABATED	MISC								
7A	12" x 12" Tan Floor Tile			North Lobby, North Stairwell & North 2nd Floor Hallway	ASSUMED	MISC								
7B	12" x 12" Light Brown Floor Tile			Room 202, Entrance To 2nd Floor Bathroom	ASSUMED	MISC								
8	9" x 9" Floor Tile Mastic abated			Throughout Building	ABATED	MISC								
8A	12" x 12" Tan Floor Tile Mastic - Abated			North Lobby, North Stairwell & North 2nd Floor Hallway	ABATED	MISC								
8B	12" x 12" Light Brown Floor Tile Mastic - Abated			Room 202, Entrance To 2nd Floor Bathroom	ABATED	MISC								
8C	9" x 9" Grey Floor Tile Mastic - Abated			Boiler Room Washroom, Center Stairwell & Room 207 & Outside Room 202	ABATED	MISC								
8D	9" x 9" White Floor Tile Mastic - Abated			Throughout Corridors & Locker Room	ABATED	MISC								
8E	9" x 9" Black Floor Tile Mastic - Abated			Throughout Corridors & Locker	ABATED	MISC								

Chicago Public Schools

School Shoesmith School Unit 25371 Building ID 5920

Address 1330 E. 50th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room										
8F	9" x 9" Tan w/Spots Floor Tile Mastic - Abated			Rooms 204, 208, & 107, Lunchroom P. E., Lunchroom NW	ABATED	MISC								
8g	9" x 9" Pink Floor Tile Mastic - Abated			Room 100	ABATED	MISC								
8h	9" x 9" Blue Floor Tile Mastic - Abated			Room 100	ABATED	MISC								
8i	9" x 9" Brown w/Spots Floor Tile Mastic - Abated			Main Office Area, Rooms 203 & 205	ABATED	MISC								
8j	9" x 9" Brown Stripe Floor Tile Mastic - Abated			Lunchroom, Rooms 103, 203, 204, & 205	ABATED	MISC								
8k	9" x 9" Grey w/Spots Floor Tile Mastic - Abated			Rooms 104, 105, 107, 108 & 207	ABATED	MISC								
9	Ceramic Tile Grout			Kitchen/Toilets Throughout	ASSUMED	MISC								
A	Boiler Insulation - Abated			Boiler Room	ABATED	TSI								
B	Tank Insulation abated			Boiler Room	ABATED	TSI								
C	Boiler Breeching abated			Boiler Room	ABATED	TSI								
D	Joint Compound Off Fiberglass Pipe Insulation			Gym Teacher's Office, Equipment Room & Gym Storage Room	AMO_CHR	TSI								
E	Duct Manifold			Mechanical Room	CHR	TSI								
EXT	Exterior Brick - Not AHERA			Exterior	UNDEFINE D									
EXT-1	Exterior Brick Mortar - Not AHERA			Exterior	UNDEFINE D									
F	Insulation Board			Above Ceiling	ASSUMED	MISC								
G	Vibration Damper	20	LF	2nd. Floor Fan Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
INW	Interior Window Caulk Abated			Throughout Building	ABATED	MISC								
OTW	Exterior Window Caulk - Not AHERA			Exterior	CHR	MISC								

Chicago Public Schools

School Shoesmith School Unit 25371 Building ID 5920

Address 1330 E. 50th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>12/19/2019</u>
Inspector Name	<u>Marcos Iwankiw</u>
<u>100-03175</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
11	
12	
14	
15	
16	Not observed 2019
17	
18	
19	
20	
21	
22	Not observed 2019
23	Not observed 2019
24	Not observed 2019
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	

Chicago Public Schools

School Shoesmith School **Unit** 25371 **Building ID** 5920

Address 1330 E. 50th St. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
34	
35	
36	
37	Not observed 2019
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
6	
6A	
6B	
6C	
6D	

Chicago Public Schools

School Shoesmith School **Unit** 25371 **Building ID** 5920

Address 1330 E. 50th St. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
6E	
6F	
6G	
6H	
6I	
7A	Not observed 2019
7B	Not observed 2019
8	
8A	
8B	
8C	
8D	
8E	
8F	
8g	
8h	
8i	
8j	
8k	
9	Not observed 2019
A	
B	
C	
D	Not observed 2019
E	Not observed 2019
EXT	
EXT-1	
F	Not observed 2019
G	

Chicago Public Schools

School Shoesmith School **Unit** 25371 **Building ID** 5920

Address 1330 E. 50th St. **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
INW	
OTW	

Table II

Management Planner's Review

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
11	Baseboards			Material Not Present	Assumed	MISC					
12	Baseboard Mastic	0		Material Not Present	Assumed	MISC					
14	12' x 12" Grayish Speckled Floor Tile	50	SF	Boiler Room Entrance, Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12' x 12" Grayish Speckled Floor Tile Mastic	50	SF	Boiler Room Entrance, Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Interior Door Caulk			Throughout Building at Entrance Doors	Chrysotile	MISC					
17	Blue/Gray Mixed Carpet Mastic - REMOVED			1st Floor Teacher's Resource Room, Room 206 & Counselor's Office	Assumed	MISC					
18	12" x 12" Light Peach Speckled Floor Tile - ABATED			1st Floor Men's Washroom	Abated						
19	12" x 12" Light Peach Speckled Floor Tile Mastic - ABATED			1st Floor Men's Washroom	Abated						
20	Vibration Collar	3	SF	Kitchen Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Vault Door Insulation	28	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Interior Fire Doors Insulation			Boiler Room	Assumed	MISC					
23	Incinerator Brick			Incinerator Room	Assumed	MISC					
24	Incinerator Brick Mortar			Incinerator Room	Assumed	MISC					
25	12" X 12" White w/Blue Speckles Floor Tile	6,350	SF	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings	Assumed	MISC	No	45	SF	5 ACBM with potential for significant damage	Follow O&M Plan
26	12" X 12" Blue Floor Tile	15,170	SF	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" X 12" Purple Floor Tile	2,008	SF	1st & 2nd Floor Corridors and Stair Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Mastic Associated with 12" x 12" Floor Tile	21,400	SF	Throughout School (HA 25-27)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	1' x 1' Off White RPH Ceiling Tile	21,400	SF	Throughout School	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
3	Hard Plaster	540	SF	Kitchen	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	1' x 1' Off White RPH Ceiling Tile Adhesive	21,400	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	1'x1' White Sm.Fissured w/RPHCeilingTile (Patching)	130	SF	Rooms 108, 106, 104 and the 2nd Floor North Stairwell and Hallway, Teachers Lounge	Assumed	MISC	Yes	35	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
32	1'x1' White Lg.Fissured w/RPHCeilingTile (Patching)	283	SF	2nd Floor North Stairwell, 104, 106, 203, 206, 208, and Corridors, Teachers	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Lounge and Janitors clos							
33	1'x1' White Med.Fissuredw/RPHCeilingTile (Patching)	150	SF	Rooms 103-106 and the 1st Floor Janitor's Closet	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Chalk/Marker Board Adhesive	2,560	SF	1st and 2nd Floor Classrooms, Teachers Lounge and Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	2' x 2' Off-white Ceiling Tiles	2,900	SF	Gym	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	2' x 2' Off-white Ceiling Tile Mastic	2,900	SF	Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Pipe Insulation			Pipe Chase in Washrooms	Assumed	TSI					
38	1' X 1' Small Fissured Ceiling Tile	850	SF	101, 103-108, 206, 1st and 2nd FI Coridors, Teachers Lounge and Janitor's Closet	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
39	1' X 1' Large fissured Ceiling Tiles	253	SF	104, 106, 1st FI Coridor, 203, 206, 208	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
4	Drywall	240	SF	Mechanical and Electrical Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Sink Undercoating	4	SF	206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Stair Tread Covering	416	SF	All Stairways and Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Stair Tread Covering Mastic	416	SF	All Stairways and Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Black vinyl Baseboard	308	LF	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Black vinyl Baseboard Mastic	308	LF	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	Chalk Board Adhesive	1,040	SF	100, 102, 104-109, Teachers Lounge and 203-208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Marker Board Adhesive	960	SF	100, 102, 104-109, 203-208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" X 12" Beige w/Brown Specks Floor Tile	1,260	SF	Classrooms in the mobile trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12" X 12" Beige w/Brown Specks Floor Tile Mastic	1,260	SF	Classrooms in the moble trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	5" Beige Base Boards	200	LF	Classrooms in the moble trailer unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
50	5" Beige Base Board Mastic	200	LF	Classrooms in the moble trailer unit	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	4' X 8' Ceiling Panels	1,518	SF	All ceilings in the mobile trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Insulation In Metal Walls	1,780	SF	Exterior walls in the mobile trailer unit	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
53	Yellow Rolled Flooring	192	SF	Entrances and Washrooms in the mobile trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
54	Yellow Rolled Flooring Adhesive	192	SF	Entrances and Washrooms in the mobile trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Interior Wall Panels	760	SF	Interior walls of the mobile trailer unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	2' x 4' inlay ceiling tile	1,180	SF	Lunchroom	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
6	9" x 9" Floor Tile	0		Throughout Building	Abated						
6A	9" x 9" Grey Floor Tile	0		Center Stairwell & Room 207 & Outside Room 202, Incinerator Room, Engineer's Office, Corridors	Abated	MISC					
6B	9" x 9" White Floor Tile	0		Throughout Corridors & Locker Room	Abated	MISC					
6C	9" x 9" Black Floor Tile	0		Throughout Corridors & Locker Room	Abated	MISC					
6D	9" x 9" Tan w/Spots Floor Tile	0		Rooms 204, 208, & 107, Lunchroom P. E., Lunchroom NW	Abated	MISC					
6E	9" x 9" Pink Floor Tile	0		Room 100	Abated	MISC					
6F	9" x 9" Blue Floor Tile - Abated			Room 100	Abated	MISC					
6G	9" x 9" Brown w/Spots Floor Tile - Abated			Main Office Area, Rooms 203 & 205	Abated	MISC					
6H	9" x 9" Brown Striped Floor Tile - Abated			Lunchroom, Rooms 103, 203, 204, 205 & 208	Abated	MISC					
6I	9" x 9" Grey w/Spots Floor Tile - Abated			Rooms 104, 105, 107, 108 & 207	Abated	MISC					
7A	12" x 12" Tan Floor Tile			North Lobby, North Stairwell & North 2nd Floor Hallway	Assumed	MISC					
7B	12" x 12" Light Brown Floor Tile			Room 202, Entrance To 2nd Floor Bathroom	Assumed	MISC					
8	9" x 9" Floor Tile Mastic abated			Throughout Building	Abated	MISC					
8A	12" x 12" Tan Floor Tile Mastic - Abated			North Lobby, North Stairwell & North 2nd Floor Hallway	Abated	MISC					
8B	12" x 12" Light Brown Floor Tile Mastic - Abated			Room 202, Entrance To 2nd Floor Bathroom	Abated	MISC					
8C	9" x 9" Grey Floor Tile Mastic - Abated			Boiler Room Washroom, Center Stairwell & Room 207 & Outside Room 202	Abated	MISC					
8D	9" x 9" White Floor Tile Mastic - Abated			Throughout Corridors & Locker Room	Abated	MISC					
8E	9" x 9" Black Floor Tile Mastic - Abated			Throughout Corridors & Locker Room	Abated	MISC					
8F	9" x 9" Tan w/Spots Floor Tile Mastic - Abated			Rooms 204, 208, & 107, Lunchroom P.	Abated	MISC					

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				E., Lunchroom NW							
8g	9" x 9" Pink Floor Tile Mastic - Abated			Room 100	Abated	MISC					
8h	9" x 9" Blue Floor Tile Mastic - Abated			Room 100	Abated	MISC					
8i	9" x 9" Brown w/Spots Floor Tile Mastic - Abated			Main Office Area, Rooms 203 & 205	Abated	MISC					
8j	9" x 9" Brown Stripe Floor Tile Mastic - Abated			Lunchroom, Rooms 103, 203, 204, & 205	Abated	MISC					
8k	9" x 9" Grey w/Spots Floor Tile Mastic - Abated			Rooms 104, 105, 107, 108 & 207	Abated	MISC					
9	Ceramic Tile Grout			Kitchen/Toilets Throughout	Assumed	MISC					
A	Boiler Insulation - Abated			Boiler Room	Abated	TSI					
B	Tank Insulation abated			Boiler Room	Abated	TSI					
C	Boiler Breeching abated			Boiler Room	Abated	TSI					
D	Joint Compound Off Fiberglass Pipe Insulation			Gym Teacher's Office, Equipment Room & Gym Storage Room	Amosite, Chrysotile	TSI					
E	Duct Manifold			Mechanical Room	Chrysotile	TSI					
EXT	Exterior Brick - Not AHERA			Exterior	Undefined						
EXT-1	Exterior Brick Mortar - Not AHERA			Exterior	Undefined						
F	Insulation Board			Above Ceiling	Assumed	MISC					
G	Vibration Damper	20	LF	2nd. Floor Fan Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
INW	Interior Window Caulk Abated			Throughout Building	Abated	MISC					
OTW	Exterior Window Caulk - Not AHERA			Exterior	Chrysotile	MISC					

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/23/2019
Manager Planner Name	Randy Livingston
100-01934	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
11	
12	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	Repair or Replace as feasible.
26	
27	
28	

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
29	
3	
30	
31	remove or repair damaged materials
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	

Chicago Public Schools

School Shoesmith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
53	
54	
55	
56	
6	
6A	
6B	
6C	
6D	
6E	
6F	
6G	
6H	
6I	
7A	
7B	
8	
8A	
8B	
8C	
8D	
8E	
8F	
8g	
8h	
8i	

Chicago Public Schools

School Shoemith School

Unit 25371

Building ID 5920

Address 1330 E. 50th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
8j	
8k	
9	
A	
B	
C	
D	
E	
EXT	
EXT-1	
F	
G	
INW	
OTW	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11	
MATERIAL DESCRIPTION:	Baseboards	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Baseboards**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Material Not Present

MATERIAL QUANTITY: 0

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12' x 12" Grayish Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Entrance, Washroom		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12' x 12" Grayish Speckled Floor Tile**

MATERIAL LOCATION: **Boiler Room Entrance, Washroom**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12' x 12" Grayish Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Entrance, Washroom		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12' x 12" Grayish Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Boiler Room Entrance, Washroom**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building at Entrance Doors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Throughout Building at Entrance Doors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17	
MATERIAL DESCRIPTION:	Blue/Gray Mixed Carpet Mastic - REMOVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Teacher's Resource Room, Room 206 & Counselor's Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Blue/Gray Mixed Carpet Mastic - REMOVED**

MATERIAL LOCATION: **1st Floor Teacher's Resource Room, Room 206 & Counselor's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	12" x 12" Light Peach Speckled Floor Tile - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Men's Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Light Peach Speckled Floor Tile - ABATED**

MATERIAL LOCATION: **1st Floor Men's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	12" x 12" Light Peach Speckled Floor Tile Mastic - ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Men's Washroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Light Peach Speckled Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1st Floor Men's Washroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Vibration Collar		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Store Room		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Vibration Collar**

MATERIAL LOCATION: **Kitchen Store Room**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Vault Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	28	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **28**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22	
MATERIAL DESCRIPTION:	Interior Fire Doors Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Interior Fire Doors Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23	
MATERIAL DESCRIPTION:	Incinerator Brick	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Incinerator Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Incinerator Brick**

MATERIAL LOCATION: **Incinerator Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	Incinerator Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Incinerator Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Incinerator Brick Mortar**

MATERIAL LOCATION: **Incinerator Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" X 12" White w/Blue Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings		
MATERIAL QUANTITY:	6350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	45	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	25				
MATERIAL DESCRIPTION:	12" X 12" White w/Blue Speckles Floor Tile				
MATERIAL LOCATION:	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings				
MATERIAL QUANTITY:	6350	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	45	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair or Replace as feasible.

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12" X 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings		
MATERIAL QUANTITY:	15170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	26				
MATERIAL DESCRIPTION:	12" X 12" Blue Floor Tile				
MATERIAL LOCATION:	1st - 2nd floor corridors, classrooms, Main Office, Principal's Offices, Lunchroom and Stair Landings				
MATERIAL QUANTITY:	15170	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12" X 12" Purple Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Corridors and Stair Landings		
MATERIAL QUANTITY:	2008	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" X 12" Purple Floor Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridors and Stair Landings**

MATERIAL QUANTITY: **2008**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Mastic Associated with 12" x 12" Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School (HA 25-27)		
MATERIAL QUANTITY:	21400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Mastic Associated with 12" x 12" Floor Tile**

MATERIAL LOCATION: **Throughout School (HA 25-27)**

MATERIAL QUANTITY: **21400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	1' x 1' Off White RPH Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	21400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **1' x 1' Off White RPH Ceiling Tile**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **21400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	Hard Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Hard Plaster**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	1' x 1' Off White RPH Ceiling Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	21400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1' x 1' Off White RPH Ceiling Tile Adhesive**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **21400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	1'x1' White Sm.Fissured w/RPHCeilingTile(Patching)		
HISTORICAL AHERA DAMAGE CATEGORY	4 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 108, 106, 104 and the 2nd Floor North Stairwell and Hallway, Teachers Lounge		
MATERIAL QUANTITY:	130	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	35	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	31				
MATERIAL DESCRIPTION:	1'x1' White Sm.Fissured w/RPHCeilingTile(Patching)				
MATERIAL LOCATION:	Rooms 108, 106, 104 and the 2nd Floor North Stairwell and Hallway, Teachers Lounge				
MATERIAL QUANTITY:	130	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	35	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

remove or repair damaged materials

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	1'x1' White Lg.Fissured w/RPHCeilingTile(Patching)		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor North Stairwell, 104, 106, 203, 206, 208, and Corridors, Teachers Lounge and Janitors clos		
MATERIAL QUANTITY:	283	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	32				
MATERIAL DESCRIPTION:	1'x1' White Lg.Fissured w/RPHCeilingTile(Patching)				
MATERIAL LOCATION:	2nd Floor North Stairwell, 104, 106, 203, 206, 208, and Corridors, Teachers Lounge and Janitors clos				
MATERIAL QUANTITY:	283	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	1'x1' White Med.Fissuredw/RPHCeilingTile(Patching)		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103-106 and the 1st Floor Janitor's Closet		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **1'x1' White Med.Fissuredw/RPHCeilingTile(Patching)**

MATERIAL LOCATION: **Rooms 103-106 and the 1st Floor Janitor's Closet**

MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Chalk/Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Classrooms, Teachers Lounge and Offices		
MATERIAL QUANTITY:	2560	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Chalk/Marker Board Adhesive**

MATERIAL LOCATION: **1st and 2nd Floor Classrooms, Teachers Lounge and Offices**

MATERIAL QUANTITY:	2560	MATERIAL UNITS:	SF
--------------------	-------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	2' x 2' Off-white Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	2900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **2' x 2' Off-white Ceiling Tiles**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **2900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	2' x 2' Off-white Ceiling Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	2900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **2' x 2' Off-white Ceiling Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **2900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pipe Chase in Washrooms

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Pipe Insulation**

MATERIAL LOCATION: **Pipe Chase in Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	1' X 1' Small Fissured Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	101, 103-108, 206, 1st and 2nd FI Corridors, Teachers Lounge and Janitor's Closet		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	1' X 1' Small Fissured Ceiling Tile		
MATERIAL LOCATION:	101, 103-108, 206, 1st and 2nd Fl Corridors, Teachers Lounge and Janitor's Closet		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	1' X 1' Large fissured Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	104, 106, 1st Fl Coridor, 203, 206, 208		
MATERIAL QUANTITY:	253	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **1' X 1' Large fissured Ceiling Tiles**

MATERIAL LOCATION: **104, 106, 1st Fl Corridor, 203, 206, 208**

MATERIAL QUANTITY: **253**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical and Electrical Rooms		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Mechanical and Electrical Rooms**

MATERIAL QUANTITY:	240	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	206		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **206**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Stair Tread Covering		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Stairways and Stage		
MATERIAL QUANTITY:	416	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Stair Tread Covering**

MATERIAL LOCATION: **All Stairways and Stage**

MATERIAL QUANTITY:	416	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Stair Tread Covering Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Stairways and Stage		
MATERIAL QUANTITY:	416	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Stair Tread Covering Mastic**

MATERIAL LOCATION: **All Stairways and Stage**

MATERIAL QUANTITY:	416	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	4" Black vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library		
MATERIAL QUANTITY:	308	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Black vinyl Baseboard**

MATERIAL LOCATION: **Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library**

MATERIAL QUANTITY:	308	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	4" Black vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library		
MATERIAL QUANTITY:	308	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Black vinyl Baseboard Mastic**

MATERIAL LOCATION: **Lunchroom, Offices, 100-108, 202-208, Stage, East Entrance, Library**

MATERIAL QUANTITY:	308	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Chalk Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	100, 102, 104-109, Teachers Lounge and 203-208		
MATERIAL QUANTITY:	1040	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Chalk Board Adhesive**

MATERIAL LOCATION: **100, 102, 104-109, Teachers Lounge and 203-208**

MATERIAL QUANTITY: **1040**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Marker Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	100, 102, 104-109, 203-208		
MATERIAL QUANTITY:	960	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Marker Board Adhesive**

MATERIAL LOCATION: **100, 102, 104-109, 203-208**

MATERIAL QUANTITY: **960**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12" X 12" Beige w/Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms in the mobile trailer unit		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" X 12" Beige w/Brown Specks Floor Tile**

MATERIAL LOCATION: **Classrooms in the mobile trailer unit**

MATERIAL QUANTITY: **1260**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12" X 12" Beige w/Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms in the mobile trailer unit		
MATERIAL QUANTITY:	1260	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12" X 12" Beige w/Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms in the mobile trailer unit**

MATERIAL QUANTITY: **1260**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	5" Beige Base Boards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms in the mobile trailer unit		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **5" Beige Base Boards**

MATERIAL LOCATION: **Classrooms in the mobile trailer unit**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	5" Beige Base Board Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms in the mobile trailer unit		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **5" Beige Base Board Mastic**

MATERIAL LOCATION: **Classrooms in the mobile trailer unit**

MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	4' X 8' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All ceilings in the mobile trailer unit		
MATERIAL QUANTITY:	1518	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **4' X 8' Ceiling Panels**

MATERIAL LOCATION: **All ceilings in the mobile trailer unit**

MATERIAL QUANTITY: **1518**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Insulation In Metal Walls		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Exterior walls in the mobile trailer unit		
MATERIAL QUANTITY:	1780	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Insulation In Metal Walls**

MATERIAL LOCATION: **Exterior walls in the mobile trailer unit**

MATERIAL QUANTITY: **1780**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Yellow Rolled Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrances and Washrooms in the mobile trailer unit		
MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Yellow Rolled Flooring**

MATERIAL LOCATION: **Entrances and Washrooms in the mobile trailer unit**

MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Yellow Rolled Flooring Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrances and Washrooms in the mobile trailer unit		
MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Yellow Rolled Flooring Adhesive**

MATERIAL LOCATION: **Entrances and Washrooms in the mobile trailer unit**

MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Interior Wall Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Interior walls of the mobile trailer unit		
MATERIAL QUANTITY:	760	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Interior Wall Panels**

MATERIAL LOCATION: **Interior walls of the mobile trailer unit**

MATERIAL QUANTITY:	760	MATERIAL UNITS:	SF
--------------------	------------	-----------------	-----------

DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
------------------	----------	---------------	-----------

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	2' x 4' inlay ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	1180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **2' x 4' inlay ceiling tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1180**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6	
MATERIAL DESCRIPTION:	9" x 9" Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: 0

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6A	
MATERIAL DESCRIPTION:	9" x 9" Grey Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	Center Stairwell & Room 207 & Outside Room 202, Incinerator Room, Engineer's Office, Corridors
--------------------	------------------------------------------------------------------------------------------------

MATERIAL QUANTITY:	0	MATERIAL UNITS:
--------------------	---	-----------------

DAMAGE QUANTITY:		DAMAGE UNITS:
------------------	--	---------------

COMMENTS:

Inspector's Signature:	_____	Date:	12/19/2019
------------------------	-------	-------	------------

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 9" Grey Floor Tile**

MATERIAL LOCATION: **Center Stairwell & Room 207 & Outside Room 202, Incinerator Room, Engineer's Office, Corridors**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6B	
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors & Locker Room

MATERIAL QUANTITY: 0 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6B**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile**

MATERIAL LOCATION: **Throughout Corridors & Locker Room**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6C	
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors & Locker Room

MATERIAL QUANTITY: 0

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6C**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Throughout Corridors & Locker Room**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6D	
MATERIAL DESCRIPTION:	9" x 9" Tan w/Spots Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW

MATERIAL QUANTITY: 0 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6D**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Spots Floor Tile**

MATERIAL LOCATION: **Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6E	
MATERIAL DESCRIPTION:	9" x 9" Pink Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100

MATERIAL QUANTITY: 0

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6E**

MATERIAL DESCRIPTION: **9" x 9" Pink Floor Tile**

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6F	
MATERIAL DESCRIPTION:	9" x 9" Blue Floor Tile - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6F**

MATERIAL DESCRIPTION: **9" x 9" Blue Floor Tile - Abated**

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6G	
MATERIAL DESCRIPTION:	9" x 9" Brown w/Spots Floor Tile - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office Area, Rooms 203 & 205

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6G**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Spots Floor Tile - Abated**

MATERIAL LOCATION: **Main Office Area, Rooms 203 & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6H	
MATERIAL DESCRIPTION:	9" x 9" Brown Striped Floor Tile - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom, Rooms 103, 203, 204, 205 & 208

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6H**

MATERIAL DESCRIPTION: **9" x 9" Brown Striped Floor Tile - Abated**

MATERIAL LOCATION: **Lunchroom, Rooms 103, 203, 204, 205 & 208**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6I	
MATERIAL DESCRIPTION:	9" x 9" Grey w/Spots Floor Tile - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 104, 105, 107, 108 & 207

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6I**

MATERIAL DESCRIPTION: **9" x 9" Grey w/Spots Floor Tile - Abated**

MATERIAL LOCATION: **Rooms 104, 105, 107, 108 & 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7A	
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: North Lobby, North Stairwell & North 2nd Floor Hallway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **7A**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **North Lobby, North Stairwell & North 2nd Floor Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7B	
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 202, Entrance To 2nd Floor Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **7B**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Room 202, Entrance To 2nd Floor Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8	
MATERIAL DESCRIPTION:	9" x 9" Floor Tile Mastic abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic abated**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8A	
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: North Lobby, North Stairwell & North 2nd Floor Hallway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic - Abated**

MATERIAL LOCATION: **North Lobby, North Stairwell & North 2nd Floor Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8B	
MATERIAL DESCRIPTION:	12" x 12" Light Brown Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 202, Entrance To 2nd Floor Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8B**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 202, Entrance To 2nd Floor Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8C	
MATERIAL DESCRIPTION:	9" x 9" Grey Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room Washroom, Center Stairwell & Room 207 & Outside Room 202

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8C**

MATERIAL DESCRIPTION: **9" x 9" Grey Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Boiler Room Washroom, Center Stairwell & Room 207 & Outside Room 202**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8D	
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors & Locker Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8D**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Throughout Corridors & Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8E	
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Corridors & Locker Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8E**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Throughout Corridors & Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8F	
MATERIAL DESCRIPTION:	9" x 9" Tan w/Spots Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8F**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Spots Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Rooms 204, 208, & 107, Lunchroom P.E., Lunchroom NW**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8g	
MATERIAL DESCRIPTION:	9" x 9" Pink Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8g**

MATERIAL DESCRIPTION: **9" x 9" Pink Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8h	
MATERIAL DESCRIPTION:	9" x 9" Blue Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8h**

MATERIAL DESCRIPTION: **9" x 9" Blue Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 100**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8i	
MATERIAL DESCRIPTION:	9" x 9" Brown w/Spots Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office Area, Rooms 203 & 205

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8i**

MATERIAL DESCRIPTION: **9" x 9" Brown w/Spots Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Main Office Area, Rooms 203 & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8j	
MATERIAL DESCRIPTION:	9" x 9" Brown Stripe Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom, Rooms 103, 203, 204, & 205

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8j**

MATERIAL DESCRIPTION: **9" x 9" Brown Stripe Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Lunchroom, Rooms 103, 203, 204, & 205**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8k	
MATERIAL DESCRIPTION:	9" x 9" Grey w/Spots Floor Tile Mastic - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 104, 105, 107, 108 & 207

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8k**

MATERIAL DESCRIPTION: **9" x 9" Grey w/Spots Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Rooms 104, 105, 107, 108 & 207**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9	
MATERIAL DESCRIPTION:	Ceramic Tile Grout	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen/Toilets Throughout

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Kitchen/Toilets Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	Boiler Insulation - Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Insulation - Abated**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Tank Insulation abated		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Tank Insulation abated**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C	
MATERIAL DESCRIPTION:	Boiler Breeching abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Breeching abated**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Joint Compound Off Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Amosite, Chrysotile	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym Teacher's Office, Equipment Room & Gym Storage Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Joint Compound Off Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Gym Teacher's Office, Equipment Room & Gym Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E	
MATERIAL DESCRIPTION:	Duct Manifold	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Mechanical Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Duct Manifold**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	EXT	
MATERIAL DESCRIPTION:	Exterior Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **EXT**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	EXT-1	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Undefined	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **EXT-1**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F	
MATERIAL DESCRIPTION:	Insulation Board	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Above Ceiling

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Insulation Board**

MATERIAL LOCATION: **Above Ceiling**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Vibration Damper		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd. Floor Fan Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Vibration Damper**

MATERIAL LOCATION: **2nd. Floor Fan Room**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	INW	
MATERIAL DESCRIPTION:	Interior Window Caulk Abated	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **INW**

MATERIAL DESCRIPTION: **Interior Window Caulk Abated**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/23/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Shoesmith School	INSPECTION DATE:	12/19/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	OTW	
MATERIAL DESCRIPTION:	Exterior Window Caulk - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 12/19/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25371	BUILDING ID:	5920
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston		
SCHOOL NAME:	Shoesmith School	REVIEW DATE:	12/23/2019		
ADDRESS:	1330 E. 50th St.	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **OTW**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 12/23/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Randolph Livingston


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 10/24/2019

Exam Date: 10/24/2019

Expiration Date: 10/24/2020

Certificate Number: MPR1910242073



Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 01934

ISSUED
11/5/2019

EXPIRES
05/15/2020

RANDOLPH LIVINGSTON
9549 S. EUCLID AVE
CHICAGO, IL 60617

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

2/6/2020

MANAGEMENT PLANNER

10/24/2020

PROJECT MANAGER

5/4/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed