ILLINOIS DEPARTMENT OF PUBLIC HEALTH AHERA THREE YEAR REINSPECTION ASBESTOS ABATEMENT PROGRAM SCHOOL INFORMATION FORM

CHICAGO SCHOOL DIST 299

SECTION I

NAME OF SCHOOL DISTRICT:

SCHOOL ID NUMBER: 14-016-2990-2442 **SCHOOL NAME:** Schmid School ADDRESS OF SCHOOL: 9755 S Greenwood CITY: Chicago, IL, 60628 DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/22/2016 If the address on this form is different than the address of the building, submit a written explanation. **SECTION II** (Please type or print) PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION: DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 199 IDPH INSPECTOR LICENSE NUMBER: 100-11070 IDPH LICENSED INSPECTOR NAME(Please Print): Mallory Jones IDPH MP LICENSE NUMBER: 100-09786 IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197 Lander 10/1/2019 Signature of Designated Person Date **SECTION III** PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT. School building has been sold. Date of Sale: School has been closed. Date closed: School building has been demolished. Date: School building is <u>asbestos free</u> since last reinspection: Please explain in writing why the school building is now asbestos free and include the supporting documentation. If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building. Explain in writing if the address of the building is different than the address on this form:

IL-482-1026 Revised 10.03

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Schmid School

9755 S Greenwood Chicago, IL, 60628

Unit: 25391 Building ID: 5950

IDPH ID Number: 14-016-2990-2442

REPORT DATE:

Tuesday, October 01, 2019

Prepared for: Chicago Public Schools 42 West Madison Street Chicago, IL 60602

Prepared by: TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

DO NOT REMOVE FROM SCHOOL REQUIRED BY FEDERAL LAW

August 22, 2019

Mr. Glen E. Garner Asbestos Program Illinois Department of Public Health 525 West Jefferson Street Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25391 Region: 06 IDPH ID:14-016-2990-2442

School: Schmid School Building ID: 5950

Address: 9755 S Greenwood

Chicago, IL, 60628

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/18/2019

Inspector: Mallory Jones Inspector IDPH License: 100-11070

Management Planner: John Fenn Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,

TEM Environmental, Inc.

John Fenn 100-09786

Environmental Notification to Occupants

To: Faculty, Staff and Parents From: Chicago Public Schools Date: August 22, 2019

RE: Schmid School, Unit 25391

9755 S Greenwood Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Schmid School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Schmid School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Schmid School Unit: 25391 Region: 06

Address: 9755 S Greenwood Chicago, IL, 60628 Building ID: 5950

Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:

Total Square Footage: No of Floors:

Current Occupancy: 199

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197

Address: 42 West Madison Street Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc. Contact: Steven Geneser Address 174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Mallory Jones

Signature:

Inspector IDPH license # 100-11070 Date: 8/22/2019

6. Management Planner

Management Planner Name: John Fenn

Signature:

Management Planner IDPH license # 100-09786 Date: 09/18/2019

7. Review Date:09/18/2019

8. LEA Designated Person's Acknowledgement

fluchote

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Schmid School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5950:

B. The following new homogenous areas have been identified for Building 5950:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	10v10 Dust w/White Speaks Floor Tile
03A	12x12 Rust w/White Specks Floor Tile
	12x12 Brown w/White Specks Floor Tile
03B	12x12 Cream Floor Tile
05	12x12 Rust w/White Specks Floor Tile Mastic
07	drywall
08	Dark Brown Vinyl Baseboard
08A	Beige Vinyl Baseboard
09	Dark Brown Vinyl Baseboard Mastic
09A	Beige Vinyl Baseboard Mastic
10	2x4 Ceiling Tile
11	Purple Carpet Mastic
12	Carpet Mastic
13	Orange/Brown Carpet Mastic - Not Observed
14	Red Carpet Mastic - Not Observed
15	9x9 Dark Brown Floor Tile
16	9x9 Dark Floor Tile Mastic
17	12"X 12" Beige w/Gray Specks Floor Tile
18	12"X 12" Beige w/Gray Specks Floor Tile Mastic
19	Beige Flooring Mastic
20	Gray Flooring Mastic
21	Yellow, Brown & Beige Ceramic Tile Grout
22	Yellow, Brown and Beige Ceramic Tile Adhesive
23	Grey and Black Speckled Terrazzo
24	12x12 Blue Floor Tile
24M	12 x 12 Blue Floor Tile Mastic
25	Beige and Tan Ceramic Tile Grout
26	Beige and Tan Ceramic Tile Grout
27	Gray Baseboard
27A	Gray Baseboard Adhesive
28	Red Ceramic Tile Grout
29	Red Ceramic Tile Adhesive
30	12x12 White w/Blue and Red Speckles Floor Tile
30M	12x12 White w/Blue and Red Speckles Floor Tile
	Mastic
31	Beige Flooring
32	Gray Flooring
33	12" X 12" White w/Blue Specks Vinyl Floor Tile
34	12" x 12" White w/Blue Specks Mastic
35	12" x 12" Cream w/Tan Specks Vinyl Floor Tile
36	12" X 12" Cream w/Tan Specks Mastic
37	Fire Doors

The following areas were deemed to be inaccessible:

12x12 Rust w/White Specks Floor Tile Mastic
12x12 Brown w/White Specks Floor Tile Mastic
12x12 Cream Floor Tile Mastic
9x9 Light Brown w/Specks Floor Tile Mastic
Dark Brown Vinyl Baseboard Mastic
Beige Vinyl Baseboard Mastic
Purple Carpet Mastic
Carpet Mastic
Orange/Brown Carpet Mastic - Not Observed
9x9 Dark Brown Floor Tile
9x9 Dark Floor Tile Mastic
12"X 12" Beige w/Gray Specks Floor Tile
12"X 12" Beige w/Gray Specks Floor Tile Mastic
Beige Flooring Mastic
Gray Flooring Mastic
Yellow, Brown and Beige Ceramic Tile Adhesive
12 x 12 Blue Floor Tile Mastic
Beige and Tan Ceramic Tile Grout
Gray Baseboard Adhesive
Red Ceramic Tile Adhesive
12x12 White w/Blue and Red Speckles Floor Tile
Mastic
Gray Flooring
Fire Doors

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

- 1. Review current management plan, identify HA(s) and extract appropriate information.
- 2. Examine and verify abatement records.
- 3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
- 4. Touchand visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
- 5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
- 6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
- 7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
- 8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Schmid School Building 5950 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I Inspector's Reinspection Findings

School Schmid School Unit 25391 Building ID 5950
Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	12x12 Rust w/White Specks Floor Tile	2,804	SF	Annex Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	12x12 Brown w/White Specks Floor Tile	5,198	SF	Annex Building- All classrooms (except 406,404) and 1/2 Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03B	12x12 Cream Floor Tile	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	9x9 Light Brown w/Specks Floor Tile	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	12x12 Rust w/White Specks Floor Tile Mastic	2,804	SF	Annex Building- 1st Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12x12 Brown w/White Specks Floor Tile Mastic	5,198	SF	Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	12x12 Cream Floor Tile Mastic	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9x9 Light Brown w/Specks Floor Tile Mastic	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	drywall	36,000	SF	Throughout Annex Building, Covered with Metal)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Dark Brown Vinyl Baseboard	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	Beige Vinyl Baseboard	86	LF	Annex Building- Principal's Office, Store Room in Main	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

School Schmid School Unit 25391 Building ID 5950
Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
09	Dark Brown Vinyl Baseboard Mastic	145	LF	Office Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	Beige Vinyl Baseboard Mastic	86	LF	Annex Building- Principal's Office, Store Rooms in Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	2x4 Ceiling Tile	18,000	SF	Throughout Buildings; Annex Building- Engineer's Office/Washroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
11	Purple Carpet Mastic	2,222	SF	Annex Building- Room 411, Library, Detention Room 404, Room 403	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Carpet Mastic	395	SF	Annex Building- Main Office, Principal's Office, Main Office Store Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Orange/Brown Carpet Mastic - Not Observed			Annex Building- Room 403	ASSUMED	MISC								
14	Red Carpet Mastic - Not Observed			Annex Building- Main Office	ASSUMED	MISC					No			
15	9x9 Dark Brown Floor Tile	100	SF	Main Building- Engineer's Office Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9x9 Dark Floor Tile Mastic	100	SF	Main Building- Engineer's Office Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"X 12" Beige w/Gray Specks Floor Tile	300	SF	Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"X 12" Beige w/Gray Specks Floor Tile Mastic	300	SF	Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Beige Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

School Schmid School Unit 25391 Building ID 5950
Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	Gray Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Yellow, Brown & Beige Ceramic Tile Grout	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Yellow, Brown and Beige Ceramic Tile Adhesive	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Grey and Black Speckled Terrazzo	2,176	SF	1st and 2nd Floor Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12x12 Blue Floor Tile	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
24M	12 x 12 Blue Floor Tile Mastic	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Bldg) and Main Office, Kitchen (ANNEX)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Beige and Tan Ceramic Tile Grout	960	SF	Annex- Boys and Girls Restrooms, Teacher's Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Beige and Tan Ceramic Tile Grout	960	SF	Annex- Boys and Girls Restrooms, Teacher's Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Gray Baseboard	136	LF	Annex Building- E- W Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	Gray Baseboard Adhesive	136	LF	Annex Building- E- W Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Red Ceramic Tile Grout	120	SF	Annex Building- North and South Entrances	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
29	Red Ceramic Tile Adhesive	120	SF	Annex Building- North and South Entrances	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

School Schmid School Unit 25391 Building ID 5950
Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30	12x12 White w/Blue and Red Speckles Floor Tile	416	SF	Annex Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30M	12x12 White w/Blue and Red Speckles Floor Tile Mastic	416	SF	Annex Building- Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Beige Flooring	1,100	SF	1st Floor Corridor, Assistant Principal's Office (Room 101)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
32	Gray Flooring	1,100	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
33	12" X 12" White w/Blue Specks Vinyl Floor Tile	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	12" x 12" White w/Blue Specks Mastic	530	SF	Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12" x 12" Cream w/Tan Specks Vinyl Floor Tile	100	SF	Room 102/ Principal's Office, Stage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" X 12" Cream w/Tan Specks Mastic	100	SF	Rm 102/ Principal's Office, Stage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Fire Doors	80	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

School Schmid School Unit 25391 Building ID 5950

Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/22/2019

Inspector Name Mallory Jones

<u>100-11070</u> <u>5/15/2020</u>

Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
03	•
03A	
03B	
04	
05	
05A	
05B	
06	
07	
08	
A80	
09	
09A	
10	
11	
12	
13	Not Observed 2019
14	Not observed 2019
15	
16	
17	
18	
19	

School Schmid School Unit 25391 Building ID 5950
Address 9755 S Greenwood Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA Number:	Inspector Comments:
20	
21	
22	
23	
24	
24M	
25	
26	
27	
27A	
28	
29	
30	
30M	
31	Principal's Office has Hardwood Floor
32	
33	
34	
35	
36	
37	

Table II

Management Planner's Review

SchoolSchmid SchoolUnit25391Building ID5950

Address9755 S GreenwoodChicago, IL, 60628Region06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

							<u> </u>			ments Summarized at th	
łΑ	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
lumber		Quantity	Units		Type	Category		Quantity	Units		
3	12x12 Rust w/White Specks Floor Tile	2,804	SF	Annex Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	12x12 Brown w/White Specks Floor Tile	5,198	SF	Annex Building- All classrooms (except 406,404) and 1/2 Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3B	12x12 Cream Floor Tile	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9x9 Light Brown w/Specks Floor Tile	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	12x12 Rust w/White Specks Floor Tile Mastic	2,804	SF	Annex Building- 1st Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A	12x12 Brown w/White Specks Floor Tile Mastic	5,198	SF	Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5B	12x12 Cream Floor Tile Mastic	5,198	SF	All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9x9 Light Brown w/Specks Floor Tile Mastic	4,000	SF	Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	drywall	36,000	SF	Throughout Annex Building, Covered with Metal)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3	Dark Brown Vinyl Baseboard	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
8A	Beige Vinyl Baseboard	86	LF	Annex Building- Principal's Office, Store Room in Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
9	Dark Brown Vinyl Baseboard Mastic	145	LF	Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
9A	Beige Vinyl Baseboard Mastic	86	LF	Annex Building- Principal's Office, Store Rooms in Main Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
)	2x4 Ceiling Tile	18,000	SF	Throughout Buildings; Annex Building- Engineer's Office/Washroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
	Purple Carpet Mastic	2,222	SF	Annex Building- Room 411, Library, Detention Room 404, Room 403	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2	Carpet Mastic	395	SF	Annex Building- Main Office, Principal's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

SchoolSchmid SchoolUnit25391Building ID5950

Address 9755 S Greenwood Chicago, IL, 60628 Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

НА	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Number	material Besonption	Quantity	Units	material Education	Type	Category	Triable	Quantity	Units	Damage Gategory	Response
Hullibei		Quantity	Office	Office, Main Office Store Rooms	Турс	Category		Quantity	Office		
13	Orange/Brown Carpet Mastic - Not Observed		-	Annex Building- Room 403	Assumed	MISC					
4	Red Carpet Mastic - Not Observed		-	Annex Building-Main Office	Assumed	MISC					
15	9x9 Dark Brown Floor Tile	100	SF	Main Building- Engineer's Office Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9x9 Dark Floor Tile Mastic	100	SF	Main Building- Engineer's Ofiice Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"X 12" Beige w/Gray Specks Floor Tile	300	SF	Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"X 12" Beige w/Gray Specks Floor Tile Mastic	300	SF	Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Beige Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Gray Flooring Mastic	1,100	SF	Main Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Yellow, Brown & Beige Ceramic Tile Grout	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Yellow, Brown and Beige Ceramic Tile Adhesive	1,684	SF	Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet, NE and SE Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Grey and Black Speckled Terrazzo	2,176	SF	1st and 2nd Floor Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Blue Floor Tile	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24M	12 x 12 Blue Floor Tile Mastic	2,936	SF	2nd Floor Corridor, Teachers Lounge (Main Bldg) and Main Office, Kitchen (ANNEX)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Beige and Tan Ceramic Tile Grout	960	SF	Annex- Boys and Girls Restrooms, Teacher's Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Beige and Tan Ceramic Tile Grout	960	SF	Annex- Boys and Girls Restrooms, Teacher's Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Gray Baseboard	136	LF	Annex Building- E-W Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
27A	Gray Baseboard Adhesive	136	LF	Annex Building- E-W Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28	Red Ceramic Tile Grout	120	SF	Annex Building- North and South Entrances	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

SchoolSchoolUnit25391Building ID5950

Address 9755 S Greenwood Chicago, IL, 60628 Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Number		Quantity	Units		Туре	Category		Quantity	Units		
29	Red Ceramic Tile Adhesive	120	SF	Annex Building- North and South	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Entrances							
30	12x12 White w/Blue and Red Speckles Floor Tile	416	SF	Annex Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	12x12 White w/Blue and Red Speckles Floor Tile	416	SF	Annex Building- Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
	Mastic										
31	Beige Flooring	1,100	SF	1st Floor Corridor, Assistant Principal's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Office (Room 101)							
32	Gray Flooring	1,100	SF	1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" X 12" White w/Blue Specks Vinyl Floor Tile	530	SF	Main Building- 2nd Floor Corridor, 2nd	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Floor Teachers' Lounge							
34	12" x 12" White w/Blue Specks Mastic	530	SF	Main Building- 2nd Floor Corridor, 2nd	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Floor Teachers' Lounge							
35	12" x 12" Cream w/Tan Specks Vinyl Floor Tile	100	SF	Room 102/ Principal's Office, Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
				Room							
36	12" X 12" Cream w/Tan Specks Mastic	100	SF	Rm 102/ Principal's Office, Stage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Fire Doors	80	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

 School
 School
 Unit
 25391
 Building ID
 5950

 Address
 9755 S Greenwood
 Chicago, IL, 60628
 Region
 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Review Date	09/18/2019	
Manager Planner Name	John Fenn	
100-09786	5/15/2020	
Manager IDPH License No/Expiration		

HA Number	Management Comments
03	
03A	
03B	
04	
05	
05A	
05B	
06	
07	
08	
08A	
09	
09A	
10	
11	
12	
13	
14	
15	

 School
 Schmid School
 Unit
 25391
 Building ID
 5950

 Address
 9755 S Greenwood
 Chicago, IL, 60628
 Region
 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

HA Number	Management Comments
16	
17	
18	
19	
20	
21	
22	
23	
24	
24M	
25	
26	
27	
27A	
28	
29	
30	
30M	
31	
32	
33	
34	
35	
36	
37	

 School
 Schmid School
 Unit
 25391
 Building ID
 5950

 Address
 9755 S Greenwood
 Chicago, IL, 60628
 Region
 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

TEM Environmental, Inc. 2019 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03

MATERIAL DESCRIPTION: 12x12 Rust w/White Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- 1st Floor Corridor

MATERIAL QUANTITY: 2804 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	 Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S	Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS A	REA:	03			
MATERIAL DESCRI	PTION:	12x12 Rust w	/White Specks Floor Tile		
MATERIAL LOCATION	ON:	Annex Buildin	ng- 1st Floor Corridor		
MATERIAL QUANTI	TY:	2804		MATERIAL UNITS:	SF
DAMAGE QUANTIT	Y:	0		DAMAGE UNITS:	SF
management planner original inspection of t the following recomme	to review he above endations.	the results of th identified homo	of the Asbestos Hazard Emergenc e inspection and assessment and r geneous area has been reviewed in	ecommend appropriate res	ponse actions. The
The RESPONSE AC	TION rec	ommendation is	:		
Follow O&M Plan					
Comments:					
Management Plan	ner's Sig	nature:		Date: 09/18 /	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03A

MATERIAL DESCRIPTION: 12x12 Brown w/White Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- All classrooms (except 406,404) and 1/2 Main Office

MATERIAL QUANTITY: 5198 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:		Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA: 03A			
MATERIAL DESCRIF	PTION: 12x12 Brown v	v/White Specks Floor Tile		
MATERIAL LOCATIO	N: Annex Buildin	g- All classrooms (except 40	6,404) and 1/2 Main Office	
MATERIAL QUANTIT	Y: 5198		MATERIAL UNITS:	SF
DAMAGE QUANTITY	′ : 0		DAMAGE UNITS:	SF
management planner t	o review the results of the ne above identified homog	inspection and assessment a	ency Response Act (AHERA) t nd recommend appropriate res ed in accordance with Sections	ponse actions. The
The RESPONSE ACT	ΓΙΟΝ recommendation is:			
Follow O&M Plan				
Comments:				
Management Plann	er's Signature:		Date:09/18/	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03B

MATERIAL DESCRIPTION: 12x12 Cream Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's

Office, Washroom (Annex Building)

MATERIAL QUANTITY: 5198 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:	Date:	08/22/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Managament Blannar Baylow Form

		wana	gement Plan	ner Revi	ew Form			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	25391	BUIDLING ID:	5950		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PI	_ANNER:	John Fenn			
SCHOOL NAME:	Schmid	School	REVIEW DATE:		9/18/2019			
ADDRESS:	9755 S G	Greenwood	IDPH LICENSE NO) :	100-11070			
HOMOGENEOUS A	REA:	03B						
MATERIAL DESCRI	PTION:	12x12 Cream Flo	oor Tile					
MATERIAL LOCATION	ON:	All Classrooms (Washroom (Ann		, and 1/2 of Ma	ain Office; Main	Building	Engineer's Office,	
MATERIAL QUANTI	TY:	5198			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	Y :	0			DAMAGE UNIT	S:	SF	
he following recomme The RESPONSE AC Follow O&M Plan Comments:	endations.	_					763.88 and 763.90 with	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 04

MATERIAL DESCRIPTION: 9x9 Light Brown w/Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room

MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

nspector's Signature:		Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	04			
MATERIAL DESCRIP	PTION:	9x9 Light Brow	n w/Specks Floor Tile		
MATERIAL LOCATIO	N:	Annex Building	g- Gym/Lunchroom, Kitchen, En	gineer's Office, Store Ro	om
MATERIAL QUANTIT	ΓΥ:	4000		MATERIAL UNITS:	SF
DAMAGE QUANTITY	′ :	0		DAMAGE UNITS:	SF
management planner t	o review the above	the results of the	f the Asbestos Hazard Emergency inspection and assessment and re eneous area has been reviewed in	commend appropriate res	ponse actions. The
The RESPONSE ACT	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Plann	ner's Sigi	nature:		Date: <u>09/18/</u>	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05

MATERIAL DESCRIPTION: 12x12 Rust w/White Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- 1st Floor Corridors

MATERIAL QUANTITY: 2804 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

nspector's Signature:	Date:	08/22/2019

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE: Chicago,		o, Illinois	MANAGEMENT PLANNER:	John Fenn				
SCHOOL NAME: Schmid Sc		School	REVIEW DATE:	9/18/2019				
ADDRESS: 9755 S G		Greenwood IDPH LICENSE NO: 100-1		100-11070	-11070			
HOMOGENEOUS AREA:		05						
MATERIAL DESCRIPTION:		12x12 Rust w/White Specks Floor Tile Mastic						
MATERIAL LOCATION:		Annex Building- 1st Floor Corridors						
MATERIAL QUANTITY:		2804 MAT		MATERIAL UNITS:	SF			
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF			
management planner t	o review to above	the results of the identified homog	of the Asbestos Hazard Emergency inspection and assessment and re eneous area has been reviewed in	ecommend appropriate resp	oonse actions. The			
The RESPONSE AC	TION reco	ommendation is:						
Follow O&M Plan								
Comments:								
Management Planr	ner's Sigı	nature:		Date:09/18/	2019			

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05A

MATERIAL DESCRIPTION: 12x12 Brown w/White Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- All Classrooms (except 406, 404) and 1/2 Main Office

MATERIAL QUANTITY: 5198 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

nspector's Signature:	 	Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME: Schmid School		REVIEW DATE:	REVIEW DATE: 9/18/2019							
ADDRESS:	9755 S Greenwood	IDPH LICENSE NO:	100-11070							
HOMOGENEOUS AF	REA: 05A									
MATERIAL DESCRIP	PTION: 12x12 Brown	w/White Specks Floor Tile N	lastic							
MATERIAL LOCATIO	N: Annex Buildi	ng- All Classrooms (except 4	106, 404) and 1/2 Main Office							
MATERIAL QUANTIT	Y: 5198		MATERIAL UNITS:	SF						
DAMAGE QUANTITY	′: 0		DAMAGE UNITS:	SF						
management planner t original inspection of th	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.									
The RESPONSE AC	FION recommendation is	5:								
Follow O&M Plan										
Comments:										
Management Planr	ner's Signature:		Date: 09/18/	2019						

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 05B

MATERIAL DESCRIPTION: 12x12 Cream Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's

Office, Washroom (Annex Building)

MATERIAL QUANTITY: 5198 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	Date:	08/22/2019
	 _	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: Chicago Public Schools UNIT NUMBER: BUIDLING ID: 5950 25391 CITY/STATE: Chicago, Illinois MANAGEMENT PLANNER: John Fenn SCHOOL NAME: **Schmid School** REVIEW DATE: 9/18/2019 ADDRESS: IDPH LICENSE NO: 9755 S Greenwood 100-11070 HOMOGENEOUS AREA: 05B 12x12 Cream Floor Tile Mastic MATERIAL DESCRIPTION: MATERIAL LOCATION: All Classrooms (Except 404 & 406), and 1/2 of Main Office; Main Building Engineer's Office, Washroom (Annex Building) MATERIAL QUANTITY: 5198 MATERIAL UNITS: SF DAMAGE QUANTITY: 0 DAMAGE UNITS: SF In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations. The RESPONSE ACTION recommendation is: Follow O&M Plan Comments:

Date: 09/18/2019

Management Planner's Signature:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06

MATERIAL DESCRIPTION: 9x9 Light Brown w/Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Gym/Lunchroom, Kitchen, Engineer's Office, Store Room

MATERIAL QUANTITY: 4000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Chicago Public Schools UNIT NUMBER:

LEA NAME:

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois		MANAGEMENT PLANNER:								
SCHOOL NAME: Schmid School		REVIEW DATE:	9/18/2019							
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070						
HOMOGENEOUS AF	REA:	06								
MATERIAL DESCRIP	PTION:	9x9 Light Brov	vn w/Specks Floor Tile Mastic							
MATERIAL LOCATIO	DN:	Annex Buildin	g- Gym/Lunchroom, Kitchen, En	ngineer's Office, Store Ro	om					
MATERIAL QUANTIT	ΓΥ:	4000		MATERIAL UNITS:	SF					
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF					
management planner t original inspection of th	n accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.									
	HON TEC	ommendation is.								
Follow O&M Plan										
Comments:										
Management Planr	ner's Sigi	nature:		Date: _09/18/	2019					

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: drywall

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Throughout Annex Building, Covered with Metal)

MATERIAL QUANTITY: 36000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn							
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019							
ADDRESS:	9755 S	Greenwood	IDPH LICENSE NO:	100-11070							
HOMOGENEOUS AF	REA:	07									
MATERIAL DESCRIP	PTION:	drywall									
MATERIAL LOCATIO	DN:	Throughout Ann	Throughout Annex Building, Covered with Metal)								
MATERIAL QUANTIT	ΓY:	36000		MATERIAL UNITS:	SF						
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF						
management planner t	o review ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency F nspection and assessment and reco neous area has been reviewed in a	ommend appropriate	response actions. The						
The RESPONSE AC	TION reco	ommendation is:									
Follow O&M Plan											
Comments:											
Commonte.											
Management Planr	ner's Sigi	nature:		Date: <u>09</u> /	/18/2019						

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08

MATERIAL DESCRIPTION: Dark Brown Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom

MATERIAL QUANTITY: 145 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:	 	_ Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

Chicago Public Schools UNIT NUMBER:

LEA NAME:

BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois		MANAGEMENT PLANNER:	John Fenn		
SCHOOL NAME:	SCHOOL NAME: Schmid School		REVIEW DATE:	9/18/2019	
ADDRESS: 9755 S Greenwood		IDPH LICENSE NO:	100-11070		
HOMOGENEOUS AF	REA:	08			
MATERIAL DESCRI	PTION:	Dark Brown Viny	/I Baseboard		
MATERIAL LOCATION	ON:	Annex Building-	Engineer's Office/Washroom, St	ore Room, Main Office \	Vashroom
MATERIAL QUANTIT	ΓY:	145		MATERIAL UNITS:	LF
DAMAGE QUANTITY	Y:	0		DAMAGE UNITS:	LF
management planner t	to review ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency Raspection and assessment and reconneous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sig	nature:		Date: 09/18/2	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08A

MATERIAL DESCRIPTION: Beige Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Principal's Office, Store Room in Main Office

MATERIAL QUANTITY: 86 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:	Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE: Chicago, Illinois		o, Illinois	MANAGEMENT PLANNER: John Fenn		
SCHOOL NAME: Schmid School		School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	08A			
MATERIAL DESCRIP	PTION:	Beige Vinyl Base	eboard		
MATERIAL LOCATIO	ON:	Annex Building-	Principal's Office, Store Room i	n Main Office	
MATERIAL QUANTIT	ΓΥ:	86		MATERIAL UNITS:	LF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	LF
management planner t original inspection of the the following recomme	o review ne above ndations.	the results of the ir identified homoger	the Asbestos Hazard Emergency F espection and assessment and rec neous area has been reviewed in a	ommend appropriate res	sponse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/18	3/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 09

MATERIAL DESCRIPTION: Dark Brown Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Engineer's Office/Washroom, Store Room, Main Office Washroom

MATERIAL QUANTITY: 145 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Chicago Public Schools UNIT NUMBER:

LEA NAME:

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois		o, Illinois	MANAGEMENT PLANNER: John Fenn		
SCHOOL NAME:	SCHOOL NAME: Schmid School		REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	09			
MATERIAL DESCRIP	PTION:	Dark Brown Viny	/I Baseboard Mastic		
MATERIAL LOCATIO	ON:	Annex Building-	Engineer's Office/Washroom, St	tore Room, Main Offi	ce Washroom
MATERIAL QUANTIT	ΓΥ:	145		MATERIAL UNITS:	LF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	LF
management planner t original inspection of the the following recomme	o review ne above ndations.	the results of the in identified homoger	the Asbestos Hazard Emergency F espection and assessment and rece neous area has been reviewed in a	ommend appropriate re	esponse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/ 1	8/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 09A

MATERIAL DESCRIPTION: Beige Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Principal's Office, Store Rooms in Main Office

MATERIAL QUANTITY: 86 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	09A			
MATERIAL DESCRI	PTION:	Beige Vinyl Base	eboard Mastic		
MATERIAL LOCATIO	ON:	Annex Building-	Principal's Office, Store Rooms	in Main Office	
MATERIAL QUANTIT	ΓY:	86		MATERIAL UNITS:	LF
DAMAGE QUANTITY	Y:	0		DAMAGE UNITS:	LF
management planner t	to review t ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency Raspection and assessment and reconneous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/18/2	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10

MATERIAL DESCRIPTION: 2x4 Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Throughout Buildings; Annex Building- Engineer's Office/Washroom

MATERIAL QUANTITY: 18000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:	Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	10			
MATERIAL DESCRIP	PTION:	2x4 Ceiling Ti	le		
MATERIAL LOCATIO	N:	Throughout B	Buildings; Annex Building- Engine	eer's Office/Washroom	
MATERIAL QUANTIT	ΓY:	18000		MATERIAL UNITS:	SF
DAMAGE QUANTITY	' :	0		DAMAGE UNITS:	SF
management planner t	o review the above	the results of the	of the Asbestos Hazard Emergency e inspection and assessment and re geneous area has been reviewed in	ecommend appropriate res	ponse actions. The
The RESPONSE ACT	TION reco	ommendation is	:		
Follow O&M Plan					
Comments:					
Management Plann	ner's Sigi	nature:		Date: 09/18/	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: Purple Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Room 411, Library, Detention Room 404, Room 403

MATERIAL QUANTITY: 2222 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

Chicago Public Schools UNIT NUMBER:

LEA NAME:

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	11			
MATERIAL DESCRIP	PTION:	Purple Carpet Ma	astic		
MATERIAL LOCATIO	ON:	Annex Building-	Room 411, Library, Detention Ro	oom 404, Room 403	
MATERIAL QUANTIT	ΓΥ:	2222		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	to review the above	the results of the in identified homoger	the Asbestos Hazard Emergency R spection and assessment and reco leous area has been reviewed in ac	ommend appropriate resp	oonse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/18/ 2	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: Carpet Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Main Office, Principal's Office, Main Office Store Rooms

MATERIAL QUANTITY: 395 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:			Date:	08/22/2019	
	-				

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools		UNIT NUMBER:	BUIDLING ID:	BUIDLING ID: 5950		
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PI	_ANNER:	John Fenn		
SCHOOL NAME: Schmid School		REVIEW DATE: 9/18/		9/18/2019	18/2019		
ADDRESS:	9755 S	Greenwood	IDPH LICENSE NO):	100-11070		
HOMOGENEOUS A	REA:	12					
MATERIAL DESCRI	PTION:	Carpet Mastic					
MATERIAL LOCATION	ON:	Annex Building-	Main Office, Princ	ipal's Office, I	Main Office Store	Rooms	
MATERIAL QUANTI	TY:	395			MATERIAL UNI	TS: SF	!
DAMAGE QUANTIT	Υ:	0			DAMAGE UNITS	S: SF	
n accordance with Semanagement planner original inspection of the following recomme	to review the above	the results of the in identified homoger	nspection and asses	sment and rec	commend appropri	ate response	actions. The
The RESPONSE AC	CTION rec	ommendation is:					
Comments:							
Management Plan	ner's Sig	nature:			Date: _	09/18/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 25391 **BUIDLING ID:** 5950 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Mallory Jones** SCHOOL NAME: **Schmid School** INSPECTION DATE: 8/22/2019 ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070 INFORMATION FROM PREVIOUS INSPECTION 13 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: Orange/Brown Carpet Mastic - Not Observed HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: **Assumed** RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: **Annex Building- Room 403** MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE UNITS: DAMAGE QUANTITY: COMMENTS: Not Observed 2019

Date:

Inspector's Signature:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAIVIE.	Chicago Public Schools		UNIT NUMBER. 25391		BUIDLING ID. 3930	
CITY/STATE:	CITY/STATE: Chicago, Illinois		MANAGEMENT PL	_ANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:		9/18/2019	
ADDRESS:	9755 S	Greenwood	IDPH LICENSE NO):	100-11070	
HOMOGENEOUS A	REA:	13				
MATERIAL DESCRI	PTION:	Orange/Brown C	Carpet Mastic - Not	Observed		
MATERIAL LOCATION	ON:	Annex Building-	Room 403			
MATERIAL QUANTI	TY:				MATERIAL UNITS:	
DAMAGE QUANTIT	Y:				DAMAGE UNITS:	
nanagement planner	to review he above endations.	the results of the ir identified homoger	nspection and asses	sment and reco	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with	
Comments:						
Management Plan	ner's Sig	nature:			Date: 09/18/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: 25391 **BUIDLING ID:** 5950 CITY/STATE: Chicago, Illinois AHERA INSPECTOR: **Mallory Jones** SCHOOL NAME: **Schmid School** INSPECTION DATE: 8/22/2019 ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070 INFORMATION FROM PREVIOUS INSPECTION 14 **HOMOGENEOUS AREA:** MATERIAL DESCRIPTION: **Red Carpet Mastic - Not Observed** HISTORICAL AHERA DAMAGE CATEGORY HISTORICAL DAMAGE REASON: HISTORICAL RESPONSE ACTION: **ASBESTOS TYPE:** FRIABLE: **Assumed** RESULTS OF REINSPECTION AND REASSESSMENT This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection. The current AHERA DAMAGE CATEGORY is determined to be . DAMAGE REASON: **DISTURBANCE POTENTIAL:** MATERIAL LOCATION: **Annex Building- Main Office** MATERIAL QUANTITY: MATERIAL UNITS: DAMAGE UNITS: DAMAGE QUANTITY: COMMENTS: Not observed 2019

Date:

Inspector's Signature:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 25391	BUIDLING ID: 5950
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	John Fenn
SCHOOL NAME:	Schmid School	REVIEW DATE:	9/18/2019
ADDRESS:	9755 S Greenwood	IDPH LICENSE NO:	100-11070
HOMOGENEOUS A	REA: 14		
MATERIAL DESCRI	PTION: Red Carpet Mas	tic - Not Observed	
MATERIAL LOCATION	ON: Annex Building	- Main Office	
MATERIAL QUANTI	TY:		MATERIAL UNITS:
DAMAGE QUANTITY	Y:		DAMAGE UNITS:
management planner original inspection of the the following recomment	to review the results of the in the above identified homogen	nspection and assessment and rec	Response Act (AHERA) the LEA must select a commend appropriate response actions. The accordance with Sections 763.88 and 763.90 with
Comments:			
Management Plan	ner's Signature:		Date: 09/18/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15

MATERIAL DESCRIPTION: 9x9 Dark Brown Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- Engineer's Office Storage Room

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	15			
MATERIAL DESCRI	PTION:	9x9 Dark Brown	Floor Tile		
MATERIAL LOCATION	ON:	Main Building- E	ingineer's Office Storage Room		
MATERIAL QUANTIT	ΓΥ:	100		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	to review ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency R aspection and assessment and reco neous area has been reviewed in a	ommend appropriate respons	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: <u>09/18/2</u>	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16

MATERIAL DESCRIPTION: 9x9 Dark Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- Engineer's Office Storage Room

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	16			
MATERIAL DESCRIPTION:		9x9 Dark Floor	Γile Mastic		
MATERIAL LOCATIO	DN:	Main Building- B	Engineer's Ofiice Storage Room		
MATERIAL QUANTIT	ΓΥ:	100		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	o review the above	the results of the in identified homoge	the Asbestos Hazard Emergency F nspection and assessment and rec neous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/18/2	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: 12"X 12" Beige w/Gray Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- Engineer's Office & Toilet, 1st Floor Wardrobe Room

MATERIAL QUANTITY: 300 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019				
ADDRESS:	9755 S G	Greenwood	IDPH LICENSE NO:	100-11070				
HOMOGENEOUS AF	REA:	17						
MATERIAL DESCRIP	PTION:	12"X 12" Beige	w/Gray Specks Floor Tile					
MATERIAL LOCATIO	N:	Main Building- E	Engineer's Office & Toilet, 1st Flo	oor Wardrobe Room				
MATERIAL QUANTIT	TY:	300		MATERIAL UNITS:	SF			
DAMAGE QUANTITY	' :	0		DAMAGE UNITS:	SF			
management planner to priginal inspection of the	n accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The riginal inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with ne following recommendations.							
The RESPONSE ACT	TION reco	mmendation is:						
Follow O&M Plan								
Comments:								
Management Plann	ner's Sigr	nature:		Date: 09/18/2	019			

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18

MATERIAL DESCRIPTION: 12"X 12" Beige w/Gray Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Engineer's Office & Toilet, 1st Floor Wardrobe Room (Main Bldg)

MATERIAL QUANTITY: 300 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid S	chool	REVIEW DATE:	9/18/2	019	
ADDRESS:	9755 S Gr	reenwood	IDPH LICENSE NO:	100-11	1070	
HOMOGENEOUS AF	REA: 1	18				
MATERIAL DESCRIP	PTION: 1	12"X 12" Beige	w/Gray Specks Floor T	ile Mastic		
MATERIAL LOCATIO	ON:	Engineer's Offi	ice & Toilet, 1st Floor W	ardrobe Room (M	ain Bldg)	
MATERIAL QUANTIT	ΓΥ: 3	300		MATE	RIAL UNITS:	SF
DAMAGE QUANTITY	/: ()		DAMA	GE UNITS:	SF
management planner t	o review th ne above id	e results of the	of the Asbestos Hazard Er inspection and assessme eneous area has been re	ent and recommend	d appropriate resp	onse actions. The
The RESPONSE ACT	TION recon	nmendation is:				
Follow O&M Plan						
Comments:						
Management Planr	ner's Signa	ature:			Date: 09/18/2	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 19

MATERIAL DESCRIPTION: Beige Flooring Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- 1st Floor Corridor, Assistant Principal's Office (Room 101)

MATERIAL QUANTITY: 1100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	Dat	te:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois		o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	19			
MATERIAL DESCRIP	PTION:	Beige Flooring	g Mastic		
MATERIAL LOCATIO	DN:	Main Building	- 1st Floor Corridor, Assistant P	rincipal's Office (Room 10)1)
MATERIAL QUANTIT	ΓΥ:	1100		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	to review the above endations.	the results of the identified homog	of the Asbestos Hazard Emergend e inspection and assessment and r geneous area has been reviewed i	ecommend appropriate res	ponse actions. The
Comments:					
Management Planr	ner's Sigi	nature:		Date:09/18/	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: Gray Flooring Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- 1st Floor Corridor

MATERIAL QUANTITY: 1100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	20			
MATERIAL DESCRIP	PTION:	Gray Flooring M	lastic		
MATERIAL LOCATIO	N:	Main Building- 1	st Floor Corridor		
MATERIAL QUANTIT	ΓY:	1100		MATERIAL UNITS:	SF
DAMAGE QUANTITY	' :	0		DAMAGE UNITS:	SF
management planner to	o review the above	the results of the ir identified homoger	the Asbestos Hazard Emergency F nspection and assessment and reconneous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE ACT	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Plann	ner's Sigı	nature:		Date: <u>09/18/2</u>	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: Yellow, Brown & Beige Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet,

NE and SE Vestibules

MATERIAL QUANTITY: 1684 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	 Date:	08/22/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Managament Blannar Baylow Form

		wana	gement Plar	iner Rev	iew Form		
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	25391	BUIDLING ID:	5950	
CITY/STATE:	Chicago	, Illinois	MANAGEMENT P	LANNER:	John Fenn		
SCHOOL NAME:	Schmid	School	REVIEW DATE:		9/18/2019		
ADDRESS:	9755 S G	Greenwood	IDPH LICENSE N	O:	100-11070		
HOMOGENEOUS A	AREA:	21					
MATERIAL DESCR	IPTION:	Yellow, Brown 8	k Beige Ceramic Ti	le Grout			
MATERIAL LOCATI	ION:	Main Building- 1 Vestibules	st and 2nd Floor E	Boys and Gir	ls Restrooms, Tea	cher's Lo	unge Toilet, NE and SE
MATERIAL QUANT	ITY:	1684			MATERIAL UNI	TS:	SF
DAMAGE QUANTIT	Υ:	0			DAMAGE UNIT	S:	SF
Follow O&M Plan Comments:							
Management Plar	nner's Sigr	nature:			Date:	09/18/20	19

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22

MATERIAL DESCRIPTION: Yellow, Brown and Beige Ceramic Tile Adhesive

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- 1st and 2nd Floor Boys and Girls Restrooms, Teacher's Lounge Toilet,

NE and SE Vestibules

MATERIAL QUANTITY: 1684 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	,	Date:	08/22/2019
	_	·	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Managament Blannar Baylow Form

		Mana	gement Piai	nner Kev	new Form			
LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	25391	BUIDLING ID:	5950		
CITY/STATE:	Chicago	, Illinois	MANAGEMENT F	LANNER:	John Fenn			
SCHOOL NAME:	Schmid S	School	REVIEW DATE:		9/18/2019			
ADDRESS:	9755 S G	reenwood	IDPH LICENSE N	O:	100-11070			
HOMOGENEOUS A	AREA:	22						
MATERIAL DESCR	IPTION:	Yellow, Brown a	nd Beige Ceramic	Tile Adhesiv	/e			
MATERIAL LOCAT		Main Building- 1 Vestibules	st and 2nd Floor I	Boys and Gir	ls Restrooms, Tea	acher's L	ounge Toilet, NE a	and SE
MATERIAL QUANT	TTY:	1684			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	
Follow O&M Plan Comments:								
Management Plan	nner's Sign	ature:			Date:	09/18/2	019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23

MATERIAL DESCRIPTION: Grey and Black Speckled Terrazzo

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st and 2nd Floor Stairwells

MATERIAL QUANTITY: 2176 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	23			
MATERIAL DESCRIP	PTION:	Grey and Black	Speckled Terrazzo		
MATERIAL LOCATIO	ON:	1st and 2nd Floo	or Stairwells		
MATERIAL QUANTIT	ΓY:	2176		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	o review ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency R aspection and assessment and reconnected in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sig	nature:		Date:09/18/2	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24

MATERIAL DESCRIPTION: 12x12 Blue Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: 2nd Floor Corridor, Teachers Lounge (Main Building) and Main Office, Kitchen (Annex

Building)

MATERIAL QUANTITY: 2936 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:	,	Date:	08/22/2019
	_	·	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	S UNII NUMBER: 25391	BUIDLING ID: 5950	
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS A	REA: 24			
MATERIAL DESCRI	PTION: 12x12 Blue FI	oor Tile		
MATERIAL LOCATION	ON: 2nd Floor Co	ridor, Teachers Lounge (Main B	uilding) and Main Office, k	Kitchen (Annex Building
MATERIAL QUANTI	TY: 2936		MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y: 0		DAMAGE UNITS:	SF
management planner	to review the results of the he above identified homo-	of the Asbestos Hazard Emergence e inspection and assessment and i geneous area has been reviewed i	recommend appropriate resp	ponse actions. The
The RESPONSE AC	TION recommendation is	:		
Follow O&M Plan				
Comments:				
Management Plani	ner's Signature:		Date: 09/18/	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24M

MATERIAL DESCRIPTION: 12 x 12 Blue Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 2nd Floor Corridor, Teachers Lounge (Main Bldg) and Main Office, Kitchen (ANNEX)

MATERIAL QUANTITY: 2936 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	24M			
MATERIAL DESCRIP	PTION:	12 x 12 Blue F	loor Tile Mastic		
MATERIAL LOCATIO	ON:	2nd Floor Cor	ridor, Teachers Lounge (Main Bl	dg) and Main Office, Kitc	hen (ANNEX)
MATERIAL QUANTIT	ΓΥ:	2936		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	to review the above above above above.	the results of the identified homog	of the Asbestos Hazard Emergence inspection and assessment and regeneous area has been reviewed in	ecommend appropriate res	sponse actions. The
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigr	nature:		Date: 09/18	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25

MATERIAL DESCRIPTION: Beige and Tan Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex- Boys and Girls Restrooms, Teacher's Toilets

MATERIAL QUANTITY: 960 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

MANAGEMENT PLANNER:

25391

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	HOOL NAME: Schmid School		REVIEW DATE:	9/18/2	019	
ADDRESS:	9755 S G	reenwood	IDPH LICENSE NO:	100-1	1070	
HOMOGENEOUS AF	REA: 2	25				
MATERIAL DESCRIF	PTION: I	Beige and Tan	Ceramic Tile Grout			
MATERIAL LOCATIO	ON:	Annex- Boys a	nd Girls Restrooms, Tea	cher's Toilets		
MATERIAL QUANTIT	ГΥ: 9	960		MATE	RIAL UNITS:	SF
DAMAGE QUANTITY	/ : (0		DAMA	GE UNITS:	SF
management planner t	to review th ne above id	ne results of the	of the Asbestos Hazard Eminspection and assessment inspection and assessment eneous area has been rev	nt and recommend	d appropriate resp	oonse actions. The
The RESPONSE AC	TION recor	mmendation is:				
Follow O&M Plan						
Comments:						
Management Planr	ner's Signa	ature:			Date: 09/18/	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26

MATERIAL DESCRIPTION: Beige and Tan Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex- Boys and Girls Restrooms, Teacher's Toilets

MATERIAL QUANTITY: 960 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	HOOL NAME: Schmid School		REVIEW DATE:	9/18/2	019	
ADDRESS:	9755 S Gı	reenwood	IDPH LICENSE NO:	100-11	1070	
HOMOGENEOUS AF	REA: 2	26				
MATERIAL DESCRIF	PTION: I	Beige and Tan	Ceramic Tile Grout			
MATERIAL LOCATIO	DN:	Annex- Boys a	nd Girls Restrooms, Tea	cher's Toilets		
MATERIAL QUANTIT	ГΥ: 9	960		MATE	RIAL UNITS:	SF
DAMAGE QUANTITY	/ : (0		DAMA	GE UNITS:	SF
management planner t	o review th ne above id	e results of the	f the Asbestos Hazard Em inspection and assessmer eneous area has been rev	nt and recommend	d appropriate resp	oonse actions. The
The RESPONSE AC	TION recor	mmendation is:				
Follow O&M Plan						
Comments:						
Management Planr	ner's Signa	ature:			Date: 09/18/2	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27

MATERIAL DESCRIPTION: Gray Baseboard

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- E-W Corridor

MATERIAL QUANTITY: 136 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S	Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AI	REA:	27			
MATERIAL DESCRI	PTION:	Gray Baseboard			
MATERIAL LOCATION	ON:	Annex Building-	E-W Corridor		
MATERIAL QUANTI	TY:	136		MATERIAL UNITS:	LF
DAMAGE QUANTITY	Y:	0		DAMAGE UNITS:	LF
management planner	to review he above	the results of the ir identified homoger	the Asbestos Hazard Emergency R spection and assessment and reco neous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION rec	ommendation is:			
Follow O&M Plan					
Comments:					
Management Plani	ner's Sig	nature:		Date:09/18/2	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27A

MATERIAL DESCRIPTION: Gray Baseboard Adhesive

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- E-W Corridor

MATERIAL QUANTITY: 136 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

nspector's Signature:	D	ate:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	27A			
MATERIAL DESCRI	PTION:	Gray Baseboa	ard Adhesive		
MATERIAL LOCATIO	DN:	Annex Buildir	ng- E-W Corridor		
MATERIAL QUANTIT	ΓΥ:	136		MATERIAL UNITS:	LF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	LF
management planner to priginal inspection of the the following recomme	to review the above indations.	the results of the identified homo	of the Asbestos Hazard Emergende inspection and assessment and regeneous area has been reviewed i	ecommend appropriate res	ponse actions. The
The RESPONSE AC	TION reco	ommendation is	:		
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigr	nature:		Date: _09/18/	/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: Red Ceramic Tile Grout

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- North and South Entrances

MATERIAL QUANTITY: 120 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	28			
MATERIAL DESCRI	PTION:	Red Ceramic	Tile Grout		
MATERIAL LOCATION	ON:	Annex Buildir	ng- North and South Entrances		
MATERIAL QUANTI	ΓΥ:	120		MATERIAL UNITS:	SF
DAMAGE QUANTITY	Y:	0		DAMAGE UNITS:	SF
management planner to priginal inspection of the the following recomme	to review the above endations.	the results of the identified homog	of the Asbestos Hazard Emergence e inspection and assessment and re geneous area has been reviewed in	ecommend appropriate res	ponse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
_					
Comments:					
Management Planr	ner's Sigi	nature:		Date: 09/18/	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29

MATERIAL DESCRIPTION: Red Ceramic Tile Adhesive

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- North and South Entrances

MATERIAL QUANTITY: 120 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	RESS: 9755 S Greenwood		IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	29			
MATERIAL DESCRIP	PTION:	Red Ceramic Til	e Adhesive		
MATERIAL LOCATIO	ON:	Annex Building-	North and South Entrances		
MATERIAL QUANTIT	ΓΥ:	120		MATERIAL UNITS:	SF
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF
management planner t	to review t ne above	the results of the ir identified homoger	the Asbestos Hazard Emergency R nspection and assessment and reconneous area has been reviewed in a	ommend appropriate resp	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigi	nature:		Date:09/18/2	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30

MATERIAL DESCRIPTION: 12x12 White w/Blue and Red Speckles Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Main Office

MATERIAL QUANTITY: 416 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:	Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	30			
MATERIAL DESCRIP	PTION:	12x12 White w/E	Blue and Red Speckles Floor Tile		
MATERIAL LOCATION	DN:	Annex Building-	Main Office		
MATERIAL QUANTIT	ΓΥ:	416		MATERIAL UNITS:	SF
DAMAGE QUANTITY	′ :	0		DAMAGE UNITS:	SF
management planner t	o review the above i	the results of the in	the Asbestos Hazard Emergency R nspection and assessment and reco neous area has been reviewed in a	ommend appropriate respo	onse actions. The
The RESPONSE AC	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Planr	ner's Sigr	nature:		Date: 09/18/2	019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30M

MATERIAL DESCRIPTION: 12x12 White w/Blue and Red Speckles Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Annex Building- Main Office

MATERIAL QUANTITY: 416 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLANNER:	John Fenn					
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019					
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070					
HOMOGENEOUS AF	REA:	30M							
MATERIAL DESCRIP	PTION:	12x12 White w/B	lue and Red Speckles Floor Tile	Mastic					
MATERIAL LOCATIO	DN:	Annex Building-	Main Office						
MATERIAL QUANTIT	ΓΥ:	416		MATERIAL UNITS:	SF				
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF				
management planner t original inspection of th	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.								
The RESPONSE AC	TION reco	ommendation is:							
Follow O&M Plan									
Comments:									
Management Planr	ner's Sigi	nature:		Date: <u>09/18/2</u>	019				

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: Beige Flooring

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: 1st Floor Corridor, Assistant Principal's Office (Room 101)

MATERIAL QUANTITY: 1100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS: Principal's Office has Hardwood Floor

Inspector's Signature:	Date	e: _	08/22/2019
		_	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn	
SCHOOL NAME: Schmid School		REVIEW DATE:	9/18/2019		
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070	
HOMOGENEOUS AF	REA:	31			
MATERIAL DESCRIP	PTION:	Beige Flooring			
MATERIAL LOCATIO	DN:	1st Floor Corrid	or, Assistant Principal's Office ((Room 101)	
MATERIAL QUANTIT	ΓY:	1100		MATERIAL UNITS:	SF
DAMAGE QUANTITY	′ :	0		DAMAGE UNITS:	SF
management planner t	o review the above	the results of the i identified homoge	the Asbestos Hazard Emergency nspection and assessment and red neous area has been reviewed in	commend appropriate res	ponse actions. The
The RESPONSE ACT	TION reco	ommendation is:			
Follow O&M Plan					
Comments:					
Management Plann	ner's Sigi	nature:		Date: _ 09/18/	2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32

MATERIAL DESCRIPTION: Gray Flooring

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: 1st Floor Corridor

MATERIAL QUANTITY: 1100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	25391	BUIDLING ID:	5950
CITY/STATE:	Chicago	, Illinois	MANAGEMENT PL	ANNER:	John Fenn	
SCHOOL NAME:	Schmid	School	REVIEW DATE:		9/18/2019	
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO):	100-11070	
HOMOGENEOUS A	REA:	32				
MATERIAL DESCRI	PTION:	Gray Flooring				
MATERIAL LOCATION	ON:	1st Floor Corrido	or			
MATERIAL QUANTI	TY:	1100			MATERIAL UNI	ΓS: SF
DAMAGE QUANTITY	Y:	0			DAMAGE UNITS	S: SF
management planner	to review the above	the results of the ir	spection and assess	sment and reco	ommend appropri	ERA) the LEA must select a ate response actions. The ections 763.88 and 763.90 with
The RESPONSE AC	TION reco	ommendation is:				
Follow O&M Plan						
Comments						
Comments:						
Management Plani	ner's Sigr	nature:			Date: _	09/18/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33

MATERIAL DESCRIPTION: 12" X 12" White w/Blue Specks Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 530 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:	 [Date:	08/22/2019

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019					
ADDRESS:	9755 S C	Greenwood	IDPH LICENSE NO:	100-11070					
HOMOGENEOUS AF	REA:	33							
MATERIAL DESCRI	PTION:	12" X 12" White	e w/Blue Specks Vinyl Floor	Tile					
MATERIAL LOCATION	ON:	Main Building-	2nd Floor Corridor, 2nd Floo	or Teachers' Lounge					
MATERIAL QUANTI	ΓY:	530		MATERIAL UNITS:	SF				
DAMAGE QUANTITY	Y :	0		DAMAGE UNITS:	SF				
management planner t original inspection of th	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with he following recommendations.								
The RESPONSE AC	TION reco	ommendation is:							
Follow O&M Plan									
Comments:									
Management Planr	ner's Sigr	nature:		Date: 09/18	5/2019				

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: 12" x 12" White w/Blue Specks Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Main Building- 2nd Floor Corridor, 2nd Floor Teachers' Lounge

MATERIAL QUANTITY: 530 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

Inspector's Signature:		Date:	08/22/2019	

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

MANAGEMENT PLANNER:

25391

BUIDLING ID: 5950

John Fenn

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

SCHOOL NAME: Schmid School REVIEW DATE: 9/1		9/18/2019	9/18/2019			
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070		
HOMOGENEOUS A	REA:	34				
MATERIAL DESCRI	PTION:	12" x 12" White	w/Blue Specks Mastic			
MATERIAL LOCATION	ON:	Main Building-	2nd Floor Corridor, 2nd Flo	or Teachers' Lounge		
MATERIAL QUANTI	TY:	530		MATERIAL UN	ITS:	SF
DAMAGE QUANTITY	Y:	0		DAMAGE UNIT	S:	SF
management planner	to review t he above i	the results of the identified homoge	f the Asbestos Hazard Emerginspection and assessment a neous area has been review	nd recommend appropr	riate respo	nse actions. The
The RESPONSE AC	TION reco	ommendation is:				
Follow O&M Plan						
Comments:						
Management Plani	ner's Sigr	nature:		Date:	09/18/20)19

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35

MATERIAL DESCRIPTION: 12" x 12" Cream w/Tan Specks Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Room 102/ Principal's Office, Stage Room

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

nspector's Signature:	Date:	08/22/2019	

MANAGEMENT PLANNER:

Chicago Public Schools UNIT NUMBER:

Chicago, Illinois

LEA NAME:

CITY/STATE:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

John Fenn

SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2	019			
ADDRESS:	9755 S G	Greenwood	IDPH LICENSE NO:	100-1	1070			
HOMOGENEOUS AREA: 3		35						
MATERIAL DESCRIP	PTION:	12" x 12" Cream w/Tan Specks Vinyl Floor Tile						
MATERIAL LOCATIO	ON:	Room 102/ Principal's Office, Stage Room						
MATERIAL QUANTIT	ΓΥ:	100		MATE	RIAL UNITS:	SF		
DAMAGE QUANTITY	/ :	0		DAMA	GE UNITS:	SF		
management planner t original inspection of th	n accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a nanagement planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.							
The RESPONSE ACT	TION reco	mmendation is:						
Follow O&M Plan								
Comments:								
Management Planr	ner's Sign	nature:			Date: 09/18	/2019		

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 36

MATERIAL DESCRIPTION: 12" X 12" Cream w/Tan Specks Mastic

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Rm 102/ Principal's Office, Stage Room

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

nspector's Signature:		Date:	08/22/2019	

Chicago Public Schools UNIT NUMBER:

LEA NAME:

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PLANNER:	John Fenn					
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019					
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070					
HOMOGENEOUS AF	REA:	36							
MATERIAL DESCRIP	PTION:	12" X 12" Cream	w/Tan Specks Mastic						
MATERIAL LOCATIO	DN:	Rm 102/ Principa	Rm 102/ Principal's Office, Stage Room						
MATERIAL QUANTIT	ΓΥ:	100		MATERIAL UNITS:	SF				
DAMAGE QUANTITY	/ :	0		DAMAGE UNITS:	SF				
management planner t	o review the above	the results of the ir identified homoger	the Asbestos Hazard Emergency R aspection and assessment and reco neous area has been reviewed in a	ommend appropriate respons	onse actions. The				
The RESPONSE ACT	TION reco	ommendation is:							
Follow O&M Plan									
Comments:									
Management Planr	ner's Sigi	nature:		Date: 09/18/2	019				

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25391 BUIDLING ID: 5950

CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Mallory Jones

SCHOOL NAME: Schmid School INSPECTION DATE: 8/22/2019

ADDRESS: 9755 S Greenwood IDPH LICENSE NO: 100-11070

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: Fire Doors

HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 2nd Floor Corridor

MATERIAL QUANTITY: 80 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

COMMENTS:

nspector's Signature:	Date:	08/22/2019

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

25391

BUIDLING ID: 5950

Chicago Public Schools UNIT NUMBER:

LEA NAME:

CITY/STATE:	Chicago	, Illinois	MANAGEMENT PLANNER:	John Fenn				
SCHOOL NAME:	Schmid	School	REVIEW DATE:	9/18/2019				
ADDRESS:	9755 S (Greenwood	IDPH LICENSE NO:	100-11070				
HOMOGENEOUS AF	REA:	37						
MATERIAL DESCRIP	PTION:	Fire Doors						
MATERIAL LOCATIO	N:	2nd Floor Corridor						
MATERIAL QUANTIT	ΓY:	80		MATERIAL UNITS:	SF			
DAMAGE QUANTITY	' :	0		DAMAGE UNITS:	SF			
management planner t	o review the above indations.	the results of the in identified homoger	the Asbestos Hazard Emergency R Ispection and assessment and reco Leous area has been reviewed in ac	ommend appropriate respo	onse actions. The			
Follow O&M Plan								
Comments:								
Management Planr	ner's Sigr	nature:		Date: <u>09/18/2</u>	019			

TEM Environmental, Inc. 2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT **ASBESTOS ABATEMENT**

This is to certify that	MALLORY L. JONES S INSPECTOR'S REFRESHER course an	d successfully passed the
xamination on <u>03/18/2019</u>	with a minimum score of 70% or better.	Training was in accordance
7ith U.S. E.P.A. 40 CFR 763	Subpart E, Appendix C, Asbestos Contain	ing Materials in Schools:
Todel Accreditation Plan, TS	CA II, Authorized by both AHERA & ASI	HARA.
03/18/2019	PUBLIC HEALTH & SAFET	Y inc
ourse Dates:	Environmental and Occupational Services 37 S. Arkland Ave., Cheago, H. 60607 www.pd	Office: 312-491-0081 fic-health-safety.com Fac: 312-421-2901
03/18/2020		
xpires:	- In Rungs APA	
	All Offices 11	Phone: 312-491-0081
1903BIR10	Director of Training	_
ertificate Number:	Nicholas J. Peneff	EODIC II A GAOD
	Doctor of Public Health	FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

SUPERVISOR/WORKER

4/9/2019

INSPECTOR

3/19/2019

ID NUMBER

ISSUED

EXPIRES

4/9/2019

100 - 11070

3/6/2019

05/15/2020

AIR SAMPLING PROFESSIONAL

PROJECT MANAGER

MALLORY JONES
524 HOMELAND ROAD
MATTESON, IL 60443

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

Kathy/DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035

Kathy DeSalvo, Director

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

100 - 09786

ISSUED

4/11/2019

EXPIRES

05/15/2020

MANAGEMENT PLANNER

AIR SAMPLING PROFESSIONAL

3/19/2020

PROJECT MANAGER

3/18/2020

JOHN H FENN 2829 N TROY ST CHICAGO, IL 60618

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid

training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL CATEGORY	ACBM	Asbestos Containing Building Materials
	MISC	Miscellaneous
	SURF	Surfacing
MATERIAL UNITS	TSI	Thermal System Insulation
	LF	Linear Feet
	SF	Square Feet
DAMAGE TYPE	CF	Cubic Feet
	Loc	Localized
	Dist	Distributed