

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2177
SCHOOL NAME: Dunne School
ADDRESS OF SCHOOL: 10845 S Union
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 233
IDPH INSPECTOR LICENSE NUMBER: 100-00440
IDPH LICENSED INSPECTOR NAME(Please Print): Shawn Brown
IDPH MP LICENSE NUMBER: 100-01784
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Dunne School

10845 S Union
Chicago, IL, 60628

Unit: 25491
Building ID: 6050

IDPH ID Number: 14-016-2990-2177

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

September 3, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25491 Region: 06 IDPH ID:14-016-2990-2177

School: Dunne School Building ID: 6050

Address: 10845 S Union
Chicago, IL, 60628

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/02/2019

Inspector: Shawn Brown Inspector IDPH License: 100-00440
Management Planner: Steven Geneser Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Steven Geneser
100-01784

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 03, 2019

RE: Dunne School, Unit 25491
10845 S Union
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Dunne School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Dunne School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Dunne School
Address: 10845 S Union
IDPH ID: 14-016-2990-2177
Contact:
Unit: 25491
Chicago, IL, 60628
Building ID: 6050
Phone:
Region: 06

2. Description of Facility

Original Construction: 1953
Total Square Footage: 11990
Current Occupancy: 233
Additional Construction: 1971
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602
Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880
Fax: 630-790-0882

5. Inspector

Inspector Name: Shawn Brown

Inspector IDPH license # 100-00440

Signature:
Date: 9/3/2019

6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784

Signature:
Date: 10/02/2019

7. Review Date:10/02/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Dunne School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6050:

B. The following new homogenous areas have been identified for Building 6050:

48	2'x2' Grey Floor Tile w/Orange and Green
48A	Mastic associated with 2'x2' grey floor tile
49	2'x4' Ceiling Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	Firebrick
21	1'x1' Ceiling Tile
41	Brown and White Mosaic Ceramic Tile- Grout
41M	Brown and White Mosaic Ceramic Tile - Mastic
48	2'x2' Grey Floor Tile w/Orange and Green
48A	Mastic associated with 2'x2' grey floor tile
49	2'x4' Ceiling Tile

The following areas were deemed to be inaccessible:

19	Black Baseboard Mastic
20	Insulation in Fire Rated Door
25	12"x12" Gray Floor Tile Mastic
27	12"x12" White Floor Tile Mastic ABATED
37	Carpet Mastic
39	Gray Carpet Mastic
41M	Brown and White Mosaic Ceramic Tile - Mastic
42	Blue Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shawn Brown, IDPH License # 100-00440. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Dunne School Building 6050 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	1'x1' White Ceiling Tile			1953 Building- Rooms 100-102, 104-107, Engineer's Office	NO_ACBM	MISC	Y							
02	12x12 White Floor Tile	0	SF	1953 Building- Room 101, Main Corridor, 1st floor, 104, Engineer's Office, Room 100	NO_ACBM	MISC	N							
03	9"x9" Brown Floor Tile ABATED			1953 Building- 1st floor, Room 102	ABATED	MISC	N							
04	12"x12" White Floor Tile Mastic ABATED			1953 Building- Room 101, Main Corridor, 1st floor, Engineer's Office, Rooms 100 & 104	ABATED	MISC	N							
05	9"x9" Brown Floor Tile Mastic ABATED			1953 Building- 1st Floor, Room 102	ABATED	MISC	N		0					
06	Transite ABATED			1953 Building- 1st Floor: Rooms 104 & 105	ABATED	MISC	N							
07	12 x 12 Vinyl Floor Tile- Light Green, Pink, Rose Specks			1953 Building- Rooms 103-107, Restrooms	NO_ACBM	MISC								
08	12 x 12 Vinyl Floor Tile Mastic Light Green, Pink, Rose Specks			1953 Building- Rooms 103-107, Restrooms	NO_ACBM	MISC	N							LOW
09	Fire Door ABATED			1953 Building: Boiler Room	ABATED	MISC	N	None						
10	Firebrick	50	SF	1953 Building: Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
11	Incinerator Door Insulation	5	SF	1953 Building: Boiler Room	ABATED	MISC	N	NONE	0					
12	Boiler Gasket			1953 Building: Boiler Room	ABATED	MISC								LOW
13	Vibration Damper Air Unit Vent Fitting			1953 Building: Boiler Room	ABATED	MISC	N							
14	12"x12" Brown Floor Tile ABATED	0	SF	1971 Building- 4 Rooms SW, 3 Rooms SE 1st Floor, 2nd Floor Corridor, 2 Rooms SW and 4 Rooms SE	ABATED	MISC	N							
15	9"x9" Brown Floor Tile ABATED	0	SF	1971 Building- 1st	ABATED	MISC	N							

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				5 Rooms SE; 2nd Floor- 4 Rooms SW, 5 Rooms SE										
39	Gray Carpet Mastic	0	SF	Main Office	NO_ACBM	MISC								
40	Grout - Blue Ceramic Tile			1953 Building-Boys' and Girls' Washrooms	NO_ACBM	SURFACE	N							
40M	Mastic- Blue Ceramic Tile			1953 Building-Boys' and Girls' Washrooms	NO_ACBM	MISC	N							
41	Brown and White Mosaic Ceramic Tile-Grout	500	SF	1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
41M	Brown and White Mosaic Ceramic Tile - Mastic	500	SF	1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Blue Carpet Mastic	0	SF	1971 Building - Library & 1st Floor Storeroom	NO_ACBM	MISC	N							
43	12" X 12" White w/Red & Blue Specks Floor Tile	275	SF	1971 Building-Room 108	NO_ACBM	MISC								
44	12" X 12" White w/Red & Blue Specks Mastic	275	SF	1971 Building - Room 108	NO_ACBM	MISC								
45	12" X 12" Yellow Floor Tile	0	SF	1971 Building-Multipurpose Room and Kitchen	NO_ACBM	MISC								
46	12" 12" Yellow Floor Tile Mastic	0	SF	1971 Building-Multipurpose Room and Kitchen	NO_ACBM	MISC								
47	2 x 4 Ceiling Tile			1953 Building-Corridor, Rooms 102 & 103	NO_ACBM	MISC								
48	2'x2' Grey Floor Tile w/Orange and Green	25,000	SF	New Addition hallways and old building hallways, rooms 159 and 161	ASSUMED	MISC		NONE				ACBM with the potential for damage		MODERATE
48A	Mastic associated with 2'x2' grey floor tile	25,000	SF	New Addition hallways old building hallways and room s159/161	ASSUMED	MISC		NONE				ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
49	2'x4' Ceiling Tile	50,000	SF	Throughout Old and New Buildings	ASSUMED	MISC		NONE				ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation ABATED (NO RECORDS)			1953 Building-Boiler Room	ABATED	MISC	Y							
B	Fittings on Aircell ABATED			1953 Building-Boiler Room, Toilets, Above Ceiling Tile Throughout	ABATED	TSI	Y							
C	Paperwrap Pipe Insulation ABATED (NO RECORDS)			1953 Building-Boiler Room	ABATED	TSI								
D	Fittings on Paperwrap ABATED (NO RECORDS)			1953 Building-Boiler Room	ABATED	TSI								
E	Mag Block Boiler Insulation ABATED (NO RECORDS)			1953 Building-Boiler Room	ABATED	TSI								
F	Magblock Pipe Insulation ABATED (NO RECORDS)			1953 Building-Boiler Room	ABATED	TSI								
G	Fittings on Fiberglass	20	LF	1971 Building- 1st Floor Girls' and Boys' Washroom, Janitor's Closet	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/3/2019
Inspector Name Shawn Brown
100-00440 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	1953 Building Demolished
02	1953 Building Demolished
03	1953 Building Demolished
04	1953 Building Demolished
05	1953 Building Demolished
06	1953 Building Demolished
07	1953 Building Demolished
08	1953 Building Demolished
09	1953 Building Demolished
10	1953 Building Demolished
11	Not Observed 2019. 1953 Building Demolished
12	1953 Building Demolished
13	1953 Building Demolished
14	
15	
16	
17	
18	
19	
20	
21	Not Observed 2019
22	
23	

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
24	
25	
26	
27	
28	
29	1953 Building Demolished
30	1953 Building Demolished
31	1953 Building Demolished
32	Not Observed 2019. 1953 Building Demolished
33	Not Observed 2019. 1953 Building Demolished
34	
35	
36	
37	
38	
39	
40	1953 Building Demolished
40M	1953 Building Demolished
41	
41M	
42	
43	
44	
45	
46	
47	1953 Building Demolished
48	
48A	
49	

Chicago Public Schools

School Dunne School Unit 25491 Building ID 6050

Address 10845 S Union Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
A	Abated, No Records. 1953 Building Demolished
B	1953 Building Demolished
C	Abated, No Records. 1953 Building Demolished
D	Abated, No Records. 1953 Building Demolished
E	Abated, No Records. New Boilers. 1953 Building Demolished
F	Abated. No Records. 1953 Building Demolished
G	

Table II

Management Planner's Review

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	1'x1' White Ceiling Tile			1953 Building- Rooms 100-102, 104-107, Engineer's Office	No ACBM	MISC	Yes				
02	12x12 White Floor Tile	0	SF	1953 Building- Room 101, Main Corridor, 1st floor, 104, Engineer's Office, Room 100	No ACBM	MISC	No		SF		
03	9"x9" Brown Floor Tile ABATED			1953 Building- 1st floor, Room 102	Abated	MISC	No				
04	12"x12" White Floor Tile Mastic ABATED			1953 Building- Room 101, Main Corridor, 1st floor, Engineer's Office, Rooms 100 & 104	Abated	MISC	No				
05	9"x9" Brown Floor Tile Mastic ABATED			1953 Building- 1st Floor, Room 102	Abated	MISC	No	0			
06	Transite ABATED			1953 Building- 1st Floor: Rooms 104 & 105	Abated	MISC	No				
07	12 x 12 Vinyl Floor Tile- Light Green, Pink, Rose Specks			1953 Building- Rooms 103-107, Restrooms	No ACBM	MISC					
08	12 x 12 Vinyl Floor Tile Mastic Light Green, Pink, Rose Specks			1953 Building- Rooms 103-107, Restrooms	No ACBM	MISC	No				
09	Fire Door ABATED			1953 Building: Boiler Room	Abated	MISC	No				
10	Firebrick	50	SF	1953 Building: Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Incinerator Door Insulation	5	SF	1953 Building: Boiler Room	Abated	MISC	No	0	SF		
12	Boiler Gasket			1953 Building: Boiler Room	Abated	MISC					
13	Vibration Damper Air Unit Vent Fitting			1953 Building: Boiler Room	Abated	MISC	No				
14	12"x12" Brown Floor Tile ABATED	0	SF	1971 Building- 4 Rooms SW, 3 Rooms SE 1st Floor, 2nd Floor Corridor, 2 Rooms SW and 4 Rooms SE	Abated	MISC	No		SF		
15	9"x9" Brown Floor Tile ABATED	0	SF	1971 Building- 1st Floor South Entrance	Abated	MISC	No		SF		
16	12"x12" Brown Floor Tile Mastic ABATED	0	SF	1971 Building- 1st Floor: 4 Rooms SW, 2 Rooms SE, 209, 210, 208, 207, 203, 112, 113, 115, 116, 117, 118, 2nd Floor Corridor	Abated	MISC	No		SF		
17	9"x9" Brown Floor Tile Mastic ABATED	0	SF	1971 Building- 1st Floor South Entrance	Abated	MISC	No		SF		
18	Black Baseboard	1,000	LF	1971 Building- Throughout 1st and 2nd Floor	No ACBM	MISC			LF		
19	Black Baseboard Mastic	1,000	LF	1971 Building Throughout 1st and 2nd	No ACBM	MISC			LF		

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Floor							
20	Insulation in Fire Rated Door	1	EA	1971 Building: 1st Floor Mechanical Room	No ACBM	TSI			EA		
21	1'x1' Ceiling Tile	50	SF	1971 Building- 1st Floor Mechanical Room (Not Observed 2013)	Assumed	MISC			SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Drywall	35,000	SF	1971 Building- 2nd Floor Throughout	No ACBM	MISC			SF		
23	Hardcoat Plaster	1,500	SF	1953 Building: 1st Floor Mechanical Areas, Councilor's Office, Ceilings	No ACBM	SURFACE			SF		
24	12"x12" Gray Floor Tile	0	SF	1971 Building- 2nd Floor: 1 Room NE, Room 201	No ACBM	MISC			SF		
25	12"x12" Gray Floor Tile Mastic	0	SF	1971 Building- 2nd Floor: 1 Room NE, 701, Room 201	No ACBM	MISC		0	SF		
26	12"x12" White Floor Tile ABATED	0	SF	1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209	Abated	MISC	No		SF		
27	12"x12" White Floor Tile Mastic ABATED	0	SF	1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209	Abated	MISC			SF		
28	12"x12" Brown Floor Tile	0	SF	1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office	No ACBM	MISC			SF		
29	12"x12" Brown Floor Tile Mastic ABATED			1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office	Abated	MISC					
30	12"x12" Light Brown Floor Tile ABATED			1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room	Abated	MISC	No				
31	12"x12" Light Brown Floor Tile Mastic ABATED			1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room	Abated	MISC	No				
32	12"X12" Floor Tile Light Green, Tan w/Red Marks ABATED			1953 Building- Rooms 102, 103, 105, Office. (Not observed in 2013)	Abated	MISC	No				
33	12"x12" Light Green Floor Tile Mastic ABATED			1953 Building- Rooms 102, 103, 105, Office	Abated	MISC					
34	9"x9" Tan Floor Tile	1,720	SF	1971 Building- 1st Floor Multi-Purpose Room, Kitchen	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	9"x9" Tan Floor Tile Mastic	1,720	SF	1971 Building- 1st Floor Multi-Purpose	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room, Kitchen							
36	2'x4' Ceiling Tile	22,550	SF	1971 Building: 1st & 2nd Floor Throughout, 102, 103 and 1st Floor Storage	No ACBM	MISC			SF		
37	Carpet Mastic	650	SF	1971 Building- 1st Floor Storeroom, 2nd Floor Library	No ACBM	MISC	No		SF		
38	Tectum Wall Panels	1,900	SF	1971 Building: 1st floor- 4 Rooms SW, 5 Rooms SE; 2nd Floor- 4 Rooms SW, 5 Rooms SE	No ACBM	MISC			SF		
39	Gray Carpet Mastic	0	SF	Main Office	No ACBM	MISC			SF		
40	Grout - Blue Ceramic Tile			1953 Building- Boys' and Girls' Washrooms	No ACBM	SURFACE	No				
40M	Mastic- Blue Ceramic Tile			1953 Building- Boys' and Girls' Washrooms	No ACBM	MISC	No				
41	Brown and White Mosaic Ceramic Tile- Grout	500	SF	1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41M	Brown and White Mosaic Ceramic Tile - Mastic	500	SF	1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Blue Carpet Mastic	0	SF	1971 Building - Library & 1st Floor Storeroom	No ACBM	MISC	No		SF		
43	12" X 12" White w/Red & Blue Specks Floor Tile	275	SF	1971 Building- Room 108	No ACBM	MISC			SF		
44	12" X 12" White w/Red & Blue Specks Mastic	275	SF	1971 Building - Room 108	No ACBM	MISC			SF		
45	12" X 12" Yellow Floor Tile	0	SF	1971 Building- Multipurpose Room and Kitchen	No ACBM	MISC			SF		
46	12" 12" Yellow Floor Tile Mastic	0	SF	1971 Building- Multipurpose Room and Kitchen	No ACBM	MISC			SF		
47	2 x 4 Ceiling Tile			1953 Building- Corridor, Rooms 102 & 103	No ACBM	MISC					
48	2'x2' Grey Floor Tile w/Orange and Green	25,000	SF	New Addition hallways and old building hallways, rooms 159 and 161	Assumed	MISC			SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	Mastic associated with 2'x2' grey floor tile	25,000	SF	New Addition hallways old building hallways and room s159/161	Assumed	MISC			SF	6 ACBM with the potential for damage	Follow O&M Plan
49	2'x4' Ceiling Tile	50,000	SF	Throughout Old and New Buildings	Assumed	MISC			SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
 Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A	Aircell Pipe Insulation ABATED (NO RECORDS)			1953 Building- Boiler Room	Abated	MISC	Yes				
B	Fittings on Aircell ABATED			1953 Building- Boiler Room, Toilets, Above Ceiling Tile Throughout	Abated	TSI	Yes				
C	Paperwrap Pipe Insulation ABATED (NO RECORDS)			1953 Building- Boiler Room	Abated	TSI					
D	Fittings on Paperwrap ABATED (NO RECORDS)			1953 Building- Boiler Room	Abated	TSI					
E	Mag Block Boiler Insulation ABATED (NO RECORDS)			1953 Building- Boiler Room	Abated	TSI					
F	Magblock Pipe Insulation ABATED (NO RECORDS)			1953 Building- Boiler Room	Abated	TSI					
G	Fittings on Fiberglass	20	LF	1971 Building- 1st Floor Girls' and Boys' Washroom, Janitor's Closet	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
 Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/02/2019
Manager Planner Name	Steven Geneser
100-01784	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
 Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
40M	
41	
41M	
42	
43	
44	
45	
46	
47	

Chicago Public Schools

School Dunne School
Address 10845 S Union

Unit 25491
Chicago, IL, 60628

Building ID 6050
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
48	
48A	
49	
A	
B	
C	
D	
E	
F	
G	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Rooms 100-102, 104-107, Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**

MATERIAL LOCATION: **1953 Building- Rooms 100-102, 104-107, Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Room 101, Main Corridor, 1st floor, 104, Engineer's Office, Room 100**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **1953 Building- Room 101, Main Corridor, 1st floor, 104, Engineer's Office, Room 100**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st floor, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile ABATED**

MATERIAL LOCATION: **1953 Building- 1st floor, Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Room 101, Main Corridor, 1st floor, Engineer's Office, Rooms 100 & 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1953 Building- Room 101, Main Corridor, 1st floor, Engineer's Office, Rooms 100 & 104**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1953 Building- 1st Floor, Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Transite ABATED**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor: Rooms 104 & 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Transite ABATED**

MATERIAL LOCATION: **1953 Building- 1st Floor: Rooms 104 & 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **12 x 12 Vinyl Floor Tile- Light Green, Pink, Rose Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Rooms 103-107, Restrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12 x 12 Vinyl Floor Tile- Light Green, Pink, Rose Specks**

MATERIAL LOCATION: **1953 Building- Rooms 103-107, Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12 x 12 Vinyl Floor Tile Mastic Light Green, Pink, Rose Specks**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building- Rooms 103-107, Restrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12 x 12 Vinyl Floor Tile Mastic Light Green, Pink, Rose Specks**

MATERIAL LOCATION: **1953 Building- Rooms 103-107, Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Fire Door ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____

Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Fire Door ABATED**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Firebrick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Firebrick**
MATERIAL LOCATION: **1953 Building: Boiler Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Incinerator Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2019. 1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Incinerator Door Insulation**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY: **5**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Boiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Vibration Damper Air Unit Vent Fitting**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Vibration Damper Air Unit Vent Fitting**

MATERIAL LOCATION: **1953 Building: Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 4 Rooms SW, 3 Rooms SE 1st Floor, 2nd Floor Corridor, 2 Rooms SW and 4 Rooms SE**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile ABATED**
MATERIAL LOCATION: **1971 Building- 4 Rooms SW, 3 Rooms SE 1st Floor, 2nd Floor Corridor, 2 Rooms SW and 4 Rooms SE**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st Floor South Entrance**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile ABATED**
MATERIAL LOCATION: **1971 Building- 1st Floor South Entrance**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st Floor: 4 Rooms SW, 2 Rooms SE, 209, 210, 208, 207, 203, 112, 113, 115, 116, 117, 118, 2nd Floor Corridor**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1971 Building- 1st Floor: 4 Rooms SW, 2 Rooms SE, 209, 210, 208, 207, 203, 112, 113, 115, 116, 117, 118, 2nd Floor Corridor**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st Floor South Entrance**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1971 Building- 1st Floor South Entrance**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Throughout 1st and 2nd Floor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **1971 Building- Throughout 1st and 2nd Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building Throughout 1st and 2nd Floor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **1971 Building Throughout 1st and 2nd Floor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Insulation in Fire Rated Door**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building: 1st Floor Mechanical Room**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Insulation in Fire Rated Door**

MATERIAL LOCATION: **1971 Building: 1st Floor Mechanical Room**

MATERIAL QUANTITY: **1**

MATERIAL UNITS: **EA**

DAMAGE QUANTITY:

DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1971 Building- 1st Floor Mechanical Room (Not Observed 2013)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
MATERIAL LOCATION: **1971 Building- 1st Floor Mechanical Room (Not Observed 2013)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 2nd Floor Throughout**

MATERIAL QUANTITY: **35000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **1971 Building- 2nd Floor Throughout**
MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building: 1st Floor Mechanical Areas, Councilor's Office, Ceilings**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Hardcoat Plaster**
MATERIAL LOCATION: **1953 Building: 1st Floor Mechanical Areas, Councilor's Office, Ceilings**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 2nd Floor: 1 Room NE, Room 201**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
MATERIAL LOCATION: **1971 Building- 2nd Floor: 1 Room NE, Room 201**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 2nd Floor: 1 Room NE, 701, Room 201**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **1971 Building- 2nd Floor: 1 Room NE, 701, Room 201**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile ABATED**

MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1971 Building- 1st & 2nd Floor Corridors, 117, 118, 116, 115, 114, 112, 111, 109, 201, 203, 204, 205, 206, 210, 207, 209**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**
MATERIAL LOCATION: **1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1953 Building- 1st Floor Corridor, Rooms 101, 100, Engineer's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile ABATED**
MATERIAL LOCATION: **1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1953 Building- 1st Floor: Room 106, Teachers' Room, Storage Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"X12" Floor Tile Light Green, Tan w/Red Marks ABATED**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Rooms 102, 103, 105, Office. (Not observed in 2013)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019. 1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12"X12" Floor Tile Light Green, Tan w/Red Marks ABATED**
MATERIAL LOCATION: **1953 Building- Rooms 102, 103, 105, Office. (Not observed in 2013)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Rooms 102, 103, 105, Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019. 1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1953 Building- Rooms 102, 103, 105, Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**

MATERIAL LOCATION: **1971 Building- 1st Floor Multi-Purpose Room, Kitchen**

MATERIAL QUANTITY: **1720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile**
MATERIAL LOCATION: **1971 Building- 1st Floor Multi-Purpose Room, Kitchen**
MATERIAL QUANTITY: **1720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **1971 Building- 1st Floor Multi-Purpose Room, Kitchen**
MATERIAL QUANTITY: **1720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic**
MATERIAL LOCATION: **1971 Building- 1st Floor Multi-Purpose Room, Kitchen**
MATERIAL QUANTITY: **1720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building: 1st & 2nd Floor Throughout, 102, 103 and 1st Floor Storage**

MATERIAL QUANTITY: **22550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **1971 Building: 1st & 2nd Floor Throughout, 102, 103 and 1st Floor Storage**
MATERIAL QUANTITY: **22550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- 1st Floor Storeroom, 2nd Floor Library**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **1971 Building- 1st Floor Storeroom, 2nd Floor Library**
MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Tectum Wall Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building: 1st floor- 4 Rooms SW, 5 Rooms SE; 2nd Floor- 4 Rooms SW, 5 Rooms SE**

MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Tectum Wall Panels**
MATERIAL LOCATION: **1971 Building: 1st floor- 4 Rooms SW, 5 Rooms SE; 2nd Floor- 4 Rooms SW, 5 Rooms SE**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Grout - Blue Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boys' and Girls' Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Grout - Blue Ceramic Tile**

MATERIAL LOCATION: **1953 Building- Boys' and Girls' Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40M**
MATERIAL DESCRIPTION: **Mastic- Blue Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boys' and Girls' Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **40M**
MATERIAL DESCRIPTION: **Mastic- Blue Ceramic Tile**
MATERIAL LOCATION: **1953 Building- Boys' and Girls' Washrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Brown and White Mosaic Ceramic Tile- Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Brown and White Mosaic Ceramic Tile- Grout**
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41M**
MATERIAL DESCRIPTION: **Brown and White Mosaic Ceramic Tile - Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **41M**
MATERIAL DESCRIPTION: **Brown and White Mosaic Ceramic Tile - Mastic**
MATERIAL LOCATION: **1971 Building- 1st and 2nd Floor Boys' and Girls' Washrooms and Faculty Washrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building - Library & 1st Floor Storeroom**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **1971 Building - Library & 1st Floor Storeroom**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" X 12" White w/Red & Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Room 108**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12" X 12" White w/Red & Blue Specks Floor Tile**
MATERIAL LOCATION: **1971 Building- Room 108**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" X 12" White w/Red & Blue Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building - Room 108**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" X 12" White w/Red & Blue Specks Mastic**
MATERIAL LOCATION: **1971 Building - Room 108**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Multipurpose Room and Kitchen**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" X 12" Yellow Floor Tile**
MATERIAL LOCATION: **1971 Building- Multipurpose Room and Kitchen**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1971 Building- Multipurpose Room and Kitchen**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12" 12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **1971 Building- Multipurpose Room and Kitchen**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Corridor, Rooms 102 & 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **2 x 4 Ceiling Tile**

MATERIAL LOCATION: **1953 Building- Corridor, Rooms 102 & 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED (NO RECORDS)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated, No Records. 1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED (NO RECORDS)**

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Fittings on Aircell ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room, Toilets, Above Ceiling Tile Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Fittings on Aircell ABATED**
MATERIAL LOCATION: **1953 Building- Boiler Room, Toilets, Above Ceiling Tile Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation ABATED (NO RECORDS)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated, No Records. 1953 Building Demolished**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation ABATED (NO RECORDS)**
MATERIAL LOCATION: **1953 Building- Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Fittings on Paperwrap ABATED (NO RECORDS)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated, No Records. 1953 Building Demolished**

Inspector's Signature: _____

Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Fittings on Paperwrap ABATED (NO RECORDS)**

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Block Boiler Insulation ABATED (NO RECORDS)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated, No Records. New Boilers. 1953 Building Demolished**

Inspector's Signature: _____

Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Mag Block Boiler Insulation ABATED (NO RECORDS)**

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Magblock Pipe Insulation ABATED (NO RECORDS)**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Abated. No Records. 1953 Building Demolished**

Inspector's Signature: _____

Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Magblock Pipe Insulation ABATED (NO RECORDS)**

MATERIAL LOCATION: **1953 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fittings on Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1971 Building- 1st Floor Girls' and Boys' Washroom, Janitor's Closet**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUIDLING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Fittings on Fiberglass**
MATERIAL LOCATION: **1971 Building- 1st Floor Girls' and Boys' Washroom, Janitor's Closet**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Old and New Buildings**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Old and New Buildings**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48A**
MATERIAL DESCRIPTION: **Mastic associated with 2'x2' grey floor tile**
MATERIAL LOCATION: **New Addition hallways old building hallways and room s159/161**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **48A**
MATERIAL DESCRIPTION: **Mastic associated with 2'x2' grey floor tile**
MATERIAL LOCATION: **New Addition hallways old building hallways and room s159/161**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shawn Brown**
SCHOOL NAME: **Dunne School** INSPECTION DATE: **9/3/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **2'x2' Grey Floor Tile w/Orange and Green**
MATERIAL LOCATION: **New Addition hallways and old building hallways, rooms 159 and 161**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25491** BUILDING ID: **6050**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**
SCHOOL NAME: **Dunne School** REVIEW DATE: **10/2/2019**
ADDRESS: **10845 S Union** IDPH LICENSE NO: **100-00440**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **2'x2' Grey Floor Tile w/Orange and Green**
MATERIAL LOCATION: **New Addition hallways and old building hallways, rooms 159 and 161**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/02/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY inc.
Environmental and Occupational Services
375 Ashland Ave., Chicago, IL 60607
www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2801

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.
Environmental and Occupational Services
311 S. Ashland Ave., Chicago, IL 60607

Office: 312-491-0081
Fax: 312-421-2901
www.public-health-safety.com

Director of Training
Nicholas J. Peneff
Doctor of Public Health




Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	3/19/2019
100 - 02950	3/6/2019	05/15/2020			
KEITH CLOUGH				PROJECT MANAGER	4/9/2019
524 HOMELAND RD				AIR SAMPLING PROFESSIONAL	
MATTESON, IL 60443				Alteration of this license shall result in legal action	
Environmental Health				This license issued under authority of the State of Illinois	
				Department of Public Health	
				This license is valid only when accompanied by a valid training course certificate.	

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed