

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2494
SCHOOL NAME: Volta School
ADDRESS OF SCHOOL: 4950 N Avers Avenue
CITY: Chicago, IL, 60625

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/18/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 816
IDPH INSPECTOR LICENSE NUMBER: 100-11255
IDPH LICENSED INSPECTOR NAME(Please Print): Esteban Nunez
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Volta School

4950 N Avers Avenue
Chicago, IL, 60625

Unit: 25681
Building ID: 6270

IDPH ID Number: 14-016-2990-2494

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

October 22, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25681 Region: 01 IDPH ID:14-016-2990-2494

School: Volta School Building ID: 6270

Address: 4950 N Avers Avenue

Chicago, IL, 60625

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/29/2019

Inspector: Esteban Nunez

Inspector IDPH License: 100-11255

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,
GSG-Probe Consulting, Inc.

Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 22, 2019

RE: Volta School, Unit 25681
4950 N Avers Avenue
Chicago, IL, 60625

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Volta School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Volta School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Volta School Unit: 25681 Region: 01
Address: 4950 N Avers Avenue Chicago, IL, 60625
IDPH ID: 14-016-2990-2494 Building ID: 6270
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 816

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren
Chicago, IL, 60612
Phone: 3123197575 Fax:

5. Inspector

Inspector Name: Esteban Nunez

Inspector IDPH license # 100-11255
Signature:
Date: 10/22/2019

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342
Signature:
Date: 10/29/2019

7. Review Date: 10/29/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Volta School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6270:

B. The following new homogenous areas have been identified for Building 6270:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	12"x12" White Vinyl Floor Tile
03A	12"x12" White Vinyl Floor Tile Mastic
04	12"x12" Red Vinyl Floor Tile
09	12"x12" White w/ Black Speckles VFT
10	12"x12" White w/ Pink Speckles Vinyl Floor Tile
10A	12"x12" White w/ Pink Speckles VFT Mastic
11	12"x12" Black w/ White Speckles Vinyl Floor Tile
11A	12"x12" Black w/ White Speckles VFT Mastic
12	12"x12" Peach Vinyl Floor Tile
12A	12"x12" Peach Vinyl Floor Tile Mastic
15	9"x9" Beige w/ White Speckles Vinyl Floor Tile
15A	9"x9" Beige w/ White Speckles VFT Mastic
16	9"x9" Dark Beige w/ White & Brown Speckles VFT
17	12"x12" Peach w/ White Streaks VFT
17A	12"x12" Peach w/ White Streaks VFT Mastic
19	12"x12" Gray VFT
20	12"x12" Gray VFT Mastic
21	2'x4' White Ceiling Tile
22	Vinyl Baseboard
23	Vinyl Baseboard Mastic
24	Drywall
25	Drywall Joint Compound
26	Terrazzo
27	Decorative Plaster
28	Carpet Mastic
29	Fire Doors
30	Decorative Plaster
31	12"x12" White w/ Light Gray and Gray Streaks VFT
31A	12"x12" White w/ Light Gray and Gray Streaks VFT Mastic

The following areas were deemed to be inaccessible:

02A	9"x9" Light Brown Vinyl Floor Tile Mastic
-----	---

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The

Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Volta School Building 6270 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" Light Brown w/ Dark Brown Speckles VFT	5,500	SF	1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01A	12"x12" Light Brown w/ Dark Brown Speckles VFT Mastic	5,500	SF	1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	9"x9" Light Brown Vinyl Floor Tile	1,200	SF	1st Floor Center Corridor & room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02A	9"x9" Light Brown Vinyl Floor Tile Mastic	1,200	SF	1st Floor Center Corridor & room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	12"x12" White Vinyl Floor Tile	100	SF	Main Office Entryway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03A	12"x12" White Vinyl Floor Tile Mastic	100	SF	Main Office Entryway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" Red Vinyl Floor Tile	100	SF	Main Office Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04A	12"x12" Red Vinyl Floor Tile Mastic	100	SF	Main Office Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12"x12" Dark Brown w/ White Streaks VFT	1,200	SF	1st Floor Center Corridor, Balcony (now covered in red carpet), & Help's Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12"x12" Dark Brown w/ White Streaks VFT Mastic	1,200	SF	1st Floor Center Corridor, Balcony (now covered in red carpet), & Help's Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9"x9" Brown w/ White Streaks Vinyl Floor Tile	800	SF	1st Floor Main Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	9"x9" Brown w/ White Streaks VFT Mastic	800	SF	1st Floor Main Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	9"x9" Rust Vinyl Floor Tile	4,500	SF	Basement Engineer's Storage & Auditorium(now covered in red carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	9"x9" Rust Vinyl Floor Tile Mastic	4,500	SF	Basement Engineer's Storage, & Auditorium(now	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				covered in red carpet)										
08	9"x9" Black w/ White Streaks Vinyl Floor Tile-NOT OBSERVED	700	SF	Room 310	CHR	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		
08A	9"x9" Black w/ White Streaks VFT Mastic-NOT OBSERVED	700	SF	Room 310	CHR	MISC	N	UNKNO WN	0		No	ACBM with the potential for damage		LOW
09	12"x12" White w/ Black Speckles VFT	2,625	SF	Lunchroom (Rooms 115/117) and Room 110, Room 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	12"x12" White w/ Black Speckles VFT Mastic	2,625	SF	Lunchroom (Rooms 115/117) and Room 110, Room 107	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12"x12" White w/ Pink Speckles Vinyl Floor Tile	40	SF	Principal's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	12"x12" White w/ Pink Speckles VFT Mastic	40	SF	Principal's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12"x12" Black w/ White Speckles Vinyl Floor Tile	1,625	SF	Lunchroom (115/117), Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11A	12"x12" Black w/ White Speckles VFT Mastic	1,625	SF	Lunchroom (115/117), Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Peach Vinyl Floor Tile	2,000	SF	Mobile Classroom Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	12"x12" Peach Vinyl Floor Tile Mastic	2,000	SF	Mobile Classroom Building #1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	9"x 9" Black Vinyl Floor Tile	4,500	SF	Engineer's Store Room, Auditorium (also under the carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13A	9"x9" Black Vinyl Floor Tile Mastic	4,500	SF	Engineer's Store Room, Auditorium (also under carpet)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	9"x9" Dark Brown Vinyl Floor Tile	850	SF	Engineer's Office & Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14A	9"x9" Dark Brown Vinyl Floor Tile Mastic	850	SF	Engineer's Office & Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9"x9" Beige w/ White Speckles Vinyl Floor Tile	760	SF	1st Floor Center Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15A	9"x9" Beige w/ White Speckles VFT Mastic	760	SF	1st Floor Center Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9"x9" Dark Beige w/ White & Brown Speckles VFT	760	SF	1st Floor Center Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	9"x9" Dark Beige w/ White & Brown	760	SF	1st Floor Center	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Speckles VFT Mastic			Corridor								potential for damage		
17	12"x12" Peach w/ White Streaks VFT	600	SF	Assembly Hall(New Red Carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12"x12" Peach w/ White Streaks VFT Mastic	600	SF	Assembly Hall (New Red Carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Black Vinyl Floor Tile NOT OBSERVED	80	SF	Engineer's Help Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12"x12" Black Vinyl Floor Tile Mastic NOT OBSERVED	80	SF	Engineer's Help Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Gray VFT	50,000	SF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Gray VFT Mastic	50,000	SF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	2'x4' White Ceiling Tile	40,000	SF	Throughout 1996 Annex	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Vinyl Baseboard	60,000	SF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Vinyl Baseboard Mastic	60,000	SF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Drywall	130,000	SF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Drywall Joint Compound	20,000	LF	Throughout 1996 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Terrazzo	5,000	SF	All stairwells, entry vestibules, and all corridors all levels around the boarders.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Decorative Plaster	2,000	SF	Assembly Hall and Balcony	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Carpet Mastic	1,410	SF	Assembly Hall and Balcony, 2nd Floor Teachers Lounge, Kitchen Main Office, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Fire Doors	7	EA	Auditorium, Projector Room, Stage Door, Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	Decorative Plaster	800	SF	Auditorium, Stage, Balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" White w/ Light Gray and Gray Streaks VFT	350	SF	Engineer's Office, Eng Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31A	12"x12" White w/ Light Gray and Gray Streaks VFT Mastic	350	SF	Engineer's Office, Eng Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A	Aircell Duct Insulation	2,650	SF	East, NE, North, South, & SW Unexcavated Areas	CHR	TSI	Y	LOC	200		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
B	Aircell Pipe Insulation	237	LF	S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toilet, Engineer Off., 2nd Flr Boys Tol. Chase	CHR	TSI	Y	LOC	60		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
C	Cardboard Pipe Insulation	800	LF	Throughout (See Hatching Maps)	CHR	TSI	Y	LOC	25		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
D	MJP on Cardboard Pipe Insulation	95	FITTING	Throughout (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Preformed Pipe Insulation	2,150	LF	Throughout (See Hatching Maps)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP on Preform Pipe Insulation	415	FITTING	Throughout (See Hatching Maps)	CHR	TSI	Y	LOC	15		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	MJP on Fiberglass Pipe Insulation	85	FITTING	N. Air Tunnel, NE Unexcavated, East Unexcavated, N. Engine Room, Boiler Room, Pump Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Packing	3	LF	North Heating Coil (Fan Coil Unit in North Engine Room)	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Tank Insulation	150	SF	Tank Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	MJP on Aircell Pipe Insulation	20	FITTING	S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toilet, Engineer Off., 2nd Flr Boys Tol. Chase	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	2'x4' Lay in Ceiling Tile	0		Main & Principal's Offices, Auditorium, Balcony, Library (206/208)	NO_ACBM						No			
L	2'x4' Lay in Ceiling Tile	0		Mobile Classroom Building #1	NO_ACBM				0		No			

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
M	Brown Coat Plaster	0		Tank Room	NO_ACBM				0		No			

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 10/22/2019
Inspector Name Esteban Nunez
100-11255 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
02	
02A	
03	
03A	
04	
04A	
05	
05A	
06	
06A	
07	
07A	
08	
08A	
09	
09A	
10	
10A	
11	
11A	
12	

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
12A	
13	
13A	
14	
14A	
15	
15A	
16	
16A	
17	
17A	
18	
18A	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
31A	
A	Damage in SW Unexcavated Area
B	Damage in SW Unexcavated Area

Chicago Public Schools

School Volta School Unit 25681 Building ID 6270

Address 4950 N Avers Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
C	Damage in SW Unexcavated Area
D	
E	
F	Damage in Boiler Room
G	
H	
I	
J	
K	
L	
M	

Table II

Management Planner's Review

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" Light Brown w/ Dark Brown Speckles VFT	5,500	SF	1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01A	12"x12" Light Brown w/ Dark Brown Speckles VFT Mastic	5,500	SF	1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	9"x9" Light Brown Vinyl Floor Tile	1,200	SF	1st Floor Center Corridor & room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02A	9"x9" Light Brown Vinyl Floor Tile Mastic	1,200	SF	1st Floor Center Corridor & room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	12"x12" White Vinyl Floor Tile	100	SF	Main Office Entryway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03A	12"x12" White Vinyl Floor Tile Mastic	100	SF	Main Office Entryway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Red Vinyl Floor Tile	100	SF	Main Office Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04A	12"x12" Red Vinyl Floor Tile Mastic	100	SF	Main Office Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Dark Brown w/ White Streaks VFT	1,200	SF	1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12"x12" Dark Brown w/ White Streaks VFT Mastic	1,200	SF	1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Brown w/ White Streaks Vinyl Floor Tile	800	SF	1st Floor Main Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9"x9" Brown w/ White Streaks VFT Mastic	800	SF	1st Floor Main Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Rust Vinyl Floor Tile	4,500	SF	Basement Engineer's Storage & Auditorium(now covered in red carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07A	9"x9" Rust Vinyl Floor Tile Mastic	4,500	SF	Basement Engineer's Storage, & Auditorium(now covered in red carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x9" Black w/ White Streaks Vinyl Floor Tile- NOT OBSERVED	700	SF	Room 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
08A	9"x9" Black w/ White Streaks VFT Mastic-NOT OBSERVED	700	SF	Room 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
09	12"x12" White w/ Black Speckles VFT	2,625	SF	Lunchroom (Rooms 115/117) and Room 110, Room 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	12"x12" White w/ Black Speckles VFT Mastic	2,625	SF	Lunchroom (Rooms 115/117) and Room 110, Room 107	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" White w/ Pink Speckles Vinyl Floor Tile	40	SF	Principal's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	12"x12" White w/ Pink Speckles VFT Mastic	40	SF	Principal's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12"x12" Black w/ White Speckles Vinyl Floor Tile	1,625	SF	Lunchroom (115/117), Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	12"x12" Black w/ White Speckles VFT Mastic	1,625	SF	Lunchroom (115/117), Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Peach Vinyl Floor Tile	2,000	SF	Mobile Classroom Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12"x12" Peach Vinyl Floor Tile Mastic	2,000	SF	Mobile Classroom Building #1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
13	9"x 9" Black Vinyl Floor Tile	4,500	SF	Engineer's Store Room, Auditorium (also under the carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	9"x9" Black Vinyl Floor Tile Mastic	4,500	SF	Engineer's Store Room, Auditorium (also under carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9"x9" Dark Brown Vinyl Floor Tile	850	SF	Engineer's Office & Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14A	9"x9" Dark Brown Vinyl Floor Tile Mastic	850	SF	Engineer's Office & Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x9" Beige w/ White Speckles Vinyl Floor Tile	760	SF	1st Floor Center Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	9"x9" Beige w/ White Speckles VFT Mastic	760	SF	1st Floor Center Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x9" Dark Beige w/ White & Brown Speckles VFT	760	SF	1st Floor Center Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	9"x9" Dark Beige w/ White & Brown Speckles VFT Mastic	760	SF	1st Floor Center Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Peach w/ White Streaks VFT	600	SF	Assembly Hall(New Red Carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12"x12" Peach w/ White Streaks VFT Mastic	600	SF	Assembly Hall (New Red Carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Black Vinyl Floor Tile NOT OBSERVED	80	SF	Engineer's Help Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12"x12" Black Vinyl Floor Tile Mastic NOT OBSERVED	80	SF	Engineer's Help Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Gray VFT	50,000	SF	Throughout 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Gray VFT Mastic	50,000	SF	Throughout 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	2'x4' White Ceiling Tile	40,000	SF	Throughout 1996 Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Vinyl Baseboard	60,000	SF	Throughout 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Vinyl Baseboard Mastic	60,000	SF	Throughout 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Drywall	130,000	SF	Throughout 1996 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Drywall Joint Compound	20,000	LF	Throughout 1996 Annex	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
26	Terrazzo	5,000	SF	All stairwells, entry vestibules, and all corridors all levels around the boarders.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Decorative Plaster	2,000	SF	Assembly Hall and Balcony	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Carpet Mastic	1,410	SF	Assembly Hall and Balcony, 2nd Floor Teachers Lounge, Kitchen Main Office, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Fire Doors	7	EA	Auditorium, Projector Room, Stage Door, Boiler Room	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
30	Decorative Plaster	800	SF	Auditorium, Stage, Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" White w/ Light Gray and Gray Streaks	350	SF	Engineer's Office, Eng Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	VFT										
31A	12"x12" White w/ Light Gray and Gray Streaks VFT Mastic	350	SF	Engineer's Office, Eng Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Duct Insulation	2,650	SF	East, NE, North, South, & SW Unexcavated Areas	Chrysotile	TSI	Yes	200	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
B	Aircell Pipe Insulation	237	LF	S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase	Chrysotile	TSI	Yes	60	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
C	Cardboard Pipe Insulation	800	LF	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	25	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D	MJP on Cardboard Pipe Insulation	95	FITTING	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
E	Preformed Pipe Insulation	2,150	LF	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP on Preform Pipe Insulation	415	FITTING	Throughout (See Hatching Maps)	Chrysotile	TSI	Yes	15	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
G	MJP on Fiberglass Pipe Insulation	85	FITTING	N. Air Tunnel, NE Unexcavated, East Unexcavated, N. Engine Room, Boiler Room, Pump Room	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
H	Packing	3	LF	North Heating Coil (Fan Coil Unit in North Engine Room)	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Tank Insulation	150	SF	Tank Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	MJP on Aircell Pipe Insulation	20	FITTING	S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
K	2'x4' Lay in Ceiling Tile	0		Main & Principal's Offices, Auditorium, Balcony, Library (206/208)	No ACBM						
L	2'x4' Lay in Ceiling Tile	0		Mobile Classroom Building #1	No ACBM			0			
M	Brown Coat Plaster	0		Tank Room	No ACBM			0			

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
 Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	10/29/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
02	
02A	
03	
03A	
04	
04A	
05	
05A	

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
06	
06A	
07	
07A	
08	
08A	
09	
09A	
10	
10A	
11	
11A	
12	
12A	
13	
13A	
14	
14A	
15	
15A	
16	
16A	
17	
17A	
18	
18A	

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
 Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
31A	
A	Isolate Area until repair is completed
B	Isolate area until repair is completed
C	Isolate Area until repair is completed
D	
E	
F	Isolate Area, Repair ASAP
G	
H	
I	
J	
K	
L	

Chicago Public Schools

School Volta School
Address 4950 N Avers Avenue

Unit 25681
Chicago, IL, 60625

Building ID 6270
Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
M	

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Brown Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Brown Speckles VFT**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Brown Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Light Brown w/ Dark Brown Speckles VFT Mastic**
MATERIAL LOCATION: **1st, 2nd, & 3rd Floor Corridors, Rooms 103, 109, 109 Storage**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Light Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor & room 202**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9"x9" Light Brown Vinyl Floor Tile**
MATERIAL LOCATION: **1st Floor Center Corridor & room 202**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **9"x9" Light Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor & room 202**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **02A**
MATERIAL DESCRIPTION: **9"x9" Light Brown Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Center Corridor & room 202**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Entryway**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
MATERIAL LOCATION: **Main Office Entryway**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Entryway**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Office Entryway**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12"x12" Red Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **12"x12" Red Vinyl Floor Tile**

MATERIAL LOCATION: **Main Office Storage Room**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Red Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Red Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Office Storage Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Streaks VFT**
MATERIAL LOCATION: **1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor Center Corridor, Balcony(now covered in red carpet), & Help's Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Main Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Main Corridor**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Main Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **1st Floor Main Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Rust Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Engineer's Storage & Auditorium(now covered in red carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **9"x9" Rust Vinyl Floor Tile**
MATERIAL LOCATION: **Basement Engineer's Storage & Auditorium(now covered in red carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9"x9" Rust Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Engineer's Storage, & Auditorium(now covered in red carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **9"x9" Rust Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Basement Engineer's Storage, & Auditorium(now covered in red carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks Vinyl Floor Tile-NOT OBSERVED**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9"x9" Black w/ White Streaks VFT Mastic-NOT OBSERVED**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" White w/ Black Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom (Rooms 115/117) and Room 110, Room 107**
MATERIAL QUANTITY: **2625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12"x12" White w/ Black Speckles VFT**
MATERIAL LOCATION: **Lunchroom (Rooms 115/117) and Room 110, Room 107**
MATERIAL QUANTITY: **2625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12"x12" White w/ Black Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom (Rooms 115/117) and Room 110, Room 107**
MATERIAL QUANTITY: **2625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12"x12" White w/ Black Speckles VFT Mastic**
MATERIAL LOCATION: **Lunchroom (Rooms 115/117) and Room 110, Room 107**
MATERIAL QUANTITY: **2625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12"x12" White w/ Pink Speckles Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Toilet**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" White w/ Pink Speckles Vinyl Floor Tile**

MATERIAL LOCATION: **Principal's Toilet**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **12"x12" White w/ Pink Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Principal's Toilet**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12"x12" White w/ Pink Speckles VFT Mastic**

MATERIAL LOCATION: **Principal's Toilet**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom (115/117), Room 110**
MATERIAL QUANTITY: **1625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles Vinyl Floor Tile**
MATERIAL LOCATION: **Lunchroom (115/117), Room 110**
MATERIAL QUANTITY: **1625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom (115/117), Room 110**
MATERIAL QUANTITY: **1625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12"x12" Black w/ White Speckles VFT Mastic**
MATERIAL LOCATION: **Lunchroom (115/117), Room 110**
MATERIAL QUANTITY: **1625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mobile Classroom Building #1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile**
MATERIAL LOCATION: **Mobile Classroom Building #1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mobile Classroom Building #1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12"x12" Peach Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Mobile Classroom Building #1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x 9" Black Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Store Room, Auditorium (also under the carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **9"x 9" Black Vinyl Floor Tile**
MATERIAL LOCATION: **Engineer's Store Room, Auditorium (also under the carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Store Room, Auditorium (also under carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **9"x9" Black Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Store Room, Auditorium (also under carpet)**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office & Room 202**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Vinyl Floor Tile**
MATERIAL LOCATION: **Engineer's Office & Room 202**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office & Room 202**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **9"x9" Dark Brown Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office & Room 202**
MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Speckles Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x9" Beige w/ White Speckles Vinyl Floor Tile**

MATERIAL LOCATION: **1st Floor Center Corridor**

MATERIAL QUANTITY: **760**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **9"x9" Beige w/ White Speckles VFT Mastic**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **9"x9" Dark Beige w/ White & Brown Speckles VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9"x9" Dark Beige w/ White & Brown Speckles VFT**

MATERIAL LOCATION: **1st Floor Center Corridor**

MATERIAL QUANTITY: **760**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **9"x9" Dark Beige w/ White & Brown Speckles VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **9"x9" Dark Beige w/ White & Brown Speckles VFT Mastic**
MATERIAL LOCATION: **1st Floor Center Corridor**
MATERIAL QUANTITY: **760** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall(New Red Carpet)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT**
MATERIAL LOCATION: **Assembly Hall(New Red Carpet)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall (New Red Carpet)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12"x12" Peach w/ White Streaks VFT Mastic**
MATERIAL LOCATION: **Assembly Hall (New Red Carpet)**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Help Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Engineer's Help Room**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Help Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **12"x12" Black Vinyl Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Engineer's Help Room**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Gray VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Gray VFT**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Gray VFT Mastic**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**

MATERIAL LOCATION: **Throughout 1996 Annex**

MATERIAL QUANTITY: **40000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1996 Annex**

MATERIAL QUANTITY: **60000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **130000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout 1996 Annex**

MATERIAL QUANTITY: **130000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Throughout 1996 Annex**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All stairwells, entry vestibules, and all corridors all levels around the borders.**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUILDING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **All stairwells, entry vestibules, and all corridors all levels around the borders.**

MATERIAL QUANTITY: **5000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assembly Hall and Balcony**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Decorative Plaster**
MATERIAL LOCATION: **Assembly Hall and Balcony**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Assembly Hall and Balcony, 2nd Floor Teachers Lounge, Kitchen Main Office, Main Office**

MATERIAL QUANTITY: **1410**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Assembly Hall and Balcony, 2nd Floor Teachers Lounge, Kitchen Main Office, Main Office**
MATERIAL QUANTITY: **1410** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, Projector Room, Stage Door, Boiler Room**
MATERIAL QUANTITY: **7** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **Auditorium, Projector Room, Stage Door, Boiler Room**
MATERIAL QUANTITY: **7** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Decorative Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, Stage, Balcony**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium, Stage, Balcony**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Gray and Gray Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Eng Storage Room**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" White w/ Light Gray and Gray Streaks VFT**

MATERIAL LOCATION: **Engineer's Office, Eng Storage Room**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Gray and Gray Streaks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Eng Storage Room**

MATERIAL QUANTITY: **350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **12"x12" White w/ Light Gray and Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Engineer's Office, Eng Storage Room**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **East, NE, North, South, & SW Unexcavated Areas**
MATERIAL QUANTITY: **2650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**
COMMENTS: **Damage in SW Unexcavated Area**

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell Duct Insulation**
MATERIAL LOCATION: **East, NE, North, South, & SW Unexcavated Areas**
MATERIAL QUANTITY: **2650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Isolate Area until repair is completed

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase**
MATERIAL QUANTITY: **237** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**
COMMENTS: **Damage in SW Unexcavated Area**

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase**
MATERIAL QUANTITY: **237** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **60** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Isolate area until repair is completed

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**
COMMENTS: **Damage in SW Unexcavated Area**

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **25** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Isolate Area until repair is completed

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **95** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps)**

MATERIAL QUANTITY: **95**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Preformed Pipe Insulation**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **MJP on Preform Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout (See Hatching Maps)**
MATERIAL QUANTITY: **415** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **FITTING**
COMMENTS: **Damage in Boiler Room**

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP on Preform Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps)**

MATERIAL QUANTITY: **415**

MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **15**

DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Isolate Area, Repair ASAP

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **N. Air Tunnel, NE Unexcavated, East Unexcavated, N. Engine Room, Boiler Room, Pump Room**

MATERIAL QUANTITY: **85** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **N. Air Tunnel, NE Unexcavated, East Unexcavated, N. Engine Room, Boiler Room, Pump Room**
MATERIAL QUANTITY: **85** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Packing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Heating Coil (Fan Coil Unit in North Engine Room)**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Packing**
MATERIAL LOCATION: **North Heating Coil (Fan Coil Unit in North Engine Room)**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Tank Insulation**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**
MATERIAL LOCATION: **S. Air Tunnel, & Engine Room, SW Unex., Helps Room Toliet, Engineer Off., 2nd Flr Boys Tol. Chase**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **2'x4' Lay in Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main & Principal's Offices, Auditorium, Balcony, Library (206/208)**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **10/22/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **2'x4' Lay in Ceiling Tile**
MATERIAL LOCATION: **Main & Principal's Offices, Auditorium, Balcony, Library (206/208)**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **2'x4' Lay in Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mobile Classroom Building #1**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **2'x4' Lay in Ceiling Tile**

MATERIAL LOCATION: **Mobile Classroom Building #1**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**
SCHOOL NAME: **Volta School** INSPECTION DATE: **10/22/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Brown Coat Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 10/22/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25681** BUIDLING ID: **6270**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: **Volta School** REVIEW DATE: **10/29/2019**
ADDRESS: **4950 N Avers Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Brown Coat Plaster**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/29/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR20

Certificate Number:



Office: 312-491-0081
Fax: 312-421-2901

A handwritten signature in black ink, appearing to read "N. Peneff", is written over a horizontal line.

Director of Training
Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

FRONT OF LICENSE		BACK OF LICENSE	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11255	ISSUED 4/19/2019	INSPECTOR	2/9/2020
ESTEBAN NUNEZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health	EXPIRES 05/15/2020 	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/15/2019
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
			INSPECTOR	2/28/2020
ID NUMBER	ISSUED	EXPIRES	PROJECT DESIGNER	3/15/2020
100 - 07342	4/19/2019	05/15/2020	MANAGEMENT PLANNER	2/28/2020
JIGAR M SHAH			PROJECT MANAGER	2/22/2020
2942 W VAN BUREN ST			AIR SAMPLING PROFESSIONAL	
CHICAGO, IL 60612			Alteration of this license shall result in legal action	
Environmental Health			This license issued under authority of the State of Illinois	
			Department of Public Health	
			This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed