

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2512
SCHOOL NAME: Whistler School
ADDRESS OF SCHOOL: 11533 S Ada
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/29/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 339

IDPH INSPECTOR LICENSE NUMBER: 100-11102

IDPH LICENSED INSPECTOR NAME(Please Print): Elmer Spraggins II

IDPH MP LICENSE NUMBER: 100-00746

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Whistler School

11533 S Ada
Chicago, IL, 60643

Unit: 25831
Building ID: 6420

IDPH ID Number: 14-016-2990-2512

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 15, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25831 Region: 06 IDPH ID:14-016-2990-2512

School: Whistler School Building ID: 6420

Address: 11533 S Ada

Chicago, IL, 60643

Building Contact: Bainbridge, John

Contact Phone:773-842-9806

Current Building Owners: Chicago Public Schools

Review Date: 09/12/2019

Inspector: Elmer Spraggins II

Inspector IDPH License: 100-11102

Management Planner: Amy Williams

Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 15, 2019

RE: Whistler School, Unit 25831
11533 S Ada
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Whistler School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Whistler School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Whistler School
Address: 11533 S Ada
IDPH ID: 14-016-2990-2512
Contact: Bainbridge, John

Unit: 25831
Chicago, IL, 60643
Building ID: 6420
Phone: 773-842-9806

Region: 06

2. Description of Facility

Original Construction: 1968
Total Square Footage: 32950
Current Occupancy: 339

Additional Construction: 1958,1963
No of Floors: 2

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Elmer Spraggins II

Inspector IDPH license # 100-11102

Signature:
Date: 8/15/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:
Date: 09/12/2019

7. Review Date:09/12/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Whistler School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6420:

101	12x12 Black Floor Tile
101A	12" Black Vinyl Floor Tile Mastic
102	12x12 Blue Floor Tile
102A	12" Blue Floor Tile Mastic
56	12x12 Gray Mottled Vinyl Floor Tile
D	Preform Boiler Breeching
E	Mag Block Insulation

B. The following new homogenous areas have been identified for Building 6420:

101	12x12 Black Floor Tile
101A	12" Black Vinyl Floor Tile Mastic
102	12x12 Blue Floor Tile
102A	12" Blue Floor Tile Mastic
55	12" Cream Mottled Vinyl Floor Tile
55A	12" Cream Mottled Vinyl Floor Tile Mastic
56	12x12 Gray Mottled Vinyl Floor Tile
56A	12" Gray Mottled Vinyl Floor Tile Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

101	12x12 Black Floor Tile
101A	12" Black Vinyl Floor Tile Mastic
102	12x12 Blue Floor Tile
102A	12" Blue Floor Tile Mastic
15	Insulation in Fire Doors
16	Fire Brick
17	Transite
21A	9x9 White/Green Streak Floor Tile Mastic, under 12x12
21B	9x9 Brown/White Streak Floor Tile Mastic
21C	9x9 Grey/Black & White Streak Floor Tile Mastic
21D	9x9 Tan/Beige Streak Floor Tile Mastic
21E	9x9 Tan/Green & Orange Streaks Floor Tile Mastic
21H	9x9 Black/White Streaks Floor Tile Mastic
34	Plaster
35	Brown, Tan & White Ceramic Tile Grout
36	Brown, Tan & White Ceramic Tile Adhesive
37	Grey and Green Ceramic Tile Grout
38	Grey and Green Ceramic Tile Adhesive
39	Grey Carpet Mastic
40	Purple and Grey Ceramic Tile Grout
41	Purple and Grey Ceramic Tile Adhesive
43	12x12 Dark Blue Floor Tile
43M	12x12 Dark Blue Floor Tile Mastic
44	Brown and White Ceramic Tile Grout
45	Brown and White Ceramic Tile Adhesive
46	2x4 White Ceiling Tile
47	9x9 Tan Speckled Floor Tile
47M	12x12 Tan Speckled Floor Tile Mastic
48	Light Grey Ceramic Tile Grout
49	Light Grey Ceramic Tile Adhesive
50	Grey Speckled Terrazzo
51	12x12 Blue-Streaked Vinyl Floor Tile
51A	12x12 Blue-Streaked Vinyl Floor Tile Mastic
52	12x12 Tan Streaked Vinyl Floor Tile
52A	12x12 Tan-Streaked Vinyl Floor Tile Mastic
53	12x12 White-Streaked Vinyl Floor Tile
53A	12x12 White-Streaked Vinyl Floor Tile Mastic
54	12x12 Blue Vinyl Floor Tile
54A	12x12 Blue Vinyl Floor Tile Mastic
55	12" Cream Mottled Vinyl Floor Tile
55A	12" Cream Mottled Vinyl Floor Tile Mastic

56	12x12 Gray Mottled Vinyl Floor Tile
56A	12" Gray Mottled Vinyl Floor Tile Mastic
H	12x12 Blue Floor Tile
I	12x12 Blue Floor Tile Mastic
J	1'x1' Acoustic Ceiling Tile
K	1'x1' Acoustic Ceiling Tile
L	1'x1' Acoustic Ceiling Tile

The following areas were deemed to be inaccessible:

101A	12" Black Vinyl Floor Tile Mastic
102A	12" Blue Floor Tile Mastic
21A	9x9 White/Green Streak Floor Tile Mastic, under 12x12
21B	9x9 Brown/White Streak Floor Tile Mastic
21C	9x9 Grey/Black & White Streak Floor Tile Mastic
21D	9x9 Tan/Beige Streak Floor Tile Mastic
21E	9x9 Tan/Green & Orange Streaks Floor Tile Mastic
21H	9x9 Black/White Streaks Floor Tile Mastic
36	Brown, Tan & White Ceramic Tile Adhesive
38	Grey and Green Ceramic Tile Adhesive
39	Grey Carpet Mastic
41	Purple and Grey Ceramic Tile Adhesive
43M	12x12 Dark Blue Floor Tile Mastic
45	Brown and White Ceramic Tile Adhesive
47M	12x12 Tan Speckled Floor Tile Mastic
49	Light Grey Ceramic Tile Adhesive
55A	12" Cream Mottled Vinyl Floor Tile Mastic
56A	12" Gray Mottled Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Elmer Spraggins II, IDPH License # 100-11102. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Whistler School Building 6420 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01E	9x9 Light Green w/White Streaks Floor Tile	1,040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
01A	9x9 Brown/White Streaks Floor Tile	1,680	SF	Room 119 & 122	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
01B	9x9 Light Gray/Brown & White Streak Floor Tile	3,390	SF	Rooms 116, 117, 120 & 123	CHR	MISC	N	NONE	250		No	ACBM with the potential for damage	2	HIGH
01C	9x9 Tan/Brown & White Streak Floor Tile	8,600	SF	Rooms 105, 121, 118, 217, 218, 219, 220, 221, 222, 223	CHR	MISC	N	NONE	500		No	ACBM with the potential for damage	3	HIGH
01D	9x9 Light Gray/White Streaks Floor Tile	1,975	SF	2nd Floor Corridor	CHR	MISC	N	LOC	5		No	ACBM with the potential for damage	3	MODERATE
06A	9x9 Tan/White Streak Floor Tile ABATED			Main Office, Principal's Office, Office Store Room, and Vault ABATED	ABATED	MISC								Low
06B	9x9 Light Gray/White Streak Floor Tile	2,720	SF	Rooms 115, 129, 126, 125, 216, and Adjustment Room	CHR	MISC	N	NONE	300		No	ACBM with the potential for damage	2	MODERATE
06C	9"x9" Beige w/Brown Streaks Floor tile	2,522	SF	Rooms 124, 127 (Kitchen) and 128	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09A	9x9 White/Green Streaked Floor Tile	1,680	SF	1957 Building-Rooms 114 & 115	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09B	9"x9" Brown w/White Streaks Floor Tile	881	SF	1957 Building-Men's Washroom and Teacher's Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09C	9x9 Gray w/White and Black Streaks Floor Tile	3,242	SF	Rooms 113,115,110,103,and 104	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09D	9x9 Tan/Beige Streak Floor Tile	1,680	SF	Rooms 112 and 102	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09E	9x9 Tan/Green and Orange Streak Floor Tile	1,680	SF	Rooms 101 & 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09F	9x9 Tan/White Specks Floor Tile	2,158	SF	Rooms 108 and 109	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09G	9x9 Green/White Specks Floor Tile	1,080	SF	Room 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09H	9x9 Black/White Streaks Floor Tile	840	SF	Room 100, 110, 115	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12x12 Black Floor Tile	700	SF	Room 220	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
34	Plaster	67,000	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Brown, Tan & White Ceramic Tile Grout	25	SF	Teachers' Lounge Toilet (Room 148)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Brown, Tan & White Ceramic Tile Adhesive	25	SF	Teachers' Lounge Toilet (Room 148)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Grey and Green Ceramic Tile Grout	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Grey and Green Ceramic Tile Adhesive	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Grey Carpet Mastic	728	SF	Room 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Purple and Grey Ceramic Tile Grout	280	SF	North Center Girls' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Purple and Grey Ceramic Tile Adhesive	280	SF	North Center Girls' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12x12 Dark Blue Floor Tile	575	SF	Gym Stage and Gym Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43M	12x12 Dark Blue Floor Tile Mastic	575	SF	Gym Stage and Gym Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Brown and White Ceramic Tile Grout	1,148	SF	SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Brown and White Ceramic Tile Adhesive	1,148	SF	SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	2x4 White Ceiling Tile	13,472	SF	Rooms 116 - 123, and 216 - 223	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
47	9x9 Tan Speckled Floor Tile	1,448	SF	Main Office and Assistant Principal's Office	ASSUMED	MISC	N	LOC	6		No	ACBM with the potential for damage		LOW
47M	12x12 Tan Speckled Floor Tile Mastic	1,448	SF	Main Office and Assistant Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Light Grey Ceramic Tile Grout	504	SF	Lobby Boys' and Girls' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Light Grey Ceramic Tile Adhesive	504	SF	Lobby Boys' and Girls' Restrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
50	Grey Speckled Terrazzo	7,525	SF	Throughout School Corridors, except 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12x12 Blue-Streaked Vinyl Floor Tile	800	SF	Rooms 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51A	12x12 Blue-Streaked Vinyl Floor Tile Mastic	800	SF	Rooms 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12x12 Tan Streaked Vinyl Floor Tile	3,800	SF	Rooms 107/Library, 114, 116/117 (Lunchroom) and 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52A	12x12 Tan-Streaked Vinyl Floor Tile Mastic	3,800	SF	Rooms 107/Library, 114, 116/117 (Lunchroom) and 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12x12 White-Streaked Vinyl Floor Tile	100	SF	Coach's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53A	12x12 White-Streaked Vinyl Floor Tile Mastic	100	SF	Coach's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12x12 Blue Vinyl Floor Tile	80	SF	Coach's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54A	12x12 Blue Vinyl Floor Tile Mastic	80	SF	Coach's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12" Cream Mottled Vinyl Floor Tile	1,700	SF	Principal's & Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55A	12" Cream Mottled Vinyl Floor Tile Mastic	1,700	SF	Principal's & Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12x12 Gray Mottled Vinyl Floor Tile	700	SF	Room 102	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
56A	12" Gray Mottled Vinyl Floor Tile Mastic	700	SF	Room 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Preform Insulation Breaching	25	LF	1966 Building-Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Hard Fittings on Fiberglass Insulation	150	LF	Throughout 1966 Building Boiler Room and Corridors	CHR	TSI	Y	LOC	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
C	Hard Fittings on Fiberglass Insulation	150	LF	Throughout 1957 Building-1st Floor Boiler Room (on Pipe near E Wall) and Corridors	CHR	TSI	Y	DIST	18		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D	Preform Boiler Breaching	50	LF	1957 Boiler room	CHR	TSI	Y	NONE	14		Yes	Damaged or significantly damaged		MODERATE

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												friable thermal system insulating ACBM		
E	Mag Block Insulation	450	SF	1957 Boiler Room	CHR	TSI	Y	NONE	32		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
F	Hard Fittings on Fiberglass Insulation	125	LF	Throughout 1962 Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
G	Spray-On Fireproofing	1,700	SF	1966 Building-Boiler Room and 2nd Floor Mechanical Room	CHR	SURFACE	Y	DIST	500		No	Significantly damaged friable surfacing ACBM	2	HIGH
H	12x12 Blue Floor Tile	500	SF	Kitchen	ASSUMED	MISC	N	NONE	100		No	ACBM with the potential for damage	5	MODERATE
I	12x12 Blue Floor Tile Mastic	500	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J	1'x1' Acoustic Ceiling Tile	9,500	SF	1966 Building-Corridors and All Purpose Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	1'x1' Acoustic Ceiling Tile	7,700	SF	1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	1'x1' Acoustic Ceiling Tile	7,700	SF	1957 Classrooms and Library	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/15/2019
Inspector Name <u>Elmer Spraggins II</u>
<u>100-11102</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01E	
01A	
01B	Room 123 - Floor Popping Up, Tile Held Down w/Wax
01C	Roiums 221 & 222: Tiles Held In Place by Wax
01D	
06A	
06B	Floor Popping Up in Rooms 126 & 129- Held Down with Wax
06C	Mastic says Abated (HA 23C), Observed 2019
09A	
09B	
09C	
09D	
09E	No Access to Room 111
09F	
09G	
09H	
101	
101A	
102	
102A	
12	Teacher's Lounge Prep Room: 3 SQ FT Spray-On Plaster Only Remains by Light Fixture in Poor Condition. Pieces of Acoustical Spray-On Plaster Found on Floor.
13	
14	

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
15	
16	
17	
18A	
18B	
20	
21A	
21B	
21C	
21D	
21E	No Access to Room 111
21F	
21G	
21H	
23A	VFT Marked as Abated (HA 06A)
23B	
23C	
24	
25	
26A	
26B	
26C	20 SF of Damage in Room 222, 30 SF of Damage in Room 221
26D	
26E	
27	
28	
29	
30	
31	

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
43	
43M	
44	
45	
46	
47	Not Observed-possibly beneath other tile
47M	Not Observed-possibly beneath other tile
48	
49	
50	
51	
51A	
52	
52A	
53	
53A	
54	
54A	
55	

Chicago Public Schools

School Whistler School Unit 25831 Building ID 6420

Address 11533 S Ada Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
55A	
56	
56A	
A	
B	
C	Boiler Rooms 1 & 2
D	Boiler Room 2- Some on pipes at Boiler, not Breeching
E	Boiler Rm 2, boilers 1 & 2
F	
G	Boiler Room 1
H	
I	
J	
K	
L	

Table II

Management Planner's Review

Chicago Public Schools

School Whistler School

Unit 25831

Building ID 6420

Address 11533 S Ada

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01E	9x9 Light Green w/White Streaks Floor Tile	1,040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01A	9x9 Brown/White Streaks Floor Tile	1,680	SF	Room 119 & 122	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01B	9x9 Light Gray/Brown & White Streak Floor Tile	3,390	SF	Rooms 116, 117, 120 & 123	Chrysotile	MISC	No	250	SF	6 ACBM with the potential for damage	Remove
01C	9x9 Tan/Brown & White Streak Floor Tile	8,600	SF	Rooms 105, 121, 118, 217, 218, 219, 220, 221, 222, 223	Chrysotile	MISC	No	500	SF	6 ACBM with the potential for damage	Remove
01D	9x9 Light Gray/White Streaks Floor Tile	1,975	SF	2nd Floor Corridor	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9x9 Tan/White Streak Floor Tile ABATED			Main Office, Principal's Office, Office Store Room, and Vault ABATED	Abated	MISC					
06B	9x9 Light Gray/White Streak Floor Tile	2,720	SF	Rooms 115, 129, 126, 125, 216, and Adjustment Room	Chrysotile	MISC	No	300	SF	6 ACBM with the potential for damage	Remove
06C	9"x9" Beige w/Brown Streaks Floor tile	2,522	SF	Rooms 124, 127 (Kitchen) and 128	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09A	9x9 White/Green Streaked Floor Tile	1,680	SF	1957 Building- Rooms 114 & 115	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09B	9"x9" Brown w/White Streaks Floor Tile	881	SF	1957 Building- Men's Washroom and Teacher's Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09C	9x9 Gray w/White and Black Streaks Floor Tile	3,242	SF	Rooms 113,115,110,103,and 104	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09D	9x9 Tan/Beige Streak Floor Tile	1,680	SF	Rooms 112 and 102	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09E	9x9 Tan/Green and Orange Streak Floor Tile	1,680	SF	Rooms 101 & 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09F	9x9 Tan/White Specks Floor Tile	2,158	SF	Rooms 108 and 109	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09G	9x9 Green/White Specks Floor Tile	1,080	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09H	9x9 Black/White Streaks Floor Tile	840	SF	Room 100, 110, 115	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12x12 Black Floor Tile	700	SF	Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101A	12" Black Vinyl Floor Tile Mastic	700	SF	Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12x12 Blue Floor Tile	1,500	SF	Rooms 218 & 219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	12" Blue Floor Tile Mastic	1,500	SF	Rooms 218 & 219	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Acoustical Spray-On Plaster	1,860	SF	1957 Building- Ceiling of Teacher's Lounge and Prep Room	Chrysotile	SURFACE	Yes	3	SF	2 Damaged friable surfacing ACBM	Repair
13	Baseboard - No ACBM			6 FT in Each Classroom	No ACBM	MISC					
14	Baseboard Mastic - No ACBM			6 LF in Each Classroom	No ACBM	MISC					
15	Insulation in Fire Doors	8	EA	Boiler Room Doors	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
16	Fire Brick	20	SF	Boiler Room Incinerator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Transite	3	SF	Boiler Room Incinerator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	Boiler Gasket	40	LF	1966 Boiler Room	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Whistler School

Unit 25831

Building ID 6420

Address 11533 S Ada

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18B	Boiler Gasket - No ACBM			1957 Boiler Room	No ACBM	MISC					
20	Vibration Dampener Cloth - No ACBM			1966 Mechanical Room, 2nd Floor	No ACBM	MISC					
21A	9x9 White/Green Streak Floor Tile Mastic, under 12x12	1,680	SF	Rooms 114 and 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21B	9x9 Brown/White Streak Floor Tile Mastic	881	SF	1957 Building- Men's Toilet & Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21C	9x9 Grey/Black & White Streak Floor Tile Mastic	3,242	SF	Rooms 103, 104, 110, 113 & 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21D	9x9 Tan/Beige Streak Floor Tile Mastic	1,680	SF	Rooms 102 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21E	9x9 Tan/Green & Orange Streaks Floor Tile Mastic	1,680	SF	Rooms 101 & 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21F	9x9 Tan/White Specks Floor Tile Mastic	2,158	SF	Rooms 108 & 109	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21G	9x9 Green/White Specks Floor Tile Mastic	1,080	SF	Room 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21H	9x9 Black/White Streaks Floor Tile Mastic	840	SF	Rooms 100, 110 & 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	9x9 Tan/White Streaks Floor Tile Mastic - Abated			Main Office, Principal's Office, Office Store Room, and Vault		MISC					
23B	9x9 Light Gray/White Streaks Floor Tile Mastic	2,720	SF	Rooms 115, 129, 126, 125, 216, and Adjustment Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23C	9x9 Beige w/Brown Streaks Vinyl Floor Tile Mastic ABATED			Rooms 124, 127, 128 & Kitchen	Abated	MISC					
24	Baseboard - No ACBM			Classrooms, Lobby and Main Office	No ACBM	MISC					
25	Baseboard Mastic - No ACBM			1962 Classrooms, Lobby & Main Office	No ACBM	MISC					
26A	9x9 Brown/White Streaks Floor Tile Mastic	1,680	SF	Room 119 & 122	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26B	9x9 Light Gray/Brown & White Streaks Floor Tile Mastic	3,390	SF	Rooms 116, 117, 120 & 123	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26C	9x9 Tan/Brown & White Streaks Floor Tile Mastic	8,700	SF	Rooms 105, 118, 121, 217, 218, 219, 220, 221, 222, 223, and Coach's Office in Gym	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Follow O&M Plan
26D	9x9 Light Gray/White Streaks Floor Tile Mastic	1,975	SF	2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26E	9x9 Light Green w/White Streaks Floor Tile Mastic	1,040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Carpet Mastic - No ACBM			Library (Room 107)	No ACBM	MISC					
28	1x1 Acoustical Ceiling Tile Mastic - No ACBM			1966 Throughout Corridors and All Purpose Room	No ACBM	MISC					

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	1x1 Acoustical Ceiling Tile Mastic - No ACBM			1962 Classrooms, Office and Corridors	No ACBM	MISC					
30	1x1 Acoustical Ceiling Tile Mastic - No ACBM			1957 Classrooms and Library	No ACBM	MISC					
31	Baseboard - No ACBM			1957 Building- 6 LF in Each Classroom	No ACBM	MISC					
32	Baseboard Mastic - No ACBM			1957 Building- 6 LF in Each Classroom	No ACBM	MISC					
33	Window Glazing			Windows Throughout 1966 Building		MISC					
34	Plaster	67,000	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Brown, Tan & White Ceramic Tile Grout	25	SF	Teachers' Lounge Toilet (Room 148)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Brown, Tan & White Ceramic Tile Adhesive	25	SF	Teachers' Lounge Toilet (Room 148)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Grey and Green Ceramic Tile Grout	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Grey and Green Ceramic Tile Adhesive	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Grey Carpet Mastic	728	SF	Room 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Purple and Grey Ceramic Tile Grout	280	SF	North Center Girls' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Purple and Grey Ceramic Tile Adhesive	280	SF	North Center Girls' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Dark Blue Floor Tile	575	SF	Gym Stage and Gym Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43M	12x12 Dark Blue Floor Tile Mastic	575	SF	Gym Stage and Gym Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Brown and White Ceramic Tile Grout	1,148	SF	SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Brown and White Ceramic Tile Adhesive	1,148	SF	SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2x4 White Ceiling Tile	13,472	SF	Rooms 116 - 123, and 216 - 223	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
47	9x9 Tan Speckled Floor Tile	1,448	SF	Main Office and Assistant Principal's Office	Assumed	MISC	No	6	SF	6 ACBM with the potential for damage	Follow O&M Plan
47M	12x12 Tan Speckled Floor Tile Mastic	1,448	SF	Main Office and Assistant Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Light Grey Ceramic Tile Grout	504	SF	Lobby Boys' and Girls' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Light Grey Ceramic Tile Adhesive	504	SF	Lobby Boys' and Girls' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Grey Speckled Terrazzo	7,525	SF	Throughout School Corridors, except 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12x12 Blue-Streaked Vinyl Floor Tile	800	SF	Rooms 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51A	12x12 Blue-Streaked Vinyl Floor Tile Mastic	800	SF	Rooms 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12x12 Tan Streaked Vinyl Floor Tile	3,800	SF	Rooms 107/Library, 114, 116/117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Whistler School

Unit 25831

Building ID 6420

Address 11533 S Ada

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(Lunchroom) and 133							
52A	12x12 Tan-Streaked Vinyl Floor Tile Mastic	3,800	SF	Rooms 107/Library, 114, 116/117 (Lunchroom) and 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12x12 White-Streaked Vinyl Floor Tile	100	SF	Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53A	12x12 White-Streaked Vinyl Floor Tile Mastic	100	SF	Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12x12 Blue Vinyl Floor Tile	80	SF	Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54A	12x12 Blue Vinyl Floor Tile Mastic	80	SF	Coach's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" Cream Mottled Vinyl Floor Tile	1,700	SF	Principal's & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12" Cream Mottled Vinyl Floor Tile Mastic	1,700	SF	Principal's & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12x12 Gray Mottled Vinyl Floor Tile	700	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	12" Gray Mottled Vinyl Floor Tile Mastic	700	SF	Room 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Preform Insulation Breeching	25	LF	1966 Building- Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Hard Fittings on Fiberglass Insulation	150	LF	Throughout 1966 Building Boiler Room and Corridors	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Hard Fittings on Fiberglass Insulation	150	LF	Throughout 1957 Building-1st Floor Boiler Room (on Pipe near E Wall) and Corridors	Chrysotile	TSI	Yes	18	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D	Preform Boiler Breeching	50	LF	1957 Boiler room	Chrysotile	TSI	Yes	14	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
E	Mag Block Insulation	450	SF	1957 Boiler Room	Chrysotile	TSI	Yes	32	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
F	Hard Fittings on Fiberglass Insulation	125	LF	Throughout 1962 Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Spray-On Fireproofing	1,700	SF	1966 Building- Boiler Room and 2nd Floor Mechanical Room	Chrysotile	SURFACE	Yes	500	SF	3 Significantly damaged friable surfacing ACBM	Repair
H	12x12 Blue Floor Tile	500	SF	Kitchen	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	12x12 Blue Floor Tile Mastic	500	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	1'x1' Acoustic Ceiling Tile	9,500	SF	1966 Building- Corridors and All Purpose Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	1'x1' Acoustic Ceiling Tile	7,700	SF	1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	1'x1' Acoustic Ceiling Tile	7,700	SF	1957 Classrooms and Library	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/12/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01E	
01A	
01B	
01C	
01D	
06A	

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
 Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
06B	
06C	
09A	
09B	
09C	
09D	
09E	
09F	
09G	
09H	
101	
101A	
102	
102A	
12	
13	
14	
15	
16	
17	
18A	
18B	
20	
21A	
21B	
21C	

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
 Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
21D	
21E	
21F	
21G	
21H	
23A	
23B	
23C	
24	
25	
26A	
26B	
26C	
26D	
26E	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
 Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
38	
39	
40	
41	
43	
43M	
44	
45	
46	
47	
47M	
48	
49	
50	
51	
51A	
52	
52A	
53	
53A	
54	
54A	
55	
55A	
56	
56A	

Chicago Public Schools

School Whistler School
Address 11533 S Ada

Unit 25831
Chicago, IL, 60643

Building ID 6420
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Light Green w/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage**

MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01E**
MATERIAL DESCRIPTION: **9x9 Light Green w/White Streaks Floor Tile**
MATERIAL LOCATION: **Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9x9 Brown/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 119 & 122**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **9x9 Brown/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 119 & 122**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Light Gray/Brown & White Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Rooms 116, 117, 120 & 123**
MATERIAL QUANTITY: **3390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **250** DAMAGE UNITS: **SF**
COMMENTS: **Room 123 - Floor Popping Up, Tile Held Down w/Wax**

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **9x9 Light Gray/Brown & White Streak Floor Tile**
MATERIAL LOCATION: **Rooms 116, 117, 120 & 123**
MATERIAL QUANTITY: **3390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **250** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 Tan/Brown & White Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **Rooms 105, 121, 118, 217, 218, 219, 220, 221, 222, 223**
MATERIAL QUANTITY: **8600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS: **Roiums 221 & 222: Tiles Held In Place by Wax**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **9x9 Tan/Brown & White Streak Floor Tile**
MATERIAL LOCATION: **Rooms 105, 121, 118, 217, 218, 219, 220, 221, 222, 223**
MATERIAL QUANTITY: **8600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Cooridor**
MATERIAL QUANTITY: **1975** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **01D**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile**
MATERIAL LOCATION: **2nd Floor Cooridor**
MATERIAL QUANTITY: **1975** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9x9 Tan/White Streak Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Main Office, Principal's Office, Office Store Room, and Vault ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **9x9 Tan/White Streak Floor Tile ABATED**
MATERIAL LOCATION: **Main Office, Principal's Office, Office Store Room, and Vault ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 115, 129, 126, 125, 216, and Adjustment Room**
MATERIAL QUANTITY: **2720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**
COMMENTS: **Floor Popping Up in Rooms 126 & 129- Held Down with Wax**

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streak Floor Tile**
MATERIAL LOCATION: **Rooms 115, 129, 126, 125, 216, and Adjustment Room**
MATERIAL QUANTITY: **2720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **9"x9" Beige w/Brown Streaks Floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 124, 127 (Kitchen) and 128**
MATERIAL QUANTITY: **2522** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Mastic says Abated (HA 23C), Observed 2019**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **9"x9" Beige w/Brown Streaks Floor tile**
MATERIAL LOCATION: **Rooms 124, 127 (Kitchen) and 128**
MATERIAL QUANTITY: **2522** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **9x9 White/Green Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- Rooms 114 & 115**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **9x9 White/Green Streaked Floor Tile**
MATERIAL LOCATION: **1957 Building- Rooms 114 & 115**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **9"x9" Brown w/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- Men's Washroom and Teacher's Lounge**
MATERIAL QUANTITY: **881** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **9"x9" Brown w/White Streaks Floor Tile**
MATERIAL LOCATION: **1957 Building- Men's Washroom and Teacher's Lounge**
MATERIAL QUANTITY: **881** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09C**
MATERIAL DESCRIPTION: **9x9 Gray w/White and Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 113,115,110,103,and 104**
MATERIAL QUANTITY: **3242** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09C**
MATERIAL DESCRIPTION: **9x9 Gray w/White and Black Streaks Floor Tile**
MATERIAL LOCATION: **Rooms 113,115,110,103,and 104**
MATERIAL QUANTITY: **3242** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09D**
MATERIAL DESCRIPTION: **9x9 Tan/Beige Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112 and 102**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09D**
MATERIAL DESCRIPTION: **9x9 Tan/Beige Streak Floor Tile**
MATERIAL LOCATION: **Rooms 112 and 102**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09E**
MATERIAL DESCRIPTION: **9x9 Tan/Green and Orange Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101 & 111**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **No Access to Room 111**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09E**
MATERIAL DESCRIPTION: **9x9 Tan/Green and Orange Streak Floor Tile**
MATERIAL LOCATION: **Rooms 101 & 111**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09F**
MATERIAL DESCRIPTION: **9x9 Tan/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 and 109**
MATERIAL QUANTITY: **2158** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09F**
MATERIAL DESCRIPTION: **9x9 Tan/White Specks Floor Tile**
MATERIAL LOCATION: **Rooms 108 and 109**
MATERIAL QUANTITY: **2158** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09G**
MATERIAL DESCRIPTION: **9x9 Green/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09G**
MATERIAL DESCRIPTION: **9x9 Green/White Specks Floor Tile**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09H**
MATERIAL DESCRIPTION: **9x9 Black/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100, 110, 115**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **09H**
MATERIAL DESCRIPTION: **9x9 Black/White Streaks Floor Tile**
MATERIAL LOCATION: **Room 100, 110, 115**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Acoustical Spray-On Plaster**
HISTORICAL AHERA DAMAGE CATEGORY: **2 Damaged friable surfacing ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON: **Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- Ceiling of Teacher's Lounge and Prep Room**
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

COMMENTS: **Teacher's Lounge Prep Room: 3 SQ FT Spray-On Plaster Only Remains by Light Fixture in Poor Condition. Pieces of Acoustical Spray-On Plaster Found on Floor.**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Acoustical Spray-On Plaster**
MATERIAL LOCATION: **1957 Building- Ceiling of Teacher's Lounge and Prep Room**
MATERIAL QUANTITY: **1860** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Baseboard - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **6 FT in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Baseboard - No ACBM**

MATERIAL LOCATION: **6 FT in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **6 LF in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**

MATERIAL LOCATION: **6 LF in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Insulation in Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Doors**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Insulation in Fire Doors**
MATERIAL LOCATION: **Boiler Room Doors**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Fire Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Incinerator**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Fire Brick**
MATERIAL LOCATION: **Boiler Room Incinerator**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Transite**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room Incinerator**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Transite**
MATERIAL LOCATION: **Boiler Room Incinerator**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Boiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Boiler Gasket**
MATERIAL LOCATION: **1966 Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18B**
MATERIAL DESCRIPTION: **Boiler Gasket - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **18B**
MATERIAL DESCRIPTION: **Boiler Gasket - No ACBM**
MATERIAL LOCATION: **1957 Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Vibration Dampener Cloth - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Mechanical Room, 2nd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Vibration Dampener Cloth - No ACBM**

MATERIAL LOCATION: **1966 Mechanical Room, 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **9x9 White/Green Streak Floor Tile Mastic, under 12x12**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114 and 115**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **9x9 White/Green Streak Floor Tile Mastic, under 12x12**
MATERIAL LOCATION: **Rooms 114 and 115**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21B**
MATERIAL DESCRIPTION: **9x9 Brown/White Streak Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Building- Men's Toilet & Teacher's Lounge**
MATERIAL QUANTITY: **881** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21B**
MATERIAL DESCRIPTION: **9x9 Brown/White Streak Floor Tile Mastic**
MATERIAL LOCATION: **1957 Building- Men's Toilet & Teacher's Lounge**
MATERIAL QUANTITY: **881** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21C**
MATERIAL DESCRIPTION: **9x9 Grey/Black & White Streak Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 103, 104, 110, 113 & 115**
MATERIAL QUANTITY: **3242** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21C**
MATERIAL DESCRIPTION: **9x9 Grey/Black & White Streak Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 103, 104, 110, 113 & 115**
MATERIAL QUANTITY: **3242** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21D**
MATERIAL DESCRIPTION: **9x9 Tan/Beige Streak Floor Tile Mstic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102 & 112**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21D**
MATERIAL DESCRIPTION: **9x9 Tan/Beige Streak Floor Tile Mstic**
MATERIAL LOCATION: **Rooms 102 & 112**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21E**
MATERIAL DESCRIPTION: **9x9 Tan/Green & Orange Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101 & 111**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **No Access to Room 111**

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21E**
MATERIAL DESCRIPTION: **9x9 Tan/Green & Orange Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101 & 111**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21F**
MATERIAL DESCRIPTION: **9x9 Tan/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 & 109**
MATERIAL QUANTITY: **2158** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21F**
MATERIAL DESCRIPTION: **9x9 Tan/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 108 & 109**
MATERIAL QUANTITY: **2158** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21G**
MATERIAL DESCRIPTION: **9x9 Green/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21G**
MATERIAL DESCRIPTION: **9x9 Green/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 106**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21H**
MATERIAL DESCRIPTION: **9x9 Black/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 100, 110 & 115**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21H**
MATERIAL DESCRIPTION: **9x9 Black/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 100, 110 & 115**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **9x9 Tan/White Streaks Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Main Office, Principal's Office, Office Store Room, and Vault**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **VFT Marked as Abated (HA 06A)**

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **9x9 Tan/White Streaks Floor Tile Mastic - Abated**
MATERIAL LOCATION: **Main Office, Principal's Office, Office Store Room, and Vault**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23B**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 115, 129, 126, 125, 216, and Adjustment Room**
MATERIAL QUANTITY: **2720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **23B**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 115, 129, 126, 125, 216, and Adjustment Room**
MATERIAL QUANTITY: **2720** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23C**
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Vinyl Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 124, 127, 128 & Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **23C**
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks Vinyl Floor Tile Mastic ABATED**
MATERIAL LOCATION: **Rooms 124, 127, 128 & Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Baseboard - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms, Lobby and Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Baseboard - No ACBM**

MATERIAL LOCATION: **Classrooms, Lobby and Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 Classrooms, Lobby & Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**

MATERIAL LOCATION: **1962 Classrooms, Lobby & Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **9x9 Brown/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 119 & 122**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **9x9 Brown/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 119 & 122**
MATERIAL QUANTITY: **1680** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26B**
MATERIAL DESCRIPTION: **9x9 Light Gray/Brown & White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116, 117, 120 & 123**
MATERIAL QUANTITY: **3390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26B**
MATERIAL DESCRIPTION: **9x9 Light Gray/Brown & White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 116, 117, 120 & 123**
MATERIAL QUANTITY: **3390** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26C**
MATERIAL DESCRIPTION: **9x9 Tan/Brown & White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 105, 118, 121, 217, 218, 219, 220, 221, 222, 223, and Coach's Office in Gym**
MATERIAL QUANTITY: **8700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS: **20 SF of Damage in Room 222, 30 SF of Damage in Room 221**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26C**
MATERIAL DESCRIPTION: **9x9 Tan/Brown & White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 105, 118, 121, 217, 218, 219, 220, 221, 222, 223, and Coach's Office in Gym**
MATERIAL QUANTITY: **8700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26D**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile Masic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors**
MATERIAL QUANTITY: **1975** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26D**
MATERIAL DESCRIPTION: **9x9 Light Gray/White Streaks Floor Tile Masic**
MATERIAL LOCATION: **2nd Floor Corridors**
MATERIAL QUANTITY: **1975** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26E**
MATERIAL DESCRIPTION: **9x9 Light Green w/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage**

MATERIAL QUANTITY: **1040**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26E**
MATERIAL DESCRIPTION: **9x9 Light Green w/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Carpet Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (Room 107)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet Mastic - No ACBM**

MATERIAL LOCATION: **Library (Room 107)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Throughout Corridors and All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**

MATERIAL LOCATION: **1966 Throughout Corridors and All Purpose Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1962 Classrooms, Office and Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**

MATERIAL LOCATION: **1962 Classrooms, Office and Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Classrooms and Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **1x1 Acoustical Ceiling Tile Mastic - No ACBM**

MATERIAL LOCATION: **1957 Classrooms and Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Baseboard - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Building- 6 LF in Each Classroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Baseboard - No ACBM**

MATERIAL LOCATION: **1957 Building- 6 LF in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1957 Building- 6 LF in Each Classroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Baseboard Mastic - No ACBM**

MATERIAL LOCATION: **1957 Building- 6 LF in Each Classroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Windows Throughout 1966 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Windows Throughout 1966 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **67000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout School**
MATERIAL QUANTITY: **67000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Brown, Tan & White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teachers' Lounge Toilet (Room 148)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Brown, Tan & White Ceramic Tile Grout**
MATERIAL LOCATION: **Teachers' Lounge Toilet (Room 148)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Brown, Tan & White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teachers' Lounge Toilet (Room 148)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Brown, Tan & White Ceramic Tile Adhesive**
MATERIAL LOCATION: **Teachers' Lounge Toilet (Room 148)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Grey and Green Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 108, 109, and Principal's Office Toilet**
MATERIAL QUANTITY: **352** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Grey and Green Ceramic Tile Grout**
MATERIAL LOCATION: **Rooms 106, 108, 109, and Principal's Office Toilet**
MATERIAL QUANTITY: **352** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Grey and Green Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 108, 109, and Principal's Office Toilet**
MATERIAL QUANTITY: **352** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Grey and Green Ceramic Tile Adhesive**
MATERIAL LOCATION: **Rooms 106, 108, 109, and Principal's Office Toilet**
MATERIAL QUANTITY: **352** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Grey Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 114**
MATERIAL QUANTITY: **728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Grey Carpet Mastic**
MATERIAL LOCATION: **Room 114**
MATERIAL QUANTITY: **728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Purple and Grey Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Center Girls' Restroom**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Purple and Grey Ceramic Tile Grout**
MATERIAL LOCATION: **North Center Girls' Restroom**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Purple and Grey Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Center Girls' Restroom**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Purple and Grey Ceramic Tile Adhesive**
MATERIAL LOCATION: **North Center Girls' Restroom**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Stage and Gym Storage Room**
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile**
MATERIAL LOCATION: **Gym Stage and Gym Storage Room**
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43M**
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Stage and Gym Storage Room**
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **43M**
MATERIAL DESCRIPTION: **12x12 Dark Blue Floor Tile Mastic**
MATERIAL LOCATION: **Gym Stage and Gym Storage Room**
MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Brown and White Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom**
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Brown and White Ceramic Tile Grout**
MATERIAL LOCATION: **SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom**
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Brown and White Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom**
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Brown and White Ceramic Tile Adhesive**
MATERIAL LOCATION: **SE Boys' and Girls' Restrooms and 2nd Floor Boys' Restroom**
MATERIAL QUANTITY: **1148** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 116 - 123, and 216 - 223**
MATERIAL QUANTITY: **13472** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **2x4 White Ceiling Tile**
MATERIAL LOCATION: **Rooms 116 - 123, and 216 - 223**
MATERIAL QUANTITY: **13472** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Assistant Principal's Office**
MATERIAL QUANTITY: **1448** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

COMMENTS: **Not Observed-possibly beneath other tile**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile**
MATERIAL LOCATION: **Main Office and Assistant Principal's Office**
MATERIAL QUANTITY: **1448** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47M**
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Assistant Principal's Office**
MATERIAL QUANTITY: **1448** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Not Observed-possibly beneath other tile**

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **47M**
MATERIAL DESCRIPTION: **12x12 Tan Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Main Office and Assistant Principal's Office**
MATERIAL QUANTITY: **1448** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Light Grey Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lobby Boys' and Girls' Restrooms**
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Light Grey Ceramic Tile Grout**
MATERIAL LOCATION: **Lobby Boys' and Girls' Restrooms**
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Light Grey Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lobby Boys' and Girls' Restrooms**
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Light Grey Ceramic Tile Adhesive**
MATERIAL LOCATION: **Lobby Boys' and Girls' Restrooms**
MATERIAL QUANTITY: **504** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Grey Speckled Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout School Corridors, except 2nd Floor Corridor**
MATERIAL QUANTITY: **7525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Grey Speckled Terrazzo**
MATERIAL LOCATION: **Throughout School Corridors, except 2nd Floor Corridor**
MATERIAL QUANTITY: **7525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12x12 Blue-Streaked Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12x12 Blue-Streaked Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51A**
MATERIAL DESCRIPTION: **12x12 Blue-Streaked Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **51A**
MATERIAL DESCRIPTION: **12x12 Blue-Streaked Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 112**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 Tan Streaked Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 107/Library, 114, 116/117 (Lunchroom) and 133**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12x12 Tan Streaked Vinyl Floor Tile**
MATERIAL LOCATION: **Rooms 107/Library, 114, 116/117 (Lunchroom) and 133**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52A**
MATERIAL DESCRIPTION: **12x12 Tan-Streaked Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 107/Library, 114, 116/117 (Lunchroom) and 133**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **52A**
MATERIAL DESCRIPTION: **12x12 Tan-Streaked Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 107/Library, 114, 116/117 (Lunchroom) and 133**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 White-Streaked Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12x12 White-Streaked Vinyl Floor Tile**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **12x12 White-Streaked Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **53A**
MATERIAL DESCRIPTION: **12x12 White-Streaked Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **54A**
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Coach's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Preform Insulation Breeching**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building- Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Preform Insulation Breeching**
MATERIAL LOCATION: **1966 Building- Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage
Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1966 Building Boiler Room and Corridors**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
MATERIAL LOCATION: **Throughout 1966 Building Boiler Room and Corridors**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1957 Building-1st Floor Boiler Room (on Pipe near E Wall) and Corridors**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **18** DAMAGE UNITS: **LF**
COMMENTS: **Boiler Rooms 1 & 2**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
MATERIAL LOCATION: **Throughout 1957 Building-1st Floor Boiler Room (on Pipe near E Wall) and Corridors**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **18** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Preform Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1957 Boiler room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **14**

DAMAGE UNITS: **LF**

COMMENTS: **Boiler Room 2- Some on pipes at Boiler, not Breeching**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Preform Boiler Breeching**
MATERIAL LOCATION: **1957 Boiler room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **14** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Block Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1957 Boiler Room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **32** DAMAGE UNITS: **SF**
COMMENTS: **Boiler Rm 2, boilers 1 & 2**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Mag Block Insulation**
MATERIAL LOCATION: **1957 Boiler Room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **32** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout 1962 Building**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Hard Fittings on Fiberglass Insulation**
MATERIAL LOCATION: **Throughout 1962 Building**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Spray-On Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY: **3 Significantly damaged friable surfacing ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **3. Significantly damaged friable surfacing ACBM**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **HIGH**
MATERIAL LOCATION: **1966 Building- Boiler Room and 2nd Floor Mechanical Room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**
COMMENTS: **Boiler Room 1**

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Spray-On Fireproofing**
MATERIAL LOCATION: **1966 Building- Boiler Room and 2nd Floor Mechanical Room**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **500** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 Building- Corridors and All Purpose Room**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
MATERIAL LOCATION: **1966 Building- Corridors and All Purpose Room**
MATERIAL QUANTITY: **9500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217**

MATERIAL QUANTITY: **7700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
MATERIAL LOCATION: **1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217**
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1957 Classrooms and Library**
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUIDLING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **1'x1' Acoustic Ceiling Tile**
MATERIAL LOCATION: **1957 Classrooms and Library**
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12x12 Black Floor Tile**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **12x12 Black Floor Tile**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12x12 Gray Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12x12 Gray Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12" Cream Mottled Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Principal's & Main Office**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **55A**
MATERIAL DESCRIPTION: **12" Cream Mottled Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Principal's & Main Office**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12" Black Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **101A**
MATERIAL DESCRIPTION: **12" Black Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" Cream Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Principal's & Main Office**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/15/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" Cream Mottled Vinyl Floor Tile**
MATERIAL LOCATION: **Principal's & Main Office**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102A**
MATERIAL DESCRIPTION: **12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 218 & 219**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **102A**

MATERIAL DESCRIPTION: **12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 218 & 219**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **Rooms 218 & 219**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **12x12 Blue Floor Tile**
MATERIAL LOCATION: **Rooms 218 & 219**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Whistler School** INSPECTION DATE: **8/15/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56A**
MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 102**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25831** BUILDING ID: **6420**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Whistler School** REVIEW DATE: **9/12/2019**
ADDRESS: **11533 S Ada** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **56A**

MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/12/2019**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ELMER SPRAGGINS II
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI06

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
275 Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081

Fax: 312-421-2921

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	1/30/2020
100 - 11102	4/16/2019	05/15/2020		PROJECT MANAGER	3/29/2020
ELMER SPRAGGINS II				AIR SAMPLING PROFESSIONAL	
12823 S GREEN				Alteration of this license shall result in legal action	
CHICAGO, IL 60643				This license issued under authority of the State of Illinois	
Environmental Health				Department of Public Health	
				This license is valid only when accompanied by a valid training course certificate.	

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

William S. Williams

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher

Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

4/21/2019

100 - 00746

4/11/2019

05/15/2020

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed