

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2437
SCHOOL NAME: Ashe School
ADDRESS OF SCHOOL: 8505 S Ingleside Avenue
CITY: Chicago, IL, 60619

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 352
IDPH INSPECTOR LICENSE NUMBER: 100-11070
IDPH LICENSED INSPECTOR NAME(Please Print): Mallory Jones
IDPH MP LICENSE NUMBER: 100-00746
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Ashe School

8505 S Ingleside Avenue
Chicago, IL, 60619

Unit: 26191
Building ID: 6900

IDPH ID Number: 14-016-2990-2437

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Amy Williams
100-00746

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: October 02, 2019

RE: Ashe School, Unit 26191
8505 S Ingleside Avenue
Chicago, IL, 60619

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Ashe School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Ashe School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:	Ashe School	Unit:	26191	Region:	06
Address:	8505 S Ingleside Avenue		Chicago, IL, 60619		
IDPH ID:	14-016-2990-2437	Building ID:	6900		
Contact:	Barrett, Lester	Phone:	(312)218-8288		

2. Description of Facility

Original Construction:	1963	Additional Construction:	
Total Square Footage:	55335	No of Floors:	3
Current Occupancy:	352		

3. LEA Designated Person

Contact:	Robert Christlieb	Phone:	(773) 553-3197
Address:	42 West Madison Street		
	Chicago, IL 60602		

4. Managing Environmental Consultant

MEC:	TEM Environmental, Inc.		
Contact:	Steven Geneser		
Address	174 N. Brandon Drive		
	Glendale Heights, IL, 60139		
Phone:	630-790-0880	Fax:	630-790-0882

5. Inspector

Inspector Name: Mallory Jones

Inspector IDPH license #	100-11070	Signature:	
		Date:	10/2/2019

6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license #	100-00746	Signature:	
		Date:	10/31/2019

7. Review Date:10/31/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Ashe School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6900:

08	Encapsulated Spray-On
20	Textured Plaster Ceiling
SP1	Plaster

B. The following new homogenous areas have been identified for Building 6900:

23	Pipe Insulation
24	Pipe Fittings

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	1'x1' Ceiling Tiles
06	12"x12" Brown Floor Tile
08	Encapsulated Spray-On
09	12"x12" Aqua Floor Tile
10	12"x12" Aqua Floor Tile Mastic
11	Baseboard
12	Baseboard Mastic
15	Vibration Damper
16	12"x12" Gray Vinyl Floor Tile
16A	12"x12" Gray Vinyl Floor Tile Mastic
16B	TSI
17	12"x12" Gray Vinyl Floor Tile
17A	12"x12" Gray Vinyl Floor Tile Mastic
18	12"x12" Peach Vinyl Floor Tile
18A	12"X12" Peach Vinyl Floor Tile Mastic
19	12"x12" Light Blue Vinyl Floor Tile
19A	12"x12" Light Blue Vinyl Floor Tile Mastic
20	Textured Plaster Ceiling
21	MJP on Fiberglass Pipe Insulation
22	Blue Carpet Mastic
23	Pipe Insulation
24	Pipe Fittings
FT1	12"x12" Dark Blue Floor Tile
FT2	12"x12" Light Blue Floor Tile
FTM1	12"x12" Dark Blue Floor Tile Mastic
MF1	Beige & Green Terrazzo
SP1	Plaster

The following areas were deemed to be inaccessible:

07	12"x12" Brown Floor Tile Mastic
10	12"x12" Aqua Floor Tile Mastic
12	Baseboard Mastic
15	Vibration Damper
16A	12"x12" Gray Vinyl Floor Tile Mastic
17A	12"x12" Gray Vinyl Floor Tile Mastic
18A	12"X12" Peach Vinyl Floor Tile Mastic
19A	12"x12" Light Blue Vinyl Floor Tile Mastic
22	Blue Carpet Mastic
23	Pipe Insulation

24	Pipe Fittings
CM1	Carpet Mastic (NOT OBSERVED)
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)
FTM1	12"x12" Dark Blue Floor Tile Mastic
FTM2	12"x12" Light Blue Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/1/2019

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Ashe School Building 6900 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	1'x1' Ceiling Tiles	425	SF	Over Trophy Case on 1st Floor (next to stairs)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
06	12"x12" Brown Floor Tile	3,000	SF	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teachers' Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	12"x12" Brown Floor Tile Mastic	3,000	SF	Rooms 300 and 309, South End of 3rd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Encapsulated Spray-On	80,000	SF	Throughout Building	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
09	12"x12" Aqua Floor Tile	55,000	SF	Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12"x12" Aqua Floor Tile Mastic	55,000	SF	1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Baseboard	500	LF	Office Area and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Baseboard Mastic	500	LF	Office Area and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Vibration Damper	5	SF	Fan Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" Gray Vinyl Floor Tile	350	SF	Engineer's Office/Washroom and Locker Room/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16A	12"x12" Gray Vinyl Floor Tile Mastic	350	SF	Engineer's Office/Washroom and Locker Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16B	TSI	872	LF	Small Boiler in	ASSUMED	TSI	Y	LOC	250		No	Damaged or	3	MODERATE

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room near Engineer's Doorway								significantly damaged friable thermal system insulating ACBM		
17	12"x12" Gray Vinyl Floor Tile	80	SF	Engineer's Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17A	12"x12" Gray Vinyl Floor Tile Mastic	80	SF	Engineer's Office/Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12"x12" Peach Vinyl Floor Tile	120	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	12"x12" Peach Vinyl Floor Tile Mastic	120	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Light Blue Vinyl Floor Tile	100	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
19A	12"x12" Light Blue Vinyl Floor Tile Mastic	100	SF	Patchwork in Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Textured Plaster Ceiling	700	SF	Fan Room	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
21	MJP on Fiberglass Pipe Insulation	250	EA	Fan Room and Crawlspace	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Blue Carpet Mastic	1,800	SF	Main Office and Library (Room 104)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Pipe Insulation	300	LF	Pipe Chases - hidden behind walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
24	Pipe Fittings	90	LF	Pipe Chases - hidden behind walls	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
CM1	Carpet Mastic (NOT OBSERVED)			West/North/West Center Wall in Room 302 (NOT OBSERVED)		MISC								
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)			West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)		MISC								
FT1	12"x12" Dark Blue Floor Tile	3,500	SF	Teachers' Dining Area, Sink Room in Cafeteria Area	ASSUMED	MISC	N	DIST	5		No	ACBM with the potential for damage	5	LOW
FT2	12"x12" Light Blue Floor Tile	3,500	SF	Gym Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM1	12"x12" Dark Blue Floor Tile Mastic	3,500	SF	Teacher's Dining Room and Sink	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room in Cafeteria Area										
FTM2	12"x12" Light Blue Floor Tile Mastic	3,500	SF	Gym Area	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MF1	Beige & Green Terrazzo	5,000	SF	Stairs and Landings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
SP1	Plaster	34,000	SF	Ceilings Throughout Facility	ASSUMED	SURFACE	Y	NONE	240		Yes	Significantly damaged friable surfacing ACBM	10	MODERATE

Chicago Public Schools

School Ashe School Unit 26191 Building ID 6900

Address 8505 S Ingleside Avenue Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>10/2/2019</u>
Inspector Name	<u>Mallory Jones</u>
<u>100-11070</u>	<u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
04	
06	
07	
08	
09	There is No Room 111
10	
11	
12	
15	
16	
16A	
16B	Appears to be metal-clad mineral wool insulation
17	
17A	Appears to be 12" Gray Vinyl Floor Tile
18	
18A	
19	
19A	
20	
21	Insulation Removed, Has Bare Pipes; Possibly in inaccessible Crawl Space area
22	
23	
24	

Chicago Public Schools

School Ashe School **Unit** 26191 **Building ID** 6900

Address 8505 S Ingleside Avenue **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
CM1	Not Observed 2019
CM2	Not Observed 2019
FT1	Damage in Cafeteria
FT2	VFT Appears to be 12" Green Floor Tile
FTM1	
FTM2	VFT Appears to be 12" Green Floor Tile
MF1	
SP1	Boiler Room Ceiling Damaged Throughout

Table II

Management Planner's Review

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	1'x1' Ceiling Tiles	425	SF	Over Trophy Case on 1st Floor (next to stairs)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Brown Floor Tile	3,000	SF	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teachers' Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Brown Floor Tile Mastic	3,000	SF	Rooms 300 and 309, South End of 3rd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Encapsulated Spray-On	80,000	SF	Throughout Building	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
09	12"x12" Aqua Floor Tile	55,000	SF	Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" Aqua Floor Tile Mastic	55,000	SF	1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Baseboard	500	LF	Office Area and Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Baseboard Mastic	500	LF	Office Area and Lunchroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15	Vibration Damper	5	SF	Fan Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Gray Vinyl Floor Tile	350	SF	Engineer's Office/Washroom and Locker Room/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16A	12"x12" Gray Vinyl Floor Tile Mastic	350	SF	Engineer's Office/Washroom and Locker Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	TSI	872	LF	Small Boiler in Boiler Room near Engineer's Doorway	Assumed	TSI	Yes	250	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
17	12"x12" Gray Vinyl Floor Tile	80	SF	Engineer's Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	12"x12" Gray Vinyl Floor Tile Mastic	80	SF	Engineer's Office/Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12"x12" Peach Vinyl Floor Tile	120	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	12"X12" Peach Vinyl Floor Tile Mastic	120	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Light Blue Vinyl Floor Tile	100	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19A	12"x12" Light Blue Vinyl Floor Tile Mastic	100	SF	Patchwork in Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Textured Plaster Ceiling	700	SF	Fan Room	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
21	MJP on Fiberglass Pipe Insulation	250	EA	Fan Room and Crawlspace	Assumed	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
22	Blue Carpet Mastic	1,800	SF	Main Office and Library (Room 104)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Pipe Insulation	300	LF	Pipe Chases - hidden behind walls	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	Pipe Fittings	90	LF	Pipe Chases - hidden behind walls	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CM1	Carpet Mastic (NOT OBSERVED)			West/North/West Center Wall in Room 302 (NOT OBSERVED)		MISC					
CM2	Carpet Mastic (MATERIAL NOT OBSERVED)			West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)		MISC					
FT1	12"x12" Dark Blue Floor Tile	3,500	SF	Teachers' Dining Area, Sink Room in Cafeteria Area	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT2	12"x12" Light Blue Floor Tile	3,500	SF	Gym Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM1	12"x12" Dark Blue Floor Tile Mastic	3,500	SF	Teacher's Dining Room and Sink Room in Cafeteria Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM2	12"x12" Light Blue Floor Tile Mastic	3,500	SF	Gym Area	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
MF1	Beige & Green Terrazzo	5,000	SF	Stairs and Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
SP1	Plaster	34,000	SF	Ceilings Throughout Facility	Assumed	SURFACE	Yes	240	SF	3 Significantly damaged friable surfacing ACBM	Repair

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/31/2019
Manager Planner Name	Amy Williams
100-00746	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
06	
07	
08	
09	
10	
11	
12	
15	
16	
16A	
16B	
17	
17A	
18	
18A	
19	
19A	
20	

Chicago Public Schools

School Ashe School
Address 8505 S Ingleside Avenue

Unit 26191
Chicago, IL, 60619

Building ID 6900
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
21	
22	
23	
24	
CM1	
CM2	
FT1	
FT2	
FTM1	
FTM2	
MF1	
SP1	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Over Trophy Case on 1st Floor (next to stairs)		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tiles		
MATERIAL LOCATION:	Over Trophy Case on 1st Floor (next to stairs)		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teachers' Washroom		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
MATERIAL LOCATION:	Rooms 300 and 309 (Aqua), 3rd Floor Corridor and 3rd Floor Teachers' Washroom		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 300 and 309, South End of 3rd Floor Corridor		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	07				
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic				
MATERIAL LOCATION:	Rooms 300 and 309, South End of 3rd Floor Corridor				
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Encapsulated Spray-On		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Encapsulated Spray-On		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12"x12" Aqua Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet**

MATERIAL QUANTITY: **55000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **There is No Room 111**

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	09				
MATERIAL DESCRIPTION:	12"x12" Aqua Floor Tile				
MATERIAL LOCATION:	Rooms 101-111, 201-211, 301- 310, 2nd Floor Teacher's Lounge (next to boy's washroom) and 3rd Floor Janitor's Closet				
MATERIAL QUANTITY:	55000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12"x12" Aqua Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet**

MATERIAL QUANTITY: **55000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12"x12" Aqua Floor Tile Mastic		
MATERIAL LOCATION:	1st, 2nd and 3rd Corridors, Rooms 101-111, 201-211, 301-310, 2nd Floor Teacher's Lounge (next to boy's washroom), 3rd Floor Janitor's Closet		
MATERIAL QUANTITY:	55000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office Area and Lunchroom		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Baseboard		
MATERIAL LOCATION:	Office Area and Lunchroom		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office Area and Lunchroom		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Baseboard Mastic		
MATERIAL LOCATION:	Office Area and Lunchroom		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Vibration Damper		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Fan Room		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Vibration Damper		
MATERIAL LOCATION:	Fan Room		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office/Washroom and Locker Room/Washroom		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile		
MATERIAL LOCATION:	Engineer's Office/Washroom and Locker Room/Washroom		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office/Washroom and Locker Office/Washroom		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	16A				
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	Engineer's Office/Washroom and Locker Office/Washroom				
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16B		
MATERIAL DESCRIPTION:	TSI		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 1. **Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Small Boiler in Boiler Room near Engineer's Doorway		
MATERIAL QUANTITY:	872	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	250	DAMAGE UNITS:	LF
COMMENTS:	Appears to be metal-clad mineral wool insulation		

Inspector's Signature:	_____	Date:	10/02/2019
------------------------	-------	-------	------------

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	16B		
MATERIAL DESCRIPTION:	TSI		
MATERIAL LOCATION:	Small Boiler in Boiler Room near Engineer's Doorway		
MATERIAL QUANTITY:	872	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	250	DAMAGE UNITS:	LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office/Washroom		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile		
MATERIAL LOCATION:	Engineer's Office/Washroom		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17A		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office/Washroom		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	Appears to be 12" Gray Vinyl Floor Tile		

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	17A		
MATERIAL DESCRIPTION:	12"x12" Gray Vinyl Floor Tile Mastic		
MATERIAL LOCATION:	Engineer's Office/Washroom		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" Peach Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" Peach Vinyl Floor Tile		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18A		
MATERIAL DESCRIPTION:	12"X12" Peach Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	18A				
MATERIAL DESCRIPTION:	12"X12" Peach Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	Patchwork in Kitchen				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Light Blue Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Light Blue Vinyl Floor Tile		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19A		
MATERIAL DESCRIPTION:	12"x12" Light Blue Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Patchwork in Kitchen		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	19A				
MATERIAL DESCRIPTION:	12"x12" Light Blue Vinyl Floor Tile Mastic				
MATERIAL LOCATION:	Patchwork in Kitchen				
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Textured Plaster Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Fan Room		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Textured Plaster Ceiling		
MATERIAL LOCATION:	Fan Room		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **10/2/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Room and Crawlspace**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**
COMMENTS: **Insulation Removed, Has Bare Pipes; Possibly in inaccessible Crawl Space area**

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
MATERIAL LOCATION:	Fan Room and Crawlspace		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	EA
DAMAGE QUANTITY:	0	DAMAGE UNITS:	EA

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office and Library (Room 104)		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
MATERIAL LOCATION:	Main Office and Library (Room 104)		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **10/2/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CM1**
MATERIAL DESCRIPTION: **Carpet Mastic (NOT OBSERVED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **West/North/West Center Wall in Room 302 (NOT OBSERVED)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	CM1	
MATERIAL DESCRIPTION:	Carpet Mastic (NOT OBSERVED)	
MATERIAL LOCATION:	West/North/West Center Wall in Room 302 (NOT OBSERVED)	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	CM2
MATERIAL DESCRIPTION:	Carpet Mastic (MATERIAL NOT OBSERVED)
HISTORICAL AHERA DAMAGE CATEGORY	
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2019

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	CM2
MATERIAL DESCRIPTION:	Carpet Mastic (MATERIAL NOT OBSERVED)
MATERIAL LOCATION:	West/South/West Center Walls in Library (MATERIAL NOT OBSERVED)
MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT1		
MATERIAL DESCRIPTION:	12"x12" Dark Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Dining Area, Sink Room in Cafeteria Area		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	5	DAMAGE UNITS:	SF
COMMENTS:	Damage in Cafeteria		

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	FT1				
MATERIAL DESCRIPTION:	12"x12" Dark Blue Floor Tile				
MATERIAL LOCATION:	Teachers' Dining Area, Sink Room in Cafeteria Area				
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	5	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FT2		
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Area		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:	VFT Appears to be 12" Green Floor Tile		

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	FT2				
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile				
MATERIAL LOCATION:	Gym Area				
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	FTM1		
MATERIAL DESCRIPTION:	12"x12" Dark Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher's Dining Room and Sink Room in Cafeteria Area		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	FTM1		
MATERIAL DESCRIPTION:	12"x12" Dark Blue Floor Tile Mastic		
MATERIAL LOCATION:	Teacher's Dining Room and Sink Room in Cafeteria Area		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: 10/31/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **10/2/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM2**
MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Area**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **VFT Appears to be 12" Green Floor Tile**

Inspector's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	FTM2				
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile Mastic				
MATERIAL LOCATION:	Gym Area				
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	MF1		
MATERIAL DESCRIPTION:	Beige & Green Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairs and Landings		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	MF1		
MATERIAL DESCRIPTION:	Beige & Green Terrazzo		
MATERIAL LOCATION:	Stairs and Landings		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**
SCHOOL NAME: **Ashe School** INSPECTION DATE: **10/2/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SP1**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **3 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **3. Significantly damaged friable surfacing ACBM**

DAMAGE REASON: **Water
Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Ceilings Throughout Facility**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **240** DAMAGE UNITS: **SF**
COMMENTS: **Boiler Room Ceiling Damaged Throughout**

Inspector's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Amy Williams		
SCHOOL NAME:	Ashe School	REVIEW DATE:	10/31/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

HOMOGENEOUS AREA:	SP1		
MATERIAL DESCRIPTION:	Plaster		
MATERIAL LOCATION:	Ceilings Throughout Facility		
MATERIAL QUANTITY:	34000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	240	DAMAGE UNITS:	SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Pipe Fittings		
MATERIAL LOCATION:	Pipe Chases - hidden behind walls		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	TSI	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: **10/02/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Ashe School** REVIEW DATE: **10/31/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Pipe Fittings**
MATERIAL LOCATION: **Pipe Chases - hidden behind walls**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26191	BUILDING ID:	6900
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Ashe School	INSPECTION DATE:	10/2/2019		
ADDRESS:	8505 S Ingleside Avenue	IDPH LICENSE NO:	100-11070		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Pipe Insulation		
MATERIAL LOCATION:	Pipe Chases - hidden behind walls		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	TSI	FRIABLE:	
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 10/02/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26191** BUILDING ID: **6900**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**
SCHOOL NAME: **Ashe School** REVIEW DATE: **10/31/2019**
ADDRESS: **8505 S Ingleside Avenue** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Pipe Insulation**
MATERIAL LOCATION: **Pipe Chases - hidden behind walls**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **10/31/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY L. JONES
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR10

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 11070

ISSUED
3/6/2019

EXPIRES
05/15/2020

MALLORY JONES
524 HOMELAND ROAD
MATTESON, IL 60443
Environmental Health



ENDORSEMENTS

SUPERVISOR/WORKER
INSPECTOR

TC EXPIRES

4/9/2019
3/19/2019

PROJECT MANAGER

4/9/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Building Inspector Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

COURSE LENGTH: 4 HOURS

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

Certificate Number: BIR/0808

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com



2539 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

William Williams

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least
70% for re-accreditation under AHERA (Title II)*

Asbestos Management Planner Refresher


Class Date: 02/15/2019
Examination Date: 02/15/2019
STC Certificate Number: STC-20190215-000527AMPR
Certification Expiration: 02/15/2020

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/21/2019

ID NUMBER

ISSUED

EXPIRES

100 - 00746

4/11/2019

05/15/2020

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

AMY J WILLIAMS

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed