

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2450  
SCHOOL NAME: McNair Center  
ADDRESS OF SCHOOL: 4840 West Walton  
CITY: Chicago, IL, 60651

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 384  
IDPH INSPECTOR LICENSE NUMBER: 100-08023  
IDPH LICENSED INSPECTOR NAME(Please Print): Tommy Thompson  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**McNair Center**

4840 West Walton  
Chicago, IL, 60651

Unit: 26301  
Building ID: 7040

IDPH ID Number: 14-016-2990-2450

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 19, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 26301            Region: 02            IDPH ID:14-016-2990-2450

School: McNair Center            Building ID: 7040

Address: 4840 West Walton

Chicago, IL, 60651

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/15/2019

Inspector: Tommy Thompson

Inspector IDPH License: 100-08023

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 19, 2019

RE: McNair Center, Unit 26301  
4840 West Walton  
Chicago, IL, 60651

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at McNair Center, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at McNair Center, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms



## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the McNair Center. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7040:

B. The following new homogenous areas have been identified for Building 7040:

01	Hard Coat Plaster
02	Canvas
03	Hard Coat Plaster
04	1' x 1' White Ceiling Tile
06	12" x 12" Gray VFT
08	Brown Linoleum
10	12" x 12" Gray VFT mastic
11	Brown Linoleum Mastic
12	9" x 9" Red w/ White VFT
13	9" x 9" Red w/ White VFT Mastic
14	9" x 9" Gray w/ Yellow VFT
15	9" x 9" Gray w/ Yellow VFT Mastic
16	12" x 12" Tan VFT
17	12" x 12" Tan VFT Mastic
20	9" x 9" Marble green VFT
21	9" x 9" Marble green VFT Mastic
24	9" x 9" Brown w/ Red & White VFT
25	9" x 9" Brown w/ Red & White VFT Mastic
26	9" x 9" Green VFT
27	9" x 9" Green VFT Mastic
28	12" x 12" White VFT
29	12" x 12" White VFT mastic
30	12" x 12" Black VFT



31	12" x 12" Black VFT Mastic
36	9" x 9" Brown w/ green & cream VFT
37	9" x 9" Brown w/ green & cream VFT Mastic
38	9" x 9" Cream w/ Brown & green VFT
39	9" x 9" Cream w/ Brown & Green VFT Mastic
42	Black Vinyl Baseboard
43	Black Vinyl Baseboard Mastic
44	Brown Vinyl Baseboard
45	Brown Vinyl baseboard mastic
46	9" x 9" Brown VFT
47	9" x 9" Brown VFT Mastic
48	Black Tile border
49	Black Tile border Mastic
50	Green Wall Covering
51	Brown Wall Covering
52	1' x 1' White Ceiling tile
53	9" x 9" Red VFT
54	9" x 9" Red VFT Mastic
55	9" x 9" Brown VFT
56	9" x 9" Brown VFT mastic
57	12" x 12" White w/ Brown streaks VFT
58	12" x 12" White w/ brown streaks VFT Mastic
63	12" x 12" White w/ Blue specks VFT
64	12" x 12" White w/ Blue specks VFT Mastic
65	12" x 12" Brown VFT

66	12" x 12" Brown VFT Mastic
67	12" x 12" Brown VFT
68	12" x 12" Brown VFT Mastic
A	Cardboard Pipe insulation
B	MJP E/F/V on cardboard pipe insulation
C	Aircell Pipe Insulation
D	MJP E/F/V on aircell pipe insulation
E	Wall Caulk

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Tommy Thompson, IDPH License # 100-08023. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The McNair Center Building 7040 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Hard Coat Plaster			Through 1897 Bldg	NO_ACBM						No			
02	Canvas			Throughout 1897 Bldg	NO_ACBM						No			
03	Hard Coat Plaster			Throughout Annex	NO_ACBM						No			
04	1' x 1' White Ceiling Tile			Throughout 1897 Bldg	NO_ACBM						No			
06	12" x 12" Gray VFT			Main Office (14)-1897 Bldg	NO_ACBM						No			
08	Brown Linoleum			Rooms 203, 204 and 208- Annex	NO_ACBM						No			
10	12" x 12" Gray VFT mastic			Main Office -1897 Bldg	NO_ACBM						No			
11	Brown Linoleum Mastic			Rooms 203, 204, 208	NO_ACBM						No			
12	9" x 9" Red w/ White VFT			Room 24, 26 -1897 Bldg	NO_ACBM						No			
13	9" x 9" Red w/ White VFT Mastic			Room 24, 26 -1897 Bldg	NO_ACBM						No			
14	9" x 9" Gray w/ Yellow VFT			Room 13, 25 -1897 Bldg	NO_ACBM						No			
15	9" x 9" Gray w/ Yellow VFT Mastic			Room 13, 25 -1897 Bldg	NO_ACBM						No			
16	12" x 12" Tan VFT			1st Floor teachers lounge & toilet-1897 Bldg	NO_ACBM						No			
17	12" x 12" Tan VFT Mastic			1st Floor teachers lounge & toilet -1897	NO_ACBM						No			
20	9" x 9" Marble green VFT			Room 13, 25 -1897 Bldg	NO_ACBM						No			
21	9" x 9" Marble green VFT Mastic			Room 13, 25 - Bldg	NO_ACBM						No			
24	9" x 9" Brown w/ Red & White VFT			Room 15 - 1897 Bldg	NO_ACBM						No			
25	9" x 9" Brown w/ Red & White VFT Mastic			Room 15 -1897 Bldg	NO_ACBM						No			
26	9" x 9" Green VFT			1st, 2nd, & 3rd floor corridors & west stairwell -1897 bldg	NO_ACBM						No			
27	9" x 9" Green VFT Mastic	1,000	SF	1st, 2nd, & 3rd floor corridors & west stairwell -1897 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
28	12" x 12" White VFT			1st, 2nd, & 3rd floor corridors - 1897 Bldg	NO_ACBM						No			
29	12" x 12" White VFT mastic	1,200	SF	1st, 2nd & 3rd floor	CHR	MISC	N	NONE	0		No	ACBM with the		

# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				corridors - 1897 Bldg								potential for damage		
30	12" x 12" Black VFT	200	SF	1st, 2nd, 3rd & floor corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
31	12" x 12" Black VFT Mastic	200	SF	1st, 2nd, & 3rd floor corridors -1897 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
36	9" x 9" Brown w/ green & cream VFT			Room 15 - 1897 Bldg	NO_ACBM						No			
37	9" x 9" Brown w/ green & cream VFT Mastic			Room 15 - 1897 Bldg	NO_ACBM						No			
38	9" x 9" Cream w/ Brown & green VFT			Room 15 - 1897 Bldg	NO_ACBM						No			
39	9" x 9" Cream w/ Brown & Green VFT Mastic			Room 15 - 1897 Bldg	NO_ACBM						No			
42	Black Vinyl Baseboard			Throughout 1897 Bldg	NO_ACBM						No			
43	Black Vinyl Baseboard Mastic			Throughout 1897 Bldg	NO_ACBM						No			
44	Brown Vinyl Baseboard			Throughout 1897 Bldg	NO_ACBM						No			
45	Brown Vinyl baseboard mastic			Throughout 1897 Bldg	NO_ACBM						No			
46	9" x 9" Brown VFT	3,000	SF	Rooms 202, 203, 204, 206, 207 & 208 -annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
47	9" x 9" Brown VFT Mastic	3,000	SF	Rooms 202, 203, 204, 206, 207 & 208 -annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
48	Black Tile border	500	SF	Rooms 202, 203, 204, 206, 207 & 208 -annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
49	Black Tile border Mastic	500	SF	Rooms 202, 203, 204, 206, 207 & 208 -annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
50	Green Wall Covering			206, 207, & 208 - annex	NO_ACBM						No			
51	Brown Wall Covering			202, 203 & 204 - Annex	NO_ACBM						No			
52	1' x 1' White Ceiling tile			Corridor, rooms 202-204, 203, 207 & 206-208 - Annex	NO_ACBM						No			
53	9" x 9" Red VFT	1,500	SF	Cafeteria - Annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
54	9" x 9" Red VFT Mastic	1,500	SF	Cafeteria - Annex	CHR	MISC	N	NONE	0		No	ACBM with the		

# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
55	9" x 9" Brown VFT	1,600	SF	Cafeteria & Basement stairway - Annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
56	9" x 9" Brown VFT mastic	1,600	SF	Cafeteria & basement stairway - Annex	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
57	12" x 12" White w/ Brown streaks VFT			Principals office, 2nd & 3rd floor janitors closet - 1897 Bldg	NO_ACBM						No			
58	12" x 12" White w/ brown streaks VFT Mastic	300	SF	Principal's office 2nd Floor janitor's closet - 1897 Bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		
63	12" x 12" White w/ Blue specks VFT	0		Corridors & stairwells -1897	NO_ACBM						No			
64	12" x 12" White w/ Blue specks VFT Mastic	0		Corridors & stairwells -1897	NO_ACBM						No			
65	12" x 12" Brown VFT			Stair treads and classrooms throughout 1897	NO_ACBM						No			
66	12" x 12" Brown VFT Mastic	0		Stair treads and classrooms throughout 1897	NO_ACBM						No			
67	12" x 12" Brown VFT	0		Room 203, 202 and 204 - annex	NO_ACBM						No			
68	12" x 12" Brown VFT Mastic	0		Room 203, 202, 204 - annex	NO_ACBM						No			
A	Cardboard Pipe insulation	250	LF	Boiler & basement boys & girls toilets - 1897 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
B	MJP E/F/V on cardboard pipe insulation	52	LF	Boiler Room & basement boys & girls toilets -1897 Bldg	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
C	Aircell Pipe Insulation	785	LF	Basement Boys & girls toilets - annex	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
D	MJP E/F/V on aircell pipe insulation	100	LF	Basement boys & girls toilets - annex	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		
E	Wall Caulk			Throughout 1897 Bldg	NO_ACBM						No			



# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/19/2019</b>
Inspector Name <b>Tommy Thompson</b>
<b>100-08023</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
06	
08	
10	
11	
12	
13	
14	
15	
16	
17	
20	
21	
24	
25	
26	
27	
28	
29	
30	

# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	
36	
37	
38	
39	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
63	
64	
65	
66	
67	
68	
A	

# Chicago Public Schools

School McNair Center Unit 26301 Building ID 7040

Address 4840 West Walton Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
B	
C	
D	
E	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Hard Coat Plaster			Through 1897 Bldg	No ACBM						Follow O&M Plan
02	Canvas			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
03	Hard Coat Plaster			Throughout Annex	No ACBM						Follow O&M Plan
04	1' x 1' White Ceiling Tile			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
06	12" x 12" Gray VFT			Main Office (14)- 1897 Bldg	No ACBM						Follow O&M Plan
08	Brown Linoleum			Rooms 203, 204 and 208- Annex	No ACBM						Follow O&M Plan
10	12" x 12" Gray VFT mastic			Main Office -1897 Bldg	No ACBM						Follow O&M Plan
11	Brown Linoleum Mastic			Rooms 203, 204, 208	No ACBM						Follow O&M Plan
12	9"x 9" Red w/ White VFT			Room 24, 26 - 1897 Bldg	No ACBM						Follow O&M Plan
13	9" x 9" Red w/ White VFT Mastic			Room 24, 26 -1897	No ACBM						Follow O&M Plan
14	9" x 9" Gray w/ Yellow VFT			Room 13, 25 -1897 Bldg	No ACBM						Follow O&M Plan
15	9" x 9" Gray w/ Yellow VFT Mastic			Room 13, 25 -1897 Bldg	No ACBM						Follow O&M Plan
16	12" x 12" Tan VFT			1st Floor teachers lounge & toilet- 1897 Bldg	No ACBM						Follow O&M Plan
17	12" x 12" Tan VFT Mastic			1st Floor teachers lounge & toilet -1897	No ACBM						Follow O&M Plan
20	9" x 9" Marble green VFT			Room 13, 25 -1897 Bldg	No ACBM						Follow O&M Plan
21	9" x 9" Marble green VFT Mastic			Room 13, 25 - Bldg	No ACBM						Follow O&M Plan
24	9" x 9" Brown w/ Red & White VFT			Room 15 - 1897 Bldg	No ACBM						Follow O&M Plan
25	9" x 9" Brown w/ Red & White VFT Mastic			Room 15 -1897 Bldg	No ACBM						Follow O&M Plan
26	9" x 9" Green VFT			1st, 2nd, & 3rd floor corridors & west stairwell -1897 bldg	No ACBM						Follow O&M Plan
27	9" x 9" Green VFT Mastic	1,000	SF	1st, 2nd, & 3rd floor corridors & west stairwell -1897 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" White VFT			1st, 2nd, & 3rd floor corridors - 1897 Bldg	No ACBM						Follow O&M Plan
29	12" x 12" White VFT mastic	1,200	SF	1st, 2nd & 3rd floor corridors - 1897 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Black VFT	200	SF	1st, 2nd, 3rd & floor corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Black VFT Mastic	200	SF	1st, 2nd, & 3rd floor corridors -1897 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9" x 9" Brown w/ green & cream VFT			Room 15 - 1897 Bldg	No ACBM						Follow O&M Plan
37	9" x 9" Brown w/ green & cream VFT Mastic			Room 15 - 1897 Bldg	No ACBM						Follow O&M Plan
38	9" x 9" Cream w/ Brown & green VFT			Room 15 - 1897 Bldg	No ACBM						Follow O&M Plan
39	9" x 9" Cream w/ Brown & Green VFT Mastic			Room 15 - 1897 Bldg	No ACBM						Follow O&M Plan

# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42	Black Vinyl Baseboard			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
43	Black Vinyl Baseboard Mastic			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
44	Brown Vinyl Baseboard			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
45	Brown Vinyl baseboard mastic			Throughout 1897 Bldg	No ACBM						Follow O&M Plan
46	9" x 9" Brown VFT	3,000	SF	Rooms 202, 203, 204, 206, 207 & 208 - annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9" x 9" Brown VFT Mastic	3,000	SF	Rooms 202, 203, 204, 206, 207 & 208 - annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Black Tile border	500	SF	Rooms 202, 203, 204, 206, 207 & 208 - annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Black Tile border Mastic	500	SF	Rooms 202, 203, 204, 206, 207 & 208 - annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Green Wall Covering			206, 207, & 208 - annex	No ACBM						Follow O&M Plan
51	Brown Wall Covering			202, 203 & 204 -Annex	No ACBM						Follow O&M Plan
52	1' x 1' White Ceiling tile			Corridor, rooms 202-204, 203, 207 & 206-208 - Annex	No ACBM						Follow O&M Plan
53	9" x 9" Red VFT	1,500	SF	Cafeteria - Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	9" x 9" Red VFT Mastic	1,500	SF	Cafeteria - Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	9" x 9" Brown VFT	1,600	SF	Cafeteria & Basement stairway - Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	9" x 9" Brown VFT mastic	1,600	SF	Cafeteria & basement stairway - Annex	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" White w/ Brown streaks VFT			Principals office, 2nd & 3rd floor janitors closet - 1897 Bldg	No ACBM						Follow O&M Plan
58	12" x 12" White w/ brown streaks VFT Mastic	300	SF	Principal's office 2nd Floor janitor's closet - 1897 Bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12" x 12" White w/ Blue specks VFT	0		Corridors & stairwells -1897	No ACBM						Follow O&M Plan
64	12" x 12" White w/ Blue specks VFT Mastic	0		Corridors & stairwells -1897	No ACBM						Follow O&M Plan
65	12" x 12" Brown VFT			Stair treads and classrooms throughout 1897	No ACBM						Follow O&M Plan
66	12" x 12" Brown VFT Mastic	0		Stair treads and classrooms throughout 1897	No ACBM						Follow O&M Plan
67	12" x 12" Brown VFT	0		Room 203, 202 and 204 - annex	No ACBM						Follow O&M Plan
68	12" x 12" Brown VFT Mastic	0		Room 203, 202, 204 - annex	No ACBM						Follow O&M Plan
A	Cardboard Pipe insulation	250	LF	Boiler & basement boys & girls toilets - 1897 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
 Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
B	MJP E/F/V on cardboard pipe insulation	52	LF	Boiler Room & basement boys & girls toilets -1897 Bldg	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	785	LF	Basement Boys & girls toilets - annex	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on aircell pipe insulation	100	LF	Basement boys & girls toilets - annex	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Wall Caulk			Throughout 1897 Bldg	No ACBM						Follow O&M Plan

# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
 Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	10/15/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
06	
08	
10	
11	
12	
13	
14	
15	
16	
17	
20	
21	
24	
25	
26	
27	
28	
29	
30	
31	
36	
37	



# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
38	
39	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
63	
64	
65	
66	
67	
68	
A	

# Chicago Public Schools

**School** McNair Center  
**Address** 4840 West Walton

**Unit** 26301  
Chicago, IL, 60651

**Building ID** 7040  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
B	
C	
D	
E	

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Through 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY:      FRIABLE:  
ASBESTOS TYPE: **No ACBM**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Through 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red & White VFT Mastic**  
MATERIAL LOCATION: **Room 15 -1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" White w/ brown streaks VFT Mastic**  
MATERIAL LOCATION: **Principal's office 2nd Floor janitor's closet - 1897 Bldg**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" White w/ brown streaks VFT Mastic**  
MATERIAL LOCATION: **Principal's office 2nd Floor janitor's closet - 1897 Bldg**  
MATERIAL QUANTITY: **300**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT**  
MATERIAL LOCATION: **Room 203, 202 and 204 - annex**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic**  
MATERIAL LOCATION: **Room 203, 202, 204 - annex**  
MATERIAL QUANTITY: **0**      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on aircell pipe insulation**  
MATERIAL LOCATION: **Basement boys & girls toilets - annex**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **TSI**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **MJP E/F/V on aircell pipe insulation**  
MATERIAL LOCATION: **Basement boys & girls toilets - annex**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **9"x 9" Red w/ White VFT**  
MATERIAL LOCATION: **Room 24, 26 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **9" x 9" Green VFT**  
MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors & west stairwell -1897 bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **9" x 9" Green VFT Mastic**  
MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors & west stairwell -1897 Bldg**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ green & cream VFT**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY:      FRIABLE:  
ASBESTOS TYPE: **No ACBM**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ green & cream VFT**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ green & cream VFT Mastic**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout 1897 Bldg**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1' x 1' White Ceiling tile**  
MATERIAL LOCATION: **Corridor, rooms 202-204, 203, 207 & 206-208 - Annex**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY:      FRIABLE:  
ASBESTOS TYPE: **No ACBM**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **1' x 1' White Ceiling tile**  
MATERIAL LOCATION: **Corridor, rooms 202-204, 203, 207 & 206-208 - Annex**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT Mastic**  
MATERIAL LOCATION: **Stair treads and classrooms throughout 1897**  
MATERIAL QUANTITY: **0**      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**  
MATERIAL LOCATION: **Main Office (14)- 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **Rooms 203, 204 and 208- Annex**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Yellow VFT**  
MATERIAL LOCATION: **Room 13, 25 -1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Yellow VFT Mastic**  
MATERIAL LOCATION: **Room 13, 25 -1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Tan VFT Mastic**

MATERIAL LOCATION: **1st Floor teachers lounge & toilet -1897**

MATERIAL QUANTITY:      MATERIAL UNITS:

DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red & White VFT**

MATERIAL LOCATION: **Room 15 - 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/ Red & White VFT**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/ Brown & green VFT**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY:      FRIABLE:  
ASBESTOS TYPE: **No ACBM**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/ Brown & green VFT**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:

DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Brown Wall Covering**

MATERIAL LOCATION: **202, 203 & 204 -Annex**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Brown Wall Covering**  
MATERIAL LOCATION: **202, 203 & 204 -Annex**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue specks VFT Mastic**  
MATERIAL LOCATION: **Corridors & stairwells -1897**  
MATERIAL QUANTITY: **0**      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **1' x 1' White Ceiling Tile**  
MATERIAL LOCATION: **Throughout 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12" x 12" White VFT**  
MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY:      FRIABLE:  
ASBESTOS TYPE: **No ACBM**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" White VFT**

MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors - 1897 Bldg**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**  
MATERIAL LOCATION: **Throughout 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Black Tile border Mastic**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Black Tile border Mastic**

MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**

MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT mastic**  
MATERIAL LOCATION: **Cafeteria & basement stairway - Annex**  
MATERIAL QUANTITY: **1600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT mastic**  
MATERIAL LOCATION: **Cafeteria & basement stairway - Annex**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue specks VFT**

MATERIAL LOCATION: **Corridors & stairwells -1897**

MATERIAL QUANTITY: **0**      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue specks VFT**  
MATERIAL LOCATION: **Corridors & stairwells -1897**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **9" x 9" Red w/ White VFT Mastic**  
MATERIAL LOCATION: **Room 24, 26 -1897**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12" x 12" Tan VFT**  
MATERIAL LOCATION: **1st Floor teachers lounge & toilet- 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9" x 9" Marble green VFT Mastic**  
MATERIAL LOCATION: **Room 13, 25 - Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT**  
MATERIAL LOCATION: **1st, 2nd, 3rd & floor corridors**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 10/15/2019





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/ Brown & Green VFT Mastic**  
MATERIAL LOCATION: **Room 15 - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Brown Vinyl baseboard mastic**

MATERIAL LOCATION: **Throughout 1897 Bldg**

MATERIAL QUANTITY:      MATERIAL UNITS:

DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT Mastic**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT Mastic**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Cardboard Pipe insulation**  
MATERIAL LOCATION: **Boiler & basement boys & girls toilets - 1897 Bldg**  
MATERIAL QUANTITY: **250**      MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT mastic**  
MATERIAL LOCATION: **Main Office -1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9" x 9" Marble green VFT**  
MATERIAL LOCATION: **Room 13, 25 -1897 Bldg**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT**  
MATERIAL LOCATION: **Cafeteria & Basement stairway - Annex**  
MATERIAL QUANTITY: **1600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **9" x 9" Brown VFT**  
MATERIAL LOCATION: **Cafeteria & Basement stairway - Annex**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on cardboard pipe insulation**  
MATERIAL LOCATION: **Boiler Room & basement boys & girls toilets -1897 Bldg**  
MATERIAL QUANTITY: **52**    MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **TSI**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **MJP E/F/V on cardboard pipe insulation**  
MATERIAL LOCATION: **Boiler Room & basement boys & girls toilets -1897 Bldg**  
MATERIAL QUANTITY: **52**      MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Basement Boys & girls toilets - annex**  
MATERIAL QUANTITY: **785**      MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Canvas**  
MATERIAL LOCATION: **Throughout 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" White VFT mastic**  
MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors - 1897 Bldg**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26301** BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center** REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton** IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" x 12" White VFT mastic**  
MATERIAL LOCATION: **1st, 2nd & 3rd floor corridors - 1897 Bldg**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors -1897 Bldg**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Barely Reachable**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
MATERIAL LOCATION: **1st, 2nd, & 3rd floor corridors -1897 Bldg**  
MATERIAL QUANTITY: **200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 10/15/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26301**    BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**    INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**    IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **9" x 9" Red VFT**  
MATERIAL LOCATION: **Cafeteria - Annex**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **9" x 9" Red VFT**  
MATERIAL LOCATION: **Cafeteria - Annex**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **9" x 9" Red VFT Mastic**  
MATERIAL LOCATION: **Cafeteria - Annex**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12" White w/ Brown streaks VFT**  
MATERIAL LOCATION: **Principals office, 2nd & 3rd floor janitors closet - 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Wall Caulk**  
MATERIAL LOCATION: **Throughout 1897 Bldg**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **Rooms 203, 204, 208**

MATERIAL QUANTITY:      MATERIAL UNITS:

MATERIAL CATEGORY:      FRIABLE:

ASBESTOS TYPE: **No ACBM**

DISTURBANCE POTENTIAL:      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/19/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic**  
MATERIAL LOCATION: **Rooms 203, 204, 208**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Tommy Thompson**  
SCHOOL NAME: **McNair Center**      INSPECTION DATE: **9/19/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Black Tile border**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/19/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Black Tile border**  
MATERIAL LOCATION: **Rooms 202, 203, 204, 206, 207 & 208 -annex**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 10/15/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Green Wall Covering**  
MATERIAL LOCATION: **206, 207, & 208 - annex**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26301**      BUILDING ID: **7040**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **McNair Center**      REVIEW DATE: **10/15/2019**  
ADDRESS: **4840 West Walton**      IDPH LICENSE NO: **100-08023**

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Brown VFT**  
MATERIAL LOCATION: **Stair treads and classrooms throughout 1897**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/15/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that TOMMY R. THOMPSON  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR21

Certificate Number:



A handwritten signature in black ink, appearing to read "N. Peneff".

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TOMMY THOMPSON**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

5/9/2018

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08023

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

ID NUMBER		ISSUED	EXPIRES	ENDORSEMENTS	TC EXPIRES
100 - 08023		5/9/2018	05/15/2019	INSPECTOR	2/10/2019
<b>TOMMY THOMPSON</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/3/2019
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that TOMMY R. THOMPSON  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR21

Certificate Number:

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that TOMMY R. THOMPSON  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR21

Certificate Number:



*Nicholas J. Peneff*

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TOMMY THOMPSON**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08023

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

FRONT OF LICENSE		BACK OF LICENSE	
	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 08023	<b>ISSUED</b> 4/19/2019	INSPECTOR	2/9/2020
<b>EXPIRES</b> 05/15/2020		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/2/2020
<b>TOMMY THOMPSON</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*





625-935 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

4/18/2016

**TOMMY THOMPSON**  
855 W. Adams, Suite 200  
Chicago, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08023

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>		<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR</p> <p>PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p> <p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	<p><b>TC EXPIRES</b></p> <p>2/13/2017</p> <p>2/6/2017</p>
<p><b>ID NUMBER</b> 100 - 08023</p> <p><b>TOMMY THOMPSON</b> 855 W. Adams, Suite 200 Chicago, IL 60607 Environmental Health</p>	<p><b>ISSUED</b> 4/18/2016</p> <p><b>EXPIRES</b> 05/15/2017</p> 		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 07342	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/28/2020 3/15/2020 2/28/2020 2/22/2020
<b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed