

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2267  
SCHOOL NAME: Hinton School  
ADDRESS OF SCHOOL: 644 W. 71st St.  
CITY: Chicago, IL, 60621

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/14/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 230  
IDPH INSPECTOR LICENSE NUMBER: 100-09106  
IDPH LICENSED INSPECTOR NAME(Please Print): Michael Hasier  
IDPH MP LICENSE NUMBER: 100-00746  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Amy Williams

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Hinton School**

644 W. 71st St.  
Chicago, IL, 60621

Unit: 26371  
Building ID: 7250

IDPH ID Number: 14-016-2990-2267

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 25, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 26371            Region: 05            IDPH ID:14-016-2990-2267

School: Hinton School            Building ID: 7250

Address: 644 W. 71st St.

Chicago, IL, 60621

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/20/2019

Inspector: Michael Hasier

Inspector IDPH License: 100-09106

Management Planner: Amy Williams

Management Planner IDPH License: 100-00746

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Amy Williams  
100-00746

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 25, 2019

RE: Hinton School, Unit 26371  
644 W. 71st St.  
Chicago, IL, 60621

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Hinton School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Hinton School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Hinton School  
Address: 644 W. 71st St.  
IDPH ID: 14-016-2990-2267  
Contact:

Unit: 26371  
Chicago, IL, 60621  
Building ID: 7250  
Phone:

Region: 05

### 2. Description of Facility

Original Construction: 1965  
Total Square Footage: 71892  
Current Occupancy: 230

Additional Construction:  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Michael Hasier

Inspector IDPH license # 100-09106

Signature:  
Date: 9/25/2019

### 6. Management Planner

Management Planner Name: Amy Williams

Management Planner IDPH license # 100-00746

Signature:  
Date: 10/20/2019

### 7. Review Date: 10/20/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hinton School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7250:

B. The following new homogenous areas have been identified for Building 7250:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|    |  |
|----|--|
| 02 | Drywall  |
| 10 | 12x12 Dark Blue w/White Floor Tile Mastic        |
| 11 | 12x12 Blue w/White Floor Tile                    |
| 12 | 12x12 Blue w/White Floor Tile Mastic             |
| 13 | Green Chalkboard                                 |
| 14 | Green Chalkboard Adhesive                        |
| 15 | 2x4 Ceiling Tile                                 |
| 16 | 12x12 White w/Tan Floor Tile                     |
| 17 | 12x12 White w/Tan Floor Tile Mastic              |
| 18 | 12x12 Light Brown w/Dark Brown Floor Tile        |
| 19 | 12x12 Light Brown w/Dark Brown Floor Tile Mastic |
| 20 | Maroon & Tan Terrazzo                            |
| 21 | 12x12 Grey Floor Tile                            |
| 22 | 12x12 Grey Floor Tile Mastic                     |
| 23 | 12"X12" Light Blue Vinyl Floor Tile              |
| 24 | 12"X12" Light Blue Vinyl Floor Tile Mastic       |
| 8A | 12x12 White w/Blue Floor Tile                    |
| 8B | 12x12 White w/Blue Floor Tile Mastic             |
| 9  | 12x12 Dark Blue w/White Floor Tile               |

The following areas were deemed to be inaccessible:

|    |  |
|----|--|
| 10 | 12x12 Dark Blue w/White Floor Tile Mastic        |
| 12 | 12x12 Blue w/White Floor Tile Mastic             |
| 14 | Green Chalkboard Adhesive                        |
| 17 | 12x12 White w/Tan Floor Tile Mastic              |
| 19 | 12x12 Light Brown w/Dark Brown Floor Tile Mastic |
| 22 | 12x12 Grey Floor Tile Mastic                     |
| 24 | 12"X12" Light Blue Vinyl Floor Tile Mastic       |
| 8B | 12x12 White w/Blue Floor Tile Mastic             |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Hasier, IDPH License # 100-09106. The Management Plan was updated by Amy Williams, IDPH License # 100-00746. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Hinton School Building 7250 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Hinton School Unit 26371 Building ID 7250

Address 644 W. 71st St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 01B   | Hard Plaster-NOT OBSERVED                         |                   |                | 2nd Floor Fan Room & Storage Room in Kitchen                                      | CHR           | SURFACE           |         |             |                 |              |                               |  |               |                       |
| 02    | Drywall   | 1,000             | SF             | 2nd Floor Fan Room & Storage Room in Kitchen                                      | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 03    | 12x12 Vinyl Floor Tile - ABATED Summer 1995       |                   |                | 1st Floor East Corridor & Kitchen   | ABATED        | MISC              |         |             |                 |              |                               |  |               | Moderate              |
| 07    | 12x12 Vinyl Floor Tile Mastic- ABATED Summer 1995 |                   |                | 1st Floor East Corridor & Kitchen   | ABATED        | MISC              |         |             |                 |              |                               |  |               |                       |
| 10    | 12x12 Dark Blue w/White Floor Tile Mastic         | 20,000            | SF             | 1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 11    | 12x12 Blue w/White Floor Tile                     | 30,000            | SF             | 1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 12    | 12x12 Blue w/White Floor Tile Mastic              | 30,000            | SF             | 1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym                             | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 13    | Green Chalkboard                                  | 6,000             | SF             | Classrooms  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 14    | Green Chalkboard Adhesive                         | 6,000             | SF             | Classrooms  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 15    | 2x4 Ceiling Tile                                  | 50,000            | SF             | Throughout  | ASSUMED       | MISC              | Y       | NONE        | 0               |              | No                            | Any remaining friable ACBM or friable suspect ACBM |               | LOW                   |
| 16    | 12x12 White w/Tan Floor Tile                      | 2,000             | SF             | 3rd Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 17    | 12x12 White w/Tan Floor Tile Mastic               | 2,000             | SF             | 3rd Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 18    | 12x12 Light Brown w/Dark Brown Floor Tile         | 2,000             | SF             | 3rd Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 19    | 12x12 Light Brown w/Dark Brown Floor Tile Mastic  | 2,000             | SF             | 3rd Floor Hallway   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 20    | Maroon & Tan Terrazzo                             | 3,000             | SF             | Stairwell & Entrance  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 21    | 12x12 Grey Floor Tile                             | 100               | SF             | Engineer's Office   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 22    | 12x12 Grey Floor Tile Mastic                      | 100               | SF             | Engineer's Office   | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the                                      |               | LOW                   |



# Chicago Public Schools

School Hinton School Unit 26371 Building ID 7250

Address 644 W. 71st St. Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>9/25/2019</b>                |
| Inspector Name <b>Michael Hasier</b>              |
| <b>100-09106</b> <b>5/15/2020</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments:         |
|------------|-----------------------------|
| 01B        | Not Observed Multiple Years |
| 02         |                             |
| 03         |                             |
| 07         |                             |
| 10         |                             |
| 11         |                             |
| 12         |                             |
| 13         |                             |
| 14         |                             |
| 15         |                             |
| 16         |                             |
| 17         |                             |
| 18         |                             |
| 19         |                             |
| 20         |                             |
| 21         |                             |
| 22         |                             |
| 23         |                             |
| 24         |                             |
| 8A         |                             |
| 8B         |                             |
| 9          |                             |
| C          |                             |

# Chicago Public Schools

**School** Hinton School **Unit** 26371 **Building ID** 7250

**Address** 644 W. 71st St. **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** Hinton School  
**Address** 644 W. 71st St.

**Unit** 26371  
Chicago, IL, 60621

**Building ID** 7250  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description                              | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 01B       | Hard Plaster-NOT OBSERVED                         |                   |                | 2nd Floor Fan Room & Storage Room in Kitchen                                      | Chrysotile    | SURFACE           |         |                 |              |  |                 |
| 02        | Drywall   | 1,000             | SF             | 2nd Floor Fan Room & Storage Room in Kitchen                                      | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 03        | 12x12 Vinyl Floor Tile - ABATED Summer 1995       |                   |                | 1st Floor East Corridor & Kitchen   | Abated        | MISC              |         |                 |              |  |                 |
| 07        | 12x12 Vinyl Floor Tile Mastic- ABATED Summer 1995 |                   |                | 1st Floor East Corridor & Kitchen   | Abated        | MISC              |         |                 |              |  |                 |
| 10        | 12x12 Dark Blue w/White Floor Tile Mastic         | 20,000            | SF             | 1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 11        | 12x12 Blue w/White Floor Tile                     | 30,000            | SF             | 1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym                             | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 12        | 12x12 Blue w/White Floor Tile Mastic              | 30,000            | SF             | 1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym                             | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 13        | Green Chalkboard                                  | 6,000             | SF             | Classrooms  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 14        | Green Chalkboard Adhesive                         | 6,000             | SF             | Classrooms  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 15        | 2x4 Ceiling Tile                                  | 50,000            | SF             | Throughout  | Assumed       | MISC              | Yes     | 0               | SF           | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 16        | 12x12 White w/Tan Floor Tile                      | 2,000             | SF             | 3rd Floor Hallway   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 17        | 12x12 White w/Tan Floor Tile Mastic               | 2,000             | SF             | 3rd Floor Hallway   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 18        | 12x12 Light Brown w/Dark Brown Floor Tile         | 2,000             | SF             | 3rd Floor Hallway   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 19        | 12x12 Light Brown w/Dark Brown Floor Tile Mastic  | 2,000             | SF             | 3rd Floor Hallway   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 20        | Maroon & Tan Terrazzo                             | 3,000             | SF             | Stairwell & Entrance  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 21        | 12x12 Grey Floor Tile                             | 100               | SF             | Engineer's Office   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 22        | 12x12 Grey Floor Tile Mastic                      | 100               | SF             | Engineer's Office   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 23        | 12"X12" Light Blue Vinyl Floor Tile               | 200               | SF             | Throughout Gym, Kitchen, and Lunchroom  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 24        | 12"X12" Light Blue Vinyl Floor Tile Mastic        | 200               | SF             | Throughout Gym, Kitchen, and Lunchroom  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 8A        | 12x12 White w/Blue Floor Tile                     | 6,000             | SF             | Cafeteria/Kitchen   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 8B        | 12x12 White w/Blue Floor Tile Mastic              | 6,000             | SF             | Cafeteria/Kitchen   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 9         | 12x12 Dark Blue w/White Floor Tile                | 20,000            | SF             | 1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen &           | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |

# Chicago Public Schools

**School** Hinton School  
**Address** 644 W. 71st St.

**Unit** 26371  
 Chicago, IL, 60621

**Building ID** 7250  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|-----------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-----------------|--------------|-----------------|----------|
|           |                      |                   |                | Lunchroom         |               |                   |         |                 |              |                 |          |
| C         | Boiler Gasket ABATED |                   |                | Boiler Room       | Abated        | MISC              |         |                 |              |                 |          |

|                      |              |
|----------------------|--------------|
| Review Date          | 10/20/2019   |
| Manager Planner Name | Amy Williams |

| HA Number | Management Comments |
|-----------|---------------------|
| 01B       |                     |

# Chicago Public Schools

**School** Hinton School  
**Address** 644 W. 71st St.

**Unit** 26371  
 Chicago, IL, 60621

**Building ID** 7250  
**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

|                                    |           |
|------------------------------------|-----------|
| 100-00746                          | 5/15/2020 |
| Manager IDPH License No/Expiration |           |

| HA Number | Management Comments |
|-----------|---------------------|
| 02        |                     |
| 03        |                     |
| 07        |                     |
| 10        |                     |
| 11        |                     |
| 12        |                     |
| 13        |                     |
| 14        |                     |
| 15        |                     |
| 16        |                     |
| 17        |                     |
| 18        |                     |
| 19        |                     |
| 20        |                     |
| 21        |                     |
| 22        |                     |
| 23        |                     |
| 24        |                     |
| 8A        |                     |
| 8B        |                     |
| 9         |                     |
| C         |                     |

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**  
MATERIAL DESCRIPTION: **Hard Plaster-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Fan Room & Storage Room in Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **01B**

MATERIAL DESCRIPTION: **Hard Plaster-NOT OBSERVED**

MATERIAL LOCATION: **2nd Floor Fan Room & Storage Room in Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Fan Room & Storage Room in Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **2nd Floor Fan Room & Storage Room in Kitchen**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile - ABATED Summer 1995**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **1st Floor East Corridor & Kitchen**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile - ABATED Summer 1995**

MATERIAL LOCATION: **1st Floor East Corridor & Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Mastic- ABATED Summer 1995**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor East Corridor & Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile Mastic- ABATED Summer 1995**

MATERIAL LOCATION: **1st Floor East Corridor & Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUILDING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom**  
MATERIAL QUANTITY: **20000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/White Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Blue w/White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Blue w/White Floor Tile**  
MATERIAL LOCATION: **1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12x12 Blue w/White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym**  
MATERIAL QUANTITY: **30000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **12x12 Blue w/White Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Teachers' Lounge, Classrooms, and Gym**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Green Chalkboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Green Chalkboard**  
MATERIAL LOCATION: **Classrooms**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUILDING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Green Chalkboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms**  
MATERIAL QUANTITY: **6000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Green Chalkboard Adhesive**  
MATERIAL LOCATION: **Classrooms**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **50000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**  
MATERIAL LOCATION: **Throughout**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Floor Tile**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 White w/Tan Floor Tile Mastic**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Dark Brown Floor Tile**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **12x12 Light Brown w/Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **3rd Floor Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Maroon & Tan Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwell & Entrance**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Maroon & Tan Terrazzo**  
MATERIAL LOCATION: **Stairwell & Entrance**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUILDING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUILDING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"X12" Light Blue Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Gym, Kitchen, and Lunchroom**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12"X12" Light Blue Vinyl Floor Tile**  
MATERIAL LOCATION: **Throughout Gym, Kitchen, and Lunchroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"X12" Light Blue Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Gym, Kitchen, and Lunchroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12"X12" Light Blue Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Gym, Kitchen, and Lunchroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria/Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Floor Tile**  
MATERIAL LOCATION: **Cafeteria/Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria/Kitchen**  
MATERIAL QUANTITY: **6000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/25/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12x12 White w/Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria/Kitchen**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26371**    BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School**    INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.**    IDPH LICENSE NO: **100-09106**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom**  
MATERIAL QUANTITY: **20000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/White Floor Tile**  
MATERIAL LOCATION: **1st & 2nd Floor Hallways, Room 114, Office Copy Room, Office, Kitchen & Lunchroom**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Michael Hasier**  
SCHOOL NAME: **Hinton School** INSPECTION DATE: **9/25/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Boiler Gasket ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/25/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26371** BUIDLING ID: **7250**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Amy Williams**  
SCHOOL NAME: **Hinton School** REVIEW DATE: **10/20/2019**  
ADDRESS: **644 W. 71st St.** IDPH LICENSE NO: **100-09106**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Gasket ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/20/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## **Inspector and Management Planner Licenses**


---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MICHAEL HASIER  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 05/01/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

05/01/2019  
Course Dates:  
05/01/2020  
Expires:  
1905BIR02  
Certificate Number:



Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

| ENDORSEMENTS      | TC EXPIRES |
|-------------------|------------|
| SUPERVISOR/WORKER | 3/1/2020   |
| INSPECTOR         | 5/1/2020   |

| ID NUMBER   | ISSUED   | EXPIRES    |
|-------------|----------|------------|
| 100 - 09106 | 5/8/2019 | 05/15/2020 |

**MICHAEL S HASIER**  
444 OLD BARN RD., APT. B  
BARRINGTON, IL 60010

Environmental Health



PROJECT MANAGER 3/1/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Amy J. Williams**

*has on 04/03/19, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 03, 2019

**COURSE LENGTH: 4 HOURS**

Examination Date: April 03, 2019

Expiration Date: April 03, 2020

*William S. Williams*

Certificate Number: BIR/0808

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



2539 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

*Does hereby certify*

**William Williams**

4211 Westgate Drive, Springfield, IL 62711

*Has successfully completed and passed the course examination with at least  
70% for re-accreditation under AHERA (Title II)*

**Asbestos Management Planner Refresher**


**Class Date:** 02/15/2019  
**Examination Date:** 02/15/2019  
**STC Certificate Number:** STC-20190215-000527AMPR  
**Certification Expiration:** 02/15/2020

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

|             |           |            |
|-------------|-----------|------------|
| ID NUMBER   | ISSUED    | EXPIRES    |
| 100 - 00746 | 4/11/2019 | 05/15/2020 |

INSPECTOR

4/21/2019

MANAGEMENT PLANNER

4/21/2019

PROJECT MANAGER

4/2/2020


AIR SAMPLING PROFESSIONAL

**AMY J WILLIAMS**

1408 S CLAY

JACKSONVILLE, IL 62650

Environmental Health



**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |