

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2193
SCHOOL NAME: Evers School
ADDRESS OF SCHOOL: 9811 S Lowe
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/25/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 265
IDPH INSPECTOR LICENSE NUMBER: 100-11102
IDPH LICENSED INSPECTOR NAME(Please Print): Elmer Spraggins II
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Evers School

9811 S Lowe
Chicago, IL, 60628

Unit: 26591
Building ID: 7990

IDPH ID Number: 14-016-2990-2193

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

September 3, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26591 Region: 06 IDPH ID:14-016-2990-2193

School: Evers School Building ID: 7990

Address: 9811 S Lowe

Chicago, IL, 60628

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/03/2019

Inspector: Elmer Spraggins II

Inspector IDPH License: 100-11102

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 03, 2019

RE: Evers School, Unit 26591
9811 S Lowe
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Evers School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Evers School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Evers School
Address: 9811 S Lowe
IDPH ID: 14-016-2990-2193
Contact:

Unit: 26591
Chicago, IL, 60628
Building ID: 7990
Phone:

Region: 06

2. Description of Facility

Original Construction: 1969
Total Square Footage: 52968
Current Occupancy: 265

Additional Construction:
No of Floors: 2

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Elmer Spraggins II

Inspector IDPH license # 100-11102

Signature:
Date: 9/3/2019

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613

Signature:
Date: 10/03/2019

7. Review Date:10/03/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Evers School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7990:

B. The following new homogenous areas have been identified for Building 7990:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04F	1 x 1 Ceiling Tile and Adhesive (Six 4' X 8' Panels on the Wall)
18	Brown Baseboard
19	Brown Baseboard Mastic
20	Drywall
21	Drywall Compound
22	Black Baseboard
23	Black Baseboard Mastic
24	9x9 Green w/White Floor Tile
25	9x9 Green w/White Floor Tile Mastic
26	Gray, Green, Blue (Scattered Pattern) Carpet Adhesive
27	Blue Carpet Adhesive
28	Gray Carpet Adhesive
29	Red Carpet Adhesive
30	White w/Black Specks Terrazzo Floor
31	Mint w/Gray Specks Terrazo Floor Border
32	Beige Window Caulk
33	Blue-Patterned Ceramic Tile Grout
34	12x12 Gray w/White Speckles Floor Tile
35	12x12 Gray w/White Speckles Floor Tile Mastic
36	12x12 Light Gray w/Dark Gray Speckles Floor Tile
37	12x12 Light Gray w/Dark Gray Speckles Floor Tile Mastic
38	12x12 Green Floor Tile
39	12x12 Green Floor Tile Mastic
C	12x12 White Vinyl Floor Tile
D	12x12 White Vinyl Floor Tile Mastic

The following areas were deemed to be inaccessible:

26	Gray, Green, Blue (Scattered Pattern) Carpet Adhesive
27	Blue Carpet Adhesive
28	Gray Carpet Adhesive
29	Red Carpet Adhesive
B	Vibration Cloth
D	12x12 White Vinyl Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Elmer Spraggins II, IDPH License # 100-11102. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Evers School Building 7990 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Evers School Unit 26591 Building ID 7990

Address 9811 S Lowe Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	2' X 4' Acoustical Ceiling Tile	41,000	SF	Throughout	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	9" X 9" Salmon Floor Tile	3,400	SF	Rooms 118, 120, 200, 202, 208 and Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04B	9" X 9" White Floor Tile w/Brown Speckles	3,200	SF	1st Floor Lounge, Rooms 104, 106, 121, 203, 210, Gym Storage and Gym Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04C	9"x9" Beige Floor Tile	4,600	SF	Rooms 200, 216, 218, 220, 221, Book Room, Vault and Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04D	9 X 9 Gray w/White Speckle Floor Tile	3,900	SF	Rooms 112, 201, 204, 206 and 214, 2nd Floor Storage (LAN Room) and Office Vault	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04E	9" X 9" White Floor Tile	5,200	SF	Gym, Gym Storage Rooms and Stage Vestibules	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04F	1 x 1 Ceiling Tile and Adhesive (Six 4' X 8' Panels on the Wall)	250	SF	Gym Wall	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	Science Lab Tables	15	SF	Room 100	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	9"x9" Salmon Floor Tile Mastic	2,400	SF	Rooms 118, 120, 208 & Principal's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06B	9" X 9" White w/Brown Specks Floor Tile Mastic	3,600	SF	1st Floor Lounge, Gym Office, Rooms 106/104/121/203 and 210	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06C	9" X 9" Beige Floor Tile Mastic	4,600	SF	Rooms 200, 216, 218, 220, 221, 220, Book Room Vault, and Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06D	9"x9" Gray w/White Specks Floor Tile Mastic	3,900	SF	Rooms 112, 206, 201,204, 214, 2nd Floor Storage, (LAN Room)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06E	9"x9" White Floor Tile Mastic	4,200	SF	Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13D	9"x9" White w/Gray Streaks Floor Tile	0		Not Observed		MISC					No			MODERATE

Chicago Public Schools

School Evers School Unit 26591 Building ID 7990

Address 9811 S Lowe Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18	Brown Baseboard	150	LF	Book Room and 2nd Floor Storage Room (LAN Room)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Brown Baseboard Mastic	150	LF	Book Room and 2nd Floor Storage Room (LAN Room)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall	3,000	SF	Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
21	Drywall Compound	3,000	SF	Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
22	Black Baseboard	360	LF	Library (200), Room 100, Science Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Black Baseboard Mastic	360	LF	Library (200), Room 100, Science Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	9x9 Green w/White Floor Tile	80	SF	Room 100 Science Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
25	9x9 Green w/White Floor Tile Mastic	80	SF	Room 100 Science Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Gray, Green, Blue (Scattered Pattern) Carpet Adhesive	1,200	SF	Library & Library Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	Blue Carpet Adhesive	660	SF	Main Office, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Gray Carpet Adhesive	620	SF	Room 123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Red Carpet Adhesive	290	SF	Room 125 (Gym Office)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	White w/Black Specks Terrazzo Floor	2,400	SF	Main Entrance and Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Mint w/Gray Specks Terrazo Floor Border	1,400	SF	Main Entrance and Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Beige Window Caulk	2,400	LF	All Windows Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Blue-Patterned Ceramic Tile Grout	1,600	SF	1st and 2nd Floor Boys' and Girls' Toilets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
34	12x12 Gray w/White Speckles Floor Tile	600	SF	Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

Chicago Public Schools

School Evers School Unit 26591 Building ID 7990

Address 9811 S Lowe Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
35	12x12 Gray w/White Speckles Floor Tile Mastic	600	SF	Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12x12 Light Gray w/Dark Gray Speckles Floor Tile	600	SF	Room 123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37	12x12 Light Gray w/Dark Gray Speckles Floor Tile Mastic	600	SF	Room 123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12x12 Green Floor Tile	150	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39	12x12 Green Floor Tile Mastic	150	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	TSI Joints and Fittings	500	LF	2nd Floor Fan Room, Boys' and Girls' Washrooms	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	Vibration Cloth	15	SF	2nd Floor Fan Room	NO_ACBM	MISC	Y		0		No	ACBM with the potential for damage		MODERATE
C	12x12 White Vinyl Floor Tile	28,000	SF	1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
D	12x12 White Vinyl Floor Tile Mastic	28,000	SF	1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Evers School Unit 26591 Building ID 7990

Address 9811 S Lowe Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/3/2019
Inspector Name <u>Elmer Spraggins II</u>
<u>100-11102</u> <u>5/15/2020</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
04B	
04C	
04D	
04E	
04F	
05	
06	
06B	
06C	
06D	
06E	
13D	NOT OBSERVED
18	
19	
20	
21	
22	
23	
24	
25	
26	

Chicago Public Schools

School Evers School Unit 26591 Building ID 7990

Address 9811 S Lowe Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
A	
B	
C	Old 9X9 Tiles Replaced with New 12 X 12
D	

Table II

Management Planner's Review

Chicago Public Schools

School Evers School

Unit 26591

Building ID 7990

Address 9811 S Lowe

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	2' X 4' Acoustical Ceiling Tile	41,000	SF	Throughout	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9" X 9" Salmon Floor Tile	3,400	SF	Rooms 118, 120, 200, 202, 208 and Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04B	9" X 9" White Floor Tile w/Brown Speckles	3,200	SF	1st Floor Lounge, Rooms 104, 106, 121, 203, 210, Gym Storage and Gym Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04C	9"x9" Beige Floor Tile	4,600	SF	Rooms 200, 216, 218, 220, 221, Book Room, Vault and Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04D	9 X 9 Gray w/White Speckle Floor Tile	3,900	SF	Rooms 112, 201, 204, 206 and 214, 2nd Floor Storage (LAN Room) and Office Vault	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04E	9" X 9" White Floor Tile	5,200	SF	Gym, Gym Storage Rooms and Stage Vestibules	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04F	1 x 1 Ceiling Tile and Adhesive (Six 4' X 8' Panels on the Wall)	250	SF	Gym Wall	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Science Lab Tables	15	SF	Room 100	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Salmon Floor Tile Mastic	2,400	SF	Rooms 118, 120, 208 & Principal's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06B	9" X 9" White w/Brown Specks Floor Tile Mastic	3,600	SF	1st Floor Lounge, Gym Office, Rooms 106/104/121/203 and 210	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06C	9" X 9" Beige Floor Tile Mastic	4,600	SF	Rooms 200, 216, 218, 220, 221, 220, Book Room Vault, and Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06D	9"x9" Gray w/White Specks Floor Tile Mastic	3,900	SF	Rooms 112, 206, 201,204, 214, 2nd Floor Storage, (LAN Room)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06E	9"x9" White Floor Tile Mastic	4,200	SF	Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13D	9"x9" White w/Gray Streaks Floor Tile	0		Not Observed		MISC					Follow O&M Plan
18	Brown Baseboard	150	LF	Book Room and 2nd Floor Storage Room (LAN Room)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Brown Baseboard Mastic	150	LF	Book Room and 2nd Floor Storage Room (LAN Room)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Drywall	3,000	SF	Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Drywall Compound	3,000	SF	Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Evers School

Unit 26591

Building ID 7990

Address 9811 S Lowe

Chicago, IL, 60628

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room (LAN Room)							
22	Black Baseboard	360	LF	Library (200), Room 100, Science Lab	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
23	Black Baseboard Mastic	360	LF	Library (200), Room 100, Science Lab	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	9x9 Green w/White Floor Tile	80	SF	Room 100 Science Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	9x9 Green w/White Floor Tile Mastic	80	SF	Room 100 Science Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Gray, Green, Blue (Scattered Pattern) Carpet Adhesive	1,200	SF	Library & Library Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Blue Carpet Adhesive	660	SF	Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Gray Carpet Adhesive	620	SF	Room 123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Red Carpet Adhesive	290	SF	Room 125 (Gym Office)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	White w/Black Specks Terrazzo Floor	2,400	SF	Main Entrance and Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Mint w/Gray Specks Terrazo Floor Border	1,400	SF	Main Entrance and Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Beige Window Caulk	2,400	LF	All Windows Throughout	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
33	Blue-Patterned Ceramic Tile Grout	1,600	SF	1st and 2nd Floor Boys' and Girls' Toilets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12x12 Gray w/White Speckles Floor Tile	600	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12x12 Gray w/White Speckles Floor Tile Mastic	600	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12x12 Light Gray w/Dark Gray Speckles Floor Tile	600	SF	Room 123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12x12 Light Gray w/Dark Gray Speckles Floor Tile Mastic	600	SF	Room 123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12x12 Green Floor Tile	150	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12x12 Green Floor Tile Mastic	150	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	TSI Joints and Fittings	500	LF	2nd Floor Fan Room, Boys' and Girls' Washrooms	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Vibration Cloth	15	SF	2nd Floor Fan Room	No ACBM	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	12x12 White Vinyl Floor Tile	28,000	SF	1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	12x12 White Vinyl Floor Tile Mastic	28,000	SF	1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Evers School
Address 9811 S Lowe

Unit 26591
Chicago, IL, 60628

Building ID 7990
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	10/03/2019
Manager Planner Name	Daniel Juneau
100-03613	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
04B	
04C	
04D	
04E	

Chicago Public Schools

School Evers School
Address 9811 S Lowe

Unit 26591
Chicago, IL, 60628

Building ID 7990
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
04F	
05	
06	
06B	
06C	
06D	
06E	
13D	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	

Chicago Public Schools

School Evers School
Address 9811 S Lowe

Unit 26591
Chicago, IL, 60628

Building ID 7990
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
36	
37	
38	
39	
A	
B	
C	
D	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **41000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: **41000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9" X 9" Salmon Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 118, 120, 200, 202, 208 and Principal's Office**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **9" X 9" Salmon Floor Tile**
MATERIAL LOCATION: **Rooms 118, 120, 200, 202, 208 and Principal's Office**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **9" X 9" White Floor Tile w/Brown Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st Floor Lounge, Rooms 104, 106, 121, 203, 210, Gym Storage and Gym Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **9" X 9" White Floor Tile w/Brown Speckles**
MATERIAL LOCATION: **1st Floor Lounge, Rooms 104, 106, 121, 203, 210, Gym Storage and Gym Office**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 200, 216, 218, 220, 221, Book Room, Vault and Storage Room**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 200, 216, 218, 220, 221, Book Room, Vault and Storage Room**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **9 X 9 Gray w/White Speckle Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 112, 201, 204, 206 and 214, 2nd Floor Storage (LAN Room) and Office Vault**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **9 X 9 Gray w/White Speckle Floor Tile**
MATERIAL LOCATION: **Rooms 112, 201, 204, 206 and 214, 2nd Floor Storage (LAN Room) and Office Vault**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **9" X 9" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Gym, Gym Storage Rooms and Stage Vestibules**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **9" X 9" White Floor Tile**
MATERIAL LOCATION: **Gym, Gym Storage Rooms and Stage Vestibules**
MATERIAL QUANTITY: **5200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile and Adhesive (Six 4' X 8' Panels on the Wall)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Wall**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **04F**
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile and Adhesive (Six 4' X 8' Panels on the Wall)**
MATERIAL LOCATION: **Gym Wall**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Science Lab Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Science Lab Tables**
MATERIAL LOCATION: **Room 100**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Salmon Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 118, 120, 208 & Principal's Office**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **9"x9" Salmon Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 118, 120, 208 & Principal's Office**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **9" X 9" White w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Lounge, Gym Office, Rooms 106/104/121/203 and 210**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06B**
MATERIAL DESCRIPTION: **9" X 9" White w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Lounge, Gym Office, Rooms 106/104/121/203 and 210**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **9" X 9" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 200, 216, 218, 220, 221, 220, Book Room Vault, and Storage Room**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06C**
MATERIAL DESCRIPTION: **9" X 9" Beige Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 200, 216, 218, 220, 221, 220, Book Room Vault, and Storage Room**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **9"x9" Gray w/White Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 112, 206, 201,204, 214, 2nd Floor Storage, (LAN Room)**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06D**
MATERIAL DESCRIPTION: **9"x9" Gray w/White Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 112, 206, 201,204, 214, 2nd Floor Storage, (LAN Room)**
MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUILDING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06E**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **06E**
MATERIAL DESCRIPTION: **9"x9" White Floor Tile Mastic**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13D**
MATERIAL DESCRIPTION: **9"x9" White w/Gray Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Not Observed**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **NOT OBSERVED**

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **13D**
MATERIAL DESCRIPTION: **9"x9" White w/Gray Streaks Floor Tile**
MATERIAL LOCATION: **Not Observed**
MATERIAL QUANTITY: **0** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Book Room and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **Book Room and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Book Room and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Book Room and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Book Room, Janitor's Closet, Entry, Gym Baths, and 2nd Floor Storage Room (LAN Room)**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library (200), Room 100, Science Lab**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Library (200), Room 100, Science Lab**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library (200), Room 100, Science Lab**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Library (200), Room 100, Science Lab**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9x9 Green w/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 100 Science Lab**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9x9 Green w/White Floor Tile**

MATERIAL LOCATION: **Room 100 Science Lab**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9x9 Green w/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 100 Science Lab**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **9x9 Green w/White Floor Tile Mastic**
MATERIAL LOCATION: **Room 100 Science Lab**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Gray, Green, Blue (Scattered Pattern) Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library & Library Closet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Gray, Green, Blue (Scattered Pattern) Carpet Adhesive**
MATERIAL LOCATION: **Library & Library Closet**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUILDING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Principal's Office**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
MATERIAL LOCATION: **Main Office, Principal's Office**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUILDING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Gray Carpet Adhesive**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Red Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 125 (Gym Office)**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Red Carpet Adhesive**
MATERIAL LOCATION: **Room 125 (Gym Office)**
MATERIAL QUANTITY: **290** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **White w/Black Specks Terrazzo Floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Entrance and Stairways**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **White w/Black Specks Terrazzo Floor**
MATERIAL LOCATION: **Main Entrance and Stairways**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Mint w/Gray Specks Terrazo Floor Border**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Entrance and Stairways**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Mint w/Gray Specks Terrazo Floor Border**
MATERIAL LOCATION: **Main Entrance and Stairways**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Beige Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All Windows Throughout**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Beige Window Caulk**
MATERIAL LOCATION: **All Windows Throughout**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Blue-Patterned Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1st and 2nd Floor Boys' and Girls' Toilets**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Blue-Patterned Ceramic Tile Grout**
MATERIAL LOCATION: **1st and 2nd Floor Boys' and Girls' Toilets**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 Gray w/White Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12x12 Gray w/White Speckles Floor Tile**
MATERIAL LOCATION: **Room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Gray w/White Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **12x12 Gray w/White Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Room 116**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Dark Gray Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Dark Gray Speckles Floor Tile**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Dark Gray Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Dark Gray Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Room 123**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUILDING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUILDING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **TSI Joints and Fittings**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Fan Room, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **TSI Joints and Fittings**
MATERIAL LOCATION: **2nd Floor Fan Room, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Vibration Cloth**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **2nd Floor Fan Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **09/03/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Vibration Cloth**
MATERIAL LOCATION: **2nd Floor Fan Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12x12 White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge**

MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Old 9X9 Tiles Replaced with New 12 X 12**

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **12x12 White Vinyl Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**
SCHOOL NAME: **Evers School** INSPECTION DATE: **9/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **12x12 White Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge**

MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 09/03/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26591** BUIDLING ID: **7990**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**
SCHOOL NAME: **Evers School** REVIEW DATE: **10/3/2019**
ADDRESS: **9811 S Lowe** IDPH LICENSE NO: **100-11102**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **12x12 White Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Library, Rooms 202, 212, 222, Lunchroom, Rooms 100, 108, 110, 114, Main Office and Lounge**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **10/03/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ELMER SPRAGGINS II
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI06

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
275 Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081

Fax: 312-421-2921

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	1/30/2020
100 - 11102	4/16/2019	05/15/2020		PROJECT MANAGER	3/29/2020
ELMER SPRAGGINS II				AIR SAMPLING PROFESSIONAL	
12823 S GREEN				Alteration of this license shall result in legal action	
CHICAGO, IL 60643				This license issued under authority of the State of Illinois	
Environmental Health				Department of Public Health	
				This license is valid only when accompanied by a valid training course certificate.	

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: BIR1811203167

Kathy DeSalvo, Director

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: MPR1811203186

Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
4/17/2019

EXPIRES
05/15/2020

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/20/2019

MANAGEMENT PLANNER

11/20/2019

PROJECT MANAGER

11/6/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed