

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2497
SCHOOL NAME: Wacker School
ADDRESS OF SCHOOL: 9746 S Morgan
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/8/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 245
IDPH INSPECTOR LICENSE NUMBER: 100-19717
IDPH LICENSED INSPECTOR NAME(Please Print): Shaquille Crews
IDPH MP LICENSE NUMBER: 100-00440
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Wacker School

9746 S Morgan
Chicago, IL, 60643

Unit: 26621
Building ID: 8030

IDPH ID Number: 14-016-2990-2497

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 6, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26621 Region: 06 IDPH ID:14-016-2990-2497

School: Wacker School Building ID: 8030

Address: 9746 S Morgan
Chicago, IL, 60643

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/04/2019

Inspector: Shaquille Crews Inspector IDPH License: 100-19717
Management Planner: Shawn Brown Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Shawn Brown
100-00440

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 06, 0219

RE: Wacker School, Unit 26621
9746 S Morgan
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Wacker School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Wacker School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Wacker School
Address: 9746 S Morgan
IDPH ID: 14-016-2990-2497
Contact:

Unit: 26621
Chicago, IL, 60643
Building ID: 8030
Phone:

Region: 06

2. Description of Facility

Original Construction: 1954
Total Square Footage: 27552
Current Occupancy: 245

Additional Construction:
No of Floors: 2

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Shaquille Crews

Inspector IDPH license # 100-19717

Signature:
Date: 8/6/2019

6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440

Signature:
Date: 09/04/2019

7. Review Date:09/04/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Wacker School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 8030:

02	Acoustic Plaster
03	Fireproofing
24	1 x 1 White Fissured Ceiling Tile
K	Fiberglass Joint

B. The following new homogenous areas have been identified for Building 8030:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05A	Hard Plaster
06 - DUPLICATE	Acoustical Plaster - DUPLICATE HA - SAME AS HA #02
07B	12x12 Beige & White Floor Tile
08A	9x9 Brown Floor Tile
11A	12x12 Brown Floor Tile (part of checkerboard)
11AA	12x12 Beige Floor Tile (part of checkerboard)
11B	12x12 Gray Floor Tile (part of checkerboard)
11BB	12x12 White Floor Tile (part of checkerboard)
11C	12x12 White Floor Tile
11D	12x12 Dark Brown Border Floor Tile
11E	9x9 Tan w/Streaks Floor Tile
11F	12x12 Brown w/White Specks Floor Tile
12D	12x12 Dark Brown Floor Tile Mastic
12E	9x9 Tan w/Streaks Floor Tile Mastic
14	12x12 Off-White Floor Tile
15	12x12 Off-White Floor Tile Mastic
16	12x12 Red Floor Tile
16M	12x12 Red Floor Tile Mastic
17	Ceramic Tile Grout
18	Ceramic Tile Adhesive
19	Beige w/Red Specks Terrazzo
20	Brown Mosaic Ceramic Tile Grout
21	Brown Mosaic Ceramic Tile Adhesive
22	Tan Mosaic Ceramic Tile Grout
23	Tan Mosaic Ceramic Tile Adhesive
24	1 x 1 White Fissured Ceiling Tile
25	1 x 1 White Fissured Ceiling Tile Glue
26	12x12 Brown Floor Tile
26M	12x12 Brown Floor Tile Mastic
28	12x12 Off-White w/Tan Specks Floor Tile
28A	12x12 Off-White w/Tan Specks Floor Tile Mastic
29	Floor Tile (under HA 16 and HA 16M)
29A	Floor Tile Mastic (under HA 16 and HA 16M)
I	Fiberglass Insulation
L	Fiberglass Pipe Insulation
M	Duct Wrap over Fiberglass

The following areas were deemed to be inaccessible:

09A	12x12 Green Marble Floor Tile Mastic
09B	12x12 Beige and White Floor Tile Mastic
10A	Mastic Under 9x9 Brown Floor Tile
12A	12x12 Brown/Beige Floor Tile Mastic
12B	12x12 Gray/White Floor Tile Mastic
12C	12x12 White Floor Tile Mastic
12E	9x9 Tan w/Streaks Floor Tile Mastic
15	12x12 Off-White Floor Tile Mastic
16M	12x12 Red Floor Tile Mastic
18	Ceramic Tile Adhesive
21	Brown Mosaic Ceramic Tile Adhesive
23	Tan Mosaic Ceramic Tile Adhesive
25	1 x 1 White Fissured Ceiling Tile Glue
26M	12x12 Brown Floor Tile Mastic
28A	12x12 Off-White w/Tan Specks Floor Tile Mastic
29	Floor Tile (under HA 16 and HA 16M)
29A	Floor Tile Mastic (under HA 16 and HA 16M)
D	Fiberglass Joint
F	Joint on Fiberglass
G	Cardboard Pipe Insulation
H	Aircell Pipe Insulation
I	Fiberglass Insulation
K	Fiberglass Joint
L	Fiberglass Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shaquille Crews, IDPH License # 100-19717. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Wacker School Building 8030 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
09A	12x12 Green Marble Floor Tile Mastic	5,050	SF	1953 Main Building-Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09B	12x12 Beige and White Floor Tile Mastic	2,000	SF	1953 Main Building-Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09D	Mastic Under 12x12 Red Floor Tile - ABATED			Main Building-North Corridor, Teachers' Restroom, Teachers Lounge/Restroom, 107, 110, 112-114, 210	ABATED	MISC								
10A	Mastic Under 9x9 Brown Floor Tile			1965 Annex-Classrooms, Closets, Teachers' Lounge		MISC	N				No	ACBM with the potential for damage		LOW
10B	Mastic Under 9x9 Red Floor Tile- ABATED			1965 Annex-Teachers' Lounge ABATED	ABATED	MISC								
11A	12x12 Brown Floor Tile (part of checkerboard)	800	SF	1965 Annex- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11AA	12x12 Beige Floor Tile (part of checkerboard)	800	SF	1965 Annex- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11B	12x12 Gray Floor Tile (part of checkerboard)	700	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11BB	12x12 White Floor Tile (part of checkerboard)	700	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11C	12x12 White Floor Tile	2,100	SF	1965 Annex- Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11D	12x12 Dark Brown Border Floor Tile	200	SF	1965 Annex-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Gymnasium Border								potential for damage		
11E	9x9 Tan w/Streaks Floor Tile	1,500	SF	1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11F	12x12 Brown w/White Specks Floor Tile	40	SF	Assistant Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12A	12x12 Brown/Beige Floor Tile Mastic	1,600	SF	1965 Building- 1st Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12B	12x12 Gray/White Floor Tile Mastic	1,400	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12C	12x12 White Floor Tile Mastic	2,100	SF	1965 Annex- Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12D	12x12 Dark Brown Floor Tile Mastic	200	SF	1965 Annex- Gym Border	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12E	9x9 Tan w/Streaks Floor Tile Mastic	1,500	SF	1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Carpet Mastic ABATED			1st Floor Teachers' Restroom, Main Office	ABATED	MISC								
14	12x12 Off-White Floor Tile	800	SF	1965 Building-Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12x12 Off-White Floor Tile Mastic	800	SF	1965 Building-Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12x12 Red Floor Tile	4,750	SF	1965 Building-Kitchen 108, 110, 107, 210, 212, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and 1st Floor Teacher's Lounge/Office 121										
16M	12x12 Red Floor Tile Mastic	4,750	SF	1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Ceramic Tile Grout	360	SF	1965 Building- 2nd Floor Girls' and Boys' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Ceramic Tile Adhesive	360	SF	1965 Building- 2nd Floor Girls' and Boys' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Beige w/Red Specks Terrazzo	500	SF	1965 Building- Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Brown Mosaic Ceramic Tile Grout	505	SF	1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Brown Mosaic Ceramic Tile Adhesive	505	SF	1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Tan Mosaic Ceramic Tile Grout	550	SF	1953 Building- Girls' and Boys' Washrooms and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Tan Mosaic Ceramic Tile Adhesive	550	SF	1953 Building- Girls' and Boys' Washrooms and Vestibules	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	1 x 1 White Fissured Ceiling Tile	7,900	SF	1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
25	1 x 1 White Fissured Ceiling Tile Glue	7,900	SF	1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Brown Floor Tile	1,500	SF	1953 Building- Corridors and Main	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Office										
26M	12x12 Brown Floor Tile Mastic	1,500	SF	1953 Building-Corridors and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Gold Vinyl Floor Tile ABATED			1st Floor Teachers' Restroom	ABATED	MISC								
27A	12x12 Gold Vinyl Floor Tile Mastic ABATED			1st Floor Teachers' Restroom	ABATED	MISC								
28	12x12 Off-White w/Tan Specks Floor Tile	120	SF	1953 Building-Room 105 Toilet, Room 106 (area by toilet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28A	12x12 Off-White w/Tan Specks Floor Tile Mastic	120	SF	1953 Building-Room 105 Toilet, Room 106 (area by Toilet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Floor Tile (under HA 16 and HA 16M)	2,000	SF	1965 Addition-Rooms 208, 212, & Kitchen (108)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29A	Floor Tile Mastic (under HA 16 and HA 16M)	2,000	SF	1965 Addition-Rooms 208, 212, & Kitchen (108)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Insulation ABATED			Boiler Room	ABATED									
B	Tank Insulation ABATED			Boiler Room	ABATED									
D	Fiberglass Joint	80	LF	1965 Addition- Pipe Chase & Above Ceilings	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Joint on Fiberglass	250	LF	1953 Addition- Pipe Chase & Above Ceiling	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Cardboard Pipe Insulation	700	SF	1953 & 1965 Buildings-Crawlspace	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Aircell Pipe Insulation	900	LF	1953 Building- Pipe Chases and Crawlspace	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Fiberglass Insulation	1,500	LF	1953 & 1965 Buildings-Throughout	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Fiberglass Joint	70	LF	1965 Annex-Crawlspace	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
L	Fiberglass Pipe Insulation	750	LF	1963 Building-Unexcavated Area	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Duct Wrap over Fiberglass	50	SF	1965 Addition- Fan	ASSUMED	TSI	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room								potential for damage		

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/6/2019
Inspector Name Shaquille Crews
100-19717 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
05	
05A	
06 - DUPLICATE	
07A	
07B	
07D - DUPLICATE	DUPLICATE SAME AS HA 16 & 16M
08A	
08B	Not Observed 2019
09A	Under HA 26 & HA 26M
09B	
09D	
10A	
10B	
11A	
11AA	
11B	
11BB	
11C	
11D	
11E	

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
11F	
12A	
12B	
12C	
12D	
12E	
13	
14	
15	
16	
16M	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
26M	
27	Not Observed 2019. ABATED
27A	Not Observed 2019. ABATED
28	
28A	
29	
29A	
A	ABATED

Chicago Public Schools

School Wacker School Unit 26621 Building ID 8030

Address 9746 S Morgan Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
B	ABATED
D	
F	
G	
H	
I	
K	
L	
M	

Table II

Management Planner's Review

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	Acoustic Plaster	5,600	SF	1965 Addition- Kitchen 108, Rooms 107, 110, 112, Office 121 207, 208, 210, and 212	Chrysotile	SURFACE	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
03	Fireproofing	2,248	SF	1965 Building- 2nd Floor: I Beams above Ceiling in Annex, 2nd floor	Chrysotile	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	Hard Plaster	450	SF	1965 Annex- Restrooms	Chrysotile	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	Hard Plaster	550	SF	Boiler Room & Rizzo Room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06 - DUPLICATE	Acoustical Plaster - DUPLICATE HA - SAME AS HA #02			Kitchen 108, Rooms 107, 110, 112, Office 121, 207, 208, 210, and 212	Assumed	SURFACE	No	0		6 ACBM with the potential for damage	Follow O&M Plan
07A	12x12 Green Marble Floor Tile	5,050	SF	1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07B	12x12 Beige & White Floor Tile	2,000	SF	1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D - DUPLICATE	12x12 Red Floor Tile			1953 Main Building- North Corridor, Teachers' Restroom, Teachers' Lounge/Restroom, 107, 110, 112-114, 210		MISC					
08A	9x9 Brown Floor Tile	10,000	SF	1965 Annex- Classrooms, including 1st and 2nd Floor Corridor Closets, 112 and Gym Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	9x9 Red Floor Tile Patch ABATED			1965 Annex- Teachers' Lounge	Abated	MISC					
09A	12x12 Green Marble Floor Tile Mastic	5,050	SF	1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09B	12x12 Beige and White Floor Tile Mastic	2,000	SF	1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09D	Mastic Under 12x12 Red Floor Tile - ABATED			Main Building- North Corridor, Teachers' Restroom, Teachers' Lounge/Restroom, 107, 110, 112-114,	Abated	MISC					

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				210							
10A	Mastic Under 9x9 Brown Floor Tile			1965 Annex- Classrooms, Closets, Teachers' Lounge		MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
10B	Mastic Under 9x9 Red Floor Tile- ABATED			1965 Annex- Teachers' Lounge ABATED	Abated	MISC					
11A	12x12 Brown Floor Tile (part of checkerboard)	800	SF	1965 Annex- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11AA	12x12 Beige Floor Tile (part of checkerboard)	800	SF	1965 Annex- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11B	12x12 Gray Floor Tile (part of checkerboard)	700	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11BB	12x12 White Floor Tile (part of checkerboard)	700	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11C	12x12 White Floor Tile	2,100	SF	1965 Annex- Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11D	12x12 Dark Brown Border Floor Tile	200	SF	1965 Annex- Gymnasium Border	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11E	9x9 Tan w/Streaks Floor Tile	1,500	SF	1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11F	12x12 Brown w/White Specks Floor Tile	40	SF	Assistant Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	12x12 Brown/Beige Floor Tile Mastic	1,600	SF	1965 Building- 1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12B	12x12 Gray/White Floor Tile Mastic	1,400	SF	1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12C	12x12 White Floor Tile Mastic	2,100	SF	1965 Annex- Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12D	12x12 Dark Brown Floor Tile Mastic	200	SF	1965 Annex- Gym Border	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12E	9x9 Tan w/Streaks Floor Tile Mastic	1,500	SF	1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Carpet Mastic ABATED			1st Floor Teachers' Restroom, Main Office	Abated	MISC					
14	12x12 Off-White Floor Tile	800	SF	1965 Building- Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15	12x12 Off-White Floor Tile Mastic	800	SF	1965 Building- Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Red Floor Tile	4,750	SF	1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16M	12x12 Red Floor Tile Mastic	4,750	SF	1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Ceramic Tile Grout	360	SF	1965 Building- 2nd Floor Girls' and Boys' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Ceramic Tile Adhesive	360	SF	1965 Building- 2nd Floor Girls' and Boys' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Beige w/Red Specks Terrazzo	500	SF	1965 Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Brown Mosaic Ceramic Tile Grout	505	SF	1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Brown Mosaic Ceramic Tile Adhesive	505	SF	1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Tan Mosaic Ceramic Tile Grout	550	SF	1953 Building- Girls' and Boys' Washrooms and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Tan Mosaic Ceramic Tile Adhesive	550	SF	1953 Building- Girls' and Boys' Washrooms and Vestibules	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	1 x 1 White Fissured Ceiling Tile	7,900	SF	1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	1 x 1 White Fissured Ceiling Tile Glue	7,900	SF	1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Brown Floor Tile	1,500	SF	1953 Building- Corridors and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26M	12x12 Brown Floor Tile Mastic	1,500	SF	1953 Building- Corridors and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Gold Vinyl Floor Tile ABATED			1st Floor Teachers' Restroom	Abated	MISC					
27A	12x12 Gold Vinyl Floor Tile Mastic ABATED			1st Floor Teachers' Restroom	Abated	MISC					
28	12x12 Off-White w/Tan Specks Floor Tile	120	SF	1953 Building- Room 105 Toilet, Room 106 (area by toilet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	12x12 Off-White w/Tan Specks Floor Tile Mastic	120	SF	1953 Building- Room 105 Toilet, Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
 Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				106 (area by Toilet)							
29	Floor Tile (under HA 16 and HA 16M)	2,000	SF	1965 Addition- Rooms 208, 212, & Kitchen (108)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29A	Floor Tile Mastic (under HA 16 and HA 16M)	2,000	SF	1965 Addition- Rooms 208, 212, & Kitchen (108)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Insulation ABATED			Boiler Room	Abated						
B	Tank Insulation ABATED			Boiler Room	Abated						
D	Fiberglass Joint	80	LF	1965 Addition- Pipe Chase & Above Ceilings	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Joint on Fiberglass	250	LF	1953 Addition- Pipe Chase & Above Ceiling	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
G	Cardboard Pipe Insulation	700	SF	1953 & 1965 Buildings- Crawlspace	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Aircell Pipe Insulation	900	LF	1953 Building- Pipe Chases and Crawlspace	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Fiberglass Insulation	1,500	LF	1953 & 1965 Buildings- Throughout	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Fiberglass Joint	70	LF	1965 Annex- Crawlspace	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Fiberglass Pipe Insulation	750	LF	1963 Building- Unexcavated Area	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M	Duct Wrap over Fiberglass	50	SF	1965 Addition- Fan Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
 Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	09/04/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
05	
05A	
06 - DUPLICATE	
07A	
07B	
07D - DUPLICATE	
08A	
08B	
09A	
09B	
09D	
10A	
10B	

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
 Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
11A	
11AA	
11B	
11BB	
11C	
11D	
11E	
11F	
12A	
12B	
12C	
12D	
12E	
13	
14	
15	
16	
16M	
17	
18	
19	
20	
21	
22	
23	
24	

Chicago Public Schools

School Wacker School
Address 9746 S Morgan

Unit 26621
Chicago, IL, 60643

Building ID 8030
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
26M	
27	
27A	
28	
28A	
29	
29A	
A	
B	
D	
F	
G	
H	
I	
K	
L	
M	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Acoustic Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1965 Addition- Kitchen 108, Rooms 107, 110, 112, Office 121 207, 208, 210, and 212**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Acoustic Plaster**
MATERIAL LOCATION: **1965 Addition- Kitchen 108, Rooms 107, 110, 112, Office 121 207, 208, 210, and 212**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 2nd Floor: I Beams above Ceiling in Annex, 2nd floor**
MATERIAL QUANTITY: **2248** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **Fireproofing**
MATERIAL LOCATION: **1965 Building- 2nd Floor: I Beams above Ceiling in Annex, 2nd floor**
MATERIAL QUANTITY: **2248** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Restrooms**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Hard Plaster**
MATERIAL LOCATION: **1965 Annex- Restrooms**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room & Rizzo Room**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **Hard Plaster**
MATERIAL LOCATION: **Boiler Room & Rizzo Room**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06 - DUPLICATE**
MATERIAL DESCRIPTION: **Acoustical Plaster - DUPLICATE HA - SAME AS HA #02**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen 108, Rooms 107, 110, 112, Office 121, 207, 208, 210, and 212**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **06 - DUPLICATE**
MATERIAL DESCRIPTION: **Acoustical Plaster - DUPLICATE HA - SAME AS HA #02**
MATERIAL LOCATION: **Kitchen 108, Rooms 107, 110, 112, Office 121, 207, 208, 210, and 212**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **12x12 Green Marble Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)**

MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **12x12 Green Marble Floor Tile**
MATERIAL LOCATION: **1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)**
MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **12x12 Beige & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **12x12 Beige & White Floor Tile**
MATERIAL LOCATION: **1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07D - DUPLICATE**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Main Building- North Corridor, Teachers' Restroom, Teachers' Lounge/Restroom, 107, 110, 112-114, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **DUPLICATE SAME AS HA 16 & 16M**

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **07D - DUPLICATE**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**
MATERIAL LOCATION: **1953 Main Building- North Corridor, Teachers' Restroom, Teachers' Lounge/Restroom, 107, 110, 112-114, 210**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Classrooms, including 1st and 2nd Floor Corridor Closets, 112 and Gym Storage**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
MATERIAL LOCATION: **1965 Annex- Classrooms, including 1st and 2nd Floor Corridor Closets, 112 and Gym Storage**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **9x9 Red Floor Tile Patch ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1965 Annex- Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **9x9 Red Floor Tile Patch ABATED**
MATERIAL LOCATION: **1965 Annex- Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12x12 Green Marble Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)**

MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Under HA 26 & HA 26M**

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **12x12 Green Marble Floor Tile Mastic**
MATERIAL LOCATION: **1953 Main Building- Room 105 & Closet, 106 & Closet, 103 Closet & Toilet, 104 Closet & Toilet, and Corridors (under HA 26 & HA 26M)**
MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **12x12 Beige and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **12x12 Beige and White Floor Tile Mastic**
MATERIAL LOCATION: **1953 Main Building- Rooms 101, 102, Teachers' Restroom, Boiler Room Toilet, Boiler Room Stairs Landing**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09D**
MATERIAL DESCRIPTION: **Mastic Under 12x12 Red Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- North Corridor, Teachers' Restroom, Teachers Lounge/Restroom, 107, 110, 112-114, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **09D**
MATERIAL DESCRIPTION: **Mastic Under 12x12 Red Floor Tile - ABATED**
MATERIAL LOCATION: **Main Building- North Corridor, Teachers' Restroom, Teachers Lounge/Restroom, 107, 110, 112-114, 210**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **Mastic Under 9x9 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1965 Annex- Classrooms, Closets, Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **Mastic Under 9x9 Brown Floor Tile**
MATERIAL LOCATION: **1965 Annex- Classrooms, Closets, Teachers' Lounge**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**
MATERIAL DESCRIPTION: **Mastic Under 9x9 Red Floor Tile- ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1965 Annex- Teachers' Lounge ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **10B**
MATERIAL DESCRIPTION: **Mastic Under 9x9 Red Floor Tile- ABATED**
MATERIAL LOCATION: **1965 Annex- Teachers' Lounge ABATED**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile (part of checkerboard)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile (part of checkerboard)**
MATERIAL LOCATION: **1965 Annex- 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11AA**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile (part of checkerboard)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11AA**
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile (part of checkerboard)**
MATERIAL LOCATION: **1965 Annex- 1st Floor Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile (part of checkerboard)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile (part of checkerboard)**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11BB**
MATERIAL DESCRIPTION: **12x12 White Floor Tile (part of checkerboard)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11BB**
MATERIAL DESCRIPTION: **12x12 White Floor Tile (part of checkerboard)**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Gym**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile**
MATERIAL LOCATION: **1965 Annex- Gym**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Border Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Gymnasium Border**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Border Floor Tile**
MATERIAL LOCATION: **1965 Annex- Gymnasium Border**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **9x9 Tan w/Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11E**
MATERIAL DESCRIPTION: **9x9 Tan w/Streaks Floor Tile**
MATERIAL LOCATION: **1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11F**
MATERIAL DESCRIPTION: **12x12 Brown w/White Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Assistant Principal's Office Toilet**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **11F**
MATERIAL DESCRIPTION: **12x12 Brown w/White Specks Floor Tile**
MATERIAL LOCATION: **Assistant Principal's Office Toilet**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12x12 Brown/Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12x12 Brown/Beige Floor Tile Mastic**
MATERIAL LOCATION: **1965 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **12x12 Gray/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **12x12 Gray/White Floor Tile Mastic**
MATERIAL LOCATION: **1965 Annex- 2nd Floor Corridor and Janitor's Closet, 1st Floor Teacher's Lounge/Office 121 Toilet**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Gym**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **12C**
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**
MATERIAL LOCATION: **1965 Annex- Gym**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Gym Border**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **12D**
MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **1965 Annex- Gym Border**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12E**
MATERIAL DESCRIPTION: **9x9 Tan w/Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **12E**
MATERIAL DESCRIPTION: **9x9 Tan w/Streaks Floor Tile Mastic**
MATERIAL LOCATION: **1965 Building- 1st Floor Janitor's Closet by Kitchen 108, Room 112, 107 Closet, 1st Floor Storage Closet by Girls' Toilet, Gym Office, 2nd Floor Storage Closet by Girls' Toilet**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Carpet Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1srt Floor Teachers' Restroom, Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Carpet Mastic ABATED**
MATERIAL LOCATION: **1srt Floor Teachers' Restroom, Main Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- Room 207**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**
MATERIAL LOCATION: **1965 Building- Room 207**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- Room 207**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**
MATERIAL LOCATION: **1965 Building- Room 207**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121**
MATERIAL QUANTITY: **4750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**
MATERIAL LOCATION: **1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121**
MATERIAL QUANTITY: **4750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16M**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121**
MATERIAL QUANTITY: **4750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **16M**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**
MATERIAL LOCATION: **1965 Building- Kitchen 108, 110, 107, 210, 212, 208 and 1st Floor Teacher's Lounge/Office 121**
MATERIAL QUANTITY: **4750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 2nd Floor Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **1965 Building- 2nd Floor Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 2nd Floor Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
MATERIAL LOCATION: **1965 Building- 2nd Floor Girls' and Boys' Washrooms**
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Beige w/Red Specks Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- Stairways**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Beige w/Red Specks Terrazzo**
MATERIAL LOCATION: **1965 Building- Stairways**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **505** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **505** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **505** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1965 Building- 1st Floor Vestibules, Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **505** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Tan Mosaic Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Girls' and Boys' Washrooms and Vestibules**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Tan Mosaic Ceramic Tile Grout**
MATERIAL LOCATION: **1953 Building- Girls' and Boys' Washrooms and Vestibules**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Tan Mosaic Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Girls' and Boys' Washrooms and Vestibules**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Tan Mosaic Ceramic Tile Adhesive**
MATERIAL LOCATION: **1953 Building- Girls' and Boys' Washrooms and Vestibules**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**
MATERIAL LOCATION: **1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Glue**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Glue**
MATERIAL LOCATION: **1953 Building- Throughout, Except Boiler Room and Boys' and Girls' Washrooms**
MATERIAL QUANTITY: **7900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Corridors and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **1953 Building- Corridors and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26M**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Corridors and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **26M**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
MATERIAL LOCATION: **1953 Building- Corridors and Main Office**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12x12 Gold Vinyl Floor Tile ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teachers' Restroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019. ABATED**

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 Gold Vinyl Floor Tile ABATED**

MATERIAL LOCATION: **1st Floor Teachers' Restroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12x12 Gold Vinyl Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teachers' Restroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019. ABATED**

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12x12 Gold Vinyl Floor Tile Mastic ABATED**
MATERIAL LOCATION: **1st Floor Teachers' Restroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Room 105 Toilet, Room 106 (area by toilet)**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Specks Floor Tile**
MATERIAL LOCATION: **1953 Building- Room 105 Toilet, Room 106 (area by toilet)**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Room 105 Toilet, Room 106 (area by Toilet)**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12x12 Off-White w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **1953 Building- Room 105 Toilet, Room 106 (area by Toilet)**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Floor Tile (under HA 16 and HA 16M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Addition- Rooms 208, 212, & Kitchen (108)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Floor Tile (under HA 16 and HA 16M)**
MATERIAL LOCATION: **1965 Addition- Rooms 208, 212, & Kitchen (108)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29A**
MATERIAL DESCRIPTION: **Floor Tile Mastic (under HA 16 and HA 16M)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Addition- Rooms 208, 212, & Kitchen (108)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **29A**
MATERIAL DESCRIPTION: **Floor Tile Mastic (under HA 16 and HA 16M)**
MATERIAL LOCATION: **1965 Addition- Rooms 208, 212, & Kitchen (108)**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Boiler Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **ABATED**

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Tank Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS: **ABATED**

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Fiberglass Joint**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Addition- Pipe Chase & Above Ceilings**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Fiberglass Joint**
MATERIAL LOCATION: **1965 Addition- Pipe Chase & Above Ceilings**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joint on Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Addition- Pipe Chase & Above Ceiling**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joint on Fiberglass**
MATERIAL LOCATION: **1953 Addition- Pipe Chase & Above Ceiling**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 & 1965 Buildings- Crawlspace**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **1953 & 1965 Buildings- Crawlspace**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- Pipe Chases and Crawlspace**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **1953 Building- Pipe Chases and Crawlspace**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 & 1965 Buildings- Throughout**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/0219**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Fiberglass Insulation**
MATERIAL LOCATION: **1953 & 1965 Buildings- Throughout**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Fiberglass Joint**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Annex- Crawlspace**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Fiberglass Joint**
MATERIAL LOCATION: **1965 Annex- Crawlspace**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1963 Building- Unexcavated Area**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/06/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
MATERIAL LOCATION: **1963 Building- Unexcavated Area**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUIDLING ID: **8030**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**
SCHOOL NAME: **Wacker School** INSPECTION DATE: **8/6/0219**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Duct Wrap over Fiberglass**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1965 Addition- Fan Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/06/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26621** BUILDING ID: **8030**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**
SCHOOL NAME: **Wacker School** REVIEW DATE: **9/4/2019**
ADDRESS: **9746 S Morgan** IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Duct Wrap over Fiberglass**
MATERIAL LOCATION: **1965 Addition- Fan Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/04/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAQUILLE CREWS
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI01

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.

Environmental and Occupational Services
37 E. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office 312-491-0081
Fax 312-421-2901

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19717

ISSUED
4/16/2019

EXPIRES
05/15/2020

SHAQUILLE CREWS
12823 S GREEN
CHICAGO, IL 60643
Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/30/2020

PROJECT MANAGER

3/29/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



PUBLIC HEALTH & SAFETY Inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
371 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
		INSPECTOR	3/19/2019
ID NUMBER	ISSUED	EXPIRES	
100 - 02950	3/6/2019	05/15/2020	
KEITH CLOUGH			
524 HOMELAND RD			
MATTESON, IL 60443			
Environmental Health			
		PROJECT MANAGER	4/9/2019
		AIR SAMPLING PROFESSIONAL	
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed