

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2849  
SCHOOL NAME: Uplift Community High School  
ADDRESS OF SCHOOL: 900 W Wilson Ave  
CITY: Chicago, IL, 60640

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 117  
IDPH INSPECTOR LICENSE NUMBER: 100-06327  
IDPH LICENSED INSPECTOR NAME(Please Print): Roberto Rivera  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Uplift Community High School**

900 W Wilson Ave  
Chicago, IL, 60640

Unit: 26861  
Building ID: 2210

IDPH ID Number: 14-016-2990-2849

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 12, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 26861            Region: 01            IDPH ID:14-016-2990-2849

School: Uplift Community High School            Building ID: 2210

Address: 900 W Wilson Ave  
Chicago, IL, 60640

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/08/2019

Inspector: Roberto Rivera            Inspector IDPH License: 100-06327  
Management Planner: Jigar Shah            Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 12, 2019

RE: Uplift Community High School, Unit 26861  
900 W Wilson Ave  
Chicago, IL, 60640

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Uplift Community High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Uplift Community High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Uplift Community High School  
Address: 900 W Wilson Ave  
IDPH ID: 14-016-2990-2849  
Contact: School  
Unit: 26861  
Chicago, IL, 60640  
Building ID: 2210  
Phone: Region: 01

### 2. Description of Facility

Original Construction: 1975  
Total Square Footage: 105665  
Current Occupancy: 117  
Additional Construction:  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602  
Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575  
Fax:

### 5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327

Signature:  
Date: 9/12/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:  
Date: 10/08/2019

### 7. Review Date:10/08/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Uplift Community High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2210:

B. The following new homogenous areas have been identified for Building 2210:

24	18" X 18" Beige w/ brown & tan waves VFT
24A	18" X 18" Beige w/ brown & tan waves VFT mastic
25	White/gray linoleum flooring
25A	White/gray linoleum flooring mastic
26	2' X 4' rough w/ pin holes ceiling tile
27	12" x 12" White w/ brown specks VFT
27A	12" X 12" white w/ brown specks VFT Mastic
28	2' X 4' ceiling tile w/ large grooves and pin holes
29	12" X 12" beige w/ white & brown specks VFT
29A	12" X 12" beige w/ white & brown specks VFT Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

12	Stucco Ceiling Plaster
15	2 x 4 ft Ceiling Tiles with Grooves
16	MJP E/F/V on Fiberglass
17	Carpet Mastic
18	Terrazzo
19	150 Fire Doors
20	Drywall, Tape, and Compound
21	12"x12" Black w/White Specks VFT
21A	12"x12" Black w/White Specks VFT Mastic
22	2'X4' White Smooth Ceiling Tiles
23	White w/Pinholes Ceiling Tiles
24	18" X 18" Beige w/ brown & tan waves VFT
24A	18" X 18" Beige w/ brown & tan waves VFT mastic
25	White/gray linoleum flooring
25A	White/gray linoleum flooring mastic
26	2' X 4' rough w/ pin holes ceiling tile
27	12" x 12" White w/ brown specks VFT
27A	12" X 12" white w/ brown specks VFT Mastic
28	2' X 4' ceiling tile w/ large grooves and pin holes
29	12" X 12" beige w/ white & brown specks VFT
29A	12" X 12" beige w/ white & brown specks VFT Mastic
3A	Exterior Window Caulk
4A	Interior Window Caulk
5A	Exterior Window Glaze

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Uplift Community High School Building 2210 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Uplift Community High School Unit 26861 Building ID 2210

Address 900 W Wilson Ave Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
12	Stucco Ceiling Plaster	5,000	SF	Toilets- Main Building and Physical Ed Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Incinerator Gasket	3	SF	Incinerator Room- Main Building	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
15	2 x 4 ft Ceiling Tiles with Grooves	2,500	SF	Janitor's Closets, B 200, B 201, Main Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
16	MJP E/F/V on Fiberglass	300	LF	Throughout Main and Gym Bldgs	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
17	Carpet Mastic	10,000	SF	Rooms C 300, C 301, 319, MDF 3rd Floor, B 310, Comp Lab 313, A301, 331, Music room balcony 327,328, 2nd floor library, 220, 221, 228, 227, music room 229, C 208, B 208, Math lab 210 and offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Terrazzo	5,000	SF	Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	150 Fire Doors	150	SF	Throughout Main and Phy. Ed. Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
1A	12"x12" Brown w/Yellow Streaks VFT	104,500	SF	Throughout (See Hatching Maps) - Main Building and Physical Ed Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Drywall, Tape, and Compound	2,000	SF	Indoor Courts and Stairwells (Main & Phy. Ed. Bldg)	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
21	12"x12" Black w/White Specks VFT	16,000	SF	Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Uplift Community High School Unit 26861 Building ID 2210

Address 900 W Wilson Ave Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center										
21A	12"x12" Black w/White Specks VFT Mastic	16,000	SF	Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	2'X4' White Smooth Ceiling Tiles	50,000	SF	Throughout Main Bldg	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
23	White w/Pinholes Ceiling Tiles	30,000	SF	Throughout Phy. Ed. Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
24	18" X 18" Beige w/ brown & tan waves VFT	2,000	SF	Classroom 321 - Main Bldg	ASSUMED	MISC	N	NONE	0					LOW
24A	18" X 18" Beige w/ brown & tan waves VFT mastic	2,000	SF	Classroom 321-main bldg	ASSUMED	MISC	N	NONE	0					LOW
25	White/gray linoleum flooring	6,000	SF	Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201	ASSUMED	MISC	N	NONE	0					LOW
25A	White/gray linoleum flooring mastic	6,000	SF	Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201	ASSUMED	MISC	N	NONE	0					LOW

# Chicago Public Schools

School Uplift Community High School Unit 26861 Building ID 2210  
 Address 900 W Wilson Ave Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
26	2' X 4' rough w/ pin holes ceiling tile	3,000	SF	Mens lockers 219 and girls lockers B-Building, 2nd floor elevator lobby.	ASSUMED	MISC	Y	NONE	0					LOW
27	12" x 12" White w/ brown specks VFT	1,600	SF	1st floor health center and associated rooms and break room. - main bldg	ASSUMED	MISC	N	NONE	0					LOW
27A	12" X 12" white w/ brown specks VFT Mastic	1,600	SF	1st floor health center and associated rooms and break room. - main bldg	ASSUMED	MISC	N	NONE	0					LOW
28	2' X 4' ceiling tile w/ large grooves and pin holes	2,000	SF	Throughout health center - main bldg 1st floor	ASSUMED	MISC	Y	NONE	0					LOW
29	12" X 12" beige w/ white & brown specks VFT	400	SF	Health center hallway - main bldg 1st floor	ASSUMED	MISC	N	NONE	0					LOW
29A	12" X 12" beige w/ white & brown specks VFT Mastic	400	SF	Health center hallway - main bldg	ASSUMED	MISC	N	NONE	0					LOW
2A	12"x12" Brown w/Yellow Streaks VFT Mastic	104,500	SF	Throughout (See Hatching Maps) - Main Building and Physical Ed Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3A	Exterior Window Caulk	0		Exterior Windows- Main Building	ASSUMED						No			
4A	Interior Window Caulk	0		Interior Windows - Main Building	ASSUMED						No			
5A	Exterior Window Glaze	0		Exterior Windows - Main Building	ASSUMED						No			

# Chicago Public Schools

School Uplift Community High School Unit 26861 Building ID 2210  
Address 900 W Wilson Ave Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612  
Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/12/2019</b>
Inspector Name <b>Roberto Rivera</b>
<b>100-06327</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
12	
14	
15	
16	
17	
18	
19	
1A	
20	
21	
21A	
22	
23	
24	
24A	
25	
25A	
26	
27	
27A	
28	
29	
29A	

# Chicago Public Schools

**School** Uplift Community High School **Unit** 26861 **Building ID** 2210  
**Address** 900 W Wilson Ave **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
2A	
3A	
4A	
5A	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Uplift Community High School

**Unit** 26861

**Building ID** 2210

**Address** 900 W Wilson Ave

Chicago, IL, 60640

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
12	Stucco Ceiling Plaster	5,000	SF	Toilets- Main Building and Physical Ed Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Incinerator Gasket	3	SF	Incinerator Room- Main Building	Chrysotile	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	2 x 4 ft Ceiling Tiles with Grooves	2,500	SF	Janitor's Closets, B 200, B 201, Main Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	MJP E/F/V on Fiberglass	300	LF	Throughout Main and Gym Bldgs	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
17	Carpet Mastic	10,000	SF	Rooms C 300, C 301, 319, MDF 3rd Floor, B 310, Comp Lab 313, A301, 331, Music room balcony 327,328, 2nd floor library, 220, 221, 228, 227, music room 229, C 208, B 208, Math lab 210 and offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Terrazzo	5,000	SF	Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	150 Fire Doors	150	SF	Throughout Main and Phy. Ed. Bldg	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
1A	12"x12" Brown w/Yellow Streaks VFT	104,500	SF	Throughout (See Hatching Maps) - Main Building and Physical Ed Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Drywall, Tape, and Compound	2,000	SF	Indoor Courts and Stairwells (Main & Phy. Ed. Bldg)	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Black w/White Specks VFT	16,000	SF	Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio-visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	12"x12" Black w/White Specks VFT Mastic	16,000	SF	Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio-	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Uplift Community High School

Unit 26861

Building ID 2210

Address 900 W Wilson Ave

Chicago, IL, 60640

Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center							
22	2'X4' White Smooth Ceiling Tiles	50,000	SF	Throughout Main Bldg	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	White w/Pinholes Ceiling Tiles	30,000	SF	Throughout Phy. Ed. Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	18" X 18" Beige w/ brown & tan waves VFT	2,000	SF	Classroom 321 - Main Bldg	Assumed	MISC	No	0	SF		Follow O&M Plan
24A	18" X 18" Beige w/ brown & tan waves VFT mastic	2,000	SF	Classroom 321- main bldg	Assumed	MISC	No	0	SF		Follow O&M Plan
25	White/gray linoleum flooring	6,000	SF	Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201	Assumed	MISC	No	0	SF		Follow O&M Plan
25A	White/gray linoleum flooring mastic	6,000	SF	Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201	Assumed	MISC	No	0	SF		Follow O&M Plan
26	2' X 4' rough w/ pin holes ceiling tile	3,000	SF	Mens lockers 219 and girls lockers B-Building, 2nd floor elevator lobby.	Assumed	MISC	Yes	0	SF		Follow O&M Plan
27	12" x 12" White w/ brown specks VFT	1,600	SF	1st floor health center and associated rooms and break room. - main bldg	Assumed	MISC	No	0	SF		Follow O&M Plan
27A	12" X 12" white w/ brown specks VFT Mastic	1,600	SF	1st floor health center and associated rooms and break room. - main bldg	Assumed	MISC	No	0	SF		Follow O&M Plan
28	2' X 4' ceiling tile w/ large grooves and pin holes	2,000	SF	Throughout health center - main bldg 1st floor	Assumed	MISC	Yes	0	SF		Follow O&M Plan
29	12" X 12" beige w/ white & brown specks VFT	400	SF	Health center hallway - main bldg 1st floor	Assumed	MISC	No	0	SF		Follow O&M Plan
29A	12" X 12" beige w/ white & brown specks VFT Mastic	400	SF	Health center hallway - main bldg	Assumed	MISC	No	0	SF		Follow O&M Plan
2A	12"x12" Brown w/Yellow Streaks VFT Mastic	104,500	SF	Throughout (See Hatching Maps) - Main Building and Physical Ed Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	Exterior Window Caulk	0		Exterior Windows- Main Building	Assumed						
4A	Interior Window Caulk	0		Interior Windows - Main Building	Assumed						
5A	Exterior Window Glaze	0		Exterior Windows - Main Building	Assumed						

# Chicago Public Schools

**School** Uplift Community High School

**Unit** 26861

**Building ID** 2210

**Address** 900 W Wilson Ave

Chicago, IL, 60640

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/08/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
12	
14	
15	
16	
17	
18	

# Chicago Public Schools

**School** Uplift Community High School  
**Address** 900 W Wilson Ave

**Unit** 26861  
Chicago, IL, 60640

**Building ID** 2210  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612  
Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
19	
1A	
20	
21	
21A	
22	
23	
24	
24A	
25	
25A	
26	
27	
27A	
28	
29	
29A	
2A	
3A	
4A	
5A	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26861**    BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**    INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Tolietts- Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **5000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Stucco Ceiling Plaster**  
MATERIAL LOCATION: **Toilets- Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Incinerator Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Incinerator Room- Main Building**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Incinerator Gasket**  
MATERIAL LOCATION: **Incinerator Room- Main Building**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2 x 4 ft Ceiling Tiles with Grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Janitor's Closets, B 200, B 201, Main Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **2 x 4 ft Ceiling Tiles with Grooves**  
MATERIAL LOCATION: **Janitor's Closets, B 200, B 201, Main Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Main and Gym Bldgs**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass**  
MATERIAL LOCATION: **Throughout Main and Gym Bldgs**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms C 300, C 301, 319, MDF 3rd Floor, B 310, Comp Lab 313, A301, 331, Music room balcony 327,328, 2nd floor library, 220, 221, 228, 227, music room 229, C 208, B 208, Math lab 210 and offices**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Rooms C 300, C 301, 319, MDF 3rd Floor, B 310, Comp Lab 313, A301, 331, Music room balcony 327,328, 2nd floor library, 220, 221, 228, 227, music room 229, C 208, B 208, Math lab 210 and offices**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **150 Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Main and Phy. Ed. Bldg**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **150 Fire Doors**  
MATERIAL LOCATION: **Throughout Main and Phy. Ed. Bldg**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **26861**    BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**    INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**    IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/Yellow Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **104500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **1A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/Yellow Streaks VFT**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **104500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall, Tape, and Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Indoor Courts and Stairwells (Main & Phy. Ed. Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Drywall, Tape, and Compound**  
MATERIAL LOCATION: **Indoor Courts and Stairwells (Main & Phy. Ed. Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x12" Black w/White Specks VFT**

MATERIAL LOCATION: **Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center**

MATERIAL QUANTITY: **16000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **12"x12" Black w/White Specks VFT Mastic**  
MATERIAL LOCATION: **Lunch Rm B, Kiva Area, Door #7 Entry (Main Bldg), C 311, C 310, 332, 3rd floor hall lobby, B 311, B 300, B 301, A 311, A 310, A 300, 310, 329, Audio- visual 203, C 209, 219, Teachers lounge next to 219, 2nd floor lobby, B209, Seminar 211 (storage), A 209, A 208, 200, 2nd floor elevator lobby-b building, A 100, A 101, A 102, B 100, B 101, B 102, 1st Floor hall by health center**  
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **2'X4' White Smooth Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Main Bldg**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **2'X4' White Smooth Ceiling Tiles**  
MATERIAL LOCATION: **Throughout Main Bldg**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **White w/Pinholes Ceiling Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Phy. Ed. Bldg.**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **White w/Pinholes Ceiling Tiles**  
MATERIAL LOCATION: **Throughout Phy. Ed. Bldg.**  
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/Yellow Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **104500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/Yellow Streaks VFT Mastic**  
MATERIAL LOCATION: **Throughout (See Hatching Maps) - Main Building and Physical Ed Building**  
MATERIAL QUANTITY: **104500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows- Main Building**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **3A**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
MATERIAL LOCATION: **Exterior Windows- Main Building**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows - Main Building**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/12/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **4A**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
MATERIAL LOCATION: **Interior Windows - Main Building**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School** INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**  
MATERIAL DESCRIPTION: **Exterior Window Glaze**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows - Main Building**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26861** BUIDLING ID: **2210**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School** REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **5A**  
MATERIAL DESCRIPTION: **Exterior Window Glaze**  
MATERIAL LOCATION: **Exterior Windows - Main Building**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **2' X 4' ceiling tile w/ large grooves and pin holes**

MATERIAL LOCATION: **Throughout health center - main bldg 1st floor**

MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY:

ACCESSIBILITY:

DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **2' X 4' ceiling tile w/ large grooves and pin holes**  
MATERIAL LOCATION: **Throughout health center - main bldg 1st floor**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **25A**  
MATERIAL DESCRIPTION: **White/gray linoleum flooring mastic**  
MATERIAL LOCATION: **Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201**  
MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **25A**

MATERIAL DESCRIPTION: **White/gray linoleum flooring mastic**

MATERIAL LOCATION: **Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201**

MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" X 12" beige w/ white & brown specks VFT**  
MATERIAL LOCATION: **Health center hallway - main bldg 1st floor**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12" X 12" beige w/ white & brown specks VFT**  
MATERIAL LOCATION: **Health center hallway - main bldg 1st floor**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **White/gray linoleum flooring**  
MATERIAL LOCATION: **Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201**  
MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **White/gray linoleum flooring**  
MATERIAL LOCATION: **Classrooms: C 200/ C 201, B 201/ B 201, A 200, A 201**  
MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **29A**  
MATERIAL DESCRIPTION: **12" X 12" beige w/ white & brown specks VFT Mastic**  
MATERIAL LOCATION: **Health center hallway - main bldg**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **29A**

MATERIAL DESCRIPTION: **12" X 12" beige w/ white & brown specks VFT Mastic**

MATERIAL LOCATION: **Health center hallway - main bldg**

MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **27A**  
MATERIAL DESCRIPTION: **12" X 12" white w/ brown specks VFT Mastic**  
MATERIAL LOCATION: **1st floor health center and associated rooms and break room. - main bldg**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **27A**  
MATERIAL DESCRIPTION: **12" X 12" white w/ brown specks VFT Mastic**  
MATERIAL LOCATION: **1st floor health center and associated rooms and break room. - main bldg**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **2' X 4' rough w/ pin holes ceiling tile**  
MATERIAL LOCATION: **Mens lockers 219 and girls lockers B-Building, 2nd floor elevator lobby.**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **2' X 4' rough w/ pin holes ceiling tile**  
MATERIAL LOCATION: **Mens lockers 219 and girls lockers B-Building, 2nd floor elevator lobby.**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" White w/ brown specks VFT**  
MATERIAL LOCATION: **1st floor health center and associated rooms and break room. - main bldg**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12" x 12" White w/ brown specks VFT**  
MATERIAL LOCATION: **1st floor health center and associated rooms and break room. - main bldg**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24A**  
MATERIAL DESCRIPTION: **18" X 18" Beige w/ brown & tan waves VFT mastic**  
MATERIAL LOCATION: **Classroom 321- main bldg**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **24A**  
MATERIAL DESCRIPTION: **18" X 18" Beige w/ brown & tan waves VFT mastic**  
MATERIAL LOCATION: **Classroom 321- main bldg**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Uplift Community High School**      INSPECTION DATE: **9/12/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **18" X 18" Beige w/ brown & tan waves VFT**  
MATERIAL LOCATION: **Classroom 321 - Main Bldg**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY:  
  
ACCESSIBILITY:      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE UNITS: **SF**  
  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/12/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **26861**      BUILDING ID: **2210**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Uplift Community High School**      REVIEW DATE: **10/8/2019**  
ADDRESS: **900 W Wilson Ave**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **18" X 18" Beige w/ brown & tan waves VFT**  
MATERIAL LOCATION: **Classroom 321 - Main Bldg**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-6000 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**ROBERTO RIVERA**  
855 WEST ADAMS STREET, STE 200  
CHICAGO, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>			<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR	<b>TC EXPIRES</b> 1/20/2017 1/6/2017
<b>ID NUMBER</b> 100 - 06327	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017	<b>PROJECT MANAGER</b> AIR SAMPLING PROFESSIONAL	1/20/2017
<b>ROBERTO RIVERA</b> 855 WEST ADAMS STREET, ST CHICAGO, IL 60607 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/15/2019

Exam Date: 2/15/2019

Expiration Date: 2/15/2020

Certificate Number: BIR1902150525

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

			<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 06327	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020	SUPERVISOR/WORKER INSPECTOR		2/22/2020 2/15/2020	
<b>ROBERTO RIVERA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL		2/22/2020	
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**  
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060030

  
\_\_\_\_\_  
Kathy DeSalvo, Director

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <p><b>ASBESTOS PROFESSIONAL LICENSE</b></p>		<p><b>ENDORSEMENTS</b></p> <p>INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL</p>	<p><b>TC EXPIRES</b></p> <p>2/28/2020 3/15/2020 2/28/2020 2/22/2020</p>
<p>ID NUMBER 100 - 07342</p>	<p>ISSUED 4/19/2019</p>	<p>EXPIRES 05/15/2020</p>	
<p><b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health</p>			<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed