

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2451
SCHOOL NAME: Sheridan Magnet
ADDRESS OF SCHOOL: 533 W. 27th St.
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/5/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 549
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-01934
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Randy Livingston

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sheridan Magnet

533 W. 27th St.
Chicago, IL, 60616

Unit: 29201
Building ID: 4920

IDPH ID Number: 14-016-2990-2451

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 22, 2019

RE: Sheridan Magnet, Unit 29201
533 W. 27th St.
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Sheridan Magnet, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Sheridan Magnet, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sheridan Magnet
Address: 533 W. 27th St.
IDPH ID: 14-016-2990-2451
Contact: Frost, Steven

Unit: 29201
Chicago, IL, 60616
Building ID: 4920
Phone: 773 534 9118/77

Region: 04

2. Description of Facility

Original Construction: 1881
Total Square Footage: 68750
Current Occupancy: 549

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 11/22/2019

6. Management Planner

Management Planner Name: Randy Livingston

Management Planner IDPH license # 100-01934

Signature:
Date: 11/26/2019

7. Review Date: 11/26/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sheridan Magnet. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4920:

48	12"x12" Lt Beige Floor Tile
49	12"x12" Lt Beige Floor Tile Mastic
F	Aircell Joint Insulation
L	Breeching Liner
S	Block Pipe Insulation

B. The following new homogenous areas have been identified for Building 4920:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

32	Cloth Window Blinds
33	Window Caulk
34	4" Gray Vinyl Baseboard
35	4" Gray Vinyl Baseboard Adhesive
36	Blue Ceramic Floor Tile Grout
37	4" Lt Gray Vinyl Baseboard
38	4" Lt Gray Vinyl Baseboard Adhesive
39	White Ceramic Wall Tile Grout
3A	12" X 12" Floor Tile (Speckled/Tan)
3C	12" X 12" Floor Tile (Dark Beige)
3D	12" X 12" Floor Tile (Beige Marbled) (now blue, red, green multi-color carpet)
3E	12" X 12" Floor Tile (Cream) (now blue, red, green multi-color carpet)
3F	12" X 12" Floor Tile (Tan)
3G	12" X 12" Floor Tile (Light Tan Patches)
3H	12x12 Gray FT W/White, Gray Specks
40	White Ceramic Wall Tile Adhesive
41	18"x18" White Ceramic Tile
42	Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive
43	4" Gray/Black Vinyl Baseboard
44	4" Gray/Black Vinyl Baseboard Adhesive
45	Blue Carpet Mastic
46	Black Vinyl Baseboard
47	Black Vinyl Baseboard Adhesive
48	12"x12" Lt Beige Floor Tile
49	12"x12" Lt Beige Floor Tile Mastic
4H	12x12 gray FT W/White, Gray Specks Mastic
50	Green Carpet Mastic
51	12"x12" Orange/Rust Floor Tile
52	12"x12" Orange/Rust Floor Tile Mastic
53	Lab Tables
54	12"x12" Gray Floor Tile w/ White and Black Spots
55	12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic
56	Kiln brick
I	Interior Fire Brick
L	Breeching Liner
M	Refractory Brick

The following areas were deemed to be inaccessible:

28	9x9 VFT, Beneath 12x12 VFT
28A	Mastic for 9x9 VFT, Beneath 12x12 VFT
35	4" Gray Vinyl Baseboard Adhesive
38	4" Lt Gray Vinyl Baseboard Adhesive
40	White Ceramic Wall Tile Adhesive
42	Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive
44	4" Gray/Black Vinyl Baseboard Adhesive
45	Blue Carpet Mastic
47	Black Vinyl Baseboard Adhesive
49	12"x12" Lt Beige Floor Tile Mastic
4A	Mastic for 12x12 Speckled/Tan Floor Tile
4B	Mastic for 12x12 Red/Speckled Floor Tile
4G	Mastic for 12x12 Floor Tile (Light Tan Patches)
4H	12x12 gray FT W/White, Gray Specks Mastic
50	Green Carpet Mastic
52	12"x12" Orange/Rust Floor Tile Mastic
55	12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic
I	Interior Fire Brick
L	Breeching Liner
M	Refractory Brick
S	Block Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sheridan Magnet Building 4920 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Restrooms										
22A	Mortar for 8"x16" Glazed Block			Basement Restrooms	NO_ACBM									
23	8"x16" Cinderblock			Scattered	NO_ACBM									
23A	Mortar for 8"x16" Cinderblock			Scattered	NO_ACBM									
24	Exterior Brick- Not AHERA			1881- Exterior	NO_ACBM									
24A	Mortar for Exterior Brick- Not AHERA			1881- Exterior	NO_ACBM									
25	Exterior Brick- Not AHERA			1902- Exterior	NO_ACBM									
25A	Mortar for Exterior Brick- Not AHERA			1902- Exterior	NO_ACBM									
26	Ceramic Caulk			2nd Floor Restrooms	NO_ACBM									
27	Sink Insulation, Sink Under Coating	100	SF	Rooms 102 and 202, 007	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9x9 VFT, Beneath 12x12 VFT	1,200	SF	Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28A	Mastic for 9x9 VFT, Beneath 12x12 VFT	1,200	SF	Lunchroom, Beneath 12x12 VFT	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Window Frame Caulk			1881- Interior	NO_ACBM									
2A	2' X 4' Acoustical Ceiling Tile- Perforated			Rooms 105	NO_ACBM									
2B	2' X 4' Acoustical Ceiling Tile- Lightly Fissured			Room 105	NO_ACBM									
2C	2' X 4' Fissured & Perforated Ceiling Tile			Room 008	NO_ACBM									
2D	2' X 4' Gypsum Ceiling Tile			2nd Floor (Men's Room)	NO_ACBM									
30	Window Frame Caulk			1902- Interior	NO_ACBM									
31	1'x1' Ceiling Tile			3rd Floor Hallway	NO_ACBM									
32	Cloth Window Blinds			1976- Throughout	ASSUMED									
33	Window Caulk			1998- Exterior Not AHERA	ASSUMED	MISC								
34	4" Gray Vinyl Baseboard	180	LF	Engineer's Office and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	4" Gray Vinyl Baseboard Adhesive	180	LF	Engineer's Office and Teachers' Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Blue Ceramic Floor Tile Grout	60	SF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	4" Lt Gray Vinyl Baseboard	30	LF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	4" Lt Gray Vinyl Baseboard Adhesive	30	SF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	White Ceramic Wall Tile Grout	30	SF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3A	12" X 12" Floor Tile (Speckled/Tan)	4,500	SF	1st FL-Toilet, 2nd	ASSUMED	MISC	N	DIST	50		No	ACBM with the	5	LOW

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108								potential for damage		
3B	12" X 12" Floor Tile (Red/Speckled)	3,000	SF	Rooms 106, 206, 203	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3C	12" X 12" Floor Tile (Dark Beige)	300	SF	2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet	ASSUMED	MISC	N	DIST	40		No	ACBM with the potential for damage	5	LOW
3D	12" X 12" Floor Tile (Beige Marbled) (now blue, red, green multi-color carpet)	800	SF	Boy's Playroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3E	12" X 12" Floor Tile (Cream) (now blue, red, green multi-color carpet)	800	SF	Girl's Playroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3F	12" X 12" Floor Tile (Tan)	800	SF	Room 008	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3G	12" X 12" Floor Tile (Light Tan Patches)	2,000	SF	101, 3rd FL Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3H	12x12 Gray FT W/White, Gray Specks	1,080	SF	Engineer Office and Adjacent Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	White Ceramic Wall Tile Adhesive	30	SF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	18"x18" White Ceramic Tile	60	SF	Engineer's Office Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive	1,600	SF	Computer Lab and Room 007	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	4" Gray/Black Vinyl Baseboard	300	SF	Computer Lab, Room 007 and Lunchroom area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	4" Gray/Black Vinyl Baseboard Adhesive	300	LF	Computer Lab, Room 007, Lunchroom Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Blue Carpet Mastic	1,600	SF	Library, 2nd Floor Counselor's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Black Vinyl Baseboard	40	LF	Room 008	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Black Vinyl Baseboard Adhesive	40	LF	Room 008	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12"x12" Lt Beige Floor Tile	4,000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	ASSUMED	MISC	N	LOC	50		Yes	ACBM with the potential for damage	3	LOW
49	12"x12" Lt Beige Floor Tile Mastic	4,000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	ASSUMED	MISC	N	LOC	50		Yes	ACBM with the potential for damage	3	LOW

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A	Fiberglass Pipe Insulation			Throughout										
B	Fiberglass Joint Insulation	200	LF	Throughout Bldg. Boiler Room, Mechanical Room and Chases	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Cardboard Pipe Insulation	2,000	LF	1902- Basement, 102, 202	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Cardboard Joint Insulation	250	LF	1902- Basement, 102, 202	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell Pipe Insulation	680	LF	1881- Basement and Fan Rooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Joint Insulation	81	LF	1881- Basement and Fan Rooms	CHR	TSI	Y	LOC	8		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	Boiler Gaskets	40	LF	Inspection Doors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Boiler Rope Gaskets	30	LF	Clean-Out Doors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I	Interior Fire Brick	100	SF	Boilers	ASSUMED	MISC	N	NONE	0		No			LOW
J	Hot Water Make-up Tank Insulation			Boiler Room	NO_ACBM									
K	Breeching (Brick Lining)			Incinerator	NO_ACBM									
L	Breeching Liner	150	SF	Boilers	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Refractory Brick	10	SF	Boilers	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Fire Brick			Incinerator	NO_ACBM									
O	Chimney Brick			Boiler Room	NO_ACBM									
O1	Chimney Brick Mortar			Boiler Room	NO_ACBM									
P	Chimney Liner Brick			Boiler Room	NO_ACBM									
P1	Chimney Liner Brick Mortar			Boiler Room	NO_ACBM									
Q	Chimney Soot			Boiler Room	NO_ACBM									
R- Field	Roof Field - Not AHERA			Roof- Section E	NO_ACBM									
R- Flash	Roof Flashings - Not AHERA			Roof- Section E	CHR									
R- X Joint	Expansion Joint			Roof- Section E	NO_ACBM									
S	Block Pipe Insulation	30	LF	1881 Building- Throughout Building	AMO_CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/22/2019
Inspector Name <u>Marcos Iwankiw</u>
100-03175 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
11	
12	
12A	
12B	
13	
13A	
13B	
14	
14A	
14B	
15	
15A	
16	
17	Not observed
18	
18A	
19	
19A	
1A	
20	Damage in lunchroom on floors and walls
20A	
21	
21A	

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22	
22A	
23	
23A	
24	
24A	
25	
25A	
26	
27	
28	Not observed
28A	Not observed
29	
2A	Not observed
2B	Not observed
2C	Not observed
2D	
30	
31	
32	Not observed
33	
34	
35	
36	
37	
38	
39	
3A	
3B	

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
3C	
3D	Not observed
3E	Not observed
3F	
3G	Room 101 - no access
3H	
40	
41	
42	
43	
44	
45	
46	
47	
48	Damage is located in center of the SW lunchroom
49	Damage is located in the center of the SW lunchroom
4A	1st and 2nd floor janitor's closet are hardwood
4B	
4C	
4D	
4E	
4F	
4G	
4H	
5	
50	
51	
52	
53	

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
54	Not observed
55	Room 107 now hardwood floor
56	Not observed
6	
6A/7	
8	
9	
9A	
A	Not a suspect material
B	
C	
D	
E	
F	
G	Not observed
H	Not observed
I	Not observed
J	
K	
L	Not observed
M	
N	
O	
O1	
P	
P1	
Q	
R- Field	Not observed
R- Flash	Not observed

Chicago Public Schools

School Sheridan Magnet Unit 29201 Building ID 4920

Address 533 W. 27th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
R- X Joint	Not observed
S	

Table II

Management Planner's Review

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
11	Caulk			2nd Floor Urinals	No ACBM						
12	4"x4" White Ceramic Tile			2nd Floor Walls	No ACBM						
12A	Grout for 4"x4" White Ceramic Tile			2nd Floor Walls	No ACBM						
12B	Mastic for 4"x4" White Ceramic Tile			2nd floor walls	No ACBM						
13	1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors	No ACBM						
13A	Grout for 1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors	No ACBM						
13B	Mastic for 1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors	No ACBM						
14	1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom	No ACBM						
14A	Grout for 1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom	No ACBM						
14B	Adhesive for 1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom	No ACBM						
15	Wood Window Glaze			1881- Interior Hallways	No ACBM						
15A	Wood Window Glaze			1902- Interior Hallways	No ACBM						
16	Metal Window Glaze			1976- Interior Abated 1999	Abated						
17	Metal Window Caulk			1976- Exterior Not AHERA	Chrysotile						
18	New 2"x8" Brick			Interior	No ACBM						
18A	Mortar for 2"x8" Brick			Interior	No ACBM						
19	2"x8" Glazed Brick			Interior Basement Restrooms	No ACBM						
19A	Mortar for 2"x8" Glazed Brick			Interior Basement Restrooms	No ACBM						
1A	Plaster			Throughout 1881 Construction	No ACBM						
20	Interior Brick			1881- Basement	No ACBM			50			
20A	Mortar for Interior Brick			1881- Basement	No ACBM						
21	Interior Brick			1902- Basement	No ACBM						
21A	Mortar for Interior Brick			1902- Basement	No ACBM						
22	8"x16" Glazed Block			Basement Restrooms	No ACBM						
22A	Mortar for 8"x16" Glazed Block			Basement Restrooms	No ACBM						
23	8"x16" Cinderblock			Scattered	No ACBM						
23A	Mortar for 8"x16" Cinderblock			Scattered	No ACBM						
24	Exterior Brick- Not AHERA			1881- Exterior	No ACBM						
24A	Mortar for Exterior Brick- Not AHERA			1881- Exterior	No ACBM						
25	Exterior Brick- Not AHERA			1902- Exterior	No ACBM						
25A	Mortar for Exterior Brick- Not AHERA			1902- Exterior	No ACBM						

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
26	Ceramic Caulk			2nd Floor Restrooms	No ACBM						
27	Sink Insulation, Sink Under Coating	100	SF	Rooms 102 and 202, 007	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	9x9 VFT, Beneath 12x12 VFT	1,200	SF	Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	Mastic for 9x9 VFT, Beneath 12x12 VFT	1,200	SF	Lunchroom, Beneath 12x12 VFT	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Window Frame Caulk			1881- Interior	No ACBM						
2A	2' X 4' Acoustical Ceiling Tile- Perforated			Rooms 105	No ACBM						
2B	2' X 4' Acoustical Ceiling Tile- Lightly Fissured			Room 105	No ACBM						
2C	2' X 4' Fissured & Perforated Ceiling Tile			Room 008	No ACBM						
2D	2' X 4' Gypsum Ceiling Tile			2nd Floor (Men's Room)	No ACBM						
30	Window Frame Caulk			1902- Interior	No ACBM						
31	1'x1' Ceiling Tile			3rd Floor Hallway	No ACBM						
32	Cloth Window Blinds			1976- Throughout	Assumed						
33	Window Caulk			1998- Exterior Not AHERA	Assumed	MISC					
34	4" Gray Vinyl Baseboard	180	LF	Engineer's Office and Teachers' Lounge	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
35	4" Gray Vinyl Baseboard Adhesive	180	LF	Engineer's Office and Teachers' Lounge	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	Blue Ceramic Floor Tile Grout	60	SF	Engineer's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	4" It Gray Vinyl Baseboard	30	LF	Engineer's Office Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
38	4" Lt Gray Vinyl Baseboard Adhesive	30	SF	Engineer's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	White Ceramic Wall Tile Grout	30	SF	Engineer's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	12" X 12" Floor Tile (Speckled/Tan)	4,500	SF	1st FL-Toilet, 2nd FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Repair
3B	12" X 12" Floor Tile (Red/Speckled)	3,000	SF	Rooms 106, 206, 203	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3C	12" X 12" Floor Tile (Dark Beige)	300	SF	2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Repair
3D	12" X 12" Floor Tile (Beige Marbled) (now blue, red, green multi-color carpet)	800	SF	Boy's Playroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3E	12" X 12" Floor Tile (Cream) (now blue, red, green multi-color carpet)	800	SF	Girl's Playroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3F	12" X 12" Floor Tile (Tan)	800	SF	Room 008	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3G	12" X 12" Floor Tile (Light Tan Patches)	2,000	SF	101, 3rd FL Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3H	12x12 Gray FT W/White, Gray Specks	1,080	SF	Engineer Office and Adjacent Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
40	White Ceramic Wall Tile Adhesive	30	SF	Engineer's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	18"x18" White Ceramic Tile	60	SF	Engineer's Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Blue,Red, Yellow,Purple Multi-Color Carpet Adhesive	1,600	SF	Computer Lab and Room 007	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Gray/Black Vinyl Baseboard	300	SF	Computer Lab, Room 007 and Lunchroom area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Gray/Black Vinyl Baseboard Adhesive	300	LF	Computer Lab,Room 007, Lunchroom Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	Blue Carpet Mastic	1,600	SF	Library, 2nd Floor Counselor's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Black Vinyl Baseboard	40	LF	Room 008	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
47	Black Vinyl Baseboard Adhesive	40	LF	Room 008	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" Lt Beige Floor Tile	4,000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Remove
49	12"x12" Lt Beige Floor Tile Mastic	4,000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Remove
4A	Mastic for 12x12 Speckled/Tan Floor Tile	11,000	SF	008, 009, 210, Basement LR, See HA 3A Locations, 108, 311, 3rd floor hallway, first floor toilet, 2nd floor janitors closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4B	Mastic for 12x12 Red/Speckled Floor Tile	2,100	SF	Rooms 206, 203	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4C	Mastic for 12x12 Floor Tile (Dark Beige)			2nd and 3rd Floor Janitor's Closets	No ACBM						
4D	Mastic for 12x12 Floor Tile (Beige Marbled)			Boy's Playroom	No ACBM						
4E	Mastic for 12x12 Floor Tile (Cream)			Girl's Playroom	No ACBM						
4F	Mastic for 12x12 Floor Tile (White)			room 008	No ACBM						
4G	Mastic for 12x12 Floor Tile (Light Tan Patches)	40	SF	101, 3rd Floor Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4H	12x12 gray FT W/White, Gray Specks Mastic	1,080	SF	Engineer Office and Adjacent Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Plaster Walls			1902 building	No ACBM						
50	Green Carpet Mastic	1,200	SF	Main Office and Asst. Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Orange/Rust Floor Tile	3,100	SF	Room 202,207,106	Assumed	MISC	No	30	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Orange/Rust Floor Tile Mastic	3,100	SF	Room 202,207,106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Lab Tables	150	SF	Lab Rooms 202 and 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Gray Floor Tile w/ White and Black Spots	50	SF	Room 107 Washroom, Boiler Room Stair Landing and Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic	50	SF	Room 107 Washroom, Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Stair Landing and Washroom							
56	Kiln brick	20	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Black Vinyl Cove Base			Basement, 1st, 2nd	No ACBM						
6A/7	Adhesive for Black Vinyl Cove Base			Basement, 1st, 2nd	No ACBM						
8	Plaster on Sheetrock			Basement	No ACBM						
9	Sheetrock			Scattered	No ACBM						
9A	Joint Compound on Sheetrock			Scattered	No ACBM						
A	Fiberglass Pipe Insulation			Throughout							
B	Fiberglass Joint Insulation	200	LF	Throughout Bldg. Boiler Room, Mechanical Room and Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Cardboard Pipe Insulation	2,000	LF	1902- Basement, 102, 202	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Cardboard Joint Insulation	250	LF	1902- Basement, 102, 202	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell Pipe Insulation	680	LF	1881- Basement and Fan Rooms	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Joint Insulation	81	LF	1881- Basement and Fan Rooms	Chrysotile	TSI	Yes	8	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
G	Boiler Gaskets	40	LF	Inspection Doors	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	
H	Boiler Rope Gaskets	30	LF	Clean-Out Doors	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Interior Fire Brick	100	SF	Boilers	Assumed	MISC	No	0	SF		
J	Hot Water Make-up Tank Insulation			Boiler Room	No ACBM						
K	Breeching (Brick Lining)			Incinerator	No ACBM						
L	Breeching Liner	150	SF	Boilers	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Refractory Brick	10	SF	Boilers	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Fire Brick			Incinerator	No ACBM						
O	Chimney Brick			Boiler Room	No ACBM						
O1	Chimney Brick Mortar			Boiler Room	No ACBM						
P	Chimney Liner Brick			Boiler Room	No ACBM						
P1	Chimney Liner Brick Mortar			Boiler Room	No ACBM						
Q	Chimney Soot			Boiler Room	No ACBM						
R- Field	Roof Field - Not AHERA			Roof- Section E	No ACBM						
R- Flash	Roof Flashings - Not AHERA			Roof- Section E	Chrysotile						

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
 Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
R- X Joint	Expansion Joint			Roof- Section E	No ACBM						
S	Block Pipe Insulation	30	LF	1881 Building-Throughout Building	Amosite, Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Review Date 11/26/2019

HA Number	Management Comments

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
 Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Manager Planner Name	Randy Livingston
100-01934	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
11	
12	
12A	
12B	
13	
13A	
13B	
14	
14A	
14B	
15	
15A	
16	
17	
18	
18A	
19	
19A	
1A	
20	
20A	
21	
21A	
22	
22A	
23	

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
 Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
23A	
24	
24A	
25	
25A	
26	
27	
28	
28A	
29	
2A	
2B	
2C	
2D	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	Repair damaged floor tile and associated mastic
3B	

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
 Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
3C	Repair damaged floor tile and associated mastic
3D	
3E	
3F	
3G	
3H	
40	
41	
42	
43	
44	
45	
46	
47	
48	Remove and abate and replace the damaged floor tile in the center of the SW lunchroom
49	See HA 48
4A	
4B	
4C	
4D	
4E	
4F	
4G	
4H	
5	
50	

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
51	
52	
53	
54	
55	
56	
6	
6A/7	
8	
9	
9A	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	

Chicago Public Schools

School Sheridan Magnet
Address 533 W. 27th St.

Unit 29201
Chicago, IL, 60616

Building ID 4920
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
O1	
P	
P1	
Q	
R- Field	
R- Flash	
R- X Joint	
S	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Urinals**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Caulk**

MATERIAL LOCATION: **2nd Floor Urinals**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **4"x4" White Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **4"x4" White Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **Grout for 4"x4" White Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **12A**

MATERIAL DESCRIPTION: **Grout for 4"x4" White Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**
MATERIAL DESCRIPTION: **Mastic for 4"x4" White Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd floor walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **12B**

MATERIAL DESCRIPTION: **Mastic for 4"x4" White Ceramic Tile**

MATERIAL LOCATION: **2nd floor walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **1"x1" Pastel Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **1"x1" Pastel Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **Grout for 1"x1" Pastel Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **Grout for 1"x1" Pastel Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **Mastic for 1"x1" Pastel Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **13B**

MATERIAL DESCRIPTION: **Mastic for 1"x1" Pastel Ceramic Tile**

MATERIAL LOCATION: **2nd Floor Restroom Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **1"x1" Dark Multi-Colored Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **1"x1" Dark Multi-Colored Ceramic Tile**

MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **Grout for 1"x1" Dark Multi-Colored Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **14A**

MATERIAL DESCRIPTION: **Grout for 1"x1" Dark Multi-Colored Ceramic Tile**

MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **Adhesive for 1"x1" Dark Multi-Colored Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **14B**
MATERIAL DESCRIPTION: **Adhesive for 1"x1" Dark Multi-Colored Ceramic Tile**
MATERIAL LOCATION: **Basement Restrooms and Entry to 1st Floor Boy's Restroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Wood Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Interior Hallways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Wood Window Glaze**

MATERIAL LOCATION: **1881- Interior Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **Wood Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Interior Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **Wood Window Glaze**

MATERIAL LOCATION: **1902- Interior Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Metal Window Glaze**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1976- Interior Abated 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Metal Window Glaze**

MATERIAL LOCATION: **1976- Interior Abated 1999**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Metal Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1976- Exterior Not AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Metal Window Caulk**

MATERIAL LOCATION: **1976- Exterior Not AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **New 2"x8" Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **New 2"x8" Brick**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Mortar for 2"x8" Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **Mortar for 2"x8" Brick**

MATERIAL LOCATION: **Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **2"x8" Glazed Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Basement Restrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **2"x8" Glazed Brick**

MATERIAL LOCATION: **Interior Basement Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**
MATERIAL DESCRIPTION: **Mortar for 2"x8" Glazed Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Basement Restrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **Mortar for 2"x8" Glazed Brick**

MATERIAL LOCATION: **Interior Basement Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1A**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1881 Construction**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **1A**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout 1881 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **50**

DAMAGE UNITS:

COMMENTS: **Damage in lunchroom on floors and walls**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **1881- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **50**

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**
MATERIAL DESCRIPTION: **Mortar for Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **Mortar for Interior Brick**

MATERIAL LOCATION: **1881- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **1902- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21A**
MATERIAL DESCRIPTION: **Mortar for Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **Mortar for Interior Brick**

MATERIAL LOCATION: **1902- Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **8"x16" Glazed Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Restrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **8"x16" Glazed Block**

MATERIAL LOCATION: **Basement Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**
MATERIAL DESCRIPTION: **Mortar for 8"x16" Glazed Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **Mortar for 8"x16" Glazed Block**

MATERIAL LOCATION: **Basement Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **8"x16" Cinderblock**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **8"x16" Cinderblock**

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **Mortar for 8"x16" Cinderblock**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **23A**

MATERIAL DESCRIPTION: **Mortar for 8"x16" Cinderblock**

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Exterior Brick- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Exterior Brick- Not AHERA**

MATERIAL LOCATION: **1881- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24A**
MATERIAL DESCRIPTION: **Mortar for Exterior Brick- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **24A**

MATERIAL DESCRIPTION: **Mortar for Exterior Brick- Not AHERA**

MATERIAL LOCATION: **1881- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Exterior Brick- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Exterior Brick- Not AHERA**

MATERIAL LOCATION: **1902- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **Mortar for Exterior Brick- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **25A**

MATERIAL DESCRIPTION: **Mortar for Exterior Brick- Not AHERA**

MATERIAL LOCATION: **1902- Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Ceramic Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Ceramic Caulk**

MATERIAL LOCATION: **2nd Floor Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Sink Insulation, Sink Under Coating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102 and 202, 007**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Sink Insulation, Sink Under Coating**

MATERIAL LOCATION: **Rooms 102 and 202, 007**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **9x9 VFT, Beneath 12x12 VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9x9 VFT, Beneath 12x12 VFT**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **Mastic for 9x9 VFT, Beneath 12x12 VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom, Beneath 12x12 VFT**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **Mastic for 9x9 VFT, Beneath 12x12 VFT**
MATERIAL LOCATION: **Lunchroom, Beneath 12x12 VFT**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Window Frame Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1881- Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Window Frame Caulk**

MATERIAL LOCATION: **1881- Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**
MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile- Perforated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile- Perforated**

MATERIAL LOCATION: **Rooms 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**
MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile- Lightly Fissured**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **2' X 4' Acoustical Ceiling Tile- Lightly Fissured**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2C**
MATERIAL DESCRIPTION: **2' X 4' Fissured & Perforated Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 008**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2C**

MATERIAL DESCRIPTION: **2' X 4' Fissured & Perforated Ceiling Tile**

MATERIAL LOCATION: **Room 008**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2D**
MATERIAL DESCRIPTION: **2' X 4' Gypsum Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor (Men's Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2D**

MATERIAL DESCRIPTION: **2' X 4' Gypsum Ceiling Tile**

MATERIAL LOCATION: **2nd Floor (Men's Room)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Window Frame Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902- Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Window Frame Caulk**

MATERIAL LOCATION: **1902- Interior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**

MATERIAL LOCATION: **3rd Floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Cloth Window Blinds**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1976- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Cloth Window Blinds**

MATERIAL LOCATION: **1976- Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1998- Exterior Not AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **1998- Exterior Not AHERA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office and Teachers' Lounge**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
MATERIAL LOCATION: **Engineer's Office and Teachers' Lounge**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office and Teachers' Lounge**
MATERIAL QUANTITY: **180** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Engineer's Office and Teachers' Lounge**

MATERIAL QUANTITY: **180**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **4" It Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **4" It Gray Vinyl Baseboard**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **4" Lt Gray Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **4" Lt Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **White Ceramic Wall Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **White Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Speckled/Tan)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st FL-Toilet, 2nd FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3A**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Speckled/Tan)**
MATERIAL LOCATION: **1st FL-Toilet, 2nd FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Red/Speckled)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 206, 203**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Red/Speckled)**

MATERIAL LOCATION: **Rooms 106, 206, 203**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Dark Beige)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3C**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Dark Beige)**
MATERIAL LOCATION: **2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Repair damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3D**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Beige Marbled) (now blue, red, green multi-color carpet)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boy's Playroom**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3D**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Beige Marbled) (now blue, red, green multi-color carpet)**
MATERIAL LOCATION: **Boy's Playroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3E**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Cream) (now blue, red, green multi-color carpet)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girl's Playroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3E**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Cream) (now blue, red, green multi-color carpet)**
MATERIAL LOCATION: **Girl's Playroom**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3F**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Tan)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 008**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3F**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Tan)**
MATERIAL LOCATION: **Room 008**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3G**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Light Tan Patches)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101, 3rd FL Hallway**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Room 101 - no access**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3G**
MATERIAL DESCRIPTION: **12" X 12" Floor Tile (Light Tan Patches)**
MATERIAL LOCATION: **101, 3rd FL Hallway**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3H**
MATERIAL DESCRIPTION: **12x12 Gray FT W/White, Gray Specks**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office and Adjacent Room**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3H**
MATERIAL DESCRIPTION: **12x12 Gray FT W/White, Gray Specks**
MATERIAL LOCATION: **Engineer Office and Adjacent Room**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **White Ceramic Wall Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **White Ceramic Wall Tile Adhesive**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **18"x18" White Ceramic Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office Washroom**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **18"x18" White Ceramic Tile**

MATERIAL LOCATION: **Engineer's Office Washroom**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Computer Lab and Room 007**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive**
MATERIAL LOCATION: **Computer Lab and Room 007**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Gray/Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Computer Lab, Room 007 and Lunchroom area**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Gray/Black Vinyl Baseboard**

MATERIAL LOCATION: **Computer Lab, Room 007 and Lunchroom area**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Gray/Black Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Computer Lab, Room 007, Lunchroom Area**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Gray/Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Computer Lab,Room 007, Lunchroom Area**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, 2nd Floor Counselor's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Library, 2nd Floor Counselor's Office**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 008**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **Room 008**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 008**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Room 008**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **12"x12" Lt Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in center of the SW lunchroom**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12"x12" Lt Beige Floor Tile**

MATERIAL LOCATION: **Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Remove and abate and replace the damaged floor tile in the center of the SW lunchroom

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **12"x12" Lt Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in the center of the SW lunchroom**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"x12" Lt Beige Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311**

MATERIAL QUANTITY: **4000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

See HA 48

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A**
MATERIAL DESCRIPTION: **Mastic for 12x12 Speckled/Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **008, 009, 210, Basement LR, See HA 3A Locations, 108, 311, 3rd floor hallway, first floor toilet, 2nd floor janitors closet**

MATERIAL QUANTITY: **11000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **1st and 2nd floor janitor's closet are hardwood**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4A**
MATERIAL DESCRIPTION: **Mastic for 12x12 Speckled/Tan Floor Tile**
MATERIAL LOCATION: **008, 009, 210, Basement LR, See HA 3A Locations, 108, 311, 3rd floor hallway, first floor toilet, 2nd floor janitors closet**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4B**
MATERIAL DESCRIPTION: **Mastic for 12x12 Red/Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 206, 203**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4B**

MATERIAL DESCRIPTION: **Mastic for 12x12 Red/Speckled Floor Tile**

MATERIAL LOCATION: **Rooms 206, 203**

MATERIAL QUANTITY: **2100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4C**
MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Dark Beige)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Janitor's Closets**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4C**

MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Dark Beige)**

MATERIAL LOCATION: **2nd and 3rd Floor Janitor's Closets**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4D**
MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Beige Marbled)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Playroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4D**

MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Beige Marbled)**

MATERIAL LOCATION: **Boy's Playroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4E**
MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Cream)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's Playroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4E**

MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Cream)**

MATERIAL LOCATION: **Girl's Playroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4F**
MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (White)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 008**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4F**

MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (White)**

MATERIAL LOCATION: **room 008**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4G**
MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Light Tan Patches)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **101, 3rd Floor Hallway**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4G**

MATERIAL DESCRIPTION: **Mastic for 12x12 Floor Tile (Light Tan Patches)**

MATERIAL LOCATION: **101, 3rd Floor Hallway**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4H**
MATERIAL DESCRIPTION: **12x12 gray FT W/White, Gray Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office and Adjacent Room**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4H**
MATERIAL DESCRIPTION: **12x12 gray FT W/White, Gray Specks Mastic**
MATERIAL LOCATION: **Engineer Office and Adjacent Room**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Plaster Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1902 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **1902 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office and Asst. Principal's Office**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Green Carpet Mastic**
MATERIAL LOCATION: **Main Office and Asst. Principal's Office**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Orange/Rust Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202,207,106**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **12"x12" Orange/Rust Floor Tile**
MATERIAL LOCATION: **Room 202,207,106**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Orange/Rust Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202,207,106**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12"x12" Orange/Rust Floor Tile Mastic**
MATERIAL LOCATION: **Room 202,207,106**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lab Rooms 202 and 309**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab Tables**
MATERIAL LOCATION: **Lab Rooms 202 and 309**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ White and Black Spots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107 Washroom, Boiler Room Stair Landing and Washroom**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/ White and Black Spots**

MATERIAL LOCATION: **Room 107 Washroom, Boiler Room Stair Landing and Washroom**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107 Washroom, Boiler Room Stair Landing and Washroom**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Room 107 now hardwood floor**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic**
MATERIAL LOCATION: **Room 107 Washroom, Boiler Room Stair Landing and Washroom**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Kiln brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Kiln brick**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Black Vinyl Cove Base**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, 1st, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Black Vinyl Cove Base**

MATERIAL LOCATION: **Basement, 1st, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A/7**
MATERIAL DESCRIPTION: **Adhesive for Black Vinyl Cove Base**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, 1st, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A/7**

MATERIAL DESCRIPTION: **Adhesive for Black Vinyl Cove Base**

MATERIAL LOCATION: **Basement, 1st, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Plaster on Sheetrock**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Plaster on Sheetrock**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Sheetrock**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Sheetrock**

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9A**
MATERIAL DESCRIPTION: **Joint Compound on Sheetrock**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **9A**

MATERIAL DESCRIPTION: **Joint Compound on Sheetrock**

MATERIAL LOCATION: **Scattered**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not a suspect material**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Bldg. Boiler Room, Mechanical Room and Chases**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**

MATERIAL LOCATION: **Throughout Bldg. Boiler Room, Mechanical Room and Chases**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902- Basement, 102, 202**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **1902- Basement, 102, 202**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1902- Basement, 102, 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cardboard Joint Insulation**
MATERIAL LOCATION: **1902- Basement, 102, 202**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1881- Basement and Fan Rooms**
MATERIAL QUANTITY: **680** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **1881- Basement and Fan Rooms**
MATERIAL QUANTITY: **680** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Joint Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1881- Basement and Fan Rooms**
MATERIAL QUANTITY: **81** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Aircell Joint Insulation**
MATERIAL LOCATION: **1881- Basement and Fan Rooms**
MATERIAL QUANTITY: **81** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Inspection Doors**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Inspection Doors**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Rope Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Clean-Out Doors**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Boiler Rope Gaskets**
MATERIAL LOCATION: **Clean-Out Doors**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **Interior Fire Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boilers**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Interior Fire Brick**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **Hot Water Make-up Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Hot Water Make-up Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Breeching (Brick Lining)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Incinerator**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Breeching (Brick Lining)**

MATERIAL LOCATION: **Incinerator**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Breeching Liner**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boilers**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Breeching Liner**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Refractory Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boilers**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Refractory Brick**

MATERIAL LOCATION: **Boilers**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Fire Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Incinerator**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Fire Brick**

MATERIAL LOCATION: **Incinerator**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**
MATERIAL DESCRIPTION: **Chimney Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Chimney Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O1**
MATERIAL DESCRIPTION: **Chimney Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **O1**

MATERIAL DESCRIPTION: **Chimney Brick Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Chimney Liner Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Chimney Liner Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P1**
MATERIAL DESCRIPTION: **Chimney Liner Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **P1**

MATERIAL DESCRIPTION: **Chimney Liner Brick Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **Chimney Soot**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Chimney Soot**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R- Field**
MATERIAL DESCRIPTION: **Roof Field - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R- Field**

MATERIAL DESCRIPTION: **Roof Field - Not AHERA**

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R- Flash**
MATERIAL DESCRIPTION: **Roof Flashings - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R- Flash**

MATERIAL DESCRIPTION: **Roof Flashings - Not AHERA**

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUILDING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R- X Joint**
MATERIAL DESCRIPTION: **Expansion Joint**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **11/22/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R- X Joint**

MATERIAL DESCRIPTION: **Expansion Joint**

MATERIAL LOCATION: **Roof- Section E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Sheridan Magnet** INSPECTION DATE: **11/22/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Block Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1881 Building-Throughout Building**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/22/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **29201** BUIDLING ID: **4920**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Sheridan Magnet** REVIEW DATE: **11/26/2019**
ADDRESS: **533 W. 27th St.** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **S**
MATERIAL DESCRIPTION: **Block Pipe Insulation**
MATERIAL LOCATION: **1881 Building-Throughout Building**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **11/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Randolph Livingston


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/24/2019

Exam Date: 10/24/2019

Expiration Date: 10/24/2020

Certificate Number: MPR1910242073



Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 01934

ISSUED
11/5/2019

EXPIRES
05/15/2020

RANDOLPH LIVINGSTON
9549 S. EUCLID AVE
CHICAGO, IL 60617

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

2/6/2020

MANAGEMENT PLANNER

10/24/2020

PROJECT MANAGER

3/4/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed