ILLINOIS DEPARTMENT OF PUBLIC HEALTH	ł
AHERA THREE YEAR REINSPECTION	
ASBESTOS ABATEMENT PROGRAM	
SCHOOL INFORMATION FORM	

SECTION I

NAME OF SCHOOL DISTRICT:	CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER:	14-016-2990-2168
SCHOOL NAME:	Pershing West Multiplex
ADDRESS OF SCHOOL:	3200 S. Calumet
CITY:	Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 3/15/2016

If the address on this form is different than the address of the building, submit a written explanation.

<u>SECTION II</u> (<i>Please type or print</i>) PLEASE COMPLETE THE FOLLOWING FOR YOUR THR	EE YEAR REINSPECTION:
DATE REINSPECTION COMPLETED: 10/1/2019	ENROLLMENT 575
IDPH INSPECTOR LICENSE NUMBER: 100-0317	5
IDPH LICENSED INSPECTOR NAME(Please Print):	Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-01934	
IDPH LICENSED MANAGEMENT PLANNER NAM	E (Please Print): Randy Livingston
DESIGNATED PERSON (Please Print): Robert Chris	stlieb PHONE: (773) 553-3197
Adurante	10/1/2019
Signature of Designated Person	Date
SECTION III	
PLEASE COMPLETE THE FOLLOWING INFORMATION FOR	ANY CHANGES WITHIN THE SCHOOL DISTRICT.
School building has been sold. Date of Sale:	
School has been closed. Date closed:	
School building has been demolished. Date:	
School building is asbestos free since last reinspection:	

<u>Please explain in writing why the school building is now asbestos free and include the supporting documentation.</u>

If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Pershing West Multiplex

3200 S. Calumet Chicago, IL, 60616

Unit: 29251 Building ID: 3090

IDPH ID Number: 14-016-2990-2168

REPORT DATE: Tuesday, October 01, 2019

Prepared for: Chicago Public Schools 42 West Madison Street Chicago, IL 60602

Prepared by: Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, II, 60607

Phone (312) 762-2900

Fax (312) 782-5145

DO NOT REMOVE FROM SCHOOL REQUIRED BY FEDERAL LAW

December 15, 2019

Mr. Glen E. Garner Asbestos Program Illinois Department of Public Health 525 West Jefferson Street Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299	Unit: 31051	Region: 03	IDPH ID:14-016-2990-2168
School: Pershing West N	lultiplex		Building ID: 3090
Address: 3200 S. Calumet	t		
Chicago, IL, 606	16		
Building Contact:		Contact Phone:	
Current Building Owners:	Chicago Public Schools		
Review Date: 12/23/2019			
Inspector: Marcos Iwankiw	I	Inspector IDPH Licen	se: 100-03175
Management Planner: Ra	indy Livingston	Management Planner	r IDPH License: 100-01934
If you have any questions	or comments, please cor	ntact us at (312) 762-2	900

Sincerely, Carnow, Conibear and Associates

Randy Livingston 100-01934

Environmental Notification to Occupants

To: Faculty, Staff and Parents From: Chicago Public Schools Date: December 15, 2019

RE: Pershing West Multiplex, Unit 29251 3200 S. Calumet Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Pershing West Multiplex, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Pershing West Multiplex, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions
- Table I: Inspector's Reinspection Findings
- Table II: Management Planner's Review

APPENDICES:

Appendix A:	Assessment Sheets, Drawings and Photos
Appendix B:	Inspector and Management Planner Licenses
Appendix C:	Laboratory Accreditations
Appendix D:	Laboratory Results
Appendix E:	Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

Pershing West Multiplex Region: 03 School: Unit: 31051 Address: 3200 S. Calumet Chicago, IL, 60616 Building ID: 3090 IDPH ID: 14-016-2990-2168 Contact: Phone: **Description of Facility** 2. Original Construction: Additional Construction: Total Square Footage: No of Floors: Current Occupancy: 575 3. LEA Designated Person Contact: Robert Christlieb Phone: (773) 553-3197 Address: 42 West Madison Street Chicago, IL 60602 **Managing Environmental Consultant** 4. MEC: Carnow, Conibear and Associates Contact: Doug McCormick Address 600 West Van Buren St., Ste 500 Chicago, II, 60607 Phone: (312) 762-2900 Fax: (312) 782-5145 Inspector 5. Inspector Name: Marcos Iwankiw Signature: Date: 12/15/2019 Inspector IDPH license # 100-03175 Management Planner 6. Management Planner Name: Randy Livingston Signature: Management Planner IDPH license # 100-01934 Date: 12/23/2019 7. Review Date:12/23/2019 8. LEA Designated Person's Acknowledgement The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

fluch 2

Date: 10/1/2019

Name: Robert Christlieb

Signature:

Unit : 31051

Pershing West Multiplex

Building: 3090

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pershing West Multiplex. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3090:

B. The following new homogenous areas have been identified for Building 3090:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	Gasket
15	9" x 9" Brown w/White Streaks Floor Tile Mastic
22	12" x 12" Cream w/Brown Streaks Floor Tile
3	2' x 2' Ceiling Tile
34	12" x 12" Brown w/White Streaks Floor Tile
36	Roof Flashing - Non AHERA
37	Roof Field - Non AHERA
4,5,6	Plaster
42	Red Carpet Adhesive
43	Blue Carpet Adhesive
44	Vault Door Liner
45	Incinerator Interior Material
48	12"x12" Cream/Gray Speckled Floor Tile
49	12"x12" Cream/Gray Speckled Floor Tile-Mastic
50	4" Brown Vinyl Baseboard
51	4" Brown Vinyl Baseboard - Adhesive
52	12"x12" Cream/Beige Speckled Floor Tile
53	12"x12" Cream/Beige Speckled Floor Tile-Mastic
54	6" Black Vinyl Baseboard
55	6" Black Vinyl Baseboard Adhesive
56	2x2 Gypsum Ceiling Tile
57	12x12 Tan Mottle Floor Tile
58	12x12 Tan Mottle Floor Tile Mastic
59	Lab Counters
60	Tan Rubber Floor Adhesive
61	Brown Carpet Adhesive
62	Grey Multipurpose Adhesive
63	Decorative Plaster
64	Decorative Plaster Ceiling
65	Terrazzo
E	Boiler #1 Insulation

The following areas were deemed to be inaccessible:

11	Gasket
14	9" x 9" Black w/White Streaks Floor Tile Mastic
15	9" x 9" Brown w/White Streaks Floor Tile Mastic
17	12" x 12" Beige w/Brown Streaks Floor Tile Mastic
21	12" x 12" Brown Floor Tile Mastic
3	2' x 2' Ceiling Tile

35 12" x 12" Brown w/White Streaks	Floor Tile Mastic
44 Vault Door Liner	
51 4" Brown Vinyl Baseboard - Adhes	sive
53 12"x12" Cream/Beige Speckled Flo	oor Tile-Mastic
55 6" Black Vinyl Baseboard Adhesiv	e
60 Tan Rubber Floor Adhesive	
61 Brown Carpet Adhesive	
62 Grey Multipurpose Adhesive	

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

- 1. Review current management plan, identify HA(s) and extract appropriate information.
- 2. Examine and verify abatement records.
- 3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
- 4. Touchand visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
- 5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
- 6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
- 7. Tabulate reinspection findings nd submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
- 8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Pershing West Multiplex Building 3090 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Spray-on Fireproofing			Boiler room	NO_ACBM	MISC								
10,12	Aircell Duct Breeching	800	SF	Plenum Chambers	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
11	Gasket	20	LF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
13	12" x 12" Beige w/White Streaks Floor Tile Mastic			1st, 2nd and 3rd Floor Corridors	CHR	MISC								
14	9" x 9" Black w/White Streaks Floor Tile Mastic	2,000	SF	Rooms 111, 127, 1st , 2nd, and 3rd floor corridors edge design	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9" x 9" Brown w/White Streaks Floor Tile Mastic	2,000	SF	1st, 2nd, and 3rd Floor Corridors edge design	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12" x 12" Beige w/Brown Streaks Floor Tile	4,700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	4,700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors	CHR	MISC	Ν	NONE	0		No	ACBM with the potential for damage		LOW
18	12" x 12" Crème Floor Tile			Rooms 319 and 325	ABATED	MISC								
19	12" x 12" Crème Floor Tile Mastic			Rm 325	ABATED	MISC								
2	2' x 4' Ceiling Tile			North West Stairwell	NO_ACBM	MISC								
20	12" x 12" Brown Floor Tile	1,200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg, north bldg adjacent to HA 16	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12" x 12" Brown Floor Tile Mastic	1,200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
22	12" x 12" Cream w/Brown Streaks Floor Tile	1,000	SF	(1924 bldg) North West Stairwells in Basement, 1st, and 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12" x 12" Cream w/Brown Streaks Floor Tile Mastic	1,000	SF	(1924 bldg) North West Stairwells in Basement, 1st and 2nd Floors, Basement Delivery Ramp, Lunchroom, 3rd Floor Stairwell	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	9" x 9" Tan Floor Tile			Room 127	CHR	MISC								
25	9" x 9" Tan Floor Tile Mastic			Room 127	CHR	MISC								
26	Carpet mastic -Brown Multi - colored			Basement Room 100, rm 310	NO_ACBM	MISC								
27	Exterior Window Caulk - Not AHERA			Exterior of Windows on South West Side	CHR	MISC	N				No			
28	Window Glaze - Not AHERA			Exterior of Windows on South West Side	CHR	MISC								
29	Exterior Door Caulk - Not AHERA			Exterior Doors	CHR	MISC								
3	2' x 2' Ceiling Tile	1,200	SF	Office and Lunchroom	ASSUMED	MISC	Ν	NONE	0		No	ACBM with the potential for damage		LOW
30	Brick - Not AHERA			Exterior of Building	NO_ACBM	MISC								
31	Brick Mortar - Not AHERA			Exterior of Building	NO_ACBM	MISC								
32	9" x 9" Green Floor Tile			Room 111	CHR	MISC								
33	9" x 9" Green Floor Tile Mastic			Room 111	CHR	MISC		None						
34	12" x 12" Brown w/White Streaks Floor Tile	1,200	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12" x 12" Brown w/White Streaks Floor Tile Mastic	1,200	SF	Lunchroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Roof Flashing - Non AHERA			Roof	ASSUMED	MISC								
37	Roof Field - Non AHERA			Roof	ASSUMED	MISC								
38	Size Unknown Floor Tile (Under Carpet)			Room 100, Office	CHR	MISC								
39	Size Unknown Floor Tile (Under Carpet) Mastic			Room 100	CHR	MISC								
4,5,6	Plaster	300,000	SF	Throughout building	ASSUMED	SURFACE	Ν	NONE	0		No	ACBM with the potential for damage		LOW
40	9" x 9" Dark Brown Floor Tile		1	Room 127	CHR	MISC		1			1		1	1
41	9' x 9" Dark Brown Floor Tile Mastic			Room 127	CHR	MISC								
42	Red Carpet Adhesive			Auditorium	ASSUMED	MISC		None						Low
43	Blue Carpet Adhesive			Rooms 200	ASSUMED	MISC		None						Low
44	Vault Door Liner	15	SF	Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
45	Incinerator Interior Material	160	SF	Boiler Room Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" x 12" Black Floor Tile against Wall			Room 319	ABATED	MISC								
47	12" x 12" Black Floor Tile Mastic against Wall			Room 319	ABATED	MISC								
48	12"x12" Cream/Gray Speckled Floor Tile			Engineers Office	ASSUMED	MISC		None						High
49	12"x12" Cream/Gray Speckled Floor Tile- Mastic			Engineer's Office	ASSUMED	MISC		None						Low
50	4" Brown Vinyl Baseboard	46	LF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	4" Brown Vinyl Baseboard - Adhesive	46	LF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Cream/Beige Speckled Floor Tile	4,900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x12" Cream/Beige Speckled Floor Tile- Mastic	4,900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	6" Black Vinyl Baseboard	100	LF	1st, 2nd, 3rd Floor Elevator Areas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	6" Black Vinyl Baseboard Adhesive	100	SF	1st, 2nd, 3rd Floor Elevator Areas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	2x2 Gypsum Ceiling Tile	800	SF	Kitchen	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
57	12x12 Tan Mottle Floor Tile	2,500	SF	Lunchroom in Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12x12 Tan Mottle Floor Tile Mastic	2,500	SF	Lunchroom in Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Lab Counters	10	SF	Room 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Tan Rubber Floor Adhesive	100	SF	NW Entrance	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Brown Carpet Adhesive	1,800	SF	Multipurpose Room	ASSUMED	MISC	Ν	NONE	0		No	ACBM with the potential for damage		LOW
62	Grey Multipurpose Adhesive	2,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Decorative Plaster	15,000	SF	Auditorium	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
64	Decorative Plaster Ceiling	5,000	SF	Auditorium	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
65	Теггаzzo	5,000	SF	1924 Building 1st, 2nd, and 3rd Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	12" x 12" Beige w/White Streaks Floor Tile			1st, 2nd, and 3rd Floor Corridors	CHR	MISC								
8	9" x 9" Brown w/White Streaks Floor Tile			Room 115	CHR	MISC								
9	9" x 9" Black w/White Streaks Floor Tile			Rooms 111, 127	CHR	MISC								
E	Boiler #1 Insulation	400	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Boiler # 2 Insulation	400	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
н	Fittings Off Fiberglass Pipe Insulation			Fan Rooms and Basement	CHR	TSI		None						
I	Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Hallway	CHR	TSI		None						Moderate
J	Fittings Off Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Fan Room	CHR	TSI								
K	Mag (Preformed) Pipe Insulation			Basement Corridor and Fan Room	CHR	TSI		None						Moderate
L	Fittings Off Mag Pipe Insulation			Basement Corridor and Fan Rooms	CHR	TSI		None						
Μ	Cardboard Pipe Insulation			Boiler Room	NO_ACBM	MISC								
Ν	Fittings on Cardboard Pipe Insulation			Boiler Room	NO_ACBM	TSI								
0	Canvas (Thermal) Pipe Wrap			Basement Plenum Chamber	CHR	TSI								

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Reinspection Date 12/15/2	019	Inspector's Comments					
Inspector Name Marcos	s Iwankiw						
<u>100-03175</u>	<u>5/15/2020</u>	HA Number:	Inspector Comments:				
Inspector's IDPH License N			Inspector Comments.				
Inspector 3 IDI TI License I		10,12					
		11					
		13	Not obersved 2019				
		14					
		15					
		16					
		17					
		18					
		19					
		2					
		20					
		21					
		22					
		23					
		24	Not obersved 2019				
		25	Not obersved 2019				
		26					
		27					
		28					
		29					
		3					
		30					

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA Number:	Inspector Comments:
31	
32	Not observed 2019
33	Not obersved 2019
34	
35	
36	
37	
38	Not obersved 2019
39	Not observed 2019
4,5,6	
40	Not observed 2019
41	Not observed 2019
42	Not observed 2019
43	Not observed 2019
44	
45	
46	
47	
48	Not observed 2019
49	Not observed 2019
50	
51	
52	
53	
54	
55	
56	
57	
58	

SchoolPershing West MultiplexUnit31051Building ID3090Address3200 S. CalumetRegion03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA Number:	Inspector Comments:
59	
60	
61	
62	
63	
64	
65	
7	Not observed 2019
8	Not observed 2019
9	Not observed 2019
E	
F	
Н	Not observed 2019
1	Not observed 2019
J	Not observed 2019
К	Not observed 2019
L	Not observed 2019
М	
Ν	
0	Not observed 2019

Table II

Unit 31051 Building ID 3090

Address 3200 S. Calumet

School Pershing West Multiplex

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Region 03

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

Chicago, IL, 60616

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Number	·	Quantity	Units		Type	Category		Quantity	Units		· ·
1	Spray-on Fireproofing	1		Boiler room	No ACBM	MISC		1			
10,12	Aircell Duct Breeching	800	SF	Plenum Chambers	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	Gasket	20	LF	Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	12" x 12" Beige w/White Streaks Floor Tile Mastic			1st, 2nd and 3rd Floor Corridors	Chrysotile	MISC					
14	9" x 9" Black w/White Streaks Floor Tile Mastic	2,000	SF	Rooms 111, 127, 1st, 2nd, and 3rd floor corridors edge design	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9" x 9" Brown w/White Streaks Floor Tile Mastic	2,000	SF	1st, 2nd, and 3rd Floor Corridors edge design	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12" x 12" Beige w/Brown Streaks Floor Tile	4,700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	4,700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" Crème Floor Tile			Rooms 319 and 325	Abated	MISC					
19	12" x 12" Crème Floor Tile Mastic			Rm 325	Abated	MISC					
2	2' x 4' Ceiling Tile			North West Stairwell	No ACBM	MISC					
20	12" x 12" Brown Floor Tile	1,200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg, north bldg adjacent to HA 16	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" Brown Floor Tile Mastic	1,200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Cream w/Brown Streaks Floor Tile	1,000	SF	(1924 bldg) North West Stairwells in Basement, 1st, and 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Cream w/Brown Streaks Floor Tile Mastic	1,000	SF	(1924 bldg) North West Stairwells in Basement, 1st and 2nd Floors, Basement Delivery Ramp, Lunchroom, 3rd Floor Stairwell	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9" x 9" Tan Floor Tile			Room 127	Chrysotile	MISC					
25	9" x 9" Tan Floor Tile Mastic			Room 127	Chrysotile	MISC					
26	Carpet mastic -Brown Multi - colored			Basement Room 100, rm 310	No ACBM	MISC					

Unit 31051 Building ID 3090

Address 3200 S. Calumet

School Pershing West Multiplex

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

Chicago, IL, 60616

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

HA	Meterial Description	Matarial	Matarial	Meterial Leastian	Ashastas		Friable			Demons Cotomony	
	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Number		Quantity	Units		Туре	Category		Quantity	Units		
27	Exterior Window Caulk - Not AHERA			Exterior of Windows on South West Side	Chrysotile	MISC	No				
28	Window Glaze - Not AHERA			Exterior of Windows on South West Side	Chrysotile	MISC					
29	Exterior Door Caulk - Not AHERA			Exterior Doors	Chrysotile	MISC					
3	2' x 2' Ceiling Tile	1,200	SF	Office and Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Brick - Not AHERA			Exterior of Building	No ACBM	MISC				· · · · · ·	
31	Brick Mortar - Not AHERA			Exterior of Building	No ACBM	MISC					
32	9" x 9" Green Floor Tile			Room 111	Chrysotile	MISC					
33	9" x 9" Green Floor Tile Mastic			Room 111	Chrysotile	MISC					
34	12" x 12" Brown w/White Streaks Floor Tile	1,200	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Brown w/White Streaks Floor Tile Mastic	1,200	SF	Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Roof Flashing - Non AHERA			Roof	Assumed	MISC					
37	Roof Field - Non AHERA			Roof	Assumed	MISC					
38	Size Unknown Floor Tile (Under Carpet)			Room 100, Office	Chrysotile	MISC					
39	Size Unknown Floor Tile (Under Carpet) Mastic			Room 100	Chrysotile	MISC					
4,5,6	Plaster	300,000	SF	Throughout building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	9" x 9" Dark Brown Floor Tile			Room 127	Chrysotile	MISC					
41	9' x 9" Dark Brown Floor Tile Mastic			Room 127	Chrysotile	MISC					
42	Red Carpet Adhesive			Auditorium	Assumed	MISC					
43	Blue Carpet Adhesive			Rooms 200	Assumed	MISC					
44	Vault Door Liner	15	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Incinerator Interior Material	160	SF	Boiler Room Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Black Floor Tile against Wall			Room 319	Abated	MISC					
47	12" x 12" Black Floor Tile Mastic against Wall			Room 319	Abated	MISC					
48	12"x12" Cream/Gray Speckled Floor Tile			Engineers Office	Assumed	MISC					
49	12"x12" Cream/Gray Speckled Floor Tile-Mastic			Engineer's Office	Assumed	MISC					
50	4" Brown Vinyl Baseboard	46	LF	Engineer's Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	4" Brown Vinyl Baseboard - Adhesive	46	LF	Engineer's Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Cream/Beige Speckled Floor Tile	4,900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Cream/Beige Speckled Floor Tile-Mastic	4,900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Unit 31051 Building ID 3090

Address 3200 S. Calumet

School Pershing West Multiplex

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

Chicago, IL, 60616

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

HA	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Category	Response
Number		Quantity	Units		Type	Category		Quantity	Units		
54	6" Black Vinyl Baseboard	100	LF	1st, 2nd, 3rd Floor Elevator Areas	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	6" Black Vinyl Baseboard Adhesive	100	SF	1st, 2nd, 3rd Floor Elevator Areas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	2x2 Gypsum Ceiling Tile	800	SF	Kitchen	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12x12 Tan Mottle Floor Tile	2,500	SF	Lunchroom in Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12x12 Tan Mottle Floor Tile Mastic	2,500	SF	Lunchroom in Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Lab Counters	10	SF	Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Tan Rubber Floor Adhesive	100	SF	NW Entrance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Brown Carpet Adhesive	1,800	SF	Multipurpose Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Grey Multipurpose Adhesive	2,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Decorative Plaster	15,000	SF	Auditorium	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
64	Decorative Plaster Ceiling	5,000	SF	Auditorium	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
65	Terrazzo	5,000	SF	1924 Building 1st, 2nd, and 3rd Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	12" x 12" Beige w/White Streaks Floor Tile			1st, 2nd, and 3rd Floor Corridors	Chrysotile	MISC					
8	9" x 9" Brown w/White Streaks Floor Tile			Room 115	Chrysotile	MISC					
9	9" x 9" Black w/White Streaks Floor Tile			Rooms 111, 127	Chrysotile	MISC					
E	Boiler #1 Insulation	400	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Boiler # 2 Insulation	400	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Н	Fittings Off Fiberglass Pipe Insulation			Fan Rooms and Basement	Chrysotile	TSI					
I	Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Hallway	Chrysotile	TSI					
J	Fittings Off Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Fan Room	Chrysotile	TSI					
К	Mag (Preformed) Pipe Insulation			Basement Corridor and Fan Room	Chrysotile	TSI					
L	Fittings Off Mag Pipe Insulation			Basement Corridor and Fan Rooms	Chrysotile	TSI					
М	Cardboard Pipe Insulation			Boiler Room	No ACBM	MISC					
Ν	Fittings on Cardboard Pipe Insulation			Boiler Room	No ACBM	TSI					
0	Canvas (Thermal) Pipe Wrap			Basement Plenum Chamber	Chrysotile	TSI					

School Pershing West Multiplex Unit 31051 Building ID 3090

Address 3200 S. Calumet Chicago, IL, 60616

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900 Fax

Fax: (312) 782-5145

Review Date	12/23/2019	HA Number	Management Comments
	Randy Livingston	1	
100-01934	5/15/2020	10,12	
Manager IDPH License N		11	
Manager IDFTT License N		13	
		14	
		15	

School Pershing West Multiplex Unit 31051 Building ID 3090

Chicago, IL, 60616

Address 3200 S. Calumet

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA Number	Management Comments
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	

School Pershing West Multiplex Building ID 3090 Unit 31051

Chicago, IL, 60616

Address 3200 S. Calumet

Region 03 ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, II, 60607

(312) 762-2900 Fax: (312) 782-5145 Phone:

HA Number	Management Comments
4,5,6	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	

School Pershing West Multiplex Unit 31051 Building ID 3090

Chicago, IL, 60616

Address 3200 S. Calumet

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, II, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

HA Number	Management Comments
65	
7	
8	
9	
E	
F	
Н	
J	
К	
L	
М	
Ν	
0	

Carnow, Conibear and Associates 2019 AHERA REINSPECTION Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECT	OR: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DAT	E: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	D: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1	
MATERIAL DESCRIPTION:	Spray-on Fireproofing	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE	REASON:
D/ III// IOE	

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

Boiler room

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS: DAMAGE UNITS:

Inspector's Signature:

Date: 12/15/2019

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	IS UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	CITY/STATE: Chicago, Illinois		Randy Livingston
SCHOOL NAME: Pershing West Multiplex		REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 1		
MATERIAL DESCR	IPTION: Spray-on Fire	eproofing	
MATERIAL LOCATI	ON: Boiler room		
MATERIAL QUANTITY: MATERIAL UNITS:			
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10,12		
MATERIAL DESCRIPTION:	Aircell Duct Breeching		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM o	r friable suspect	ACBM
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL:LOWMATERIAL LOCATION:Plenum ChambersMATERIAL QUANTITY:800DAMAGE QUANTITY:0

COMMENTS:

Inspector's Signature:

MATERIAL UNITS:

DAMAGE UNITS:

SF

SF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershing West R Multiplex		REVIEW DATE:	REVIEW DATE:				
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	10,12						
MATERIAL DESCRIPTION: Aircell Duct Breeching								
MATERIAL LOCAT	ION:	Plenum Chambe	ers					
MATERIAL QUANT	TTY:	800			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM o	r friable suspect	ACBM
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershiı Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	11						
MATERIAL DESCR	IPTION:	Gasket						
MATERIAL LOCAT	ION:	Boiler Room						
MATERIAL QUANT	ITY:	20			MATERIAL UNI	ITS:	LF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	LF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	12" x 12" Beige w/White Streaks F	Floor Tile Mastic
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

1st, 2nd and 3rd Floor Corridors

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

COMMENTS: Not obersved 2019

DAMAGE UNITS:

Inspector's Signature:

Date: 12/15/2019

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	IS UNIT NUMBER:	31051 BUIDLING	ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PL/	ANNER: Randy Liv	vingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019)
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175	
HOMOGENEOUS A	REA: 13			
MATERIAL DESCRIPTION: 12" x 12" Beige w/White Streaks Floor Tile Mastic				
MATERIAL LOCATI	MATERIAL LOCATION: 1st, 2nd and 3rd Floor Corridors			
MATERIAL QUANTITY: MATERIAL UNITS:				
DAMAGE QUANTIT	Y:		DAMAGE	JNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	9" x 9" Black w/White Streaks Flo	or Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Rooms 111, 127, 1st , 2nd, and 3rd floor corridors edge design		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS AREA: 14								
MATERIAL DESCRIPTION: 9" x 9" Black w/			White Streaks Floor	r Tile Mastic				
MATERIAL LOCAT	ION:	Rooms 111, 127	7, 1st , 2nd, and 3rd	floor corrido	rs edge design			
MATERIAL QUANT	TTY:	2000			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15				
MATERIAL DESCRIPTION:	9" x 9" Brown w/White Streaks Fl	oor Tile Mastic			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage				
HISTORICAL DAMAGE REASON:					
HISTORICAL RESPONSE ACTION:	Follow O&M Plan				
ASBESTOS TYPE:	Assumed	FRIABLE:	No		

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, and 3rd Floor Corridors edge desig	n	
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicag	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS AREA: 15								
MATERIAL DESCRIPTION: 9" x 9" Brown w		/White Streaks Floo	or Tile Mastic					
MATERIAL LOCAT	MATERIAL LOCATION: 1st, 2nd, and 3rd Floor Corridors edge design							
MATERIAL QUANT	TTY:	2000			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16			
MATERIAL DESCRIPTION:	12" x 12" Beige w/Brown Streaks	Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm
127, 123, 111, 1st and 2nd floor corridorsMATERIAL QUANTITY:4700MATERIAL UNITS:SFDAMAGE QUANTITY:0DAMAGE UNITS:SFCOMMENTS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS		16						
MATERIAL DESCR	RIPTION:	12" x 12" Beige	w/Brown Streaks Fl	loor Tile				
MATERIAL LOCAT	MATERIAL LOCATION: Engineers office, Library, elevator lobby 1-3, Rm 1st and 2nd floor corridors			n 231, Teacher's	Lounge,	Office, Rm 1	127, 123, 111,	
MATERIAL QUANT	TTY:	4700			MATERIAL UNI	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17			
MATERIAL DESCRIPTION:	12" x 12" Beige w/Brown Streak	s Floor Tile Ma	stic	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm
127, 123, 111, 1st and 2nd floor corridorsMATERIAL QUANTITY:4700MATERIAL UNITS:SFDAMAGE QUANTITY:0DAMAGE UNITS:SFCOMMENTS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago F	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago,	Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershing Multiplex		REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. C	Calumet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	AREA:	17				
MATERIAL DESCR	IPTION:	12" x 12" Beige	w/Brown Streaks Fl	oor Tile Mast	tic	
MATERIAL LOCATION: Engineers office, Lil 1st and 2nd floor co				obby 1-3, Rm	231, Teacher's	Lounge, Office, Rm 127, 123, 111,
MATERIAL QUANT	ITY:	4700			MATERIAL UNI	ITS: SF
DAMAGE QUANTIT	FY:	0			DAMAGE UNIT	TS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	AHE	ERA INSPECTOR:	Marcos Iwankiw	
SCHOOL NAME:	Pershing West Multiplex	INS	PECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDP	H LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	12" x 12" Crème Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

Rooms 319 and 325

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	s UNIT NUMBER: 3105	1 BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNE	R: Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 18		
MATERIAL DESCR	IPTION: 12" x 12" Crè	me Floor Tile	
MATERIAL LOCATI	ON: Rooms 319 a	nd 325	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	12" x 12" Crème Floor Tile Mastic	;
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rm 325

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS: DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 19		
MATERIAL DESCR	PTION: 12" x 12" Crèm	ne Floor Tile Mastic	
MATERIAL LOCATI	ON: Rm 325		
MATERIAL QUANT	TY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 3	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	AHEF	RA INSPECTOR:	Marcos Iwankiw	/
SCHOOL NAME:	Pershing West Multiplex	INSP	PECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDPH	LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2	
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

North West Stairwell

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public	Schools UNIT N	IUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illino	s MANAG	GEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershing West Multiplex	REVIE	W DATE:		12/23/2019	
ADDRESS:	3200 S. Calum	et IDPH L	ICENSE NO:	:	100-03175	
HOMOGENEOUS AREA: 2						
MATERIAL DESCR	IPTION: 2' x 4'	Ceiling Tile				
MATERIAL LOCATI	ON: North	West Stairwell				
MATERIAL QUANTITY:					MATERIAL UNI	TS:
DAMAGE QUANTITY:					DAMAGE UNITS	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg, north bldg adjacent to HA 16		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS AREA: 20								
MATERIAL DESCR	RIPTION:	12" x 12" Browr	n Floor Tile					
MATERIAL LOCAT	ION:	1st, 2nd, and 3r	d Floor Corridors A	gainst Walls,	In south bldg, n	orth bldg	adjacent to HA 16	
MATERIAL QUANT	TTY:	1200			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21			
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Νο	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS	21							
MATERIAL DESCR	RIPTION:	12" x 12" Browr	Floor Tile Mastic					
MATERIAL LOCAT	ION:	1st, 2nd, and 3r	d Floor Corridors A	gainst Walls,	In south bldg			
MATERIAL QUANT	TITY:	1200			MATERIAL UN	ITS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Cream w/Brown Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	(1924 bldg) North West Stairwells in Basement, 1st, and 2nd Floors				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		
COMMENTS:					

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS AREA: 22								
MATERIAL DESCR	IPTION:	12" x 12" Cream	n w/Brown Streaks F	loor Tile				
MATERIAL LOCAT	ION:	(1924 bldg) Nor	th West Stairwells ir	n Basement,	1st, and 2nd Flo	ors		
MATERIAL QUANT	TTY:	1000			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23				
MATERIAL DESCRIPTION:	12" x 12" Cream w/Brown Streaks Floor Tile Mastic				
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage				
HISTORICAL DAMAGE REASON:					
HISTORICAL RESPONSE ACTION:	Follow O&M Plan				
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No		

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:(1924 bldg) North West Stairwells in Basement, 1st and 2nd Floors, Basement Delivery
Ramp, Lunchroom, 3rd Floor StairwellMATERIAL QUANTITY:1000MATERIAL UNITS:SFDAMAGE QUANTITY:0DAMAGE UNITS:SF

COMMENTS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Sc	NOOIS UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT I	PLANNER:	Randy Living	ston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE N	IO:	100-03175	
HOMOGENEOUS	AREA: 23				
MATERIAL DESCR	IPTION: 12" x 12"	Cream w/Brown Streaks	Floor Tile Ma	stic	
MATERIAL LOCAT	(g) North West Stairwells m, 3rd Floor Stairwell	in Basement,	1st and 2nd Floo	ors, Basement Delivery Ramp,
MATERIAL QUANT	ITY: 1000			MATERIAL UN	ITS: SF
DAMAGE QUANTI	-Y: 0			DAMAGE UNIT	-S: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	AHE	ERA INSPECTOR:	Marcos Iwankiw	
SCHOOL NAME:	Pershing West Multiplex	INS	PECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDP	H LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24	
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 127

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not obersved 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Living	ston
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	REA:	24				
MATERIAL DESCR	IPTION:	9" x 9" Tan Floo	or Tile			
MATERIAL LOCATI	ON:	Room 127				
MATERIAL QUANT	ITY:				MATERIAL UN	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTO	R: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE	E: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25	
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 127

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not obersved 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicage	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershin Multiple	•	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	REA:	25				
MATERIAL DESCRI	PTION:	9" x 9" Tan Floo	r Tile Mastic			
MATERIAL LOCATIO	ON:	Room 127				
MATERIAL QUANTI	TY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26	
MATERIAL DESCRIPTION:	Carpet mastic -Brown Multi - colo	ored
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

Basement Room 100, rm 310

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	DIS UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 26		
MATERIAL DESCR	IPTION: Carpet mast	ic -Brown Multi - colored	
MATERIAL LOCATI	ON: Basement R	oom 100, rm 310	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Exterior Window Caulk - Not AHE	RA	
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

Exterior of Windows on South West Side

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 27		
MATERIAL DESCR	IPTION: Exterior Windo	ow Caulk - Not AHERA	
MATERIAL LOCATI	ON: Exterior of Wir	ndows on South West Side	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	AHERA IN	SPECTOR: Marcos Iwankiw	
SCHOOL NAME:	Pershing West Multiplex	INSPECTIO	ON DATE: 12/15/2019	
ADDRESS:	3200 S. Calumet	IDPH LICE	NSE NO: 100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28	
MATERIAL DESCRIPTION:	Window Glaze - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

Exterior of Windows on South West Side

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public S	chools UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT F	PLANNER:	Randy Livings	ston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE N	Ю:	100-03175	
HOMOGENEOUS A	REA: 28				
MATERIAL DESCR	IPTION: Window	Glaze - Not AHERA			
MATERIAL LOCATI	ON: Exterior	of Windows on South We	st Side		
MATERIAL QUANT	ITY:			MATERIAL UN	TS:
DAMAGE QUANTIT	Y:			DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	Al	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	IN	SPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	ID	PH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Not AHERA	ι
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

Exterior Doors

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	s UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 29		
MATERIAL DESCR	IPTION: Exterior Door	Caulk - Not AHERA	
MATERIAL LOCATI	ON: Exterior Door	S	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	2' x 2' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Office and Lunchroom
MATERIAL QUANTITY: 1200 MATERIAL UNITS:
DAMAGE QUANTITY: 0 DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

SF

SF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Living	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	3						
MATERIAL DESCR	IPTION:	2' x 2' Ceiling Ti	le					
MATERIAL LOCAT	ION:	Office and Lunc	hroom					
MATERIAL QUANT	TTY:	1200			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	А	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	AI 1	SPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IC	OPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	Brick - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

Exterior of Building

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago P	ublic Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago,	Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershing Multiplex		REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. C	alumet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	REA: 3	30				
MATERIAL DESCRI	PTION: E	Brick - Not AHE	RA			
MATERIAL LOCATI	ON: E	Exterior of Build	ling			
MATERIAL QUANTI	TY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	Al	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	i IN	ISPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	ID	PH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31	
MATERIAL DESCRIPTION:	Brick Mortar - Not AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

Exterior of Building

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	IS UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 31		
MATERIAL DESCR	IPTION: Brick Mortar	- Not AHERA	
MATERIAL LOCATI	ON: Exterior of B	uilding	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AI	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	IN	ISPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	ID	PH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 111

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	REA:	32				
MATERIAL DESCR	IPTION:	9" x 9" Green Fl	oor Tile			
MATERIAL LOCATI	ON:	Room 111				
MATERIAL QUANT	ITY:				MATERIAL UN	ITS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 111

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not obersved 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Sc	hools UNIT NUMBER:	31051 BUIDLING	D: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PI	ANNER: Randy Liv	ingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	D: 100-03175	
HOMOGENEOUS A	AREA: 33			
MATERIAL DESCR	IPTION: 9" x 9" G	reen Floor Tile Mastic		
MATERIAL LOCAT	ON: Room 11	1		
MATERIAL QUANT	ITY:		MATERIAL	UNITS:
DAMAGE QUANTIT	Y:		DAMAGE L	NITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 12" Brown w/White Streak	s Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	34						
MATERIAL DESCRIPTION: 12" x 12" Brown		n w/White Streaks Fl	loor Tile					
MATERIAL LOCAT	ION:	Lunchroom						
MATERIAL QUANT	TTY:	1200			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35			
MATERIAL DESCRIPTION:	12" x 12" Brown w/White Streaks Floor Tile Mastic			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicag	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Living	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	35						
MATERIAL DESCRIPTION: 12" x 12" Brown			n w/White Streaks Fl	oor Tile Mas	tic			
MATERIAL LOCAT	ION:	Lunchroom						
MATERIAL QUANT	TTY:	1200			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTO	R: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE	E: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	Roof Flashing - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Put	blic Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illi	inois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershing W Multiplex	est	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calı	umet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	REA: 36					
MATERIAL DESCR	IPTION: Ro	of Flashing -	Non AHERA			
MATERIAL LOCATI	ON: Ro	of				
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	Roof Field - Non AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Pu	ıblic Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, II	linois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershing V Multiplex	Vest	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Ca	lumet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	REA: 37	7				
MATERIAL DESCR	IPTION: R	oof Field - Non	AHERA			
MATERIAL LOCATI	ON: Re	oof				
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPE	CTOR: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION E	DATE: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE	NO: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	Size Unknown Floor Tile (Under C	Carpet)
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

Room 100, Office

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not obersved 2019

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	AREA:	38				
MATERIAL DESCR	IPTION:	Size Unknown F	loor Tile (Under Ca	rpet)		
MATERIAL LOCATI	ON:	Room 100, Offic	e			
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	Size Unknown Floor Tile (Under Carpet) Masti	c
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

COMMENTS: Not observed 2019

MATERIAL QUANTITY:

DAMAGE QUANTITY:

Room 100

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Pub	lic Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illi	nois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershing We Multiplex	est	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calu	ımet	IDPH LICENSE NO	:	100-03175	
HOMOGENEOUS A	REA: 39					
MATERIAL DESCR	IPTION: Size	e Unknown F	loor Tile (Under Car	pet) Mastic		
MATERIAL LOCATI	ON: Roo	om 100				
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNITS	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4,5,6			
MATERIAL DESCRIPTION:	Plaster			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage		
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Throughout building
MATERIAL QUANTITY: 300000 MATERIAL UNITS: SF
DAMAGE QUANTITY: 0 DAMAGE UNITS: SF
COMMENTS:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS	AREA:	4,5,6						
MATERIAL DESCR	RIPTION:	Plaster						
MATERIAL LOCAT	ION:	Throughout bui	lding					
MATERIAL QUANT	TTY:	300000			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	AHE	ERA INSPECTOR:	Marcos Iwankiw	
SCHOOL NAME:	Pershing West Multiplex	INS	PECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDP	H LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	9" x 9" Dark Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 127

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Sch	nools UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	AREA: 40		
MATERIAL DESCR	IPTION: 9" x 9" Da	ark Brown Floor Tile	
MATERIAL LOCATI	ON: Room 127	7	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	AHE	RA INSPECTOR:	Marcos Iwankiw	1
SCHOOL NAME:	Pershing West Multiplex	INSF	PECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDPH	H LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	9' x 9" Dark Brown Floor Tile Mas	tic
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 127

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Scho	ools UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 41		
MATERIAL DESCR	IPTION: 9' x 9" Dark	Brown Floor Tile Mastic	
MATERIAL LOCATI	ON: Room 127		
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	А	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	AI 1	SPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IC	OPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	Red Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

MATERIAL UNITS: DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	REA:	42				
MATERIAL DESCR	IPTION:	Red Carpet Adh	esive			
MATERIAL LOCATI	ON:	Auditorium				
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43	
MATERIAL DESCRIPTION:	Blue Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Rooms 200

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

MATERIAL UNITS: DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershin Multiple	•	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	REA:	43				
MATERIAL DESCR	IPTION:	Blue Carpet Adl	hesive			
MATERIAL LOCATI	ON:	Rooms 200				
MATERIAL QUANT	ITY:				MATERIAL UN	ITS:
DAMAGE QUANTIT	Y:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Vault Door Liner		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	image	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Office		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	44						
MATERIAL DESCR	IPTION:	Vault Door Line	r					
MATERIAL LOCAT	ION:	Office						
MATERIAL QUANT	TTY:	15			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Incinerator Interior Material		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Boiler Room Addition

MATERIAL QUANTITY:	160	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	45						
MATERIAL DESCRIPTION: In		Incinerator Inter	rior Material					
MATERIAL LOCAT	ION:	Boiler Room Ad	ldition					
MATERIAL QUANT	TTY:	160			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46	
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile against	Wall
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

Room 319

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS: DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	IS UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 46		
MATERIAL DESCR	IPTION: 12" x 12" Bla	ck Floor Tile against Wall	
MATERIAL LOCATI	ON: Room 319		
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile Mastic against Wall
HISTORICAL AHERA DAMAGE CATEGORY	
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	
ASBESTOS TYPE:	Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

Room 319

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ton
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NO):	100-03175	
HOMOGENEOUS A	AREA:	47				
MATERIAL DESCR	IPTION:	12" x 12" Black	Floor Tile Mastic ag	ainst Wall		
MATERIAL LOCAT	ION:	Room 319				
MATERIAL QUANT	TTY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	ΓY:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48	
MATERIAL DESCRIPTION:	12"x12" Cream/Gray Speckled Flo	oor Tile
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: High

MATERIAL LOCATION: Engineers Office

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

Inspector's Signature:

Date: 12/15/2019

MATERIAL UNITS:

DAMAGE UNITS:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	S UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 48		
MATERIAL DESCR	IPTION: 12"x12" Crea	m/Gray Speckled Floor Tile	
MATERIAL LOCATI	ON: Engineers Of	fice	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49	
MATERIAL DESCRIPTION:	12"x12" Cream/Gray Speckled Flo	oor Tile-Mastic
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Low

MATERIAL LOCATION: Engineer's Office

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

Inspector's Signature:

Date: 12/15/2019

MATERIAL UNITS:

DAMAGE UNITS:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public S	Schools UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT	PLANNER:	Randy Livings	ston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE N	10:	100-03175	
HOMOGENEOUS AREA: 49					
MATERIAL DESCRIPTION: 12"x12" Cream/Gray Speckled Floor Tile-Mastic					
MATERIAL LOCATI	ON: Engine	er's Office			
MATERIAL QUANT	ITY:			MATERIAL UN	TS:
DAMAGE QUANTIT	Y:			DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50			
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:LOWMATERIAL LOCATION:Engineer's OfficeMATERIAL QUANTITY:46DAMAGE QUANTITY:0

COMMENTS:

Inspector's Signature:

MATERIAL UNITS:

DAMAGE UNITS:

LF

LF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	50						
MATERIAL DESCR	IPTION:	4" Brown Vinyl	Baseboard					
MATERIAL LOCAT	ION:	Engineer's Offic	e					
MATERIAL QUANT	TTY:	46			MATERIAL UN	TS:	LF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	LF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTO	R: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE	E: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard - Adl	nesive	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:LOWMATERIAL LOCATION:Engineer's OfficeMATERIAL QUANTITY:46DAMAGE QUANTITY:0

COMMENTS:

Inspector's Signature:

MATERIAL UNITS:

DAMAGE UNITS:

LF

LF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	51						
MATERIAL DESCR	IPTION:	4" Brown Vinyl	Baseboard - Adhesi	ve				
MATERIAL LOCAT	ION:	Engineer's Offic	e					
MATERIAL QUANT	TTY:	46			MATERIAL UNI	TS:	LF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	LF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12"x12" Cream/Beige Speckled	Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office		
MATERIAL QUANTITY:	4900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershiı Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS AREA: 52								
MATERIAL DESCR	IPTION:	12"x12" Cream/	Beige Speckled Floo	or Tile				
MATERIAL LOCAT	ION:	1st, 2nd, 3rd Flo	oor Elevator Areas, I	Rooms 306, ⁻	123, 127, 111, Of	ice		
MATERIAL QUANT	TTY:	4900			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12"x12" Cream/Beige Speckled Floor Tile-Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office			
MATERIAL QUANTITY:	4900	MATERIAL UNITS:	SF	
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershiı Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS AREA: 53								
MATERIAL DESCR	RIPTION:	12"x12" Cream/	Beige Speckled Floo	or Tile-Mastie	C			
MATERIAL LOCAT	ION:	1st, 2nd, 3rd Flo	oor Elevator Areas, I	Rooms 306, 1	123, 127, 111, Off	ice		
MATERIAL QUANT	TTY:	4900			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	6" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, 3rd Floor Elevator Areas		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	HOMOGENEOUS AREA: 54							
MATERIAL DESCR	IPTION:	6" Black Vinyl B	Baseboard					
MATERIAL LOCATI	ION:	1st, 2nd, 3rd Flo	oor Elevator Areas					
MATERIAL QUANT	ITY:	100			MATERIAL UN	ITS:	LF	
DAMAGE QUANTIT	TY:	0			DAMAGE UNIT	S:	LF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55			
MATERIAL DESCRIPTION:	6" Black Vinyl Baseboard Adhes	sive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1st, 2nd, 3rd Floor Elevator Areas		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershiı Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS AREA: 55								
MATERIAL DESCR	IPTION:	6" Black Vinyl B	aseboard Adhesive					
MATERIAL LOCATION: 1st, 2nd, 3rd Floor Elevator Areas								
MATERIAL QUANT	TTY:	100			MATERIAL UNI	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56			
MATERIAL DESCRIPTION:	2x2 Gypsum Ceiling Tile			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	56						
MATERIAL DESCR	RIPTION:	2x2 Gypsum Ce	iling Tile					
MATERIAL LOCAT	ION:	Kitchen						
MATERIAL QUANT	TTY:	800			MATERIAL UN	ITS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57			
MATERIAL DESCRIPTION:	12x12 Tan Mottle Floor Tile			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	No	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

COMMENTS:

DISTURBANCE POTENTIAL:LOWMATERIAL LOCATION:Lunchroom in BasementMATERIAL QUANTITY:2500DAMAGE QUANTITY:0

Inspector's Signature:

MATERIAL UNITS:

DAMAGE UNITS:

SF

SF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Living	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS AREA: 57								
MATERIAL DESCR	IPTION:	12x12 Tan Mottl	e Floor Tile					
MATERIAL LOCAT	ION:	Lunchroom in B	Basement					
MATERIAL QUANT	TTY:	2500			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12x12 Tan Mottle Floor Tile Mas	tic	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:LOWMATERIAL LOCATION:Lunchroom in BasementMATERIAL QUANTITY:2500DAMAGE QUANTITY:0

COMMENTS:

Inspector's Signature:

MATERIAL UNITS:

DAMAGE UNITS:

SF

SF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	58						
MATERIAL DESCR	IPTION:	12x12 Tan Mottl	e Floor Tile Mastic					
MATERIAL LOCAT	ION:	Lunchroom in B	Basement					
MATERIAL QUANT	ITY:	2500			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Lab Counters		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Room 211		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	59						
MATERIAL DESCR	IPTION:	Lab Counters						
MATERIAL LOCATI	ION:	Room 211						
MATERIAL QUANT	ITY:	10			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Tan Rubber Floor Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	NW Entrance		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	60						
MATERIAL DESCR	RIPTION:	Tan Rubber Flo	or Adhesive					
MATERIAL LOCAT	ION:	NW Entrance						
MATERIAL QUANT	TTY:	100			MATERIAL UN	ITS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 310)51	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	AHERA	INSPECTOR:	Marcos Iwankiw	v
SCHOOL NAME:	Pershing West Multiplex	INSPE	CTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDPH L	ICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61			
MATERIAL DESCRIPTION:	Brown Carpet Adhesive			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Multipurpose Room
MATERIAL QUANTITY: 1800 MATERIAL UNITS:
DAMAGE QUANTITY: 0 DAMAGE UNITS:
COMMENTS:

Inspector's Signature:

SF

SF

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	61						
MATERIAL DESCR	IPTION:	Brown Carpet A	dhesive					
MATERIAL LOCAT	ION:	Multipurpose R	oom					
MATERIAL QUANT	TTY:	1800			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62			
MATERIAL DESCRIPTION:	Grey Multipurpose Adhesive			
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Νο	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO):	100-03175			
HOMOGENEOUS A	AREA:	62						
MATERIAL DESCR	RIPTION:	Grey Multipurpo	ose Adhesive					
MATERIAL LOCAT	ION:	Auditorium						
MATERIAL QUANT	TTY:	2000			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63			
MATERIAL DESCRIPTION:	Decorative Plaster			
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NO	D:	100-03175			
HOMOGENEOUS A	AREA:	63						
MATERIAL DESCR	IPTION:	Decorative Plas	ter					
MATERIAL LOCAT	ION:	Auditorium						
MATERIAL QUANT	TTY:	15000			MATERIAL UN	ITS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64			
MATERIAL DESCRIPTION:	Decorative Plaster Ceiling			
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	jo, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershi Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	. Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	64						
MATERIAL DESCR	RIPTION:	Decorative Plas	ter Ceiling					
MATERIAL LOCAT	ION:	Auditorium						
MATERIAL QUANT	TTY:	5000			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for da	amage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	1924 Building 1st, 2nd, and 3rd Corridors		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicage	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershiı Multipl	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S	Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	65						
MATERIAL DESCR	IPTION:	Terrazzo						
MATERIAL LOCAT	ION:	1924 Building 1	st, 2nd, and 3rd Cor	ridors				
MATERIAL QUANT	TTY:	5000			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7	
MATERIAL DESCRIPTION:	12" x 12" Beige w/White Streaks I	Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

1st, 2nd, and 3rd Floor Corridors

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 7		
MATERIAL DESCR	IPTION: 12" x 12" Beig	e w/White Streaks Floor Tile	
MATERIAL LOCATI	ON: 1st, 2nd, and 3	ord Floor Corridors	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8	
MATERIAL DESCRIPTION:	9" x 9" Brown w/White Streaks Fl	oor Tile
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

Room 115

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	s UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: 8		
MATERIAL DESCR	IPTION: 9" x 9" Brown	w/White Streaks Floor Tile	
MATERIAL LOCATI	ON: Room 115		
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Υ:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPEC	CTOR: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION D	ATE: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE	NO: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9	
MATERIAL DESCRIPTION:	9" x 9" Black w/White Streaks Flo	or Tile
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 111, 127

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicage	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershin Multiple	-	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NO):	100-03175	
HOMOGENEOUS A	REA:	9				
MATERIAL DESCR	IPTION:	9" x 9" Black w/	White Streaks Floor	Tile		
MATERIAL LOCATI	ON:	Rooms 111, 127				
MATERIAL QUANT	ITY:				MATERIAL UNI	TS:
DAMAGE QUANTIT	۲:				DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E			
MATERIAL DESCRIPTION:	Boiler #1 Insulation			
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	E						
MATERIAL DESCR	IPTION:	Boiler #1 Insula	tion					
MATERIAL LOCAT	ION:	Boiler Room						
MATERIAL QUANT	TTY:	400			MATERIAL UN	TS:	SF	
DAMAGE QUANTIT	ΓY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F			
MATERIAL DESCRIPTION:	Boiler # 2 Insulation			
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM			
HISTORICAL DAMAGE REASON:				
HISTORICAL RESPONSE ACTION:	Follow O&M Plan			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF
COMMENTS:			

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090		
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston		
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019			
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175			
HOMOGENEOUS A	AREA:	F						
MATERIAL DESCR	RIPTION:	Boiler # 2 Insula	ation					
MATERIAL LOCAT	ION:	Boiler Room						
MATERIAL QUANT	TTY:	400			MATERIAL UN	TS:	SF	
DAMAGE QUANTI	TY:	0			DAMAGE UNIT	S:	SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	н	
MATERIAL DESCRIPTION:	Fittings Off Fiberglass Pipe Insul	ation
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

Fan Rooms and Basement

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS: DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	s UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS A	REA: H		
MATERIAL DESCR	IPTION: Fittings Off Fi	iberglass Pipe Insulation	
MATERIAL LOCATI	ON: Fan Rooms a	nd Basement	
MATERIAL QUANT	ITY:		MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	Al	HERA INSPECTOR:	Marcos Iwankiw	
SCHOOL NAME:	Pershing West Multiplex	IN	SPECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	ID	PH LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I	
MATERIAL DESCRIPTION:	Aircell Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Moderate

MATERIAL LOCATION:

Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium,

Bsmnt Hallway

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

Inspector's Signature:

Date: 12/15/2019

MATERIAL UNITS:

DAMAGE UNITS:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PL	ANNER:	Randy Living	ston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO):	100-03175	
HOMOGENEOUS AREA: I					
MATERIAL DESCR	IPTION: Aircell Pipe Ins	ulation			
MATERIAL LOCATION: Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Hallway					
MATERIAL QUANT	ITY:			MATERIAL UN	ITS:
DAMAGE QUANTIT	Y:			DAMAGE UNIT	TS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J	
MATERIAL DESCRIPTION:	Fittings Off Aircell Pipe Insulation	ı
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Fan Room

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago	o Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicag	o, Illinois	MANAGEMENT PL	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershir Multiple	ng West ex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S.	Calumet	IDPH LICENSE NC):	100-03175	
HOMOGENEOUS A	HOMOGENEOUS AREA: J					
MATERIAL DESCRIPTION: Fittings Off Aircell Pipe Insulation						
MATERIAL LOCATION: Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Fan Room				nchrm, Auditorium, Bsmnt Fan		
MATERIAL QUANTITY: MATERIAL UNITS:				ITS:		
DAMAGE QUANTIT	ΓY:				DAMAGE UNIT	"S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	AH	IERA INSPECTOR:	Marcos Iwankiv	v
SCHOOL NAME:	Pershing West Multiplex	INS	SPECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDI	PH LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	К	
MATERIAL DESCRIPTION:	Mag (Preformed) Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

Basement Corridor and Fan Room

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: Moderate

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS: Not observed 2019

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston	
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175	
HOMOGENEOUS AREA: K				
MATERIAL DESCR	PTION: Mag (Preforme	ed) Pipe Insulation		
MATERIAL LOCATION: Basement Corridor and Fan Ro		ridor and Fan Room		
MATERIAL QUANTITY:			MATERIAL UNITS:	
DAMAGE QUANTIT	Y:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTO	R: Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE	E: 12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO	: 100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L	
MATERIAL DESCRIPTION:	Fittings Off Mag Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

Basement Corridor and Fan Rooms

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

COMMENTS: Not observed 2019

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston	
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175	
HOMOGENEOUS AREA: L				
MATERIAL DESCR	PTION: Fittings Off Ma	ag Pipe Insulation		
MATERIAL LOCATI	ON: Basement Cor	ridor and Fan Rooms		
MATERIAL QUANTITY:			MATERIAL UNITS:	
DAMAGE QUANTIT	Y:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AI	HERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	IN	ISPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	ID	PH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Μ	
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

Boiler Room

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schoo	DIS UNIT NUMBER: 31051	BUIDLING ID: 3090	
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER	Randy Livingston	
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175	
HOMOGENEOUS AREA: M				
MATERIAL DESCR	IPTION: Cardboard I	Pipe Insulation		
MATERIAL LOCATI	ON: Boiler Roon	I		
MATERIAL QUANT	ITY:		MATERIAL UNITS:	
DAMAGE QUANTIT	Y:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw
SCHOOL NAME:	Pershing West Multiplex	INSPECTION DATE:	12/15/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Ν	
MATERIAL DESCRIPTION:	Fittings on Cardboard Pipe Insula	ation
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

Boiler Room

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

COMMENTS:

MATERIAL UNITS:

DAMAGE UNITS:

Inspector's Signature:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public School	S UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PL/	ANNER:	Randy Livings	ston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:		12/23/2019	
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	:	100-03175	
HOMOGENEOUS AREA: N					
MATERIAL DESCRIPTION: Fittings on Cardboard Pipe Insulation					
MATERIAL LOCATION: Boiler Room					
MATERIAL QUANT			MATERIAL UN	TS:	
DAMAGE QUANTIT	Y:			DAMAGE UNIT	S:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	31051	BUIDLING ID:	3090
CITY/STATE:	Chicago, Illinois	AH	IERA INSPECTOR:	Marcos Iwankiv	v
SCHOOL NAME:	Pershing West Multiplex	INS	SPECTION DATE:	12/15/2019	
ADDRESS:	3200 S. Calumet	IDI	PH LICENSE NO:	100-03175	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	0	
MATERIAL DESCRIPTION:	Canvas (Thermal) Pipe Wrap	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

Basement Plenum Chamber

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not observed 2019

Inspector's Signature:

Date: 12/15/2019

MATERIAL UNITS:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	SUNIT NUMBER: 31051	BUIDLING ID: 3090
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Randy Livingston
SCHOOL NAME:	Pershing West Multiplex	REVIEW DATE:	12/23/2019
ADDRESS:	3200 S. Calumet	IDPH LICENSE NO:	100-03175
HOMOGENEOUS AREA: O			
MATERIAL DESCRIPTION: Canvas (Thermal) Pipe Wrap			
MATERIAL LOCATION: Basement Plenum Chamber			
MATERIAL QUANTITY:			MATERIAL UNITS:
DAMAGE QUANTIT	Y:		DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



ASBESTOS IDPH PROFESSIONAL LICENSE

ID NUMBER 100 - 01934 ISSUED 11/5/2019

EXPIRES 05/15/2020

RANDOLPH LIVINGSTON 9549 S. EUCLID AVE CHICAGO, IL 60617 Environmental Health



ENDORSEMENTS

INSPECTOR

TC EXPIRES

2/6/2020 MANAGEMENT PLANNER 10/24/2020 PROJECT MANAGER 3/4/2019 AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

	CODE	KEY
MATERIAL MATERIAL CATEGORY	ACBM	Asbestos Containing Building Materials
	MISC	Miscellaneous
	SURF	Surfacing
MATERIAL UNITS	TSI	Thermal System Insulation
	LF	Linear Feet
	SF	Square Feet
DAMAGE TYPE	CF	Cubic Feet
	Loc	Localized
	Dist	Distributed

Three-Year Reinspection Key to Terms