

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2304
SCHOOL NAME: Kozminski Academy
ADDRESS OF SCHOOL: 936 E. 54th St.
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/23/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 265
IDPH INSPECTOR LICENSE NUMBER: 100-04437
IDPH LICENSED INSPECTOR NAME(Please Print): Mary Hicks
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: N

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Kozminski Academy

936 E. 54th St.
Chicago, IL, 60615

Unit: 31151
Building ID: 4390

IDPH ID Number: 14-016-2990-2304

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 11, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31151 Region: 04 IDPH ID:14-016-2990-2304

School: Kozminski Academy Building ID: 4390

Address: 936 E. 54th St.

Chicago, IL, 60615

Building Contact: Durham, Dwayne

Contact Phone:773 706 7673

Current Building Owners: Chicago Public Schools

Review Date: 04/20/2019

Inspector: Mary Hicks

Inspector IDPH License: 100-04437

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 11, 2019

RE: Kozminski Academy, Unit 31151
936 E. 54th St.
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Kozminski Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Kozminski Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Kozminski Academy Unit: 31151 Region: 04
Address: 936 E. 54th St. Chicago, IL, 60615
IDPH ID: 14-016-2990-2304 Building ID: 4390
Contact: Durham, Dwayne Phone: 773 706 7673

2. Description of Facility

Original Construction: 1897 Additional Construction: 1929
Total Square Footage: 63345 No of Floors: 3
Current Occupancy: 265

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, Il, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Mary Hicks

Inspector IDPH license # 100-04437

Signature:
Date: 4/11/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 04/20/2019

7. Review Date:04/20/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Kozminski Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4390:

003 D	12" x 12" Multi-Brown Floor Tile
047	Brown Carpet Mastic
103	9" x 9" Tan w/ Black Specks Floor Tile
104	Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile
B	Joint Insulation off Fiberglass Pipe Insulation
C	Cardboard Pipe Insulation
D	Joint Insulation off Cardboard Pipe Insulation

B. The following new homogenous areas have been identified for Building 4390:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

003 G	12" x 12" Black Floor Tile w/White Streaks
003 H	12" x 12" White Floor Tile
003 I	12" x 12" Light Brown Floor Tile
003 J	12" x 12" White Floor Tile
008 B	12" x 12" Tan Floor Tile
031	1' x 1' Ceiling Tiles
035	Tan & Brown Ceramic Tile Grout
044	Black Slate Material
046	Brown Carpet Mastic
047	Brown Carpet Mastic
048	Purple Carpet Mastic
049	2" Square Ceramic Tile Grout
050	Fire Brick in Incinerator
051	Fire Door Insulation
057	Flashings on Roof B - Not AHERA
080	12" x 12" Beige Floor Tile w/ White Streaks
081	12" x 12" Beige Floor Tile w/ White Streaks Mastic
083	1' x 1' Ceiling Tile Mastic
084	12"x12" Black w/Gray Specks Floor Tile (Patch)
085	12"x12" Black w/Gray Specks Floor Tile Mastic
086	2'x1' Black Border Tile
087	2'x1' Black Border Tile Mastic
088	Blackboards
093	Sink Undercoating
094	12"x12" White/Gray Mix Floor Tile
095	12"x12" White/Gray Mix Floor Tile Mastic
096	12"x12" Beige w/Red Streaks Floor Tile
097	12"x12" Beige w/Red Streaks Floor Tile Mastic
098	Blue Carpet Adhesive
099	12" x 12" Grey w/ Dk. Grey/White streaks floor tile
100	Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile
101	Blackboard Adhesive
102	Grey Carpet Adhesive
103	9" x 9" Tan w/ Black Specks Floor Tile
104	Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile
K	Glue Under Rubber Floor

The following areas were deemed to be inaccessible:

003 C	Tile Beneath 12" x 12" Brown Floor Tile
005	12" x 12" Brown Floor Tile Mastic
006	Floor Tile Mastic For Tile Beneath 12" x 12" Brown
008 C	12" x 12" Tan Floor Tile Mastic
044	Black Slate Material
047	Brown Carpet Mastic
050	Fire Brick in Incinerator
081	12" x 12" Beige Floor Tile w/ White Streaks Mastic
083	1' x 1' Ceiling Tile Mastic
098	Blue Carpet Adhesive
100	Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile
102	Grey Carpet Adhesive
104	Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile
K	Glue Under Rubber Floor

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mary Hicks, IDPH License # 100-04437. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Kozminski Academy Building 4390 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001 A	Plaster Walls and Ceilings			1896 Building	NO_ACBM									
001 B	Plaster Walls and Ceilings			1927 Building	NO_ACBM									
003 A	12" x 12" White Floor Tile w/ Gray Streaks	34,500	SF	Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 B	12" x 12" Brown Floor Tile	20	SF	Closet Across from 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 C	Tile Beneath 12" x 12" Brown Floor Tile	20	SF	Closet Across from 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 D	12" x 12" Multi-Brown Floor Tile	1,738	SF	Rooms 106 and 208	CHR	MISC	N	LOC	50		Yes	ACBM with the potential for damage	2	MODERATE
003 E	12" x 12" Black Floor Tile	1,440	SF	Auditorium	CHR	MISC	N	LOC	50		No	ACBM with the potential for damage	2	MODERATE
003 F	12" x 12" Brown Floor Tile	1,440	SF	Auditorium	CHR	MISC	N	LOC	100		No	Damaged or significantly damaged friable misc. ACBM	2	MODERATE
003 G	12" x 12" Black Floor Tile w/White Streaks	1,400	SF	Auditorium	ASSUMED	MISC	N	DIST	100		No	ACBM with the potential for damage	5	LOW
003 H	12" x 12" White Floor Tile	800	SF	Room 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 I	12" x 12" Light Brown Floor Tile	80	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003 J	12" x 12" White Floor Tile	80	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004	12" x 12" White Floor Tile w/Gray Streaks Mastic	34,500	SF	Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways	CHR	MISC	N	DIST	20		No	ACBM with the potential for damage	3	LOW
005	12" x 12" Brown Floor Tile Mastic	20	SF	Closet Across from 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006	Floor Tile Mastic For Tile Beneath 12" x 12" Brown	20	SF	Custodial Closet Across From 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007	12" x 12" Multi-Brown Floor Tile Mastic	1,738	SF	Rooms 208 and 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008	12" x 12" Black Floor Tile Mastic	620	SF	Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 B	12" x 12" Tan Floor Tile	100	SF	2nd Floor Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008 C	12" x 12" Tan Floor Tile Mastic	100	SF	2nd Floor Lobby	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
059	Roof A Core - Not AHERA			Third Elevation Roof	NO_ACBM									
060	Roof Core - Not AHERA			Second Elevation Roof	NO_ACBM									
061	Roof Flashing - Not AHERA			Second Elevation Roof B	CHR	MISC								
062	Roof Flashing - Not AHERA			Second Elevation Roof C	CHR	MISC								
063	Roof Core - Not AHERA			Second Elevation Roof C	NO_ACBM									
064	Roof Core - Not AHERA			Second Elevation Roof D	NO_ACBM									
065	Roof Flashing - Not AHERA			Second Elevation Roof D	NO_ACBM									
066	Roof Sealant - Not AHERA			1896 Building	CHR	MISC								
067	Roof Sealant- Not AHERA			1928 Building	CHR	MISC								
068	Roof Flashing - Not AHERA			First Elevation Roof F	CHR	MISC								
069	Roof Core - Not AHERA			First Elevation Roof F	NO_ACBM									
070	Roof Flashing - Not AHERA			First Elevation Roof E	CHR	MISC								
071	Roof Tile - Not AHERA			First Elevation Roof E	NO_ACBM									
072	Roof Sealant - Not AHERA			First Elevation Roof	CHR	MISC								
073	Roof Tile - Not AHERA			Roof B	NO_ACBM									
074	Roof Tile - Not AHERA			Roof D	CHR	MISC								
075	Roof Tile - Not AHERA			Roof 7	NO_ACBM									
076	Exterior Window Caulk - Not AHERA			1896 Building	NO_ACBM									
080	12" x 12" Beige Floor Tile w/ White Streaks	500	SF	Rooms 202, 301, and 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
081	12" x 12" Beige Floor Tile w/ White Streaks Mastic	150	SF	Rooms 202, 301, and 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
082	Lab Counter and Sink	50	SF	Room 303	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
083	1' x 1' Ceiling Tile Mastic	50	SF	Music Room (Room 310)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
084	12"x12" Black w/Gray Specks Floor Tile (Patch)	55	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
085	12"x12" Black w/Gray Specks Floor Tile Mastic	55	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
086	2'x1' Black Border Tile	170	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
087	2'x1' Black Border Tile Mastic	170	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
088	Blackboards	5,000	SF	006, 008, 101-104, 106-109, 201-210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
089	12"x12" Gray Mix Floor Tile			Material Not Present	ABATED	MISC		None						High
090	12"x12" Gray Mix Floor Tile Mastic			Material Not Present	ABATED	MISC		None						Low
091	12"x12" Beige w/Gray Speckles Floor Tile			Material Not Present	ABATED	MISC		None						High
092	12"x12" Beige w/Gray Speckles Floor Tile Mastic			Material Not Present	ABATED	MISC		None						Low
093	Sink Undercoating	15	SF	Room 006	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
094	12"x12" White/Gray Mix Floor Tile	900	SF	Room 202	ASSUMED	MISC	N	LOC	100		No	ACBM with the potential for damage	2	LOW
095	12"x12" White/Gray Mix Floor Tile Mastic	900	SF	Room 202	ASSUMED	MISC	N	LOC	100		No	ACBM with the potential for damage	2	LOW
096	12"x12" Beige w/Red Streaks Floor Tile	535	SF	Room 301, South Door Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
097	12"x12" Beige w/Red Streaks Floor Tile Mastic	535	SF	Room 301, South Door Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
098	Blue Carpet Adhesive	200	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
099	12" x 12" Grey w/Dk. Grey/White streaks floor tile	150	SF	Kitchen office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile	150	SF	Kitchen Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	Blackboard Adhesive	5,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	Grey Carpet Adhesive	500	SF	Room 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	9" x 9" Tan w/ Black Specks Floor Tile	87	SF	Vault in Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
104	Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile	87	SF	Vault in Main Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Fiberglass Pipe Insulation			Throughout Building	NO_ACBM									
B	Joint Insulation off Fiberglass Pipe Insulation	240	LF	1896 Construction	CHR	TSI	Y	LOC	6		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
C	Cardboard Pipe Insulation	160	LF	Basement Tank Room	CHR	TSI	Y	LOC	6		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D	Joint Insulation off Cardboard Pipe	20	LF	Tank Room	CHR	TSI	Y	LOC	12		Yes	Damaged or	3	MODERATE

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Insulation											significantly damaged friable thermal system insulating ACBM		
E	Aircell Pipe Insulation	1,500	LF	Basement	CHR	TSI	Y	LOC	80		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
F	Joint Insulation off Aircell Pipe Insulation	100	LF	Basement	CHR	TSI	Y	LOC	15		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
G 1	Boiler Insulation			Boiler Room by Outside Door	NO_ACBM									
G 2	Boiler Insulation			Boiler Room by Inside Door	NO_ACBM									
K	Glue Under Rubber Floor	3,000	SF	Kitchen, Lunchroom, West Lunchroom Entrance Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/11/2019
Inspector Name Mary Hicks
100-04437 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001 A	
001 B	
003 A	
003 B	
003 C	
003 D	Damage located in rooms 106 and 208
003 E	Damage located in auditorium
003 F	Damage located in auditorium
003 G	
003 H	
003 I	
003 J	
004	Damage located in room 306 closet
005	
006	
007	
008	
008 B	
008 C	
009	Damage located in auditorium
010	
011	
012	

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	Not observed
027	Not observed, damage located in room 004
028	Not observed
029	
030	
031	
032	
033	Not observed
034	
035	
036	
037	
038	
039	
040	
041	

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
071	
072	
073	
074	
075	
076	
080	
081	
082	
083	
084	
085	
086	
087	
088	
089	Not observed
090	Not observed
091	Not observed
092	Not observed
093	
094	
095	Sample to determine asbestos content, remove damaged ACBM
096	
097	
098	
099	
100	
101	
102	

Chicago Public Schools

School Kozminski Academy Unit 31151 Building ID 4390

Address 936 E. 54th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
103	
104	
A	
B	
C	
D	
E	
F	
G 1	
G 2	
K	

Table II

Management Planner's Review

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001 A	Plaster Walls and Ceilings			1896 Building	No ACBM						
001 B	Plaster Walls and Ceilings			1927 Building	No ACBM						
003 A	12" x 12" White Floor Tile w/ Gray Streaks	34,500	SF	Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 B	12" x 12" Brown Floor Tile	20	SF	Closet Across from 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 C	Tile Beneath 12" x 12" Brown Floor Tile	20	SF	Closet Across from 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 D	12" x 12" Multi-Brown Floor Tile	1,738	SF	Rooms 106 and 208	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Remove
003 E	12" x 12" Black Floor Tile	1,440	SF	Auditorium	Chrysotile	MISC	No	50	SF	6 ACBM with the potential for damage	Remove
003 F	12" x 12" Brown Floor Tile	1,440	SF	Auditorium	Chrysotile	MISC	No	100	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
003 G	12" x 12" Black Floor Tile w/White Streaks	1,400	SF	Auditorium	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Remove
003 H	12" x 12" White Floor Tile	800	SF	Room 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 I	12" x 12" Light Brown Floor Tile	80	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
003 J	12" x 12" White Floor Tile	80	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	12" x 12" White Floor Tile w/Gray Streaks Mastic	34,500	SF	Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Follow O&M Plan
005	12" x 12" Brown Floor Tile Mastic	20	SF	Closet Across from 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006	Floor Tile Mastic For Tile Beneath 12" x 12" Brown	20	SF	Custodial Closet Across From 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
007	12" x 12" Multi-Brown Floor Tile Mastic	1,738	SF	Rooms 208 and 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008	12" x 12" Black Floor Tile Mastic	620	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 B	12" x 12" Tan Floor Tile	100	SF	2nd Floor Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008 C	12" x 12" Tan Floor Tile Mastic	100	SF	2nd Floor Lobby	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
009	12" x 12" Brown Floor Tile Mastic	1,440	SF	Auditorium	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Remove
010	12" x 12" Black Floor Tile w/White Streaks Mastic	620	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
011	12" x 12" White Floor Tile Mastic			Room 311	No ACBM						
012	12" x 12" Light Brown Floor Tile Mastic			Engineer's Office	No ACBM	MISC					
013	12" x 12" White Floor Tile Mastic			Engineer's Office	No ACBM						
014	Cementitious Patches on Walls			Boiler Room	No ACBM						
015	Large Stone Mortar			Boiler Room and Coal Room	No ACBM						
016	6" Black Vinyl Baseboard			Throughout Facility	No ACBM						
017	6" Black Vinyl Baseboard Mastic			Throughout Facility	No ACBM						

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
018	4" Black Baseboard			Throughout Classrooms	No ACBM						
019	4" Black Baseboard Mastic			Throughout Classrooms	No ACBM						
020	4" Gray Vinyl Baseboard			Room 311	No ACBM						
021	4" Gray Vinyl Baseboard Mastic			Room 311	No ACBM						
022	Interior Brick			Basement	No ACBM						
023	Interior Brick Mortar			Basement	No ACBM						
024	Cinder Block Mortar			Basement	No ACBM						
025	Window Glazing			Throughout 1896 Construction	No ACBM						
026	Window Glazing	2,500	LF	Throughout 1928 Construction	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
027	Material Beneath 12"x12" Floor Tile	725	SF	Room 004 (Parents Room)	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
028	Material Beneath Floor Tiles			Room 106	No ACBM						
029	Orange Floor Leveler			Auditorium	No ACBM						
030	2' x 4' Ceiling Panels			Room 311	No ACBM						
031	1' x 1' Ceiling Tiles	800	SF	Room 310	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
032	Terrazzo Wall Panels			Washrooms Throughout Facility	No ACBM						
033	Finished Brick Mortar			Throughout Facility	No ACBM						
034	Tan Ceramic Tile Grout			Washrooms and Rear Exit	No ACBM						
035	Tan & Brown Ceramic Tile Grout	400	SF	Washrooms & Hall by Student Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036	Terrazzo			1928 Stairways & Corridors	No ACBM						
037	Brown & Tan Terrazzo			Auditorium Entry & Stairs	No ACBM						
038	Green Terrazzo			Auditorium and Vestibule	No ACBM						
039	Insulation Over Fiberglass Insulation	10	LF	Boiler Room on Wall by Sink	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
040	Wrap on Insulation Over Fiberglass Pipe Insulation	4	LF	Boiler Room on Wall by Sink	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
041	Drywall			Room 210 and 211	No ACBM						
042	Gray Window Caulk			Throughout Building as Patches on Windows	No ACBM						
043	Black Marker Boards			Classrooms	No ACBM						
044	Black Slate Material	210	SF	Classrooms Under Beneath Various Marker Boards Including Those in Rooms 106, 108 & 109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
045	Asphalt Flooring			1896 Stairs and Landings	No ACBM						
046	Brown Carpet Mastic			Kitchen Office	Assumed	MISC					
047	Brown Carpet Mastic	100	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
048	Purple Carpet Mastic	500	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
049	2" Square Ceramic Tile Grout	160	SF	Boy's Washrooms Under Urinals	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
050	Fire Brick in Incinerator	150	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
051	Fire Door Insulation	408	SF	Entrances, Exits, Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
052	Exterior Brick Mortar - Not AHERA			1896 Building	No ACBM						
053	Exterior Brick - Not AHERA			1896 Building	No ACBM	MISC					
054	Exterior Brick Mortar - Not AHERA			1928 Building	No ACBM						
055	Exterior Brick - Not AHERA			1928 Building	No ACBM						
056	Exterior Window Caulk - Not AHERA			1928 Building	Chrysotile	MISC					
057	Flashings on Roof B - Not AHERA			Third Elevation Roof	Assumed	MISC					
058	Flashing on Roof C- Not AHERA			Third Elevation Roof	Chrysotile	MISC					
059	Roof A Core - Not AHERA			Third Elevation Roof	No ACBM						
060	Roof Core - Not AHERA			Second Elevation Roof	No ACBM						
061	Roof Flashing - Not AHERA			Second Elevation Roof B	Chrysotile	MISC					
062	Roof Flashing - Not AHERA			Second Elevation Roof C	Chrysotile	MISC					
063	Roof Core - Not AHERA			Second Elevation Roof C	No ACBM						
064	Roof Core - Not AHERA			Second Elevation Roof D	No ACBM						
065	Roof Flashing - Not AHERA			Second Elevation Roof D	No ACBM						
066	Roof Sealant - Not AHERA			1896 Building	Chrysotile	MISC					
067	Roof Sealant- Not AHERA			1928 Building	Chrysotile	MISC					
068	Roof Flashing - Not AHERA			First Elevation Roof F	Chrysotile	MISC					
069	Roof Core - Not AHERA			First Elevation Roof F	No ACBM						
070	Roof Flashing - Not AHERA			First Elevation Roof E	Chrysotile	MISC					
071	Roof Tile - Not AHERA			First Elevation Roof E	No ACBM						
072	Roof Sealant - Not AHERA			First Elevation Roof	Chrysotile	MISC					
073	Roof Tile - Not AHERA			Roof B	No ACBM						
074	Roof Tile - Not AHERA			Roof D	Chrysotile	MISC					
075	Roof Tile - Not AHERA			Roof 7	No ACBM						
076	Exterior Window Caulk - Not AHERA			1896 Building	No ACBM						
080	12" x 12" Beige Floor Tile w/ White Streaks	500	SF	Rooms 202, 301, and 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
081	12" x 12" Beige Floor Tile w/ White Streaks	150	SF	Rooms 202, 301, and 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic										
082	Lab Counter and Sink	50	SF	Room 303	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
083	1' x 1' Ceiling Tile Mastic	50	SF	Music Room (Room 310)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
084	12"x12" Black w/Gray Specks Floor Tile (Patch)	55	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
085	12"x12" Black w/Gray Specks Floor Tile Mastic	55	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
086	2'x1' Black Border Tile	170	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
087	2'x1' Black Border Tile Mastic	170	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
088	Blackboards	5,000	SF	006, 008, 101-104, 106-109, 201-210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
089	12"x12" Gray Mix Floor Tile			Material Not Present	Abated	MISC					
090	12"x12" Gray Mix Floor Tile Mastic			Material Not Present	Abated	MISC					
091	12"x12" Beige w/Gray Speckles Floor Tile			Material Not Present	Abated	MISC					
092	12"x12" Beige w/Gray Speckles Floor Tile Mastic			Material Not Present	Abated	MISC					
093	Sink Undercoating	15	SF	Room 006	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
094	12"x12" White/Gray Mix Floor Tile	900	SF	Room 202	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
095	12"x12" White/Gray Mix Floor Tile Mastic	900	SF	Room 202	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
096	12"x12" Beige w/Red Streaks Floor Tile	535	SF	Room 301, South Door Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
097	12"x12" Beige w/Red Streaks Floor Tile Mastic	535	SF	Room 301, South Door Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
098	Blue Carpet Adhesive	200	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
099	12" x 12" Grey w/ Dk. Grey/White streaks floor tile	150	SF	Kitchen office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile	150	SF	Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Blackboard Adhesive	5,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Grey Carpet Adhesive	500	SF	Room 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	9" x 9" Tan w/ Black Specks Floor Tile	87	SF	Vault in Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile	87	SF	Vault in Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Fiberglass Pipe Insulation			Throughout Building	No ACBM						
B	Joint Insulation off Fiberglass Pipe Insulation	240	LF	1896 Construction	Chrysotile	TSI	Yes	6	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
C	Cardboard Pipe Insulation	160	LF	Basement Tank Room	Chrysotile	TSI	Yes	6	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
D	Joint Insulation off Cardboard Pipe Insulation	20	LF	Tank Room	Chrysotile	TSI	Yes	12	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
E	Aircell Pipe Insulation	1,500	LF	Basement	Chrysotile	TSI	Yes	80	LF	1 Damaged or significantly damaged	Remove

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										friable thermal system insulating ACBM	
F	Joint Insulation off Aircell Pipe Insulation	100	LF	Basement	Chrysotile	TSI	Yes	15	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
G 1	Boiler Insulation			Boiler Room by Outside Door	No ACBM						
G 2	Boiler Insulation			Boiler Room by Inside Door	No ACBM						
K	Glue Under Rubber Floor	3,000	SF	Kitchen, Lunchroom, West Lunchroom Entrance Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Kozminski Academy

Unit 31151

Building ID 4390

Address 936 E. 54th St.

Chicago, IL, 60615

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	04/20/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
001 A	
001 B	
003 A	
003 B	
003 C	
003 D	Remove Damaged Material
003 E	Remove Damaged Material
003 F	Remove Damaged Material
003 G	Sample to determine asbestos content, remove damaged ACBM
003 H	
003 I	
003 J	
004	
005	
006	
007	
008	
008 B	
008 C	
009	Remove Damaged Material
010	
011	
012	
013	
014	

Chicago Public Schools

School Kozminski Academy
Address 936 E. 54th St.

Unit 31151
Chicago, IL, 60615

Building ID 4390
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	Repair or Remove Damaged Material
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	

Chicago Public Schools

School Kozminski Academy
Address 936 E. 54th St.

Unit 31151
Chicago, IL, 60615

Building ID 4390
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	

Chicago Public Schools

School Kozminski Academy
Address 936 E. 54th St.

Unit 31151
 Chicago, IL, 60615

Building ID 4390
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
067	
068	
069	
070	
071	
072	
073	
074	
075	
076	
080	
081	
082	
083	
084	
085	
086	
087	
088	
089	
090	
091	
092	
093	
094	Sample to determine asbestos content, remove damaged ACBM
095	

Chicago Public Schools

School Kozminski Academy
Address 936 E. 54th St.

Unit 31151
 Chicago, IL, 60615

Building ID 4390
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
096	
097	
098	
099	
100	
101	
102	
103	
104	
A	
B	Remove or Repair Damage
C	Remove or Repair Damage Material
D	Remove or Repair Damaged Material
E	Remove or Repair Damaged Material
F	Remove or Repair Damaged Material
G 1	
G 2	
K	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001 A**
MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **001 A**

MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001 B**
MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1927 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **001 B**

MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**

MATERIAL LOCATION: **1927 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways**

MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 A**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks**
MATERIAL LOCATION: **Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 B**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Closet Across from 303**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 B**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Closet Across from 303**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 C**
MATERIAL DESCRIPTION: **Tile Beneath 12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Closet Across from 303**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 C**

MATERIAL DESCRIPTION: **Tile Beneath 12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Closet Across from 303**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 D**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Delamination**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Rooms 106 and 208**
MATERIAL QUANTITY: **1738** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in rooms 106 and 208**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 D**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile**
MATERIAL LOCATION: **Rooms 106 and 208**
MATERIAL QUANTITY: **1738** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 E**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in auditorium**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 E**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 F**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in auditorium**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 F**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 G**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 G**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 H**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 311**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 H**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Room 311**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 I**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 I**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003 J**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **003 J**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in room 306 closet**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Gray Streaks Mastic**
MATERIAL LOCATION: **Rooms 002-008, 101, 102, 107-111, 201-207, 209-211, 301-310, Main Office and all Hallways**
MATERIAL QUANTITY: **34500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Closet Across from 303**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Closet Across from 303**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Floor Tile Mastic For Tile Beneath 12" x 12" Brown**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Custodial Closet Across From 303**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **Floor Tile Mastic For Tile Beneath 12" x 12" Brown**
MATERIAL LOCATION: **Custodial Closet Across From 303**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208 and 106**
MATERIAL QUANTITY: **1738** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Multi-Brown Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 208 and 106**
MATERIAL QUANTITY: **1738** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 B**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Lobby**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **008 B**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
MATERIAL LOCATION: **2nd Floor Lobby**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008 C**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Lobby**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **008 C**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Lobby**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in auditorium**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **1440** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/White Streaks Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **620** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **Cementitious Patches on Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **014**

MATERIAL DESCRIPTION: **Cementitious Patches on Walls**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Large Stone Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room and Coal Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Large Stone Mortar**
MATERIAL LOCATION: **Boiler Room and Coal Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **4" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **4" Black Baseboard**
MATERIAL LOCATION: **Throughout Classrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **019**

MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **020**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **022**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **024**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1896 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **025**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Throughout 1896 Construction**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1928 Construction**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **Window Glazing**
MATERIAL LOCATION: **Throughout 1928 Construction**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **Material Beneath 12"x12" Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 004 (Parents Room)**
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS: **Not observed, damage located in room 004**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **Material Beneath 12"x12" Floor Tile**
MATERIAL LOCATION: **Room 004 (Parents Room)**
MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repair or Remove Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **Material Beneath Floor Tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **028**

MATERIAL DESCRIPTION: **Material Beneath Floor Tiles**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **Orange Floor Leveler**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **Orange Floor Leveler**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **030**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Room 311**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **Terrazzo Wall Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **Terrazzo Wall Panels**

MATERIAL LOCATION: **Washrooms Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **Finished Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **033**

MATERIAL DESCRIPTION: **Finished Brick Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms and Rear Exit**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**
MATERIAL LOCATION: **Washrooms and Rear Exit**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Tan & Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms & Hall by Student Lunchroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **Tan & Brown Ceramic Tile Grout**
MATERIAL LOCATION: **Washrooms & Hall by Student Lunchroom**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1928 Stairways & Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **1928 Stairways & Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **Brown & Tan Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Entry & Stairs**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **Brown & Tan Terrazzo**

MATERIAL LOCATION: **Auditorium Entry & Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Green Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium and Vestibule**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **Green Terrazzo**
MATERIAL LOCATION: **Auditorium and Vestibule**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Insulation Over Fiberglass Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room on Wall by Sink**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **Insulation Over Fiberglass Insulation**
MATERIAL LOCATION: **Boiler Room on Wall by Sink**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Wrap on Insulation Over Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room on Wall by Sink**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **Wrap on Insulation Over Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Boiler Room on Wall by Sink**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210 and 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 210 and 211**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Gray Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building as Patches on Windows**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **Gray Window Caulk**
MATERIAL LOCATION: **Throughout Building as Patches on Windows**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **Black Marker Boards**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **Black Marker Boards**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Black Slate Material**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms Under Beneath Various Marker Boards Including Those in Rooms 106, 108 & 109**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **Black Slate Material**
MATERIAL LOCATION: **Classrooms Under Beneath Various Marker Boards Including Those in Rooms 106, 108 & 109**
MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Asphalt Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Stairs and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **Asphalt Flooring**

MATERIAL LOCATION: **1896 Stairs and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **2" Square Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boy's Washrooms Under Urinals**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **2" Square Ceramic Tile Grout**
MATERIAL LOCATION: **Boy's Washrooms Under Urinals**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Fire Brick in Incinerator**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Fire Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Entrances, Exits, Boiler Room**
MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Entrances, Exits, Boiler Room**

MATERIAL QUANTITY: **408** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **052**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **053**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
MATERIAL LOCATION: **1928 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**
MATERIAL LOCATION: **1928 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Flashings on Roof B - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Elevation Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **Flashings on Roof B - Not AHERA**

MATERIAL LOCATION: **Third Elevation Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Flashing on Roof C- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Elevation Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **Flashing on Roof C- Not AHERA**

MATERIAL LOCATION: **Third Elevation Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Roof A Core - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Elevation Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Roof A Core - Not AHERA**
MATERIAL LOCATION: **Third Elevation Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Roof Core - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **060**

MATERIAL DESCRIPTION: **Roof Core - Not AHERA**

MATERIAL LOCATION: **Second Elevation Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **061**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Second Elevation Roof B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof C**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Second Elevation Roof C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Roof Core - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof C**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **Roof Core - Not AHERA**

MATERIAL LOCATION: **Second Elevation Roof C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **Roof Core - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof D**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **Roof Core - Not AHERA**
MATERIAL LOCATION: **Second Elevation Roof D**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Elevation Roof D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
MATERIAL LOCATION: **Second Elevation Roof D**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **Roof Sealant - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **066**

MATERIAL DESCRIPTION: **Roof Sealant - Not AHERA**

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **Roof Sealant- Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **067**

MATERIAL DESCRIPTION: **Roof Sealant- Not AHERA**

MATERIAL LOCATION: **1928 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Elevation Roof F**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **068**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **First Elevation Roof F**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Roof Core - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Elevation Roof F**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **069**

MATERIAL DESCRIPTION: **Roof Core - Not AHERA**

MATERIAL LOCATION: **First Elevation Roof F**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Elevation Roof E**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **070**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **First Elevation Roof E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **071**
MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Elevation Roof E**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **071**

MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**

MATERIAL LOCATION: **First Elevation Roof E**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **072**
MATERIAL DESCRIPTION: **Roof Sealant - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Elevation Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **072**

MATERIAL DESCRIPTION: **Roof Sealant - Not AHERA**

MATERIAL LOCATION: **First Elevation Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **073**
MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **073**

MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**

MATERIAL LOCATION: **Roof B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**
MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **074**

MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**

MATERIAL LOCATION: **Roof D**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**
MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof 7**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **075**

MATERIAL DESCRIPTION: **Roof Tile - Not AHERA**

MATERIAL LOCATION: **Roof 7**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **076**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION: **1896 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 202, 301, and 308**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **080**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Rooms 202, 301, and 308**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 202, 301, and 308**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **081**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks Mastic**
MATERIAL LOCATION: **Rooms 202, 301, and 308**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **Lab Counter and Sink**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 303**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **082**
MATERIAL DESCRIPTION: **Lab Counter and Sink**
MATERIAL LOCATION: **Room 303**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Music Room (Room 310)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **083**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**
MATERIAL LOCATION: **Music Room (Room 310)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **12"x12" Black w/Gray Specks Floor Tile (Patch)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **084**
MATERIAL DESCRIPTION: **12"x12" Black w/Gray Specks Floor Tile (Patch)**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **12"x12" Black w/Gray Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **085**
MATERIAL DESCRIPTION: **12"x12" Black w/Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **55** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **2'x1' Black Border Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **086**
MATERIAL DESCRIPTION: **2'x1' Black Border Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **2'x1' Black Border Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **087**
MATERIAL DESCRIPTION: **2'x1' Black Border Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **Blackboards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **006, 008, 101-104, 106-109, 201-210**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **088**
MATERIAL DESCRIPTION: **Blackboards**
MATERIAL LOCATION: **006, 008, 101-104, 106-109, 201-210**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **089**
MATERIAL DESCRIPTION: **12"x12" Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **089**

MATERIAL DESCRIPTION: **12"x12" Gray Mix Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **12"x12" Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **090**

MATERIAL DESCRIPTION: **12"x12" Gray Mix Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **091**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **High**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **091**

MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Speckles Floor Tile**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **092**
MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **092**

MATERIAL DESCRIPTION: **12"x12" Beige w/Gray Speckles Floor Tile Mastic**

MATERIAL LOCATION: **Material Not Present**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Sink Undercoating**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 006**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **093**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Room 006**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **12"x12" White/Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **094**
MATERIAL DESCRIPTION: **12"x12" White/Gray Mix Floor Tile**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **12"x12" White/Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Delamination
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS: **Sample to determine asbestos content, remove damaged ACBM**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **095**
MATERIAL DESCRIPTION: **12"x12" White/Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **12"x12" Beige w/Red Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301, South Door Vestibule**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **096**
MATERIAL DESCRIPTION: **12"x12" Beige w/Red Streaks Floor Tile**
MATERIAL LOCATION: **Room 301, South Door Vestibule**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **12"x12" Beige w/Red Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 301, South Door Vestibule**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **097**
MATERIAL DESCRIPTION: **12"x12" Beige w/Red Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 301, South Door Vestibule**
MATERIAL QUANTITY: **535** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **098**
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **12" x 12" Grey w/ Dk. Grey/White streaks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **099**
MATERIAL DESCRIPTION: **12" x 12" Grey w/ Dk. Grey/White streaks floor tile**
MATERIAL LOCATION: **Kitchen office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Mastic with 12" x 12" Grey w/ Dk. Grey/White streaks floor tile**
MATERIAL LOCATION: **Kitchen Office**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Blackboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Blackboard Adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Grey Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Grey Carpet Adhesive**
MATERIAL LOCATION: **Room 310**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Tan w/ Black Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Vault in Main Office**
MATERIAL QUANTITY: **87** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Tan w/ Black Specks Floor Tile**
MATERIAL LOCATION: **Vault in Main Office**
MATERIAL QUANTITY: **87** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Vault in Main Office**

MATERIAL QUANTITY: **87**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **Mastic Associated w/ 9" x 9" Tan w/ Black Specks Floor Tile**
MATERIAL LOCATION: **Vault in Main Office**
MATERIAL QUANTITY: **87** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Joint Insulation off Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1896 Construction**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Joint Insulation off Fiberglass Pipe Insulation**
MATERIAL LOCATION: **1896 Construction**
MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damage

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement Tank Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
MATERIAL LOCATION: **Basement Tank Room**
MATERIAL QUANTITY: **160** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damage Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Joint Insulation off Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Tank Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **12** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Joint Insulation off Cardboard Pipe Insulation**

MATERIAL LOCATION: **Tank Room**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **12**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Physical Damage Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **80** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **80** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joint Insulation off Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Joint Insulation off Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Remove or Repair Damaged Material

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUILDING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G 1**
MATERIAL DESCRIPTION: **Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room by Outside Door**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **G 1**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **Boiler Room by Outside Door**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G 2**
MATERIAL DESCRIPTION: **Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room by Inside Door**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **G 2**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **Boiler Room by Inside Door**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mary Hicks**
SCHOOL NAME: **Kozminski Academy** INSPECTION DATE: **4/11/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Glue Under Rubber Floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, Lunchroom, West Lunchroom Entrance Hall**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31151** BUIDLING ID: **4390**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Kozminski Academy** REVIEW DATE: **4/20/2019**
ADDRESS: **936 E. 54th St.** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **Glue Under Rubber Floor**
MATERIAL LOCATION: **Kitchen, Lunchroom, West Lunchroom Entrance Hall**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION


APPENDIX B

Inspector and Management Planner Licenses

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 04437

ISSUED
4/15/2019

EXPIRES
05/15/2020

MARY H HICKS
12823 S GREEN
CHICAGO, IL 60643

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/18/2020

MANAGEMENT PLANNER

3/18/2020

PROJECT MANAGER

4/27/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS
has completed the Asbestos Management Planner Refresher course and passed the examination
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR05

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

N. Penoff dtd

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-011

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR08

Certificate Number:



PUBLIC HEALTH & SAFETY inc.

Environmental and Occupational Services
37 S. Ashland Ave., Chicago, IL 60607

www.public-health-safety.com

Office: 312-491-0081
Fax: 312-421-2901

Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063


Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed