

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2309
SCHOOL NAME: Lawndale Academy
ADDRESS OF SCHOOL: 3500 W. Douglas
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/18/2016

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 212
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-01934
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Randy Livingston

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Lawndale Academy

3500 W. Douglas
Chicago, IL, 60623

Unit: 31161
Building ID: 4430

IDPH ID Number: 14-016-2990-2309

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

November 20, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 31161 Region: 03 IDPH ID:14-016-2990-2309

School: Lawndale Academy Building ID: 4430

Address: 3500 W. Douglas

Chicago, IL, 60623

Building Contact: Zuffa, Steve

Contact Phone:7085895348

Current Building Owners: Chicago Public Schools

Review Date: 12/09/2019

Inspector: Marcos Iwankiw

Inspector IDPH License: 100-03175

Management Planner: Randy Livingston

Management Planner IDPH License: 100-01934

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Randy Livingston
100-01934

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 20, 2019

RE: Lawndale Academy, Unit 31161
3500 W. Douglas
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Lawndale Academy, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Lawndale Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Lawndale Academy Unit: 31161 Region: 03
Address: 3500 W. Douglas Chicago, IL, 60623
IDPH ID: 14-016-2990-2309 Building ID: 4430
Contact: Zuffa, Steve Phone: 7085895348

2. Description of Facility

Original Construction: 1923 Additional Construction:
Total Square Footage: 77725 No of Floors: 4
Current Occupancy: 212

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, Il, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 11/20/2019

6. Management Planner

Management Planner Name: Randy Livingston

Management Planner IDPH license # 100-01934

Signature:
Date: 12/09/2019

7. Review Date: 12/09/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lawndale Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4430:

104	12" x 12" White Floor Tile w/Black Flecks
145	Transite Tables
1C	1' x 1' Acoustical Ceiling Tile
3C1	12" x 12" Brown Floor Tile w/ White Streaks
3C2	12" x 12" White Floor Tile w/ Brown Streaks
4C1	9" x 9" Gray Floor Tile w/Black & White Streaks
5A7	12" x 12" Green Floor Tile
6A4	9" x 9" Brown Floor Tile w/ Brown & White Streaks
6A7	9" x 9" Tan Floor Tile

B1

Hard Joint Compound on Fiberglass Pipe Insulation

B. The following new homogenous areas have been identified for Building 4430:

145

Transite Tables

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

B1	Joint Insulation off Fiberglass Pipe Insulation
10	Tan Ceramic Tile Grout
100	Exterior Brick - Not AHERA
101	Exterior Brick Mortar - Not AHERA
102	Roofing and Flashing - Not AHERA
104	12" x 12" White Floor Tile w/Black Flecks
105	12" x 12" White Floor Tile w/Black Flecks Mastic
106	4" Black Vinyl Baseboard
107	4" Black Vinyl Baseboard Mastic
108	12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED
109	12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED
11	Red Clay Tile (Clay Brick)
110	12"x12" White Vinyl Floor Tile
111	12" x 12" White Vinyl Floor Tile - Matic
112	12" x 12" Brown and Tan Vinyl Floor Tile
113	12" x 12" Brown and Tan Vinyl Floor Tile - Mastic
114	12" x 12" Blue Vinyl Floor Tile
115	12" x 12" Blue Vinyl Floor Tile - Mastic
117	12"x12" White Vinyl Floor Tile - Patches
118	12"x12" White Vinyl Floor Tile - Patches - Mastic
119	Brown Carpet
12	Red Clay Tile Mortar (Brick Mortar)
120	Brown Carpet - Adhesive
121	Drywall
122	Drywall Compound
123	T.S.I.
124	Gray Linoleum Adhesive
125	Red Linoleum Adhesive
126	12"x12" Brown Floor Tile - Mastic
13	Terrazzo Wall Panels
130	Tan, Black Terrazo Flooring
131	Blue, White Ceramic Floor Tile Grout
132	Blue, White Ceramic Floor Tile Adhesive
133	White, Grey Ceramic Floor Tile Grout
134	White Grey Ceramic Floor Tile Adhesive
135	Brown Ceramic Floor Tile Grout
136	Brown Ceramic Floor Tile Adhesive
137	Blue Ceramic Floor Tile Grout
138	Blue Ceramic Floor Tile Adhesive
139	Black, White, Brown Terrazo Flooring

14	Fireplace Brick
140	Black Vibration Collars
141	Red Ceramic Flooring & Grout
142	Red Ceramic Tile Mastic
143	12" X 12" Beige Floor Tile
144	Mastic Associated w/ 12" x 12" Beige Floor Tile
145	Transite Tables
15	Fireplace Brick Mortar
17	9" Stone Floor Tile
18	Stone Tile Mortar
19	Red Ceramic Tile Grout
1B	Plaster Walls
1C	1' x 1' Acoustical Ceiling Tile
20	Vibration Collars
21	Block
22	Block Mortar
23	12"x12" Gray w/ White Streaks Floor Tile Mastic
25	Black Baseboard
26	Black Baseboard Mastic
2B	Plaster Ceilings
30	12" x 12" Ceiling Tiles With Holes
3B	1' x 1' Acoustical Ceiling Tile
3C1	12" x 12" Brown Floor Tile w/ White Streaks
3C2	12" x 12" White Floor Tile w/ Brown Streaks
3C3	12" x 12" Gray Floor Tile w/ White & Black Streaks
3C4	12" x 12" Blue Floor Tile
43	Ceiling Plaster
45	Brown Ceramic Tile Grout
46	Interior Window Caulk
4A2	Red Linoleum
52	Joint Compound
53	Cinder Block Mortar
54	Cinder Block
57	White Baseboard
58	White Baseboard Mastic
59	Stone Baseboard Mastic
5A1	12" x 12" Yellow Floor Tile w/ Brown Streaks
5A2	12" x 12" Gray Floor Tile w/ White Streaks
5A3	12" x 12" Black Floor Tile w/ White Specks
5A4	12" x 12" Orange Floor Tile
5A6	12" x 12" Blue Floor Tile
5A8	12" x 12" Brown Floor Tile
60	Interior Window Grout
61	Interior Window Glazing
62	Black and Brown Carpet Mastic
63	Insulation Inside of Fire Doors
67	Block Walls
68	Block Mortar

69	Brick Walls
70	Brick Mortar
71	Terrazzo Flooring
73	Exterior Face Brick - Not AHERA
74	Exterior Face Brick Mortar - Not AHERA
75	Exterior Brick - Not AHERA
76	Exterior Brick Mortar - Not AHERA
77	Roof and Flashing - Not AHERA
78	12" x 12" Tan Floor Tile
79	12" x 12" Tan Floor Tile Mastic
7A	Stage Curtain
80	Brick Walls
81	Brick Mortar
85	12" x 12" Blue Floor Tile Mastic
88	Cinder Block Mortar
89	Gray Baseboard
8A	Black and Brown Terrazzo
8B	Tan, Black, and Brown Terrazzo
8C	Tan and Brown Terrazzo
9	Blue Ceramic Tile Grout
90	Gray Baseboard Mastic
91	Glazed Brick Mortar
92	Brown Baseboard
93	Brown Baseboard Mastic
94	12" x 12" Ceiling Tile
95	Gray Baseboard
96	Gray Baseboard Mastic
97	Drywall
98	Mastic for Wall Tile in Washroom
99	Ceramic Tile Grout
B1	Hard Joint Compound on Fiberglass Pipe Insulation
E1	Cardboard Pipe Insulation
E2	Cardboard Pipe Insulation
EB1	Exterior Brick (Not AHERA)
EM1	Exterior Brick Mortar (Not AHERA)
EWC1	Exterior Window Glazing (Not AHERA)
EWG1	Exterior Window Glazing (Not AHERA)
F1	Flashing (Not AHERA)
F2	Cementitious Joint Insulation off Cardboard Lines
F3	Flashing (Not AHERA)
F4	Flashing (Not AHERA)
F5	Flashing (Not AHERA)
R1	Roofing (Not AHERA)
R2	Shingles (Not AHERA)
R3	Roofing (Not AHERA)
R4	Roofing (Not AHERA)
R6	Roofing (Not AHERA)
TP1	Tar Paper (Not AHERA)

The following areas were deemed to be inaccessible:

103	9" x 9" Gray w/ Black & White Floor Tile Mastic
105	12" x 12" White Floor Tile w/Black Flecks Mastic
107	4" Black Vinyl Baseboard Mastic
111	12" x 12" White Vinyl Floor Tile - Matic
113	12" x 12" Brown and Tan Vinyl Floor Tile - Mastic
115	12" x 12" Blue Vinyl Floor Tile - Mastic
118	12"x12" White Vinyl Floor Tile - Patches - Mastic
120	Brown Carpet - Adhesive
132	Blue, White Ceramic Floor Tile Adhesive
134	White Grey Ceramic Floor Tile Adhesive
136	Brown Ceramic Floor Tile Adhesive
138	Blue Ceramic Floor Tile Adhesive
140	Black Vibration Collars
142	Red Ceramic Tile Mastic
144	Mastic Associated w/ 12" x 12" Beige Floor Tile
26	Black Baseboard Mastic
27	9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic
28	12" x 12" Yellow Floor Tile Mastic
29	12" x 12" Orange Floor Tile Mastic
31	12" x 12" Brown Floor Tile Mastic
32	12" x 12" Black Floor Tile w/ White Specks Mastic
34	9" x 9" Red Floor Tile w/ White Streaks Mastic
35	9" x 9" Purple Floor Tile Mastic
36	9" x 9" Dark Brown w/White & Brn Floor Tile Mastic
37	12" x 12" Green Floor Tile Mastic
38	12" x 12" Blue Floor Tile Mastic
39	9" x 9" Brown w/White & Brown Floor Tile Mastic
40	9" x 9" Brown Floor Tile w/ White Streaks Mastic
41	9" x 9" Gray Floor Tile w/ Black & White Mastic
42	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic
44	Fire Door Insulation
48	Beige Vinyl Baseboard Mastic
50	Paper Insulation
58	White Baseboard Mastic
59	Stone Baseboard Mastic
62	Black and Brown Carpet Mastic
63	Insulation Inside of Fire Doors
6A10	9" x 9" Brown Floor Tile w/ Light Brown Streaks
82	9"x9" Light Brown FT w/Blk & White Streaks Mastic
83	12" x 12" White Floor Tile w/ Brown Streaks Mastic

84	12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic
85	12" x 12" Blue Floor Tile Mastic
86	12"x12" White Floor Tile w/ Brown Streaks Mastic
87	Aircell Pipe Insulation
8A	Black and Brown Terrazzo
90	Gray Baseboard Mastic
93	Brown Baseboard Mastic
96	Gray Baseboard Mastic
98	Mastic for Wall Tile in Washroom
A3	Cementitious Pipe Joints Insulation
F2	Cementitious Joint Insulation off Cardboard Lines

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Lawndale Academy Building 4430 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
B1	Joint Insulation off Fiberglass Pipe Insulation	400	LF	Main Building - Throughout	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
10	Tan Ceramic Tile Grout	600	SF	Main Building - Shower Rooms and Men's Lounge	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACM or friable suspect ACM		LOW
100	Exterior Brick - Not AHERA			1959 Addition	ASSUMED	MISC								
101	Exterior Brick Mortar - Not AHERA			1959 Addition	ASSUMED	MISC								
102	Roofing and Flashing - Not AHERA			1959 Addition Roof	ASSUMED	MISC								
103	9" x 9" Gray w/ Black & White Floor Tile Mastic	10,100	SF	1959-Rms 114,116-118, 212, 214-218, 220,312, 314,315, 317-320, 2nd and 3rd Floor & Halls & Storages	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" White Floor Tile w/Black Flecks	800	SF	Room 121	ASSUMED	MISC	N	LOC	100		Yes	ACBM with potential for significant damage	5	LOW
105	12" x 12" White Floor Tile w/Black Flecks Mastic	800	SF	Room 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	4" Black Vinyl Baseboard	130	LF	Room 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	4" Black Vinyl Baseboard Mastic	130	LF	Room 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED			Room 324 in the 1927 Building	ASSUMED	MISC								
109	12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED			Room 324 in the 1927 Building	ASSUMED	MISC								
11	Red Clay Tile (Clay Brick)	2,000	SF	Main Bldg.-Locker Rooms, Shower Room, Basement Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	12"x12" White Vinyl Floor Tile	1,275	SF	Room 330, 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12" x 12" White Vinyl Floor Tile - Matic	1,275	SF	Room 330, 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12" x 12" Brown and Tan Vinyl Floor Tile	425	SF	Room 114, 319, 324	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12" x 12" Brown and Tan Vinyl Floor Tile - Mastic	425	SF	Room 114, 319, 324	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12" x 12" Blue Vinyl Floor Tile	1,550	SF	Room 116, 122, 315, 322	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	12" x 12" Blue Vinyl Floor Tile - Mastic	1,550	SF	Room 116, 122, 315, 322	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	Tank Insulation			Boiler Room Tank	ABATED	TSI		None						

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				#1										
117	12"x12" White Vinyl Floor Tile - Patches	80	SF	Parent Room, 04	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12"x12" White Vinyl Floor Tile - Patches - Mastic	80	SF	Parent Room, 04	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	Brown Carpet	750	SF	Room 327	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Red Clay Tile Mortar (Brick Mortar)	2,000	SF	Main Bldg.-Locker Rooms, Shower Room, Basement Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
120	Brown Carpet - Adhesive	750	SF	Room 327	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	Drywall	800	SF	New Boiler Room, New Electrical Room in Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	Drywall Compound	800	SF	New Boiler Room, New Electrical Room in Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	T.S.I.			Hanging Tank - Boiler Room Tank #3	ASSUMED	TSI								
124	Gray Linoleum Adhesive			Room 222	ASSUMED	MISC								
125	Red Linoleum Adhesive			Room 221	ASSUMED	MISC								
126	12"x12" Brown Floor Tile - Mastic			Wall by Boiler Room	ASSUMED	MISC								
13	Terrazzo Wall Panels	6,000	SF	Main Bldg.-Boys & Girls Washrooms, Showers, Locker Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
130	Tan, Black Terrazzo Flooring	875	SF	Main Entrance East Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	Blue, White Ceramic Floor Tile Grout	1,080	SF	1st, 2nd, 3rd Floors Boys Wash Rooms East Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	Blue, White Ceramic Floor Tile Adhesive	1,080	SF	1st, 2nd, 3rd Floors Boys Wash Room East Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	White, Grey Ceramic Floor Tile Grout	1,080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	White Grey Ceramic Floor Tile Adhesive	1,080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
135	Brown Ceramic Floor Tile Grout	1,800	SF	1st, 2nd, 3rd Floors Girls Wash Rooms West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	Brown Ceramic Floor Tile Adhesive	1,800	SF	1st, 2nd, 3rd Floors Girls Wash Room West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	Blue Ceramic Floor Tile Grout	1,800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
138	Blue Ceramic Floor Tile Adhesive	1,800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	Black, White, Brown Terrazo Flooring	20,000	SF	Throught The West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Fireplace Brick	200	SF	Main Building - Rooms 102/now 122 and 103, 121, 123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
140	Black Vibration Collars	20	SF	Engineers Office, West Buildings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
141	Red Ceramic Flooring & Grout	5,000	SF	West Bldg. Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142	Red Ceramic Tile Mastic	5,000	SF	West Bldg. Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	12" X 12" Beige Floor Tile	1,025	SF	Rooms 221 (Storage Room) and 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144	Mastic Associated w/ 12" x 12" Beige Floor Tile	1,025	SF	Rooms 221 (Storage Room) and 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	Transite Tables	384	SF	Rm. 114 Annex	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
15	Fireplace Brick Mortar	200	SF	Rooms 122 and 123	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Blue Carpet Mastic - ABATED			Room 121	ABATED	MISC								
17	9" Stone Floor Tile			Room 01 and Basement Hall	ASSUMED	MISC								
18	Stone Tile Mortar			Room 01 and Basement Hall	ASSUMED	MISC								
19	Red Ceramic Tile Grout	1,300	SF	2nd and 3rd Floor Girls Washroom, Girls Shower Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1B	Plaster Walls	1,000	SF	Throughout 1927 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1C	1' x 1' Acoustical Ceiling Tile	20,000	SF	1959 Addition	ASSUMED	MISC	Y	LOC	75		Yes	Damaged or significantly damaged friable misc. ACBM	10	LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
20	Vibration Collars	50	LF	Fan Rooms-4th Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Block	3,000	SF	Boiler Room and Fan Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Block Mortar	3,000	SF	Boiler Room and Fan Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Gray w/ White Streaks Floor Tile Mastic			Rooms 322	ASSUMED	MISC								
24	9" x 9" Tan Floor Tile Mastic			Room 221 Pantry	ABATED	MISC								
25	Black Baseboard	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Black Baseboard Mastic	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic	3,725	SF	Rooms 422, 322, 324, 325, 329, 331, and 421	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12" x 12" Yellow Floor Tile Mastic	4,400	SF	Rooms 222, 223, 224, 225, 226, 227, 228, 229	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12" x 12" Orange Floor Tile Mastic	2,600	SF	Engineer's Office & Room Before Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
2B	Plaster Ceilings			Throughout 1927 Annex	ASSUMED	MISC								
30	12" x 12" Ceiling Tiles With Holes	1,000	SF	Room 327	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12" x 12" Brown Floor Tile Mastic	750	SF	Room 227 Wardrobe	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12" x 12" Black Floor Tile w/ White Specks Mastic	525	SF	Room 329	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	9"x9" Black Floor Tile White Streaks-Mastic-ABATED			Engineer's Work Room, Room 332, and Office Left of Pool	CHR	MISC								
34	9" x 9" Red Floor Tile w/ White Streaks Mastic	1,200	SF	Engineer Office 03	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	9" x 9" Purple Floor Tile Mastic	1,200	SF	Engineer Office 03	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	9" x 9" Dark Brown w/White & Brn Floor Tile Mastic	3,500	SF	Rooms 421, 422, 328, 329, 330, 331.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and 323										
37	12" x 12" Green Floor Tile Mastic	8,710	SF	Teacher's Lounge (Now Parent Room), Adjacent Hall & Basement Rm. 01	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12" x 12" Blue Floor Tile Mastic	3,500	SF	Auditorium	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	9" x 9" Brown w/White & Brown Floor Tile Mastic	5,375	SF	Rooms 421, 422, 322, 323, 324, 325, 328, 329, 330 & 331	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3B	1' x 1' Acoustical Ceiling Tile	2,000	SF	Throughout 1927 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3C1	12" x 12" Brown Floor Tile w/ White Streaks	8,000	SF	Kitchen Complex & 1st Floor Hall	ASSUMED	MISC	N	LOC	10		Yes	ACBM with potential for significant damage	5	LOW
3C2	12" x 12" White Floor Tile w/ Brown Streaks	6,000	SF	Kitchen Complex & 1st Floor Hall, Room 330	ASSUMED	MISC	N	LOC	10		Yes	ACBM with potential for significant damage	3	LOW
3C3	12" x 12" Gray Floor Tile w/ White & Black Streaks	4,820	SF	3rd Floor Teacher's Lounge, 2nd and 3rd Floor Halls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3C4	12" x 12" Blue Floor Tile	900	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	9" x 9" Brown Floor Tile w/ White Streaks Mastic	950	SF	Room 323 and 331	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	9" x 9" Gray Floor Tile w/ Black & White Mastic	1,650	SF	Rooms 102/now 122 and 422	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	3,400	SF	Rooms 321, 322, 323, 324, 329, and 422	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Ceiling Plaster	4,050	LF	Pool Area	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
44	Fire Door Insulation	21	SF	Pool Area-Bleacher Area	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Brown Ceramic Tile Grout	5,000	SF	Pool Floor and Shower Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Interior Window Caulk	100	LF	Pool Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Beige Vinyl Baseboard	108	LF	Office Area Left of Pool	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Beige Vinyl Baseboard Mastic	108	LF	Office Area Left of Pool	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Vibration Damper	50	LF	Mechanical Room Left of Pool	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Equipment Area										
4A1	Gray Linoleum			Room 222	ABATED	MISC								
4A2	Red Linoleum	750	SF	Room 221	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4B1	9" x 9" Green Floor Tile - ABATED			Annex	ABATED	MISC								
4B2	9" x 9" Brown Floor Tile - ABATED			Annex: 1st Floor Girls Washroom, 2nd Floor Hall, Rooms 208 and 211	ABATED	MISC								
4C1	9" x 9" Gray Floor Tile w/Black & White Streaks	11,800	SF	Rooms 114, 116-118, 212, 214-218, 220, 312, 314, 315, 317-320, 2nd and 3rd Floor & Halls & Storages	CHR	MISC	N	DIST	120		Yes	ACBM with potential for significant damage	5	LOW
4C2	9" x 9" Light Brown Floor Tile w/Blk & Wh Streaks	3,750	SF	Rooms 220, 218, 315, 317, and 319	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Paper Insulation	0	LF	Pool Tunnel	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
51	Cementitious Joint Insulation on Paper Wrap Pipes			Pool Tunnel	ABATED	TSI								
52	Joint Compound	50	LF	C wall (patched area) in Pool Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Cinder Block Mortar	3,000	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Cinder Block	3,000	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55 A	Tank Insulation			Boiler Room (Tank Closest to Wall)	ABATED	TSI								
55 B	Tank Insulation			Boiler Room-Tank Furthest From Wall	ABATED	TSI								
56	First Layer of Insulation			Boiler Room-(Tank Closest to Wall)	ABATED	MISC								
57	White Baseboard	100	LF	Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	White Baseboard Mastic	100	LF	Locker Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Stone Baseboard Mastic	4,000	SF	Throughout 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A1	12" x 12" Yellow Floor Tile w/ Brown Streaks	1,400	SF	Rooms 222-229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A2	12" x 12" Gray Floor Tile w/ White Streaks	900	SF	Rooms 322	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
5A3	12" x 12" Black Floor Tile w/ White Specks	20	SF	Room 329	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A4	12" x 12" Orange Floor Tile	2,600	SF	Room in Front of Boiler Room and Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A5	12" x 12" Brown Floor Tile	750	SF	Room 227 Wardrobe	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A6	12" x 12" Blue Floor Tile	3,500	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5A7	12" x 12" Green Floor Tile	4,035	SF	Teachers Lounge (Now Parent Room), Adjacent Hall & Basement Room 01	CHR	MISC	N	LOC	600		Yes	ACBM with potential for significant damage	5	LOW
5A8	12" x 12" Brown Floor Tile	175	SF	Hall by Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5B	12" x 12" Tan Floor Tile - ABATED			Rooms 104, 105, 107, and 108 Annex Building - DEMOLISHED	ABATED	MISC								
60	Interior Window Grout	500	LF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Interior Window Glazing	500	LF	Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Black and Brown Carpet Mastic	300	SF	Men's Teachers Lounge, 2nd Floor Landing	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Insulation Inside of Fire Doors		SF	Entrances and Exits	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	9" x 9" Green Floor Tile Mastic - ABATED			1929 Annex - 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED	ABATED	MISC								
65	9" x 9" Brown Floor Tile Mastic - ABATED			1929 Annex- 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED	ABATED	MISC								
66	12" x 12" Tan Floor Tile Mastic - ABATED			1929 Annex - Rooms 103, 104, 105, 107 - DEMOLISHED	ABATED	MISC								
67	Block Walls	420	SF	1929 Annex Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
7A	Stage Curtain	2,500	SF	Stage in Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Brick Walls			Fieldhouse - DEMOLISHED	ASSUMED	MISC								
81	Brick Mortar			Fieldhouse Walls - DEMOLISHED	ASSUMED	MISC								
82	9"x9" Light Brown FT w/Blk & White Streaks Mastic	3,750	SF	Rooms 218, 220, 315, 317, and 319	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12" x 12" White Floor Tile w/ Brown Streaks Mastic	6,600	SF	Cafeteria, Kitchen, Serving Room, 1st Floor Hall, Room 330	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic	3,350	SF	3rd Floor Teachers Lounge, 2nd and 3rd Floor Halls	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12" x 12" Blue Floor Tile Mastic	75	SF	Room 112 East Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12"x12" White Floor Tile w/ Brown Streaks Mastic	3,350	SF	Cafeteria, Kitchen, 1st Floor Hall, Serving Room, Faculty Dining Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	Aircell Pipe Insulation	2,500	LF	Inside Walls Throughout Facility	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
88	Cinder Block Mortar	5,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Gray Baseboard	1,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8A	Black and Brown Terrazzo	15,000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Engineer's Storage, Lobby and Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8B	Tan, Black, and Brown Terrazzo	12,000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Lobby, Engineer's Storage, Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8C	Tan and Brown Terrazzo	1,000	SF	Engineer's Storage Room, Lobby and Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
9	Blue Ceramic Tile Grout	1,300	SF	2nd and 3rd Floor Mens Washrooms and Locker Rooms	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
90	Gray Baseboard Mastic	600	LF	Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
91	Glazed Brick Mortar	30,000	SF	Throughout Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
92	Brown Baseboard	600	LF	Faculty Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	Brown Baseboard Mastic	600	LF	Faculty Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	12" x 12" Ceiling Tile	300	SF	Women's 1st Floor Faculty Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
95	Gray Baseboard	500	LF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	Gray Baseboard Mastic	500	LF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	Drywall	700	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	Mastic for Wall Tile in Washroom	1,500	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	Ceramic Tile Grout	840	SF	Washrooms and Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A1	Fiberglass Pipe Insulation			Throughout Facility	NOT_TESTED	TSI								
A2	Fiberglass Pipe Insulation			Throughout Facility	NOT_TESTED	TSI								
A3	Cementitious Pipe Joints Insulation	125	SF	Throughout Facility	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B1	Hard Joint Compound on Fiberglass Pipe Insulation	200	LF	Throughout Main Building	ASSUMED	TSI	Y	LOC	40		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
B2	Cementitious Joint Insulation on Fiberglass Lines	30	LF	Throughout Facility	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C1	Aircell Pipe Insulation	950	LF	Throughout Facility	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C2	Aircell Pipe Insulation	1,700	LF	Throughout Facility	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D1	Cementitious Joint Insulation off Aircell Lines	225	LF	Throughout Facility	AMO_CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D2	Cementitious Joint Insulation off Aircell Lines	50	SF	Throughout Facility	AMO_CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/20/2019
Inspector Name <u>Marcos Iwankiw</u>
100-03175 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
B1	
10	
100	
101	
102	
103	Not observed in Rm. 114 - 2019
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
12	
120	
121	
122	
123	Not observed 2019
124	Not observed 2019
125	Not observed 2019
126	Not observed 2019
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	Inaccessible 2019
144	Inaccessible 2019
145	
15	Inaccessible 2019
16	
17	Not observed 2019

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
18	Not observed 2019
19	
1B	
1C	MDF Room
20	
21	
22	
23	Not observed 2019
24	
25	
26	
27	
28	
29	
2B	Not observed 2019
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3B	
3C1	Damage in cafeteria
3C2	Damage located in cafeteria
3C3	

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
3C4	Inaccessible 2019
40	
41	Inaccessible 2019
42	Rm. 322 inaccessible 2019
43	
44	
45	
46	
47	
48	
49	
4A1	
4A2	
4B1	
4B2	
4C1	
4C2	
50	
51	
52	
53	
54	
55 A	
55 B	
56	
57	
58	
59	
5A1	

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
5A2	Inaccessible 2019
5A3	
5A4	
5A5	Inaccessible 2019
5A6	
5A7	Damage in basement
5A8	
5B	
60	Inaccessible 2019
61	Inaccessible 2019
62	Inaccessible 2019
63	
64	
65	
66	
67	
68	
69	
6A1	
6A10	
6A2	
6A3	
6A4	Rm. 422 inaccessible - 2019
6A5	Rm. 324 inaccessible - 2019
6A6	Rms. 421 and 422 inaccessible 2019
6A7	
6A8	
6A9	Rm. 422 inaccessible - 2019
70	

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
71	
72	
73	
74	
75	
76	
77	
78	Not observed 2019
79	Not observed 2019
7A	
80	
81	
82	
83	
84	
85	Inaccessible 2019
86	
87	
88	
89	
8A	
8B	
8C	
9	
90	
91	
92	
93	
94	

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
95	Inaccessible 2019
96	Inaccessible 2019
97	Inaccessible 2019
98	Inaccessible 2019
99	
A1	
A2	
A3	
B1	
B2	
C1	
C2	
D1	
D2	
E1	Not observed 2019
E2	Not observed 2019
EB1	
EM1	
EWC1	
EWG1	
F1	
F2	
F3	
F4	
F5	
G2 T2	Not observed 2019
G2B	Not observed 2019
G2T1	Not observed 2019
R1	Not observed 2019

Chicago Public Schools

School Lawndale Academy Unit 31161 Building ID 4430

Address 3500 W. Douglas Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
R2	
R3	
R4	
R5	
R6	
TP1	

Table II

Management Planner's Review

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
B1	Joint Insulation off Fiberglass Pipe Insulation	400	LF	Main Building - Throughout	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	Tan Ceramic Tile Grout	600	SF	Main Building - Shower Rooms and Men's Lounge	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
100	Exterior Brick - Not AHERA			1959 Addition	Assumed	MISC					
101	Exterior Brick Mortar - Not AHERA			1959 Addition	Assumed	MISC					
102	Roofing and Flashing - Not AHERA			1959 Addition Roof	Assumed	MISC					
103	9" x 9" Gray w/ Black & White Floor Tile Mastic	10,100	SF	1959-Rms 114,116-118, 212, 214-218, 220,312, 314,315, 317-320, 2nd and 3rd Floor & Halls & Storages	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" White Floor Tile w/Black Flecks	800	SF	Room 121	Assumed	MISC	No	100	SF	5 ACBM with potential for significant damage	Remove
105	12" x 12" White Floor Tile w/Black Flecks Mastic	800	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Remove
106	4" Black Vinyl Baseboard	130	LF	Room 121	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
107	4" Black Vinyl Baseboard Mastic	130	LF	Room 121	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED			Room 324 in the 1927 Building	Assumed	MISC					
109	12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED			Room 324 in the 1927 Building	Assumed	MISC					
11	Red Clay Tile (Clay Brick)	2,000	SF	Main Bldg.-Locker Rooms, Shower Room, Basement Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	12"x12" White Vinyl Floor Tile	1,275	SF	Room 330, 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12" x 12" White Vinyl Floor Tile - Matic	1,275	SF	Room 330, 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12" x 12" Brown and Tan Vinyl Floor Tile	425	SF	Room 114, 319, 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Brown and Tan Vinyl Floor Tile - Mastic	425	SF	Room 114, 319, 324	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12" x 12" Blue Vinyl Floor Tile	1,550	SF	Room 116, 122, 315, 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12" x 12" Blue Vinyl Floor Tile - Mastic	1,550	SF	Room 116, 122, 315, 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	Tank Insulation			Boiler Room Tank #1	Abated	TSI					
117	12"x12" White Vinyl Floor Tile - Patches	80	SF	Parent Room, 04	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" White Vinyl Floor Tile - Patches - Mastic	80	SF	Parent Room, 04	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	Brown Carpet	750	SF	Room 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Red Clay Tile Mortar (Brick Mortar)	2,000	SF	Main Bldg.-Locker Rooms, Shower Room, Basement Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120	Brown Carpet - Adhesive	750	SF	Room 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
121	Drywall	800	SF	New Boiler Room, New Electrical Room in Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Drywall Compound	800	SF	New Boiler Room, New Electrical Room in Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	T.S.I.			Hanging Tank - Boiler Room Tank #3	Assumed	TSI					Follow O&M Plan
124	Gray Linoleum Adhesive			Room 222	Assumed	MISC					Follow O&M Plan
125	Red Linoleum Adhesive			Room 221	Assumed	MISC					Follow O&M Plan
126	12"x12" Brown Floor Tile - Mastic			Wall by Boiler Room	Assumed	MISC					Follow O&M Plan
13	Terrazzo Wall Panels	6,000	SF	Main Bldg.-Boys & Girls Washrooms, Showers, Locker Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
130	Tan, Black Terrazo Flooring	875	SF	Main Entrance East Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	Blue, White Ceramic Floor Tile Grout	1,080	SF	1st, 2nd, 3rd Floors Boys Wash Rooms East Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	Blue, White Ceramic Floor Tile Adhesive	1,080	SF	1st, 2nd, 3rd Floors Boys Wash Room East Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	White, Grey Ceramic Floor Tile Grout	1,080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	White Grey Ceramic Floor Tile Adhesive	1,080	SF	1st, 2nd, 3rd Floors Girls Wash Room East Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	Brown Ceramic Floor Tile Grout	1,800	SF	1st, 2nd, 3rd Floors Girls Wash Rooms West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	Brown Ceramic Floor Tile Adhesive	1,800	SF	1st, 2nd, 3rd Floors Girls Wash Room West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	Blue Ceramic Floor Tile Grout	1,800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	Blue Ceramic Floor Tile Adhesive	1,800	SF	1st, 2nd, 3rd Floors Boys Wash Room West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	Black, White, Brown Terrazo Flooring	20,000	SF	Throught The West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Fireplace Brick	200	SF	Main Building - Rooms 102/nov 122 and 103, 121, 123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Black Vibration Collars	20	SF	Engineers Office, West Buildings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Red Ceramic Flooring & Grout	5,000	SF	West Bldg. Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	Red Ceramic Tile Mastic	5,000	SF	West Bldg. Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	12" X 12" Beige Floor Tile	1,025	SF	Rooms 221 (Storage Room) and 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
144	Mastic Associated w/ 12" x 12" Beige Floor Tile	1,025	SF	Rooms 221 (Storage Room) and 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	Transite Tables	384	SF	Rm. 114 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Fireplace Brick Mortar	200	SF	Rooms 122 and 123	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Blue Carpet Mastic - ABATED			Room 121	Abated	MISC					
17	9" Stone Floor Tile			Room 01 and Basement Hall	Assumed	MISC					Follow O&M Plan
18	Stone Tile Mortar			Room 01 and Basement Hall	Assumed	MISC					Follow O&M Plan
19	Red Ceramic Tile Grout	1,300	SF	2nd and 3rd Floor Girls Washroom, Girls Shower Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1B	Plaster Walls	1,000	SF	Throughout 1927 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1C	1' x 1' Acoustical Ceiling Tile	20,000	SF	1959 Addition	Assumed	MISC	Yes	75	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
20	Vibration Collars	50	LF	Fan Rooms-4th Floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
21	Block	3,000	SF	Boiler Room and Fan Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Block Mortar	3,000	SF	Boiler Room and Fan Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Gray w/ White Streaks Floor Tile Mastic			Rooms 322	Assumed	MISC					Follow O&M Plan
24	9" x 9" Tan Floor Tile Mastic			Room 221 Pantry	Abated	MISC					
25	Black Baseboard	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
26	Black Baseboard Mastic	600	LF	Room 04, Mens & Womens Basement Washrooms, Room 221	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
27	9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic	3,725	SF	Rooms 422, 322, 324, 325, 329, 331, and 421	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Yellow Floor Tile Mastic	4,400	SF	Rooms 222, 223, 224, 225, 226, 227, 228, 229	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Orange Floor Tile Mastic	2,600	SF	Engineer's Office & Room Before Boiler Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	Plaster Ceilings			Throughout 1927 Annex	Assumed	MISC					Follow O&M Plan
30	12" x 12" Ceiling Tiles With Holes	1,000	SF	Room 327	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Brown Floor Tile Mastic	750	SF	Room 227 Wardrobe	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Black Floor Tile w/ White Specks Mastic	525	SF	Room 329	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	9"x9" Black Floor Tile White Streaks-Mastic-ABATED			Engineer's Work Room, Room 332, and Office Left of Pool	Chrysotile	MISC					
34	9" x 9" Red Floor Tile w/ White Streaks Mastic	1,200	SF	Engineer Office 03	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	9" x 9" Purple Floor Tile Mastic	1,200	SF	Engineer Office 03	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
36	9" x 9" Dark Brown w/White & Brn Floor Tile Mastic	3,500	SF	Rooms 421, 422, 328, 329, 330, 331, and 323	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" x 12" Green Floor Tile Mastic	8,710	SF	Teacher's Lounge (Now Parent Room), Adjacent Hall & Basement Rm. 01	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Blue Floor Tile Mastic	3,500	SF	Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	9" x 9" Brown w/White & Brown Floor Tile Mastic	5,375	SF	Rooms 421, 422, 322, 323, 324, 325, 328, 329, 330 & 331	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3B	1' x 1' Acoustical Ceiling Tile	2,000	SF	Throughout 1927 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3C1	12" x 12" Brown Floor Tile w/ White Streaks	8,000	SF	Kitchen Complex & 1st Floor Hall	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
3C2	12" x 12" White Floor Tile w/ Brown Streaks	6,000	SF	Kitchen Complex & 1st Floor Hall, Room 330	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
3C3	12" x 12" Gray Floor Tile w/ White & Black Streaks	4,820	SF	3rd Floor Teacher's Lounge, 2nd and 3rd Floor Halls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3C4	12" x 12" Blue Floor Tile	900	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	9" x 9" Brown Floor Tile w/ White Streaks Mastic	950	SF	Room 323 and 331	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	9" x 9" Gray Floor Tile w/ Black & White Mastic	1,650	SF	Rooms 102/now 122 and 422	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	9" x 9" Brown Floor Tile w/ Brown Streaks Mastic	3,400	SF	Rooms 321, 322, 323, 324, 329, and 422	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Ceiling Plaster	4,050	LF	Pool Area	Assumed	MISC	No	0	LF	5 ACBM with potential for significant damage	Follow O&M Plan
44	Fire Door Insulation	21	SF	Pool Area-Bleacher Area	Chrysotile	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Brown Ceramic Tile Grout	5,000	SF	Pool Floor and Shower Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Interior Window Caulk	100	LF	Pool Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
47	Beige Vinyl Baseboard	108	LF	Office Area Left of Pool	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	Beige Vinyl Baseboard Mastic	108	LF	Office Area Left of Pool	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Vibration Damper	50	LF	Mechanical Room Left of Pool Equipment Area	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
4A1	Gray Linoleum			Room 222	Abated	MISC					
4A2	Red Linoleum	750	SF	Room 221	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4B1	9" x 9" Green Floor Tile - ABATED			Annex	Abated	MISC					
4B2	9" x 9" Brown Floor Tile - ABATED			Annex: 1st Floor Girls Washroom, 2nd Floor Hall, Rooms 208 and 211	Abated	MISC					
4C1	9" x 9" Gray Floor Tile w/Black & White Streaks	11,800	SF	Rooms 114, 116-118, 212, 214-218,	Chrysotile	MISC	No	120	SF	5 ACBM with potential for significant	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				220, 312, 314, 315, 317-320, 2nd and 3rd Floor & Halls & Storages						damage	
4C2	9" x 9" Light Brown Floor Tile w/Blk & Wh Streaks	3,750	SF	Rooms 220, 218, 315, 317, and 319	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Paper Insulation	0	LF	Pool Tunnel	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Cementitious Joint Insulation on Paper Wrap Pipes			Pool Tunnel	Abated	TSI					
52	Joint Compound	50	LF	C wall (patched area) in Pool Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
53	Cinder Block Mortar	3,000	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Cinder Block	3,000	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55 A	Tank Insulation			Boiler Room (Tank Closest to Wall)	Abated	TSI					
55 B	Tank Insulation			Boiler Room-Tank Furthest From Wall	Abated	TSI					
56	First Layer of Insulation			Boiler Room-(Tank Closest to Wall)	Abated	MISC					
57	White Baseboard	100	LF	Locker Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
58	White Baseboard Mastic	100	LF	Locker Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	Stone Baseboard Mastic	4,000	SF	Throughout 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A1	12" x 12" Yellow Floor Tile w/ Brown Streaks	1,400	SF	Rooms 222-229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A2	12" x 12" Gray Floor Tile w/ White Streaks	900	SF	Rooms 322	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A3	12" x 12" Black Floor Tile w/ White Specks	20	SF	Room 329	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A4	12" x 12" Orange Floor Tile	2,600	SF	Room in Front of Boiler Room and Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A5	12" x 12" Brown Floor Tile	750	SF	Room 227 Wardrobe	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A6	12" x 12" Blue Floor Tile	3,500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5A7	12" x 12" Green Floor Tile	4,035	SF	Teachers Lounge (Now Parent Room), Adjacent Hall & Basement Room 01	Chrysotile	MISC	No	600	SF	5 ACBM with potential for significant damage	Remove
5A8	12" x 12" Brown Floor Tile	175	SF	Hall by Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5B	12" x 12" Tan Floor Tile - ABATED			Rooms 104, 105, 107, and 108 Annex Building - DEMOLISHED	Abated	MISC					
60	Interior Window Grout	500	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
61	Interior Window Glazing	500	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
62	Black and Brown Carpet Mastic	300	SF	Men's Teachers Lounge, 2nd Floor Landing	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Insulation Inside of Fire Doors		SF	Entrances and Exits	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
64	9" x 9" Green Floor Tile Mastic - ABATED			1929 Annex - 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED	Abated	MISC					
65	9" x 9" Brown Floor Tile Mastic - ABATED			1929 Annex- 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED	Abated	MISC					
66	12" x 12" Tan Floor Tile Mastic - ABATED			1929 Annex - Rooms 103, 104, 105, 107 - DEMOLISHED	Abated	MISC					
67	Block Walls	420	SF	1929 Annex Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Block Mortar	420	SF	1929 Annex- Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Brick Walls	420	SF	1929 Annex- Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A1	9" x 9" Black Floor Tile w/ White Streaks - ABATED			Engineer's Workroom, Room 332, Office left of Pool	Abated	MISC					
6A10	9" x 9" Brown Floor Tile w/ Light Brown Streaks	3,400	SF	Rooms 321, 322, 323, 324, 329, and 422	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A2	9" x 9" Red Floor Tile w/ White Streaks	1,200	SF	Engineer's Office 03	Chrysotile	MISC	No	1,200	SF	5 ACBM with potential for significant damage	Remove
6A3	9" x 9" Purple Floor Tile	1,200	SF	Engineer Office 03	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A4	9" x 9" Brown Floor Tile w/ Brown & White Streaks	3,000	SF	Rooms 421, 422, 323, 325, 328, 329, 330, 331, and 323	Chrysotile	MISC	No	100	SF	5 ACBM with potential for significant damage	Remove
6A5	9" x 9" Brown Floor Tile w/ White and Red Streaks	3,500	SF	Rooms 421, 422, 322, 324, 325, 329, and 331	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A6	9" x 9" Dark Brown Floor Tile w/ Wh & Brn Streaks	3,350	SF	Rooms 322-325, 328-331, and 421-422	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A7	9" x 9" Tan Floor Tile	625	SF	Room 221 Pantry	Chrysotile	MISC	No	150	SF	5 ACBM with potential for significant damage	Repair
6A8	9" x 9" Brown Floor Tile w/ White Streaks	950	SF	Rooms 331 and 323	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A9	9" x 9" Gray Floor Tile w/ Black & White Streaks	1,650	SF	Rooms 102/now 122 and 422	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Brick Mortar	420	SF	1929 Annex- Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Terrazzo Flooring			1929 Annex- Hallways - DEMOLISHED	Assumed	MISC					
72	Terrazzo Stall Panels			1929 Annex - DEMOLISHED	Abated	MISC					
73	Exterior Face Brick - Not AHERA			1929 Annex	Assumed	MISC					
74	Exterior Face Brick Mortar - Not AHERA			1929 Annex	Assumed	MISC					

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
75	Exterior Brick - Not AHERA			1929 Annex	Assumed	MISC					
76	Exterior Brick Mortar - Not AHERA			1929 Annex	Assumed	MISC					
77	Roof and Flashing - Not AHERA			1929 Annex roof	Assumed	MISC					
78	12" x 12" Tan Floor Tile			Fieldhouse	Assumed	MISC					
79	12" x 12" Tan Floor Tile Mastic			Fieldhouse	Assumed	MISC					
7A	Stage Curtain	2,500	SF	Stage in Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Brick Walls			Fieldhouse - DEMOLISHED	Assumed	MISC					
81	Brick Mortar			Fieldhouse Walls - DEMOLISHED	Assumed	MISC					
82	9"x9" Light Brown FT w/Blk & White Streaks Mastic	3,750	SF	Rooms 218, 220, 315, 317, and 319	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" White Floor Tile w/ Brown Streaks Mastic	6,600	SF	Cafeteria, Kitchen, Serving Room, 1st Floor Hall, Room 330	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic	3,350	SF	3rd Floor Teachers Lounge, 2nd and 3rd Floor Halls	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" Blue Floor Tile Mastic	75	SF	Room 112 East Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12"x12" White Floor Tile w/ Brown Streaks Mastic	3,350	SF	Cafeteria, Kitchen, 1st Floor Hall, Serving Room, Faculty Dining Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Aircell Pipe Insulation	2,500	LF	Inside Walls Throughout Facility	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
88	Cinder Block Mortar	5,000	SF	Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Gray Baseboard	1,000	LF	Throughout Facility	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
8A	Black and Brown Terrazzo	15,000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Engineer's Storage, Lobby and Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	Tan, Black, and Brown Terrazzo	12,000	SF	1st, 2nd, 3rd, and 4th Floor Halls, Lobby, Engineer's Storage, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8C	Tan and Brown Terrazzo	1,000	SF	Engineer's Storage Room, Lobby and Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Blue Ceramic Tile Grout	1,300	SF	2nd and 3rd Floor Mens Washrooms and Locker Rooms	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	Gray Baseboard Mastic	600	LF	Throughout Facility	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
91	Glazed Brick Mortar	30,000	SF	Throughout Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Brown Baseboard	600	LF	Faculty Dining Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
93	Brown Baseboard Mastic	600	LF	Faculty Dining Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Ceiling Tile	300	SF	Women's 1st Floor Faculty Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
95	Gray Baseboard	500	LF	Room 112	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
96	Gray Baseboard Mastic	500	LF	Room 112	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
97	Drywall	700	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Mastic for Wall Tile in Washroom	1,500	SF	Room 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Ceramic Tile Grout	840	SF	Washrooms and Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A1	Fiberglass Pipe Insulation			Throughout Facility	Not Tested	TSI					
A2	Fiberglass Pipe Insulation			Throughout Facility	Not Tested	TSI					
A3	Cementitious Pipe Joints Insulation	125	SF	Throughout Facility	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B1	Hard Joint Compound on Fiberglass Pipe Insulation	200	LF	Throughout Main Building	Assumed	TSI	Yes	40	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove
B2	Cementitious Joint Insulation on Fiberglass Lines	30	LF	Throughout Facility	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C1	Aircell Pipe Insulation	950	LF	Throughout Facility	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C2	Aircell Pipe Insulation	1,700	LF	Throughout Facility	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D1	Cementitious Joint Insulation off Aircell Lines	225	LF	Throughout Facility	Amosite, Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D2	Cementitious Joint Insulation off Aircell Lines	50	SF	Throughout Facility	Amosite, Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E1	Cardboard Pipe Insulation			Boiler Room	Assumed	TSI					Follow O&M Plan
E2	Cardboard Pipe Insulation			T Room	Assumed	TSI					Follow O&M Plan
EB1	Exterior Brick (Not AHERA)			Main Building	Assumed	MISC					
EM1	Exterior Brick Mortar (Not AHERA)			Main Building	Assumed	MISC					
EW1	Exterior Window Glazing (Not AHERA)			Main Building	Assumed	MISC					
EWG1	Exterior Window Glazing (Not AHERA)			Main Building	Assumed	MISC					
F1	Flashing (Not AHERA)			Upper Level Roof Above Gym- Main Building	Assumed	MISC					
F2	Cementitious Joint Insulation off Cardboard Lines	20	LF	Annex T Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F3	Flashing (Not AHERA)			Lower Level Roof above Gym- Main Building	Assumed	TSI					
F4	Flashing (Not AHERA)			3rd Story Roof- Main Building	Assumed	TSI					

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
F5	Flashing (Not AHERA)			4th Story Roof	Assumed	TSI					
G2 T2	Insulation on Large Tank			Boiler Room- 1929 Annex	Amosite, Chrysotile	TSI					
G2B	Boiler Insulation			Boiler Room- 1929 Annex	Chrysotile	TSI					
G2T1	Insulation on Small Tank			Boiler Room- 1929 Annex	Chrysotile	TSI					
R1	Roofing (Not AHERA)			Upper Level Roof Above Gym	Assumed	SURFACE					
R2	Shingles (Not AHERA)			Shingled Slant Roof- Main Building	Assumed	MISC					
R3	Roofing (Not AHERA)			Lower Level Roof above Gym	Assumed	SURFACE					
R4	Roofing (Not AHERA)			3rd Story Roof	Assumed	SURFACE					
R5	Roofing Material (Not AHERA)			4th Story Roof	Anthophyllite	SURFACE					
R6	Roofing (Not AHERA)			Roof Above Pool	Assumed	MISC					
TP1	Tar Paper (Not AHERA)			3rd Story Roof	Assumed	MISC					

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/09/2019
Manager Planner Name	Randy Livingston
100-01934	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
B1	
10	
100	
101	
102	
103	
104	Remove and abate damaged floor tile and associated mastic in room 121
105	See HA 104
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
144	
145	
15	
16	
17	
18	
19	
1B	
1C	Remove and abate damaged floor tile and associated mastic in the MDF room
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
2B	
30	
31	
32	
33	
34	
35	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
36	
37	
38	
39	
3B	
3C1	
3C2	
3C3	
3C4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
4A1	
4A2	
4B1	
4B2	
4C1	
4C2	
50	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
51	
52	
53	
54	
55 A	
55 B	
56	
57	
58	
59	
5A1	
5A2	
5A3	
5A4	
5A5	
5A6	
5A7	Remove and abate damaged floor tile and associated mastic in the basement
5A8	
5B	
60	
61	
62	
63	
64	
65	
66	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
67	
68	
69	
6A1	
6A10	
6A2	Remove and abate damaged floor tile and associated mastic
6A3	
6A4	Remove and abate damaged floor tile and associated mastic
6A5	
6A6	
6A7	
6A8	
6A9	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
7A	
80	
81	

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
82	
83	
84	
85	
86	
87	
88	
89	
8A	
8B	
8C	
9	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A1	
A2	
A3	
B1	Remove and abate damaged floor tile and associated mastic

Chicago Public Schools

School Lawndale Academy
Address 3500 W. Douglas

Unit 31161
 Chicago, IL, 60623

Building ID 4430
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
B2	
C1	
C2	
D1	
D2	
E1	
E2	
EB1	
EM1	
EWC1	
EWG1	
F1	
F2	
F3	
F4	
F5	
G2 T2	
G2B	
G2T1	
R1	
R2	
R3	
R4	
R5	
R6	
TP1	

Chicago Public Schools

School Lawndale Academy

Unit 31161

Building ID 4430

Address 3500 W. Douglas

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Joint Insulation off Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building - Throughout**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Joint Insulation off Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Main Building - Throughout**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Shower Rooms and Men's Lounge**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**

MATERIAL LOCATION: **Main Building - Shower Rooms and Men's Lounge**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **1959 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Roofing and Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Addition Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **Roofing and Flashing - Not AHERA**

MATERIAL LOCATION: **1959 Addition Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1959-Rms 114,116-118, 212, 214-218, 220,312, 314,315, 317-320, 2nd and 3rd Floor & Halls & Storages**

MATERIAL QUANTITY: **10100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Rm. 114 - 2019**

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black & White Floor Tile Mastic**
MATERIAL LOCATION: **1959-Rms 114,116-118, 212, 214-218, 220,312, 314,315, 317-320, 2nd and 3rd Floor & Halls & Storages**
MATERIAL QUANTITY: **10100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black Flecks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black Flecks**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic in room 121

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black Flecks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Black Flecks Mastic**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:
See HA 104

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Room 121**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324 in the 1927 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile - REMOVED**
MATERIAL LOCATION: **Room 324 in the 1927 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 324 in the 1927 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **12" x 12" Beige w/Brown Streaks Floor Tile Mastic - REMOVED**
MATERIAL LOCATION: **Room 324 in the 1927 Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Red Clay Tile (Clay Brick)**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Bldg.-Locker Rooms, Shower Room, Basement Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Red Clay Tile (Clay Brick)**

MATERIAL LOCATION: **Main Bldg.-Locker Rooms, Shower Room, Basement Hall**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 330, 121**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**
MATERIAL LOCATION: **Room 330, 121**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile - Matic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 330, 121**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile - Matic**
MATERIAL LOCATION: **Room 330, 121**
MATERIAL QUANTITY: **1275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" Brown and Tan Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 114, 319, 324**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12" x 12" Brown and Tan Vinyl Floor Tile**
MATERIAL LOCATION: **Room 114, 319, 324**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12" x 12" Brown and Tan Vinyl Floor Tile - Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 114, 319, 324**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12" x 12" Brown and Tan Vinyl Floor Tile - Mastic**
MATERIAL LOCATION: **Room 114, 319, 324**
MATERIAL QUANTITY: **425** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116, 122, 315, 322**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile**
MATERIAL LOCATION: **Room 116, 122, 315, 322**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile - Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 116, 122, 315, 322**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **12" x 12" Blue Vinyl Floor Tile - Mastic**
MATERIAL LOCATION: **Room 116, 122, 315, 322**
MATERIAL QUANTITY: **1550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Tank #1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room Tank #1**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile - Patches**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Parent Room, 04**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile - Patches**
MATERIAL LOCATION: **Parent Room, 04**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile - Patches - Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Parent Room, 04**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile - Patches - Mastic**
MATERIAL LOCATION: **Parent Room, 04**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Brown Carpet**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Brown Carpet**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Red Clay Tile Mortar (Brick Mortar)**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Bldg.-Locker Rooms, Shower Room, Basement Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Red Clay Tile Mortar (Brick Mortar)**
MATERIAL LOCATION: **Main Bldg.-Locker Rooms, Shower Room, Basement Hall**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Brown Carpet - Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **120**
MATERIAL DESCRIPTION: **Brown Carpet - Adhesive**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **New Boiler Room, New Electrical Room in Cafeteria**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **121**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **New Boiler Room, New Electrical Room in Cafeteria**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **New Boiler Room, New Electrical Room in Cafeteria**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **122**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **New Boiler Room, New Electrical Room in Cafeteria**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **T.S.I.**
HISTORICAL AHERA DAMAGE CATEGORY: **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hanging Tank - Boiler Room Tank #3**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **123**
MATERIAL DESCRIPTION: **T.S.I.**
MATERIAL LOCATION: **Hanging Tank - Boiler Room Tank #3**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **124**
MATERIAL DESCRIPTION: **Gray Linoleum Adhesive**
MATERIAL LOCATION: **Room 222**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **Red Linoleum Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 221**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **125**
MATERIAL DESCRIPTION: **Red Linoleum Adhesive**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile - Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Wall by Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile - Mastic**

MATERIAL LOCATION: **Wall by Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Terrazzo Wall Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Bldg.-Boys & Girls Washrooms, Showers, Locker Rooms**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Terrazzo Wall Panels**
MATERIAL LOCATION: **Main Bldg.-Boys & Girls Washrooms, Showers, Locker Rooms**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Tan, Black Terrazo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Entrance East Building**
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **130**
MATERIAL DESCRIPTION: **Tan, Black Terrazo Flooring**
MATERIAL LOCATION: **Main Entrance East Building**
MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Rooms East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **131**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Grout**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Rooms East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **132**
MATERIAL DESCRIPTION: **Blue, White Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **White, Grey Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **133**
MATERIAL DESCRIPTION: **White, Grey Ceramic Floor Tile Grout**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **White Grey Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **134**
MATERIAL DESCRIPTION: **White Grey Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room East Buildings**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Rooms West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **135**
MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile Grout**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Rooms West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **136**
MATERIAL DESCRIPTION: **Brown Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Girls Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **137**
MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Grout**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **138**
MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **1st, 2nd, 3rd Floors Boys Wash Room West Buildings**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Black, White, Brown Terrazo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throught The West Buildings**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Black, White, Brown Terrazo Flooring**
MATERIAL LOCATION: **Throught The West Buildings**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Fireplace Brick**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Rooms 102/now 122 and 103, 121, 123**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Fireplace Brick**
MATERIAL LOCATION: **Main Building - Rooms 102/now 122 and 103, 121, 123**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **Black Vibration Collars**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineers Office, West Buildings**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **140**
MATERIAL DESCRIPTION: **Black Vibration Collars**
MATERIAL LOCATION: **Engineers Office, West Buildings**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Red Ceramic Flooring & Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Bldg. Basement**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **141**
MATERIAL DESCRIPTION: **Red Ceramic Flooring & Grout**
MATERIAL LOCATION: **West Bldg. Basement**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Red Ceramic Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **West Bldg. Basement**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **142**
MATERIAL DESCRIPTION: **Red Ceramic Tile Mastic**
MATERIAL LOCATION: **West Bldg. Basement**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12" X 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221 (Storage Room) and 222**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **143**
MATERIAL DESCRIPTION: **12" X 12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 221 (Storage Room) and 222**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 221 (Storage Room) and 222**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **144**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **Rooms 221 (Storage Room) and 222**
MATERIAL QUANTITY: **1025** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Fireplace Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122 and 123**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Fireplace Brick Mortar**
MATERIAL LOCATION: **Rooms 122 and 123**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Blue Carpet Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Blue Carpet Mastic - ABATED**

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9" Stone Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 01 and Basement Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9" Stone Floor Tile**

MATERIAL LOCATION: **Room 01 and Basement Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Stone Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 01 and Basement Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Stone Tile Mortar**

MATERIAL LOCATION: **Room 01 and Basement Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Red Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd Floor Girls Washroom, Girls Shower Room**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Red Ceramic Tile Grout**
MATERIAL LOCATION: **2nd and 3rd Floor Girls Washroom, Girls Shower Room**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1B**
MATERIAL DESCRIPTION: **Plaster Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1927 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **1B**
MATERIAL DESCRIPTION: **Plaster Walls**
MATERIAL LOCATION: **Throughout 1927 Annex**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1C**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Water
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 Addition**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**
COMMENTS: **MDF Room**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **1C**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
MATERIAL LOCATION: **1959 Addition**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic in the MDF room

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Vibration Collars**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fan Rooms-4th Floor**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Vibration Collars**

MATERIAL LOCATION: **Fan Rooms-4th Floor**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Block**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room and Fan Rooms**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Block**

MATERIAL LOCATION: **Boiler Room and Fan Rooms**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room and Fan Rooms**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Block Mortar**

MATERIAL LOCATION: **Boiler Room and Fan Rooms**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 322**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 221 Pantry**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Room 221 Pantry**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 04, Mens & Womens Basement Washrooms, Room 221**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Room 04, Mens & Womens Basement Washrooms, Room 221**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 04, Mens & Womens Basement Washrooms, Room 221**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Room 04, Mens & Womens Basement Washrooms, Room 221**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 422, 322, 324, 325, 329, 331, and 421**
MATERIAL QUANTITY: **3725** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9"x9" Dk Brn w/ Red & Wh Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 422, 322, 324, 325, 329, 331, and 421**

MATERIAL QUANTITY: **3725**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 222, 223, 224, 225, 226, 227, 228, 229**
MATERIAL QUANTITY: **4400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 222, 223, 224, 225, 226, 227, 228, 229**
MATERIAL QUANTITY: **4400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office & Room Before Boiler Room**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**
MATERIAL LOCATION: **Engineer's Office & Room Before Boiler Room**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**
MATERIAL DESCRIPTION: **Plaster Ceilings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1927 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **Plaster Ceilings**

MATERIAL LOCATION: **Throughout 1927 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles With Holes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tiles With Holes**
MATERIAL LOCATION: **Room 327**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 227 Wardrobe**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 227 Wardrobe**

MATERIAL QUANTITY: **750**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Specks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 329**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Specks Mastic**

MATERIAL LOCATION: **Room 329**

MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile White Streaks-Mastic-ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Work Room, Room 332, and Office Left of Pool**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile White Streaks-Mastic-ABATED**

MATERIAL LOCATION: **Engineer's Work Room, Room 332, and Office Left of Pool**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Engineer Office 03**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9" x 9" Purple Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9" x 9" Purple Floor Tile Mastic**

MATERIAL LOCATION: **Engineer Office 03**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/White & Brn Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 421, 422, 328, 329, 330, 331, and 323**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/White & Brn Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 421, 422, 328, 329, 330, 331, and 323**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teacher's Lounge (Now Parent Room), Adjacent Hall & Basement Rm. 01**
MATERIAL QUANTITY: **8710** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **Teacher's Lounge (Now Parent Room), Adjacent Hall & Basement Rm. 01**
MATERIAL QUANTITY: **8710** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 421, 422, 322, 323, 324, 325, 328, 329, 330 & 331**
MATERIAL QUANTITY: **5375** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **9" x 9" Brown w/White & Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 421, 422, 322, 323, 324, 325, 328, 329, 330 & 331**

MATERIAL QUANTITY: **5375**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1927 Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3B**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
MATERIAL LOCATION: **Throughout 1927 Annex**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C1**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Complex & 1st Floor Hall**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage in cafeteria**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3C1**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Kitchen Complex & 1st Floor Hall**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C2**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen Complex & 1st Floor Hall, Room 330**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**
COMMENTS: **Damage located in cafeteria**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3C2**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown Streaks**
MATERIAL LOCATION: **Kitchen Complex & 1st Floor Hall, Room 330**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White & Black Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Teacher's Lounge, 2nd and 3rd Floor Halls**
MATERIAL QUANTITY: **4820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3C3**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White & Black Streaks**
MATERIAL LOCATION: **3rd Floor Teacher's Lounge, 2nd and 3rd Floor Halls**
MATERIAL QUANTITY: **4820** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C4**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3C4**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 323 and 331**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Room 323 and 331**

MATERIAL QUANTITY: **950**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/ Black & White Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102/now 122 and 422**
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/ Black & White Mastic**

MATERIAL LOCATION: **Rooms 102/now 122 and 422**

MATERIAL QUANTITY: **1650**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 321, 322, 323, 324, 329, and 422**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Rm. 322 inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown Streaks Mastic**
MATERIAL LOCATION: **Rooms 321, 322, 323, 324, 329, and 422**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Pool Area**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Ceiling Plaster**
MATERIAL LOCATION: **Pool Area**
MATERIAL QUANTITY: **4050** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Fire Door Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Area-Bleacher Area**
MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Pool Area-Bleacher Area**

MATERIAL QUANTITY: **21**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Floor and Shower Walls**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
MATERIAL LOCATION: **Pool Floor and Shower Walls**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Interior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Area**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Area Left of Pool**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Beige Vinyl Baseboard**

MATERIAL LOCATION: **Office Area Left of Pool**

MATERIAL QUANTITY: **108**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Area Left of Pool**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Beige Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Office Area Left of Pool**
MATERIAL QUANTITY: **108** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Vibration Damper**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room Left of Pool Equipment Area**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Vibration Damper**
MATERIAL LOCATION: **Mechanical Room Left of Pool Equipment Area**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A1**
MATERIAL DESCRIPTION: **Gray Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4A1**

MATERIAL DESCRIPTION: **Gray Linoleum**

MATERIAL LOCATION: **Room 222**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A2**
MATERIAL DESCRIPTION: **Red Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4A2**
MATERIAL DESCRIPTION: **Red Linoleum**
MATERIAL LOCATION: **Room 221**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4B1**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4B1**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile - ABATED**

MATERIAL LOCATION: **Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4B2**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex: 1st Floor Girls Washroom, 2nd Floor Hall, Rooms 208 and 211**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4B2**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile - ABATED**
MATERIAL LOCATION: **Annex: 1st Floor Girls Washroom, 2nd Floor Hall, Rooms 208 and 211**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4C1**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Black & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 114, 116-118, 212, 214-218, 220, 312, 314, 315, 317-320, 2nd and 3rd Floor & Halls & Storages**
MATERIAL QUANTITY: **11800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4C1**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/Black & White Streaks**
MATERIAL LOCATION: **Rooms 114, 116-118, 212, 214-218, 220, 312, 314, 315, 317-320, 2nd and 3rd Floor & Halls & Storages**
MATERIAL QUANTITY: **11800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **120** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4C2**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile w/Blk & Wh Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 220, 218, 315, 317, and 319**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4C2**
MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile w/Blk & Wh Streaks**
MATERIAL LOCATION: **Rooms 220, 218, 315, 317, and 319**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Paper Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Tunnel**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Paper Insulation**

MATERIAL LOCATION: **Pool Tunnel**

MATERIAL QUANTITY: **0**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Paper Wrap Pipes**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Paper Wrap Pipes**

MATERIAL LOCATION: **Pool Tunnel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **C wall (patched area) in Pool Area**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Joint Compound**
MATERIAL LOCATION: **C wall (patched area) in Pool Area**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Cinder Block**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55 A**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room (Tank Closest to Wall)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **55 A**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room (Tank Closest to Wall)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55 B**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room-Tank Furthest From Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **55 B**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room-Tank Furthest From Wall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **First Layer of Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room-(Tank Closest to Wall)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **First Layer of Insulation**

MATERIAL LOCATION: **Boiler Room-(Tank Closest to Wall)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **White Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Locker Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **White Baseboard**

MATERIAL LOCATION: **Locker Room**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **White Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Locker Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **White Baseboard Mastic**
MATERIAL LOCATION: **Locker Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Stone Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1927 Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Stone Baseboard Mastic**
MATERIAL LOCATION: **Throughout 1927 Building**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A1**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 222-229**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A1**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/ Brown Streaks**
MATERIAL LOCATION: **Rooms 222-229**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A2**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 322**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A2**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Rooms 322**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A3**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Specks**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 329**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A3**
MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile w/ White Specks**
MATERIAL LOCATION: **Room 329**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A4**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room in Front of Boiler Room and Engineer's Office**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A4**
MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**
MATERIAL LOCATION: **Room in Front of Boiler Room and Engineer's Office**
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A5**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 227 Wardrobe**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A5**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Room 227 Wardrobe**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A6**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A6**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A7**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Teachers Lounge (Now Parent Room), Adjacent Hall & Basement Room 01**
MATERIAL QUANTITY: **4035** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**
COMMENTS: **Damage in basement**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A7**
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**
MATERIAL LOCATION: **Teachers Lounge (Now Parent Room), Adjacent Hall & Basement Room 01**
MATERIAL QUANTITY: **4035** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **600** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic in the basement

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A8**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Hall by Boiler Room**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5A8**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Hall by Boiler Room**
MATERIAL QUANTITY: **175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 104, 105, 107, and 108 Annex Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5B**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile - ABATED**

MATERIAL LOCATION: **Rooms 104, 105, 107, and 108 Annex Building - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Interior Window Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Interior Window Grout**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Interior Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Black and Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's Teachers Lounge, 2nd Floor Landing**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Black and Brown Carpet Mastic**
MATERIAL LOCATION: **Men's Teachers Lounge, 2nd Floor Landing**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Insulation Inside of Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Insulation Inside of Fire Doors**

MATERIAL LOCATION: **Entrances and Exits**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex - 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1929 Annex - 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex- 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1929 Annex- 208, 211, 1st Floor Girls Washroom, 2nd Floor Hall - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex - Rooms 103, 104, 105, 107 - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **1929 Annex - Rooms 103, 104, 105, 107 - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Block Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 Annex Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Block Walls**
MATERIAL LOCATION: **1929 Annex Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 Annex- Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Block Mortar**
MATERIAL LOCATION: **1929 Annex- Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Brick Walls**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 Annex- Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Brick Walls**
MATERIAL LOCATION: **1929 Annex- Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A1**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ White Streaks - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Workroom, Room 332, Office left of Pool**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A1**
MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile w/ White Streaks - ABATED**
MATERIAL LOCATION: **Engineer's Workroom, Room 332, Office left of Pool**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A10**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Light Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 321, 322, 323, 324, 329, and 422**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A10**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Light Brown Streaks**
MATERIAL LOCATION: **Rooms 321, 322, 323, 324, 329, and 422**
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A2**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1200** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A2**
MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Engineer's Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1200** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A3**
MATERIAL DESCRIPTION: **9" x 9" Purple Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A3**
MATERIAL DESCRIPTION: **9" x 9" Purple Floor Tile**
MATERIAL LOCATION: **Engineer Office 03**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A4**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 421, 422, 323, 325, 328, 329, 330, 331, and 323**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS: **Rm. 422 inaccessible - 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A4**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Brown & White Streaks**
MATERIAL LOCATION: **Rooms 421, 422, 323, 325, 328, 329, 330, 331, and 323**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A5**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White and Red Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 421, 422, 322, 324, 325, 329, and 331**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Rm. 324 inaccessible - 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A5**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White and Red Streaks**
MATERIAL LOCATION: **Rooms 421, 422, 322, 324, 325, 329, and 331**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A6**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/ Wh & Brn Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 322-325, 328-331, and 421-422**

MATERIAL QUANTITY: **3350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **Rms. 421 and 422 inaccessible 2019**

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A6**
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile w/ Wh & Brn Streaks**
MATERIAL LOCATION: **Rooms 322-325, 328-331, and 421-422**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A7**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 221 Pantry**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A7**
MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**
MATERIAL LOCATION: **Room 221 Pantry**
MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A8**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 331 and 323**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A8**
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ White Streaks**
MATERIAL LOCATION: **Rooms 331 and 323**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A9**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/ Black & White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 102/now 122 and 422**
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Rm. 422 inaccessible - 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6A9**
MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile w/ Black & White Streaks**
MATERIAL LOCATION: **Rooms 102/now 122 and 422**
MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1929 Annex- Boiler Room**
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **1929 Annex- Boiler Room**

MATERIAL QUANTITY: **420**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex- Hallways - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **1929 Annex- Hallways - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Terrazzo Stall Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Terrazzo Stall Panels**

MATERIAL LOCATION: **1929 Annex - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Exterior Face Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Exterior Face Brick - Not AHERA**

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Exterior Face Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Exterior Face Brick Mortar - Not AHERA**

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Roof and Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1929 Annex roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Roof and Flashing - Not AHERA**

MATERIAL LOCATION: **1929 Annex roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7A**
MATERIAL DESCRIPTION: **Stage Curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stage in Auditorium**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **7A**
MATERIAL DESCRIPTION: **Stage Curtain**
MATERIAL LOCATION: **Stage in Auditorium**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Brick Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Brick Walls**

MATERIAL LOCATION: **Fieldhouse - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse Walls - DEMOLISHED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Brick Mortar**

MATERIAL LOCATION: **Fieldhouse Walls - DEMOLISHED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Light Brown FT w/Blk & White Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 218, 220, 315, 317, and 319**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **9"x9" Light Brown FT w/Blk & White Streaks Mastic**
MATERIAL LOCATION: **Rooms 218, 220, 315, 317, and 319**
MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria, Kitchen, Serving Room, 1st Floor Hall, Room 330**
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown Streaks Mastic**
MATERIAL LOCATION: **Cafeteria, Kitchen, Serving Room, 1st Floor Hall, Room 330**
MATERIAL QUANTITY: **6600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Teachers Lounge, 2nd and 3rd Floor Halls**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile w/Wh & Blk Streaks Mastic**
MATERIAL LOCATION: **3rd Floor Teachers Lounge, 2nd and 3rd Floor Halls**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112 East Building**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 112 East Building**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile w/ Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Cafeteria, Kitchen, 1st Floor Hall, Serving Room, Faculty Dining Room**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12"x12" White Floor Tile w/ Brown Streaks Mastic**
MATERIAL LOCATION: **Cafeteria, Kitchen, 1st Floor Hall, Serving Room, Faculty Dining Room**
MATERIAL QUANTITY: **3350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Inside Walls Throughout Facility**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Inside Walls Throughout Facility**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **Black and Brown Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, and 4th Floor Halls, Engineer's Storage, Lobby and Foyer**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **8A**
MATERIAL DESCRIPTION: **Black and Brown Terrazzo**
MATERIAL LOCATION: **1st, 2nd, 3rd, and 4th Floor Halls, Engineer's Storage, Lobby and Foyer**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **Tan, Black, and Brown Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd, and 4th Floor Halls, Lobby, Engineer's Storage, Office**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **8B**
MATERIAL DESCRIPTION: **Tan, Black, and Brown Terrazzo**
MATERIAL LOCATION: **1st, 2nd, 3rd, and 4th Floor Halls, Lobby, Engineer's Storage, Office**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8C**
MATERIAL DESCRIPTION: **Tan and Brown Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer's Storage Room, Lobby and Foyer**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **8C**
MATERIAL DESCRIPTION: **Tan and Brown Terrazzo**
MATERIAL LOCATION: **Engineer's Storage Room, Lobby and Foyer**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd and 3rd Floor Mens Washrooms and Locker Rooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
MATERIAL LOCATION: **2nd and 3rd Floor Mens Washrooms and Locker Rooms**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Glazed Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Glazed Brick Mortar**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Dining Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **Faculty Dining Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Faculty Dining Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Faculty Dining Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Women's 1st Floor Faculty Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile**
MATERIAL LOCATION: **Women's 1st Floor Faculty Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Mastic for Wall Tile in Washroom**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 112**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Inaccessible 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Mastic for Wall Tile in Washroom**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms and Foyer**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **Washrooms and Foyer**
MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A1**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **A1**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A2**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **A2**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A3**
MATERIAL DESCRIPTION: **Cementitious Pipe Joints Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **A3**
MATERIAL DESCRIPTION: **Cementitious Pipe Joints Insulation**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACM or friable suspect ACM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON: **Physical Damage
Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Main Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout Main Building**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **40** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove and abate damaged floor tile and associated mastic

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B2**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Fiberglass Lines**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **B2**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Fiberglass Lines**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **30**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C1**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **C1**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C2**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **C2**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D1**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Aircell Lines**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **225** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **D1**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Aircell Lines**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D2**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Aircell Lines**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **D2**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Aircell Lines**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E1**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **E1**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E2**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **T Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **E2**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **T Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EB1**
MATERIAL DESCRIPTION: **Exterior Brick (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **EB1**

MATERIAL DESCRIPTION: **Exterior Brick (Not AHERA)**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EM1**
MATERIAL DESCRIPTION: **Exterior Brick Mortar (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **EM1**

MATERIAL DESCRIPTION: **Exterior Brick Mortar (Not AHERA)**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EWC1**
MATERIAL DESCRIPTION: **Exterior Window Glazing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **EWC1**

MATERIAL DESCRIPTION: **Exterior Window Glazing (Not AHERA)**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EWG1**
MATERIAL DESCRIPTION: **Exterior Window Glazing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **EWG1**

MATERIAL DESCRIPTION: **Exterior Window Glazing (Not AHERA)**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F1**
MATERIAL DESCRIPTION: **Flashing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Upper Level Roof Above Gym- Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F1**

MATERIAL DESCRIPTION: **Flashing (Not AHERA)**

MATERIAL LOCATION: **Upper Level Roof Above Gym- Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F2**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Cardboard Lines**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex T Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F2**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation off Cardboard Lines**

MATERIAL LOCATION: **Annex T Room**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F3**
MATERIAL DESCRIPTION: **Flashing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lower Level Roof above Gym- Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F3**

MATERIAL DESCRIPTION: **Flashing (Not AHERA)**

MATERIAL LOCATION: **Lower Level Roof above Gym- Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F4**
MATERIAL DESCRIPTION: **Flashing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Story Roof- Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F4**

MATERIAL DESCRIPTION: **Flashing (Not AHERA)**

MATERIAL LOCATION: **3rd Story Roof- Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F5**
MATERIAL DESCRIPTION: **Flashing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **F5**

MATERIAL DESCRIPTION: **Flashing (Not AHERA)**

MATERIAL LOCATION: **4th Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G2 T2**
MATERIAL DESCRIPTION: **Insulation on Large Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **G2 T2**

MATERIAL DESCRIPTION: **Insulation on Large Tank**

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G2B**
MATERIAL DESCRIPTION: **Boiler Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **G2B**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G2T1**
MATERIAL DESCRIPTION: **Insulation on Small Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **G2T1**

MATERIAL DESCRIPTION: **Insulation on Small Tank**

MATERIAL LOCATION: **Boiler Room- 1929 Annex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R1**
MATERIAL DESCRIPTION: **Roofing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Upper Level Roof Above Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R1**

MATERIAL DESCRIPTION: **Roofing (Not AHERA)**

MATERIAL LOCATION: **Upper Level Roof Above Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R2**
MATERIAL DESCRIPTION: **Shingles (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Shingled Slant Roof- Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R2**

MATERIAL DESCRIPTION: **Shingles (Not AHERA)**

MATERIAL LOCATION: **Shingled Slant Roof- Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R3**
MATERIAL DESCRIPTION: **Roofing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lower Level Roof above Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R3**

MATERIAL DESCRIPTION: **Roofing (Not AHERA)**

MATERIAL LOCATION: **Lower Level Roof above Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R4**
MATERIAL DESCRIPTION: **Roofing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Story Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R4**

MATERIAL DESCRIPTION: **Roofing (Not AHERA)**

MATERIAL LOCATION: **3rd Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R5**
MATERIAL DESCRIPTION: **Roofing Material (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Anthophyllite** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R5**

MATERIAL DESCRIPTION: **Roofing Material (Not AHERA)**

MATERIAL LOCATION: **4th Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R6**
MATERIAL DESCRIPTION: **Roofing (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof Above Pool**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/20/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **R6**

MATERIAL DESCRIPTION: **Roofing (Not AHERA)**

MATERIAL LOCATION: **Roof Above Pool**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Lawndale Academy** INSPECTION DATE: **11/20/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TP1**
MATERIAL DESCRIPTION: **Tar Paper (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Story Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/20/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUIDLING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **TP1**
MATERIAL DESCRIPTION: **Tar Paper (Not AHERA)**
MATERIAL LOCATION: **3rd Story Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/09/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31161** BUILDING ID: **4430**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Lawndale Academy** REVIEW DATE: **12/9/2019**
ADDRESS: **3500 W. Douglas** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **145**

MATERIAL DESCRIPTION: **Transite Tables**

MATERIAL LOCATION: **Rm. 114 Annex**

MATERIAL QUANTITY: **384** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **12/09/2019**

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Randolph Livingston


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/24/2019

Exam Date: 10/24/2019

Expiration Date: 10/24/2020

Certificate Number: MPR1910242073



Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 01934

ISSUED
11/5/2019

EXPIRES
05/15/2020

RANDOLPH LIVINGSTON
9549 S. EUCLID AVE
CHICAGO, IL 60617

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

2/6/2020

MANAGEMENT PLANNER

10/24/2020

PROJECT MANAGER

3/4/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed