

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2846
SCHOOL NAME: Clark Academic Prep HS
ADDRESS OF SCHOOL: 5101 W. Harrison
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/3/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 511
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME(Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Clark Academic Prep HS

5101 W. Harrison
Chicago, IL, 60644

Unit: 41051
Building ID: 6620

IDPH ID Number: 14-016-2990-2846

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 5, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 41051 Region: 03 IDPH ID:14-016-2990-2846

School: Clark Academic Prep HS Building ID: 6620

Address: 5101 W. Harrison
Chicago, IL, 60644

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 04/26/2019

Inspector: Carol Ashman Inspector IDPH License: 100-19554
Management Planner: Evan Christian Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 05, 2019

RE: Clark Academic Prep HS, Unit 41051
5101 W. Harrison
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Clark Academic Prep HS, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Clark Academic Prep HS, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Clark Academic Prep HS Unit: 41051 Region: 03
Address: 5101 W. Harrison Chicago, IL, 60644
IDPH ID: 14-016-2990-2846 Building ID: 6620
Contact: Phone:

2. Description of Facility

Original Construction: 1972 Additional Construction:
Total Square Footage: 150700 No of Floors: 2
Current Occupancy: 511

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, Il, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554

Signature:
Date: 4/5/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 04/26/2019

7. Review Date:04/26/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clark Academic Prep HS. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6620:

14	Water Tank Insulation
45	12" x 12" Brown w/Pink & White Streaks FT Mastic
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
85	1' x 1' Smooth Ceiling Tiles
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile

B. The following new homogenous areas have been identified for Building 6620:

87

Beige speckled floor tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

2	12" x 12" Yellow Floor Tile
5	12" x 12" Brown Speckled Floor Tile
54	Purple/Lavender/Tan Ceramic Tile Grout
55	Wall Tile Caulk
56	Wall Tile Adhesive
57	Blue Carpet Mastic
58	Orange Carpet Mastic
59	Gray Carpet Mastic
60	12" x 12" Light Gray Floor Tile
61	12" x 12" Light Gray Floor Tile Mastic
67	12" x 12" Blue Floor Tile
68	12" x 12" Blue Floor Tile Mastic
69	Purple Carpet Mastic
71	12" x 12" Beige Floor Tile Mastic
76	Blue Linoleum Flooring
77	Blue Linoleum Mastic
78	12"x12" Dark Brown w/Lt. Grey Spec's FT
79	12"x12" Dark Brown w/Lt. Grey Spec's Mastic
80	Ceramic Floor Grout
81	12"x12" Brown w/White-Grey Spec's Floor Tile
82M	12"x12" Brown w/White-Grey FT Mastic
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
85	1' x 1' Smooth Ceiling Tiles
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile
87	Beige speckled floor tile
AA	Pink/white flooring material
BB	Mastic associate with HA# AA

The following areas were deemed to be inaccessible:

17A	12" x 12" Yellow Floor Tile Mastic
17B	12" x 12" Brown Speckled Floor Tile Mastic
23	Mastic Beneath Orange Rubber Flooring
25	12" x 12" Maroon Floor Tile w/White Flecks Mastic
37	12" x 12" White Floor Tile w/Grey Streaks Mastic
55	Wall Tile Caulk
57	Blue Carpet Mastic

58	Orange Carpet Mastic
59	Gray Carpet Mastic
61	12" x 12" Light Gray Floor Tile Mastic
68	12" x 12" Blue Floor Tile Mastic
69	Purple Carpet Mastic
71	12" x 12" Beige Floor Tile Mastic
75	Transite panel in floor radiators
77	Blue Linoleum Mastic
79	12"x12" Dark Brown w/Lt. Grey Spec's Mastic
82M	12"x12" Brown w/White-Grey FT Mastic
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Clark Academic Prep HS Building 6620 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and Boy's Locker Rooms										
29	Ceramic Floor Tile Grout			Pool Room, Girl's and Boy's Locker Rooms	NO_ACBM									
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	NO_ACBM									
30	Cinder Block			Throughout Facility	NO_ACBM									
31	Cinder Block Mortar			Throughout Facility	NO_ACBM									
32	Wall Tile Adhesive			Boy's Pool Locker Room	NO_ACBM									
33	Wall Tile Caulk			Boy's Pool Locker Room	NO_ACBM									
34	Clay Floor Tile			Kitchen	NO_ACBM									
35	Clay Floor Tile Mortar			Kitchen	NO_ACBM									
36	Ceramic Wall Grout			Kitchen	NO_ACBM									
37	12" x 12" White Floor Tile w/Grey Streaks Mastic	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Terrazzo			Stairways and Landings	NO_ACBM	SURFACE								
39	Brown Ceramic Tile Grout			Boy's Washrooms, Men's Washrooms	NO_ACBM									
4	12" x 12" White Floor Tile w/Grey Streaks	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Yellow Ceramic Tile Grout			Girl's Washrooms, Women's Washrooms	NO_ACBM									
41	White Ceramic Wall Tile Grout			Custodial Rooms in Boy's Washrooms	NO_ACBM									
42	Terrazzo Basins			Custodial Rooms in Boy's Washrooms	NO_ACBM									
43	4" Black Vinyl Baseboard			Throughout Facility	NO_ACBM									
44	4" Black Vinyl Baseboard Mastic			Throughout Facility	NO_ACBM									
45	12" x 12" Brown w/Pink & White Streaks FT Mastic	20,000	SF	Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker	CHR	MISC	N	LOC	20		Yes	ACBM with the potential for damage	3	LOW

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
66	Exterior Brick Mortar - Not AHERA			Building Exterior	NO_ACBM									
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116,212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	Purple Carpet Mastic	556	SF	Room 107,110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	Plaster Ceilings and Walls			Throughout Facility	NO_ACBM									
70	Purple Carpet Mastic			1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141, 143-145, 147, 149, 152-155, 150-154, Lockers	NO_ACBM	MISC		None						Low
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	Transite panel in floor radiators	4,000	SF	Rooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	Blue Linoleum Flooring	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241 and 243	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Blue Linoleum Mastic	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241A, 243	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12"x12" Dark Brown w/Lt. Grey Spec's FT	400	SF	1st Floor Activity Center Nr. Stairs	ASSUMED	MISC	N	LOC	5		No	ACBM with the potential for damage	3	LOW
79	12"x12" Dark Brown w/Lt. Grey Spec's Mastic	400	SF	1st Floor Activity Center Nr. Stairs	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Lab Table Tops	400	SF	Rooms 122,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Ceramic Floor Grout	4,500	SF	Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers	ASSUMED	MISC	N	LOC	8		No	ACBM with the potential for damage	5	LOW
81	12"x12" Brown w/White-Grey Spec's Floor Tile	3,800	SF	Front Entrance Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82M	12"x12" Brown w/White-Grey FT Mastic	3,800	SF	Front Entrance Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rms. 109 and 205	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rms. 109 and 205	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile	2,000	SF	Kitchen	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
87	Beige speckled floor tile	50	SF	Cafeteria	ASSUMED	MISC	N	DIST	40		No	ACBM with the potential for damage	5	LOW
9	Mag Block Duct Insulation			Kitchen & Storage area in Basement	CHR	TSI								
AA	Pink/white flooring material			Rooms 241, 122, 142,	ASSUMED	MISC								
BB	Mastic associate with HA# AA			Rooms 221, 241, 122, 142, 222, 242	ASSUMED	MISC								
CC	Panels over moveable doors room divide	2,850	SF	123/121, 132/134, 152/154, 232/234, 252/254, House commons 1,2 and Gym	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/5/2019
Inspector Name Carol Ashman
100-19554 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	Basement outside mechanical room Water damage floor tile and physical damage floor tiles loose exposed mastic.
11	Not Observed
12	
13	
14	
15	
16	Not Observed
17A	
17B	
18	
19	
2	Not Observed
20	Not Observed
21	Not Observed
22	
23	
24	
25	
26	
27	
28	
29	
3	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
75	
76	
77	
78	5 loose floor tiles, exposed mastic
79	
8	
80	Loose tiling and grout
81	
82M	
83	
84	
85	

Chicago Public Schools

School Clark Academic Prep HS Unit 41051 Building ID 6620

Address 5101 W. Harrison Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
86	
87	
9	Not Observed
AA	Not Observed
BB	Not Observed
CC	

Table II

Management Planner's Review

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12"x12" Brown Floor Tile w/Pink and White Streaks	19,500	SF	107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement	Chrysotile	MISC	No	150	SF	4 Damaged or significantly damaged friable misc. ACBM	Repair
11	Spray On Fire Proofing			Inaccessible	Chrysotile	SURFACE					
12	Cementitious Fitting Insulation on Cold Water Line			Throughout	No ACBM						
13	Cementitious Fitting Insulation on Hot Water Lines			Throughout	No ACBM						
14	Water Tank Insulation	280	SF	Basement	Amosite, Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Tank Breaching on Domestic Hot Water Tank			Pool Mechanical Room	No ACBM						
16	Metal 2' x 4' Lay In Ceiling Panels			Throughout Facility	Not Tested	MISC					
17A	12" x 12" Yellow Floor Tile Mastic	15	SF	Elevator by Faculty Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17B	12" x 12" Brown Speckled Floor Tile Mastic	30,000	SF	1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Water Heater Breaching			Mechanical Room	No ACBM						
19	Water Inlet Pipe Insulation			Mechanical Room	No ACBM						
2	12" x 12" Yellow Floor Tile			Elevator by Faculty Lounge	Assumed	MISC					
20	Block Inside Water Heater			Mechanical Room	Chrysotile	MISC					
21	Mud Inside Water Heater			Mechanical Room	Chrysotile	MISC					
22	Orange Rubber Flooring			Gym	No ACBM						
23	Mastic Beneath Orange Rubber Flooring	1,500	SF	Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Maroon Floor Tile w/White Flecks	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" x 12" Maroon Floor Tile w/White Flecks Mastic	1,000	SF	Girls & Boys Locker Rooms, Coaches Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Brown Baseboard			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM						
27	Brown Baseboard Mastic			Gym, Girls & Boys Locker Rooms, Coaches Offices	No ACBM						
28	Ceramic Wall Base Grout			Pool Room, Girl's and Boy's Locker Rooms	No ACBM						
29	Ceramic Floor Tile Grout			Pool Room, Girl's and Boy's Locker Rooms	No ACBM						
3	12" x 12" Beige Floor Tile			2nd Floor Corridor	No ACBM						

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30	Cinder Block			Throughout Facility	No ACBM						
31	Cinder Block Mortar			Throughout Facility	No ACBM						
32	Wall Tile Adhesive			Boy's Pool Locker Room	No ACBM						
33	Wall Tile Caulk			Boy's Pool Locker Room	No ACBM						
34	Clay Floor Tile			Kitchen	No ACBM						
35	Clay Floor Tile Mortar			Kitchen	No ACBM						
36	Ceramic Wall Grout			Kitchen	No ACBM						
37	12" x 12" White Floor Tile w/Grey Streaks Mastic	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Terrazzo			Stairways and Landings	No ACBM	SURFACE					
39	Brown Ceramic Tile Grout			Boy's Washrooms, Men's Washrooms	No ACBM						
4	12" x 12" White Floor Tile w/Grey Streaks	1,728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Yellow Ceramic Tile Grout			Girl's Washrooms, Women's Washrooms	No ACBM						
41	White Ceramic Wall Tile Grout			Custodial Rooms in Boy's Washrooms	No ACBM						
42	Terrazzo Basins			Custodial Rooms in Boy's Washrooms	No ACBM						
43	4" Black Vinyl Baseboard			Throughout Facility	No ACBM						
44	4" Black Vinyl Baseboard Mastic			Throughout Facility	No ACBM						
45	12" x 12" Brown w/Pink & White Streaks FT Mastic	20,000	SF	Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement	Chrysotile	MISC	No	20	SF	6 ACBM with the potential for damage	Repair
46	4" Light Brown Vinyl Baseboard (Cove Base)			Rooms 102 and 148	No ACBM						
47	4" Light Brown Vinyl Baseboard (Cove Base) Mastic			Rooms 102 and 148	No ACBM						
48	Drywall			Room 220, Industrial Arts Corridor	No ACBM						
49	Interior Brick			Throughout Facility	No ACBM						
5	12" x 12" Brown Speckled Floor Tile	50	SF	Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Interior Brick Mortar			Throughout Facility	No ACBM						
51	Interior Door Caulk	10	LF	Corridor by 241	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Interior Window Caulk			Throughout Facility	No ACBM						
53	Interior Window Glazing Non Ahera			Throughout Facility	No ACBM						

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
54	Purple/Lavender/Tan Ceramic Tile Grout	100	SF	Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Wall Tile Caulk	100	SF	Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Wall Tile Adhesive	100	SF	Office Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Blue Carpet Mastic	6,500	SF	Rooms 101-103, 202 and 214, and LRC Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Orange Carpet Mastic	4,600	SF	Activity Circle	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Gray Carpet Mastic	6,200	SF	Activity Circle, Rms. 122, 142, 241	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12" x 12" Wormy Ceiling Tile			Basement, Activity Circle, 1st Floor Men's & Women's Washrooms	No ACBM						
60	12" x 12" Light Gray Floor Tile	100	SF	At Doors of Commons 1+2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Light Gray Floor Tile Mastic	100	SF	At Doors of Commons 1+2	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Exterior Door Caulk (Not AHERA)			Building Exterior	No ACBM						
63	12"x12"Light Brown Floor Tile w/Dark Brown Streaks			Room 217	Abated	MISC					
64	12"x12" Lt Brn Floor Tile w/Dk Brn Streaks Mastic			Room 217	Abated	MISC					
65	Exterior Brick - Not AHERA			Building Exterior	No ACBM						
66	Exterior Brick Mortar - Not AHERA			Building Exterior	No ACBM						
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116,212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Purple Carpet Mastic	556	SF	Room 107,110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster Ceilings and Walls			Throughout Facility	No ACBM						
70	Purple Carpet Mastic			1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141, 143-145, 147, 149, 152-155, 150-154, Lockers	No ACBM	MISC					
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Transite panel in floor radiators	4,000	SF	Rooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Blue Linoleum Flooring	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241 and 243	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Blue Linoleum Mastic	3,600	SF	Rooms 142, 223, 223A, 221, 241, 241A, 243	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12"x12" Dark Brown w/Lt. Grey Spec's FT	400	SF	1st Floor Activity Center Nr. Stairs	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Repair
79	12"x12" Dark Brown w/Lt. Grey Spec's Mastic	400	SF	1st Floor Activity Center Nr. Stairs	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Lab Table Tops	400	SF	Rooms 122,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
80	Ceramic Floor Grout	4,500	SF	Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers	Assumed	MISC	No	8	SF	6 ACBM with the potential for damage	Repair
81	12"x12" Brown w/White-Grey Spec's Floor Tile	3,800	SF	Front Entrance Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	12"x12" Brown w/White-Grey FT Mastic	3,800	SF	Front Entrance Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rms. 109 and 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1,000	SF	Rms. 109 and 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	1' x 1' Smooth Ceiling Tiles	2,000	SF	Kitchen	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile	2,000	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Beige speckled floor tile	50	SF	Cafeteria	Assumed	MISC	No	40	SF	6 ACBM with the potential for damage	Remove
9	Mag Block Duct Insulation			Kitchen & Storage area in Basement	Chrysotile	TSI					
AA	Pink/white flooring material			Rooms 241, 122, 142,	Assumed	MISC					
BB	Mastic associate with HA# AA			Rooms 221, 241, 122, 142, 222, 242	Assumed	MISC					
CC	Panels over moveable doors room divide	2,850	SF	123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	04/26/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
11	
12	
13	
14	
15	
16	
17A	
17B	
18	
19	
2	
20	
21	
22	
23	
24	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	

Chicago Public Schools

School Clark Academic Prep HS

Unit 41051

Building ID 6620

Address 5101 W. Harrison

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
75	
76	
77	
78	
79	
8	
80	Sample material to determine asbestos content. Repair all damaged ACBM
81	
82M	
83	
84	
85	
86	
87	Sample material to determine asbestos content. and remove all damaged ACBM
9	
AA	
BB	
CC	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/Pink and White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Water**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**
MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**
COMMENTS: **Basement outside mechanical room Water damage floor tile and physical damage floor tiles loose exposed mastic.**

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile w/Pink and White Streaks**
MATERIAL LOCATION: **107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**
MATERIAL QUANTITY: **19500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **150** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Spray On Fire Proofing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Inaccessible**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Spray On Fire Proofing**

MATERIAL LOCATION: **Inaccessible**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Cold Water Line**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Cold Water Line**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Hot Water Lines**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Cementitious Fitting Insulation on Hot Water Lines**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite, Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Water Tank Insulation**
MATERIAL LOCATION: **Basement**
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Tank Breeching on Domestic Hot Water Tank**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Tank Breeching on Domestic Hot Water Tank**

MATERIAL LOCATION: **Pool Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Metal 2' x 4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Not Tested** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Metal 2' x 4' Lay In Ceiling Panels**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Elevator by Faculty Lounge**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **17A**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Elevator by Faculty Lounge**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **17B**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Corridors**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Water Heater Breeching**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Water Heater Breaching**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Water Inlet Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Water Inlet Pipe Insulation**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Elevator by Faculty Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **Elevator by Faculty Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Block Inside Water Heater**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Block Inside Water Heater**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Mud Inside Water Heater**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Mud Inside Water Heater**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Orange Rubber Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Orange Rubber Flooring**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic Beneath Orange Rubber Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Mastic Beneath Orange Rubber Flooring**
MATERIAL LOCATION: **Gym**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Maroon Floor Tile w/White Flecks Mastic**
MATERIAL LOCATION: **Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Gym, Girls & Boys Locker Rooms, Coaches Offices**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Ceramic Wall Base Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Ceramic Wall Base Grout**

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Pool Room, Girl's and Boy's Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Wall Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Wall Tile Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Pool Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Wall Tile Caulk**
MATERIAL LOCATION: **Boy's Pool Locker Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Clay Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Clay Floor Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Clay Floor Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Clay Floor Tile Mortar**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Ceramic Wall Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Ceramic Wall Grout**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Grey Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Grey Streaks Mastic**
MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232**
MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairways and Landings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boy's Washrooms, Men's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Boy's Washrooms, Men's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Grey Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232**

MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/Grey Streaks**
MATERIAL LOCATION: **Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232**
MATERIAL QUANTITY: **1728** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Girl's Washrooms, Women's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Yellow Ceramic Tile Grout**

MATERIAL LOCATION: **Girl's Washrooms, Women's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **White Ceramic Wall Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Custodial Rooms in Boy's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **White Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Custodial Rooms in Boy's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo Basins**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Custodial Rooms in Boy's Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Terrazzo Basins**
MATERIAL LOCATION: **Custodial Rooms in Boy's Washrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Pink & White Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Brown w/Pink & White Streaks FT Mastic**
MATERIAL LOCATION: **Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base)**

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base) Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Light Brown Vinyl Baseboard (Cove Base) Mastic**

MATERIAL LOCATION: **Rooms 102 and 148**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220, Industrial Arts Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 220, Industrial Arts Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**
MATERIAL LOCATION: **Office**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Interior Door Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor by 241**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Interior Door Caulk**
MATERIAL LOCATION: **Corridor by 241**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Interior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Interior Window Glazing Non Ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Interior Window Glazing Non Ahera**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Purple/Lavender/Tan Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Purple/Lavender/Tan Ceramic Tile Grout**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Wall Tile Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Wall Tile Caulk**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Wall Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Wall Tile Adhesive**
MATERIAL LOCATION: **Office Washroom**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101-103, 202 and 214, and LRC Offices**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Rooms 101-103, 202 and 214, and LRC Offices**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Orange Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Activity Circle**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Orange Carpet Mastic**
MATERIAL LOCATION: **Activity Circle**
MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Activity Circle, Rms. 122, 142, 241**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Activity Circle, Rms. 122, 142, 241**
MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Wormy Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Activity Circle, 1st Floor Men's & Women's Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **12" x 12" Wormy Ceiling Tile**
MATERIAL LOCATION: **Basement, Activity Circle, 1st Floor Men's & Women's Washrooms**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**
MATERIAL LOCATION: **At Doors of Commons 1+2**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Exterior Door Caulk (Not AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior Door Caulk (Not AHERA)**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12"x12"Light Brown Floor Tile w/Dark Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12"x12"Light Brown Floor Tile w/Dark Brown Streaks**
MATERIAL LOCATION: **Room 217**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12"x12" Lt Brn Floor Tile w/Dk Brn Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12"x12" Lt Brn Floor Tile w/Dk Brn Streaks Mastic**
MATERIAL LOCATION: **Room 217**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room in 116,212**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**
MATERIAL LOCATION: **MDF Room in 116,212**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **MDF Room in 116**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
MATERIAL LOCATION: **MDF Room in 116**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 107,110**
MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
MATERIAL LOCATION: **Room 107,110**
MATERIAL QUANTITY: **556** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster Ceilings and Walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster Ceilings and Walls**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141 , 143-145, 147, 149 , 152-155, 150-154, Lockers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141 , 143-145, 147, 149 , 152-155, 150-154, Lockers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 04/26/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Corridor**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Transite panel in floor radiators**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Transite panel in floor radiators**
MATERIAL LOCATION: **Rooms**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Blue Linoleum Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241 and 243**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **Blue Linoleum Flooring**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241 and 243**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241A, 243**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **Rooms 142, 223, 223A, 221, 241, 241A, 243**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12'x12" Dark Brown w/Lt. Grey Spec's FT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**
COMMENTS: **5 loose floor tiles, exposed mastic**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12'x12" Dark Brown w/Lt. Grey Spec's FT**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/Lt. Grey Spec's Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/Lt. Grey Spec's Mastic**
MATERIAL LOCATION: **1st Floor Activity Center Nr. Stairs**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Lab Table Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 122,**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Lab Table Tops**
MATERIAL LOCATION: **Rooms 122,**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Ceramic Floor Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**
COMMENTS: **Loose tiling and grout**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Ceramic Floor Grout**
MATERIAL LOCATION: **Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample material to determine asbestos content. Repair all damaged ACBM

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12"x12" Brown w/White-Grey Spec's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12"x12" Brown w/White-Grey Spec's Floor Tile**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82M**
MATERIAL DESCRIPTION: **12"x12" Brown w/White-Grey FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **82M**
MATERIAL DESCRIPTION: **12"x12" Brown w/White-Grey FT Mastic**
MATERIAL LOCATION: **Front Entrance Hallway**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
MATERIAL LOCATION: **Rms. 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile**
MATERIAL LOCATION: **Rms. 109 and 205**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **1' x 1' Smooth Ceiling Tiles**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/05/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Mag Block Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Storage area in Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Mag Block Duct Insulation**

MATERIAL LOCATION: **Kitchen & Storage area in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Pink/white flooring material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 241, 122, 142,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Pink/white flooring material**
MATERIAL LOCATION: **Rooms 241, 122, 142,**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **Mastic associate with HA# AA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 221, 241, 122, 142, 222, 242**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed**

Inspector's Signature: _____

Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **BB**

MATERIAL DESCRIPTION: **Mastic associate with HA# AA**

MATERIAL LOCATION: **Rooms 221, 241, 122, 142, 222, 242**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Panels over moveable doors room divide**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **Panels over moveable doors room divide**
MATERIAL LOCATION: **123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **04/26/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUIDLING ID: **6620**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Clark Academic Prep HS** INSPECTION DATE: **4/5/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Beige speckled floor tile**
MATERIAL LOCATION: **Cafeteria**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **40** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/05/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **41051** BUILDING ID: **6620**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Clark Academic Prep HS** REVIEW DATE: **4/26/2019**
ADDRESS: **5101 W. Harrison** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Beige speckled floor tile**

MATERIAL LOCATION: **Cafeteria**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **40** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample material to determine asbestos content. and remove all damaged ACBM

Management Planner's Signature: _____ Date: **04/26/2019**

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Carol Ashman


has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/22/2019 - 1/24/2019

Exam Date: 1/24/2019

Expiration Date: 1/24/2020

Certificate Number: ABI1901240283


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

CAROL L ASHMAN
1633 Mc KAY ST.
WAUKEGAN, IL 60087

3/8/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19554

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 19554	ISSUED 3/8/2019	EXPIRES 05/15/2020		INSPECTOR	1/24/2020
CAROL L ASHMAN 1633 Mc KAY ST. WAUKEGAN, IL 60087 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/22/2020
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063


Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed