

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0039  
SCHOOL NAME: King High School  
ADDRESS OF SCHOOL: 4445 S. Drexel  
CITY: Chicago, IL, 60653

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/19/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 471  
IDPH INSPECTOR LICENSE NUMBER: 100-19717  
IDPH LICENSED INSPECTOR NAME(Please Print): Shaquille Crews  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**King High School**

4445 S. Drexel  
Chicago, IL, 60653

Unit: 46371  
Building ID: 1760

IDPH ID Number: 14-016-2990-0039

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

April 18, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 46371            Region: 04            IDPH ID:14-016-2990-0039

School: King High School            Building ID: 1760

Address: 4445 S. Drexel

Chicago, IL, 60653

Building Contact: Chew, Fatima

Contact Phone:708 646 8209

Current Building Owners: Chicago Public Schools

Review Date: 05/07/2019

Inspector: Shaquille Crews

Inspector IDPH License: 100-19717

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 18, 2019

RE: King High School, Unit 46371  
4445 S. Drexel  
Chicago, IL, 60653

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at King High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at King High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: King High School Unit: 46371 Region: 04  
Address: 4445 S. Drexel Chicago, IL, 60653  
IDPH ID: 14-016-2990-0039 Building ID: 1760  
Contact: Chew, Fatima Phone: 708 646 8209

### 2. Description of Facility

Original Construction: 1971 Additional Construction:  
Total Square Footage: 310545 No of Floors: 3  
Current Occupancy: 471

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Chicago, Il, 60607  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Shaquille Crews

Inspector IDPH license # 100-19717

Signature:  
Date: 4/18/2019

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:  
Date: 05/07/2019

### 7. Review Date:05/07/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the King High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1760:

68	12" x 12" Sky Blue w/ White Specks VFT
73	12"x12" Dark Green Floor Tile
88	1' x 1' Ceiling Tile
89	Mastic Associated w/ 1' x 1' Ceiling Tile
S-1	12x12 black w/ white specs

B. The following new homogenous areas have been identified for Building 1760:

90

12x12 lavender floor tile



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Wood Fire Doors without Labels
31	12" x 12" Tan Floor Tile w/ Grey Speckles
40	6" x 6" Ceramic Tile
41	Grout for Ceramic Tile (HA 40)
42	Grout for 6" x 12" White Ceramic Block (HA 42A)
42A	6" x 12" White Ceramic Block
43A	Transite
5	Wood Fire Doors with Labels
50	Stage Light Wiring (not Accessible)
51	Fittings
52	12" X 12" Lt. Beige Floor Tile
53	12" X 12" Lt. Beige Floor Tile-MASTIC
54	12" X 12" Gray w/White Specks Floor Tile
55	12" X 12" Gray w/White Specks Floor Tile-MASTIC
56	Brown Carpet Mastic
57	12" x 12" Light Pink w/ White Streaks VFT
58	12" x 12" Light Pink w/ White Streaks VFT-MASTIC
59	Brown Covebase
6	24" x 24" Blue Floor Tile
60	Brown Covebase Adhesive
61	2' x 2' White Ceiling Tile
62	12" x 12" White w/Blue Specks VFT
63	12" x 12" White w/Blue Specks VFT Mastic
64	12" x 12" Maroon VFT
65	12" x 12" Maroon VFT Mastic
66	Maroon Covebase
67	Maroon Covebase Adhesive
68	12" x 12" Sky Blue w/ White Specks VFT
69	12x12 Sky Blue w/ White Specks VFT Mastic
6A	24" x 24" Orange Floor Tile
70	Mastic for 2' X 2' Grey Rubber Floor
71	12'X12' Lt. Green Floor Tile
72	12"X12" Lt Green Tile Mastic
73	12"x12" Dark Green Floor Tile
74	12"X12" Dark Green Floor Tile Mastic
75	Linoleum
76	Linoleum Mastic
77	Lab Benches & Counter Tops
78	12" X 12" Dark Gray VFT
79	12" X 12" Dark Gray VFT Mastic

8	Tectum
80	4" Brown Baseboard
81	4" Brown Baseboard Adhesive
82	Vault Door Insulation
83	12" x 12" Light Blue VFT
84	12" x 12" Light Blue VFT Mastic
85	Blue Carpet Mastic
86	12"x12" Green VFT
87	12"x12" Green VFT Mastic
88	1' x 1' Ceiling Tile
89	Mastic Associated w/ 1' x 1' Ceiling Tile
90	12x12 lavender floor tile
K	12"x12" Dark Green Floor Tile
L	Joint on Fiberglass Pipe (see HA P)
R	Tank Insulation
S-1	12x12 black w/ white specs
S-2	12x12 black w/ white specs-mastic

The following areas were deemed to be inaccessible:

13	12" x 12" Brown Granite Looking Floor Tile-MASTIC
32	Mastic for 12" x 12" Tan Floor Tile (HA 31)
53	12" X 12" Lt. Beige Floor Tile-MASTIC
55	12" X 12" Gray w/White Specks Floor Tile-MASTIC
56	Brown Carpet Mastic
58	12" x 12" Light Pink w/ White Streaks VFT-MASTIC
60	Brown Covebase Adhesive
63	12" x 12" White w/Blue Specks VFT Mastic
65	12" x 12" Maroon VFT Mastic
67	Maroon Covebase Adhesive
69	12x12 Sky Blue w/ White Specks VFT Mastic
70	Mastic for 2' X 2' Grey Rubber Floor
72	12"X12" Lt Green Tile Mastic
74	12"X12" Dark Green Floor Tile Mastic
76	Linoleum Mastic
79	12" X 12" Dark Gray VFT Mastic
8	Tectum
81	4" Brown Baseboard Adhesive
82	Vault Door Insulation
84	12" x 12" Light Blue VFT Mastic
85	Blue Carpet Mastic
89	Mastic Associated w/ 1' x 1' Ceiling Tile
S-2	12x12 black w/ white specs-mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Shaquille Crews, IDPH License # 100-19717. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The King High School Building 1760 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Wood Fire Doors without Labels	100	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	1' x 1' Glue on Ceiling Tile			Auditorium	NO_ACBM									
10A	Mastic for 1' x 1' Ceiling Tile (HA 10)			Auditorium	NO_ACBM									
11	2' x 5' Ceiling Tile			Throughout School	NO_ACBM									
11A	2' x 5' Lay-in Ceiling Tile with Small Fissure			Throughout School	NO_ACBM									
12	Hard-coat Plaster			Washrooms, Storage Rooms, and Classroom Entrance Ways	NO_ACBM									
13	12" x 12" Brown Granite Looking Floor Tile-MASTIC	8,900	SF	1st floor corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	24" x 24" Floor Tile Mastic			Lunch and Dining Rooms on HA 6 & 6A	NO_ACBM									
15	Grey Covebase			Throughout	NO_ACBM									
16	Mastic for Grey Covebase			Throughout School	NO_ACBM									
17	Cinder Block			Throughout School	NO_ACBM									
18	Cinder Block Mortar			Throughout	NO_ACBM									
19	Window Caulk Interior	80,000	LF	Throughout School	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Window Caulk - Exterior- Not AHERA			Exterior of School	NO_ACBM									
21	12" x 12" Off-White Floor Tile w/Brn & Wht Streaks	44,656	SF	2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117	CHR	MISC	N	LOC	200		No	ACBM with potential for significant damage	3	LOW
22	Mastic for 12" x 12" Off-white Floor Tile (HA 21)			2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117	NO_ACBM									
23	Black Mastic for Cove Base (HA 24)			Throughout School	NO_ACBM									
24	Black Covebase			Throughout School	NO_ACBM									
25	Grout for 1" x 1" Ceramic Tile (HA 26)			Restrooms	NO_ACBM									
26	1" x 1" Dark Grey Ceramic Tile			Restrooms	NO_ACBM									
27	Mastic for 1" x 1" Ceramic Tile (HA 25)			Restrooms	NO_ACBM									
28	Ceramic Blocks			Base of Walls	NO_ACBM									
29	Linoleum over Tan Floor Tile			Room #327	NO_ACBM									
30	Mastic for Linoleum (HA 29)			Room 327	NO_ACBM									
31	12" x 12" Tan Floor Tile w/ Grey Speckles	936	SF	Hall by Rm. 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Mastic for 12" x 12" Tan Floor Tile (HA 31)	936	SF	Hall by Room 302	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
33	6" Black Cove Base			Auditorium	NO_ACBM									
34	Mastic for 6" Cove Base (HA 33)			Auditorium	NO_ACBM									
35	Mastic for Stair (Skid)			Stairs	NO_ACBM									
36	4" Black Cove Base			Library	NO_ACBM									
37	Mastic for 4" Black Cove Base (HA 036)			Library	NO_ACBM									
38	Sheet Rock			Between Rooms 220 & 222	NO_ACBM									
39	Joint Compound for Sheet Rock			Between Rooms 220 & 222	NO_ACBM									
40	6" x 6" Ceramic Tile	600	SF	Food Prep in Kitchen and Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Grout for Ceramic Tile (HA 40)	600	SF	Food Prep in Kitchen and Dining Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Grout for 6" x 12" White Ceramic Block (HA 42A)			Kitchen	ASSUMED	MISC								
42A	6" x 12" White Ceramic Block			Kitchen	ASSUMED	MISC		None						Low
43	Window Glazing (exterior) - NON AHERA			Exterior	CHR	MISC								
43A	Transite	350	SF	in Hood Rm 350, Rm. 230, 232, 346	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	1" x 1" Ceramic Tile - White w/Black Speckles			Pool Area	NO_ACBM									
45	Grout for 1"x1" Ceramic Tile (HA 44)			Pool Area	NO_ACBM									
46	Mastic (Brown) for 1"x1" Ceramic Tile (HA 44)			Pool Area	NO_ACBM									
47	1" x 2" White Ceramic Tile			Basement Shower Area	NO_ACBM									
48	Grout for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area	NO_ACBM									
49	Mastic for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area	NO_ACBM									
4A	Mastic for Carpeting			Office and Library, Auditorium	NO_ACBM									
5	Wood Fire Doors with Labels	220	SF	2nd and 3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Stage Light Wiring (not Accessible)			Stage	ASSUMED	MISC		None						
51	Fittings			in Sealed Pipe Chases (not Accessible)	ASSUMED	TSI		Unknown						
52	12" X 12" Lt. Beige Floor Tile	55,400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102										
53	12" X 12" Lt. Beige Floor Tile-MASTIC	55,400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" X 12" Gray w/White Specks Floor Tile	3,200	SF	Basement Corridor, Rooms 012, 013, 014, 016	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12" X 12" Gray w/White Specks Floor Tile-MASTIC	3,200	SF	Basement Corridor, Rooms 012, 013, 014, 016	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Brown Carpet Mastic	10,000	SF	Main Office, Rooms 100E, H, F, K, C, B, P, R, Computer Room 243B, C, and 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12" x 12" Light Pink w/ White Streaks VFT	6,150	SF	Room 119 (Cafeteria), 120A	ASSUMED	MISC	N	DIST	200		No	ACBM with the potential for damage	5	LOW
58	12" x 12" Light Pink w/ White Streaks VFT-MASTIC	6,150	SF	Room 119 (Cafeteria), 120A	ASSUMED	MISC	N	DIST	200		No	ACBM with the potential for damage	5	LOW
59	Brown Covebase	500	LF	Room 119 (Cafeteria)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	24" x 24" Blue Floor Tile			Lunch and Dining Room	ASSUMED	MISC								
60	Brown Covebase Adhesive	500	SF	Room 119 (Cafeteria)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	2' x 2' White Ceiling Tile	66,000	SF	Rooms 119D, C, 202-210, 212-220, 240-248, 324-340	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
62	12" x 12" White w/Blue Specks VFT	550	SF	Room 226, 226E	ASSUMED	MISC	N	DIST	550		No	ACBM with the potential for damage	3	LOW
63	12" x 12" White w/Blue Specks VFT Mastic	550	SF	Room 226, 226E	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12" x 12" Maroon VFT	400	SF	Room 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12" x 12" Maroon VFT Mastic	400	SF	Room 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Maroon Covebase	100	LF	Room 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
67	Maroon Covebase Adhesive	100	LF	Room 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12" x 12" Sky Blue w/ White Specks VFT	3,000	SF	Room 343A	ASSUMED	MISC	N	LOC	50		Yes	ACBM with the potential for damage	3	LOW
69	12x12 Sky Blue w/ White Specks VFT Mastic	3,000	SF	Room 343A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6A	24" x 24" Orange Floor Tile			Lunch and Dining Room	ASSUMED	MISC								
7	12" x 12" Brown Floor Tile	8,900	SF	1st floor corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Mastic for 2' X 2' Grey Rubber Floor	2,800	SF	Rm. 011, 005, 030 and 018	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"X12" Lt. Green Floor Tile	3,100	SF	Rm. 222, 224, and Practice Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12"X12" Lt Green Tile Mastic	3,100	SF	Room 222, 224, & Practice Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12"x12" Dark Green Floor Tile	1,350	SF	Room 222	ASSUMED	MISC	N	LOC	3		Yes	ACBM with the potential for damage	5	LOW
74	12"X12" Dark Green Floor Tile Mastic	1,350	SF	Room 222	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	Linoleum	4,240	SF	Rm 346, 348, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	Linoleum Mastic	4,240	SF	Rm 346, 348, 350	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	Lab Benches & Counter Tops	3,008	SF	Rm 352, 350, 348, 346, 230, 232, & Science Storage Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" X 12" Dark Gray VFT	225	SF	Basement Rm. 003	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12" X 12" Dark Gray VFT Mastic	225	SF	Basement Rm. 003	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Tectum	2,600	SF	Auditorium and Band Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	4" Brown Baseboard	10,000	LF	1st Floor Corridor & Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	4" Brown Baseboard Adhesive	10,000	LF	1st Floor Corridor & Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Vault Door Insulation	36	SF	Main Office	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
83	12" x 12" Light Blue VFT	3,132	SF	Rm. 118	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
N	Duct Insulation (Foil & Fiberglass)			Ceiling of 1,2, & 3rd Floors	NO_ACBM									
O	White Air Duct Insulation	1,500	SF	Above Ceiling in Kitchen Serving Area	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Joints on Fiberglass Pipe Insulation, Boiler Room	2,500	LF	Boiler room, Tunnels, Rm 126, 129	CHR	TSI	Y	DIST	14		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
Q	Fiberglass Pipe Insulation			Throughout School	NO_ACBM									
R	Tank Insulation	200	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
S-1	12x12 black w/ white specs	4,100	SF	Stage, Room 116	ASSUMED	MISC	N	LOC	25		Yes	ACBM with the potential for damage	5	LOW
S-2	12x12 black w/ white specs-mastic	4,100	SF	Stage, Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>4/18/2019</b>
Inspector Name <b>Shaquille Crews</b>
<b>100-19717</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
10A	
11	
11A	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	Not observed in Room 117 - has carpet and cement floor
22	
23	
24	
25	
26	
27	
28	
29	

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	Not observed
42A	Not observed
43	
43A	
44	
45	
46	
47	
48	
49	
4A	
5	
50	No access
51	No access
52	
53	
54	

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
55	
56	
57	
58	
59	
6	Not observed
60	
61	
62	Entirety of Room 226 damaged
63	NA
64	NA
65	NA
66	NA
67	NA
68	Damage located in Room 343A
69	
6A	Not observed
7	
70	
71	
72	
73	
74	
75	Not observed
76	Not observed
77	
78	
79	
8	

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
A	
B	Not observed
C	
D	
E	
F	
G	Not observed
H	
I	
J	
K	Not observed
L	
M	
N	
O	
P	
Q	
R	

# Chicago Public Schools

School King High School Unit 46371 Building ID 1760

Address 4445 S. Drexel Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
S-1	Damage located on stage
S-2	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Wood Fire Doors without Labels	100	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	1' x 1' Glue on Ceiling Tile			Auditorium	No ACBM						
10A	Mastic for 1' x 1' Ceiling Tile (HA 10)			Auditorium	No ACBM						
11	2' x 5' Ceiling Tile			Throughout School	No ACBM						
11A	2' x 5' Lay-in Ceiling Tile with Small Fissure			Throughout School	No ACBM						
12	Hard-coat Plaster			Washrooms, Storage Rooms, and Classroom Entrance Ways	No ACBM						
13	12" x 12" Brown Granite Looking Floor Tile-MASTIC	8,900	SF	1st floor corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	24" x 24" Floor Tile Mastic			Lunch and Dining Rooms on HA 6 & 6A	No ACBM						
15	Grey Covebase			Throughout	No ACBM						
16	Mastic for Grey Covebase			Throughout School	No ACBM						
17	Cinder Block			Throughout School	No ACBM						
18	Cinder Block Mortar			Throughout	No ACBM						
19	Window Caulk Interior	80,000	LF	Throughout School	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Window Caulk - Exterior- Not AHERA			Exterior of School	No ACBM						
21	12" x 12" Off-White Floor Tile w/Brn & Wht Streaks	44,656	SF	2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117	Chrysotile	MISC	No	200	SF	5 ACBM with potential for significant damage	Remove
22	Mastic for 12" x 12" Off-white Floor Tile (HA 21)			2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117	No ACBM						
23	Black Mastic for Cove Base (HA 24)			Throughout School	No ACBM						
24	Black Covebase			Throughout School	No ACBM						
25	Grout for 1" x 1" Ceramic Tile (HA 26)			Restrooms	No ACBM						
26	1" x 1" Dark Grey Ceramic Tile			Restrooms	No ACBM						
27	Mastic for 1" x 1" Ceramic Tile (HA 25)			Restrooms	No ACBM						
28	Ceramic Blocks			Base of Walls	No ACBM						
29	Linoleum over Tan Floor Tile			Room #327	No ACBM						
30	Mastic for Linoleum (HA 29)			Room 327	No ACBM						
31	12" x 12" Tan Floor Tile w/ Grey Speckles	936	SF	Hall by Rm. 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Mastic for 12" x 12" Tan Floor Tile (HA 31)	936	SF	Hall by Room 302	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	6" Black Cove Base			Auditorium	No ACBM						
34	Mastic for 6" Cove Base (HA 33)			Auditorium	No ACBM						
35	Mastic for Stair (Skid)			Stairs	No ACBM						
36	4" Black Cove Base			Library	No ACBM						

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Mastic for 4" Black Cove Base (HA 036)			Library	No ACBM						
38	Sheet Rock			Between Rooms 220 & 222	No ACBM						
39	Joint Compound for Sheet Rock			Between Rooms 220 & 222	No ACBM						
40	6" x 6" Ceramic Tile	600	SF	Food Prep in Kitchen and Dining Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Grout for Ceramic Tile (HA 40)	600	SF	Food Prep in Kitchen and Dining Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Grout for 6" x 12" White Ceramic Block (HA 42A)			Kitchen	Assumed	MISC					
42A	6" x 12" White Ceramic Block			Kitchen	Assumed	MISC					
43	Window Glazing (exterior) - NON AHERA			Exterior	Chrysotile	MISC					
43A	Transite	350	SF	in Hood Rm 350, Rm. 230, 232, 346	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	1" x 1" Ceramic Tile - White w/Black Speckles			Pool Area	No ACBM						
45	Grout for 1"x1" Ceramic Tile (HA 44)			Pool Area	No ACBM						
46	Mastic (Brown) for 1"x1" Ceramic Tile (HA 44)			Pool Area	No ACBM						
47	1" x 2" White Ceramic Tile			Basement Shower Area	No ACBM						
48	Grout for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area	No ACBM						
49	Mastic for 1" x 2" White Ceramic Tile (HA 47)			Basement Shower Area	No ACBM						
4A	Mastic for Carpeting			Office and Library, Auditorium	No ACBM						
5	Wood Fire Doors with Labels	220	SF	2nd and 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Stage Light Wiring (not Accessible)			Stage	Assumed	MISC					
51	Fittings			in Sealed Pipe Chases (not Accessible)	Assumed	TSI					
52	12" X 12" Lt. Beige Floor Tile	55,400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" X 12" Lt. Beige Floor Tile-MASTIC	55,400	SF	Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" X 12" Gray w/White Specks Floor Tile	3,200	SF	Basement Corridor, Rooms 012, 013, 014, 016	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" X 12" Gray w/White Specks Floor Tile-MASTIC	3,200	SF	Basement Corridor, Rooms 012, 013, 014, 016	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Brown Carpet Mastic	10,000	SF	Main Office, Rooms 100E, H, F, K, C, B, P, R, Computer Room 243B, C, and 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School King High School

Unit 46371

Building ID 1760

Address 4445 S. Drexel

Chicago, IL, 60653

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
57	12" x 12" Light Pink w/ White Streaks VFT	6,150	SF	Room 119 (Cafeteria), 120A	Assumed	MISC	No	200	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Light Pink w/ White Streaks VFT-MASTIC	6,150	SF	Room 119 (Cafeteria), 120A	Assumed	MISC	No	200	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Brown Covebase	500	LF	Room 119 (Cafeteria)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
6	24" x 24" Blue Floor Tile			Lunch and Dining Room	Assumed	MISC					
60	Brown Covebase Adhesive	500	SF	Room 119 (Cafeteria)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	2' x 2' White Ceiling Tile	66,000	SF	Rooms 119D, C, 202-210, 212-220, 240-248, 324-340	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
62	12" x 12" White w/Blue Specks VFT	550	SF	Room 226, 226E	Assumed	MISC	No	550	SF	6 ACBM with the potential for damage	Remove
63	12" x 12" White w/Blue Specks VFT Mastic	550	SF	Room 226, 226E	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Maroon VFT	400	SF	Room 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Maroon VFT Mastic	400	SF	Room 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Maroon Covebase	100	LF	Room 226	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
67	Maroon Covebase Adhesive	100	LF	Room 226	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Sky Blue w/ White Specks VFT	3,000	SF	Room 343A	Assumed	MISC	No	50	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12x12 Sky Blue w/ White Specks VFT Mastic	3,000	SF	Room 343A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6A	24" x 24" Orange Floor Tile			Lunch and Dining Room	Assumed	MISC					
7	12" x 12" Brown Floor Tile	8,900	SF	1st floor corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Mastic for 2' X 2' Grey Rubber Floor	2,800	SF	Rm. 011, 005, 030 and 018	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"X12" Lt. Green Floor Tile	3,100	SF	Rm. 222, 224, and Practice Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"X12" Lt Green Tile Mastic	3,100	SF	Room 222, 224, & Practice Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12"x12" Dark Green Floor Tile	1,350	SF	Room 222	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"X12" Dark Green Floor Tile Mastic	1,350	SF	Room 222	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Linoleum	4,240	SF	Rm 346, 348, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	Linoleum Mastic	4,240	SF	Rm 346, 348, 350	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Lab Benches & Counter Tops	3,008	SF	Rm 352, 350, 348, 346, 230, 232, & Science Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" X 12" Dark Gray VFT	225	SF	Basement Rm. 003	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" X 12" Dark Gray VFT Mastic	225	SF	Basement Rm. 003	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Tectum	2,600	SF	Auditorium and Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	4" Brown Baseboard	10,000	LF	1st Floor Corridor & Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
81	4" Brown Baseboard Adhesive	10,000	LF	1st Floor Corridor & Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
82	Vault Door Insulation	36	SF	Main Office	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

School King High School

Unit 46371

Building ID 1760

Address 4445 S. Drexel

Chicago, IL, 60653

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
83	12" x 12" Light Blue VFT	3,132	SF	Rm. 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Light Blue VFT Mastic	3,132	SF	Rm. 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Blue Carpet Mastic	400	SF	Rm. 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12"x12" Green VFT			Room 118, Restroom	Assumed	MISC					
87	12"x12" Green VFT Mastic			Room 118, Restroom	Assumed	MISC					
88	1' x 1' Ceiling Tile	3,000	SF	Rooms 343 and 343A	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
89	Mastic Associated w/ 1' x 1' Ceiling Tile	3,000	SF	Rooms 343 and 343A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12x12 lavender floor tile	550	SF	Room 226	Assumed	MISC	No	550	SF	6 ACBM with the potential for damage	Remove
A	Boiler Packing			Boiler Room	No ACBM						
B	Breeching on Boiler			Boiler Room	Chrysotile	TSI					
C	Tank Insulation 3' x 5' - 30	100	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Tank Insulation 3' x 5' - 30	150	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Tank Insulation 3' x 5' (grey)	150	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Tank Insulation 3' x 5' (Blue)	120	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Tank Insulation (Large Yellow/Orange) Heat Exchanger			Boiler Room	Chrysotile	TSI					
H	Vibration Dampers on Air Duct System			2nd and 3rd Floors	No ACBM						
I	Duct Liner			Ceiling of Auditorium	No ACBM						
J	Boiler Jacket - Fiberglass Wrap			Boiler Room	No ACBM						
K	12"x12" Dark Green Floor Tile			Univents in Classroom, Lunchroom, Office	Assumed	MISC					
L	Joint on Fiberglass Pipe (see HA P)	2,500	LF	1st Floor throughout Shops, Offices, Boiler Room, Tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Jacket Covering on Fiberglass Duct Insulation			Throughout	No ACBM						
N	Duct Insulation (Foil & Fiberglass)			Ceiling of 1,2, & 3rd Floors	No ACBM						
O	White Air Duct Insulation	1,500	SF	Above Ceiling in Kitchen Serving Area	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Joints on Fiberglass Pipe Insulation, Boiler Room	2,500	LF	Boiler room, Tunnels, Rm 126, 129	Chrysotile	TSI	Yes	14	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Remove

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
 Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
Q	Fiberglass Pipe Insulation			Throughout School	No ACBM						
R	Tank Insulation	200	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S-1	12x12 black w/ white specs	4,100	SF	Stage, Room 116	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
S-2	12x12 black w/ white specs-mastic	4,100	SF	Stage, Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
 Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	05/07/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
10A	
11	
11A	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	Remove Damaged Material
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
42A	
43	
43A	
44	
45	
46	
47	
48	
49	
4A	
5	
50	
51	
52	
53	
54	



# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
 Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
55	
56	
57	Sample to determine asbestos content, remove damaged ACBM
58	Sample to determine asbestos content, remove damaged ACBM
59	
6	
60	
61	
62	Sample to determine asbestos content, remove damaged ACBM
63	
64	
65	
66	
67	
68	Sample to determine asbestos content, remove damaged ACBM
69	
6A	
7	
70	
71	
72	
73	
74	
75	
76	
77	

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
 Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
78	
79	
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	Sample to determine asbestos content, remove damaged ACBM
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	

# Chicago Public Schools

**School** King High School  
**Address** 4445 S. Drexel

**Unit** 46371  
Chicago, IL, 60653

**Building ID** 1760  
**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
M	
N	
O	
P	Remove or Repair Damaged Material
Q	
R	
S-1	Sample to determine asbestos content, remove damaged ACBM
S-2	

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Wood Fire Doors without Labels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Wood Fire Doors without Labels**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **1' x 1' Glue on Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **1' x 1' Glue on Ceiling Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Mastic for 1' x 1' Ceiling Tile (HA 10)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **Mastic for 1' x 1' Ceiling Tile (HA 10)**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **2' x 5' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **2' x 5' Ceiling Tile**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **2' x 5' Lay-in Ceiling Tile with Small Fissure**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **2' x 5' Lay-in Ceiling Tile with Small Fissure**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Hard-coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms, Storage Rooms, and Classroom Entrance Ways**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Hard-coat Plaster**

MATERIAL LOCATION: **Washrooms, Storage Rooms, and Classroom Entrance Ways**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **12" x 12" Brown Granite Looking Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor corridors**  
MATERIAL QUANTITY: **8900**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" Brown Granite Looking Floor Tile-MASTIC**

MATERIAL LOCATION: **1st floor corridors**

MATERIAL QUANTITY: **8900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **24" x 24" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch and Dining Rooms on HA 6 & 6A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **24" x 24" Floor Tile Mastic**

MATERIAL LOCATION: **Lunch and Dining Rooms on HA 6 & 6A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Grey Covebase**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Grey Covebase**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Mastic for Grey Covebase**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Mastic for Grey Covebase**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Cinder Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Window Caulk Interior**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Window Caulk Interior**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **80000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Window Caulk - Exterior- Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Window Caulk - Exterior- Not AHERA**

MATERIAL LOCATION: **Exterior of School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brn & Wht Streaks**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration  
Delamination**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117**  
MATERIAL QUANTITY: **44656** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in Room 117 - has carpet and cement floor**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brn & Wht Streaks**  
MATERIAL LOCATION: **2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117**  
MATERIAL QUANTITY: **44656** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Remove Damaged Material

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-white Floor Tile (HA 21)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: **2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-white Floor Tile (HA 21)**

MATERIAL LOCATION: **2nd & 3rd floor corridors and all stairway platforms, Rms. 116, 117**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Black Mastic for Cove Base (HA 24)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Black Mastic for Cove Base (HA 24)**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Black Covebase**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Black Covebase**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Grout for 1" x 1" Ceramic Tile (HA 26)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Grout for 1" x 1" Ceramic Tile (HA 26)**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **1" x 1" Dark Grey Ceramic Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **1" x 1" Dark Grey Ceramic Tile**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Mastic for 1" x 1" Ceramic Tile (HA 25)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Mastic for 1" x 1" Ceramic Tile (HA 25)**

MATERIAL LOCATION: **Restrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Ceramic Blocks**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Base of Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Ceramic Blocks**

MATERIAL LOCATION: **Base of Walls**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Linoleum over Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room #327**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Linoleum over Tan Floor Tile**

MATERIAL LOCATION: **Room #327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Mastic for Linoleum (HA 29)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 327**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Mastic for Linoleum (HA 29)**

MATERIAL LOCATION: **Room 327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ Grey Speckles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hall by Rm. 302**  
MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ Grey Speckles**

MATERIAL LOCATION: **Hall by Rm. 302**

MATERIAL QUANTITY: **936**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan Floor Tile (HA 31)**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hall by Room 302**  
MATERIAL QUANTITY: **936**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Tan Floor Tile (HA 31)**

MATERIAL LOCATION: **Hall by Room 302**

MATERIAL QUANTITY: **936**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **6" Black Cove Base**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **6" Black Cove Base**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Mastic for 6" Cove Base (HA 33)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Mastic for 6" Cove Base (HA 33)**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Mastic for Stair (Skid)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Mastic for Stair (Skid)**

MATERIAL LOCATION: **Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **4" Black Cove Base**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **4" Black Cove Base**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Mastic for 4" Black Cove Base (HA 036)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Mastic for 4" Black Cove Base (HA 036)**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Sheet Rock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Between Rooms 220 & 222**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Sheet Rock**

MATERIAL LOCATION: **Between Rooms 220 & 222**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Joint Compound for Sheet Rock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Between Rooms 220 & 222**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Joint Compound for Sheet Rock**

MATERIAL LOCATION: **Between Rooms 220 & 222**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **6" x 6" Ceramic Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Food Prep in Kitchen and Dining Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **6" x 6" Ceramic Tile**

MATERIAL LOCATION: **Food Prep in Kitchen and Dining Room**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Grout for Ceramic Tile (HA 40)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Food Prep in Kitchen and Dining Room**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Grout for Ceramic Tile (HA 40)**  
MATERIAL LOCATION: **Food Prep in Kitchen and Dining Room**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Grout for 6" x 12" White Ceramic Block (HA 42A)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Grout for 6" x 12" White Ceramic Block (HA 42A)**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **6" x 12" White Ceramic Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **42A**

MATERIAL DESCRIPTION: **6" x 12" White Ceramic Block**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Window Glazing (exterior) - NON AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Window Glazing (exterior) - NON AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **in Hood Rm 350, Rm. 230, 232, 346**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **in Hood Rm 350, Rm. 230, 232, 346**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **1" x 1" Ceramic Tile - White w/Black Speckles**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **1" x 1" Ceramic Tile - White w/Black Speckles**

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Grout for 1"x1" Ceramic Tile (HA 44)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Grout for 1"x1" Ceramic Tile (HA 44)**

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Mastic (Brown) for 1"x1" Ceramic Tile (HA 44)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Mastic (Brown) for 1"x1" Ceramic Tile (HA 44)**

MATERIAL LOCATION: **Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **1" x 2" White Ceramic Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **1" x 2" White Ceramic Tile**

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Grout for 1" x 2" White Ceramic Tile (HA 47)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Grout for 1" x 2" White Ceramic Tile (HA 47)**

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Mastic for 1" x 2" White Ceramic Tile (HA 47)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Mastic for 1" x 2" White Ceramic Tile (HA 47)**

MATERIAL LOCATION: **Basement Shower Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A**  
MATERIAL DESCRIPTION: **Mastic for Carpeting**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office and Library, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **4A**

MATERIAL DESCRIPTION: **Mastic for Carpeting**

MATERIAL LOCATION: **Office and Library, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **Wood Fire Doors with Labels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd and 3rd Floor**  
MATERIAL QUANTITY: **220**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **Wood Fire Doors with Labels**  
MATERIAL LOCATION: **2nd and 3rd Floor**  
MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Stage Light Wiring (not Accessible)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No access**

Inspector's Signature: \_\_\_\_\_

Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Stage Light Wiring (not Accessible)**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **in Sealed Pipe Chases (not Accessible)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No access**

Inspector's Signature: \_\_\_\_\_

Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Fittings**

MATERIAL LOCATION: **in Sealed Pipe Chases (not Accessible)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12" X 12" Lt. Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102**

MATERIAL QUANTITY: **55400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12" X 12" Lt. Beige Floor Tile**  
MATERIAL LOCATION: **Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102**  
MATERIAL QUANTITY: **55400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" X 12" Lt. Beige Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102**

MATERIAL QUANTITY: **55400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12" X 12" Lt. Beige Floor Tile-MASTIC**  
MATERIAL LOCATION: **Rooms 111, 111A, 110, 107, 116A, 117A, 105, 106, 108 and 2nd & 3rd Floor Classrooms & Teacher's Offices, 102**  
MATERIAL QUANTITY: **55400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" X 12" Gray w/White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Corridor, Rooms 012, 013, 014, 016**  
MATERIAL QUANTITY: **3200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **12" X 12" Gray w/White Specks Floor Tile**  
MATERIAL LOCATION: **Basement Corridor, Rooms 012, 013, 014, 016**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" X 12" Gray w/White Specks Floor Tile-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Corridor, Rooms 012, 013, 014, 016**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12" X 12" Gray w/White Specks Floor Tile-MASTIC**  
MATERIAL LOCATION: **Basement Corridor, Rooms 012, 013, 014, 016**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office, Rooms 100E, H, F, K, C, B, P, R, Computer Room 243B, C, and 116**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **Main Office, Rooms 100E, H, F, K, C, B, P, R, Computer Room 243B, C, and 116**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119 (Cafeteria), 120A**  
MATERIAL QUANTITY: **6150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ White Streaks VFT**  
MATERIAL LOCATION: **Room 119 (Cafeteria), 120A**  
MATERIAL QUANTITY: **6150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ White Streaks VFT-MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119 (Cafeteria), 120A**  
MATERIAL QUANTITY: **6150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ White Streaks VFT-MASTIC**  
MATERIAL LOCATION: **Room 119 (Cafeteria), 120A**  
MATERIAL QUANTITY: **6150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **200** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Brown Covebase**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119 (Cafeteria)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Brown Covebase**

MATERIAL LOCATION: **Room 119 (Cafeteria)**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**  
MATERIAL DESCRIPTION: **24" x 24" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch and Dining Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **24" x 24" Blue Floor Tile**

MATERIAL LOCATION: **Lunch and Dining Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Brown Covebase Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 119 (Cafeteria)**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Brown Covebase Adhesive**

MATERIAL LOCATION: **Room 119 (Cafeteria)**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 119D, C, 202-210, 212-220, 240-248, 324-340**  
MATERIAL QUANTITY: **66000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**  
MATERIAL LOCATION: **Rooms 119D, C, 202-210, 212-220, 240-248, 324-340**  
MATERIAL QUANTITY: **66000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226, 226E**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **550** DAMAGE UNITS: **SF**  
COMMENTS: **Entirety of Room 226 damaged**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks VFT**

MATERIAL LOCATION: **Room 226, 226E**

MATERIAL QUANTITY: **550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **550**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226, 226E**  
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NA**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Specks VFT Mastic**

MATERIAL LOCATION: **Room 226, 226E**

MATERIAL QUANTITY: **550**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Maroon VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NA**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12" x 12" Maroon VFT**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12" x 12" Maroon VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **400**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NA**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Maroon VFT Mastic**

MATERIAL LOCATION: **Room 226**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Maroon Covebase**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS: **NA**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Maroon Covebase**

MATERIAL LOCATION: **Room 226**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Maroon Covebase Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**  
COMMENTS: **NA**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Maroon Covebase Adhesive**

MATERIAL LOCATION: **Room 226**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Sky Blue w/ White Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located in Room 343A**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" Sky Blue w/ White Specks VFT**  
MATERIAL LOCATION: **Room 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Sky Blue w/ White Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 343A**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12x12 Sky Blue w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Room 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A**  
MATERIAL DESCRIPTION: **24" x 24" Orange Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunch and Dining Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **24" x 24" Orange Floor Tile**

MATERIAL LOCATION: **Lunch and Dining Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st floor corridor**  
MATERIAL QUANTITY: **8900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **1st floor corridor**

MATERIAL QUANTITY: **8900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Mastic for 2' X 2' Grey Rubber Floor**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 011, 005, 030 and 018**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Mastic for 2' X 2' Grey Rubber Floor**

MATERIAL LOCATION: **Rm. 011, 005, 030 and 018**

MATERIAL QUANTITY: **2800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12'X12' Lt. Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 222, 224, and Practice Rooms**  
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12'X12' Lt. Green Floor Tile**

MATERIAL LOCATION: **Rm. 222, 224, and Practice Rooms**

MATERIAL QUANTITY: **3100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"X12" Lt Green Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 222, 224, & Practice Room**  
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"X12" Lt Green Tile Mastic**  
MATERIAL LOCATION: **Room 222, 224, & Practice Room**  
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Dark Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 222**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Dark Green Floor Tile**  
MATERIAL LOCATION: **Room 222**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"X12" Dark Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 222**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12"X12" Dark Green Floor Tile Mastic**  
MATERIAL LOCATION: **Room 222**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 346, 348, 350**  
MATERIAL QUANTITY: **4240**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **Linoleum**  
MATERIAL LOCATION: **Rm 346, 348, 350**  
MATERIAL QUANTITY: **4240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Linoleum Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 346, 348, 350**  
MATERIAL QUANTITY: **4240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Linoleum Mastic**  
MATERIAL LOCATION: **Rm 346, 348, 350**  
MATERIAL QUANTITY: **4240** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Lab Benches & Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 352, 350, 348, 346, 230, 232, & Science Storage Room**  
MATERIAL QUANTITY: **3008** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Lab Benches & Counter Tops**

MATERIAL LOCATION: **Rm 352, 350, 348, 346, 230, 232, & Science Storage Room**

MATERIAL QUANTITY: **3008**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" X 12" Dark Gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Rm. 003**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" X 12" Dark Gray VFT**  
MATERIAL LOCATION: **Basement Rm. 003**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12" X 12" Dark Gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Rm. 003**  
MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" X 12" Dark Gray VFT Mastic**

MATERIAL LOCATION: **Basement Rm. 003**

MATERIAL QUANTITY: **225**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Tectum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium and Band Room**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **8**  
MATERIAL DESCRIPTION: **Tectum**  
MATERIAL LOCATION: **Auditorium and Band Room**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor & Classrooms**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
MATERIAL LOCATION: **1st Floor Corridor & Classrooms**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Corridor & Classrooms**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**  
MATERIAL LOCATION: **1st Floor Corridor & Classrooms**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Vault Door Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **36**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 118**  
MATERIAL QUANTITY: **3132** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT**  
MATERIAL LOCATION: **Rm. 118**  
MATERIAL QUANTITY: **3132** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 118**  
MATERIAL QUANTITY: **3132** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12" x 12" Light Blue VFT Mastic**

MATERIAL LOCATION: **Rm. 118**

MATERIAL QUANTITY: **3132**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm. 101**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Rm. 101**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12"x12" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 118, Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12"x12" Green VFT**

MATERIAL LOCATION: **Room 118, Restroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 118, Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**

MATERIAL LOCATION: **Room 118, Restroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 343 and 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**  
MATERIAL LOCATION: **Rooms 343 and 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 1' x 1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 343 and 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Mastic Associated w/ 1' x 1' Ceiling Tile**  
MATERIAL LOCATION: **Rooms 343 and 343A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boiler Packing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Packing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Breeching on Boiler**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Moderate**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Breeching on Boiler**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' - 30**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' - 30**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' - 30**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **150**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' - 30**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' (grey)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' (grey)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' (Blue)**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Tank Insulation 3' x 5' (Blue)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Tank Insulation (Large Yellow/Orange) Heat Exchanger**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Tank Insulation (Large Yellow/Orange) Heat Exchanger**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Vibration Dampers on Air Duct System**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Vibration Dampers on Air Duct System**

MATERIAL LOCATION: **2nd and 3rd Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Duct Liner**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Ceiling of Auditorium**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Duct Liner**

MATERIAL LOCATION: **Ceiling of Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Boiler Jacket - Fiberglass Wrap**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Boiler Jacket - Fiberglass Wrap**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **12"x12" Dark Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Univents in Classroom, Lunchroom, Office**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **Not observed**

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **12"x12" Dark Green Floor Tile**

MATERIAL LOCATION: **Univents in Classroom, Lunchroom, Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Joint on Fiberglass Pipe (see HA P)**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor throughout Shops, Offices, Boiler Room, Tunnels**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Joint on Fiberglass Pipe (see HA P)**

MATERIAL LOCATION: **1st Floor throughout Shops, Offices, Boiler Room, Tunnels**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Jacket Covering on Fiberglass Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Jacket Covering on Fiberglass Duct Insulation**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Duct Insulation (Foil & Fiberglass)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Ceiling of 1,2, & 3rd Floors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Duct Insulation (Foil & Fiberglass)**

MATERIAL LOCATION: **Ceiling of 1,2, & 3rd Floors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **White Air Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Above Ceiling in Kitchen Serving Area**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **White Air Duct Insulation**  
MATERIAL LOCATION: **Above Ceiling in Kitchen Serving Area**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Joints on Fiberglass Pipe Insulation, Boiler Room**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage  
Deterioration  
Delamination**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler room, Tunnels, Rm 126, 129**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **14** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Joints on Fiberglass Pipe Insulation, Boiler Room**  
MATERIAL LOCATION: **Boiler room, Tunnels, Rm 126, 129**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **14** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or Repair Damaged Material

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Tank Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46371**    BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**    INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**    IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S-1**  
MATERIAL DESCRIPTION: **12x12 black w/ white specs**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage  
Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage  
Deterioration**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage, Room 116**  
MATERIAL QUANTITY: **4100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25**    DAMAGE UNITS: **SF**  
COMMENTS: **Damage located on stage**

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **S-1**  
MATERIAL DESCRIPTION: **12x12 black w/ white specs**  
MATERIAL LOCATION: **Stage, Room 116**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School** INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S-2**  
MATERIAL DESCRIPTION: **12x12 black w/ white specs-mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stage, Room 116**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/18/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46371** BUIDLING ID: **1760**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School** REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel** IDPH LICENSE NO: **100-19717**

---

HOMOGENEOUS AREA: **S-2**  
MATERIAL DESCRIPTION: **12x12 black w/ white specs-mastic**  
MATERIAL LOCATION: **Stage, Room 116**  
MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2019 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46371**      BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Shaquille Crews**  
SCHOOL NAME: **King High School**      INSPECTION DATE: **4/18/2019**  
ADDRESS: **4445 S. Drexel**      IDPH LICENSE NO: **100-19717**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **12x12 lavender floor tile**  
MATERIAL LOCATION: **Room 226**  
MATERIAL QUANTITY: **550**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **HIGH**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **550**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/18/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **46371**      BUILDING ID: **1760**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **King High School**      REVIEW DATE: **5/7/2019**  
ADDRESS: **4445 S. Drexel**      IDPH LICENSE NO: **100-19717**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12x12 lavender floor tile**

MATERIAL LOCATION: **Room 226**

MATERIAL QUANTITY: **550**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **550**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### COMMENTS:

Sample to determine asbestos content, remove damaged ACBM

Management Planner's Signature: \_\_\_\_\_ Date: **05/07/2019**

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAQUILLE CREWS  
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the  
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI01

Certificate Number:



**PUBLIC HEALTH & SAFETY** Inc.

Environmental and Occupational Services  
37 E. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office 312-491-0081  
Fax 312-421-2901

Director of Training

**Nicholas J. Penoff**

Doctor of Public Health


Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
100 - 19717

ISSUED  
4/16/2019

EXPIRES  
05/15/2020

**SHAQUILLE CREWS**  
12823 S GREEN  
CHICAGO, IL 60643  
Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

1/30/2020

PROJECT MANAGER

3/29/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

2015



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director



**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384

  
Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19466**

ISSUED  
**4/12/2019**

EXPIRES  
**05/15/2020**

**EVAN I CHRISTIAN**  
3024 N RACINE AVE, APT 2  
CHICAGO, IL 60657



Environmental Health

**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

  
Kathy DeSalvo, Director

# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed