

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0767  
SCHOOL NAME: Juarez High School  
ADDRESS OF SCHOOL: 2150 S. Laflin  
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/4/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1688  
IDPH INSPECTOR LICENSE NUMBER: 100-08696  
IDPH LICENSED INSPECTOR NAME(Please Print): Ciniata Hester  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Juarez High School**

2150 S. Laflin  
Chicago, IL, 60608

Unit: 46421  
Building ID: 1890

IDPH ID Number: 14-016-2990-0767

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

May 6, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 46421            Region: 03            IDPH ID:14-016-2990-0767

School: Juarez High School            Building ID: 1890

Address: 2150 S. Laflin

Chicago, IL, 60608

Building Contact: Soto, Leonardo

Contact Phone:773 534 7034

Current Building Owners: Chicago Public Schools

Review Date: 05/24/2019

Inspector: Ciniata Hester

Inspector IDPH License: 100-08696

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates

Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 06, 2019

RE: Juarez High School, Unit 46421  
2150 S. Laflin  
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Juarez High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Juarez High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Juarez High School Unit: 46421 Region: 03  
Address: 2150 S. Laffin Chicago, IL, 60608  
IDPH ID: 14-016-2990-0767 Building ID: 1890  
Contact: Soto, Leonardo Phone: 773 534 7034

### 2. Description of Facility

Original Construction: 1975 Additional Construction:  
Total Square Footage: 158600 No of Floors: 3  
Current Occupancy: 1688

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Chicago, IL, 60607  
Phone: (312) 762-2900 Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Ciniata Hester

Inspector IDPH license # 100-08696  
Signature:  
Date: 5/6/2019

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466  
Signature:  
Date: 05/24/2019

### 7. Review Date:05/24/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Juarez High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1890:

110	Joint Compound
111	Drywall
126	Gaskets
146	Baseboard
147	Mastic Associated w/ Baseboard
28	Light Brown Ceramic Flooring & Grout
6C	12" x 12" Speckled Brown Floor Tile
6F	12" x 12" Yellow Floor Tile
8D	12" x 12" Reddish Brown Floor Tile

B. The following new homogenous areas have been identified for Building 1890:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12"x12" VFT Dark Orange
101	12"x12" VFT Dark Orange Mastic
102	12"x12" Gold VFT
103	12"x12" Gold VFT Mastic
104	12"x12" White Multi Specks VFT
105	12"x12" White Multi Specks VFT Mastic
106	12"x12" Green VFT
107	12"x12" Green VFT Mastic
108	12"x12" Orange/Brown VFT
109	12"x12" Orange/Brown VFT Mastic
110	Joint Compound
111	Drywall
112	2x2 Ceiling Tile
113	12"x12" Dark Orange VFT
114	12"x12" Dark Orange VFT Mastic
115	12"x12" Maroon VFT
116	12"x12" Maroon VFT Mastic
117	12"x12" Dull White VFT
118	12"x12" Dull White VFT Mastic
119	12"x12" Brown Blotted VFT
120	12"x12" Brown Blotted VFT Mastic
121	12"x12" Darkyellow VFT
122	12"x12" Darkyellow VFT Mastic
123	12"x12" Pinkish Red VFT
124	12"x12" Pinkish Red VFT Mastic
125	Brake Shoes
126	Gaskets
127	Grey Multicolored Carpet
128	12x12" White/Brown Specks VFT
129	12x12" White/Brown Specks VFT Mastic
130	12"x12" Bright Orange VFT
131	12"x12" Bright Orange VFT Mastic
132	12"x12" Bright Blue VFT
133	12"x12" Bright Blue VFT Mastic
134	12"x12" Bright Green VFT
135	12"x12" Bright Green VFT Mastic
136	2x2 Ceiling Tile
137	Window Caulk
138	Door Caulk
139	Spray on Fire Proofing
140	Red Sealant
141	2x2 Black Ceiling Tile

142	12'x8' Acoustic Panels
143	Light Blue Acoustic Panels
144	Orange Acoustic Panels
145	4'x4' Ceiling Tile
146	Baseboard
147	Mastic Associated w/ Baseboard
24	Gray Linoleum w/Black, White, Gray Spots
25	Gray Linoleum w/Black, White, Gray Spots Mastic
26	New Drywall
27	New Drywall Compound
28	Light Brown Ceramic Flooring & Grout
29	Light Brown Tile Mastic
30	Blue Grey Carpet Mastic
31	Grey Ceramic Flooring & Grout
32	Grey Ceramic Flooring Mastic
33	Brown & Gold Ceramic Flooring & Grout
34	Brown & Gold Ceramic Flooring Mastic
35	Brown & White Ceramic Flooring & Grout
36	Brown & White Ceramic Floor Mastic
37	Black Ceramic Flooring and Grout
38	Black Ceramic Flooring Mastic
39	Brown Ceramic Flooring & Grout
40	Brown Ceramic Flooring Mastic
6M	12" x 12" Blue Floor Tile
8M	12' x 12" Blue Floor Tile Mastic

The following areas were deemed to be inaccessible:

101	12"x12" VFT Dark Orange Mastic
103	12"x12" Gold VFT Mastic
105	12"x12" White Multi Specks VFT Mastic
107	12"x12" Green VFT Mastic
109	12"x12" Orange/Brown VFT Mastic
110	Joint Compound
114	12"x12" Dark Orange VFT Mastic
116	12"x12" Maroon VFT Mastic
118	12"x12" Dull White VFT Mastic
120	12"x12" Brown Blotted VFT Mastic
122	12"x12" Darkyellow VFT Mastic
124	12"x12" Pinkish Red VFT Mastic
125	Brake Shoes
126	Gaskets
129	12x12" White/Brown Specks VFT Mastic
131	12"x12" Bright Orange VFT Mastic
133	12"x12" Bright Blue VFT Mastic
135	12"x12" Bright Green VFT Mastic

136	2x2 Ceiling Tile
137	Window Caulk
138	Door Caulk
139	Spray on Fire Proofing
140	Red Sealant
147	Mastic Associated w/ Baseboard
29	Light Brown Tile Mastic
30	Blue Grey Carpet Mastic
32	Grey Ceramic Flooring Mastic
34	Brown & Gold Ceramic Flooring Mastic
36	Brown & White Ceramic Floor Mastic
38	Black Ceramic Flooring Mastic
40	Brown Ceramic Flooring Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Ciniata Hester, IDPH License # 100-08696. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Juarez High School Building 1890 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Hard Spray-on Fireproofing			1st Floor Corridor & 2nd Floor Gym	NO_ACBM	SURFACE								
10	Drywall Tape			3rd Floor Corridors, Classrooms 312, 332 & 335	NO_ACBM	MISC								
100	12"x12" VFT Dark Orange	1,200	SF	Room 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12"x12" VFT Dark Orange Mastic	1,200	SF	Room 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12"x12" Gold VFT	400	SF	Room 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	12"x12" Gold VFT Mastic	400	SF	Room 100	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12"x12" White Multi Specks VFT	4,500	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12"x12" White Multi Specks VFT Mastic	4,500	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12"x12" Green VFT	450	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12"x12" Green VFT Mastic	450	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"x12" Orange/Brown VFT	450	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12"x12" Orange/Brown VFT Mastic	450	SF	Clinic	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10A	Drywall Mud			3rd Floor Corridors, Classrooms 312, 332 & 335	NO_ACBM	MISC								
11	Roof Flashing - Not AHERA			Roof Top Deck	CHR	MISC								
110	Joint Compound	1,500	LF	Clinic	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
111	Drywall	8,000	SF	Clinic	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
112	2x2 Ceiling Tile	5,500	SF	Clinic	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
113	12"x12" Dark Orange VFT	2,500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12"x12" Dark Orange VFT Mastic	2,500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	12"x12" Maroon VFT	500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	12"x12" Maroon VFT Mastic	500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
117	12"x12" Dull White VFT	500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12"x12" Dull White VFT Mastic	500	SF	Medical Lab	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	12"x12" Brown Blotted VFT	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	Roof Field - Not AHERA			Roof	NO_ACBM	MISC								
120	12"x12" Brown Blotted VFT Mastic	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	12"x12" Darkyellow VFT	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	12"x12" Darkyellow VFT Mastic	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	12"x12" Pinkish Red VFT	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	12"x12" Pinkish Red VFT Mastic	600	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	Brake Shoes	5	EA	Elevators (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
126	Gaskets	10	EA	Generator Room (not observed)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
127	Grey Multicolored Carpet	3,200	SF	Auditorium, Band Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	12x12" White/Brown Specks VFT	2,200	SF	2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
129	12x12" White/Brown Specks VFT Mastic	2,200	SF	2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Carpet Mastic			1st Floor Corridors, 126 & Scattered Throughout 2nd Floor	NO_ACBM	MISC								
130	12"x12" Bright Orange VFT	800	SF	Rooms 275-280	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	12"x12" Bright Orange VFT Mastic	800	SF	2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	12"x12" Bright Blue VFT	800	SF	Rooms 275-280	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	12"x12" Bright Blue VFT Mastic	800	SF	2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	12"x12" Bright Green VFT	800	SF	Rooms 275-280	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12"x12" Bright Green VFT Mastic	800	SF	2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW





# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor										
20	Fume Hood	15	SF	Classrooms 319	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Concrete Floor			Throughout 3rd Floor	NO_ACBM	MISC								
22	Black Baseboard			Scattered Throughout 2nd Floor	NO_ACBM	MISC								
22D	Black Baseboard Adhesive			Scattered Throughout 2nd Floor	NO_ACBM	MISC								
23	Kilns	2	EA	0115	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Gray Linoleum w/Black, White, Gray Spots			Room 344	ASSUMED	MISC								
25	Gray Linoleum w/Black, White, Gray Spots Mastic			Room 344	ASSUMED	MISC								
26	New Drywall	1,500	SF	Cafeteria, Front Breezeway Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	New Drywall Compound	1,500	SF	Cafeteria, Front Breezeway Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Light Brown Ceramic Flooring & Grout	7,500	SF	Patio	ASSUMED	MISC	N	DIST	25		Yes	ACBM with the potential for damage	3	LOW
29	Light Brown Tile Mastic	7,500	SF	Patio	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3	2' x 2' Ceiling Tile			1st Floor Corridor & Swimming Pool Area	NO_ACBM	MISC								
30	Blue Grey Carpet Mastic	10,000	SF	2nd Floor Media Center	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	Grey Ceramic Flooring & Grout	160	SF	1st Floor Womens Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Grey Ceramic Flooring Mastic	160	SF	1st Floor Womens Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Brown & Gold Ceramic Flooring & Grout	200	SF	1st Floor Boys Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Brown & Gold Ceramic Flooring Mastic	200	SF	1st Floor Boys Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Brown & White Ceramic Flooring & Grout	200	SF	1st Floor Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Brown & White Ceramic Floor Mastic	200	SF	1st Floor Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Black Ceramic Flooring and Grout	720	SF	2nd, 3rd Floor Bpys Bathroom and 3rd Floor SW Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
38	Black Ceramic Flooring Mastic	720	SF	2nd, 3rd, Floor Boys Bathroom and 3rd Floor SW Rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Ceramic Flooring & Grout	1,800	SF	1st, 2nd Mens Bathroom, 2nd, 3rd Womens and Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
4	2' x 4' Ceiling Tile			Throughout 2nd Floor and Office	NO_ACBM	MISC								
40	Brown Ceramic Flooring Mastic	1,800	SF	1st, 2nd Mens Bathroom 2nd, 3rd Womens and Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
5	2' x 4' Ceiling tile			3rd Floor Corridors, Classrooms 312, 332, 333 & 335 (332 Carpet)	NO_ACBM	MISC								
6A	12" x 12" Crème w/White Speck Floor Tile			Basement	NO_ACBM	MISC								
6B	12" x 12" Speckled Red Floor Tile			2nd & 3rd Floor Stairwells & Basement	NO_ACBM	MISC								
6C	12" x 12" Speckled Brown Floor Tile	16,800	SF	Throughout 1st & 2nd Floors & Engineer's Office in Basement., Lunch Room	CHR	MISC	N	DIST	12		Yes	ACBM with the potential for damage	3	LOW
6D	12" x 12" Reddish Brown Floor Tile			1st Floor Corridor & Room 102	NO_ACBM	MISC								
6E	12" x 12" Green Floor Tile			1st Floor Stairwell	NO_ACBM	MISC								
6F	12" x 12" Yellow Floor Tile	15,500	SF	1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320	CHR	MISC	N	DIST	3,100		Yes	ACBM with the potential for damage	3	LOW
6G	12" x 12" Crème w/Black Spots Floor Tile			1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333	NO_ACBM	MISC								
6H	12" x 12" Speckled Black Floor Tile			1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226	NO_ACBM	MISC								
6I	12" x 12" Crème w/Brown Speck Floor Tile	8,000	SF	Rooms 250, 248, 224, 214, E and W Corridor Hallways	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
8K	12" x 12" Mottled Brown Floor Tile Mastic	80	SF	2nd and 3rd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8L	12" x 12" Pepper Floor Tile Mastic	3,000	SF	Classrooms 342, 340, and 338	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8M	12" x 12" Blue Floor Tile Mastic			MDF Room	ASSUMED	MISC								
9	Sink			3rd Floor Corridors, Classrooms 312, 332 & 335	NO_ACBM	MISC								
A	Fittings on Fiberglass Pipe Insulation			Boiler Room	NO_ACBM	MISC								
B	Canvas Wrap Over Breeching			Boiler Room	NO_ACBM	MISC								
C	Fiberglass Boiler Insulation			Boiler Room	NO_ACBM	MISC								
D	Boiler Breeching			Boiler Room	NO_ACBM	MISC								
E	Canvas Wrap Over Water Tank			Boiler Room	NO_ACBM	MISC								
F	Cementitious Pipe Fittings			Throughout 1st Floor and Pool Equipment Room	NO_ACBM	MISC								
G	Cementitious Pipe Fittings			Auto Shop (on Heater)/Throughout 1st Floor	NO_ACBM	MISC								
H	Gasket on Oven	10	LF	Classroom 334 (not observed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I	Boiler Gasket	60	LF	Boiler Room (not observed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>5/6/2019</b>
Inspector Name <b>Ciniata Hester</b>
<b>100-08696</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	Missing floor tiles in Room 113
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
119	
12	
120	
121	
122	
123	
124	
125	Not observed 2019
126	Not observed 2019
127	
128	
129	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	
144	

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
145	
146	
147	
15	
16	
17	
18	
19	
2	
20	
21	
22	
22D	
23	
24	Not observed 2016 - Now a painted epoxy floor (no change)
25	Not observed 2016 - Now a painted epoxy floor (no change)
26	
27	
28	Damage located on the patio
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	

# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
38	
39	
4	
40	
5	
6A	
6B	
6C	Damage is located in Room 248 (2SF) and 137 (10SF)
6D	
6E	
6F	Damage is located throughout 2nd floor
6G	
6H	
6I	
6J	
6K	
6L	
6M	
7	
8A	
8B	
8C	
8D	Damage located throughout 1st floor
8E	
8F	
8G	
8H	
8I	
8J	



# Chicago Public Schools

School Juarez High School Unit 46421 Building ID 1890

Address 2150 S. Laflin Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
8K	
8L	
8M	Not observed 2016 - Now carpet mastic
9	
A	
B	
C	
D	
E	
F	
G	
H	
I	

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Juarez High School

Unit 46421

Building ID 1890

Address 2150 S. Laflin

Chicago, IL, 60608

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard Spray-on Fireproofing			1st Floor Corridor & 2nd Floor Gym	No ACBM	SURFACE					Follow O&M Plan
10	Drywall Tape			3rd Floor Corridors, Classrooms 312, 332 & 335	No ACBM	MISC					
100	12"x12" VFT Dark Orange	1,200	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12"x12" VFT Dark Orange Mastic	1,200	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12"x12" Gold VFT	400	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12"x12" Gold VFT Mastic	400	SF	Room 100	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12"x12" White Multi Specks VFT	4,500	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12"x12" White Multi Specks VFT Mastic	4,500	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12"x12" Green VFT	450	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" Green VFT Mastic	450	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12"x12" Orange/Brown VFT	450	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12"x12" Orange/Brown VFT Mastic	450	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	Drywall Mud			3rd Floor Corridors, Classrooms 312, 332 & 335	No ACBM	MISC					
11	Roof Flashing - Not AHERA			Roof Top Deck	Chrysotile	MISC					
110	Joint Compound	1,500	LF	Clinic	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
111	Drywall	8,000	SF	Clinic	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	2x2 Ceiling Tile	5,500	SF	Clinic	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
113	12"x12" Dark Orange VFT	2,500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	12"x12" Dark Orange VFT Mastic	2,500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	12"x12" Maroon VFT	500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	12"x12" Maroon VFT Mastic	500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" Dull White VFT	500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12"x12" Dull White VFT Mastic	500	SF	Medical Lab	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12"x12" Brown Blotted VFT	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Roof Field - Not AHERA			Roof	No ACBM	MISC					
120	12"x12" Brown Blotted VFT Mastic	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12"x12" Darkyellow VFT	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	12"x12" Darkyellow VFT Mastic	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	12"x12" Pinkish Red VFT	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	12"x12" Pinkish Red VFT Mastic	600	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	Brake Shoes	5	EA	Elevators (not observed)	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	

# Chicago Public Schools

**School** Juarez High School

**Unit** 46421

**Building ID** 1890

**Address** 2150 S. Laflin

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
126	Gaskets	10	EA	Generator Room (not observed)	Assumed	TSI	Yes	0	EA	7 Any remaining friable ACBM or friable suspect ACBM	
127	Grey Multicolored Carpet	3,200	SF	Auditorium, Band Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	12x12" White/Brown Specks VFT	2,200	SF	2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	12x12" White/Brown Specks VFT Mastic	2,200	SF	2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Carpet Mastic			1st Floor Corridors, 126 & Scattered Throughout 2nd Floor	No ACBM	MISC					
130	12"x12" Bright Orange VFT	800	SF	Rooms 275-280	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12"x12" Bright Orange VFT Mastic	800	SF	2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12"x12" Bright Blue VFT	800	SF	Rooms 275-280	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12"x12" Bright Blue VFT Mastic	800	SF	2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12"x12" Bright Green VFT	800	SF	Rooms 275-280	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12"x12" Bright Green VFT Mastic	800	SF	2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	2x2 Ceiling Tile	12,000	SF	Bridge Corridor, Rooms 275-280, 2221-2224, 2213, 1118, 1123, 1126, E Hall Stairs, Boys/Girls Dressing Rooms, 1st Floor Corridor	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
137	Window Caulk	6,000	SF	Throughout 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
138	Door Caulk	4,000	SF	Throughout 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	Spray on Fire Proofing	50,000	SF	Throughout 2nd Floor	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Troweled on Sink Covering	8	SF	Room 337 (Faculty Lunch Room)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
140	Red Sealant	10,000	LF	Throughout 2nd Floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
141	2x2 Black Ceiling Tile	1,200	SF	Control Room Auditorium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
142	12'x8' Acoustic Panels	3,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	Light Blue Acoustic Panels	500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	Orange Acoustic Panels	500	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	4'x4' Ceiling Tile	7,500	SF	Auditorium, Room 281 Choir Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
146	Baseboard	8,000	LF	Throughout School	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
147	Mastic Associated w/ Baseboard	8,000	LF	Throughout School	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
15	Exterior Brick - Not AHERA			Exterior of Building	No ACBM	MISC					
16	Exterior Brick Mortar (Non AHERA)			Exterior of Building	No ACBM	MISC					

# Chicago Public Schools

School Juarez High School

Unit 46421

Building ID 1890

Address 2150 S. Laflin

Chicago, IL, 60608

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Cinder Block			Throughout 3rd Floor	No ACBM	MISC					
18	Cinder Block Mortar			Throughout 3rd Floor	No ACBM	MISC					
19	Plaster Ceiling			Exterior of Building at Entrances	No ACBM	MISC					
2	Soft Spray-on Fire Proofing			Throughout 2nd Floor	No ACBM	SURFACE					
20	Fume Hood	15	SF	Classrooms 319	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Concrete Floor			Throughout 3rd Floor	No ACBM	MISC					
22	Black Baseboard			Scattered Throughout 2nd Floor	No ACBM	MISC					
22D	Black Baseboard Adhesive			Scattered Throughout 2nd Floor	No ACBM	MISC					Follow O&M Plan
23	Kilns	2	EA	0115	Chrysotile	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
24	Gray Linoleum w/Black, White, Gray Spots			Room 344	Assumed	MISC					
25	Gray Linoleum w/Black, White, Gray Spots Mastic			Room 344	Assumed	MISC					Follow O&M Plan
26	New Drywall	1,500	SF	Cafeteria, Front Breezeway Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	New Drywall Compound	1,500	SF	Cafeteria, Front Breezeway Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Light Brown Ceramic Flooring & Grout	7,500	SF	Patio	Assumed	MISC	No	25	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Light Brown Tile Mastic	7,500	SF	Patio	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3	2' x 2' Ceiling Tile			1st Floor Corridor & Swimming Pool Area	No ACBM	MISC					
30	Blue Grey Carpet Mastic	10,000	SF	2nd Floor Media Center	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Grey Ceramic Flooring & Grout	160	SF	1st Floor Womens Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Grey Ceramic Flooring Mastic	160	SF	1st Floor Womens Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Brown & Gold Ceramic Flooring & Grout	200	SF	1st Floor Boys Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Brown & Gold Ceramic Flooring Mastic	200	SF	1st Floor Boys Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Brown & White Ceramic Flooring & Grout	200	SF	1st Floor Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Brown & White Ceramic Floor Mastic	200	SF	1st Floor Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Black Ceramic Flooring and Grout	720	SF	2nd, 3rd Floor Bpys Bathroom and 3rd Floor SW Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Black Ceramic Flooring Mastic	720	SF	2nd, 3rd, Floor Boys Bathroom and 3rd Floor SW Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown Ceramic Flooring & Grout	1,800	SF	1st, 2nd Mens Bathroom, 2nd, 3rd Womens and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	2' x 4' Ceiling Tile			Throughout 2nd Floor and Office	No ACBM	MISC					
40	Brown Ceramic Flooring Mastic	1,800	SF	1st, 2nd Mens Bathroom 2nd, 3rd Womens and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	2' x 4' Ceiling tile			3rd Floor Corridors, Classrooms 312,	No ACBM	MISC					

# Chicago Public Schools

School Juarez High School

Unit 46421

Building ID 1890

Address 2150 S. Laflin

Chicago, IL, 60608

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				332, 333 & 335 (332 Carpet)							
6A	12" x 12" Crème w/White Speck Floor Tile			Basement	No ACBM	MISC					
6B	12" x 12" Speckled Red Floor Tile			2nd & 3rd Floor Stairwells & Basement	No ACBM	MISC					
6C	12" x 12" Speckled Brown Floor Tile	16,800	SF	Throughout 1st & 2nd Floors & Engineer's Office in Basement., Lunch Room	Chrysotile	MISC	No	12	SF	6 ACBM with the potential for damage	Repair
6D	12" x 12" Reddish Brown Floor Tile			1st Floor Corridor & Room 102	No ACBM	MISC					
6E	12" x 12" Green Floor Tile			1st Floor Stairwell	No ACBM	MISC					
6F	12" x 12" Yellow Floor Tile	15,500	SF	1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320	Chrysotile	MISC	No	3,100	SF	6 ACBM with the potential for damage	Remove
6G	12" x 12" Crème w/Black Spots Floor Tile			1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333	No ACBM	MISC					
6H	12" x 12" Speckled Black Floor Tile			1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226	No ACBM	MISC					
6I	12" x 12" Crème w/Brown Speck Floor Tile	8,000	SF	Rooms 250, 248, 224, 214, E and W Corridor Hallways	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6J	12" x 12" Crème w/Gray Specks Floor Tile			Throughout 2nd Floor	No ACBM	MISC					
6K	12" x 12" Pepper Floor Tile			Classrooms 342, 340, and 338	No ACBM	MISC					
6L	12" x 12" Mottled Brown Floor Tile			2nd and 3rd Floor Corridors	No ACBM	MISC					
6M	12" x 12" Blue Floor Tile			MDF Room (205) Room 205 is a classroom with 12x12" White/Brown Specks VFT	Assumed	MISC					
7	Lab Tables and Counter Tops	800	SF	Classrooms 319 & 354	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8A	12" x 12" Crème w/White Speck Floor Tile Mastic	100	SF	Basement Womens Restroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8B	12" x 12" Speckled Red Floor Tile Mastic	300	SF	2nd & 3rd Floors Stairwells & Basement	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8C	12" x 12" Speckled Brown Floor Tile Mastic	16,800	SF	Throughout 1st & 2nd Floors & Engineer's Office in the Basement, Lunch Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8D	12" x 12" Reddish Brown Floor Tile	6,500	SF	Room 102, 124, and 1st floor hallway	Chrysotile	MISC	No	1,300	SF	6 ACBM with the potential for damage	Remove
8E	12" x 12" Green Floor Tile Mastic	200	SF	1st Floor Stairwell	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8F	12" x 12" Yellow Floor Tile Mastic	15,500	SF	1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8G	12" x 12" Crème w/Black Spots Floor Tile Mastic			1st & 2nd Floor Corridors & Rooms	No ACBM	MISC					

# Chicago Public Schools

School Juarez High School

Unit 46421

Building ID 1890

Address 2150 S. Laflin

Chicago, IL, 60608

Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				125, 312, 312, 330, 332 & 333							
8H	12" x 12" Speckled Black Floor Tile Mastic	150	SF	1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8I	12" x 12" Crème w/Brown Speck Floor Tile Mastic	8,000	SF	Throughout 2nd Floor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8J	12" x 12" Crème w/Gray Specks Floor Tile Mastic			Throughout 2nd Floor	No ACBM	MISC					
8K	12" x 12" Mottled Brown Floor Tile Mastic	80	SF	2nd and 3rd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8L	12" x 12" Pepper Floor Tile Mastic	3,000	SF	Classrooms 342, 340, and 338	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8M	12' x 12" Blue Floor Tile Mastic			MDF Room	Assumed	MISC					
9	Sink			3rd Floor Corridors, Classrooms 312, 332 & 335	No ACBM	MISC					
A	Fittings on Fiberglass Pipe Insulation			Boiler Room	No ACBM	MISC					
B	Canvas Wrap Over Breeching			Boiler Room	No ACBM	MISC					
C	Fiberglass Boiler Insulation			Boiler Room	No ACBM	MISC					
D	Boiler Breeching			Boiler Room	No ACBM	MISC					
E	Canvas Wrap Over Water Tank			Boiler Room	No ACBM	MISC					
F	Cementitious Pipe Fittings			Throughout 1st Floor and Pool Equipment Room	No ACBM	MISC					
G	Cementitious Pipe Fittings			Auto Shop (on Heater)/Throughout 1st Floor	No ACBM	MISC					
H	Gasket on Oven	10	LF	Classroom 334 (not observed)	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Boiler Gasket	60	LF	Boiler Room (not observed)	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Juarez High School

**Unit** 46421

**Building ID** 1890

**Address** 2150 S. Laflin

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	05/24/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
11	
110	



# Chicago Public Schools

**School** Juarez High School

**Unit** 46421

**Building ID** 1890

**Address** 2150 S. Laflin

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	
134	

# Chicago Public Schools

**School** Juarez High School  
**Address** 2150 S. Laflin

**Unit** 46421  
 Chicago, IL, 60608

**Building ID** 1890  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
135	
136	
137	
138	
139	
14	
140	
141	
142	
143	
144	
145	
146	
147	
15	
16	
17	
18	
19	
2	
20	
21	
22	
22D	
23	
24	

# Chicago Public Schools

**School** Juarez High School  
**Address** 2150 S. Laflin

**Unit** 46421  
 Chicago, IL, 60608

**Building ID** 1890  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
5	
6A	
6B	
6C	Repair or Remove damaged floor tile
6D	
6E	
6F	Remove/abate the damaged floor tile
6G	

# Chicago Public Schools

**School** Juarez High School

**Unit** 46421

**Building ID** 1890

**Address** 2150 S. Laflin

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
6H	
6I	
6J	
6K	
6L	
6M	
7	
8A	
8B	
8C	
8D	Remove and abate damaged floor tile
8E	
8F	
8G	
8H	
8I	
8J	
8K	
8L	
8M	
9	
A	
B	
C	
D	
E	

# Chicago Public Schools

**School** Juarez High School

**Unit** 46421

**Building ID** 1890

**Address** 2150 S. Laflin

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
F	
G	
H	
I	

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Hard Spray-on Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor & 2nd Floor Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Missing floor tiles in Room 113**

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard Spray-on Fireproofing**

MATERIAL LOCATION: **1st Floor Corridor & 2nd Floor Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Drywall Tape**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Drywall Tape**

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12"x12" VFT Dark Orange**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12"x12" VFT Dark Orange**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12"x12" VFT Dark Orange Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12"x12" VFT Dark Orange Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Gold VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **12"x12" Gold VFT**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12"x12" Gold VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **12"x12" Gold VFT Mastic**  
MATERIAL LOCATION: **Room 100**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12" White Multi Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **12"x12" White Multi Specks VFT**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" White Multi Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **12"x12" White Multi Specks VFT Mastic**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12"x12" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12"x12" Green VFT**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12"x12" Green VFT Mastic**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12"x12" Orange/Brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12"x12" Orange/Brown VFT**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12"x12" Orange/Brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12"x12" Orange/Brown VFT Mastic**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **Drywall Mud**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **Drywall Mud**

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof Top Deck**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Roof Top Deck**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Joint Compound**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**  
MATERIAL LOCATION: **Clinic**  
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Dark Orange VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **12"x12" Dark Orange VFT**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12" Dark Orange VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **12"x12" Dark Orange VFT Mastic**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"x12" Maroon VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12"x12" Maroon VFT**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Maroon VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12"x12" Maroon VFT Mastic**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Dull White VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12"x12" Dull White VFT**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Dull White VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12"x12" Dull White VFT Mastic**  
MATERIAL LOCATION: **Medical Lab**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Brown Blotted VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12"x12" Brown Blotted VFT**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Roof Field - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Roof Field - Not AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Brown Blotted VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12"x12" Brown Blotted VFT Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Darkyellow VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12"x12" Darkyellow VFT**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Darkyellow VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **12"x12" Darkyellow VFT Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Pinkish Red VFT**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12"x12" Pinkish Red VFT**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12"x12" Pinkish Red VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **12"x12" Pinkish Red VFT Mastic**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Brake Shoes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevators (not observed)**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**  
COMMENTS: **Not observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **Brake Shoes**  
MATERIAL LOCATION: **Elevators (not observed)**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Generator Room (not observed)**  
MATERIAL QUANTITY: **10**    MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **EA**  
COMMENTS: **Not observed 2019**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Gaskets**  
MATERIAL LOCATION: **Generator Room (not observed)**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Grey Multicolored Carpet**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Band Room**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **Grey Multicolored Carpet**  
MATERIAL LOCATION: **Auditorium, Band Room**  
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12x12" White/Brown Specks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **12x12" White/Brown Specks VFT**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12x12" White/Brown Specks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **12x12" White/Brown Specks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridors, 126 & Scattered Throughout 2nd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **1st Floor Corridors, 126 & Scattered Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12"x12" Bright Orange VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12"x12" Bright Orange VFT**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12"x12" Bright Orange VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12"x12" Bright Orange VFT Mastic**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue VFT**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue VFT Mastic**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x12" Bright Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **12"x12" Bright Green VFT**  
MATERIAL LOCATION: **Rooms 275-280**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12"x12" Bright Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12"x12" Bright Green VFT Mastic**  
MATERIAL LOCATION: **2nd Floor**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bridge Corridor, Rooms 275-280, 2221-2224, 2213, 1118, 1123, 1126, E Hall Stairs, Boys/Girls Dressing Rooms, 1st Floor Corridor**

MATERIAL QUANTITY: **12000**    MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **2x2 Ceiling Tile**  
MATERIAL LOCATION: **Bridge Corridor, Rooms 275-280, 2221-2224, 2213, 1118, 1123, 1126, E Hall Stairs, Boys/Girls Dressing Rooms, 1st Floor Corridor**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **6000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **Window Caulk**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **Door Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **Door Caulk**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **Spray on Fire Proofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **Spray on Fire Proofing**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Troweled on Sink Covering**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 337 (Faculty Lunch Room)**  
MATERIAL QUANTITY: **8**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Troweled on Sink Covering**

MATERIAL LOCATION: **Room 337 (Faculty Lunch Room)**

MATERIAL QUANTITY: **8**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **Red Sealant**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **Red Sealant**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **2x2 Black Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Control Room Auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **2x2 Black Ceiling Tile**  
MATERIAL LOCATION: **Control Room Auditorium**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12'x8' Acoustic Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **142**  
MATERIAL DESCRIPTION: **12'x8' Acoustic Panels**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **Light Blue Acoustic Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **Light Blue Acoustic Panels**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **Orange Acoustic Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **Orange Acoustic Panels**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **4'x4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Room 281 Choir Room**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **4'x4' Ceiling Tile**  
MATERIAL LOCATION: **Auditorium, Room 281 Choir Room**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **Baseboard**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **Mastic Associated w/ Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **Mastic Associated w/ Baseboard**  
MATERIAL LOCATION: **Throughout School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Exterior Brick Mortar (Non\_AHERA)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar (Non\_AHERA)**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **Cinder Block**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Cinder Block Mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Plaster Ceiling**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building at Entrances**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **Exterior of Building at Entrances**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**  
MATERIAL DESCRIPTION: **Soft Spray-on Fire Proofing**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Soft Spray-on Fire Proofing**

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Fume Hood**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 319**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Fume Hood**

MATERIAL LOCATION: **Classrooms 319**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Concrete Floor**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Concrete Floor**

MATERIAL LOCATION: **Throughout 3rd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Black Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Scattered Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22D**  
MATERIAL DESCRIPTION: **Black Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Scattered Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **22D**

MATERIAL DESCRIPTION: **Black Baseboard Adhesive**

MATERIAL LOCATION: **Scattered Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Kilns**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **0115**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Kilns**  
MATERIAL LOCATION: **0115**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Gray Linoleum w/Black, White, Gray Spots**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 344**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now a painted epoxy floor (no change)**

Inspector's Signature: \_\_\_\_\_

Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Gray Linoleum w/Black, White, Gray Spots**

MATERIAL LOCATION: **Room 344**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Gray Linoleum w/Black, White, Gray Spots Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 344**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now a painted epoxy floor (no change)**

Inspector's Signature: \_\_\_\_\_

Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Gray Linoleum w/Black, White, Gray Spots Mastic**

MATERIAL LOCATION: **Room 344**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **New Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Front Breezeway Corridor**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **New Drywall**  
MATERIAL LOCATION: **Cafeteria, Front Breezeway Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **New Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, Front Breezeway Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **New Drywall Compound**  
MATERIAL LOCATION: **Cafeteria, Front Breezeway Corridor**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Light Brown Ceramic Flooring & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Patio**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located on the patio**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Light Brown Ceramic Flooring & Grout**  
MATERIAL LOCATION: **Patio**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **25** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Light Brown Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Patio**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Light Brown Tile Mastic**

MATERIAL LOCATION: **Patio**

MATERIAL QUANTITY: **7500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor & Swimming Pool Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile**

MATERIAL LOCATION: **1st Floor Corridor & Swimming Pool Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Blue Grey Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd Floor Media Center**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Blue Grey Carpet Mastic**  
MATERIAL LOCATION: **2nd Floor Media Center**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Grey Ceramic Flooring & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Womens Bathroom**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Grey Ceramic Flooring & Grout**

MATERIAL LOCATION: **1st Floor Womens Bathroom**

MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Grey Ceramic Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Womens Bathroom**  
MATERIAL QUANTITY: **160**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Grey Ceramic Flooring Mastic**

MATERIAL LOCATION: **1st Floor Womens Bathroom**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Brown & Gold Ceramic Flooring & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Boys Bathroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Brown & Gold Ceramic Flooring & Grout**

MATERIAL LOCATION: **1st Floor Boys Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Brown & Gold Ceramic Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Boys Bathroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Brown & Gold Ceramic Flooring Mastic**

MATERIAL LOCATION: **1st Floor Boys Bathroom**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown & White Ceramic Flooring & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Girls Bathroom**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown & White Ceramic Flooring & Grout**  
MATERIAL LOCATION: **1st Floor Girls Bathroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Brown & White Ceramic Floor Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Girls Bathroom**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Brown & White Ceramic Floor Mastic**

MATERIAL LOCATION: **1st Floor Girls Bathroom**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Black Ceramic Flooring and Grout**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd Floor Bpys Bathroom and 3rd Floor SW Rooms**  
MATERIAL QUANTITY: **720**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Black Ceramic Flooring and Grout**  
MATERIAL LOCATION: **2nd, 3rd Floor Bpys Bathroom and 3rd Floor SW Rooms**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Black Ceramic Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd, Floor Boys Bathroom and 3rd Floor SW Rooms**  
MATERIAL QUANTITY: **720**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Black Ceramic Flooring Mastic**  
MATERIAL LOCATION: **2nd, 3rd, Floor Boys Bathroom and 3rd Floor SW Rooms**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring & Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd Mens Bathroom, 2nd, 3rd Womens and Girls Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring & Grout**  
MATERIAL LOCATION: **1st, 2nd Mens Bathroom, 2nd, 3rd Womens and Girls Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2nd Floor and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Throughout 2nd Floor and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd Mens Bathroom 2nd, 3rd Womens and Girls Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Brown Ceramic Flooring Mastic**  
MATERIAL LOCATION: **1st, 2nd Mens Bathroom 2nd, 3rd Womens and Girls Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332, 333 & 335 (332 Carpet)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **2' x 4' Ceiling tile**

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332, 333 & 335 (332 Carpet)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/White Speck Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **12" x 12" Crème w/White Speck Floor Tile**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6B**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Stairwells & Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6B**

MATERIAL DESCRIPTION: **12" x 12" Speckled Red Floor Tile**

MATERIAL LOCATION: **2nd & 3rd Floor Stairwells & Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6C**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st & 2nd Floors & Engineer's Office in Basement., Lunch Room**  
MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located in Room 248 (2SF) and 137 (10SF)**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6C**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile**  
MATERIAL LOCATION: **Throughout 1st & 2nd Floors & Engineer's Office in Basement., Lunch Room**  
MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Repair or Remove damaged floor tile

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6D**  
MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor & Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6D**

MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor & Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6E**  
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Stairwell**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6E**

MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile**

MATERIAL LOCATION: **1st Floor Stairwell**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6F**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320**  
MATERIAL QUANTITY: **15500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3100** DAMAGE UNITS: **SF**  
COMMENTS: **Damage is located throughout 2nd floor**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6F**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**  
MATERIAL LOCATION: **1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320**  
MATERIAL QUANTITY: **15500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **3100** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Remove/abate the damaged floor tile

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6G**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Black Spots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6G**

MATERIAL DESCRIPTION: **12" x 12" Crème w/Black Spots Floor Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6H**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Black Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6H**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Black Floor Tile**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6I**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Brown Speck Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 250, 248, 224, 214, E and W Corridor Hallways**  
MATERIAL QUANTITY: **8000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6I**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Brown Speck Floor Tile**  
MATERIAL LOCATION: **Rooms 250, 248, 224, 214, E and W Corridor Hallways**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6J**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6J**

MATERIAL DESCRIPTION: **12" x 12" Crème w/Gray Specks Floor Tile**

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6K**  
MATERIAL DESCRIPTION: **12" x 12" Pepper Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 342, 340, and 338**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6K**

MATERIAL DESCRIPTION: **12" x 12" Pepper Floor Tile**

MATERIAL LOCATION: **Classrooms 342, 340, and 338**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6L**  
MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6L**

MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6M**  
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MDF Room (205) Room 205 is a classroom with 12x12" White/Brown Specks VFT**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **6M**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **MDF Room (205) Room 205 is a classroom with 12x12" White/Brown Specks VFT**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**  
MATERIAL DESCRIPTION: **Lab Tables and Counter Tops**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 319 & 354**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Lab Tables and Counter Tops**

MATERIAL LOCATION: **Classrooms 319 & 354**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/White Speck Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement Womens Restroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/White Speck Floor Tile Mastic**  
MATERIAL LOCATION: **Basement Womens Restroom**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd & 3rd Floors Stairwells & Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Red Floor Tile Mastic**  
MATERIAL LOCATION: **2nd & 3rd Floors Stairwells & Basement**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8C**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1st & 2nd Floors & Engineer's Office in the Basement, Lunch Room**  
MATERIAL QUANTITY: **16800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8C**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout 1st & 2nd Floors & Engineer's Office in the Basement, Lunch Room**  
MATERIAL QUANTITY: **16800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8D**  
MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Deterioration  
Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 102, 124, and 1st floor hallway**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1300** DAMAGE UNITS: **SF**  
COMMENTS: **Damage located throughout 1st floor**

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8D**  
MATERIAL DESCRIPTION: **12" x 12" Reddish Brown Floor Tile**  
MATERIAL LOCATION: **Room 102, 124, and 1st floor hallway**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **1300** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Remove and abate damaged floor tile

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8E**  
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Stairwell**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8E**  
MATERIAL DESCRIPTION: **12" x 12" Green Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Stairwell**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8F**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320**  
MATERIAL QUANTITY: **15500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8F**  
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 3rd Floor Corridors, Throughout 2nd Floor & Rooms 312 & 320**  
MATERIAL QUANTITY: **15500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8G**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Black Spots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8G**

MATERIAL DESCRIPTION: **12" x 12" Crème w/Black Spots Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors & Rooms 125, 312, 312, 330, 332 & 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8H**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Black Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226**  
MATERIAL QUANTITY: **150**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8H**  
MATERIAL DESCRIPTION: **12" x 12" Speckled Black Floor Tile Mastic**  
MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, 230, 248, 207, and 226**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

## Carnow, Conibear and Associates 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8I**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Brown Speck Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8I**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Brown Speck Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout 2nd Floor**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8J**  
MATERIAL DESCRIPTION: **12" x 12" Crème w/Gray Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

**2019 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8J**

MATERIAL DESCRIPTION: **12" x 12" Crème w/Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8K**  
MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8K**

MATERIAL DESCRIPTION: **12" x 12" Mottled Brown Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8L**  
MATERIAL DESCRIPTION: **12" x 12" Pepper Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms 342, 340, and 338**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8L**

MATERIAL DESCRIPTION: **12" x 12" Pepper Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms 342, 340, and 338**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8M**  
MATERIAL DESCRIPTION: **12' x 12" Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MDF Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016 - Now carpet mastic**

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **8M**

MATERIAL DESCRIPTION: **12' x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **MDF Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Sink**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Sink**

MATERIAL LOCATION: **3rd Floor Corridors, Classrooms 312, 332 & 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Canvas Wrap Over Breeching**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Canvas Wrap Over Breeching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Fiberglass Boiler Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Fiberglass Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Breeching**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Boiler Breaching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Canvas Wrap Over Water Tank**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Canvas Wrap Over Water Tank**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1st Floor and Pool Equipment Room**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**

MATERIAL LOCATION: **Throughout 1st Floor and Pool Equipment Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **46421**    BUILDING ID: **1890**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School**    INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin**    IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auto Shop (on Heater)/Throughout 1st Floor**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **05/06/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Cementitious Pipe Fittings**

MATERIAL LOCATION: **Auto Shop (on Heater)/Throughout 1st Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Gasket on Oven**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classroom 334 (not observed)**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019



# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Gasket on Oven**

MATERIAL LOCATION: **Classroom 334 (not observed)**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Ciniata Hester**  
SCHOOL NAME: **Juarez High School** INSPECTION DATE: **5/6/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room (not observed)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 05/06/2019

# Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46421** BUIDLING ID: **1890**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Juarez High School** REVIEW DATE: **5/24/2019**  
ADDRESS: **2150 S. Laflin** IDPH LICENSE NO: **100-08696**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Boiler Gasket**  
MATERIAL LOCATION: **Boiler Room (not observed)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **05/24/2019**

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2019 AHERA REINSPECTION***

# APPENDIX B

## Inspector and Management Planner Licenses

---

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

**Ciniata Hester**


has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/22/2019 - 1/24/2019

Exam Date: 1/24/2019

Expiration Date: 1/24/2020

Certificate Number: ABI1901240284



---

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**CINIATA R HESTER**  
10651 S. SANGAMON ST  
CHICAGO, IL 60643

3/5/2019



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 08696

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>	
<b>ID NUMBER</b> 100 - 08696	<b>ISSUED</b> 3/5/2019	<b>EXPIRES</b> 05/15/2020	<b>ENDORSEMENTS</b>
<b>CINIATA R HESTER</b> 10651 S. SANGAMON ST CHICAGO, IL 60643 Environmental Health			<b>TC EXPIRES</b> 1/24/2020
			INSPECTOR PROJECT MANAGER AIR SAMPLING PROFESSIONAL
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2015



# OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159

  
Katy DeSalvo, Director



**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Initial Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384

  
Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 19466**

ISSUED  
**4/12/2019**

EXPIRES  
**05/15/2020**

**EVAN I CHRISTIAN**  
3024 N RACINE AVE, APT 2  
CHICAGO, IL 60657

Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019


Expiration Date: 1/7/2020

Certificate Number: MPR1901070063

  
\_\_\_\_\_  
Kathy DeSalvo, Director

# Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW  
CONIBEAR**

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---



## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed