

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0004
SCHOOL NAME: Bowen Campus
ADDRESS OF SCHOOL: 2710 E. 89th St.
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/11/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 236
IDPH INSPECTOR LICENSE NUMBER: 100-03613
IDPH LICENSED INSPECTOR NAME(Please Print): Daniel Juneau
IDPH MP LICENSE NUMBER: 100-09786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Bowen Campus

2710 E. 89th St.
Chicago, IL, 60617

Unit: 46491
Building ID: 1240

IDPH ID Number: 14-016-2990-0004

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 17, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 46051 Region: 06 IDPH ID:14-016-2990-0004

School: Bowen Campus Building ID: 1240

Address: 2710 E. 89th St.

Chicago, IL, 60617

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/05/2019

Inspector: Daniel Juneau

Inspector IDPH License: 100-03613

Management Planner: John Fenn

Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

John Fenn
100-09786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 17, 2019

RE: Bowen Campus, Unit 46491
2710 E. 89th St.
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Bowen Campus, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Bowen Campus, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Bowen Campus
Address: 2710 E. 89th St.
IDPH ID: 14-016-2990-0004
Contact: Unit: 46051
Chicago, IL, 60617
Building ID: 1240
Phone: Region: 06

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 236

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602
Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880
Fax: 630-790-0882

5. Inspector

Inspector Name: Daniel Juneau

Inspector IDPH license # 100-03613

Signature:
Date: 8/17/2019

6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:
Date: 09/05/2019

7. Review Date:09/05/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bowen Campus. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1240:

D Pipe Fitting Insulation

B. The following new homogenous areas have been identified for Building 1240:

200	1x1 Pink Ceramic Flooring
201	Boiler Breeching

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12x12 Tan w/Brown Specks Floor Tile
01AFT	12X12 Green w/Green Specks VFT
01AM	12x12 Green w/Green Specks VFT Mastic
01CM	12x12 Dark Gray w/Specks VFT Mastic
02	9x9 Floor Tile
03FT6	12x12 Brown Floor Tile
03FT8	12x12 Beige Speckled Floor Tile
04	Tectum Ceiling
06	Linoleum Floor
06FT11	12x12 Gray Floor Tile
06FT12	12x12 Light Blue Floor Tile Mastic-under carpet
06FT13	12x12 White w/Tan Specks Floor Tile
06FT14	12x12 Cream Floor Tile
06FT7	12x12 Light Brown Floor Tile
07FT9	12x12 Red Floor Tile-NOT OBSERVED
09	12x12 Tan w/Brown Specks Floor Tile Mastic
09FT12	12x12 Light Blue Floor Tile
09FT13	12x12 White w/Tan Specks Floor Tile Mastic
09FT14	12x12 Cream Floor Tile Mastic
09FT5	12x12 Dark Brown and Cream Speckled FT Mastic
100	2' X 4' White w/Pin-Holes Ceiling Tile
101	Terrazo
102	Plaster
103	Air Cell
104	2' X 4' Ceiling Tile
105	12" X 12" Light Purple Mixed Speckled VFT
106	12" X 12" Light Purple Mixed Speckled Mastic
107	12X12 Light Vanilla Floor Tile Mastic
108	Spray-On
109	Lab Tables
16	12x12 Floor Tile Mastic
16FT6	12x12 Brown Floor Tile Mastic
16FT8	12x12 Beige Speckled Floor Tile
17	9x9 Maroon and Tan Floor Tile Mastic
19	Linoleum Mastic
1BFT	12x12 Light Gray w/Gray and White Specks VFT
1BM	12x12 Gray w/Gray and White Specks VFT Mastic
1CFT	12x12 Dark Gray w/Specks VFT
1CM	Carpet Mastic
1DS	Drywall System
20	9x9 Floor Tile Mastic
200	1x1 Pink Ceramic Flooring

201	Boiler Breeching
22	12x12 Beige w/White Streaks Floor Tile
23	12x12 Beige w/White Streaks Floor Tile Mastic
24	Turquoise Carpet Mastic
25	12x12 Gray Floor Tile
26	12x12 Gray Floor Tile Mastic
28	Gray Carpet Mastic
33	Black Baseboard
34	Black Baseboard Mastic
35	9x9 Brown Floor Tile
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic
37	9x9 Tan Floor Tile
38	9x9 Dark Brown Floor Tile
39	Brown Carpet Mastic
40	Brown Carpet w/Dots
41	Blue Carpet Mastic
42	Gray Carpet, Gray Carpet Mastic
42A	2'X2' Smooth Ceiling Tile
42B	Rubber Floor Mastic
43	Light Brown Baseboard
44	Light Brown Baseboard Mastic
45	12x12 Gray w/Green Spots Floor Tile
46	12x12 Gray w/Green Spots Floor Tile Mastic
47	Gray Baseboard
48	Gray Baseboard Mastic
49	Black Baseboard
50	Black Baseboard Mastic
51	Blue Baseboard
52	Blue Baseboard Mastic
53	Turquoise Baseboard
54	Turquoise Baseboard Mastic
55	Tan Linoleum
56	Tan Linoleum, Mastic
57	Brown Baseboard
58	Brown Baseboard Mastic
59	Blue Linoleum
60	Blue Linoleum Mastic
61	Tan Baseboard
62	Tan Baseboard Mastic
63	2x4 Ceiling Tile
64	Blue Carpet
65	Blue Carpet Mastic
66	Beige Linoleum
67	Vibration Collar
75	12 x 12 Light Vanilla VFT
76	TSI on HVAC Ducts
77	Hard Packed Fittings on Fiberglass Insulated Pipes
78	Linoleum and Associated Adhesive

79	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Glue
80	Plaster
81	Plaster
82	12x12 Orange and White Floor Tile
83	12 x 12 Orange and White Floor Tile Mastic
84	12x12 Orange Floor Tile
85	12x12 Orange Floor Tile Mastic
86	12x12 Light Vanilla Floor Tile Mastic
87	Carpet Mastic
88	Linoleum
89	Lab Counter Tops
90	9X9 Gray w/White Streaks Vinyl Floor Tile
91	9X9 Gray w/White Streaks Vinyl Floor Tile Mastic
92	12" X 12" Light Cream Mixed Speckled VFT
93	12" X 12" Light Cream Mixed Speckled VFT Mastic
94	12" X 12" Vanilla Mixed Speckled VFT
95	12" X 12" Vanilla Mixed Speckled VFT Mastic
96	12" X 12" White w/Blue Specks VFT
97	12" X 12" White w/Blue Specks VFT Mastic
98	12" X 12" Light Tan w/Streaks VFT
99	12" X 12" Light Tan w/Streaks Mastic
D	Pipe Fitting Insulation
HA-1001	1'x1' White Ceiling Tile w/Holes Glue-NOT OBSERVED
HA-1002	Mudded Pipe Fittings
HA-1003	Mudded Pipe Fittings

The following areas were deemed to be inaccessible:

01AM	12x12 Green w/Green Specks VFT Mastic
01CM	12x12 Dark Gray w/Specks VFT Mastic
04	Tectum Ceiling
05	9x9 Floor Tile ABATED 1991
09	12x12 Tan w/Brown Specks Floor Tile Mastic
09FT13	12x12 White w/Tan Specks Floor Tile Mastic
09FT14	12x12 Cream Floor Tile Mastic
09FT5	12x12 Dark Brown and Cream Speckled FT Mastic
09FT7	12x12 Light Brown Floor Tile Mastic
106	12" X 12" Light Purple Mixed Speckled Mastic
107	12X12 Light Vanilla Floor Tile Mastic
16	12x12 Floor Tile Mastic
16FT-2	12x12 Cream Floor Tile Mastic
16FT10	12x12 Orange and White Floor Tile Mastic
16FT3	12x12 Green Floor Tile Mastic

16FT4	9x9 White w/Green Specks Floor Tile Mastic
16FT6	12x12 Brown Floor Tile Mastic
16FT7	12x12 Light Brown Floor Tile Mastic
17	9x9 Maroon and Tan Floor Tile Mastic
19	Linoleum Mastic
1BM	12x12 Gray w/Gray and White Specks VFT Mastic
1CM	Carpet Mastic
20	9x9 Floor Tile Mastic
20FT1	9x9 Dark Brown Floor Tile Mastic
20FT2	9x9 light Gray Floor Tile Mastic
23	12x12 Beige w/White Streaks Floor Tile Mastic
26	12x12 Gray Floor Tile Mastic
28	Gray Carpet Mastic
34	Black Baseboard Mastic
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic
39	Brown Carpet Mastic
42B	Rubber Floor Mastic
44	Light Brown Baseboard Mastic
46	12x12 Gray w/Green Spots Floor Tile Mastic
48	Gray Baseboard Mastic
50	Black Baseboard Mastic
52	Blue Baseboard Mastic
54	Turquoise Baseboard Mastic
56	Tan Linoleum, Mastic
58	Brown Baseboard Mastic
60	Blue Linoleum Mastic
62	Tan Baseboard Mastic
63	2x4 Ceiling Tile
65	Blue Carpet Mastic
83	12 x 12 Orange and White Floor Tile Mastic
85	12x12 Orange Floor Tile Mastic
86	12x12 Light Vanilla Floor Tile Mastic
87	Carpet Mastic
91	9X9 Gray w/White Streaks Vinyl Floor Tile Mastic
93	12" X 12" Light Cream Mixed Speckled VFT Mastic
95	12" X 12" Vanilla Mixed Speckled VFT Mastic
97	12" X 12" White w/Blue Specks VFT Mastic
99	12" X 12" Light Tan w/Streaks Mastic
9FT11	12x12 Gray Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Daniel Juneau, IDPH License # 100-03613. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Bowen Campus Building 1240 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12x12 Tan w/Brown Specks Floor Tile	6,400	SF	Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01AFT	12X12 Green w/Green Specks VFT	1,400	SF	Rooms 229, 241, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01AM	12x12 Green w/Green Specks VFT Mastic	1,400	SF	Rooms 229, 241, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
01CM	12x12 Dark Gray w/Specks VFT Mastic	300	SF	261 Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	9x9 Floor Tile	0	SF	Main Building- 2nd and 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02FT1	9x9 Dark Brown Floor Tile	1,200	SF	Main Building- Rooms 210, 211, 212	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02FT2	9x9 Light Gray Floor Tile	900	SF	Main Building Room 312	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT14	12x12 Cream Floor Tile	60,000	SF	Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT3	12x12 Green Floor Tile	800	SF	Main Building- Principal's Office, Conference Room Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT4	9x9 White w/Green Specks Floor Tile	900	SF	Main Building- Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT6	12x12 Brown Floor Tile	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03FT7	12x12 Light Brown Speckled Floor Tile	15,000	SF	Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor										
03FT8	12x12 Beige Speckled Floor Tile	400	SF	Main Building-Room 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
04	Tectum Ceiling	5,000	SF	Main Building-Gymnasium	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
05	9x9 Floor Tile ABATED 1991			Annex 1st and 2nd Floor	ABATED	MISC								
06	Linoleum Floor	950	SF	Main Building-Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT11	12x12 Gray Floor Tile	14,000	SF	Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT12	12x12 Light Blue Floor Tile Mastic-under carpet	2,000	SF	Annex 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT13	12x12 White w/Tan Specks Floor Tile	1,800	SF	Annex Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT14	12x12 Cream Floor Tile	5,000	SF	Annex 1st and 2nd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT5	12x12 Dark Brown and Cream Speckled Floor Tile	7,200	SF	Annex Rooms: 241, 240, 229, 242, 129, 229A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06FT7	12x12 Light Brown Floor Tile	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07FT9	12x12 Red Floor Tile-NOT OBSERVED			Main Building-Lunchroom	ASSUMED	MISC								
09	12x12 Tan w/Brown Specks Floor Tile Mastic	6,400	SF	Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT12	12x12 Light Blue Floor Tile	2,500	SF	Annex 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT13	12x12 White w/Tan Specks Floor Tile Mastic	750	SF	Annex Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT14	12x12 Cream Floor Tile Mastic	1,850	SF	Annex 1st and 2nd	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Hallways								potential for damage		
09FT5	12x12 Dark Brown and Cream Speckled FT Mastic	7,200	SF	Annex rooms 240, 242, 129, 229A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09FT7	12x12 Light Brown Floor Tile Mastic	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	2' X 4' White w/Pin-Holes Ceiling Tile	4,300	SF	Throughout 1939 Building, Elevator Lobbies	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
101	Terrazo	2,000	SF	1939 Building- Stairwell and Baseboard	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	Plaster	17,000	SF	Throughout 1939 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
103	Air Cell	100	LF	1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
104	2' X 4' Ceiling Tile	10,000	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
105	12" X 12" Light Purple Mixed Speckled VFT	400	SF	Annex- Lobby to Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12" X 12" Light Purple Mixed Speckled Mastic	400	SF	Annex- Lobby to Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12X12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	Spray-On	1,200	SF	1st and 2nd Floor Entrance and Breezeway	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
109	Lab Tables	400	SF	Annex 229	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Transite Panels ABATED			Swimming Pool and Locker Rooms	ABATED									
16	12x12 Floor Tile Mastic	162,000	SF	Main Building, 2nd, 3rd and 4th Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT-2	12x12 Cream Floor Tile Mastic	60,000	SF	1st, 2nd, 3rd, & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A										
16FT10	12x12 Orange and White Floor Tile Mastic	100	SF	Main Building-Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT3	12x12 Green Floor Tile Mastic	600	SF	Main Building-Principal's Office, Conference Room Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT4	9x9 White w/Green Specks Floor Tile Mastic	900	SF	Main Building, Room 202	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT6	12x12 Brown Floor Tile Mastic	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT7	12x12 Light Brown Floor Tile Mastic	16,000	SF	Main Building-Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT8	12x12 Beige Speckled Floor Tile	1,000	SF	Main Building-Room 308	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16FT9	12x12 Red Floor Tile Mastic-VFT NOT OBSERVED			Main Building-Lunchroom	CHR	MISC								
17	9x9 Maroon and Tan Floor Tile Mastic	900	SF	Main Building-Swimming Pool and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Linoleum Mastic	950	SF	1908 Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1BFT	12x12 Light Gray w/Gray and White Specks VFT	4,300	SF	Rooms 229, 241, 229A, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1BM	12x12 Gray w/Gray and White Specks VFT Mastic	4,300	SF	Rooms 229, 241, 229A, 261	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1CFT	12x12 Dark Gray w/Specks VFT	300	SF	261 Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1CM	Carpet Mastic	6,400	SF	Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 240	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1DS	Drywall System		SF	Room 231, 2nd Floor Breezeway,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1st Floor Breezeway										
20	9x9 Floor Tile Mastic	0	SF	Main Building- 2nd and 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
200	1x1 Pink Ceramic Flooring	600	SF	Girls' Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
201	Boiler Breeching	1,200	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
20FT1	9x9 Dark Brown Floor Tile Mastic	1,800	SF	Main Building- Rooms 200, 211-212	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20FT2	9x9 light Gray Floor Tile Mastic	900	SF	Main Building- Room 312	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	9x9 Floor Tile Mastic ABATED			Annex Room and Office	ABATED									
22	12x12 Beige w/White Streaks Floor Tile	200	SF	Main Building - Room 211 and 211A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 Beige w/White Streaks Floor Tile Mastic	200	SF	Main Building - Room 211 and 211A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	Turquoise Carpet Mastic	400	SF	Main Building - Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12x12 Gray Floor Tile	600	SF	Main Building - Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Gray Floor Tile Mastic	1,000	SF	Main Building - Gym Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	Gray Carpet Mastic	600	SF	Main Building - Room 400	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Gray Linoleum - ABATED			Main Building - Room 306	ABATED	MISC						ACBM with the potential for damage		
30	Gray Linoleum Mastic - ABATED			Main Building- Room 306	ABATED	MISC								
31	Brown Baseboard - Abated			Main Building- Room 306	ABATED	MISC								
32	Brown Baseboard Mastic - ABATED			Main Building- Room 306	ABATED	MISC								
33	Black Baseboard	75	LF	Main Building - Boys Gym, 2nd floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Black Baseboard Mastic	75	LF	Main Building - Boys' Gym, 2nd floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	9x9 Brown Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic	15	SF	Main Building - Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	9x9 Tan Floor Tile	15	SF	Main Building- Gym Vestibule, 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	9x9 Dark Brown Floor Tile	15	SF	Main Building- Gym Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Brown Carpet Mastic	450	SF	Annex- Child Care Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Brown Carpet w/Dots	250	SF	Annex- Child Care Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Blue Carpet Mastic	750	SF	Annex- Library (228)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Gray Carpet, Gray Carpet Mastic	600	SF	Annex- Room 238, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42A	2'X2' Smooth Ceiling Tile	5,500	SF	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140I, 140A, 140, 140D, 140E, 140H, 140G	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
42B	Rubber Floor Mastic	1,400	SF	231 Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Light Brown Baseboard	675	LF	Annex- Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Light Brown Baseboard Mastic	675	LF	Annex- Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12x12 Gray w/Green Spots Floor Tile	1,800	SF	Annex- Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Gray w/Green Spots Floor Tile Mastic	1,800	SF	Annex- Rooms 126 and 127	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Gray Baseboard	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Gray Baseboard Mastic	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Black Baseboard	450	LF	Annex- Rooms 240, 241, 229, 238	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Black Baseboard Mastic	450	LF	Annex- Rooms 240,	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				241, 229, 238								potential for damage		
51	Blue Baseboard	125	LF	Annex- Childcare Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Blue Baseboard Mastic	125	LF	Annex- Childcare Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Turquoise Baseboard	450	LF	Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Turquoise Baseboard Mastic	450	LF	Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Tan Linoleum	800	SF	Annex- Childcare Room, Rm 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Tan Linoleum, Mastic	800	SF	Annex- Childcare Room, RM 133	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Brown Baseboard	200	LF	Annex- Childcare Room and YMCA Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Brown Baseboard Mastic	200	LF	Annex- Childcare Room and YMCA Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Blue Linoleum	300	SF	Annex- Childcare Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Blue Linoleum Mastic	300	SF	Annex- Childcare Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Tan Baseboard	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Tan Baseboard Mastic	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	2x4 Ceiling Tile	304,571	SF	Throughout Main & Annex Building	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
64	Blue Carpet	1,500	SF	Main Building- Social Room,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Library 211										
65	Blue Carpet Mastic	1,500	SF	Main Building-Social Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Beige Linoleum	2,500	SF	Main Building-Rooms 211, 307, 308, 310, 310A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Vibration Collar	25	LF	Annex Mechanical Room	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
75	12 x 12 Light Vanilla VFT	4,000	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	TSI on HVAC Ducts	60	LF	Annex 2nd Floor Fan Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
77	Hard Packed Fittings on Fiberglass Insulated Pipes	50	LF	Auto Shop	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
78	Linoleum and Associated Adhesive	3,600	SF	206, 207, 209, 306, 310, 205A, 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Glue	1,000	SF	238 and 239	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Plaster	304,571	SF	Throughout Main Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Plaster	25,000	SF	Throughout Annex Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12x12 Orange and White Floor Tile	100	SF	Main Building-Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12 x 12 Orange and White Floor Tile Mastic	100	SF	Main Building-Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	12x12 Orange Floor Tile	200	SF	Main Building-Cafeteria Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12x12 Orange Floor Tile Mastic	200	SF	Main Building-Cafeteria Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12x12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building-Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	Carpet Mastic	5,000	SF	Main Building-Conference Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Linoleum	700	SF	Room 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Lab Counter Tops	1,400	SF	Rooms 310, 308, 307, 306, 206, and 211 - Main Bldg	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	9X9 Gray w/White Streaks Vinyl Floor Tile	700	SF	Main Building-Rooms 201, 212, 311	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 8/17/2019
Inspector Name Daniel Juneau
100-03613 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
01AFT	
01AM	
01CM	
02	Not Observed Multiple Years
02FT1	Not Observed in Room 211
02FT2	NOT OBSERVED
03FT14	
03FT3	
03FT4	
03FT6	
03FT7	REMOVED FROM ROOMS 306 & 310
03FT8	
04	
05	
06	
06FT11	
06FT12	Under Carpet Now, Not Observed 2019
06FT13	
06FT14	
06FT5	
06FT7	New Floor in 231
07FT9	Not Observed Multiple Years

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
09	Floor Under Carpet in 240
09FT12	
09FT13	
09FT14	
09FT5	
09FT7	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
14	
16	
16FT-2	
16FT10	
16FT3	
16FT4	
16FT6	
16FT7	
16FT8	
16FT9	VFT Not Observed Multiple Years
17	
19	
1BFT	

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
1BM	
1CFT	
1CM	
1DS	
20	
200	
201	
20FT1	
20FT2	NOT OBSERVED
21	
22	
23	
24	
25	
26	
28	
29	Removed in 2019, Tested Non-ACBM
30	Removed in 2019, Tested Non-ACBM
31	Removed in 2019, Tested Non-ACBM
32	Removed in 2019, Tested Non-ACBM
33	
34	
35	
36	
37	
38	
39	
40	
41	

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
42	
42A	
42B	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
75	

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
9FT11	
A	
A(#2)	
B	
C	

Chicago Public Schools

School Bowen Campus Unit 46051 Building ID 1240

Address 2710 E. 89th St. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
D	Damage in AHU Room Behind Pump
D(#2)	
F	
G	
H	
HA-1000	Not Observed Multiple Years
HA-1001	Not Observed Multiple Years
HA-1002	
HA-1003	
N	
O	
P	
X	
Y	

Table II

Management Planner's Review

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12x12 Tan w/Brown Specks Floor Tile	6,400	SF	Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01AFT	12X12 Green w/Green Specks VFT	1,400	SF	Rooms 229, 241, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01AM	12x12 Green w/Green Specks VFT Mastic	1,400	SF	Rooms 229, 241, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01CM	12x12 Dark Gray w/Specks VFT Mastic	300	SF	261 Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	9x9 Floor Tile	0	SF	Main Building- 2nd and 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02FT1	9x9 Dark Brown Floor Tile	1,200	SF	Main Building- Rooms 210, 211, 212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02FT2	9x9 Light Gray Floor Tile	900	SF	Main Building Room 312	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT14	12x12 Cream Floor Tile	60,000	SF	Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT3	12x12 Green Floor Tile	800	SF	Main Building- Principal's Office, Conference Room Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT4	9x9 White w/Green Specks Floor Tile	900	SF	Main Building- Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT6	12x12 Brown Floor Tile	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT7	12x12 Light Brown Speckled Floor Tile	15,000	SF	Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03FT8	12x12 Beige Speckled Floor Tile	400	SF	Main Building- Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Tectum Ceiling	5,000	SF	Main Building- Gymnasium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
05	9x9 Floor Tile ABATED 1991			Annex 1st and 2nd Floor	Abated	MISC					
06	Linoleum Floor	950	SF	Main Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT11	12x12 Gray Floor Tile	14,000	SF	Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT12	12x12 Light Blue Floor Tile Mastic-under carpet	2,000	SF	Annex 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT13	12x12 White w/Tan Specks Floor Tile	1,800	SF	Annex Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
06FT14	12x12 Cream Floor Tile	5,000	SF	Annex 1st and 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT5	12x12 Dark Brown and Cream Speckled Floor Tile	7,200	SF	Annex Rooms: 241, 240, 229, 242, 129, 229A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06FT7	12x12 Light Brown Floor Tile	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07FT9	12x12 Red Floor Tile-NOT OBSERVED			Main Building- Lunchroom	Assumed	MISC					
09	12x12 Tan w/Brown Specks Floor Tile Mastic	6,400	SF	Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT12	12x12 Light Blue Floor Tile	2,500	SF	Annex 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT13	12x12 White w/Tan Specks Floor Tile Mastic	750	SF	Annex Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT14	12x12 Cream Floor Tile Mastic	1,850	SF	Annex 1st and 2nd Floor Hallways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT5	12x12 Dark Brown and Cream Speckled FT Mastic	7,200	SF	Annex rooms 240, 242, 129, 229A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09FT7	12x12 Light Brown Floor Tile Mastic	17,100	SF	Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	2' X 4' White w/Pin-Holes Ceiling Tile	4,300	SF	Throughout 1939 Building, Elevator Lobbies	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
101	Terrazo	2,000	SF	1939 Building- Stairwell and Baseboard	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Plaster	17,000	SF	Throughout 1939 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Air Cell	100	LF	1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
104	2' X 4' Ceiling Tile	10,000	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
105	12" X 12" Light Purple Mixed Speckled VFT	400	SF	Annex- Lobby to Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12" X 12" Light Purple Mixed Speckled Mastic	400	SF	Annex- Lobby to Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12X12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	Spray-On	1,200	SF	1st and 2nd Floor Entrance and Breezeway	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
109	Lab Tables	400	SF	Annex 229	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Transite Panels ABATED			Swimming Pool and Locker Rooms	Abated						
16	12x12 Floor Tile Mastic	162,000	SF	Main Building, 2nd, 3rd and 4th Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Classrooms							
16FT-2	12x12 Cream Floor Tile Mastic	60,000	SF	1st, 2nd, 3rd, & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT10	12x12 Orange and White Floor Tile Mastic	100	SF	Main Building- Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT3	12x12 Green Floor Tile Mastic	600	SF	Main Building- Principal's Office, Conference Room Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT4	9x9 White w/Green Specks Floor Tile Mastic	900	SF	Main Building, Room 202	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT6	12x12 Brown Floor Tile Mastic	800	SF	Main Building- 1st Floor Hallway Trim, Room 410	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT7	12x12 Light Brown Floor Tile Mastic	16,000	SF	Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT8	12x12 Beige Speckled Floor Tile	1,000	SF	Main Building- Room 308	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16FT9	12x12 Red Floor Tile Mastic-VFT NOT OBSERVED			Main Building- Lunchroom	Chrysotile	MISC					
17	9x9 Maroon and Tan Floor Tile Mastic	900	SF	Main Building- Swimming Pool and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Linoleum Mastic	950	SF	1908 Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1BFT	12x12 Light Gray w/Gray and White Specks VFT	4,300	SF	Rooms 229, 241, 229A, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1BM	12x12 Gray w/Gray and White Specks VFT Mastic	4,300	SF	Rooms 229, 241, 229A, 261	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1CFT	12x12 Dark Gray w/Specks VFT	300	SF	261 Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1CM	Carpet Mastic	6,400	SF	Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 240	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1DS	Drywall System		SF	Room 231, 2nd Floor Breezeway, 1st Floor Breezeway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9x9 Floor Tile Mastic	0	SF	Main Building- 2nd and 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
200	1x1 Pink Ceramic Flooring	600	SF	Girls' Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
201	Boiler Breeching	1,200	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
20FT1	9x9 Dark Brown Floor Tile Mastic	1,800	SF	Main Building- Rooms 200, 211-212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20FT2	9x9 light Gray Floor Tile Mastic	900	SF	Main Building- Room 312	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9x9 Floor Tile Mastic ABATED			Annex Room and Office	Abated						
22	12x12 Beige w/White Streaks Floor Tile	200	SF	Main Building - Room 211 and 211A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Beige w/White Streaks Floor Tile Mastic	200	SF	Main Building - Room 211 and 211A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Turquoise Carpet Mastic	400	SF	Main Building - Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12x12 Gray Floor Tile	600	SF	Main Building - Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Gray Floor Tile Mastic	1,000	SF	Main Building - Gym Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Gray Carpet Mastic	600	SF	Main Building - Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Gray Linoleum - ABATED			Main Building - Room 306	Abated	MISC				6 ACBM with the potential for damage	
30	Gray Linoleum Mastic - ABATED			Main Building- Room 306	Abated	MISC					
31	Brown Baseboard - Abated			Main Building- Room 306	Abated	MISC					
32	Brown Baseboard Mastic - ABATED			Main Building- Room 306	Abated	MISC					
33	Black Baseboard	75	LF	Main Building - Boys Gym, 2nd floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
34	Black Baseboard Mastic	75	LF	Main Building - Boys' Gym, 2nd floor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
35	9x9 Brown Floor Tile	15	SF	Main Building - Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic	15	SF	Main Building - Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Tan Floor Tile	15	SF	Main Building- Gym Vestibule, 2nd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9x9 Dark Brown Floor Tile	15	SF	Main Building- Gym Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Brown Carpet Mastic	450	SF	Annex- Child Care Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Brown Carpet w/Dots	250	SF	Annex- Child Care Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Blue Carpet Mastic	750	SF	Annex- Library (228)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Gray Carpet, Gray Carpet Mastic	600	SF	Annex- Room 238, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	2'X2' Smooth Ceiling Tile	5,500	SF	Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
42B	Rubber Floor Mastic	1,400	SF	231 Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Light Brown Baseboard	675	LF	Annex- Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
44	Light Brown Baseboard Mastic	675	LF	Annex- Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	12x12 Gray w/Green Spots Floor Tile	1,800	SF	Annex- Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
46	12x12 Gray w/Green Spots Floor Tile Mastic	1,800	SF	Annex- Rooms 126 and 127	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Gray Baseboard	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
48	Gray Baseboard Mastic	2,000	LF	Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Black Baseboard	450	LF	Annex- Rooms 240, 241, 229, 238	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
50	Black Baseboard Mastic	450	LF	Annex- Rooms 240, 241, 229, 238	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	Blue Baseboard	125	LF	Annex- Childcare Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Blue Baseboard Mastic	125	LF	Annex- Childcare Area	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
53	Turquoise Baseboard	450	LF	Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
54	Turquoise Baseboard Mastic	450	LF	Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	Tan Linoleum	800	SF	Annex- Childcare Room, Rm 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Tan Linoleum, Mastic	800	SF	Annex- Childcare Room, RM 133	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Brown Baseboard	200	LF	Annex- Childcare Room and YMCA Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
58	Brown Baseboard Mastic	200	LF	Annex- Childcare Room and YMCA Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
59	Blue Linoleum	300	SF	Annex- Childcare Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Blue Linoleum Mastic	300	SF	Annex- Childcare Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Tan Baseboard	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
62	Tan Baseboard Mastic	1,200	LF	Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
63	2x4 Ceiling Tile	304,571	SF	Throughout Main & Annex Building	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
64	Blue Carpet	1,500	SF	Main Building- Social Room, Library 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
65	Blue Carpet Mastic	1,500	SF	Main Building- Social Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Beige Linoleum	2,500	SF	Main Building- Rooms 211, 307, 308, 310, 310A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Vibration Collar	25	LF	Annex Mechanical Room	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
75	12 x 12 Light Vanilla VFT	4,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	TSI on HVAC Ducts	60	LF	Annex 2nd Floor Fan Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
77	Hard Packed Fittings on Fiberglass Insulated Pipes	50	LF	Auto Shop	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
78	Linoleum and Associated Adhesive	3,600	SF	206, 207, 209, 306, 310, 205A, 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12x12 Beige VFT/12x12 Brown VFT (Checked) w/Glue	1,000	SF	238 and 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Plaster	304,571	SF	Throughout Main Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Plaster	25,000	SF	Throughout Annex Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12x12 Orange and White Floor Tile	100	SF	Main Building- Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12 x 12 Orange and White Floor Tile Mastic	100	SF	Main Building- Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12x12 Orange Floor Tile	200	SF	Main Building- Cafeteria Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12x12 Orange Floor Tile Mastic	200	SF	Main Building- Cafeteria Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12x12 Light Vanilla Floor Tile Mastic	4,000	SF	Main Building- Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Carpet Mastic	5,000	SF	Main Building- Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Linoleum	700	SF	Room 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Lab Counter Tops	1,400	SF	Rooms 310, 308, 307, 306, 206, and 211 - Main Bldg	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	9X9 Gray w/White Streaks Vinyl Floor Tile	700	SF	Main Building- Rooms 201, 212, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	9X9 Gray w/White Streaks Vinyl Floor Tile Mastic	500	SF	Main Building- Rooms 201, 212, 311	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" X 12" Light Cream Mixed Speckled VFT	950	SF	Main Building- Rooms 205, 105A, B, C, D, E, and F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" X 12" Light Cream Mixed Speckled VFT Mastic	950	SF	Main Building- Rooms 205, 105A, B, C, D, E, and F	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" X 12" Vanilla Mixed Speckled VFT	1,300	SF	Main Building- Rooms 300 and 207, Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" X 12" Vanilla Mixed Speckled VFT Mastic	1,300	SF	Main Building- Rooms 300 and 207, Elevator Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" X 12" White w/Blue Specks VFT	550	SF	Main Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
97	12" X 12" White w/Blue Specks VFT Mastic	550	SF	Main Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" X 12" Light Tan w/Streaks VFT	2,800	SF	1939 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" X 12" Light Tan w/Streaks Mastic	2,800	SF	1939 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9FT11	12x12 Gray Floor Tile Mastic	13,500	SF	Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Tank Insulation ABATED			Annex Boiler Room	Abated						
A(#2)	Aircell Pipe Insulation ABATED			Main Building- Mechanical Area, Classrooms, Lunchroom	Abated						
B	Boiler Breaching ABATED			Annex Boiler Room	Abated						
C	Cardboard Insulation ABATED			Main Building- Classrooms and Mechanical Areas	Abated						
D	Pipe Fitting Insulation	130	LF	Throughout Annex	Assumed	TSI	Yes	1	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
D(#2)	Cementitious Joints on Cardboard ABATED			Main Building- Classrooms, Mechanical Area	Abated						
F	Joints and Elbows on Fiberglass Runs ABATED			Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor	Abated	TSI					
G	Pre-Form Pipe Insulation ABATED			Main Building	Abated						
H	Elbows on Pre-Formed Pipe Insulation ABATED			Main Building	Abated						
HA-1000	1'x1' White Ceiling Tile w/Random and Regular Holes-NOT OBSERVED			Kitchen		MISC					
HA-1001	1'x1' White Ceiling Tile w/Holes Glue-NOT OBSERVED			Kitchen	Assumed	MISC					
HA-1002	Mudded Pipe Fittings	20	LF	1908 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-1003	Mudded Pipe Fittings	30	LF	1953 Building- AHU by GYM, GYM	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Cardboard Pipe Insulation ABATED			Main Building- Mechanical Room	Abated						
O	Cementitious Joints ABATED			Main Building- Mechanical Rooms	Abated	TSI					
P	Cementitious Fittings on Fiberglass ABATED			Main Building- Unexcavated Area and Boiler Room	Abated						
X	Paper Wrap Pipe Insulation ABATED			Main Building- Throughout 1st Floor Corridor, Above Plaster Celng	Abated						

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
 Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
Y	Joints on Cardboard Pipe Insulation ABATED			Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling	Abated						

Review Date	09/05/2019
Manager Planner Name	John Fenn

HA Number	Management Comments
01	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
 Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01AFT	
01AM	
01CM	
02	
02FT1	
02FT2	
03FT14	
03FT3	
03FT4	
03FT6	
03FT7	
03FT8	
04	
05	
06	
06FT11	
06FT12	
06FT13	
06FT14	
06FT5	
06FT7	
07FT9	No response based on previous MP
09	
09FT12	
09FT13	
09FT14	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
 Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
09FT5	
09FT7	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
14	
16	
16FT-2	
16FT10	
16FT3	
16FT4	
16FT6	
16FT7	
16FT8	
16FT9	
17	
19	
1BFT	
1BM	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
1CFT	
1CM	
1DS	
20	
200	
201	
20FT1	
20FT2	
21	
22	
23	
24	
25	
26	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
40	
41	
42	
42A	
42B	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
64	
65	
66	
67	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	

Chicago Public Schools

School Bowen Campus
Address 2710 E. 89th St.

Unit 46051
 Chicago, IL, 60617

Building ID 1240
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
97	
98	
99	
9FT11	
A	
A(#2)	
B	
C	
D	
D(#2)	
F	
G	
H	
HA-1000	
HA-1001	
HA-1002	
HA-1003	
N	
O	
P	
X	
Y	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile**
MATERIAL LOCATION: **Annex Rooms: 490, 312, 240, 224, 225, 230, 231, 242, 234, 235, 129, Dean's Office, Library**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01AFT**
MATERIAL DESCRIPTION: **12X12 Green w/Green Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 229, 241, 261**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **01AFT**
MATERIAL DESCRIPTION: **12X12 Green w/Green Specks VFT**
MATERIAL LOCATION: **Rooms 229, 241, 261**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01AM**
MATERIAL DESCRIPTION: **12x12 Green w/Green Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 229, 241, 261**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **01AM**
MATERIAL DESCRIPTION: **12x12 Green w/Green Specks VFT Mastic**
MATERIAL LOCATION: **Rooms 229, 241, 261**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01CM**
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **261 Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **01CM**
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specks VFT Mastic**
MATERIAL LOCATION: **261 Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9x9 Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Building- 2nd and 3rd Floor Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **9x9 Floor Tile**
MATERIAL LOCATION: **Main Building- 2nd and 3rd Floor Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02FT1**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 210, 211, 212**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not Observed in Room 211**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **02FT1**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**
MATERIAL LOCATION: **Main Building- Rooms 210, 211, 212**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02FT2**
MATERIAL DESCRIPTION: **9x9 Light Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building Room 312**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **NOT OBSERVED**

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **02FT2**
MATERIAL DESCRIPTION: **9x9 Light Gray Floor Tile**
MATERIAL LOCATION: **Main Building Room 312**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**
MATERIAL LOCATION: **Teachers' Lounge, 1st, 2nd, 3rd, & 4th Floor Hallways, 1st Floor Women's Bathroom, 3rd Floor Men's Bathroom, Rooms 490, 314, 204, 285A; 2nd Floor Handicap Toilet**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT3**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT3**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile**
MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT4**
MATERIAL DESCRIPTION: **9x9 White w/Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT4**
MATERIAL DESCRIPTION: **9x9 White w/Green Specks Floor Tile**
MATERIAL LOCATION: **Main Building- Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT6**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT6**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**
MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **REMOVED FROM ROOMS 306 & 310**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Speckled Floor Tile**
MATERIAL LOCATION: **Main Building- Rooms 300, 310, 314, 315, 316, 306, 1st and 3rd Floor Faculty Bathrooms, 208A, 207, Main Office, and 2nd Floor Corridor**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03FT8**
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Main Building- Room 308**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **03FT8**
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**
MATERIAL LOCATION: **Main Building- Room 308**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Tectum Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Gymnasium**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **Tectum Ceiling**
MATERIAL LOCATION: **Main Building- Gymnasium**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED 1991**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex 1st and 2nd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **9x9 Floor Tile ABATED 1991**

MATERIAL LOCATION: **Annex 1st and 2nd Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Linoleum Floor**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Stairways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Linoleum Floor**
MATERIAL LOCATION: **Main Building- Stairways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT11**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT11**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
MATERIAL LOCATION: **Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT12**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic-under carpet**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Under Carpet Now, Not Observed 2019**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT12**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic-under carpet**
MATERIAL LOCATION: **Annex 1st Floor Offices, 2nd Floor Faculty Lounge, 140-A-J**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT13**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT13**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile**
MATERIAL LOCATION: **Annex Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex 1st and 2nd Floor Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**
MATERIAL LOCATION: **Annex 1st and 2nd Floor Hallways**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT5**
MATERIAL DESCRIPTION: **12x12 Dark Brown and Cream Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms: 241, 240, 229, 242, 129, 229A**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT5**
MATERIAL DESCRIPTION: **12x12 Dark Brown and Cream Speckled Floor Tile**
MATERIAL LOCATION: **Annex Rooms: 241, 240, 229, 242, 129, 229A**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**
MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **New Floor in 231**

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **06FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**
MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**
MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07FT9**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____

Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **07FT9**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile-NOT OBSERVED**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

No response based on previous MP

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library**

MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **Floor Under Carpet in 240**

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12x12 Tan w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex Rooms: 241, 240, 224, 225, 229, 230, 231, 242, 234, 235, 129, Dean's Office, and Library**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT12**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09FT12**
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**
MATERIAL LOCATION: **Annex 1st Floor Offices, 2nd Floor Faculty Lounge, Room 140-AJ**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT13**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms 126 and 127**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09FT13**
MATERIAL DESCRIPTION: **12x12 White w/Tan Specks Floor Tile Mastic**
MATERIAL LOCATION: **Annex Rooms 126 and 127**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex 1st and 2nd Floor Hallways**
MATERIAL QUANTITY: **1850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09FT14**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
MATERIAL LOCATION: **Annex 1st and 2nd Floor Hallways**
MATERIAL QUANTITY: **1850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT5**
MATERIAL DESCRIPTION: **12x12 Dark Brown and Cream Speckled FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex rooms 240, 242, 129, 229A**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09FT5**
MATERIAL DESCRIPTION: **12x12 Dark Brown and Cream Speckled FT Mastic**
MATERIAL LOCATION: **Annex rooms 240, 242, 129, 229A**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**
MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **09FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Annex Rooms: 224, 225, 230, 231, 239, 122, 123, 134, 135, 136, 238**
MATERIAL QUANTITY: **17100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2' X 4' White w/Pin-Holes Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1939 Building, Elevator Lobbies**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **2' X 4' White w/Pin-Holes Ceiling Tile**
MATERIAL LOCATION: **Throughout 1939 Building, Elevator Lobbies**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Terrazo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 Building- Stairwell and Baseboard**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **101**
MATERIAL DESCRIPTION: **Terrazo**
MATERIAL LOCATION: **1939 Building- Stairwell and Baseboard**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1939 Building**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout 1939 Building**
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Air Cell**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Air Cell**
MATERIAL LOCATION: **1939 Building- Boys' Bathroom in Locker Room, Basement Vault, Boiler Room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2' X 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2' X 4' Ceiling Tile**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" X 12" Light Purple Mixed Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Lobby to Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" X 12" Light Purple Mixed Speckled VFT**
MATERIAL LOCATION: **Annex- Lobby to Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" X 12" Light Purple Mixed Speckled Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Lobby to Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12" X 12" Light Purple Mixed Speckled Mastic**
MATERIAL LOCATION: **Annex- Lobby to Gym**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12X12 Light Vanilla Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12X12 Light Vanilla Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Spray-On**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st and 2nd Floor Entrance and Breezeway**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **Spray-On**
MATERIAL LOCATION: **1st and 2nd Floor Entrance and Breezeway**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Lab Tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex 229**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **Lab Tables**
MATERIAL LOCATION: **Annex 229**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Transite Panels ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Swimming Pool and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Transite Panels ABATED**

MATERIAL LOCATION: **Swimming Pool and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building, 2nd, 3rd and 4th Floor Classrooms**
MATERIAL QUANTITY: **162000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12x12 Floor Tile Mastic**
MATERIAL LOCATION: **Main Building, 2nd, 3rd and 4th Floor Classrooms**
MATERIAL QUANTITY: **162000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT-2**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, 3rd, & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A**

MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT-2**
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd, 3rd, & 4th Floor Hallways, 3rd Floor Men's Bathroom, 1st Floor Women's Bathroom, 2nd Floor Handicap Toilet, Rooms 490, 314, 204, 285A**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT10**
MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT10**
MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT3**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT3**
MATERIAL DESCRIPTION: **12x12 Green Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Principal's Office, Conference Room Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT4**
MATERIAL DESCRIPTION: **9x9 White w/Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building, Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT4**
MATERIAL DESCRIPTION: **9x9 White w/Green Specks Floor Tile Mastic**
MATERIAL LOCATION: **Main Building, Room 202**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT6**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT6**
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- 1st Floor Hallway Trim, Room 410**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)**

MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT7**
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Rooms: 300, 310, 314, 315, 316, 306, 3rd & 1st Floor Faculty Bathroom, 208A, 207, Main Office, and 2nd Floor Corridor (306 & 310 Removed)**
MATERIAL QUANTITY: **16000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT8**
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Room 308**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT8**
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**
MATERIAL LOCATION: **Main Building- Room 308**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16FT9**
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic-VFT NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **VFT Not Observed Multiple Years**

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **16FT9**

MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic-VFT NOT OBSERVED**

MATERIAL LOCATION: **Main Building- Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9x9 Maroon and Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Swimming Pool and Corridors**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **9x9 Maroon and Tan Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Swimming Pool and Corridors**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1908 Stairways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Linoleum Mastic**
MATERIAL LOCATION: **1908 Stairways**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1BFT**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray and White Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **1BFT**
MATERIAL DESCRIPTION: **12x12 Light Gray w/Gray and White Specks VFT**
MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1BM**
MATERIAL DESCRIPTION: **12x12 Gray w/Gray and White Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **1BM**
MATERIAL DESCRIPTION: **12x12 Gray w/Gray and White Specks VFT Mastic**
MATERIAL LOCATION: **Rooms 229, 241, 229A, 261**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1CFT**
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **261 Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **1CFT**
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Specks VFT**
MATERIAL LOCATION: **261 Lunchroom**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1CM**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 240**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **1CM**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rooms 144, 140C, 140H, 140E, 140D, 140, 140A, 140J, 200N, 240**
MATERIAL QUANTITY: **6400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1DS**
MATERIAL DESCRIPTION: **Drywall System**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 231, 2nd Floor Breezeway, 1st Floor Breezeway**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **1DS**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **Room 231, 2nd Floor Breezeway, 1st Floor Breezeway**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- 2nd and 3rd Floor Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- 2nd and 3rd Floor Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20FT1**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 200, 211-212**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **20FT1**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Rooms 200, 211-212**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20FT2**
MATERIAL DESCRIPTION: **9x9 light Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Room 312**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **NOT OBSERVED**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **20FT2**
MATERIAL DESCRIPTION: **9x9 light Gray Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Room 312**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Room and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9x9 Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Annex Room and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Room 211 and 211A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile**
MATERIAL LOCATION: **Main Building - Room 211 and 211A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Room 211 and 211A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12x12 Beige w/White Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Main Building - Room 211 and 211A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Turquoise Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Assembly Hall**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Turquoise Carpet Mastic**
MATERIAL LOCATION: **Main Building - Assembly Hall**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Gym Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**
MATERIAL LOCATION: **Main Building - Gym Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Gym Corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
MATERIAL LOCATION: **Main Building - Gym Corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Room 400**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
MATERIAL LOCATION: **Main Building - Room 400**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Gray Linoleum - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building - Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed in 2019, Tested Non-ACBM**

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Gray Linoleum - ABATED**

MATERIAL LOCATION: **Main Building - Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Gray Linoleum Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY: **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Removed in 2019, Tested Non-ACBM**

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Gray Linoleum Mastic - ABATED**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Brown Baseboard - Abated**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed in 2019, Tested Non-ACBM**

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Brown Baseboard - Abated**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Removed in 2019, Tested Non-ACBM**

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Brown Baseboard Mastic - ABATED**

MATERIAL LOCATION: **Main Building- Room 306**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Boys Gym, 2nd floor**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Main Building - Boys Gym, 2nd floor**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Boys' Gym, 2nd floor**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Main Building - Boys' Gym, 2nd floor**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**
MATERIAL LOCATION: **Main Building - Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building - Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **9x9 Brown, 9x9 Tan, & 9x9 Dark Brown Mastic**
MATERIAL LOCATION: **Main Building - Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**
MATERIAL LOCATION: **Main Building- Gym Vestibule, 2nd Floor**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Gym Vestibule**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**
MATERIAL LOCATION: **Main Building- Gym Vestibule**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Child Care Room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **Annex- Child Care Room**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Brown Carpet w/Dots**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Child Care Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Brown Carpet w/Dots**
MATERIAL LOCATION: **Annex- Child Care Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Library (228)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Annex- Library (228)**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Gray Carpet, Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Room 238, Main Office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Gray Carpet, Gray Carpet Mastic**
MATERIAL LOCATION: **Annex- Room 238, Main Office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **2'X2' Smooth Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G**

MATERIAL QUANTITY: **5500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **42A**
MATERIAL DESCRIPTION: **2'X2' Smooth Ceiling Tile**
MATERIAL LOCATION: **Staff Bathroom, Rooms 319, 241, 261, 229A, 229, 231, 140J, 140A, 140, 140D, 140E, 140H, 140G**
MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42B**
MATERIAL DESCRIPTION: **Rubber Floor Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **231 Annex**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **42B**
MATERIAL DESCRIPTION: **Rubber Floor Mastic**
MATERIAL LOCATION: **231 Annex**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Light Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Corridor**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Light Brown Baseboard**
MATERIAL LOCATION: **Annex- Corridor**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Light Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Corridor**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Light Brown Baseboard Mastic**
MATERIAL LOCATION: **Annex- Corridor**
MATERIAL QUANTITY: **675** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile**
MATERIAL LOCATION: **Annex- Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **12x12 Gray w/Green Spots Floor Tile Mastic**
MATERIAL LOCATION: **Annex- Rooms 126 and 127**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Gray Baseboard**
MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Gray Baseboard Mastic**
MATERIAL LOCATION: **Annex- Rooms: 222, 223, 226, 227, 232, 233, 235, 234, 236, 237, 124, 125, 137, 138, 139**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Black Baseboard**
MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Annex- Rooms 240, 241, 229, 238**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Blue Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Area**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Blue Baseboard**
MATERIAL LOCATION: **Annex- Childcare Area**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Area**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
MATERIAL LOCATION: **Annex- Childcare Area**
MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Turquoise Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Turquoise Baseboard**
MATERIAL LOCATION: **Annex- Rooms 228, Women's 2nd Floor Faculty Lounge, West Office Corridor and Offices**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Turquoise Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices**

MATERIAL QUANTITY: **450**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Turquoise Baseboard Mastic**
MATERIAL LOCATION: **Annex- Rooms 228, Womens 2nd Floor Faculty Lounge, West Office Corridor and Offices**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Tan Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room, Rm 133**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Tan Linoleum**
MATERIAL LOCATION: **Annex- Childcare Room, Rm 133**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Tan Linoleum, Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room, RM 133**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Tan Linoleum, Mastic**
MATERIAL LOCATION: **Annex- Childcare Room, RM 133**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Brown Baseboard**
MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**
MATERIAL LOCATION: **Annex- Childcare Room and YMCA Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Blue Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Blue Linoleum**
MATERIAL LOCATION: **Annex- Childcare Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Childcare Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Blue Linoleum Mastic**
MATERIAL LOCATION: **Annex- Childcare Room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Tan Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Tan Baseboard**
MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Tan Baseboard Mastic**
MATERIAL LOCATION: **Annex- Rooms 224, 225, 230, 231, 239, 122, 123, 126, 135, 136, 134, Infant Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Main & Annex Building**
MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **2x4 Ceiling Tile**
MATERIAL LOCATION: **Throughout Main & Annex Building**
MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Blue Carpet**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Social Room, Library 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Blue Carpet**
MATERIAL LOCATION: **Main Building- Social Room, Library 211**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Social Room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
MATERIAL LOCATION: **Main Building- Social Room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Beige Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 211, 307, 308, 310, 310A**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Beige Linoleum**
MATERIAL LOCATION: **Main Building- Rooms 211, 307, 308, 310, 310A**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Vibration Collar**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Mechanical Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **Vibration Collar**
MATERIAL LOCATION: **Annex Mechanical Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12 x 12 Light Vanilla VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12 x 12 Light Vanilla VFT**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **TSI on HVAC Ducts**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Annex 2nd Floor Fan Room**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **TSI on HVAC Ducts**
MATERIAL LOCATION: **Annex 2nd Floor Fan Room**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Hard Packed Fittings on Fiberglass Insulated Pipes**
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Auto Shop**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Hard Packed Fittings on Fiberglass Insulated Pipes**
MATERIAL LOCATION: **Auto Shop**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Linoleum and Associated Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **206, 207, 209, 306, 310, 205A, 211**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **Linoleum and Associated Adhesive**
MATERIAL LOCATION: **206, 207, 209, 306, 310, 205A, 211**
MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12x12 Beige VFT/12x12 Brown VFT (Checked) w/Glue**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **238 and 239**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **79**
MATERIAL DESCRIPTION: **12x12 Beige VFT/12x12 Brown VFT (Checkered) w/Glue**
MATERIAL LOCATION: **238 and 239**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Main Building**
MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Main Building**
MATERIAL QUANTITY: **304571** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Annex Building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Annex Building**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12x12 Orange and White Floor Tile**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12 x 12 Orange and White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12 x 12 Orange and White Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Engineer's Office**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Cafeteria Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**
MATERIAL LOCATION: **Main Building- Cafeteria Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Cafeteria Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Cafeteria Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12x12 Light Vanilla Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12x12 Light Vanilla Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Lunchroom**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Conference Room**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Main Building- Conference Room**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **Linoleum**
MATERIAL LOCATION: **Room 211**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Lab Counter Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 310, 308, 307, 306, 206, and 211 - Main Bldg**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Lab Counter Tops**
MATERIAL LOCATION: **Rooms 310, 308, 307, 306, 206, and 211 - Main Bldg**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **9X9 Gray w/White Streaks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **9X9 Gray w/White Streaks Vinyl Floor Tile**
MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **9X9 Gray w/White Streaks Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **9X9 Gray w/White Streaks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Main Building- Rooms 201, 212, 311**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" X 12" Light Cream Mixed Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **12" X 12" Light Cream Mixed Speckled VFT**
MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" X 12" Light Cream Mixed Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **12" X 12" Light Cream Mixed Speckled VFT Mastic**
MATERIAL LOCATION: **Main Building- Rooms 205, 105A, B, C, D, E, and F**
MATERIAL QUANTITY: **950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" X 12" Vanilla Mixed Speckled VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **12" X 12" Vanilla Mixed Speckled VFT**
MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" X 12" Vanilla Mixed Speckled VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **12" X 12" Vanilla Mixed Speckled VFT Mastic**
MATERIAL LOCATION: **Main Building- Rooms 300 and 207, Elevator Vestibule**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" X 12" White w/Blue Specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Room 209**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **12" X 12" White w/Blue Specks VFT**
MATERIAL LOCATION: **Main Building- Room 209**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" X 12" White w/Blue Specks VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Building- Room 209**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **12" X 12" White w/Blue Specks VFT Mastic**
MATERIAL LOCATION: **Main Building- Room 209**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" X 12" Light Tan w/Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **12" X 12" Light Tan w/Streaks VFT**
MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" X 12" Light Tan w/Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **12" X 12" Light Tan w/Streaks Mastic**
MATERIAL LOCATION: **1939 Building- 1st Floor Corridor**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9FT11**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **9FT11**
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic**
MATERIAL LOCATION: **Annex Rooms: 222, 223, 226, 227, 232, 233, 236, 237, 124, 125, 137, 138, 139, 136**
MATERIAL QUANTITY: **13500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Tank Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Tank Insulation ABATED**
MATERIAL LOCATION: **Annex Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A(#2)**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Mechanical Area, Classrooms, Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **A(#2)**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation ABATED**
MATERIAL LOCATION: **Main Building- Mechanical Area, Classrooms, Lunchroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Boiler Breaching ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Boiler Breaching ABATED**

MATERIAL LOCATION: **Annex Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Classrooms and Mechanical Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Cardboard Insulation ABATED**
MATERIAL LOCATION: **Main Building- Classrooms and Mechanical Areas**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Pipe Fitting Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Annex**

MATERIAL QUANTITY: **130**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **1**

DAMAGE UNITS: **LF**

COMMENTS: **Damage in AHU Room Behind Pump**

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Pipe Fitting Insulation**
MATERIAL LOCATION: **Throughout Annex**
MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **1** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D(#2)**
MATERIAL DESCRIPTION: **Cementitious Joints on Cardboard ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **D(#2)**
MATERIAL DESCRIPTION: **Cementitious Joints on Cardboard ABATED**
MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Area**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joints and Elbows on Fiberglass Runs ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Joints and Elbows on Fiberglass Runs ABATED**
MATERIAL LOCATION: **Main Building- Classrooms, Mechanical Areas, 1st, 2nd, and 3rd Floor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Elbows on Pre-Formed Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Elbows on Pre-Formed Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Random and Regular Holes-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____

Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **HA-1000**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Random and Regular Holes-NOT OBSERVED**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1001**
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Holes Glue-NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years**

Inspector's Signature: _____

Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **HA-1001**

MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile w/Holes Glue-NOT OBSERVED**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1002**
MATERIAL DESCRIPTION: **Mudded Pipe Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1908 Building- Boiler Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **HA-1002**
MATERIAL DESCRIPTION: **Mudded Pipe Fittings**
MATERIAL LOCATION: **1908 Building- Boiler Room**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-1003**
MATERIAL DESCRIPTION: **Mudded Pipe Fittings**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1953 Building- AHU by GYM, GYM**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **HA-1003**
MATERIAL DESCRIPTION: **Mudded Pipe Fittings**
MATERIAL LOCATION: **1953 Building- AHU by GYM, GYM**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Mechanical Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Mechanical Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Cementitious Joints ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Mechanical Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Cementitious Joints ABATED**

MATERIAL LOCATION: **Main Building- Mechanical Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Cementitious Fittings on Fiberglass ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Unexcavated Area and Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Cementitious Fittings on Fiberglass ABATED**

MATERIAL LOCATION: **Main Building- Unexcavated Area and Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **X**
MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation ABATED**
MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Celing**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUIDLING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**
MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Insulation ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/17/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **Y**

MATERIAL DESCRIPTION: **Joints on Cardboard Pipe Insulation ABATED**

MATERIAL LOCATION: **Main Building- Throughout 1st Floor Corridor, Above Plaster Ceiling**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **200**

MATERIAL DESCRIPTION: **1x1 Pink Ceramic Flooring**

MATERIAL LOCATION: **Girls' Bathrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **200**
MATERIAL DESCRIPTION: **1x1 Pink Ceramic Flooring**
MATERIAL LOCATION: **Girls' Bathrooms**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/05/2019**

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Daniel Juneau**
SCHOOL NAME: **Bowen Campus** INSPECTION DATE: **8/17/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **201**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 08/17/2019

Chicago Public Schools

TEM Environmental, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46051** BUILDING ID: **1240**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**
SCHOOL NAME: **Bowen Campus** REVIEW DATE: **9/5/2019**
ADDRESS: **2710 E. 89th St.** IDPH LICENSE NO: **100-03613**

HOMOGENEOUS AREA: **201**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **09/05/2019**

APPENDIX B

Inspector and Management Planner Licenses

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: BIR1811203167

Kathy DeSalvo, Director

2018



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: MPR1811203186



Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 03613

ISSUED
4/17/2019

EXPIRES
05/15/2020

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016
Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/20/2019

MANAGEMENT PLANNER

11/20/2019

PROJECT MANAGER

11/6/2019

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

John Fenn


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035



Kathy DeSalvo, Director

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



ASBESTOS PROFESSIONAL LICENSE

ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

JOHN H FENN

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed