

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0002
SCHOOL NAME: Austin High School
ADDRESS OF SCHOOL: 231 N Pine
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/7/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 250
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME(Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Austin High School

231 N Pine
Chicago, IL, 60644

Unit: 46621
Building ID: 1220

IDPH ID Number: 14-016-2990-0002

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 11, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66511 Region: 03 IDPH ID:14-016-2990-0002

School: Austin High School Building ID: 1220

Address: 231 N Pine

Chicago, IL, 60644

Building Contact: Teune, Gary

Contact Phone:312 909 5659

Current Building Owners: Chicago Public Schools

Review Date: 05/03/2019

Inspector: Carol Ashman

Inspector IDPH License: 100-19554

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 11, 2019

RE: Austin High School, Unit 46621
231 N Pine
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Austin High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Austin High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Austin High School Unit: 66511 Region: 03
Address: 231 N Pine Chicago, IL, 60644
IDPH ID: 14-016-2990-0002 Building ID: 1220
Contact: Teune, Gary Phone: 312 909 5659

2. Description of Facility

Original Construction: 1930 Additional Construction:
Total Square Footage: 397258 No of Floors: 4
Current Occupancy: 250

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554

Signature:
Date: 4/11/2019

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466

Signature:
Date: 05/03/2019

7. Review Date:05/03/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Austin High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1220:

27	12" x 12" Lt. Blue w/Blue & Wt. Specks FT
32	Black-White-Gray Terazzo Flooring
6	9x9 Red/Black VFT
7.7	12x12 Beige Speckle VFT
FF	2'x 4' laid in ceiling tile White
HA-103	1'x1' white grooved Ceiling Tile

B. The following new homogenous areas have been identified for Building 1220:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

110	1'x1' Wall Acoustical Tiles
111	12" x 12" White w/ Blue Specks Floor Tile
112	Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile
113	Beige Stone Pattern Sheet Flooring
114	Mastic Associated w/ Beige Stone Pattern Sheet Flooring
115	Gray Spray-on Fireproofing
13	Exterior Brick - Non-AHERA
27	12" x 12" Lt. Blue w/Blue & Wt. Specks FT
28	12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic
30	2x2 White Pin Hole Ceiling Tile
31	Black-Gold Carpet Adhesive
32	Black-White-Gray Terazzo Flooring
33	12"x12" White w/Blue-Brown Spec's Floor Tile
34	12"x12" White w/Blue-Brown Spec's Floor Tile Mastic
35	White-Gray Ceramic Grout
36	White-Gray Ceramic Adhesive
37	Green-Black-White Terrazzo
3E	9 X 9 Cream w/Off White Streaks
7	12x12 Light Red Speckle VFT
7.1	12x12 Red Speckle VFT
7.3	12x12 Gray Speckle VFT
7.5	12x12 Off White w/Beige Stripes VFT
7.7	12x12 Beige Speckle VFT
7.8	12x12 Black VFT
AA	Floor material Pinkish with white
BB	12" x 12" White Floor Tile
CC	12'x 12"Red floor tile
DD	12"x 12" black floor tile
EE	Mastic associate HA # BB,CC,DD
FF	2'x 4' laid in ceiling tile White
GG	12" x12 white spline ceiling tile
HA-100	Fire Curtain
HA-101	Woven electrical wire insulation
HA-102	Electrical wire insulation for chandeliers
HA-103	1'x1' white grooved Ceiling Tile
HA-104	Glue for 1'x1' white grooved Ceilig Tile
HA-105	12"X12" grey with white and brown specks VFT
HA-105m	Adhesive for 12"x12"grey with white and brown VFT

HA-106

Hard mud pipe fitting insulation

The following areas were deemed to be inaccessible:

11	12x12 Red/Black Vinyl Floor Tile Mastic
112	Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile
114	Mastic Associated w/ Beige Stone Pattern Sheet Flooring
12.2	12 X 12 Dark Beige Speckle Mastic
12.3	12x12 Gray Speckle VFT Mastic
12.6	12x12 White VFT Mastic
28	12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic
30	2x2 White Pin Hole Ceiling Tile
31	Black-Gold Carpet Adhesive
34	12"x12" White w/Blue-Brown Spec's Floor Tile Mastic
36	White-Gray Ceramic Adhesive
7.2	12x12 Dark Beige Speckle VFT
9	Window Panels
EE	Mastic associate HA # BB,CC,DD
FF	2'x 4' laid in ceiling tile White
GG	12" x12 white spline ceiling tile
HA-104	Glue for 1'x1' white grooved Ceilig Tile
HA-105m	Adhesive for 12"x12"grey with white and brown VFT

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Austin High School Building 1220 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	Exterior Mortar - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
15	Interior Brick Material (Masonry)			Interior of Building	NO_ACBM	MISC								
16	Interior Brick Mortar			Interior of Building	NO_ACBM	MISC								
17	Red Brick Material			3rd Floor Janitors Closet	NO_ACBM	MISC								
18	Red Brick Mortar			3rd Floor Janitors Closet	NO_ACBM	MISC								
19	Cinderblock Material (Brick)			Men's and Women's Bathrooms, Room 403, and Janitors Closet	NO_ACBM	MISC								
20	Cinderblock Mortar Material			Men's and Women's Bathrooms, Room 403, and Janitors Closet	NO_ACBM	MISC								
21	Chalkboard Material			Room 305	NO_ACBM	MISC								
22	4 Inch Black Mop Guard			Men's and Women's Bathrooms Throughout School and Room 4	NO_ACBM	MISC								
23	4 Inch Black Mop Guard Mastic			Men's and Women's Bathrooms Throughout School	NO_ACBM	MISC								
24	Exterior Window Caulk			Exterior of Building	NO_ACBM	MISC								
25	12" x 12" Multi-Beige Floor Tile - Abated			Room 313	ABATED	MISC								
26	12" x 12" Multi-Beige Floor Tile Mastic - Abated			Room 313	ABATED	MISC								
27	12" x 12" Lt. Blue w/Blue & Wt. Specks FT	1,100	SF	Room 220	ASSUMED	MISC	N	LOC	15		Yes	ACBM with the potential for damage	5	LOW
28	12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic	1,100	SF	Room 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Smooth Plaster			Throughout School	NO_ACBM	MISC								
30	2x2 White Pin Hole Ceiling Tile	4,000	SF	Lunch Room	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
31	Black-Gold Carpet Adhesive	6,100	SF	Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Black-White-Gray Terazzo Flooring	20,000	SF	1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom	ASSUMED	MISC	N	DIST	100		Yes	ACBM with the potential for damage	5	LOW

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
33	12"x12" White w/Blue-Brown Spec's Floor Tile	2,000	SF	Rooms 219,229,318,320 and 335	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12"x12" White w/Blue-Brown Spec's Floor Tile Mastie	2,000	SF	Rooms 219,229,318,320 and 335	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	White-Gray Ceramic Grout	200	SF	Engineer Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	White-Gray Ceramic Adhesive	200	SF	Engineer Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Green-Black-White Terrazzo	3,200	SF	1st, 2nd, 3rd and 4th Boy's/Girl's Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
3E	9 X 9 Cream w/Off White Streaks			1st Floor Corridor Areas Across From Room 109	ASSUMED	MISC								
6	9x9 Red/Black VFT	38,000	SF	Rooms 111, 119	CHR	MISC	N	LOC	5		Yes	ACBM with the potential for damage	5	LOW
6.1	9x9 Beige w/Brown Streaks VFT	1,900	SF	Room 219, 318, 311	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6.2	9x9 Red VFT			Room 320	CHR	MISC								
6.3	9x9 Tan w/Brown Stripes VFT	3,120	SF	Rooms 319, 321, and 313	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6.4	9x9 Light Green VFT - ABATED			Room 220	ABATED									
6.5	9x9 Beige and Brown VFT	1,608	SF	Room 335	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7	12x12 Light Red Speckle VFT	19,400	SF	Rooms 101, 123, 134, 106, 112, 1st Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.1	12x12 Red Speckle VFT	900	SF	Room 101	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.2	12x12 Dark Beige Speckle VFT	1,200	SF	Rooms 108 and 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.3	12x12 Gray Speckle VFT	1,100	SF	Rooms 207, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.4	12x12 Light Beige Speckle VFT	1,050	SF	Room 206,128	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.5	12x12 Off White w/Beige Stripes VFT	1,800	SF	Rooms 203, 327 and 403	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.6	12x12 White VFT	500	SF	Men's and Women's Bathrooms Throughout School	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
7.7	12x12 Beige Speckle VFT	5,000	SF	Room 220,134,134 A,137,138,425	ASSUMED	MISC	N	LOC	30		Yes	ACBM with the potential for damage	5	LOW
7.8	12x12 Black VFT	7,000	SF	4th Floor East	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220

Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor, Room 203								potential for damage		
8	1x6 Wall Tile			Library	NO_ACBM	MISC								
9	Window Panels	1,000	SF	Throughout Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
AA	Floor material Pinkish with white	13,000	SF	Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421	ASSUMED	MISC	N	LOC	15		No	ACBM with the potential for damage	5	LOW
BB	12" x 12" White Floor Tile	37,000	SF	2nd ,3th, 4th floor corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CC	12"x 12"Red floor tile	1,000	SF	All stairwell entrances on 2nd, 3rd, 4th floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DD	12"x 12" black floor tile	1,000	SF	All stairwell entrances on 2nd, 3rd, 4th floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
EE	Mastic associate HA # BB,CC,DD	38,000	SF	2nd, 3rd, 4th floor corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FF	2'x 4' laid in ceiling tile White	40,000	SF	Most classrooms	ASSUMED	MISC	Y	LOC	16		Yes	ACBM with the potential for damage	5	LOW
GG	12" x12 white spline ceiling tile	5,000	SF	Lunchroom	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
HA-100	Fire Curtain	400	SF	Auditorium Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-101	Woven electrical wire insulation			Auditorium stage light fixtures	ASSUMED	MISC								
HA-102	Electrical wire insulation for chandeliers			Auditorium	ASSUMED	MISC								
HA-103	1'x1' white grooved Ceiling Tile	16,900	SF	GYM	ASSUMED	MISC	Y	DIST	100		Yes	Damaged or significantly damaged friable misc, ACBM	5	LOW
HA-104	Glue for 1'x1' white grooved Ceiling Tile	2,000	SF	GYM	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-105	12"X12" grey with white and brown specks VFT	2,000	SF	Rms. 204 A, 204 B, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-105m	Adhesive for 12"x12"grey with white and brown VFT	2,000	SF	Rms. 204 A, 204B, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-106	Hard mud pipe fitting insulation			Boiler room and basement "wax" room	ASSUMED	TSI								
HA-107	Aircell pipe insulation			Garage	CHR	TSI								
HA-108	Mudded fitting insulation in aircell pipe insulation			Garage	CHR	TSI								
HA-109	Hard mudded fitting insulation on	1,000	LF	Throughout the	CHR	TSI	Y	NONE	0		No	Any remaining friable		LOW

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220
Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/11/2019
Inspector Name Carol Ashman
100-19554 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
11	
11.1	
11.2	Not observed 2019
11.3	
11.4	
11.5	Not observed 2019
110	
111	
112	
113	
114	
115	
12	
12.1	
12.2	
12.3	
12.4	
12.5	
12.6	
12.7	
12.8	
13	
14	

Chicago Public Schools

School Austin High School **Unit** 66511 **Building ID** 1220
Address 231 N Pine **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
3E	Not observed 2019
6	
6.1	
6.2	Not observed 2019
6.3	
6.4	

Chicago Public Schools

School Austin High School Unit 66511 Building ID 1220
Address 231 N Pine Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
6.5	
7	
7.1	
7.2	
7.3	
7.4	
7.5	
7.6	
7.7	
7.8	
8	
9	
AA	
BB	
CC	
DD	
EE	
FF	
GG	
HA-100	
HA-101	Not observed 2019
HA-102	Not observed 2019
HA-103	Missing 10 tiles and 15 damaged tiles
HA-104	
HA-105	
HA-105m	
HA-106	Not observed 2019
HA-107	Not observed 2019
HA-108	Not observed 2019

Chicago Public Schools

School Austin High School **Unit** 66511 **Building ID** 1220
Address 231 N Pine **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
HA-109	
O	

Table II

Management Planner's Review

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
11	12x12 Red/Black Vinyl Floor Tile Mastic	20,000	SF	Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11.1	9 X 9 Beige w/Brown Strips VFTMastic - Abated			Room 219, 318, 311, 431	Abated	MISC					
11.2	9 X 9 Red VFT Mastic			Room 320	Chrysotile	MISC					
11.3	9 X 9 Tan w/Brown Stripes VFT Mastic - Abated			Rooms 319, 321, and 313	Abated	MISC					
11.4	9 X 9 Light Green VFT Mastic - ABATED			Room 220	Abated						
11.5	9 X 9 Beige/Brown VFT Mastic			Room 335	Chrysotile	MISC					
110	1'x1' Wall Acoustical Tiles	200	SF	Room 431	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
111	12" x 12" White w/ Blue Specks Floor Tile	4,500	SF	Rooms 134, 134B, 137, 138, 431, 433	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile	4,500	SF	Rooms 134, 134B, 137, 138, 431, 433	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	Beige Stone Pattern Sheet Flooring	800	SF	Room 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Mastic Associated w/ Beige Stone Pattern Sheet Flooring	800	SF	Room 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Gray Spray-on Fireproofing	10,000	SF	Boiler Room	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	12 X 12 Light Red Speckle VFT Mastic			Rms 101, 123, 106, 112, 1st Floor Corridor	No ACBM	MISC					
12.1	12 X 12 Red Speckle VFT Mastic			Room 101	No ACBM	MISC					
12.2	12 X 12 Dark Beige Speckle Mastic	1,200	SF	Room 108 and 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.3	12x12 Gray Speckle VFT Mastic	750	SF	Rooms 207,208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.4	12x12 Light Beige Speckle VFT Mastic			RM 206	No ACBM	MISC					
12.5	12x12 Off White w/Beige Stripes VFT Mastic			Room 203, 327, 403	No ACBM						
12.6	12x12 White VFT Mastic	500	SF	Men's and Women's Bathrooms Throughout School	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12.7	12x12 Beige Speckled VFT Mastic - Abated			Room 220	Abated						
12.8	12x12 Black VFT Mastic - Abated			4th Floor East Corridor	Abated	MISC					
13	Exterior Brick - Non-AHERA			Exterior of Building	Assumed	MISC					
14	Exterior Mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					
15	Interior Brick Material (Masonry)			Interior of Building	No ACBM	MISC					
16	Interior Brick Mortar			Interior of Building	No ACBM	MISC					
17	Red Brick Material			3rd Floor Janitors Closet	No ACBM	MISC					
18	Red Brick Mortar			3rd Floor Janitors Closet	No ACBM	MISC					

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
19	Cinderblock Material (Brick)			Men's and Women's Bathrooms, Room 403, and Janitors Closet	No ACBM	MISC					
20	Cinderblock Mortar Material			Men's and Women's Bathrooms, Room 403, and Janitors Closet	No ACBM	MISC					
21	Chalkboard Material			Room 305	No ACBM	MISC					
22	4 Inch Black Mop Guard			Men's and Women's Bathrooms Throughout School and Room 4	No ACBM	MISC					
23	4 Inch Black Mop Guard Mastic			Men's and Women's Bathrooms Throughout School	No ACBM	MISC					
24	Exterior Window Caulk			Exterior of Building	No ACBM	MISC					
25	12" x 12" Multi-Beige Floor Tile - Abated			Room 313	Abated	MISC					
26	12" x 12" Multi-Beige Floor Tile Mastic - Abated			Room 313	Abated	MISC					
27	12" x 12" Lt. Blue w/Blue & Wt. Specks FT	1,100	SF	Room 220	Assumed	MISC	No	15	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic	1,100	SF	Room 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Smooth Plaster			Throughout School	No ACBM	MISC					
30	2x2 White Pin Hole Ceiling Tile	4,000	SF	Lunch Room	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	Black-Gold Carpet Adhesive	6,100	SF	Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Black-White-Gray Terazzo Flooring	20,000	SF	1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom	Assumed	MISC	No	100	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" White w/Blue-Brown Spec's Floor Tile	2,000	SF	Rooms 219,229,318,320 and 335	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" White w/Blue-Brown Spec's Floor Tile Mastic	2,000	SF	Rooms 219,229,318,320 and 335	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	White-Gray Ceramic Grout	200	SF	Engineer Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	White-Gray Ceramic Adhesive	200	SF	Engineer Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Green-Black-White Terrazzo	3,200	SF	1st, 2nd, 3rd and 4th Boy's/Girl's Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
3E	9 X 9 Cream w/Off White Streaks			1st Floor Corridor Areas Across From Room 109	Assumed	MISC					
6	9x9 Red/Black VFT	38,000	SF	Rooms 111, 119	Chrysotile	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
6.1	9x9 Beige w/Brown Streaks VFT	1,900	SF	Room 219, 318, 311	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6.2	9x9 Red VFT			Room 320	Chrysotile	MISC					
6.3	9x9 Tan w/Brown Stripes VFT	3,120	SF	Rooms 319, 321, and 313	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
6.4	9x9 Light Green VFT - ABATED			Room 220	Abated						
6.5	9x9 Beige and Brown VFT	1,608	SF	Room 335	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	12x12 Light Red Speckle VFT	19,400	SF	Rooms 101, 123, 134, 106, 112, 1st Floor Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.1	12x12 Red Speckle VFT	900	SF	Room 101	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.2	12x12 Dark Beige Speckle VFT	1,200	SF	Rooms 108 and 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.3	12x12 Gray Speckle VFT	1,100	SF	Rooms 207, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.4	12x12 Light Beige Speckle VFT	1,050	SF	Room 206,128	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.5	12x12 Off White w/Beige Stripes VFT	1,800	SF	Rooms 203, 327 and 403	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.6	12x12 White VFT	500	SF	Men's and Women's Bathrooms Throughout School	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.7	12x12 Beige Speckle VFT	5,000	SF	Room 220,134,134A,137,138,425	Assumed	MISC	No	30	SF	6 ACBM with the potential for damage	Follow O&M Plan
7.8	12x12 Black VFT	7,000	SF	4th Floor East Corridor, Room 203	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	1x6 Wall Tile			Library	No ACBM	MISC					
9	Window Panels	1,000	SF	Throughout Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AA	Floor material Pinkish with white	13,000	SF	Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421	Assumed	MISC	No	15	SF	6 ACBM with the potential for damage	Follow O&M Plan
BB	12" x 12" White Floor Tile	37,000	SF	2nd ,3th, 4th floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CC	12"x 12"Red floor tile	1,000	SF	All stairwell entrances on 2nd, 3rd, 4th floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DD	12"x 12" black floor tile	1,000	SF	All stairwell entrances on 2nd, 3rd, 4th floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
EE	Mastic associate HA # BB,CC,DD	38,000	SF	2nd, 3rd, 4th floor corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FF	2 x 4' laid in ceiling tile White	40,000	SF	Most classrooms	Assumed	MISC	Yes	16	SF	6 ACBM with the potential for damage	Follow O&M Plan
GG	12" x12 white spline ceiling tile	5,000	SF	Lunchroom	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-100	Fire Curtain	400	SF	Auditorium Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-101	Woven electrical wire insulation			Auditorium stage light fixtures	Assumed	MISC					
HA-102	Electrical wire insulation for chandeliers			Auditorium	Assumed	MISC					
HA-103	1'x1' white grooved Ceiling Tile	16,900	SF	GYM	Assumed	MISC	Yes	100	SF	4 Damaged or significantly damaged friable misc. ACBM	Remove
HA-104	Glue for 1'x1' white grooved Ceilig Tile	2,000	SF	GYM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-105	12"X12" grey with white and brown specks VFT	2,000	SF	Rms. 204 A, 204 B, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
HA-105m	Adhesive for 12"x12"grey with white and brown VFT	2,000	SF	Rms. 204 A, 204B, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-106	Hard mud pipe fitting insulation			Boiler room and basement "wax" room	Assumed	TSI					
HA-107	Aircell pipe insulation			Garage	Chrysotile	TSI					
HA-108	Mudded fitting insulation in aircell pipe insulation			Garage	Chrysotile	TSI					
HA-109	Hard mudded fitting insulation on fiberglass pipe insulation	1,000	LF	Throughout the building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Boiler Insulation (Interior)			Boiler Room	No ACBM	MISC					

Chicago Public Schools

School Austin High School
Address 231 N Pine

Unit 66511
 Chicago, IL, 60644

Building ID 1220
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	05/03/2019
Manager Planner Name	Evan Christian
100-19466	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
11	
11.1	
11.2	
11.3	
11.4	
11.5	
110	
111	
112	
113	
114	
115	
12	
12.1	
12.2	
12.3	
12.4	
12.5	
12.6	
12.7	
12.8	
13	
14	
15	
16	

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	Sample to determine asbestos content, remove all damaged ACBM
28	
29	
30	
31	
32	Sample to determine asbestos content, remove or repair damaged ACBM
33	
34	
35	
36	
37	
3E	
6	Remove or repair damaged material
6.1	
6.2	
6.3	

Chicago Public Schools

School Austin High School
Address 231 N Pine

Unit 66511
 Chicago, IL, 60644

Building ID 1220
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
6.4	
6.5	
7	
7.1	
7.2	
7.3	
7.4	
7.5	
7.6	
7.7	Sample to determine asbestos content, remove all damaged ACBM
7.8	
8	
9	
AA	Sample to determine asbestos content, removal all damaged ACBM
BB	
CC	
DD	
EE	
FF	Sample to determine asbestos content, removal all damaged ACBM
GG	
HA-100	
HA-101	
HA-102	
HA-103	Sample to determine asbestos content, removal all damaged ACBM
HA-104	
HA-105	

Chicago Public Schools

School Austin High School

Unit 66511

Building ID 1220

Address 231 N Pine

Chicago, IL, 60644

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
HA-105m	
HA-106	
HA-107	
HA-108	
HA-109	
O	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 Red/Black Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12x12 Red/Black Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Throughout 3rd, 4th, and 2nd Flr. Corridors, Auditorium**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.1**
MATERIAL DESCRIPTION: **9 X 9 Beige w/Brown Strips VFTMastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 219, 318, 311, 431**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11.1**

MATERIAL DESCRIPTION: **9 X 9 Beige w/Brown Strips VFTMastic - Abated**

MATERIAL LOCATION: **Room 219, 318, 311, 431**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.2**
MATERIAL DESCRIPTION: **9 X 9 Red VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11.2**

MATERIAL DESCRIPTION: **9 X 9 Red VFT Mastic**

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.3**
MATERIAL DESCRIPTION: **9 X 9 Tan w/Brown Stripes VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Rooms 319, 321, and 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11.3**

MATERIAL DESCRIPTION: **9 X 9 Tan w/Brown Stripes VFT Mastic - Abated**

MATERIAL LOCATION: **Rooms 319, 321, and 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.4**
MATERIAL DESCRIPTION: **9 X 9 Light Green VFT Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11.4**

MATERIAL DESCRIPTION: **9 X 9 Light Green VFT Mastic - ABATED**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11.5**
MATERIAL DESCRIPTION: **9 X 9 Beige/Brown VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **11.5**

MATERIAL DESCRIPTION: **9 X 9 Beige/Brown VFT Mastic**

MATERIAL LOCATION: **Room 335**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **1'x1' Wall Acoustical Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 431**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **1'x1' Wall Acoustical Tiles**
MATERIAL LOCATION: **Room 431**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**
MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**

MATERIAL QUANTITY: **4500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White w/ Blue Specks Floor Tile**
MATERIAL LOCATION: **Rooms 134, 134B, 137, 138, 431, 433**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Beige Stone Pattern Sheet Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **Beige Stone Pattern Sheet Flooring**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Mastic Associated w/ Beige Stone Pattern Sheet Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **Mastic Associated w/ Beige Stone Pattern Sheet Flooring**
MATERIAL LOCATION: **Room 239**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Gray Spray-on Fireproofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Gray Spray-on Fireproofing**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12 X 12 Light Red Speckle VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rms 101, 123, 106, 112, 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12 X 12 Light Red Speckle VFT Mastic**

MATERIAL LOCATION: **Rms 101, 123, 106, 112, 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.1**
MATERIAL DESCRIPTION: **12 X 12 Red Speckle VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.1**

MATERIAL DESCRIPTION: **12 X 12 Red Speckle VFT Mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.2**
MATERIAL DESCRIPTION: **12 X 12 Dark Beige Speckle Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.2**
MATERIAL DESCRIPTION: **12 X 12 Dark Beige Speckle Mastic**
MATERIAL LOCATION: **Room 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.3**
MATERIAL DESCRIPTION: **12x12 Gray Speckle VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 207,208**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.3**
MATERIAL DESCRIPTION: **12x12 Gray Speckle VFT Mastic**
MATERIAL LOCATION: **Rooms 207,208**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.4**
MATERIAL DESCRIPTION: **12x12 Light Beige Speckle VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **RM 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.4**

MATERIAL DESCRIPTION: **12x12 Light Beige Speckle VFT Mastic**

MATERIAL LOCATION: **RM 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.5**
MATERIAL DESCRIPTION: **12x12 Off White w/Beige Stripes VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203, 327, 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.5**

MATERIAL DESCRIPTION: **12x12 Off White w/Beige Stripes VFT Mastic**

MATERIAL LOCATION: **Room 203, 327, 403**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.6**
MATERIAL DESCRIPTION: **12x12 White VFT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.6**
MATERIAL DESCRIPTION: **12x12 White VFT Mastic**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.7**
MATERIAL DESCRIPTION: **12x12 Beige Speckled VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.7**

MATERIAL DESCRIPTION: **12x12 Beige Speckled VFT Mastic - Abated**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12.8**
MATERIAL DESCRIPTION: **12x12 Black VFT Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor East Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **12.8**

MATERIAL DESCRIPTION: **12x12 Black VFT Mastic - Abated**

MATERIAL LOCATION: **4th Floor East Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Exterior Mortar - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Exterior Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Interior Brick Material (Masonry)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Interior Brick Material (Masonry)**

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Interior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Red Brick Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Red Brick Material**

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Red Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Red Brick Mortar**

MATERIAL LOCATION: **3rd Floor Janitors Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Cinderblock Material (Brick)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Cinderblock Material (Brick)**

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Cinderblock Mortar Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Cinderblock Mortar Material**

MATERIAL LOCATION: **Men's and Women's Bathrooms, Room 403, and Janitors Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Chalkboard Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Chalkboard Material**

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **4 Inch Black Mop Guard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School and Room 4**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **4 Inch Black Mop Guard**

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School and Room 4**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **4 Inch Black Mop Guard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **4 Inch Black Mop Guard Mastic**

MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Exterior Window Caulk**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile - Abated**

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile Mastic - Abated**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Multi-Beige Floor Tile Mastic - Abated**

MATERIAL LOCATION: **Room 313**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Wt. Specks FT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Wt. Specks FT**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, remove all damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 220**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Lt. Blue w/Blue & Wt. Specks FT Mastic**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Smooth Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Smooth Plaster**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2x2 White Pin Hole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **2x2 White Pin Hole Ceiling Tile**
MATERIAL LOCATION: **Lunch Room**
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Black-Gold Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Black-Gold Carpet Adhesive**
MATERIAL LOCATION: **Main Office, Rooms 201,202,300,300A, 320B,414B and Engineer Office**
MATERIAL QUANTITY: **6100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Black-White-Gray Terazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Black-White-Gray Terazzo Flooring**
MATERIAL LOCATION: **1st,2nd,3rd and 4th Floor Corridors, Stairwells, Landing, Kitchen, Kit. Office and Lunchroom**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, remove or repair damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" White w/Blue-Brown Spec's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **12"x12" White w/Blue-Brown Spec's Floor Tile**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12"x12" White w/Blue-Brown Spec's Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **12"x12" White w/Blue-Brown Spec's Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 219,229,318,320 and 335**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **White-Gray Ceramic Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office Toilet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **White-Gray Ceramic Grout**

MATERIAL LOCATION: **Engineer Office Toilet**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **White-Gray Ceramic Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Engineer Office Toilet**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **White-Gray Ceramic Adhesive**

MATERIAL LOCATION: **Engineer Office Toilet**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Green-Black-White Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Boy's/Girl's Toilet**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Green-Black-White Terrazzo**
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Boy's/Girl's Toilet**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3E**
MATERIAL DESCRIPTION: **9 X 9 Cream w/Off White Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor Areas Across From Room 109**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **3E**

MATERIAL DESCRIPTION: **9 X 9 Cream w/Off White Streaks**

MATERIAL LOCATION: **1st Floor Corridor Areas Across From Room 109**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9x9 Red/Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 111, 119**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **9x9 Red/Black VFT**
MATERIAL LOCATION: **Rooms 111, 119**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair damaged material

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 219, 318, 311**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6.1**
MATERIAL DESCRIPTION: **9x9 Beige w/Brown Streaks VFT**
MATERIAL LOCATION: **Room 219, 318, 311**
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.2**
MATERIAL DESCRIPTION: **9x9 Red VFT**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6.2**

MATERIAL DESCRIPTION: **9x9 Red VFT**

MATERIAL LOCATION: **Room 320**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Stripes VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 319, 321, and 313**
MATERIAL QUANTITY: **3120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6.3**
MATERIAL DESCRIPTION: **9x9 Tan w/Brown Stripes VFT**
MATERIAL LOCATION: **Rooms 319, 321, and 313**
MATERIAL QUANTITY: **3120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.4**
MATERIAL DESCRIPTION: **9x9 Light Green VFT - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6.4**

MATERIAL DESCRIPTION: **9x9 Light Green VFT - ABATED**

MATERIAL LOCATION: **Room 220**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6.5**
MATERIAL DESCRIPTION: **9x9 Beige and Brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 335**
MATERIAL QUANTITY: **1608** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **6.5**
MATERIAL DESCRIPTION: **9x9 Beige and Brown VFT**
MATERIAL LOCATION: **Room 335**
MATERIAL QUANTITY: **1608** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12x12 Light Red Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101, 123, 134, 106, 112, 1st Floor Hall**
MATERIAL QUANTITY: **19400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **12x12 Light Red Speckle VFT**
MATERIAL LOCATION: **Rooms 101, 123, 134, 106, 112, 1st Floor Hall**
MATERIAL QUANTITY: **19400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12x12 Red Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.1**
MATERIAL DESCRIPTION: **12x12 Red Speckle VFT**
MATERIAL LOCATION: **Room 101**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **12x12 Dark Beige Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.2**
MATERIAL DESCRIPTION: **12x12 Dark Beige Speckle VFT**
MATERIAL LOCATION: **Rooms 108 and 220**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12x12 Gray Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 207, 208**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.3**
MATERIAL DESCRIPTION: **12x12 Gray Speckle VFT**
MATERIAL LOCATION: **Rooms 207, 208**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12x12 Light Beige Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 206,128**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.4**
MATERIAL DESCRIPTION: **12x12 Light Beige Speckle VFT**
MATERIAL LOCATION: **Room 206,128**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.5**
MATERIAL DESCRIPTION: **12x12 Off White w/Beige Stripes VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 203, 327 and 403**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.5**
MATERIAL DESCRIPTION: **12x12 Off White w/Beige Stripes VFT**
MATERIAL LOCATION: **Rooms 203, 327 and 403**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.6**
MATERIAL DESCRIPTION: **12x12 White VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.6**
MATERIAL DESCRIPTION: **12x12 White VFT**
MATERIAL LOCATION: **Men's and Women's Bathrooms Throughout School**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.7**
MATERIAL DESCRIPTION: **12x12 Beige Speckle VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 220,134,134A,137,138,425**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.7**
MATERIAL DESCRIPTION: **12x12 Beige Speckle VFT**
MATERIAL LOCATION: **Room 220,134,134A,137,138,425**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **30** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, remove all damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7.8**
MATERIAL DESCRIPTION: **12x12 Black VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **4th Floor East Corridor, Room 203**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **7.8**
MATERIAL DESCRIPTION: **12x12 Black VFT**
MATERIAL LOCATION: **4th Floor East Corridor, Room 203**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **1x6 Wall Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **1x6 Wall Tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Window Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **Window Panels**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Floor material Pinkish with white**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **AA**
MATERIAL DESCRIPTION: **Floor material Pinkish with white**
MATERIAL LOCATION: **Rooms 101,107,133,211,215,313,319,321,327,411,415,419,421**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, removal all damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd ,3th, 4th floor corridors**
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **BB**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **2nd ,3th, 4th floor corridors**
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **12'x 12" Red floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **CC**
MATERIAL DESCRIPTION: **12'x 12"Red floor tile**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **12"x 12" black floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **DD**
MATERIAL DESCRIPTION: **12"x 12" black floor tile**
MATERIAL LOCATION: **All stairwell entrances on 2nd, 3rd, 4th floors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Mastic associate HA # BB,CC,DD**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd, 3rd, 4th floor corridors**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **EE**
MATERIAL DESCRIPTION: **Mastic associate HA # BB,CC,DD**
MATERIAL LOCATION: **2nd, 3rd, 4th floor corridors**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FF**
MATERIAL DESCRIPTION: **2'x 4' laid in ceiling tile White**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Most classrooms**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **16** DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **FF**

MATERIAL DESCRIPTION: **2'x 4' laid in ceiling tile White**

MATERIAL LOCATION: **Most classrooms**

MATERIAL QUANTITY: **40000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **16**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, removal all damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **GG**
MATERIAL DESCRIPTION: **12" x12 white spline ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **GG**
MATERIAL DESCRIPTION: **12" x12 white spline ceiling tile**
MATERIAL LOCATION: **Lunchroom**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Fire Curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Stage**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-100**

MATERIAL DESCRIPTION: **Fire Curtain**

MATERIAL LOCATION: **Auditorium Stage**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Woven electrical wire insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium stage light fixtures**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **Woven electrical wire insulation**

MATERIAL LOCATION: **Auditorium stage light fixtures**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-102**
MATERIAL DESCRIPTION: **Electrical wire insulation for chandeliers**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-102**

MATERIAL DESCRIPTION: **Electrical wire insulation for chandeliers**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-103**
MATERIAL DESCRIPTION: **1'x1' white grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **4 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **GYM**
MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**
COMMENTS: **Missing 10 tiles and 15 damaged tiles**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-103**

MATERIAL DESCRIPTION: **1'x1' white grooved Ceiling Tile**

MATERIAL LOCATION: **GYM**

MATERIAL QUANTITY: **16900**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **100**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine asbestos content, removal all damaged ACBM

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-104**
MATERIAL DESCRIPTION: **Glue for 1'x1' white grooved Ceilig Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **GYM**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-104**

MATERIAL DESCRIPTION: **Glue for 1'x1' white grooved Ceilig Tile**

MATERIAL LOCATION: **GYM**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-105**
MATERIAL DESCRIPTION: **12"X12" grey with white and brown specks VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 204 A, 204 B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-105**

MATERIAL DESCRIPTION: **12"X12" grey with white and brown specks VFT**

MATERIAL LOCATION: **Rms. 204 A, 204 B, 208**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-105m**
MATERIAL DESCRIPTION: **Adhesive for 12"x12"grey with white and brown VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rms. 204 A, 204B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-105m**
MATERIAL DESCRIPTION: **Adhesive for 12"x12"grey with white and brown VFT**
MATERIAL LOCATION: **Rms. 204 A, 204B, 208**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-106**
MATERIAL DESCRIPTION: **Hard mud pipe fitting insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler room and basement "wax" room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-106**

MATERIAL DESCRIPTION: **Hard mud pipe fitting insulation**

MATERIAL LOCATION: **Boiler room and basement "wax" room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUILDING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-107**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-107**

MATERIAL DESCRIPTION: **Aircell pipe insulation**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-108**
MATERIAL DESCRIPTION: **Mudded fitting insulation in aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2019**

Inspector's Signature: _____

Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-108**

MATERIAL DESCRIPTION: **Mudded fitting insulation in aircell pipe insulation**

MATERIAL LOCATION: **Garage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-109**
MATERIAL DESCRIPTION: **Hard mudded fitting insulation on fiberglass pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout the building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 04/11/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **HA-109**
MATERIAL DESCRIPTION: **Hard mudded fitting insulation on fiberglass pipe insulation**
MATERIAL LOCATION: **Throughout the building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Austin High School** INSPECTION DATE: **4/11/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Boiler Insulation (Interior)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/11/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66511** BUIDLING ID: **1220**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Austin High School** REVIEW DATE: **5/3/2019**
ADDRESS: **231 N Pine** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Boiler Insulation (Interior)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **05/03/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Carol Ashman


has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/22/2019 - 1/24/2019

Exam Date: 1/24/2019

Expiration Date: 1/24/2020

Certificate Number: ABI1901240283


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

CAROL L ASHMAN
1633 Mc KAY ST.
WAUKEGAN, IL 60087

3/8/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 19554

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 19554	ISSUED 3/8/2019	EXPIRES 05/15/2020		INSPECTOR	1/24/2020
CAROL L ASHMAN 1633 Mc KAY ST. WAUKEGAN, IL 60087 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/22/2020
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2015



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024159


Katy DeSalvo, Director

Reliable
Environmental
Solutions, Inc. **RES**

This is to certify that **Evan Christian**

*has on January 28 & 29, 2016, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Initial Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: January 28 & 29, 2016

Examination Date: January 29, 2016

Expiration Date: January 29, 2017

Certificate Number: MP/0103

William S. Williams

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ www.ReliableEnv.com

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2019

Exam Date: 11/19/2019

Expiration Date: 11/19/2020

Certificate Number: BIR1911192384


Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 19466

ISSUED
4/12/2019

EXPIRES
05/15/2020

EVAN I CHRISTIAN
3024 N RACINE AVE, APT 2
CHICAGO, IL 60657

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

11/28/2019

MANAGEMENT PLANNER

1/5/2019

PROJECT MANAGER

2/5/2020

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 1/7/2019

Exam Date: 1/7/2019

Expiration Date: 1/7/2020


Certificate Number: MPR1901070063



Kathy DeSalvo, Director

Evan Christian

Illinois Licensed Project Manager, and Air Sampling Professional



ENDORSEMENTS	TC EXPIRES
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/12/2015
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

**CARNOW
CONIBEAR**

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed