

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0765
SCHOOL NAME: Collins High School
ADDRESS OF SCHOOL: 1313 S. Sacramento
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/24/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 213
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME(Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-01934
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Randy Livingston

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Collins High School

1313 S. Sacramento
Chicago, IL, 60623

Unit: 49131
Building ID: 1880

IDPH ID Number: 14-016-2990-0765

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

November 25, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299	Unit: 46411	Region: 03	IDPH ID:14-016-2990-0765
----------------------	-------------	------------	--------------------------

School: Collins High School	Building ID: 1880
-----------------------------	-------------------

Address: 1313 S. Sacramento
Chicago, IL, 60623

Building Contact:	Contact Phone:
-------------------	----------------

Current Building Owners: Chicago Public Schools

Review Date: 12/16/2019

Inspector: Marcos Iwankiw	Inspector IDPH License: 100-03175
Management Planner: Randy Livingston	Management Planner IDPH License: 100-01934

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates

Randy Livingston
100-01934

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 25, 2019

RE: Collins High School, Unit 49131
1313 S. Sacramento
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Collins High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Collins High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Collins High School Unit: 46411 Region: 03
Address: 1313 S. Sacramento Chicago, IL, 60623
IDPH ID: 14-016-2990-0765 Building ID: 1880
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 213

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Chicago, IL, 60607
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175

Signature:
Date: 11/25/2019

6. Management Planner

Management Planner Name: Randy Livingston

Management Planner IDPH license # 100-01934

Signature:
Date: 12/16/2019

7. Review Date: 12/16/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Collins High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1880:

104	2'x4' Ceiling Tile
223	12" x 12" White Floor Tile
224	Mastic Associated w/ 12" x 12" White Floor Tile
46	Purple Carpet Mastic
6	2' x 4' Ceiling Panels
HA-100	12"x12" red pattern design VFT
HA-101	Adhesive for 12"x12" red pattern design VFT

B. The following new homogenous areas have been identified for Building 1880:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

051	Vibration Absorber
1	12" x 12" White w/Reddish Brown Streaks Floor Tile
103	Carpet Mastic
104	2'x4' Ceiling Tile
105	12"x12" Off-White with Grey Specs Floor Tile
106	12"x12" Off-White with Grey Specs Floor Tile Mastic
107	12"x12" Dark Brown Floor Tile
108	12"x12" Dark Brown Floor Tile Mastic
109	4" Vinyl Baseboard
110	4" Vinyl Baseboard Mastic
111	4'x4' Ceiling Tile
112	12"x12" Off-White with Blue Patterns Floor Tile
113	12"x12" Off-White with Blue Patterns Floor Tile Mastic
114	White Sink Undercoat
115	Drywall
116	Drywall Joint Compound
117	Fire Caulk
139	Brown Carpet Mastic
206	4" Gray Vinyl Baseboard Mastic - Installed in 1998
207	Beige W/White Streak Linoleum
208	Beige W/White Streak Linoleum Mastic
209	Yellow Linoleum
210	Yellow Linoleum Mastic
211	Brown Carpet W/Grey Pattern Adhesive
212	Red Vinyl Base Cove
213	Red Vinyl Base Cove Mastic
214	Yellow Vinyl Base Cove
215	Yellow Vinyl Base Cove Mastic
216	Blue W/Gold Lines Carpet Adhesive
217	Gray W/Blue & Yellow Specs. Carpet Adhesive
218	Brown w/ Yellow & Green Specs Carpet Adhesive
219	Blue Vinyl Base Cove
220	Blue Vinyl Base Cove Mastic
221	2' X 2' Grey & Dark Grey Tile Carpet Adhesive
222	Tan Carpet Adhesive
223	12" x 12" White Floor Tile
224	Mastic Associated w/ 12" x 12" White Floor Tile
3	12" x 12" Beige Floor Tile
4	12" x 12" Gray Floor Tile

44	Roofing Material - Not AHERA
45	Roof Flashing - Not AHERA
46	Purple Carpet Mastic
47	Brown Carpet Mastic
48	Lab Tops
49	Blue Ceramic Tile Grout
5	12" x 12" Ceiling Tile and Mastic
51	Lab Hood Transite
52	12" x 12" Beige w/White Speckle Floor Tile
53	12" x 12" Beige w/White Speckle Floor Tile Mastic
54	12" x 12" Tan with Brown Streaks Floor Tile
55	12" x 12" Tan with Brown Streak Floor Tile Mastic
56	White & Red Ceramic Floor Tile and Grout
57	White & Red Ceramic Floor Tile Mastic
58	Grey Ceramic Floor Tile
59	Grey Ceramic Floor Tile Mastic
6	2' x 4' Ceiling Panels
60	12"x12" White w/Multi Colored Specks Floor Tile
61	12"x12" White w/Multi Colored Specks Floor Tile Mastic
62	12"x12" Dark Blue w/Light Blue Floor Tile
63	12"x12" Dark Blue w/Light Blue Floor Tile Mastic
64	12"x12" Yellow w/Light Yellow Floor Tile
65	12"x12" Yellow w/Light Yellow Floor Tile Mastic
66	12"x12" Beige w/Tan Floor Tile
68	12"x12" Red Floor Tile
69	12"x12" Red Floor Tile Mastic
7	4' x 4' Ceiling Panels
70	12"x12" Grey w/Blue Specks Floor Tile
71	12"x12" Grey w/Blue Specks Floor Tile Mastic
72	Drywall
73	Drywall Tape and Joint Compound
8	Hard Plaster
HA-100	12"x12" red pattern design VFT
HA-101	Adhesive for 12"x12" red pattern design VFT
HA-102	Interior lining of the Kiln

The following areas were deemed to be inaccessible:

12	12" x 12" Gray Floor Tile Mastic
208	Beige W/White Streak Linoleum Mastic
210	Yellow Linoleum Mastic
211	Brown Carpet W/Grey Pattern Adhesive
213	Red Vinyl Base Cove Mastic
215	Yellow Vinyl Base Cove Mastic
216	Blue W/Gold Lines Carpet Adhesive

217	Gray W/Blue & Yellow Specs. Carpet Adhesive
218	Brown w/ Yellow & Green Specs Carpet Adhesive
220	Blue Vinyl Base Cove Mastic
221	2' X 2' Grey & Dark Grey Tile Carpet Adhesive
222	Tan Carpet Adhesive
224	Mastic Associated w/ 12" x 12" White Floor Tile
46	Purple Carpet Mastic
55	12" x 12" Tan with Brown Streak Floor Tile Mastic
57	White & Red Ceramic Floor Tile Mastic
59	Grey Ceramic Floor Tile Mastic
61	12"x12" White w/Multi Colored Specks Floor Tile Mastic
63	12"x12" Dark Blue w/Light Blue Floor Tile Mastic
65	12"x12" Yellow w/Light Yellow Floor Tile Mastic
71	12"x12" Grey w/Blue Specks Floor Tile Mastic
HA-101	Adhesive for 12"x12" red pattern design VFT

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Randy Livingston, IDPH License # 100-01934. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Collins High School Building 1880 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
051	Vibration Absorber	10	LF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1	12" x 12" White w/Reddish Brown Streaks Floor Tile	3,000	SF	Fine Arts Building Rooms and Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	12" x 12" Brown Floor Tile Mastic - ABATED			Coach Love's Office, Weight Room, and Drivers Ed (Now ROTC Classroom), Rooms 176 & 177	ABATED	MISC		None						Low
103	Carpet Mastic	8,175	SF	Building B: First Floor - Auditorium, 134, 136, 140, 140A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	2'x4' Ceiling Tile	15,350	SF	Building B: 1st Floor - 122, 130, 130A-C, 132, 132A-B, 133, 135, 136B, 137, 140, 1410A-F, 144, 144A-B, 146, 146A, 148 and Office 1	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
105	12"x12" Off-White with Grey Specs Floor Tile	7,850	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12"x12" Off-White with Grey Specs Floor Tile Mastic	7,850	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12"x12" Dark Brown Floor Tile	2,150	SF	Building B: 1st Floor - 130, 122, 132, 144, 146, and 148	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12"x12" Dark Brown Floor Tile Mastic	2,150	SF	Building B: 1st Floor - 130, 122, 132, 144, 146, and	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				148										
109	4" Vinyl Baseboard	2,200	LF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12" x 12" Beige Floor Tile Mastic			Consumer Science and Music Complexes	NO_ACBM	MISC								
110	4" Vinyl Baseboard Mastic	2,200	LF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	4'x4' Ceiling Tile	2,800	SF	Building B: 1st Floor - 134 and 136	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12"x12" Off-White with Blue Patterns Floor Tile	830	SF	Building B: 1st Floor - 140B and 140C (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	12"x12" Off-White with Blue Patterns Floor Tile Mastic	830	SF	Building B: 1st Floor - 140B and 140C (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	White Sink Undercoat	1	EA	Building B: 1st Floor - Room 144	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Drywall	10,000	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	Drywall Joint Compound	48,000	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Complex										
17	Green Linoleum			3rd Floor Hall	NO_ACBM	MISC								
18	Clay Tile			2nd and 3rd Floor Kitchen, 3rd Floor Hall	NO_ACBM	MISC								
19	Clay Tile Mortar			2nd and 3rd Floor Kitchen, 3rd Floor Hall	NO_ACBM	MISC								
2	12" x 12" Brown Floor Tile - ABATED			Coach Love's Office, Weight Room and Driver's Ed (Now ROTC Classroom)	ABATED	MISC								
20	Black Baseboard			Throughout Complex	NO_ACBM	MISC								
206	4" Gray Vinyl Baseboard Mastic - Installed in 1998			Throughout Building (mastic not observed)	ASSUMED	MISC								
207	Beige W/White Streak Linoleum	6,500	SF	Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
208	Beige W/White Streak Linoleum Mastic	6,500	SF	Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
209	Yellow Linoleum	4,300	SF	Room 200, 200 b, 203, 205, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Black Baseboard Mastic			Throughout Complex	NO_ACBM	MISC								
210	Yellow Linoleum Mastic	4,300	SF	Room 200, 200 b, 203, 205, 205A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
211	Brown Carpet W/Grey Pattern Adhesive	200	SF	Room 329 (not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
212	Red Vinyl Base Cove	2,000	LF	Throughout 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
213	Red Vinyl Base Cove Mastic	2,000	LF	Throughout 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
214	Yellow Vinyl Base Cove	2,750	LF	Throughout 2nd & 3rd Floor Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
215	Yellow Vinyl Base Cove Mastic	2,750	LF	Throughout 2nd and 3rd Floor Hallways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
216	Blue W/Gold Lines Carpet Adhesive	7,000	SF	Library, and Library Offices 100 to 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
35	Exterior Door Caulk - Not AHERA			Throughout Complex	NO_ACBM	MISC								
36	Exterior Window Caulk - Not AHERA			Throughout Complex	NO_ACBM	MISC								
37	Tank Insulation			Pool Basement	NO_ACBM	TSI								
38	Tank Wrap			Pool Basement	NO_ACBM	MISC								
39	Fiberglass Pipe Insulation			Throughout Complex	NO_ACBM	TSI								
4	12" x 12" Gray Floor Tile	1,500	SF	3rd Floor Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Hard Joint Compound on Fiberglass Pipe Insulation			Throughout Complex	NO_ACBM	TSI								
41	Cover on Hard Joint Compound on Fiberglass Lag			Throughout Complex	NO_ACBM	TSI								
42	Duct Insulation			Hall by Kitchen	NO_ACBM	TSI								
43	Tank Insulation			Pump Room	NO_ACBM	TSI								
44	Roofing Material - Not AHERA			Roof (not observed)	ASSUMED	MISC								
45	Roof Flashing - Not AHERA			Roof	ASSUMED	MISC								
46	Purple Carpet Mastic	1,000	SF	Rooms 208, 232 (not observed)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
47	Brown Carpet Mastic			Library and Office	ASSUMED	MISC								
48	Lab Tops	1,000	SF	Rooms 300, 305, and 310, 307, 313, and Commercial Arts (observed only in 200, 205, 310, 313)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Blue Ceramic Tile Grout			Locker Rooms	ASSUMED	MISC								
5	12" x 12" Ceiling Tile and Mastic			Classrooms and Hallways (not observed)	ASSUMED	MISC								
50	Terrazzo Basins			2nd & 3rd Floor Slop Rooms and Boys Locker Room	NO_ACBM	MISC								
51	Lab Hood Transite	100	SF	Rooms 305 & 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12" x 12" Beige w/White Speckle Floor Tile	2,200	SF	1st Floor Attendance Office and Room 312	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12" x 12" Beige w/White Speckle Floor Tile Mastic	2,200	SF	1st Floor Attendance Office and Room 312	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" x 12" Tan with Brown Streaks Floor Tile	2,200	SF	2nd Floor Lunch Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
55	12" x 12" Tan with Brown Streak Floor Tile Mastic	2,200	SF	2nd Floor Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	White & Red Ceramic Floor Tile and Grout	2,100	SF	2nd & 3rd Floor Boys and Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	White & Red Ceramic Floor Tile Mastic	2,100	SF	2nd & 3rd Floor Boys and Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Grey Ceramic Floor Tile	3,500	SF	1st Floor Boys and Girls Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Grey Ceramic Floor Tile Mastic	3,500	SF	1st Floor Boys and Girls Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
6	2' x 4' Ceiling Panels	200,000	SF	Throughout Complex	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
60	12"x12" White w/Multi Colored Specks Floor Tile	12,000	SF	First and Second Floor Hallways and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12"x12" White w/Multi Colored Specks Floor Tile Mastic	12,000	SF	First and Second Floor Hallways and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12"x12" Dark Blue w/Light Blue Floor Tile	1,500	SF	First Floor Hallways and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12"x12" Dark Blue w/Light Blue Floor Tile Mastic	1,500	SF	First Floor Hallways and Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12"x12" Yellow w/Light Yellow Floor Tile	3,000	SF	Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12"x12" Yellow w/Light Yellow Floor Tile Mastic	3,000	SF	Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12"x12" Beige w/Tan Floor Tile	6,000	SF	Third Floor Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12"x12" Beige w/Tan Floor Tile Mastic			Third Floor Hallway	NO_ACBM	MISC								
68	12"x12" Red Floor Tile	500	SF	Third Floor Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Red Floor Tile Mastic	500	SF	Third Floor Hallway	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
7	4' x 4' Ceiling Panels	2,800	SF	Throughout Complex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	12"x12" Grey w/Blue Specks Floor Tile	15,000	SF	Third Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"x12" Grey w/Blue Specks Floor Tile Mastic	15,000	SF	Third Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	Drywall	25,000	SF	Throughout Academic Building "A"	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	Drywall Tape and Joint Compound	60,000	LF	Throughout Academic Building "A"	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
8	Hard Plaster	100,000	SF	Throughout Complex	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
9	12" x 12" White w/Reddish Brown Streaks FT Mastic	3,000	SF	Fine Arts Rooms and Basement	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
HA-100	12"x12" red pattern design VFT	72	SF	Detention room storage (not observed)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
HA-101	Adhesive for 12"x12" red pattern design VFT	72	SF	Detention room storage	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
HA-102	Interior lining of the Kiln	15	SF	(not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/25/2019
Inspector Name <u>Marcos Iwankiw</u>
100-03175 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
051	
1	
10	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	
13	

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
139	Not observed 2016 - same
14	
15	
16	
17	
18	
19	
2	
20	
206	Not observed 2016
207	
208	
209	
21	
210	
211	
212	
213	
214	
215	
216	
217	
218	
219	
22	
220	
221	
222	
223	

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
224	
23	
24	
25	
26	
27	
27 M	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	not observed
47	Not observed 2016

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
48	Not observed
49	
5	Not observed 2016 - same
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	

Chicago Public Schools

School Collins High School Unit 46411 Building ID 1880

Address 1313 S. Sacramento Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8	
9	
HA-100	Not observed
HA-101	
HA-102	Not observed

Table II

Management Planner's Review

Chicago Public Schools

School Collins High School

Unit 46411

Building ID 1880

Address 1313 S. Sacramento

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
051	Vibration Absorber	10	LF	Kitchen	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
1	12" x 12" White w/Reddish Brown Streaks Floor Tile	3,000	SF	Fine Arts Building Rooms and Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12" x 12" Brown Floor Tile Mastic - ABATED			Coach Love's Office, Weight Room, and Drivers Ed (Now ROTC Classroom), Rooms 176 & 177	Abated	MISC					
103	Carpet Mastic	8,175	SF	Building B: First Floor - Auditorium, 134, 136, 140, 140A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	2'x4' Ceiling Tile	15,350	SF	Building B: 1st Floor - 122, 130, 130A-C, 132, 132A-B, 133, 135, 136B, 137, 140, 1410A-F, 144, 144A-B, 146, 146A, 148 and Office 1	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
105	12"x12" Off-White with Grey Specs Floor Tile	7,850	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12"x12" Off-White with Grey Specs Floor Tile Mastic	7,850	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12"x12" Dark Brown Floor Tile	2,150	SF	Building B: 1st Floor - 130, 122, 132, 144, 146, and 148	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12"x12" Dark Brown Floor Tile Mastic	2,150	SF	Building B: 1st Floor - 130, 122, 132, 144, 146, and 148	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	4" Vinyl Baseboard	2,200	LF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Beige Floor Tile Mastic			Consumer Science and Music Complexes	No ACBM	MISC					
110	4" Vinyl Baseboard Mastic	2,200	LF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
111	4'x4' Ceiling Tile	2,800	SF	Building B: 1st Floor - 134 and 136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
112	12"x12" Off-White with Blue Patterns Floor Tile	830	SF	Building B: 1st Floor - 140B and 140C (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12"x12" Off-White with Blue Patterns Floor Tile Mastic	830	SF	Building B: 1st Floor - 140B and 140C (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	White Sink Undercoat	1	EA	Building B: 1st Floor - Room 144	Assumed	SURFACE	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
115	Drywall	10,000	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	Drywall Joint Compound	48,000	SF	Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	Fire Caulk	2,000	LF	Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
118	Flo-Tech Insulation Wrap			Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	No ACBM	MISC					
119	Duct Sealant			Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1	No ACBM	MISC					
12	12" x 12" Gray Floor Tile Mastic	150	SF	3rd Floor Lunch Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Interior Window Glazing			Throughout Complex	No ACBM	MISC					
139	Brown Carpet Mastic			10th Floor Corridor, 1039, 1236, 1339, 1700, 1720, 500, & 522 (not observed)	Assumed	MISC					Follow O&M Plan
14	Interior Brick			Throughout Complex	No ACBM	MISC					
15	Interior Brick Mortar			Throughout Complex	No ACBM	MISC					
16	Terrazzo Flooring			Throughout Complex	No ACBM	MISC					

Chicago Public Schools

School Collins High School

Unit 46411

Building ID 1880

Address 1313 S. Sacramento

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
17	Green Linoleum			3rd Floor Hall	No ACBM	MISC					
18	Clay Tile			2nd and 3rd Floor Kitchen, 3rd Floor Hall	No ACBM	MISC					
19	Clay Tile Mortar			2nd and 3rd Floor Kitchen, 3rd Floor Hall	No ACBM	MISC					
2	12" x 12" Brown Floor Tile - ABATED			Coach Love's Office, Weight Room and Driver's Ed (Now ROTC Classroom)	Abated	MISC					
20	Black Baseboard			Throughout Complex	No ACBM	MISC					
206	4" Gray Vinyl Baseboard Mastic - Installed in 1998			Throughout Building (mastic not observed)	Assumed	MISC					
207	Beige W/White Streak Linoleum	6,500	SF	Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
208	Beige W/White Streak Linoleum Mastic	6,500	SF	Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
209	Yellow Linoleum	4,300	SF	Room 200, 200 b, 203, 205, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Black Baseboard Mastic			Throughout Complex	No ACBM	MISC					
210	Yellow Linoleum Mastic	4,300	SF	Room 200, 200 b, 203, 205, 205A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
211	Brown Carpet W/Grey Pattern Adhesive	200	SF	Room 329 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
212	Red Vinyl Base Cove	2,000	LF	Throughout 3rd Floor Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
213	Red Vinyl Base Cove Mastic	2,000	LF	Throughout 3rd Floor Classrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
214	Yellow Vinyl Base Cove	2,750	LF	Throughout 2nd & 3rd Floor Hallway	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
215	Yellow Vinyl Base Cove Mastic	2,750	LF	Throughout 2nd and 3rd Floor Hallways	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
216	Blue W/Gold Lines Carpet Adhesive	7,000	SF	Library, and Library Offices 100 to 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
217	Gray W/Blue & Yellow Specs. Carpet Adhesive	800	SF	Room 140-142, 145, 120, 121, 126, 128-130	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
218	Brown w/ Yellow & Green Specs Carpet Adhesive	800	SF	132, 134-136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
219	Blue Vinyl Base Cove	2,250	LF	Throughout 1st Floor A-Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Blue Baseboard			Third Floor Hall	No ACBM	MISC					
220	Blue Vinyl Base Cove Mastic	2,250	LF	Throughout 1st A-Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
221	2' X 2' Grey & Dark Grey Tile Carpet Adhesive	3,500	SF	B-Building B140	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
222	Tan Carpet Adhesive	7,000	SF	B-Building Adhesive Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
223	12" x 12" White Floor Tile	2,400	SF	Rooms 210, 212-215	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
224	Mastic Associated w/ 12" x 12" White Floor Tile	2,400	SF	Rooms 210, 212-215 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Blue Baseboard Mastic			Third Floor Corridor	No ACBM	MISC					

Chicago Public Schools

School Collins High School

Unit 46411

Building ID 1880

Address 1313 S. Sacramento

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
24	White Wall Tile Grout			Kitchens and Washrooms	No ACBM	SURFACE					
25	Gray Carpet Mastic			Throughout Complex	No ACBM	MISC					
26	Linoleum			2nd Floor Hall	No ACBM	MISC					
27	Cinder Block			Throughout Complex	No ACBM	MISC					
27 M	Cinder Block Mortar			Throughout Complex	No ACBM	MISC					
28	Blue Carpet Mastic			Room 120	No ACBM	MISC					
29	Brown Ceramic Tile Grout			Washrooms and Locker Rooms	No ACBM	SURFACE					
3	12" x 12" Beige Floor Tile			Consumer Science and Music Complexes	Assumed	MISC					Follow O&M Plan
30	Insulation Inside Fire Doors			Throughout Complex	No ACBM	TSI					
31	Striped Carpet Mastic			Auditorium	No ACBM	MISC					
32	Brown and Green Carpet Mastic			Auditorium	No ACBM	MISC					
33	Exterior Brick - Not AHERA			Throughout Complex	No ACBM	MISC					
34	Exterior Brick Mortar - Not AHERA			Throughout Complex	No ACBM	MISC					
35	Exterior Door Caulk - Not AHERA			Throughout Complex	No ACBM	MISC					
36	Exterior Window Caulk - Not AHERA			Throughout Complex	No ACBM	MISC					
37	Tank Insulation			Pool Basement	No ACBM	TSI					
38	Tank Wrap			Pool Basement	No ACBM	MISC					
39	Fiberglass Pipe Insulation			Throughout Complex	No ACBM	TSI					
4	12" x 12" Gray Floor Tile	1,500	SF	3rd Floor Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Hard Joint Compound on Fiberglass Pipe Insulation			Throughout Complex	No ACBM	TSI					
41	Cover on Hard Joint Compound on Fiberglass Lag			Throughout Complex	No ACBM	TSI					
42	Duct Insulation			Hall by Kitchen	No ACBM	TSI					
43	Tank Insulation			Pump Room	No ACBM	TSI					
44	Roofing Material - Not AHERA			Roof (not observed)	Assumed	MISC					
45	Roof Flashing - Not AHERA			Roof	Assumed	MISC					
46	Purple Carpet Mastic	1,000	SF	Rooms 208, 232 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Brown Carpet Mastic			Library and Office	Assumed	MISC					Follow O&M Plan
48	Lab Tops	1,000	SF	Rooms 300, 305, and 310, 307, 313, and Commercial Arts (observed only in 200, 205, 310, 313)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Blue Ceramic Tile Grout			Locker Rooms	Assumed	MISC					Follow O&M Plan

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, Il, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
5	12" x 12" Ceiling Tile and Mastic			Classrooms and Hallways (not observed)	Assumed	MISC					Follow O&M Plan
50	Terrazzo Basins			2nd & 3rd Floor Slop Rooms and Boys Locker Room	No ACBM	MISC					
51	Lab Hood Transite	100	SF	Rooms 305 & 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Beige w/White Speckle Floor Tile	2,200	SF	1st Floor Attendance Office and Room 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Beige w/White Speckle Floor Tile Mastic	2,200	SF	1st Floor Attendance Office and Room 312	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Tan with Brown Streaks Floor Tile	2,200	SF	2nd Floor Lunch Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Tan with Brown Streak Floor Tile Mastic	2,200	SF	2nd Floor Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	White & Red Ceramic Floor Tile and Grout	2,100	SF	2nd & 3rd Floor Boys and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	White & Red Ceramic Floor Tile Mastic	2,100	SF	2nd & 3rd Floor Boys and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	Grey Ceramic Floor Tile	3,500	SF	1st Floor Boys and Girls Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Grey Ceramic Floor Tile Mastic	3,500	SF	1st Floor Boys and Girls Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	2' x 4' Ceiling Panels	200,000	SF	Throughout Complex	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
60	12"x12" White w/Multi Colored Specks Floor Tile	12,000	SF	First and Second Floor Hallways and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" White w/Multi Colored Specks Floor Tile Mastic	12,000	SF	First and Second Floor Hallways and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12"x12" Dark Blue w/Light Blue Floor Tile	1,500	SF	First Floor Hallways and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12"x12" Dark Blue w/Light Blue Floor Tile Mastic	1,500	SF	First Floor Hallways and Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12"x12" Yellow w/Light Yellow Floor Tile	3,000	SF	Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12"x12" Yellow w/Light Yellow Floor Tile Mastic	3,000	SF	Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" Beige w/Tan Floor Tile	6,000	SF	Third Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x12" Beige w/Tan Floor Tile Mastic			Third Floor Hallway	No ACBM	MISC					Follow O&M Plan
68	12"x12" Red Floor Tile	500	SF	Third Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
69	12"x12" Red Floor Tile Mastic	500	SF	Third Floor Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
7	4' x 4' Ceiling Panels	2,800	SF	Throughout Complex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Grey w/Blue Specks Floor Tile	15,000	SF	Third Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" Grey w/Blue Specks Floor Tile Mastic	15,000	SF	Third Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Drywall	25,000	SF	Throughout Academic Building "A"	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Drywall Tape and Joint Compound	60,000	LF	Throughout Academic Building "A"	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
8	Hard Plaster	100,000	SF	Throughout Complex	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
9	12" x 12" White w/Reddish Brown Streaks FT Mastic	3,000	SF	Fine Arts Rooms and Basement	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-100	12"x12" red pattern design VFT	72	SF	Detention room storage (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-101	Adhesive for 12"x12" red pattern design VFT	72	SF	Detention room storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-102	Interior lining of the Kiln	15	SF	(not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	12/16/2019
Manager Planner Name	Randy Livingston
100-01934	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
051	
1	
10	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
12	
13	
139	
14	
15	
16	
17	
18	
19	
2	
20	
206	
207	
208	
209	
21	
210	
211	
212	
213	
214	
215	
216	
217	
218	
219	

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
 Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
22	
220	
221	
222	
223	
224	
23	
24	
25	
26	
27	
27 M	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	

Chicago Public Schools

School Collins High School
Address 1313 S. Sacramento

Unit 46411
Chicago, IL, 60623

Building ID 1880
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500 Chicago, IL, 60607

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
8	
9	
HA-100	
HA-101	
HA-102	

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Vibration Absorber**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Vibration Absorber**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fine Arts Building Rooms and Basement**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Brown Streaks Floor Tile**
MATERIAL LOCATION: **Fine Arts Building Rooms and Basement**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Coach Love's Office, Weight Room, and Drivers Ed (Now ROTC Classroom), Rooms 176 & 177**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **Coach Love's Office, Weight Room, and Drivers Ed (Now ROTC Classroom), Rooms 176 & 177**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: First Floor - Auditorium, 134, 136, 140, 140A**
MATERIAL QUANTITY: **8175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **103**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Building B: First Floor - Auditorium, 134, 136, 140, 140A**
MATERIAL QUANTITY: **8175** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 122, 130, 130A-C, 132, 132A-B, 133, 135, 136B, 137, 140, 1410A-F, 144, 144A-B, 146, 146A, 148 and Office 1**

MATERIAL QUANTITY: **15350**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**
MATERIAL LOCATION: **Building B: 1st Floor - 122, 130, 130A-C, 132, 132A-B, 133, 135, 136B, 137, 140, 1410A-F, 144, 144A-B, 146, 146A, 148 and Office 1**
MATERIAL QUANTITY: **15350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" Off-White with Grey Specs Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1**

MATERIAL QUANTITY: **7850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12"x12" Off-White with Grey Specs Floor Tile**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1**
MATERIAL QUANTITY: **7850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" Off-White with Grey Specs Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1**

MATERIAL QUANTITY: **7850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **12"x12" Off-White with Grey Specs Floor Tile Mastic**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134B, 134D, 135, 136B, 137, 140D-F, 144, 144A-B, 146, 146A, 148 and Office 1**
MATERIAL QUANTITY: **7850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 122, 132, 144, 146, and 148**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 122, 132, 144, 146, and 148**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" Dark Brown Florr Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 122, 132, 144, 146, and 148**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12"x12" Dark Brown Florr Tile Mastic**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 122, 132, 144, 146, and 148**
MATERIAL QUANTITY: **2150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **109**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Consumer Science and Music Complexes**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Consumer Science and Music Complexes**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **4" Vinyl Baseboard Mastic**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148 and Office 1**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **4'x4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - 134 and 136**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **111**
MATERIAL DESCRIPTION: **4'x4' Ceiling Tile**
MATERIAL LOCATION: **Building B: 1st Floor - 134 and 136**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" Off-White with Blue Patterns Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - 140B and 140C (not observed)**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **112**
MATERIAL DESCRIPTION: **12"x12" Off-White with Blue Patterns Floor Tile**
MATERIAL LOCATION: **Building B: 1st Floor - 140B and 140C (not observed)**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12"x12" Off-White with Blue Patterns Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - 140B and 140C (not observed)**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **113**
MATERIAL DESCRIPTION: **12"x12" Off-White with Blue Patterns Floor Tile Mastic**
MATERIAL LOCATION: **Building B: 1st Floor - 140B and 140C (not observed)**
MATERIAL QUANTITY: **830** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **White Sink Undercoat**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Floor - Room 144**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **114**
MATERIAL DESCRIPTION: **White Sink Undercoat**
MATERIAL LOCATION: **Building B: 1st Floor - Room 144**
MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **115**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**

MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **116**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Building B: 1st Floor - 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**
MATERIAL QUANTITY: **48000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Fire Caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **117**
MATERIAL DESCRIPTION: **Fire Caulk**
MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Flo-Tech Insulation Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **118**
MATERIAL DESCRIPTION: **Flo-Tech Insulation Wrap**
MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 12/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Duct Sealant**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **119**
MATERIAL DESCRIPTION: **Duct Sealant**
MATERIAL LOCATION: **Building B: 1st Floor - Auditorium, 130, 130A-C, 132, 132A-B, 133, 134, 134B, 134D, 135, 136, 136B, 137, 140, 140A-F, 144, 144A-B, 146, 146A, 148, and Office 1**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: 12/16/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Lunch Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Lunch Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Interior Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **10th Floor Corridor, 1039, 1236, 1339, 1700, 1720, 500, & 522 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same**

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **139**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
MATERIAL LOCATION: **10th Floor Corridor, 1039, 1236, 1339, 1700, 1720, 500, & 522 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Interior Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Interior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Green Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **3rd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Clay Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Kitchen, 3rd Floor Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Clay Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Kitchen, 3rd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Clay Tile Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Kitchen, 3rd Floor Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Clay Tile Mortar**

MATERIAL LOCATION: **2nd and 3rd Floor Kitchen, 3rd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Coach Love's Office, Weight Room and Driver's Ed (Now ROTC Classroom)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile - ABATED**

MATERIAL LOCATION: **Coach Love's Office, Weight Room and Driver's Ed (Now ROTC Classroom)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Black Baseboard**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **206**
MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic - Installed in 1998**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building (mastic not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **206**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic - Installed in 1998**

MATERIAL LOCATION: **Throughout Building (mastic not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **207**
MATERIAL DESCRIPTION: **Beige W/White Streak Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **207**
MATERIAL DESCRIPTION: **Beige W/White Streak Linoleum**
MATERIAL LOCATION: **Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **208**
MATERIAL DESCRIPTION: **Beige W/White Streak Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **208**
MATERIAL DESCRIPTION: **Beige W/White Streak Linoleum Mastic**
MATERIAL LOCATION: **Rooms 304, 305, 307, 308, 309, 310, 312, 311, 313, 348, 348A**
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **209**
MATERIAL DESCRIPTION: **Yellow Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200, 200 b, 203, 205, 205A**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **209**
MATERIAL DESCRIPTION: **Yellow Linoleum**
MATERIAL LOCATION: **Room 200, 200 b, 203, 205, 205A**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Black Baseboard Mastic**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **210**
MATERIAL DESCRIPTION: **Yellow Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 200, 200 b, 203, 205, 205A**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **210**
MATERIAL DESCRIPTION: **Yellow Linoleum Mastic**
MATERIAL LOCATION: **Room 200, 200 b, 203, 205, 205A**
MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **211**
MATERIAL DESCRIPTION: **Brown Carpet W/Grey Pattern Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 329 (not observed)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **211**
MATERIAL DESCRIPTION: **Brown Carpet W/Grey Pattern Adhesive**
MATERIAL LOCATION: **Room 329 (not observed)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **212**
MATERIAL DESCRIPTION: **Red Vinyl Base Cove**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 3rd Floor Classrooms**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **212**
MATERIAL DESCRIPTION: **Red Vinyl Base Cove**
MATERIAL LOCATION: **Throughout 3rd Floor Classrooms**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **213**
MATERIAL DESCRIPTION: **Red Vinyl Base Cove Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 3rd Floor Classrooms**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **213**
MATERIAL DESCRIPTION: **Red Vinyl Base Cove Mastic**
MATERIAL LOCATION: **Throughout 3rd Floor Classrooms**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **214**
MATERIAL DESCRIPTION: **Yellow Vinyl Base Cove**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd & 3rd Floor Hallway**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **214**
MATERIAL DESCRIPTION: **Yellow Vinyl Base Cove**
MATERIAL LOCATION: **Throughout 2nd & 3rd Floor Hallway**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **215**
MATERIAL DESCRIPTION: **Yellow Vinyl Base Cove Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd and 3rd Floor Hallways**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **215**
MATERIAL DESCRIPTION: **Yellow Vinyl Base Cove Mastic**
MATERIAL LOCATION: **Throughout 2nd and 3rd Floor Hallways**
MATERIAL QUANTITY: **2750** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **216**
MATERIAL DESCRIPTION: **Blue W/Gold Lines Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library, and Library Offices 100 to 105**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **216**
MATERIAL DESCRIPTION: **Blue W/Gold Lines Carpet Adhesive**
MATERIAL LOCATION: **Library, and Library Offices 100 to 105**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **217**
MATERIAL DESCRIPTION: **Gray W/Blue & Yellow Specs. Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 140-142, 145, 120, 121, 126, 128-130**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **217**
MATERIAL DESCRIPTION: **Gray W/Blue & Yellow Specs. Carpet Adhesive**
MATERIAL LOCATION: **Room 140-142, 145, 120, 121, 126, 128-130**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **218**
MATERIAL DESCRIPTION: **Brown w/ Yellow & Green Specs Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **132, 134-136**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **218**
MATERIAL DESCRIPTION: **Brown w/ Yellow & Green Specs Carpet Adhesive**
MATERIAL LOCATION: **132, 134-136**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **219**
MATERIAL DESCRIPTION: **Blue Vinyl Base Cove**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1st Floor A-Building**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **219**
MATERIAL DESCRIPTION: **Blue Vinyl Base Cove**
MATERIAL LOCATION: **Throughout 1st Floor A-Building**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Blue Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Blue Baseboard**

MATERIAL LOCATION: **Third Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **220**
MATERIAL DESCRIPTION: **Blue Vinyl Base Cove Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 1st A-Building**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **220**
MATERIAL DESCRIPTION: **Blue Vinyl Base Cove Mastic**
MATERIAL LOCATION: **Throughout 1st A-Building**
MATERIAL QUANTITY: **2250** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **221**
MATERIAL DESCRIPTION: **2' X 2' Grey & Dark Grey Tile Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B-Building B140**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **221**
MATERIAL DESCRIPTION: **2' X 2' Grey & Dark Grey Tile Carpet Adhesive**
MATERIAL LOCATION: **B-Building B140**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **222**
MATERIAL DESCRIPTION: **Tan Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B-Building Adhesive Auditorium**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **222**
MATERIAL DESCRIPTION: **Tan Carpet Adhesive**
MATERIAL LOCATION: **B-Building Adhesive Auditorium**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **223**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 210, 212-215**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **223**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
MATERIAL LOCATION: **Rooms 210, 212-215**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **224**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 210, 212-215 (not observed)**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **224**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" White Floor Tile**
MATERIAL LOCATION: **Rooms 210, 212-215 (not observed)**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Blue Baseboard Mastic**

MATERIAL LOCATION: **Third Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **White Wall Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchens and Washrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **White Wall Tile Grout**

MATERIAL LOCATION: **Kitchens and Washrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Linoleum**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **2nd Floor Hall**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Cinder Block**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27 M**
MATERIAL DESCRIPTION: **Cinder Block Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **27 M**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **Blue Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Brown Ceramic Tile Grout**

MATERIAL LOCATION: **Washrooms and Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Consumer Science and Music Complexes**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Consumer Science and Music Complexes**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Insulation Inside Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Insulation Inside Fire Doors**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Striped Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Striped Carpet Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Brown and Green Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Brown and Green Carpet Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Exterior Brick - Not AHERA**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Not AHERA**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Not AHERA**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Not AHERA**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Pool Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Tank Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pool Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Tank Wrap**

MATERIAL LOCATION: **Pool Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Lunchroom**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **3rd Floor Lunchroom**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **Cover on Hard Joint Compound on Fiberglass Lag**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Cover on Hard Joint Compound on Fiberglass Lag**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hall by Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Hall by Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Pump Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **Roofing Material - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Roofing Material - Not AHERA**

MATERIAL LOCATION: **Roof (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Roof Flashing - Not AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Purple Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 208, 232 (not observed)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **not observed**

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Rooms 208, 232 (not observed)**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2016**

Inspector's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Library and Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Lab Tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 300, 305, and 310, 307, 313, and Commercial Arts (observed only in 200, 205, 310, 313)**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **Not observed**

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Lab Tops**
MATERIAL LOCATION: **Rooms 300, 305, and 310, 307, 313, and Commercial Arts (observed only in 200, 205, 310, 313)**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Blue Ceramic Tile Grout**

MATERIAL LOCATION: **Locker Rooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms and Hallways (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2016 - same**

Inspector's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **12" x 12" Ceiling Tile and Mastic**

MATERIAL LOCATION: **Classrooms and Hallways (not observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Terrazzo Basins**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd & 3rd Floor Slop Rooms and Boys Locker Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Terrazzo Basins**

MATERIAL LOCATION: **2nd & 3rd Floor Slop Rooms and Boys Locker Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Lab Hood Transite**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 305 & 310**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Lab Hood Transite**

MATERIAL LOCATION: **Rooms 305 & 310**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Speckle Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Attendance Office and Room 312**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Speckle Floor Tile**
MATERIAL LOCATION: **1st Floor Attendance Office and Room 312**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Speckle Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Attendance Office and Room 312**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Beige w/White Speckle Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Attendance Office and Room 312**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Tan with Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Lunch Room**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Tan with Brown Streaks Floor Tile**
MATERIAL LOCATION: **2nd Floor Lunch Room**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Tan with Brown Streak Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Lunchroom**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Tan with Brown Streak Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Lunchroom**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **White & Red Ceramic Floor Tile and Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **White & Red Ceramic Floor Tile and Grout**
MATERIAL LOCATION: **2nd & 3rd Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **White & Red Ceramic Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **White & Red Ceramic Floor Tile Mastic**
MATERIAL LOCATION: **2nd & 3rd Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Grey Ceramic Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Boys and Girls Bathrooms**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Grey Ceramic Floor Tile**
MATERIAL LOCATION: **1st Floor Boys and Girls Bathrooms**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Grey Ceramic Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Grey Ceramic Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Boys and Girls Bathroom**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Complex**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
MATERIAL LOCATION: **Throughout Complex**
MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates 2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" White w/Multi Colored Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First and Second Floor Hallways and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12"x12" White w/Multi Colored Specks Floor Tile**
MATERIAL LOCATION: **First and Second Floor Hallways and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" White w/Multi Colored Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First and Second Floor Hallways and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12"x12" White w/Multi Colored Specks Floor Tile Mastic**
MATERIAL LOCATION: **First and Second Floor Hallways and Classrooms**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12"x12" Dark Blue w/Light Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Hallways and Classrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12"x12" Dark Blue w/Light Blue Floor Tile**
MATERIAL LOCATION: **First Floor Hallways and Classrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12"x12" Dark Blue w/Light Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **First Floor Hallways and Classrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12"x12" Dark Blue w/Light Blue Floor Tile Mastic**
MATERIAL LOCATION: **First Floor Hallways and Classrooms**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12"x12" Yellow w/Light Yellow Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **12"x12" Yellow w/Light Yellow Floor Tile**
MATERIAL LOCATION: **Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12"x12" Yellow w/Light Yellow Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUILDING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12"x12" Yellow w/Light Yellow Floor Tile Mastic**
MATERIAL LOCATION: **Second Floor Hallways and Classrooms, Third Floor Classrooms, First Floor Rms - 112, 113, 114, 115**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Floor Tile**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Third Floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Beige w/Tan Floor Tile Mastic**

MATERIAL LOCATION: **Third Floor Hallway**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic**
MATERIAL LOCATION: **Third Floor Hallway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **4' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Complex**
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **4' x 4' Ceiling Panels**

MATERIAL LOCATION: **Throughout Complex**

MATERIAL QUANTITY: **2800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Grey w/Blue Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Classrooms**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **12"x12" Grey w/Blue Specks Floor Tile**
MATERIAL LOCATION: **Third Floor Classrooms**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **12"x12" Grey w/Blue Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third Floor Classrooms**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12"x12" Grey w/Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Third Floor Classrooms**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Academic Building "A"**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Academic Building "A"**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Drywall Tape and Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Academic Building "A"**
MATERIAL QUANTITY: **60000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Drywall Tape and Joint Compound**

MATERIAL LOCATION: **Throughout Academic Building "A"**

MATERIAL QUANTITY: **60000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Hard Plaster**
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Complex**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **Hard Plaster**
MATERIAL LOCATION: **Throughout Complex**
MATERIAL QUANTITY: **100000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Brown Streaks FT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Fine Arts Rooms and Basement**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" White w/Reddish Brown Streaks FT Mastic**

MATERIAL LOCATION: **Fine Arts Rooms and Basement**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **12"x12" red pattern design VFT**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Detention room storage (not observed)**
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **12"x12" red pattern design VFT**
MATERIAL LOCATION: **Detention room storage (not observed)**
MATERIAL QUANTITY: **72** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **Adhesive for 12"x12" red pattern design VFT**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Detention room storage**

MATERIAL QUANTITY: **72**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **Adhesive for 12"x12" red pattern design VFT**

MATERIAL LOCATION: **Detention room storage**

MATERIAL QUANTITY: **72**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Marcos Iwankiw**
SCHOOL NAME: **Collins High School** INSPECTION DATE: **11/25/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-102**
MATERIAL DESCRIPTION: **Interior lining of the Kiln**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **(not observed)**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**
COMMENTS: **Not observed**

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **46411** BUIDLING ID: **1880**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Randy Livingston**
SCHOOL NAME: **Collins High School** REVIEW DATE: **12/16/2019**
ADDRESS: **1313 S. Sacramento** IDPH LICENSE NO: **100-03175**

HOMOGENEOUS AREA: **HA-102**

MATERIAL DESCRIPTION: **Interior lining of the Kiln**

MATERIAL LOCATION: **(not observed)**

MATERIAL QUANTITY: **15**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **12/16/2019**

Chicago Public Schools

Carnow, Conibear and Associates

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Randolph Livingston


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/24/2019

Exam Date: 10/24/2019

Expiration Date: 10/24/2020

Certificate Number: MPR1910242073



Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 01934

ISSUED
11/5/2019

EXPIRES
05/15/2020

RANDOLPH LIVINGSTON
9549 S. EUCLID AVE
CHICAGO, IL 60617

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR	2/6/2020
MANAGEMENT PLANNER	10/24/2020
PROJECT MANAGER	3/4/2019
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed