

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2305  
SCHOOL NAME: Lafayette School  
ADDRESS OF SCHOOL: 2714 W. Augusta Blvd.  
CITY: Chicago, IL, 60622

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/23/2016

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 599  
IDPH INSPECTOR LICENSE NUMBER: 100-11089  
IDPH LICENSED INSPECTOR NAME(Please Print): Panfilo Carrazco  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Lafayette School**

2714 W. Augusta Blvd.  
Chicago, IL, 60622

Unit: 63051  
Building ID: 4400

IDPH ID Number: 14-016-2990-2305

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

June 11, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299                  Unit: 24121                  Region: 02                  IDPH ID:14-016-2990-2305

School: Lafayette School                  Building ID: 4400

Address: 2714 W. Augusta Blvd.

Chicago, IL, 60622

Building Contact: Watson, Lamont

Contact Phone:3123715715

Current Building Owners: Chicago Public Schools

Review Date: 11/08/2019

Inspector: Panfilo Carrazco

Inspector IDPH License: 100-11089

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 11, 2019

RE: Lafayette School, Unit 63051  
2714 W. Augusta Blvd.  
Chicago, IL, 60622

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Lafayette School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Lafayette School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Lafayette School Unit: 24121 Region: 02  
Address: 2714 W. Augusta Blvd. Chicago, IL, 60622  
IDPH ID: 14-016-2990-2305 Building ID: 4400  
Contact: Watson, Lamont Phone: 3123715715

### 2. Description of Facility

Original Construction: 1921 Additional Construction: 1892,1898  
Total Square Footage: 61000 No of Floors: 4  
Current Occupancy: 599

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Panfilo Carrazco

Inspector IDPH license # 100-11089

Signature:  
Date: 6/11/2019

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature:  
Date: 11/08/2019

### 7. Review Date:11/08/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Lafayette School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4400:

B. The following new homogenous areas have been identified for Building 4400:

|     |                         |
|-----|-------------------------|
| 01  | Aircell pipe insulation |
| 02  | Hard Coat Plaster       |
| 102 | frame hood panel        |
| 103 | Science Lab Tables      |
| 104 | Spray On Insulation     |
| 105 | Spray on Insulation     |
| 106 | Carpet Mastic           |
| 107 | Drywall System          |



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

|     |   |
|-----|---|
| 100 | 24"x24" Green VFT                       |
| 101 | 24"x24" Green VFT Mastic                |
| 102 | frame hood panel                        |
| 103 | Science Lab Tables                      |
| 104 | Spray On Insulation                     |
| 105 | Spray on Insulation                     |
| 106 | Carpet Mastic                           |
| 107 | Drywall System                          |
| 18  | Paperwrap Pipe Insulation               |
| 21  | Plaster                                 |
| 28  | Black Linoleum NOT OBSERVED             |
| 41  | MJP E/F/V on Fiberglass Pipe Insulation |
| 78  | 12x12 Light Blue w/ Speckles VFT        |
| 79  | 12x12 Light Blue w/ Speckles VFT Mastic |
| 83  | 2'x4' White Ceiling Tile                |
| 84  | Dry Wall Soffit                         |
| 85  | 24"x24" Beige VFT                       |
| 86  | 24"x24" Beige VFT Mastic                |
| 87  | 24"x24" light blue VFT                  |
| 88  | 24"x24" light blue VFT Mastic           |
| 89  | 24"x24" gray VFT                        |
| 90  | 24"x24" gray VFT Mastic                 |
| 91  | 24"x24" dark brown VFT                  |
| 92  | 24"x24" dark brown VFT Mastic           |
| 93  | 24"x24" Black VFT                       |
| 94  | 24"x24" Black VFT Mastic                |
| 95  | Carpet Mastic                           |
| 96  | Decorative Plaster                      |
| 97  | 2'x2' White Ceiling Tile                |
| 98  | 24"x24" Orange VFT                      |
| 99  | 24"x24" Orange VFT Mastic               |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Panfilo Carrazco, IDPH License # 100-11089. The

Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Lafayette School Building 4400 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category   | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
| 01    | Aircell pipe insulation                | 800               | LF             | Boiler room corridor by the warm air chamber across from play room 7 | CHR           | TSI               | Y       | LOC         | 5               |              | No                            | Damaged or significantly damaged friable thermal system insulating ACBM | 1             | MODERATE              |
| 02    | Hard Coat Plaster                      |                   |                | Throughout 1892 Building   | NO_ACBM       | SURFACE           |         |             |                 |              |                               |   |               |                       |
| 03    | 1'x1' Ceiling Tile (ABATED)            | 0                 |                | Rooms 207, 208, 210, 211, and 305-1892                               | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 06    | 2'x2' Ceiling Tile (ABATED)            | 0                 |                | 1st & 2nd Floor Corridors, 1st Floor Teachers Toilet - 1892          | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 100   | 24"x24" Green VFT                      | 1,500             | SF             | Rms 112, 115, and 117  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | MODERATE              |
| 101   | 24"x24" Green VFT Mastic               | 1,500             | SF             | Rms 112, 115, and 117  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | MODERATE              |
| 102   | frame hood panel                       | 12                | SF             | Room 208   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | LOW                   |
| 103   | Science Lab Tables                     | 180               | SF             | Rooms 206, 208, 207, 210 and 317                                     | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | LOW                   |
| 104   | Spray On Insulation                    | 3,000             | SF             | Attic In addition 1892   | ASSUMED       | SURFACE           | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | LOW                   |
| 105   | Spray on Insulation                    | 4,000             | SF             | Attic in Addition 1921   | ASSUMED       | SURFACE           | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 106   | Carpet Mastic                          | 900               | SF             | Auditorium and balcony isles   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | LOW                   |
| 107   | Drywall System                         | 250               | SF             | 3rd, 2nd, 1st, basement corridor for elevator door room 311          | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                                      |               | LOW                   |
| 12    | Paperwrap Pipe Insulation              | 900               | LF             | Basement Corridor, Engine Room - 1892                                | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 13    | MJP E/F/V on Aircell Pipe Insulation   | 80                | LF             | Boiler & Engine Rooms, Bsmt Cor, 007, 006 -1892                      | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 14    | MJP E/F/V on Paperwrap Pipe Insulation | 30                | LF             | Room 107, 108, 007, Basement Corridor, Engine Room - 1892            | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 15    | Air Cell Duct Insulation               | 250               | LF             | Room 002 (Playroom), 1st and 2nd floor Janitor's Closet, 2nd Girl's  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description  | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category   | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|---|---------------|-----------------------|
|       |   |                   |                | and Boys Toilet, and 1st floor Girl's Toilet - 1921   |               |                   |         |             |                 |              |                               |   |               |                       |
| 16    | Hard Coat Plaster   |                   |                | Throughout 1921   | NO_ACBM       | SURFACE           | Y       | None        |                 |              | No                            |   |               |                       |
| 18    | Paperwrap Pipe Insulation                                   | 400               | LF             | Engine Room, 021, Basement Corridor, 1st & 3rd Floor Janitors Closet - 1921                   | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 19    | Mag Block Pipe Insulation                                   | 300               | LF             | Boiler Room - 1892  | CHR           | TSI               | Y       | LOC         | 4               |              | Yes                           | Damaged or significantly damaged friable thermal system insulating ACBM | 5             | LOW                   |
| 20    | ACM Rope  | 10                | LF             | Boiler Room - 1892  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | LOW                   |
| 21    | Plaster   | 150,000           | SF             | Throughout 1921 Building  | ASSUMED       | SURFACE           | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 22    | Boiler Gaskets  | 10                | SF             | Boiler #1 in Boiler Room - 1892   | CHR           | MISC              | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 23    | Boiler Gasket (ABATED)                                      | 0                 |                | Boiler #2 in Boiler Room - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 24    | MJP E/F/V on Paperwrap Pipe Insulation                      | 50                | LF             | Engine Room, 021, Basement Corridor - 1921  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 25    | MJP E/F/V on Magblock Pipe Insulation                       | 60                | LF             | Boiler Room - 1892  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                                      |               | MODERATE              |
| 26    | 9x9 Green Off-White w/ Black Streaks Floor Tile (ABATED)    | 0                 |                | Rooms 307 & 309 - 1892  | ABATED        | MISC              |         | None        |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 27    | 12"x12" Brown w/ Speckles Floor Tile (ABATED)               | 0                 |                | 1st & 3rd Floor Corridors, 206, 105, 106, 109, 107 (Main Office), 108 and Staff Lounge - 1892 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 28    | Black Linoleum NOT OBSERVED                                 |                   |                | Auditorium - 1921   | ASSUMED       | MISC              | N       |             |                 |              | No                            |   |               |                       |
| 29    | 9"x9" Off White w/ Black Streaks Floor Tile Mastic (ABATED) | 0                 |                | Rooms 307 & 309 - 1892  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |
| 30    | 12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)        | 0                 |                | 1st & 3rd Floor Corridors, 206, 105, 106, 196, 109, 107 (Main Office), 108 and Staff Lounge - | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM                      |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                      | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |   |                   |                | 1892   |               |                   |         |             |                 |              |                               |  |               |                       |
| 31    | Brown Linoleum (ABATED)                                   | 0                 |                | Auditorium Balcony - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 32    | 9"x9" Brown Floor Tile (ABATED)                           | 0                 |                | 3rd Floor Teacher's Toilet - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 33    | 12"x12" Green w/ White Streaks Floor Tile (ABATED)        | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 34    | 9"x9" Brown Floor Tile Mastic (ABATED)                    | 0                 |                | 3rd Floor Teacher's Toilet - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 35    | 12"x12" Green w/ White Streaks Floor Tile Mastic (ABATED) | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 36    | Aircell Pipe Insulation                                   | 21                | LF             | Basement Corridor, Fan Rooms, All Janitors Closets - 1921  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 37    | MJP E/F/V on Aircell Pipe Insulation                      | 10                | LF             | Basement Corridor, Fan Rooms, All Janitors Closets - 1921  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 38    | Mag Block Pipe Insulation                                 | 14                | LF             | Room 002 - 1921  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 39    | MJP E/F/V on Mag Block Pipe Insulation                    | 7                 | LF             | Room 002 - 1921  | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 40    | MJP E/F/V on Fiberglass Pipe Insulation                   | 7                 | LF             | Coal room, Boiler room, Basement Corridor, Fan Rooms 1 and 3 - 1892                                | CHR           | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 41    | MJP E/F/V on Fiberglass Pipe Insulation                   | 50                | SF             | Boys and Girls Playrooms, Assembly Hall - 1921   | ASSUMED       | TSI               | Y       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 42    | 12"x12" Coffee Brown Floor Tile (ABATED)                  | 0                 |                | Room 306, 2nd & 3rd Floor Corridors -  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable              |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |  |                   |                | 1892   |               |                   |         |             |                 |              |                               | suspect ACBM                                       |               |                       |
| 42A   | 12"x12" Coffee Brown Floor Tile Mastic (ABATED)                | 0                 |                | Room 306, 2nd & 3rd Floor Corridors - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 43    | 12"x12" Green w/ White Streaks Floor Tile (ABATED)             | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 43A   | 12"x12" Green w/ White Streaks Floor Tile (ABATED)             | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 44    | 12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)        | 0                 |                | Rooms 005, 213, 312, 311, 305 (under carpet), 313-315, 317, 319 & 3rd Floor Corridor - 1892                | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 44A   | 12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED) | 0                 |                | Rooms 005, 213, 312, 311, 305, (under carpet) 313-315, & 3rd Floor Corridor - 1892                         | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 45    | 12"x12" White w/ Specks Floor Tile (ABATED)                    | 0                 |                | Rooms 308, 208, 211, 215, 110, 113, 115, 117, & 119 - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 46    | 9"x9" Dark Brown w/ White Streaks Floor Tile (ABATED)          | 0                 |                | Room 001,002, 003 - 1921   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 46A   | 9"x9" Dark Brown w/ Streaks Floor Tile Mastic (ABATED)         | 0                 |                | Room 001,002,003 - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 47    | 9"x9" Gray w/ White Streaks Floor Tile (under carpet) (ABATED) | 0                 |                | Engineer's Office (Under Carpet) - 1892  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 47A   | 9"x9" Gray w/ White Streaks Floor Tile Mastic (ABATED)         | 0                 |                | Engineer's Office (Under Carpet) - 1892  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 48    | 9"x9" Black VFT (ABATED)                                       | 0                 |                | 1st Floor Teacher's Toilet, & Engineer's   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable              |               |                       |



# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |  |                   |                | Office (Under Carpet) - 1892  |               |                   |         |             |                 |              |                               | suspect ACBM                                       |               |                       |
| 48A   | 9"x9" Black Floor Tile Mastic (ABATED)                           | 0                 |                | 1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 49    | 9"x9" Light Beige w/ Light Brown Streaks Floor Tile (ABATED)     | 0                 |                | Room 209 - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 49A   | 9"x9" Light Beige w/ Lt Brown Streaks Floor Tile Mastic (ABATED) | 0                 |                | Room 209 - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 50    | 12"x12" Dark Brown w/ White Speck Floor Tile (ABATED)            | 0                 |                | Room 106, & 111 - 1892  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 50A   | 12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)    | 0                 |                | Room 106, & 111 - 1892  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 51    | 12"x12" Peach Floor Tile (ABATED)                                | 0                 |                | Main Office Toilet - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 51A   | 12"x12" Peach Floor Tile Mastic (ABATED)                         | 0                 |                | Main Office Toilet - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 52    | 12"x12" Light Green Floor Tile (ABATED)                          | 0                 |                | Room 112 - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 52A   | 12"x12" Light Green Floor Tile Mastic (ABATED)                   | 0                 |                | Room 112 - 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 53    | 12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)          | 0                 |                | Rooms 002, 302, 326 - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 53A   | 12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)   | 0                 |                | Rooms 002, 302, 326 - 1921  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 54    | 9"x9" Black Floor Tile (ABATED)                                  | 0                 |                | 3rd Floor Teacher's Toilet - 1921                                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 54A   | 9"x9" Black Floor Tile Mastic (ABATED)                           | 0                 |                | 3rd Floor Teacher's Toilet - 1921                                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 55    | 12"x18" Black Floor Tile (ABATED)                                | 0                 |                | 3rd Floor Teacher's Toilet - 1921                                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable              |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                                    | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       |   |                   |                |  |               |                   |         |             |                 |              |                               | suspect ACBM                                       |               |                       |
| 55A   | 12"x18" Black Floor Tile Mastic (ABATED)                | 0                 |                | 3rd Floor Teacher's Toilet - 1921        | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 56    | 9"x9" Light Brown w/ Dark Floor Tile (ABATED)           | 0                 |                | Library (221/223) - 1921                 | ABATED        | MISC              |         | None        |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 56A   | 9"x9" Light Brown w/ Dark Floor Tile Mastic (ABATED)    | 0                 |                | Library (221/223) - 1921                 | ABATED        | MISC              |         | None        |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 57    | 12"x12" White Specks Floor Tile (ABATED)                | 0                 |                | Room 321, 218 - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 57A   | 12"x12" White Specks Floor Tile Mastic (ABATED)         | 0                 |                | Room 321, 218 - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 58    | 12"x12" Brown w/ Speckles Floor Tile (ABATED)           | 0                 |                | 2nd Floor Corridor -1921                 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 58A   | 12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)    | 0                 |                | 2nd Floor Corridor -1921                 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 59    | 12"x12" Brown Floor Tile (ABATED)                       | 0                 |                | Room 021, 023, 025, Nurses Office - 1921 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 59A   | 12"x12" Brown Floor Tile Mastic (ABATED)                | 0                 |                | Room 021, 023, 025, Nurses Office - 1921 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 60    | 9"x9" Beige w/ Brown Streaks Floor Tile (ABATED)        | 0                 |                | Assembly Hall - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 60A   | 9"x9" Beige w/ Brown Streaks Floor Tile Mastic (ABATED) | 0                 |                | Assembly Hall - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 61    | 9"x9" Brown w/ Beige Streaks Floor Tile (ABATED)        | 0                 |                | Assembly Hall - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 61A   | 9"x9" Brown w/ Beige Streaks Floor Tile Mastic (ABATED) | 0                 |                | Assembly Hall - 1921                     | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 62    | 12"x12" Off White w/ Brown Specks Floor Tile (ABATED)   | 0                 |                | Room 001, Teachers Toilet - 1921         | ABATED        | MISC              |         | None        |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 62A   | 12"x12" Off White w/ Brown Specks Floor                 | 0                 |                | Room 001 and                             | ABATED        | MISC              |         | None        |                 |              |                               | Any remaining friable                              |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description   | Material Quantity | Material Units | Material Location            | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
|       | Tile Mastic (ABATED)   |                   |                | teacher's lounge-1921        |               |                   |         |             |                 |              |                               | ACBM or friable suspect ACBM                       |               |                       |
| 63    | 12"x12" Dark Brown w/ White Specks Floor Tile (ABATED)                     | 0                 |                | Assembly Hall - 1921         | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 63A   | 12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)              | 0                 |                | Assembly Hall - 1921         | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 64    | 12"x12" Red/Orange w/ Yellow Specks Floor Tile (ABATED)                    | 0                 |                | Kitchen & Room 15            | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 64A   | 12"x12" Red/Orange w/ Yellow Specks Floor Tile Mastic (ABATED)             | 0                 |                | Kitchen & Room 15            | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 65    | Brown Carpet Adhesive (ABATED)   | 0                 |                | Basement Eng. Office         | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 66    | 12 x 12 Light Blue Mix Floor Tile (ABATED)                                 | 0                 |                | Rooms 213, 219, 313, and 315 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 67    | 12 x 12 Light Blue Mix Floor Tile Adhesive (ABATED)                        | 0                 |                | Rooms 213, 219, 313, and 315 | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 68    | 12"x12" Bright Blue Mix Floor Tile (ABATED)                                | 0                 |                | Rooms 309 and 317            | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 69    | 12"x12" Bright Blue Mix Floor Tile Adhesive (ABATED)                       | 0                 |                | Rooms 309 and 317            | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 70    | 12"x12" Medium Blue Mix Floor Tile (ABATED)                                | 0                 |                | Room 217-1892                | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 71    | 12"x12" Medium Blue Mix VFT Adhesive (ABATED)                              | 0                 |                | Room 217-1892                | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 72    | 12"x12" Beige Floor Tile (As part of Checkerboard Pattern) (ABATED)        | 0                 |                | Main Office                  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 73    | 12"x12" Beige Floor Tile Mastic (As part of Checkerboard Pattern) (ABATED) | 0                 |                | Main Office                  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 74    | 12x12 Dark Gray Specks VFT (ABATED)  | 0                 |                | 225-1921 Bldg                | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description                             | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                                    | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 75    | 12x12 Dark Gray W/ Specks VFT Mastic (ABATED)    | 0                 |                | 225 - 1921 Bldg  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 76    | 12x12 Light Blue w/ Speckles VFT (ABATED)        | 0                 |                | 019, 213, 215, 219-1892 Bldg   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 77    | 12x12 Light Blue w/ Speckles VFT Mastic (ABATED) | 0                 |                | 019, 213, 215, 219-Bldg 1892   | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 78    | 12x12 Light Blue w/ Speckles VFT                 | 1,500             | SF             | 001(Lunchroom), 002  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | MODERATE              |
| 79    | 12x12 Light Blue w/ Speckles VFT Mastic          | 1,500             | SF             | 001(Lunchroom), 002  | ASSUMED       | MISC              | N       | NONE        | 0               |              | No                            | ACBM with the potential for damage                 |               | LOW                   |
| 80    | Carpet Mastic(Tile Carpet) (ABATED)              | 0                 |                | Library  | ABATED        | MISC              |         |             |                 |              |                               | Any remaining friable ACBM or friable suspect ACBM |               |                       |
| 83    | 2'x4' White Ceiling Tile                         | 3,000             | SF             | Room 001, Room 002, Library (2nd Floor)  | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage                 |               | MODERATE              |
| 84    | Dry Wall Soffit                                  | 200               | SF             | Room 001, Room 002   | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage                 |               | LOW                   |
| 85    | 24"x24" Beige VFT                                | 30,000            | SF             | Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors. | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                 |               | MODERATE              |
| 86    | 24"x24" Beige VFT Mastic                         | 30,000            | SF             | Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320.                                    | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage                 |               | LOW                   |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

| HA No | Material Description          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category                    | Damage Reason | Disturbance Potential |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
|       |                               |                   |                | 1st, 2nd, and 3rd floor corridors.  |               |                   |         |             |                 |              |                               |                                    |               |                       |
| 87    | 24"x24" light blue VFT        | 2,500             | SF             | Rooms 003, 005, 013, 318, 320   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 88    | 24"x24" light blue VFT Mastic | 2,500             | SF             | Rooms 003, 005, 013, 318, 320   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 89    | 24"x24" gray VFT              | 8,000             | SF             | Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors            | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 90    | 24"x24" gray VFT Mastic       | 8,000             | SF             | Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors            | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 91    | 24"x24" dark brown VFT        | 3,000             | SF             | Rms 005 and 013; Lunchroom manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 92    | 24"x24" dark brown VFT Mastic | 3,000             | SF             | Rms 005 and 013; Lunchroom Manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 93    | 24"x24" Black VFT             | 3,000             | SF             | Rm 025 and Auditorium   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 94    | 24"x24" Black VFT Mastic      | 3,000             | SF             | Rm 025 and Auditorium   | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 95    | Carpet Mastic                 | 2,500             | SF             | Rm 011, Auditorium  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 96    | Decorative Plaster            | 300               | SF             | Auditorium  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | LOW                   |
| 97    | 2'x2' White Ceiling Tile      | 12,000            | SF             | Rooms 105A, 106, 107, 108, 109, 110, 205, 206, 207, 208, 210, 218A, 324, and 326                      | ASSUMED       | MISC              | Y       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 98    | 24"x24" Orange VFT            | 2,000             | SF             | Rms 205, 206, 207, 208, 210, and 221  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the potential for damage |               | MODERATE              |
| 99    | 24"x24" Orange VFT Mastic     | 2,000             | SF             | Rms 205, 206, 207,  | ASSUMED       | MISC              | N       | NONE        | 0               |              |                               | ACBM with the                      |               | MODERATE              |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category      | Damage Reason | Disturbance Potential |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|----------------------|---------------|-----------------------|
|       |                      |                   |                | 208, 210, and 221 |               |                   |         |             |                 |              |                               | potential for damage |               |                       |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

|   |
|---|
| Reinspection Date <b>6/11/2019</b>                |
| Inspector Name <b><u>Panfilo Carrazco</u></b>     |
| <b>100-11089</b> <b>5/15/2020</b>                 |
| Inspector's IDPH License Number / Expiration Date |

### Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 01         | Open ends           |
| 02         |                     |
| 03         |                     |
| 06         |                     |
| 100        |                     |
| 101        |                     |
| 102        |                     |
| 103        |                     |
| 104        |                     |
| 105        |                     |
| 106        |                     |
| 107        |                     |
| 12         |                     |
| 13         |                     |
| 14         |                     |
| 15         |                     |
| 16         |                     |
| 18         |                     |
| 19         | by Attic            |
| 20         |                     |
| 21         |                     |
| 22         |                     |
| 23         |                     |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 24         |                     |
| 25         |                     |
| 26         |                     |
| 27         |                     |
| 28         |                     |
| 29         |                     |
| 30         |                     |
| 31         |                     |
| 32         |                     |
| 33         |                     |
| 34         |                     |
| 35         |                     |
| 36         |                     |
| 37         |                     |
| 38         |                     |
| 39         |                     |
| 40         |                     |
| 41         |                     |
| 42         |                     |
| 42A        |                     |
| 43         |                     |
| 43A        |                     |
| 44         |                     |
| 44A        |                     |
| 45         |                     |
| 46         |                     |
| 46A        |                     |
| 47         |                     |
| 47A        |                     |



# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 48         |                     |
| 48A        |                     |
| 49         |                     |
| 49A        |                     |
| 50         |                     |
| 50A        |                     |
| 51         |                     |
| 51A        |                     |
| 52         |                     |
| 52A        |                     |
| 53         |                     |
| 53A        |                     |
| 54         |                     |
| 54A        |                     |
| 55         |                     |
| 55A        |                     |
| 56         |                     |
| 56A        |                     |
| 57         |                     |
| 57A        |                     |
| 58         |                     |
| 58A        |                     |
| 59         |                     |
| 59A        |                     |
| 60         |                     |
| 60A        |                     |
| 61         |                     |
| 61A        |                     |
| 62         |                     |

# Chicago Public Schools

School Lafayette School Unit 24121 Building ID 4400

Address 2714 W. Augusta Blvd. Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 62A        |                     |
| 63         |                     |
| 63A        |                     |
| 64         |                     |
| 64A        |                     |
| 65         |                     |
| 66         |                     |
| 67         |                     |
| 68         |                     |
| 69         |                     |
| 70         |                     |
| 71         |                     |
| 72         |                     |
| 73         |                     |
| 74         |                     |
| 75         |                     |
| 76         |                     |
| 77         |                     |
| 78         |                     |
| 79         |                     |
| 80         |                     |
| 83         |                     |
| 84         |                     |
| 85         |                     |
| 86         |                     |
| 87         |                     |
| 88         |                     |
| 89         |                     |
| 90         |                     |

# Chicago Public Schools

**School** Lafayette School **Unit** 24121 **Building ID** 4400

**Address** 2714 W. Augusta Blvd. **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 91         |                     |
| 92         |                     |
| 93         |                     |
| 94         |                     |
| 95         |                     |
| 96         |                     |
| 97         |                     |
| 98         |                     |
| 99         |                     |

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

School Lafayette School  
Address 2714 W. Augusta Blvd.

Unit 24121  
Chicago, IL, 60622

Building ID 4400  
Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description                   | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category   | Response        |
|-----------|--|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|---|-----------------|
| 01        | Aircell pipe insulation                | 800               | LF             | Boiler room corridor by the warm air chamber across from play room 7  | Chrysotile    | TSI               | Yes     | 5               | LF           | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Repair          |
| 02        | Hard Coat Plaster                      |                   |                | Throughout 1892 Building  | No ACBM       | SURFACE           |         |                 |              |   |                 |
| 03        | 1'x1' Ceiling Tile (ABATED)            | 0                 |                | Rooms 207, 208, 210, 211, and 305-1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM                      | Follow O&M Plan |
| 06        | 2'x2' Ceiling Tile (ABATED)            | 0                 |                | 1st & 2nd Floor Corridors, 1st Floor Teachers Toilet - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM                      | Follow O&M Plan |
| 100       | 24"x24" Green VFT                      | 1,500             | SF             | Rms 112, 115, and 117   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 101       | 24"x24" Green VFT Mastic               | 1,500             | SF             | Rms 112, 115, and 117   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 102       | frame hood panel                       | 12                | SF             | Room 208  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 103       | Science Lab Tables                     | 180               | SF             | Rooms 206, 208, 207, 210 and 317  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 104       | Spray On Insulation                    | 3,000             | SF             | Attic In addition 1892  | Assumed       | SURFACE           | Yes     | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 105       | Spray on Insulation                    | 4,000             | SF             | Attic in Addition 1921  | Assumed       | SURFACE           | Yes     | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 106       | Carpet Mastic                          | 900               | SF             | Auditorium and balcony isles  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 107       | Drywall System                         | 250               | SF             | 3rd, 2nd, 1st, basement corridor for elevator door room 311   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 12        | Paperwrap Pipe Insulation              | 900               | LF             | Basement Corridor, Engine Room - 1892   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 13        | MJP E/F/V on Aircell Pipe Insulation   | 80                | LF             | Boiler & Engine Rooms, Bsmt Cor, 007, 006 -1892   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 14        | MJP E/F/V on Paperwrap Pipe Insulation | 30                | LF             | Room 107, 108, 007, Basement Corridor, Engine Room - 1892   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 15        | Air Cell Duct Insulation               | 250               | LF             | Room 002 (Playroom), 1st and 2nd floor Janitor's Closet, 2nd Girl's and Boys Toilet, and 1st floor Girl's Toilet - 1921 | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 16        | Hard Coat Plaster                      |                   |                | Throughout 1921   | No ACBM       | SURFACE           | Yes     |                 |              |   | Follow O&M Plan |
| 18        | Paperwrap Pipe Insulation              | 400               | LF             | Engine Room, 021, Basement Corridor, 1st & 3rd Floor Janitors Closet - 1921   | Assumed       | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 19        | Mag Block Pipe Insulation              | 300               | LF             | Boiler Room - 1892  | Chrysotile    | TSI               | Yes     | 4               | LF           | 1 Damaged or significantly damaged friable thermal system insulating ACBM | Follow O&M Plan |
| 20        | ACM Rope                               | 10                | LF             | Boiler Room - 1892  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 21        | Plaster                                | 150,000           | SF             | Throughout 1921 Building  | Assumed       | SURFACE           | No      | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |
| 22        | Boiler Gaskets                         | 10                | SF             | Boiler #1 in Boiler Room - 1892   | Chrysotile    | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage                                      | Follow O&M Plan |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description  | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 23        | Boiler Gasket (ABATED)                                      | 0                 |                | Boiler #2 in Boiler Room -1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 24        | MJP E/F/V on Paperwrap Pipe Insulation                      | 50                | LF             | Engine Room, 021, Basement Corridor - 1921   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 25        | MJP E/F/V on Magblock Pipe Insulation                       | 60                | LF             | Boiler Room - 1892   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 26        | 9x9 Green Off-White w/ Black Streaks Floor Tile (ABATED)    | 0                 |                | Rooms 307 & 309 - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 27        | 12"x12" Brown w/ Speckles Floor Tile (ABATED)               | 0                 |                | 1st & 3rd Floor Corridors, 206, 105, 106, 109, 107 (Main Office),108 and Staff Lounge - 1892       | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 28        | Black Linoleum NOT OBSERVED                                 |                   |                | Auditorium - 1921  | Assumed       | MISC              | No      |                 |              |  |                 |
| 29        | 9"x9" Off White w/ Black Streaks Floor Tile Mastic (ABATED) | 0                 |                | Rooms 307 & 309 - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 30        | 12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)        | 0                 |                | 1st & 3rd Floor Corridors, 206, 105, 106,196, 109, 107 (Main Office),108 and Staff Lounge - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 31        | Brown Linoleum (ABATED)                                     | 0                 |                | Auditorium Balcony - 1921  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 32        | 9"x9" Brown Floor Tile (ABATED)                             | 0                 |                | 3rd Floor Teacher's Toilet - 1921  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 33        | 12"x12" Green w/ White Streaks Floor Tile (ABATED)          | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 34        | 9"x9" Brown Floor Tile Mastic (ABATED)                      | 0                 |                | 3rd Floor Teacher's Toilet - 1921  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 35        | 12"x12" Green w/ White Streaks Floor Tile Mastic (ABATED)   | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 36        | Aircell Pipe Insulation                                     | 21                | LF             | Basement Corridor, Fan Rooms, All Janitors Closets - 1921  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 37        | MJP E/F/V on Aircell Pipe Insulation                        | 10                | LF             | Basement Corridor, Fan Rooms, All Janitors Closets - 1921  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 38        | Mag Block Pipe Insulation                                   | 14                | LF             | Room 002 - 1921  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 39        | MJP E/F/V on Mag Block Pipe Insulation                      | 7                 | LF             | Room 002 - 1921  | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 40        | MJP E/F/V on Fiberglass Pipe Insulation                     | 7                 | LF             | Coal room, Boiler room, Basement   | Chrysotile    | TSI               | Yes     | 0               | LF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
|           |  |                   |                | Corridor, Fan Rooms 1 and 3 - 1892   |               |                   |         |                 |              |  |                 |
| 41        | MJP E/F/V on Fiberglass Pipe Insulation                        | 50                | SF             | Boys and Girls Playrooms, Assembly Hall - 1921   | Assumed       | TSI               | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 42        | 12"x12" Coffee Brown Floor Tile (ABATED)                       | 0                 |                | Room 306, 2nd & 3rd Floor Corridors - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 42A       | 12"x12" Coffee Brown Floor Tile Mastic (ABATED)                | 0                 |                | Room 306, 2nd & 3rd Floor Corridors - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 43        | 12"x12" Green w/ White Streaks Floor Tile (ABATED)             | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 43A       | 12"x12" Green w/ White Streaks Floor Tile (ABATED)             | 0                 |                | 1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 44        | 12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)        | 0                 |                | Rooms 005, 213, 312, 311, 305 (under carpet), 313-315, 317, 319 & 3rd Floor Corridor - 1892                | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 44A       | 12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED) | 0                 |                | Rooms 005, 213, 312, 311, 305, (under carpet) 313-315, & 3rd Floor Corridor - 1892                         | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 45        | 12"x12" White w/ Specks Floor Tile (ABATED)                    | 0                 |                | Rooms 308, 208, 211, 215, 110, 113, 115, 117, & 119 - 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 46        | 9"x9" Dark Brown w/ White Streaks Floor Tile (ABATED)          | 0                 |                | Room 001,002, 003 - 1921   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 46A       | 9"x9" Dark Brown w/ Streaks Floor Tile Mastic (ABATED)         | 0                 |                | Room 001,002,003 - 1921  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 47        | 9"x9" Gray w/ White Streaks Floor Tile (under carpet) (ABATED) | 0                 |                | Engineer's Office (Under Carpet) - 1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 47A       | 9"x9" Gray w/ White Streaks Floor Tile Mastic (ABATED)         | 0                 |                | Engineer's Office (Under Carpet) - 1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 48        | 9"x9" Black VFT (ABATED)                                       | 0                 |                | 1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892                                      | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 48A       | 9"x9" Black Floor Tile Mastic (ABATED)                         | 0                 |                | 1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892                                      | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 49        | 9"x9" Light Beige w/ Light Brown Streaks Floor Tile (ABATED)   | 0                 |                | Room 209 - 1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description   | Material Quantity | Material Units | Material Location                 | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 49A       | 9"x9" Light Beige w/ Lt Brown Streaks Floor Tile Mastic (ABATED) | 0                 |                | Room 209 - 1892                   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 50        | 12"x12" Dark Brown w/ White Speck Floor Tile (ABATED)            | 0                 |                | Room 106, & 111 - 1892            | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 50A       | 12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)    | 0                 |                | Room 106, & 111 - 1892            | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 51        | 12"x12" Peach Floor Tile (ABATED)                                | 0                 |                | Main Office Toilet - 1892         | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 51A       | 12"x12" Peach Floor Tile Mastic (ABATED)                         | 0                 |                | Main Office Toilet - 1892         | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 52        | 12"x12" Light Green Floor Tile (ABATED)                          | 0                 |                | Room 112 - 1892                   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 52A       | 12"x12" Light Green Floor Tile Mastic (ABATED)                   | 0                 |                | Room 112 - 1892                   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 53        | 12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)          | 0                 |                | Rooms 002, 302, 326 - 1921        | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 53A       | 12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)   | 0                 |                | Rooms 002, 302, 326 - 1921        | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 54        | 9"x9" Black Floor Tile (ABATED)                                  | 0                 |                | 3rd Floor Teacher's Toilet - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 54A       | 9"x9" Black Floor Tile Mastic (ABATED)                           | 0                 |                | 3rd Floor Teacher's Toilet - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 55        | 12"x18" Black Floor Tile (ABATED)                                | 0                 |                | 3rd Floor Teacher's Toilet - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 55A       | 12"x18" Black Floor Tile Mastic (ABATED)                         | 0                 |                | 3rd Floor Teacher's Toilet - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 56        | 9"x9" Light Brown w/ Dark Floor Tile (ABATED)                    | 0                 |                | Library (221/223) - 1921          | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 56A       | 9"x9" Light Brown w/ Dark Floor Tile Mastic (ABATED)             | 0                 |                | Library (221/223) - 1921          | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 57        | 12"x12" White Specks Floor Tile (ABATED)                         | 0                 |                | Room 321, 218 - 1921              | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 57A       | 12"x12" White Specks Floor Tile Mastic (ABATED)                  | 0                 |                | Room 321, 218 - 1921              | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 58        | 12"x12" Brown w/ Speckles Floor Tile (ABATED)                    | 0                 |                | 2nd Floor Corridor -1921          | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |



# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description   | Material Quantity | Material Units | Material Location                        | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
|           |  |                   |                |  |               |                   |         |                 |              | suspect ACBM   |                 |
| 58A       | 12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)           | 0                 |                | 2nd Floor Corridor -1921                 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 59        | 12"x12" Brown Floor Tile (ABATED)                              | 0                 |                | Room 021, 023, 025, Nurses Office - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 59A       | 12"x12" Brown Floor Tile Mastic (ABATED)                       | 0                 |                | Room 021, 023, 025, Nurses Office - 1921 | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 60        | 9"x9" Beige w/ Brown Streaks Floor Tile (ABATED)               | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 60A       | 9"x9" Beige w/ Brown Streaks Floor Tile Mastic (ABATED)        | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 61        | 9"x9" Brown w/ Beige Streaks Floor Tile (ABATED)               | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 61A       | 9"x9" Brown w/ Beige Streaks Floor Tile Mastic (ABATED)        | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 62        | 12"x12" Off White w/ Brown Specks Floor Tile (ABATED)          | 0                 |                | Room 001, Teachers Toilet - 1921         | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 62A       | 12"x12" Off White w/ Brown Specks Floor Tile Mastic (ABATED)   | 0                 |                | Room 001 and teacher's lounge- 1921      | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 63        | 12"x12" Dark Brown w/ White Specks Floor Tile (ABATED)         | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 63A       | 12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)  | 0                 |                | Assembly Hall - 1921                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 64        | 12"x12" Red/Orange w/ Yellow Specks Floor Tile (ABATED)        | 0                 |                | Kitchen & Room 15                        | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 64A       | 12"x12" Red/Orange w/ Yellow Specks Floor Tile Mastic (ABATED) | 0                 |                | Kitchen & Room 15                        | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 65        | Brown Carpet Adhesive (ABATED)                                 | 0                 |                | Basement Eng. Office                     | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 66        | 12 x 12 Light Blue Mix Floor Tile (ABATED)                     | 0                 |                | Rooms 213, 219, 313, and 315             | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 67        | 12 x 12 Light Blue Mix Floor Tile Adhesive (ABATED)            | 0                 |                | Rooms 213, 219, 313, and 315             | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 68        | 12"x12" Bright Blue Mix Floor Tile (ABATED)                    | 0                 |                | Rooms 309 and 317                        | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
 Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Material Description   | Material Quantity | Material Units | Material Location  | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                                      | Response        |
|-----------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 69        | 12"x12" Bright Blue Mix Floor Tile Adhesive (ABATED)                       | 0                 |                | Rooms 309 and 317  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 70        | 12"x12" Medium Blue Mix Floor Tile (ABATED)                                | 0                 |                | Room 217-1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 71        | 12"x12" Medium Blue Mix VFT Adhesive (ABATED)                              | 0                 |                | Room 217-1892  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 72        | 12"x12" Beige Floor Tile (As part of Checkerboard Pattern) (ABATED)        | 0                 |                | Main Office  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 73        | 12"x12" Beige Floor Tile Mastic (As part of Checkerboard Pattern) (ABATED) | 0                 |                | Main Office  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 74        | 12x12 Dark Gray Specks VFT (ABATED)  | 0                 |                | 225-1921 Bldg  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 75        | 12x12 Dark Gray W/ Specks VFT Mastic (ABATED)                              | 0                 |                | 225 - 1921 Bldg  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 76        | 12x12 Light Blue w/ Speckles VFT (ABATED)                                  | 0                 |                | 019, 213, 215, 219- 1892 Bldg  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 77        | 12x12 Light Blue w/ Speckles VFT Mastic (ABATED)                           | 0                 |                | 019, 213, 215, 219-Bldg 1892   | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 78        | 12x12 Light Blue w/ Speckles VFT   | 1,500             | SF             | 001(Lunchroom), 002  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 79        | 12x12 Light Blue w/ Speckles VFT Mastic                                    | 1,500             | SF             | 001(Lunchroom), 002  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 80        | Carpet Mastic(Tile Carpet) (ABATED)  | 0                 |                | Library  | Abated        | MISC              |         |                 |              | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 83        | 2'x4' White Ceiling Tile   | 3,000             | SF             | Room 001, Room 002, Library (2nd Floor)  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 84        | Dry Wall Soffit  | 200               | SF             | Room 001, Room 002   | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 85        | 24"x24" Beige VFT  | 30,000            | SF             | Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors. | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |
| 86        | 24"x24" Beige VFT Mastic   | 30,000            | SF             | Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108,   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage                 | Follow O&M Plan |

# Chicago Public Schools

School Lafayette School  
Address 2714 W. Augusta Blvd.

Unit 24121  
Chicago, IL, 60622

Building ID 4400  
Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

| HA Number | Material Description          | Material Quantity | Material Units | Material Location   | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category                      | Response        |
|-----------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
|           |                               |                   |                | 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors. |               |                   |         |                 |              |                                      |                 |
| 87        | 24"x24" light blue VFT        | 2,500             | SF             | Rooms 003, 005, 013, 318, 320   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 88        | 24"x24" light blue VFT Mastic | 2,500             | SF             | Rooms 003, 005, 013, 318, 320   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 89        | 24"x24" gray VFT              | 8,000             | SF             | Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 90        | 24"x24" gray VFT Mastic       | 8,000             | SF             | Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors                                | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 91        | 24"x24" dark brown VFT        | 3,000             | SF             | Rms 005 and 013; Lunchroom manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 92        | 24"x24" dark brown VFT Mastic | 3,000             | SF             | Rms 005 and 013; Lunchroom Manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors                     | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 93        | 24"x24" Black VFT             | 3,000             | SF             | Rm 025 and Auditorium   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 94        | 24"x24" Black VFT Mastic      | 3,000             | SF             | Rm 025 and Auditorium   | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 95        | Carpet Mastic                 | 2,500             | SF             | Rm 011, Auditorium  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 96        | Decorative Plaster            | 300               | SF             | Auditorium  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 97        | 2'x2' White Ceiling Tile      | 12,000            | SF             | Rooms 105A, 106, 107, 108, 109, 110, 205, 206, 207, 208, 210, 218A, 324, and 326  | Assumed       | MISC              | Yes     | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 98        | 24"x24" Orange VFT            | 2,000             | SF             | Rms 205, 206, 207, 208, 210, and 221  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |
| 99        | 24"x24" Orange VFT Mastic     | 2,000             | SF             | Rms 205, 206, 207, 208, 210, and 221  | Assumed       | MISC              | No      | 0               | SF           | 6 ACBM with the potential for damage | Follow O&M Plan |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
 Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Management Planner's Comments Summarized at the End of the Report*

|                                    |              |
|------------------------------------|--------------|
| Review Date                        | 11/08/2019   |
| Manager Planner Name               | Arturo Saenz |
| 100-04019                          | 5/15/2020    |
| Manager IDPH License No/Expiration |              |

| HA Number | Management Comments |
|-----------|---------------------|
| 01        | Repair ASAP         |
| 02        |                     |
| 03        |                     |
| 06        |                     |
| 100       |                     |
| 101       |                     |
| 102       |                     |
| 103       |                     |
| 104       |                     |
| 105       |                     |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 106       |                     |
| 107       |                     |
| 12        |                     |
| 13        |                     |
| 14        |                     |
| 15        |                     |
| 16        |                     |
| 18        |                     |
| 19        | Repair ASAP         |
| 20        |                     |
| 21        |                     |
| 22        |                     |
| 23        |                     |
| 24        |                     |
| 25        |                     |
| 26        |                     |
| 27        |                     |
| 28        |                     |
| 29        |                     |
| 30        |                     |
| 31        |                     |
| 32        |                     |
| 33        |                     |
| 34        |                     |
| 35        |                     |
| 36        |                     |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
 Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 37        |                     |
| 38        |                     |
| 39        |                     |
| 40        |                     |
| 41        |                     |
| 42        |                     |
| 42A       |                     |
| 43        |                     |
| 43A       |                     |
| 44        |                     |
| 44A       |                     |
| 45        |                     |
| 46        |                     |
| 46A       |                     |
| 47        |                     |
| 47A       |                     |
| 48        |                     |
| 48A       |                     |
| 49        |                     |
| 49A       |                     |
| 50        |                     |
| 50A       |                     |
| 51        |                     |
| 51A       |                     |
| 52        |                     |
| 52A       |                     |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
 Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 53        |                     |
| 53A       |                     |
| 54        |                     |
| 54A       |                     |
| 55        |                     |
| 55A       |                     |
| 56        |                     |
| 56A       |                     |
| 57        |                     |
| 57A       |                     |
| 58        |                     |
| 58A       |                     |
| 59        |                     |
| 59A       |                     |
| 60        |                     |
| 60A       |                     |
| 61        |                     |
| 61A       |                     |
| 62        |                     |
| 62A       |                     |
| 63        |                     |
| 63A       |                     |
| 64        |                     |
| 64A       |                     |
| 65        |                     |
| 66        |                     |

# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 67        |                     |
| 68        |                     |
| 69        |                     |
| 70        |                     |
| 71        |                     |
| 72        |                     |
| 73        |                     |
| 74        |                     |
| 75        |                     |
| 76        |                     |
| 77        |                     |
| 78        |                     |
| 79        |                     |
| 80        |                     |
| 83        |                     |
| 84        |                     |
| 85        |                     |
| 86        |                     |
| 87        |                     |
| 88        |                     |
| 89        |                     |
| 90        |                     |
| 91        |                     |
| 92        |                     |
| 93        |                     |
| 94        |                     |



# Chicago Public Schools

**School** Lafayette School  
**Address** 2714 W. Augusta Blvd.

**Unit** 24121  
Chicago, IL, 60622

**Building ID** 4400  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

| HA Number | Management Comments |
|-----------|---------------------|
| 95        |                     |
| 96        |                     |
| 97        |                     |
| 98        |                     |
| 99        |                     |

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **24121**    BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School**    INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.**    IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 207, 208, 210, 211, and 305- 1892**

MATERIAL QUANTITY: **0**    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (ABATED)**

MATERIAL LOCATION: **Rooms 207, 208, 210, 211, and 305- 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd Floor Corridors, 1st Floor Teachers Toilet - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **2'x2' Ceiling Tile (ABATED)**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, 1st Floor Teachers Toilet - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **24"x24" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 112, 115, and 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **24"x24" Green VFT**  
MATERIAL LOCATION: **Rms 112, 115, and 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **24"x24" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 112, 115, and 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **24"x24" Green VFT Mastic**  
MATERIAL LOCATION: **Rms 112, 115, and 117**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Corridor, Engine Room - 1892**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Basement Corridor, Engine Room - 1892**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler & Engine Rooms, Bsmt Cor, 007, 006 -1892**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Boiler & Engine Rooms, Bsmt Cor, 007, 006 -1892**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 107, 108, 007, Basement Corridor, Engine Room - 1892**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**  
MATERIAL LOCATION: **Room 107, 108, 007, Basement Corridor, Engine Room - 1892**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **Air Cell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Room 002 (Playroom), 1st and 2nd floor Janitor's Closet, 2nd Girl's and Boys Toilet, and 1st floor Girl's Toilet - 1921**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Air Cell Duct Insulation**

MATERIAL LOCATION: **Room 002 (Playroom), 1st and 2nd floor Janitor's Closet, 2nd Girl's and Boys Toilet, and 1st floor Girl's Toilet - 1921**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1921**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1921**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engine Room, 021, Basement Corridor, 1st & 3rd Floor Janitors Closet - 1921**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Engine Room, 021, Basement Corridor, 1st & 3rd Floor Janitors Closet - 1921**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1892**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **LF**  
COMMENTS: **by Attic**

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler Room - 1892**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:  
Repair ASAP

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **ACM Rope**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room - 1892**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **ACM Rope**  
MATERIAL LOCATION: **Boiler Room - 1892**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **150000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout 1921 Building**  
MATERIAL QUANTITY: **150000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Boiler Gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler #1 in Boiler Room - 1892**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler #1 in Boiler Room - 1892**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Boiler Gasket (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler #2 in Boiler Room -1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Boiler Gasket (ABATED)**

MATERIAL LOCATION: **Boiler #2 in Boiler Room -1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engine Room, 021, Basement Corridor - 1921**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **MJP E/F/V on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **Engine Room, 021, Basement Corridor - 1921**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **MJP E/F/V on Magblock Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boiler Room - 1892**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **MJP E/F/V on Magblock Pipe Insulation**

MATERIAL LOCATION: **Boiler Room - 1892**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **9x9 Green Off-White w/ Black Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307 & 309 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9x9 Green Off-White w/ Black Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 307 & 309 - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 206, 105, 106, 109, 107 (Main Office),108 and Staff Lounge - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile (ABATED)**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 206, 105, 106, 109, 107 (Main Office),108 and Staff Lounge - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Black Linoleum NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium - 1921**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Black Linoleum NOT OBSERVED**

MATERIAL LOCATION: **Auditorium - 1921**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 307 & 309 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **Rooms 307 & 309 - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 206, 105, 106,196, 109, 107 (Main Office),108 and Staff Lounge - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **1st & 3rd Floor Corridors, 206, 105, 106,196, 109, 107 (Main Office),108 and Staff Lounge - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Brown Linoleum (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Balcony - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Brown Linoleum (ABATED)**

MATERIAL LOCATION: **Auditorium Balcony - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Kindergarten, 2nd Floor Teacher's Toilet, Room 320, 120, 204 - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Corridor, Fan Rooms, All Janitors Closets - 1921**  
MATERIAL QUANTITY: **21** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Corridor, Fan Rooms, All Janitors Closets - 1921**

MATERIAL QUANTITY: **21**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Basement Corridor, Fan Rooms, All Janitors Closets - 1921**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Corridor, Fan Rooms, All Janitors Closets - 1921**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 002 - 1921**  
MATERIAL QUANTITY: **14** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Room 002 - 1921**

MATERIAL QUANTITY: **14**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 002 - 1921**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Room 002 - 1921**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Coal room, Boiler room, Basement Corridor, Fan Rooms 1 and 3 - 1892**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Coal room, Boiler room, Basement Corridor, Fan Rooms 1 and 3 - 1892**  
MATERIAL QUANTITY: **7** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Boys and Girls Playrooms, Assembly Hall - 1921**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Boys and Girls Playrooms, Assembly Hall - 1921**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12"x12" Coffee Brown Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 306, 2nd & 3rd Floor Corridors - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12"x12" Coffee Brown Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 306, 2nd & 3rd Floor Corridors - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12"x12" Coffee Brown Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 306, 2nd & 3rd Floor Corridors - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **42A**  
MATERIAL DESCRIPTION: **12"x12" Coffee Brown Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 306, 2nd & 3rd Floor Corridors - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge& 319, 007 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **43A**  
MATERIAL DESCRIPTION: **12"x12" Green w/ White Streaks Floor Tile (ABATED)**  
MATERIAL LOCATION: **1st, 2nd, 3rd Floor Corridors, Rooms 110, 113, 120, 222, 204, 205, 210, 317, mens lounge & 319, 007 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 005, 213, 312, 311, 305 (under carpet), 313-315, 317, 319 & 3rd Floor Corridor - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 005, 213, 312, 311, 305 (under carpet), 313-315, 317, 319 & 3rd Floor Corridor - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 005, 213, 312, 311, 305, (under carpet) 313-315, & 3rd Floor Corridor - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **44A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Rooms 005, 213, 312, 311, 305, (under carpet) 313-315, & 3rd Floor Corridor - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"x12" White w/ Specks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 308, 208, 211, 215, 110, 113, 115, 117, & 119 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12"x12" White w/ Specks Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 308, 208, 211, 215, 110, 113, 115, 117, & 119 - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 001,002, 003 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ White Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 001,002, 003 - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46A**  
MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 001,002,003 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **46A**

MATERIAL DESCRIPTION: **9"x9" Dark Brown w/ Streaks Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **Room 001,002,003 - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks Floor Tile (under carpet) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks Floor Tile (under carpet) (ABATED)**

MATERIAL LOCATION: **Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **47A**  
MATERIAL DESCRIPTION: **9"x9" Gray w/ White Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Engineer's Office (Under Carpet) - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **9"x9" Black VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **9"x9" Black VFT (ABATED)**

MATERIAL LOCATION: **1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **48A**  
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **1st Floor Teacher's Toilet, & Engineer's Office (Under Carpet) - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Light Brown Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 209 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Light Brown Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 209 - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Lt Brown Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 209 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **49A**  
MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Lt Brown Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 209 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Speck Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, & 111 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Speck Floor Tile (ABATED)**  
MATERIAL LOCATION: **Room 106, & 111 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, & 111 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **50A**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 106, & 111 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Peach Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Toilet - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Peach Floor Tile (ABATED)**  
MATERIAL LOCATION: **Main Office Toilet - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51A**  
MATERIAL DESCRIPTION: **12"x12" Peach Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Toilet - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **51A**  
MATERIAL DESCRIPTION: **12"x12" Peach Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Main Office Toilet - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 112 - 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52A**  
MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 112 - 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **52A**  
MATERIAL DESCRIPTION: **12"x12" Light Green Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 112 - 1892**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 002, 302, 326 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 002, 302, 326 - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 002, 302, 326 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **53A**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Rooms 002, 302, 326 - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54A**  
MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **54A**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x18" Black Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12"x18" Black Floor Tile (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55A**  
MATERIAL DESCRIPTION: **12"x18" Black Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **55A**

MATERIAL DESCRIPTION: **12"x18" Black Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **3rd Floor Teacher's Toilet - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Dark Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (221/223) - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Dark Floor Tile (ABATED)**

MATERIAL LOCATION: **Library (221/223) - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56A**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Dark Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library (221/223) - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **56A**  
MATERIAL DESCRIPTION: **9"x9" Light Brown w/ Dark Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Library (221/223) - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" White Specks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321, 218 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12"x12" White Specks Floor Tile (ABATED)**  
MATERIAL LOCATION: **Room 321, 218 - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57A**  
MATERIAL DESCRIPTION: **12"x12" White Specks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 321, 218 - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **57A**  
MATERIAL DESCRIPTION: **12"x12" White Specks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 321, 218 - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor -1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile (ABATED)**

MATERIAL LOCATION: **2nd Floor Corridor -1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor -1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **58A**  
MATERIAL DESCRIPTION: **12"x12" Brown w/ Speckles Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **2nd Floor Corridor -1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 021, 023, 025, Nurses Office - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 021, 023, 025, Nurses Office - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59A**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 021, 023, 025, Nurses Office - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **59A**  
MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 021, 023, 025, Nurses Office - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Brown Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9"x9" Beige w/ Brown Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60A**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Brown Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **60A**  
MATERIAL DESCRIPTION: **9"x9" Beige w/ Brown Streaks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Assembly Hall - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Beige Streaks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9"x9" Brown w/ Beige Streaks Floor Tile (ABATED)**

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61A**  
MATERIAL DESCRIPTION: **9"x9" Brown w/ Beige Streaks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **61A**

MATERIAL DESCRIPTION: **9"x9" Brown w/ Beige Streaks Floor Tile Mastic (ABATED)**

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Specks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 001, Teachers Toilet - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Specks Floor Tile (ABATED)**  
MATERIAL LOCATION: **Room 001, Teachers Toilet - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Specks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 001 and teacher's lounge- 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **62A**  
MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Specks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Room 001 and teacher's lounge- 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile (ABATED)**

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63A**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assembly Hall - 1921**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **63A**  
MATERIAL DESCRIPTION: **12"x12" Dark Brown w/ White Specks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Assembly Hall - 1921**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12"x12" Red/Orange w/ Yellow Specks Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Room 15**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12"x12" Red/Orange w/ Yellow Specks Floor Tile (ABATED)**

MATERIAL LOCATION: **Kitchen & Room 15**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64A**  
MATERIAL DESCRIPTION: **12"x12" Red/Orange w/ Yellow Specks Floor Tile Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen & Room 15**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **64A**  
MATERIAL DESCRIPTION: **12"x12" Red/Orange w/ Yellow Specks Floor Tile Mastic (ABATED)**  
MATERIAL LOCATION: **Kitchen & Room 15**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement Eng. Office**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Brown Carpet Adhesive (ABATED)**

MATERIAL LOCATION: **Basement Eng. Office**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12 x 12 Light Blue Mix Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 213, 219, 313, and 315**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12 x 12 Light Blue Mix Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 213, 219, 313, and 315**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **12 x 12 Light Blue Mix Floor Tile Adhesive (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 213, 219, 313, and 315**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12 x 12 Light Blue Mix Floor Tile Adhesive (ABATED)**

MATERIAL LOCATION: **Rooms 213, 219, 313, and 315**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue Mix Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 309 and 317**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x12" Bright Blue Mix Floor Tile (ABATED)**

MATERIAL LOCATION: **Rooms 309 and 317**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **12"x12" Bright Blue Mix Floor Tile Adhesive (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 309 and 317**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12"x12" Bright Blue Mix Floor Tile Adhesive (ABATED)**

MATERIAL LOCATION: **Rooms 309 and 317**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **12"x12" Medium Blue Mix Floor Tile (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217-1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12"x12" Medium Blue Mix Floor Tile (ABATED)**

MATERIAL LOCATION: **Room 217-1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12"x12" Medium Blue Mix VFT Adhesive (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 217-1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12"x12" Medium Blue Mix VFT Adhesive (ABATED)**

MATERIAL LOCATION: **Room 217-1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile (As part of Checkerboard Pattern) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile (As part of Checkerboard Pattern) (ABATED)**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic (As part of Checkerboard Pattern) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic (As part of Checkerboard Pattern) (ABATED)**  
MATERIAL LOCATION: **Main Office**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12x12 Dark Gray Specks VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **225-1921 Bldg**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12x12 Dark Gray Specks VFT (ABATED)**

MATERIAL LOCATION: **225-1921 Bldg**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Dark Gray W/ Specks VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **225 - 1921 Bldg**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12x12 Dark Gray W/ Specks VFT Mastic (ABATED)**

MATERIAL LOCATION: **225 - 1921 Bldg**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **019, 213, 215, 219- 1892 Bldg**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT (ABATED)**  
MATERIAL LOCATION: **019, 213, 215, 219- 1892 Bldg**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **019, 213, 215, 219-Bldg 1892**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT Mastic (ABATED)**

MATERIAL LOCATION: **019, 213, 215, 219-Bldg 1892**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **001(Lunchroom), 002**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT**  
MATERIAL LOCATION: **001(Lunchroom), 002**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **001(Lunchroom), 002**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/ Speckles VFT Mastic**  
MATERIAL LOCATION: **001(Lunchroom), 002**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Carpet Mastic(Tile Carpet) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Carpet Mastic(Tile Carpet) (ABATED)**  
MATERIAL LOCATION: **Library**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 001, Room 002, Library (2nd Floor)**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
MATERIAL LOCATION: **Room 001, Room 002, Library (2nd Floor)**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Dry Wall Soffit**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 001, Room 002**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Dry Wall Soffit**

MATERIAL LOCATION: **Room 001, Room 002**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **24"x24" Beige VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors.**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **24"x24" Beige VFT**

MATERIAL LOCATION: **Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors.**

MATERIAL QUANTITY: **30000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/08/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **24"x24" Beige VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors.**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **24"x24" Beige VFT Mastic**

MATERIAL LOCATION: **Rooms 003, 005, Engineer's Office & Vestibule, 011 Foyer, 013, 017A, 017B, 019, Aud. Store Room, 105A, 107, 108, 109, 112, 115, 117, 221, 210, 207, 208, 206, 205, 302, 312A, 312B, 308, 318, 312, 320. 1st, 2nd, and 3rd floor corridors.**

MATERIAL QUANTITY: **30000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 11/08/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **24"x24" light blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 003, 005, 013, 318, 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **24"x24" light blue VFT**  
MATERIAL LOCATION: **Rooms 003, 005, 013, 318, 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **24"x24" light blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 003, 005, 013, 318, 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **24"x24" light blue VFT Mastic**  
MATERIAL LOCATION: **Rooms 003, 005, 013, 318, 320**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **24"x24" gray VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **24"x24" gray VFT**  
MATERIAL LOCATION: **Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **24"x24" gray VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **24"x24" gray VFT Mastic**  
MATERIAL LOCATION: **Rms 003, 112, 115, 117, 205, 206, 207, 208, 210 and 221; 1st, 2nd, and 3rd Floor Corridors**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **24"x24" dark brown VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rms 005 and 013; Lunchroom manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **24"x24" dark brown VFT**  
MATERIAL LOCATION: **Rms 005 and 013; Lunchroom manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **24"x24" dark brown VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rms 005 and 013; Lunchroom Manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **24"x24" dark brown VFT Mastic**  
MATERIAL LOCATION: **Rms 005 and 013; Lunchroom Manager's Office; Engineer's Store Room; 1st, 2nd, and 3rd Floor Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **24"x24" Black VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 025 and Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **24"x24" Black VFT**  
MATERIAL LOCATION: **Rm 025 and Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **24"x24" Black VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 025 and Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **24"x24" Black VFT Mastic**  
MATERIAL LOCATION: **Rm 025 and Auditorium**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rm 011, Auditorium**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Rm 011, Auditorium**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 105A, 106, 107, 108, 109, 110, 205, 206, 207, 208, 210, 218A, 324, and 326**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**

MATERIAL LOCATION: **Rooms 105A, 106, 107, 108, 109, 110, 205, 206, 207, 208, 210, 218A, 324, and 326**

MATERIAL QUANTITY: **12000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **24"x24" Orange VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 205, 206, 207, 208, 210, and 221**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **24"x24" Orange VFT**  
MATERIAL LOCATION: **Rms 205, 206, 207, 208, 210, and 221**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School** INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **24"x24" Orange VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rms 205, 206, 207, 208, 210, and 221**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24121** BUIDLING ID: **4400**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School** REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.** IDPH LICENSE NO: **100-11089**

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **24"x24" Orange VFT Mastic**

MATERIAL LOCATION: **Rms 205, 206, 207, 208, 210, and 221**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Auditorium and balcony isles**  
MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **frame hood panel**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **12**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School**      INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Boiler room corridor by the warm air chamber across from play room 7**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **LF**  
MATERIAL CATEGORY: **TSI**      FRIABLE:  
ASBESTOS TYPE: **Chrysotile**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **5**      DAMAGE REASON:  
DAMAGE UNITS: **LF**  
  
COMMENTS:  
Open ends

Inspector's Signature: \_\_\_\_\_ Date: 06/11/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **Boiler room corridor by the warm air chamber across from play room 7**  
MATERIAL QUANTITY: **800**      MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **5**      DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

COMMENTS:  
Repair ASAP

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Panfilo Carrazco**  
SCHOOL NAME: **Lafayette School**      INSPECTION DATE: **6/11/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **3rd, 2nd, 1st, basement corridor for elevator door room 311**  
MATERIAL QUANTITY: **250**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **06/11/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **Drywall System**  
MATERIAL LOCATION: **3rd, 2nd, 1st, basement corridor for elevator door room 311**  
MATERIAL QUANTITY: **250**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Spray on Insulation**  
MATERIAL LOCATION: **Attic in Addition 1921**  
MATERIAL QUANTITY: **4000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Spray On Insulation**  
MATERIAL LOCATION: **Attic In addition 1892**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1892 Building**

MATERIAL QUANTITY:      MATERIAL UNITS:

DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24121**      BUILDING ID: **4400**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Lafayette School**      REVIEW DATE: **11/8/2019**  
ADDRESS: **2714 W. Augusta Blvd.**      IDPH LICENSE NO: **100-11089**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Science Lab Tables**

MATERIAL LOCATION: **Rooms 206, 208, 207, 210 and 317**

MATERIAL QUANTITY: **180**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **11/08/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*



# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANFILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/13/2016 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

02/13/2016

Course Dates:

02/13/2017

Expires:

1602BIR10

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
103 S. Ashland Ave., Chicago, IL 60607

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
 855 W ADAMS STREET, SUITE 200  
 CHICAGO, IL 60607

4/28/2017


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

|  |                            |  |   |  |                   |
|--|----------------------------|--|---|--|-------------------|
|   |                            | <b>ASBESTOS<br/>         PROFESSIONAL<br/>         LICENSE</b> |   | <b>ENDORSEMENTS</b>                          | <b>TC EXPIRES</b> |
| <b>ID NUMBER</b><br>100 - 11089  | <b>ISSUED</b><br>4/28/2017 | <b>EXPIRES</b><br>05/15/2018                                   | INSPECTOR   |  | 2/11/2018         |
| <b>PANFILO CARRAZCO</b><br>855 W ADAMS STREET, SUITE<br>CHICAGO, IL 60607<br>Environmental Health  |                            |  |  | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL | 2/4/2018          |
| <p style="text-align: center;"><b>Alteration of this license shall result in legal action</b><br/>         This license issued under authority of the State of Illinois<br/>         Department of Public Health<br/>         This license is valid only when accompanied by a valid<br/>         training course certificate.</p> |                            |  |   |  |                   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that PANILO CARRAZCO  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR08

Certificate Number:

*Nicholas J. Peneff*

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**PANFILO CARRAZCO**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

|   |   |                              |   |                   |
|---|---|------------------------------|---|-------------------|
| <br><b>ASBESTOS PROFESSIONAL LICENSE</b> |   |                              | <b>ENDORSEMENTS</b>   | <b>TC EXPIRES</b> |
| <b>ID NUMBER</b><br>100 - 11089   | <b>ISSUED</b><br>4/19/2019  | <b>EXPIRES</b><br>05/15/2020 | INSPECTOR   | 2/9/2020          |
| <b>PANFILO CARRAZCO</b><br>2942 W VAN BUREN ST<br>CHICAGO, IL 60612<br>Environmental Health                               |  |                              | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL  | 2/2/2020          |
|   |   |                              | <b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br>This license is valid only when accompanied by a valid<br>training course certificate. |                   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



535-535 West Jefferson Street • Springfield, Illinois 62761-0201 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/18/2016

**PANFILO CARRAZCO**  
 855 W ADAMS STREET, SUITE 200  
 CHICAGO, IL 60607



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11089

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE   |           |   | ENDORSEMENTS   | TC EXPIRES |
|---|-----------|---|--|------------|
|                  |           |   | INSPECTOR  | 2/13/2017  |
| ID NUMBER   | ISSUED    | EXPIRES   |  |            |
| 100 - 11089   | 4/18/2016 | 05/15/2017  |  |            |
| <b>PANFILO CARRAZCO</b><br>855 W ADAMS STREET, SUITE<br>CHICAGO, IL 60607<br>Environmental Health |           |  | PROJECT MANAGER<br>AIR SAMPLING PROFESSIONAL<br><b>Alteration of this license shall result in legal action</b><br>This license issued under authority of the State of Illinois<br>Department of Public Health<br><b>This license is valid only when accompanied by a valid<br/>           training course certificate.</b> | 2/6/2017   |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280693

---

Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

|                  |               |                |
|------------------|---------------|----------------|
| <b>ID NUMBER</b> | <b>ISSUED</b> | <b>EXPIRES</b> |
| 100 - 04019      | 4/30/2019     | 05/15/2020     |

**ARTURO SAENZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612  
Environmental Health



| <b>ENDORSEMENTS</b> | <b>TC EXPIRES</b> |
|---------------------|-------------------|
|---------------------|-------------------|

|                    |           |
|--------------------|-----------|
| INSPECTOR          | 2/28/2020 |
| MANAGEMENT PLANNER | 2/28/2020 |

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

|                          | <b>CODE</b> | <b>KEY</b>                             |
|--------------------------|-------------|--|
| <b>MATERIAL</b>          |             |  |
|                          | ACBM        | Asbestos Containing Building Materials |
| <b>MATERIAL CATEGORY</b> |             |  |
|                          | MISC        | Miscellaneous                          |
|                          | SURF        | Surfacing                              |
|                          | TSI         | Thermal System Insulation              |
| <b>MATERIAL UNITS</b>    |             |  |
|                          | LF          | Linear Feet                            |
|                          | SF          | Square Feet                            |
|                          | CF          | Cubic Feet                             |
| <b>DAMAGE TYPE</b>       |             |  |
|                          | Loc         | Localized                              |
|                          | Dist        | Distributed                            |