

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0124  
SCHOOL NAME: Chicago International Charter - Longwood (South)  
ADDRESS OF SCHOOL: 1309 W.95th St (9500S) 43  
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **6/2/2017**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1245  
IDPH INSPECTOR LICENSE NUMBER: 100-06327  
IDPH LICENSED INSPECTOR NAME(Please Print): Roberto Rivera  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Chicago International Charter - Longwood (South)**

1309 W.95th St (9500S) 43  
Chicago, IL, 60643

Unit: 66061  
Building ID: 2420

IDPH ID Number: 14-016-2990-0124

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

August 5, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 66061            Region: 02            IDPH ID:14-016-2990-0124

School: Chicago International Charter - Longwood (South)            Building ID: 2420

Address: 1309 W.95th St (9500S) 43

Chicago, IL, 60643

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 09/24/2019

Inspector: Roberto Rivera

Inspector IDPH License: 100-06327

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: August 05, 2019

RE: Chicago International Charter - Longwood (South), Unit 66061  
1309 W.95th St (9500S) 43  
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Chicago International Charter - Longwood (South), following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Chicago International Charter - Longwood (South), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Chicago International Charter - Longwood (South) Unit: 66061 Region: 02  
Address: 1309 W.95th St (9500S) 43 Chicago, IL, 60643  
IDPH ID: 14-016-2990-0124 Building ID: 2420  
Contact: Phone:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 1245

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327

Signature:  
Date: 8/5/2019

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:  
Date: 09/24/2019

### 7. Review Date:09/24/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago International Charter - Longwood (South). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2420:

141

Decorative Stucco

B. The following new homogenous areas have been identified for Building 2420:

142	12"x12" Gray w/ Black & Gray Specks VFT
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic
143	9"x9" Off White w/ Black Streaks VFT
143M	9"x9" Off White w/ Black Streaks VFT Mastic
144	12"x12" Light Blue w/ Streaks VFT
144M	12"x12" Light Blue w/ Streaks VFT Mastic
145	1'x1' Ceiling Tile w/ Holes
145M	1'x1' Ceiling Tile w/ Holes Mastic
146	Decorative Plaster
147	12"x12" Dark Gray w/ Black & Gray Specks VFT
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
148	Popcorn Plaster Ceiling
149	Green Carpet Mastic
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic
151	Decorative Plaster
152	12"x12" Black w/ White Specks VFT
152M	12"x12" Black w/ White Specks VFT Mastic
153	12"x12" Sand VFT
153M	12"x12" Sand VFT Mastic
154	1'x1' White Ceiling Tile



154M	1'x1' White Ceiling Tile Mastic Pucks
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
156	2'x4' Ceiling Tile
157	Terrazzo Flooring
158	Attic Plaster
159	12"x12" Light Blue w/ Streaks VFT
159M	12"x12" Light Blue w/ Streaks VFT Mastic
160	12"x12" Dark Gray w/ Light Gray Specks VFT
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic
161	9"x9" Green w/ White Streaks VFT
161M	9"x9" Green w/ White Streaks VFT Mastic
162	Decorative Plaster
163	Troweled-on Plaster Walls
164	Spray-on Fireproofing
165	12"x12" White VFT
165M	12"X12" White VFT Mastic
166	12"x12" Black w/ White Specks VFT
166M	12"x12" Black w/ White Specks VFT Mastic
167	12"x12" Yellow Streaked VFT
167M	12"x12" Yellow Streaked VFT Mastic
168	12"x12" Maroon Streaked VFT
168M	12"x12" Maroon Streaked VFT Mastic
169	2'x2' Ceiling Tile w/ Pinholes

170	Pink Ceramic Tile Grout
171	Pink Ceramic Tile Adhesive

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	9 x 9 VFT Black w/ Camoflounge (under HA# 106 & 107)
101	9 x 9 VFT Black w/ Camouflounge Mastic (under HA 106 & 107)
102	9 x 9 VFT Brown (under HA 106 & 107)
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)
104	9 x 9 Brown VFT (under HA 106 & 107)
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)
106	12 x 12 Gray VFT Speckled
107	12 x 12 Gray VFT Speckled Mastic
108	12 x 12 Gray w/ Red, White & Blue Specs VFT
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic
110	Plaster
113	1 x 1 Ceiling Tile white w/ Swirls
114	Green Terrazzo
115	Spray On Fireproofing
116	Terrazzo
117	12 x 12 VFT Gray Speckled
118	12 x 12 VFT Gray Speckled Mastic
119	1 x 1 CT White w/ Pinhole
120	9 x9 VFT White w/ gray strks
121	9 x 9 VFT White w/ gray strks Mastic
122	9 x 9 VFT Black
123	9 x 9 VFT Black Mastic
124	9 x 9 VFT Pink w/ Black Strks
125	9 x 9 VFT Pink w/ Black Strks Mastic
126	9 x 9 VFT Dark Gray w/ white strks
127	9 x 9 VFT Dark Gray w/ white strks Mastic
128	9 x 9 VFT Dark Pink w/ strks
129	9 x 9 VFT Dark Pink w/ strks Mastic
130	12 x 12 VFT Beige Mixed Speckled
131	12 x 12 VFT Beige Mixed Speckled Mastic
132	9 x 9 VFT Brown
133	9 x 9 VFT Brown Mastic
134	Plaster
135	12 x 12 VFT Purple Speckled
136	12 x 12 VFT Purple Speckled Mastic
137	12 x 12 VFT Tan w/ Lt Brown Specs
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic
141	Decorative Stucco
142	12"x12" Gray w/ Black & Gray Specks VFT
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic

143	9"x9" Off White w/ Black Streaks VFT
143M	9"x9" Off White w/ Black Streaks VFT Mastic
144	12"x12" Light Blue w/ Streaks VFT
144M	12"x12" Light Blue w/ Streaks VFT Mastic
145	1'x1' Ceiling Tile w/ Holes
145M	1'x1' Ceiling Tile w/ Holes Mastic
146	Decorative Plaster
147	12"x12" Dark Gray w/ Black & Gray Specks VFT
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
148	Popcorn Plaster Ceiling
149	Green Carpet Mastic
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic
151	Decorative Plaster
152	12"x12" Black w/ White Specks VFT
152M	12"x12" Black w/ White Specks VFT Mastic
153	12"x12" Sand VFT
153M	12"x12" Sand VFT Mastic
154	1'x1' White Ceiling Tile
154M	1'x1' White Ceiling Tile Mastic Pucks
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic
156	2'x4' Ceiling Tile
157	Terrazzo Flooring
158	Attic Plaster
159	12"x12" Light Blue w/ Streaks VFT
159M	12"x12" Light Blue w/ Streaks VFT Mastic
160	12"x12" Dark Gray w/ Light Gray Specks VFT
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic
161	9"x9" Green w/ White Streaks VFT
161M	9"x9" Green w/ White Streaks VFT Mastic
162	Decorative Plaster
163	Troweled-on Plaster Walls
164	Spray-on Fireproofing
165	12"x12" White VFT
165M	12"x12" White VFT Mastic
166	12"x12" Black w/ White Specks VFT
166M	12"x12" Black w/ White Specks VFT Mastic
167	12"x12" Yellow Streaked VFT
167M	12"x12" Yellow Streaked VFT Mastic
168	12"x12" Maroon Streaked VFT
168M	12"x12" Maroon Streaked VFT Mastic

169	2'x2' Ceiling Tile w/ Pinholes
170	Pink Ceramic Tile Grout
171	Pink Ceramic Tile Adhesive
19A	WRAP OVER FIBER GLASS
30	1'x1' Ceiling Tile (with Pinholes & Grooves)
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Celing Tile
31	2'x4' Lay In Ceiling Tile
35	PLASTER
36	Blue Carpet Adhesive
37	Brown Carpet Adhesive
41	Terrazzo
42	Ceramic Tile Grout
43	Ceramic Tile Adhesive
44	Drywall
45	Drywall Compound
46	Tectum Ceiling Panels
47	Chalkboard/Whiteboard Adhesive
48	Vinyl Stair Treads
49	Vinyl Stair Thread Adhesive
50	4" Black Baseboard
51	4" Black Baseboard Adhesive
54	4" Brown Baseboard
55	4" Brown Baseboard Adhesive
58	4" x 4" Floor Tile
59	4" x 4" Floor Tile Mastic
60	Grey and Black Carpet Adhesive
61	Acoustical Ceiling Plaster
62	Pegboard on Walls
64	1 x 1 White w/ Gooves Spline Ceiling Tile
67	9 x 9 VFT Gray w/ streaks VFT
68	9 x 9 VFT Gray w/ Streaks Mastic
71	Plaster
72	12 x 12 VFT Gray w/ Balck & White Specks
73	12 x 12 VFT Gray w/ Black & White Specs Mastic
74	9 x 9 VFT Tan (Under HA 147 & 147M)
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)
76	9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)
79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)
80	Gray Linoleum (Under HA 147 & 147M)
81	Gray Linoleum Mastic (Under HA 147 & 147M)
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)

83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)
84	Plaster
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)
86	12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)
87	2 x 4 CT White w/ Swirls
88	12 x 12 Black VFT (Terrazzo Like)
89	12 x 12 Black VFT & Mastic (Terrazzo Like)
90	9 x 9 VFT Lt. Brown w/ Specs
91	9 x 9 VFT Lt Brown w/ Specs Mastic
96	12 x 12 VFT Mixed Red Speckled
97	12 x 12 VFT Mixed Red Speckled Mastic
98	1'x1' CT White w/ Holes
99	Terrazzo

The following areas were deemed to be inaccessible:

46 Tectum Ceiling Panels

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Chicago International Charter - Longwood (South) Building 2420 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Aircell Pipe Insulation	701	LF	Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	Preform Pipe Cover (Mag Block Pipe Insulation)	367	LF	Incinerator Room, Tunnel, Main Shop Room, Electric Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
07	Cardboard Pipe Cover	49	LF	Kitchen and Maintenance Closet	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
08	Aircell Pipe Joint Packing	67	LF	Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
09	Preformed Pipe Joint Insulation	44	LF	Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	Joint packing on Fiberglass Insulated Piping	30	EA	Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
100	9 x 9 VFT Black w/ Camouflage (under HA# 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	9 x 9 VFT Black w/ Camouflage Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	9 x 9 VFT Brown (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
104	9 x 9 Brown VFT (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
106	12 x 12 Gray VFT Speckled	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry Rm. Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
107	12 x 12 Gray VFT Speckled Mastic	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12 x 12 Gray w/ Red, White & Blue Specs VFT	800	SF	Stairwell Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic	800	SF	Stairwell Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	Plaster	28,000	SF	Throughout Bldg 1920	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12 x 12 VFT Beige w/ Black Streaks - (Abated)			Rm 255 Bldg 1920	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
112	12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)	0		Rm 255 Bldg 1920	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
113	1 x 1 Ceiling Tile white w/ Swirls	2,100	SF	Weight Room and Rm 51 Bldg 1920	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
114	Green Terrazzo	600	SF	Rm 51 Bldg 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Spray On Fireproofing	2,300	SF	Attic Bldg 1890	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
116	Terrazzo	8,000	SF	Throughout Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12 x 12 VFT Gray Speckled	1,200	SF	Rm 114 and 314 Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
118	12 x 12 VFT Gray Speckled Mastic	1,200	SF	Rm 114 and 314 Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
119	1 x 1 CT White w/ Pinhole	29,000	SF	L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313,	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031										
12	Stack Insulation			Incinerator Rm	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
120	9 x9 VFT White w/ gray strks	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
121	9 x 9 VFT White w/ gray strks Mastic	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across From Mechanical Room 018 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
122	9 x 9 VFT Black	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
123	9 x 9 VFT Black Mastic	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
124	9 x 9 VFT Pink w/ Black Strks	900	SF	Rooms L307, L317, L221 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
125	9 x 9 VFT Pink w/ Black Strks Mastic	900	SF	Rooms L307, L317, L221 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
126	9 x 9 VFT Dark Gray w/ white strks	600	SF	Rooms L307, L318, L317, 205 - Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1890										
127	9 x 9 VFT Dark Gray w/ white strks Mastic	600	SF	Rooms L307, L318, L317, 205 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
128	9 x 9 VFT Dark Pink w/ strks	600	SF	Rooms L318, 205 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
129	9 x 9 VFT Dark Pink w/ strks Mastic	600	SF	Rooms L318, 205 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	KEWANEE BOILER COVER - (Abated)	0		MAIN BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
130	12 x 12 VFT Beige Mixed Speckled	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
131	12 x 12 VFT Beige Mixed Speckled Mastic	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
132	9 x 9 VFT Brown	500	SF	Room L209 - Bldg. 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
133	9 x 9 VFT Brown Mastic	500	SF	Room L209 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
134	Plaster	25,000	SF	Throughout Bldg 1890	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
135	12 x 12 VFT Purple Speckled	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
136	12 x 12 VFT Purple Speckled Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
137	12 x 12 VFT Tan w/ Lt Brown Specs	1,800	SF	Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
139	12 x 12 VFT Black - (Abated)			Basement - Bldg 1890	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
140	12 x 12 VFT Black Mastic - (Abated)			Basement - Bldg 1890	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
141	Decorative Stucco	15,000	SF	Throughout Hackman Building	ASSUMED	SURFACE	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
142	12"x12" Gray w/ Black & Gray Specks VFT	2,500	SF	Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic	2,500	SF	Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143	9"x9" Off White w/ Black Streaks VFT	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
143M	9"x9" Off White w/ Black Streaks VFT Mastic	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room H122, Janitor's Closet H128 - Hackman Building 1930										
144	12"x12" Light Blue w/ Streaks VFT	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
144M	12"x12" Light Blue w/ Streaks VFT Mastic	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
145	1'x1' Ceiling Tile w/ Holes	4,500	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
145M	1'x1' Ceiling Tile w/ Holes Mastic	4,500	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
146	Decorative Plaster	1,900	SF	Auditorium - Hackman Building 1930	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
147	12"x12" Dark Gray w/ Black & Gray Specks VFT	3,500	SF	Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,500	SF	Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
148	Popcorn Plaster Ceiling	1,600	SF	Rooms 356 & 358 - Aquinas Building 1920	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
149	Green Carpet Mastic	350	SF	Room 152 - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151	Decorative Plaster	500	SF	1st Floor Corridor by Weight Room	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
152	12"x12" Black w/ White Specks VFT	100	SF	Basement Storage Room next to Laundry Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
152M	12"x12" Black w/ White Specks VFT Mastic	100	SF	Basement Storage Room next to Laundry Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	12"x12" Sand VFT	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153M	12"x12" Sand VFT Mastic	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
154	1'x1' White Ceiling Tile	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
154M	1'x1' White Ceiling Tile Mastic Pucks	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic	3,000	SF	Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,000	SF	Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	2'x4' Ceiling Tile	1,900	SF	1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
157	Terrazzo Flooring	1,500	SF	1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
158	Attic Plaster	5,600	SF	Attic - Longwood 1890 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
159	12"x12" Light Blue w/ Streaks VFT	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
159M	12"x12" Light Blue w/ Streaks VFT Mastic	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	MAG BLOCK COVERING - (Abated)			Boiler Room	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
160	12"x12" Dark Gray w/ Light Gray Specks VFT	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161	9"x9" Green w/ White Streaks VFT	1,300	SF	Room L209, Offices L105 & L104 (under carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161M	9"x9" Green w/ White Streaks VFT Mastic	1,300	SF	Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
162	Decorative Plaster	900	SF	Rooms L111, Office	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building								potential for damage		
163	Troweled-on Plaster Walls	2,500	SF	Basement Corridor, Classroom L006 - Longwood 1890 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
164	Spray-on Fireproofing	2,900	SF	Basement Small Lunchroom - Longwood 1890 Building	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
165	12"x12" White VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
165M	12"x12" White VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12"x12" Black w/ White Specks VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166M	12"x12" Black w/ White Specks VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	12"x12" Yellow Streaked VFT	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167M	12"x12" Yellow Streaked VFT Mastic	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1890 Building										
168	12"x12" Maroon Streaked VFT	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168M	12"x12" Maroon Streaked VFT Mastic	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	2'x2' Ceiling Tile w/ Pinholes	1,800	SF	Basement Corridors - Longwood 1890 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
17	HAND PACKING-ABATED			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
170	Pink Ceramic Tile Grout	800	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
171	Pink Ceramic Tile Adhesive	2,500	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	HOT WATER HOLDING TANK - (Abated)			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
19	HOT WATER HOLDING TANK - (Abated)			BOILER ROOM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
19A	WRAP OVER FIBER GLASS	120	LF	HOT WATER HOLDING TANK-BOILER ROOM TUNNEL	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	TANK HARD PACKING (Abated)			CONVENT BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
21	COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)			MAIN BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
22	CANVAS COVERED BLOCK TYPE DUCT - (Abated)			BOILER RM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
23	PIPE JOINTS - (Abated)	0		BOILER ROOM	ABATED	TSI	Y					Any remaining friable ACBM or friable suspect ACBM		
26	LIGHT CORDS	150	LF	AUDITORIUM - Hackman Building 1930	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	ACOUSTIC PLASTER	2,500	SF	CONVENT CHAPEL	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
30	1'x1' Ceiling Tile (with Pinholes & Grooves)	6,500	SF	Cafeteria L009, Hall by Door 31	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Ceiling Tile	6,500	SF	Cafeteria, L009, Hall by Door 31	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	2'x4' Lay In Ceiling Tile	5,000	SF	Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
33	12" x 12" Floor Tile Tan Mixed Speckled	10,580	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	9"x9" Floor Tile	37,796	SF	Ground Floor	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs								potential for damage		
35	PLASTER	1,495,000	SF	Throughout All Buildings	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Blue Carpet Adhesive	1,500	SF	Offices L105, L104, L132, L112 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Brown Carpet Adhesive	120	SF	Office L212	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Purple Carpet Adhesive - (Abated)			Music Room	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
39	Brown Striped Carpet Adhesive - (Abated)			Room 277	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
40	Purple Carpet Adhesive - (Abated)			Room 132	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
41	Terrazzo	12,000	SF	Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Ceramic Tile Grout	2,746	SF	Washrooms All Floors - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Ceramic Tile Adhesive	2,746	SF	Washrooms All Floors - 1890	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building Longwood										
44	Drywall	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Drywall Compound	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Tectum Ceiling Panels	5,457	SF	Gym - 1920 Building Aquinas	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	Chalkboard/Whiteboard Adhesive	7,200	SF	Classrooms Throughout Facility	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Vinyl Stair Treads	582	SF	Stairways - 1920 Building Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Vinyl Stair Thread Adhesive	582	SF	Stairways - 1920 Building Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	4" Black Baseboard	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	4" Black Baseboard Adhesive	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	6" Brown Baseboard (Abated)			Women's Ground Floor Washroom	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
53	6" Brown Basebord Adhesive (Abated)			Women's Ground Floor Washroom	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
54	4" Brown Baseboard	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	4" Brown Baseboard Adhesive	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	4" Grey Baseboard (Abated)			Room 351	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
57	4" Gray Baseboard Adhesive (Abated)			Room 351	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
58	4" x 4" Floor Tile	25	SF	Elevator in Aquinas 1920 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	4" x 4" Floor Tile Mastic	25	SF	Elevator in Aquinas 1920 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	Grey and Black Carpet Adhesive	2,156	SF	Auditorium - Hackman Building 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	Acoustical Ceiling Plaster	1,725	SF	Auditorium - Hackman Building 1930	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
62	Pegboard on Walls	1,960	SF	Teacher's Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	1 x 1 CT White (Removed)			Rm 126, Bldg 1950-Notre Dame	ABATED	MISC	Y					Any remaining friable ACBM or friable suspect ACBM		
64	1 x 1 White w/ Gooves Spline Ceiling Tile	4,000	SF	Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
65	12 x 12 VFT Tan Mixed Speckled (Abated)			Rm 126 Bldg 1950 Notre Dame	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
66	12 x 12 VFT Tan Mixed Speckled Mastic (Abated)		SF	Rm 126 Bldg 1950 Notre Dame	ABATED	MISC	N				No	Any remaining friable ACBM or friable suspect ACBM		LOW
67	9 x 9 VFT Gray w/ streaks VFT	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dome	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	9 x 9 VFT Gray w/ Streaks Mastic	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	9 x 9 VFT Green (Abated)			Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
70	9 x 9 VFT Green Mastic (Abated)	0		Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
71	Plaster	10,000	SF	Throughout Bldg 1950 Notre Dame	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
72	12 x 12 VFT Gray w/ Balck & White Specks	500	SF	Stairway Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12 x 12 VFT Gray w/ Black & White Specs Mastic	500	SF	Stairway Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
74	9 x 9 VFT Tan (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)	1,200	SF	Rooms E301 & E302 - Bldg. 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E301 and E302 - Bldg 1955 Edison	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Gray Linoleum (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Gray Linoleum Mastic (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)	2,000	SF	Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)	2,000	SF	Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	Plaster	14,000	SF	Throughout Bldg 1930 Hackman	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
86	12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420

Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Hackman Bldg.										
87	2 x 4 CT White w/ Swirls	1,300	SF	Rooms H303 and H304 - Bldg 1930 Hackman	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
88	12 x 12 Black VFT (Terrazzo Like)	7,800	SF	1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12 x 12 Black VFT & Mastic (Terrazzo Like)	7,800	SF	1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	9 x 9 VFT Lt. Brown w/ Specs	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	9 x 9 VFT Lt Brown w/ Specs Mastic	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)			Rm HH-1 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
93	12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)			Rm HH-1 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
94	12 x 12 VFT Gray w/ white & Black Specs (Abated)			HH - 13 Bldg 1930	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		
95	12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)		SF	HH - 13 Bldg 1930	ABATED	MISC	N	NONE			No			
96	12 x 12 VFT Mixed Red Speckled	500	SF	Rm 362 - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12 x 12 VFT Mixed Red Speckled Mastic	500	SF	Rm 362 - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	1'x1' CT White w/ Holes	2,600	SF	Throughout 1920 Bldg Aquinas	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
99	Terrazzo	6,500	SF	Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MM1	9" x 9" Floor Tile Mastic	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs										
MM2	12" x 12" Floor Tile Mastic			Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms	ABATED	MISC	N					Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Chicago International Charter - Longwood (South) Unit 66061 Building ID 2420  
Address 1309 W.95th St (9500S) 43 Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612  
Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>8/5/2019</b>
Inspector Name <b>Roberto Rivera</b>
<b>100-06327</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
05	
07	
08	
09	
10	
100	Bldg 1920 = "Aquinas Bldg"
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
142M	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
143	
143M	
144	
144M	
145	
145M	
146	
147	
147M	
148	
149	
150	
150M	
151	
152	
152M	
153	
153M	
154	
154M	
155	
155M	
156	
157	
158	
159	
159M	
16	
160	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
160M	
161	
161M	
162	
163	
164	
165	
165M	
166	
166M	
167	
167M	
168	
168M	
169	
17	
170	
171	
18	
19	
19A	
20	
21	
22	
23	
26	
29	
30	
30M	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South) **Unit** 66061 **Building ID** 2420

**Address** 1309 W.95th St (9500S) 43 **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
MM1	
MM2	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)  
**Unit** 66061  
**Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43 Chicago, IL, 60643  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612  
 Phone: 3123197575 Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Aircell Pipe Insulation	701	LF	Incinerator Room , Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05	Preform Pipe Cover (Mag Block Pipe Insulation)	367	LF	Incinerator Room, Tunnel, Main Shop Room, Electric Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Cardboard Pipe Cover	49	LF	Kitchen and Maintenance Closet	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
08	Aircell Pipe Joint Packing	67	LF	Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Preformed Pipe Joint Insulation	44	LF	Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
10	Joint packing on Fiberglass Insulated Piping	30	EA	Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
100	9 x 9 VFT Black w/ Camouflouge (under HA# 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	9 x 9 VFT Brown (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	9 x 9 VFT Brown Mastic (under HA 106 & 107)	400	SF	Rm 358 (A305) Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	9 x 9 Brown VFT (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	9 x 9 Brown VFT & Mastic (under HA 106 & 107)	1,400	SF	Rm 356 and 354 Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	12 x 12 Gray VFT Speckled	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12 x 12 Gray VFT Speckled Mastic	3,700	SF	Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
108	12 x 12 Gray w/ Red, White & Blue Specs VFT	800	SF	Stairwell Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12 x 12 Gray w/ Red, White and Blue Specs Mastic	800	SF	Stairwell Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Plaster	28,000	SF	Throughout Bldg 1920	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12 x 12 VFT Beige w/ Black Streaks - (Abated)			Rm 255 Bldg 1920	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
112	12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)	0		Rm 255 Bldg 1920	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
113	1 x 1 Ceiling Tile white w/ Swirls	2,100	SF	Weight Room and Rm 51 Bldg 1920	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Green Terrazzo	600	SF	Rm 51 Bldg 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Spray On Fireproofing	2,300	SF	Attic Bldg 1890	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	Terrazzo	8,000	SF	Throughout Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12 x 12 VFT Gray Speckled	1,200	SF	Rm 114 and 314 Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12 x 12 VFT Gray Speckled Mastic	1,200	SF	Rm 114 and 314 Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
119	1 x 1 CT White w/ Pinhole	29,000	SF	L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Stack Insulation			Incinerator Rm	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
120	9 x9 VFT White w/ gray strks	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	9 x 9 VFT White w/ gray strks Mastic	1,400	SF	Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across From Mechanical Room 018 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)     
**Unit** 66061     
**Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43     
Chicago, IL, 60643     
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
122	9 x 9 VFT Black	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
123	9 x 9 VFT Black Mastic	1,900	SF	Rooms L303, L306A, L306B, L216 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	9 x 9 VFT Pink w/ Black Strks	900	SF	Rooms L307, L317, L221 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	9 x 9 VFT Pink w/ Black Strks Mastic	900	SF	Rooms L307, L317, L221 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	9 x 9 VFT Dark Gray w/ white strks	600	SF	Rooms L307, L318, L317, 205 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
127	9 x 9 VFT Dark Gray w/ white strks Mastic	600	SF	Rooms L307, L318, L317, 205 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
128	9 x 9 VFT Dark Pink w/ strks	600	SF	Rooms L318, 205 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
129	9 x 9 VFT Dark Pink w/ strks Mastic	600	SF	Rooms L318, 205 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	KEWANEE BOILER COVER - (Abated)	0		MAIN BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
130	12 x 12 VFT Beige Mixed Speckled	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12 x 12 VFT Beige Mixed Speckled Mastic	2,600	SF	Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
132	9 x 9 VFT Brown	500	SF	Room L209 - Bldg. 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
133	9 x 9 VFT Brown Mastic	500	SF	Room L209 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
134	Plaster	25,000	SF	Throughout Bldg 1890	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12 x 12 VFT Purple Speckled	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
136	12 x 12 VFT Purple Speckled Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
137	12 x 12 VFT Tan w/ Lt Brown Specs	1,800	SF	Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)     
**Unit** 66061     
**Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43     
Chicago, IL, 60643     
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575      Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
138	12 x 12 VFT Tan w/ Light Brown Specs Mastic	1,800	SF	Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12 x 12 VFT Black - (Abated)			Basement - Bldg 1890	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
140	12 x 12 VFT Black Mastic - (Abated)			Basement - Bldg 1890	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
141	Decorative Stucco	15,000	SF	Throughout Hackman Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142	12"x12" Gray w/ Black & Gray Specks VFT	2,500	SF	Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
142M	12"x12" Gray w/ Black & Gray Specks VFT Mastic	2,500	SF	Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143	9"x9" Off White w/ Black Streaks VFT	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
143M	9"x9" Off White w/ Black Streaks VFT Mastic	120	SF	Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144	12"x12" Light Blue w/ Streaks VFT	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
144M	12"x12" Light Blue w/ Streaks VFT Mastic	600	SF	2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145	1'x1' Ceiling Tile w/ Holes	4,500	SF	Auditorium - Hackman Building 1930	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
145M	1'x1' Ceiling Tile w/ Holes Mastic	4,500	SF	Auditorium - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
146	Decorative Plaster	1,900	SF	Auditorium - Hackman Building 1930	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
147	12"x12" Dark Gray w/ Black & Gray Specks VFT	3,500	SF	Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
147M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,500	SF	Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
148	Popcorn Plaster Ceiling	1,600	SF	Rooms 356 & 358 - Aquinas Building 1920	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
149	Green Carpet Mastic	350	SF	Room 152 - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150	12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150M	12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic	2,200	SF	Weight Room (Under Rubber Mats) - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	Decorative Plaster	500	SF	1st Floor Corridor by Weight Room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12"x12" Black w/ White Specks VFT	100	SF	Basement Storage Room next to Laundry Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152M	12"x12" Black w/ White Specks VFT Mastic	100	SF	Basement Storage Room next to Laundry Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12"x12" Sand VFT	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153M	12"x12" Sand VFT Mastic	2,100	SF	Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154	1'x1' White Ceiling Tile	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
154M	1'x1' White Ceiling Tile Mastic Pucks	1,200	SF	3rd Floor Corridors - Aquinas Building 1920	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic	3,000	SF	Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155M	12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic	3,000	SF	Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)     
**Unit** 66061     
**Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43     
Chicago, IL, 60643     
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575      Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
156	2'x4' Ceiling Tile	1,900	SF	1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	Terrazzo Flooring	1,500	SF	1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	Attic Plaster	5,600	SF	Attic - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	12"x12" Light Blue w/ Streaks VFT	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159M	12"x12" Light Blue w/ Streaks VFT Mastic	4,500	SF	Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	MAG BLOCK COVERING - (Abated)			Boiler Room	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
160	12"x12" Dark Gray w/ Light Gray Specks VFT	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160M	12"x12" Dark Gray w/ Light Gray Specks VFT Mastic	1,900	SF	Rooms L302A, L302B, L304, L111 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	9"x9" Green w/ White Streaks VFT	1,300	SF	Room L209, Offices L105 & L104 (under carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161M	9"x9" Green w/ White Streaks VFT Mastic	1,300	SF	Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	Decorative Plaster	900	SF	Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	Troweled-on Plaster Walls	2,500	SF	Basement Corridor, Classroom L006 - Longwood 1890 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	Spray-on Fireproofing	2,900	SF	Basement Small Lunchroom - Longwood 1890 Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
165	12"x12" White VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165M	12"X12" White VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	12"x12" Black w/ White Specks VFT	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166M	12"x12" Black w/ White Specks VFT Mastic	420	SF	Basement Classroom by LULA Elevator - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167	12"x12" Yellow Streaked VFT	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167M	12"x12" Yellow Streaked VFT Mastic	2,500	SF	Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168	12"x12" Maroon Streaked VFT	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168M	12"x12" Maroon Streaked VFT Mastic	1,900	SF	Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	2'x2' Ceiling Tile w/ Pinholes	1,800	SF	Basement Corridors - Longwood 1890 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	HAND PACKING-ABATED			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
170	Pink Ceramic Tile Grout	800	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
171	Pink Ceramic Tile Adhesive	2,500	SF	Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood -	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan



# Chicago Public Schools

School Chicago International  
Charter - Longwood  
(South)  
Address 1309 W.95th St (9500S) 43

Unit 66061  
Chicago, IL, 60643

Building ID 2420  
Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1890 Building							
18	HOT WATER HOLDING TANK - (Abated)			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
19	HOT WATER HOLDING TANK - (Abated)			BOILER ROOM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
19A	WRAP OVER FIBER GLASS	120	LF	HOT WATER HOLDING TANK- BOILER ROOM TUNNEL	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	TANK HARD PACKING (Abated)			CONVENT BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
21	COVERED VENT SUPPLYING COMBUSTION AIR - (Abated)			MAIN BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
22	CANVAS COVERED BLOCK TYPE DUCT - (Abated)			BOILER RM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
23	PIPE JOINTS - (Abated)	0		BOILER ROOM	Abated	TSI	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
26	LIGHT CORDS	150	LF	AUDITORIUM - Hackman Building 1930	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
29	ACOUSTIC PLASTER	2,500	SF	CONVENT CHAPEL	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	1'x1' Ceiling Tile (with Pinholes & Grooves)	6,500	SF	Cafeteria L009, Hall by Door 31	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30M	Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Ceiling Tile	6,500	SF	Cafeteria, L009, Hall by Door 31	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	2'x4' Lay In Ceiling Tile	5,000	SF	Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Floor Tile Tan Mixed Speckled	10,580	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	9"x9" Floor Tile	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)      **Unit** 66061      **Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43      Chicago, IL, 60643      **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575      Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs							
35	PLASTER	1,495,000	SF	Throughout All Buildings	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Blue Carpet Adhesive	1,500	SF	Offices L105, L104, L132, L112 - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Brown Carpet Adhesive	120	SF	Office L212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Purple Carpet Adhesive - (Abated)			Music Room	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
39	Brown Striped Carpet Adhesive - (Abated)			Room 277	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
40	Purple Carpet Adhesive - (Abated)			Room 132	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
41	Terrazzo	12,000	SF	Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Ceramic Tile Grout	2,746	SF	Washrooms All Floors - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Ceramic Tile Adhesive	2,746	SF	Washrooms All Floors - 1890 Building Longwood	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Drywall	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Drywall Compound	1,350	SF	Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Tectum Ceiling Panels	5,457	SF	Gym - 1920 Building Aquinas	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Chalkboard/Whiteboard Adhesive	7,200	SF	Classrooms Throughout Facility	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Vinyl Stair Treads	582	SF	Stairways - 1920 Building Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Vinyl Stair Thread Adhesive	582	SF	Stairways - 1920 Building Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
50	4" Black Baseboard	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
51	4" Black Baseboard Adhesive	701	LF	West Lunchroom, 051, 054, 281 - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	6" Brown Baseboard (Abated)			Women's Ground Floor Washroom	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
53	6" Brown Baseboard Adhesive (Abated)			Women's Ground Floor Washroom	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
54	4" Brown Baseboard	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
55	4" Brown Baseboard Adhesive	316	LF	Ground Floor Security Office and East Cafeteria - 1890 Building Longwood	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
56	4" Grey Baseboard (Abated)			Room 351	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
57	4" Gray Baseboard Adhesive (Abated)			Room 351	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
58	4" x 4" Floor Tile	25	SF	Elevator in Aquinas 1920 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	4" x 4" Floor Tile Mastic	25	SF	Elevator in Aquinas 1920 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Grey and Black Carpet Adhesive	2,156	SF	Auditorium - Hackman Building 1930	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Acoustical Ceiling Plaster	1,725	SF	Auditorium - Hackman Building 1930	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Pegboard on Walls	1,960	SF	Teacher's Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	1 x 1 CT White (Removed)			Rm 126, Bldg 1950- Notre Dame	Abated	MISC	Yes			7 Any remaining friable ACBM or friable suspect ACBM	
64	1 x 1 White w/ Gooves Spline Ceiling Tile	4,000	SF	Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12 x 12 VFT Tan Mixed Speckled (Abated)			Rm 126 Bldg 1950 Notre Dame	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
66	12 x 12 VFT Tan Mixed Speckled Mastic (Abated)		SF	Rm 126 Bldg 1950 Notre Dame	Abated	MISC	No		SF	7 Any remaining friable ACBM or friable suspect ACBM	
67	9 x 9 VFT Gray w/ streaks VFT	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dome	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
68	9 x 9 VFT Gray w/ Streaks Mastic	600	SF	Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	9 x 9 VFT Green (Abated)			Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
70	9 x 9 VFT Green Mastic (Abated)	0		Rm 128, 130, 144, 146 Bldg 1950 Notre Dame	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
71	Plaster	10,000	SF	Throughout Bldg 1950 Notre Dame	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12 x 12 VFT Gray w/ Balck & White Specks	500	SF	Stairway Bldg 1955 Eddison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12 x 12 VFT Gray w/ Black & White Specs Mastic	500	SF	Stairway Bldg 1955 Eddison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	9 x 9 VFT Tan (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	9 x 9 VFT Tan Mastic (Under HA 147 & 147M)	100	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E201 and E202 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)	1,200	SF	Rooms E301 & E302 - Bldg. 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)	1,200	SF	Rooms E301 and E302 - Bldg 1955 Edison	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Gray Linoleum (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Gray Linoleum Mastic (Under HA 147 & 147M)	60	SF	Rm 330 Closet Bldg 1955 (Edison)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)	2,000	SF	Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)	2,000	SF	Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Plaster	14,000	SF	Throughout Bldg 1930 Hackman	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12 x 12 VFT Beige w/ White Specs (Terrazzo Like)	17,000	SF	1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12 x 12 VFT Beige w/ white Specs Mastic	17,000	SF	1st and 2nd Floor Corridor, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Chicago International  
Charter - Longwood  
(South)  
Address 1309 W.95th St (9500S) 43

Unit 66061  
Chicago, IL, 60643

Building ID 2420  
Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	(Terrazzo Like)			and Stairs and 23H 1930 Hackman Bldg.							
87	2 x 4 CT White w/ Swirls	1,300	SF	Rooms H303 and H304 - Bldg 1930 Hackman	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12 x 12 Black VFT (Terrazzo Like)	7,800	SF	1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12 x 12 Black VFT & Mastic (Terrazzo Like)	7,800	SF	1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	9 x 9 VFT Lt. Brown w/ Specs	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	9 x 9 VFT Lt Brown w/ Specs Mastic	350	SF	Rooms H212, 215, H122 - Bldg 1930 Hackman	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)			Rm HH-1 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
93	12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)			Rm HH-1 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
94	12 x 12 VFT Gray w/ white & Black Specs (Abated)			HH - 13 Bldg 1930	Abated	MISC	No			7 Any remaining friable ACBM or friable suspect ACBM	
95	12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)		SF	HH - 13 Bldg 1930	Abated	MISC	No		SF		
96	12 x 12 VFT Mixed Red Speckled	500	SF	Rm 362 - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12 x 12 VFT Mixed Red Speckled Mastic	500	SF	Rm 362 - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	1'x1' CT White w/ Holes	2,600	SF	Throughout 1920 Bldg Aquinas	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Terrazzo	6,500	SF	Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
MM1	9" x 9" Floor Tile Mastic	37,796	SF	Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
MM2	12" x 12" Floor Tile Mastic			Classrooms, Teachers Lounge, W	Abated	MISC	No			7 Any remaining friable ACBM or friable	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)     
 **Unit** 66061     
 **Building ID** 2420  
**Address** 1309 W.95th St (9500S) 43     
 Chicago, IL, 60643     
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575      Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms						suspect ACBM	

# Chicago Public Schools

**School** Chicago International Charter - Longwood (South)  
**Address** 1309 W.95th St (9500S) 43  
**Unit** 66061  
 Chicago, IL, 60643  
**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	09/24/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
05	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
117	
118	
119	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
13	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	



# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
140	
141	
142	
142M	
143	
143M	
144	
144M	
145	
145M	
146	
147	
147M	
148	
149	
150	
150M	
151	
152	
152M	
153	
153M	
154	
154M	
155	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
155M	
156	
157	
158	
159	
159M	
16	
160	
160M	
161	
161M	
162	
163	
164	
165	
165M	
166	
166M	
167	
167M	
168	
168M	
169	
17	
170	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
171	
18	
19	
19A	
20	
21	
22	
23	
26	
29	
30	
30M	
31	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	

# Chicago Public Schools

**School** Chicago International  
Charter - Longwood  
(South)  
**Address** 1309 W.95th St (9500S) 43

**Unit** 66061  
Chicago, IL, 60643

**Building ID** 2420  
**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
95	
96	
97	
98	
99	
MM1	
MM2	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACM**  
HISTORICAL DAMAGE REASON: **See Comments**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Incinerator Room , Closet by Main Shop, Kitchen, Men's Washrrom Closet, 101-201-301 Janitor Closets, Aquinus Ground Floor Corridor, Tunnel leading to Convent, Weight Room & Attic Bldg 1890**  
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Preform Pipe Cover (Mag Block Pipe Insulation)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Incinerator Room, Tunnel, Main Shop Room, Electric Room**

MATERIAL QUANTITY: **367** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **Preform Pipe Cover (Mag Block Pipe Insulation)**  
MATERIAL LOCATION: **Incinerator Room, Tunnel, Main Shop Room, Electric Room**  
MATERIAL QUANTITY: **367** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Cardboard Pipe Cover**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **See Comments**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Kitchen and Maintenance Closet**  
MATERIAL QUANTITY: **49** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Cardboard Pipe Cover**  
MATERIAL LOCATION: **Kitchen and Maintenance Closet**  
MATERIAL QUANTITY: **49** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Packing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890**

MATERIAL QUANTITY: **67** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Packing**  
MATERIAL LOCATION: **Tunnels and Corridors, Incinerator Room, Closet by Main Shop, Kitchen, Men's Washroom Closet, 101-201-301 Janitor Closets, Weight Room & Attic Bldg 1890**  
MATERIAL QUANTITY: **67** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor**

MATERIAL QUANTITY: **44** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Preformed Pipe Joint Insulation**  
MATERIAL LOCATION: **Incinerator Room, Main Shop Room, Tunnel, Electrical Room, Ground Floor Corridor**  
MATERIAL QUANTITY: **44** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Joint packing on Fiberglass Insulated Piping**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **Joint packing on Fiberglass Insulated Piping**  
MATERIAL LOCATION: **Incinerator Rm, Tunnel, Basement Sink Room, Pantry and East Lunchroom**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camoflounge (under HA# 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS: **Bldg 1920 = "Aquinas Bldg"**

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camoflouge (under HA# 106 & 107)**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black w/ Camouflouge Mastic (under HA 106 & 107)**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown (under HA 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown (under HA 106 & 107)**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic (under HA 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic (under HA 106 & 107)**  
MATERIAL LOCATION: **Rm 358 (A305) Bldg. 1920**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **9 x 9 Brown VFT (under HA 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 356 and 354 Bldg. 1920**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **9 x 9 Brown VFT (under HA 106 & 107)**  
MATERIAL LOCATION: **Rm 356 and 354 Bldg. 1920**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **9 x 9 Brown VFT & Mastic (under HA 106 & 107)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 356 and 354 Bldg 1920**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **9 x 9 Brown VFT & Mastic (under HA 106 & 107)**  
MATERIAL LOCATION: **Rm 356 and 354 Bldg 1920**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920**

MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled**  
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 251, 250, Basement Laundry RM. Bldg 1920**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920**

MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12 x 12 Gray VFT Speckled Mastic**  
MATERIAL LOCATION: **Rooms 358, 356, 350, 351, 352, 257, 255, 254, 253, 252, 252, 250, Basement Laundry Rm. Bldg. 1920**  
MATERIAL QUANTITY: **3700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White & Blue Specs VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairwell Bldg 1920**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White & Blue Specs VFT**  
MATERIAL LOCATION: **Stairwell Bldg 1920**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White and Blue Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairwell Bldg 1920**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **12 x 12 Gray w/ Red, White and Blue Specs Mastic**  
MATERIAL LOCATION: **Stairwell Bldg 1920**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bldg 1920**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Bldg 1920**  
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks - (Abated)**  
MATERIAL LOCATION: **Rm 255 Bldg 1920**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 255 Bldg 1920**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ Black Streaks Mastic - (Abated)**  
MATERIAL LOCATION: **Rm 255 Bldg 1920**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile white w/ Swirls**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Weight Room and Rm 51 Bldg 1920**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **1 x 1 Ceiling Tile white w/ Swirls**  
MATERIAL LOCATION: **Weight Room and Rm 51 Bldg 1920**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Green Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 51 Bldg 1920**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Green Terrazzo**  
MATERIAL LOCATION: **Rm 51 Bldg 1920**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Spray On Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic Bldg 1890**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **Spray On Fireproofing**  
MATERIAL LOCATION: **Attic Bldg 1890**  
MATERIAL QUANTITY: **2300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bldg 1890**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Throughout Bldg 1890**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled**  
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray Speckled Mastic**  
MATERIAL LOCATION: **Rm 114 and 314 Bldg 1890**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **1 x 1 CT White w/ Pinhole**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031**

MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **1 x 1 CT White w/ Pinhole**

MATERIAL LOCATION: **L304, L302B, L306A, L306B, L302A, L307, L318, L317, L308, L313, 3rd Floor Corridor, L216, 201, L210, L209, L202, L221, L208, L207, L206, L204, 2nd Floor Corridor, L108, L107, Office L105, Office L104, L126, L121, 1st Floor Corridor, Basement Classroom by LULA Elevator, Book Storage L008, Fire Pump Room L031**

MATERIAL QUANTITY: **29000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Stack Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Incinerator Rm**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **12**  
MATERIAL DESCRIPTION: **Stack Insulation**  
MATERIAL LOCATION: **Incinerator Rm**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **9 x9 VFT White w/ gray strks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **9 x9 VFT White w/ gray strks**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across from Mechanical Room L018 - Bldg 1890**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **9 x 9 VFT White w/ gray strks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across From Mechanical Room 018 - Bldg 1890**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **9 x 9 VFT White w/ gray strks Mastic**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L309, Electrical L311, L216, L117, Basement Room Across From Mechanical Room 018 - Bldg 1890**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **9 x 9 VFT Black Mastic**  
MATERIAL LOCATION: **Rooms L303, L306A, L306B, L216 - Bldg. 1890**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks**  
MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **9 x 9 VFT Pink w/ Black Strks Mastic**  
MATERIAL LOCATION: **Rooms L307, L317, L221 - Bldg 1890**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg. 1890**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks**  
MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg. 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg 1890**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **127**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Gray w/ white strks Mastic**  
MATERIAL LOCATION: **Rooms L307, L318, L317, 205 - Bldg 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **128**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks**  
MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **129**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Pink w/ strks Mastic**  
MATERIAL LOCATION: **Rooms L318, 205 - Bldg 1890**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **KEWANEE BOILER COVER - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **KEWANEE BOILER COVER - (Abated)**  
MATERIAL LOCATION: **MAIN BOILER RM**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **130**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled**  
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **131**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige Mixed Speckled Mastic**  
MATERIAL LOCATION: **Rooms L213, L202, L107, L125, Teacher's Lounge L113, Copy Room L115 - Bldg 1890**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room L209 - Bldg. 1890**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **132**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown**  
MATERIAL LOCATION: **Room L209 - Bldg. 1890**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room L209 - Bldg 1890**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **133**  
MATERIAL DESCRIPTION: **9 x 9 VFT Brown Mastic**  
MATERIAL LOCATION: **Room L209 - Bldg 1890**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bldg 1890**  
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **134**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Bldg 1890**  
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **135**  
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled**  
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule by Door 31 - Bldg 1890**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Speckled Mastic**  
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Basement Women's Toilet Vestibule near Door 31 - Bldg 1890**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Lt Brown Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Lt Brown Specs**  
MATERIAL LOCATION: **Cafeteria L009, Basement by Door 31, Basement Women's Toilet Vestibule near Door 31 - 1890**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Light Brown Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Light Brown Specs Mastic**  
MATERIAL LOCATION: **Cafeteria L009, Basement Hall by Door 31, Women's Toilet Vestibule near Door 31 - Bldg 1890**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12 x 12 VFT Black - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12 x 12 VFT Black - (Abated)**  
MATERIAL LOCATION: **Basement - Bldg 1890**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12 x 12 VFT Black Mastic - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Bldg 1890**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **140**  
MATERIAL DESCRIPTION: **12 x 12 VFT Black Mastic - (Abated)**  
MATERIAL LOCATION: **Basement - Bldg 1890**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Decorative Stucco**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Hackman Building**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **141**  
MATERIAL DESCRIPTION: **Decorative Stucco**  
MATERIAL LOCATION: **Throughout Hackman Building**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **MAG BLOCK COVERING - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **MAG BLOCK COVERING - (Abated)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **HAND PACKING-ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **HAND PACKING-ABATED**  
MATERIAL LOCATION: **BOILER RM**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**  
MATERIAL LOCATION: **BOILER RM**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **HOT WATER HOLDING TANK - (Abated)**  
MATERIAL LOCATION: **BOILER ROOM**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **WRAP OVER FIBER GLASS**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **HOT WATER HOLDING TANK-BOILER ROOM TUNNEL**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **WRAP OVER FIBER GLASS**  
MATERIAL LOCATION: **HOT WATER HOLDING TANK-BOILER ROOM TUNNEL**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **TANK HARD PACKING (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **CONVENT BOILER RM**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **TANK HARD PACKING (Abated)**  
MATERIAL LOCATION: **CONVENT BOILER RM**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MAIN BOILER RM**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **COVERED VENT SUPPLYNG COMBUSTION AIR - (Abated)**  
MATERIAL LOCATION: **MAIN BOILER RM**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **CANVAS COVERED BLOCK TYPE DUCT - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **CANVAS COVERED BLOCK TYPE DUCT - (Abated)**

MATERIAL LOCATION: **BOILER RM**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **PIPE JOINTS - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **BOILER ROOM**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **PIPE JOINTS - (Abated)**  
MATERIAL LOCATION: **BOILER ROOM**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **LIGHT CORDS**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **AUDITORIUM - Hackman Building 1930**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **LIGHT CORDS**  
MATERIAL LOCATION: **AUDITORIUM - Hackman Building 1930**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **ACOUSTIC PLASTER**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **CONVENT CHAPEL**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **ACOUSTIC PLASTER**  
MATERIAL LOCATION: **CONVENT CHAPEL**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (with Pinholes & Grooves)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Cafeteria L009, Hall by Door 31**

MATERIAL QUANTITY: **6500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile (with Pinholes & Grooves)**  
MATERIAL LOCATION: **Cafeteria L009, Hall by Door 31**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Celing Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria, L009, Hall by Door 31**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **30M**  
MATERIAL DESCRIPTION: **Mastic Associated with 1' x 1' White w/ Pinholes and Grooves Celing Tile**  
MATERIAL LOCATION: **Cafeteria, L009, Hall by Door 31**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON: **Water**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**  
MATERIAL LOCATION: **Rooms 253, 251 250, 254, 255, 257, 356 - Aquinas Building**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan Mixed Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Water**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,**

MATERIAL QUANTITY: **10580** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Tan Mixed Speckled**  
MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, m, Washrooms, Classrooms, Corridors, Stairs,**  
MATERIAL QUANTITY: **10580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **9"x9" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **9"x9" Floor Tile**  
MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**  
MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **PLASTER**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout All Buildings**  
MATERIAL QUANTITY: **1495000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **PLASTER**  
MATERIAL LOCATION: **Throughout All Buildings**  
MATERIAL QUANTITY: **1495000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Offices L105, L104, L132, L112 - 1890 Building Longwood**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**  
MATERIAL LOCATION: **Offices L105, L104, L132, L112 - 1890 Building Longwood**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Office L212**

MATERIAL QUANTITY: **120**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Brown Carpet Adhesive**  
MATERIAL LOCATION: **Office L212**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Music Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**  
MATERIAL LOCATION: **Music Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Striped Carpet Adhesive - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 277**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Brown Striped Carpet Adhesive - (Abated)**  
MATERIAL LOCATION: **Room 277**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive - (Abated)**

MATERIAL LOCATION: **Room 132**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006**

MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwells, Basement Lunchroom, Book Storage 008, Fire Pump Room L031, Electrical Room L022, Kitchen Office L024, Kitchen Staff Toilet L029, Classroom L006**  
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**  
MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Ceramic Tile Grout**  
MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**  
MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**

MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Washrooms All Floors - 1890 Building Longwood**  
MATERIAL QUANTITY: **2746** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **Throughout Facility Including: Ground Floor Pantry, Corridor by Rooms 402-404, Room 281**  
MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Tectum Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym - 1920 Building Aquinas**

MATERIAL QUANTITY: **5457**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Tectum Ceiling Panels**  
MATERIAL LOCATION: **Gym - 1920 Building Aquinas**  
MATERIAL QUANTITY: **5457** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Chalkboard/Whiteboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Classrooms Throughout Facility**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Chalkboard/Whiteboard Adhesive**  
MATERIAL LOCATION: **Classrooms Throughout Facility**  
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Vinyl Stair Treads**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**

MATERIAL QUANTITY: **582**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Vinyl Stair Treads**  
MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**  
MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Vinyl Stair Thread Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**  
MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Vinyl Stair Thread Adhesive**  
MATERIAL LOCATION: **Stairways - 1920 Building Aquinas**  
MATERIAL QUANTITY: **582** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **4" Black Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**  
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **4" Black Baseboard**  
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**  
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **4" Black Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**  
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **4" Black Baseboard Adhesive**  
MATERIAL LOCATION: **West Lunchroom, 051, 054, 281 - 1890 Building Longwood**  
MATERIAL QUANTITY: **701** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **6" Brown Baseboard (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **6" Brown Baseboard (Abated)**  
MATERIAL LOCATION: **Women's Ground Floor Washroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **6" Brown Basebord Adhesive (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Women's Ground Floor Washroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **6" Brown Basebord Adhesive (Abated)**  
MATERIAL LOCATION: **Women's Ground Floor Washroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**  
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **4" Brown Baseboard**  
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**  
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**  
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **4" Brown Baseboard Adhesive**  
MATERIAL LOCATION: **Ground Floor Security Office and East Cafeteria - 1890 Building Longwood**  
MATERIAL QUANTITY: **316** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **4" Grey Baseboard (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **4" Grey Baseboard (Abated)**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **4" Gray Baseboard Adhesive (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 351**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **4" Gray Baseboard Adhesive (Abated)**  
MATERIAL LOCATION: **Room 351**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **4" x 4" Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator in Aquinas 1920 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **4" x 4" Floor Tile**  
MATERIAL LOCATION: **Elevator in Aquinas 1920 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **4" x 4" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Elevator in Aquinus 1920 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **4" x 4" Floor Tile Mastic**  
MATERIAL LOCATION: **Elevator in Aquinus 1920 Building**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Grey and Black Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Auditorium - Hackman Building 1930**

MATERIAL QUANTITY: **2156**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Grey and Black Carpet Adhesive**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **2156** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **1725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Acoustical Ceiling Plaster**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **1725** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Pegboard on Walls**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teacher's Lounge**  
MATERIAL QUANTITY: **1960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Pegboard on Walls**  
MATERIAL LOCATION: **Teacher's Lounge**  
MATERIAL QUANTITY: **1960** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **1 x 1 CT White (Removed)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 126, Bldg 1950- Notre Dame**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **1 x 1 CT White (Removed)**  
MATERIAL LOCATION: **Rm 126, Bldg 1950- Notre Dame**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **1 x 1 White w/ Gooves Spline Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **1 x 1 White w/ Gooves Spline Ceiling Tile**  
MATERIAL LOCATION: **Rooms 148, ND 114 (146), ND 113, ND 106, ND 122, ND 125, ND 104, ND 103 - 1950 Building Notre Dame**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Abated)**  
MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Abated)**  
MATERIAL LOCATION: **Rm 126 Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dome**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ streaks VFT**  
MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dome**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ Streaks Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **9 x 9 VFT Gray w/ Streaks Mastic**  
MATERIAL LOCATION: **Rooms 146, 140, 138, 129 - Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9 x 9 VFT Green (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9 x 9 VFT Green (Abated)**  
MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9 x 9 VFT Green Mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **9 x 9 VFT Green Mastic (Abated)**  
MATERIAL LOCATION: **Rm 128, 130, 144, 146 Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Bldg 1950 Notre Dame**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Balck & White Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Balck & White Specks**  
MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Black & White Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ Black & White Specs Mastic**  
MATERIAL LOCATION: **Stairway Bldg 1955 Eddison**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **9 x 9 VFT Tan (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **9 x 9 VFT Tan (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **9 x 9 VFT Tan Mastic (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **9 x 9 VFT Tan Mastic (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **9 x9 VFT Dark Brown VFT (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **9 x 9 VFT Dark Brown Mastic (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E201 and E202 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms E301 & E302 - Bldg. 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E301 & E302 - Bldg. 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms E301 and E302 - Bldg 1955 Edison**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan w/ Brown Specs Mastic (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rooms E301 and E302 - Bldg 1955 Edison**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Gray Linoleum (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Gray Linoleum (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Gray Linoleum Mastic (Under HA 147 & 147M)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Gray Linoleum Mastic (Under HA 147 & 147M)**  
MATERIAL LOCATION: **Rm 330 Closet Bldg 1955 (Edison)**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled (Terrazzo Like)**  
MATERIAL LOCATION: **Rm 54, 56, 22 HH, 03 HH, Bldg 1930 Hackman**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled Mastic (Terrazzo Like)**  
MATERIAL LOCATION: **Rm 54, 56, 22HH, 03 HH, Bldg 1930 Hackman**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Bldg 1930 Hackman**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Plaster**  
MATERIAL LOCATION: **Throughout Bldg 1930 Hackman**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ White Specs (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ White Specs (Terrazzo Like)**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H - 1930 Hackman Bldg.**  
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.**  
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **12 x 12 VFT Beige w/ white Specs Mastic (Terrazzo Like)**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor, Auditorium and Stairs and 23H 1930 Hackman Bldg.**  
MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **2 x 4 CT White w/ Swirls**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms H303 and H304 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **2 x 4 CT White w/ Swirls**  
MATERIAL LOCATION: **Rooms H303 and H304 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman**  
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT (Terrazzo Like)**  
MATERIAL LOCATION: **1st and 2nd Flr Corridor and Auditorium Bldg 1930 Hackman**  
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT & Mastic (Terrazzo Like)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **12 x 12 Black VFT & Mastic (Terrazzo Like)**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor and Auditorium - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **7800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **9 x 9 VFT Lt. Brown w/ Specs**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **9 x 9 VFT Lt. Brown w/ Specs**  
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **9 x 9 VFT Lt Brown w/ Specs Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **9 x 9 VFT Lt Brown w/ Specs Mastic**  
MATERIAL LOCATION: **Rooms H212, 215, H122 - Bldg 1930 Hackman**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ Mixed Specs (Abated)**  
MATERIAL LOCATION: **Rm HH-1 Bldg 1930**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rm HH-1 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12 x 12 VFT Lt Brown w/ mixed specs Mastic (Abated)**  
MATERIAL LOCATION: **Rm HH-1 Bldg 1930**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ white & Black Specs (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12 x 12 VFT Gray w/ white & Black Specs (Abated)**  
MATERIAL LOCATION: **HH - 13 Bldg 1930**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **HH - 13 Bldg 1930**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **12 x12 VFT Gray w/ White & Black Specs Mastic (Abated)**  
MATERIAL LOCATION: **HH - 13 Bldg 1930**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled**  
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12 x 12 VFT Mixed Red Speckled Mastic**  
MATERIAL LOCATION: **Rm 362 - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **1'x1' CT White w/ Holes**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout 1920 Bldg Aquinas**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **1'x1' CT White w/ Holes**  
MATERIAL LOCATION: **Throughout 1920 Bldg Aquinas**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Rooms 363, 352, 350, 3rd Floor East Stairwell - Bldg 1920 Aquinas**  
MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM1**  
MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**

MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **MM1**  
MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**  
MATERIAL LOCATION: **Ground Floor Security Office, Corridor & Entrance, West Cafeteria, Teacher's Lounge, 100, 102, 103, 110, 114, 116, 124, 206, 208, 214, 314, 330, 331, 362, 052, 2, 053, Exits, Auditorium Entry & Foyer, Reading Room, Washrooms, 178, 282, Corridors, Stairs**  
MATERIAL QUANTITY: **37796** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM2**  
MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Abated** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

HOMOGENEOUS AREA: **MM2**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms, Teachers Lounge, W Cafeteria, Ground Floor Corridor & Entries, Auditorium Entrance & Foyer, Reading Room, Staff Washrooms, Corridors, and Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **12"x12" White VFT**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66061</b>	BUILDING ID:	<b>2420</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Chicago International Charter - Longwood (South)</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>1309 W.95th St (9500S) 43</b>	IDPH LICENSE NO:	<b>100-06327</b>		
HOMOGENEOUS AREA:	<b>165</b>				
MATERIAL DESCRIPTION:	<b>12"x12" White VFT</b>				
MATERIAL LOCATION:	<b>Basement Classroom by LULA Elevator - Longwood 1890 Building</b>				
MATERIAL QUANTITY:	<b>420</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12"X12" White VFT Mastic**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12"X12" White VFT Mastic**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT**  
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.**  
MATERIAL QUANTITY: **2500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT**  
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood - 1890 Bldg.**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **145M**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes Mastic**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **145M**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes Mastic**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **153M**

MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**

MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**

MATERIAL QUANTITY: **2100**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **153M**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT Mastic**  
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **Terrazzo Flooring**  
MATERIAL LOCATION: **1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **Terrazzo Flooring**  
MATERIAL LOCATION: **1st Floor Corridors, Stairs, Entry Vestibules 24 / 3, Toilets - Notre Dame Building 1950**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **159**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**

MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**

MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**  
MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **159M**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**

MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **159M**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**  
MATERIAL LOCATION: **Rooms L215 & Electrical Room L215, L210, L206, L108, L107, Office L118, L121, Entrance Vestibule by Door 29 - Longwood 1890 Building**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT**  
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT**  
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
MATERIAL LOCATION: **Basement Small Lunchroom - Longwood 1890 Building**  
MATERIAL QUANTITY: **2900**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **Spray-on Fireproofing**  
MATERIAL LOCATION: **Basement Small Lunchroom - Longwood 1890 Building**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUIDLING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC** FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW** CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE QUANTITY: **0** DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>66061</b>	BUILDING ID:	<b>2420</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Chicago International Charter - Longwood (South)</b>	REVIEW DATE:	<b>9/24/2019</b>		
ADDRESS:	<b>1309 W.95th St (9500S) 43</b>	IDPH LICENSE NO:	<b>100-06327</b>		
HOMOGENEOUS AREA:	<b>166</b>				
MATERIAL DESCRIPTION:	<b>12"x12" Black w/ White Specks VFT</b>				
MATERIAL LOCATION:	<b>Basement Classroom by LULA Elevator - Longwood 1890 Building</b>				
MATERIAL QUANTITY:	<b>420</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **Popcorn Plaster Ceiling**  
MATERIAL LOCATION: **Rooms 356 & 358 - Aquinas Building 1920**  
MATERIAL QUANTITY: **1600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **148**  
MATERIAL DESCRIPTION: **Popcorn Plaster Ceiling**  
MATERIAL LOCATION: **Rooms 356 & 358 - Aquinas Building 1920**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic**  
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**  
MATERIAL QUANTITY: **2200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT & Mastic**  
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **150M**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic**  
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**  
MATERIAL QUANTITY: **2200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **150M**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Dark & Light Streaks VFT Mastic**  
MATERIAL LOCATION: **Weight Room (Under Rubber Mats) - Aquinas Building 1920**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **1st Floor Corridor by Weight Room**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **1st Floor Corridor by Weight Room**  
MATERIAL QUANTITY: **500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/ Pinholes**  
MATERIAL LOCATION: **Basement Corridors - Longwood 1890 Building**  
MATERIAL QUANTITY: **1800**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **2'x2' Ceiling Tile w/ Pinholes**  
MATERIAL LOCATION: **Basement Corridors - Longwood 1890 Building**  
MATERIAL QUANTITY: **1800**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **4500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **145**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile w/ Holes**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **4500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT**  
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building  
1920**  
MATERIAL QUANTITY: **2100**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12"x12" Sand VFT**  
MATERIAL LOCATION: **Basement Classroom A003, A004, and outside Elevator in Basement - Aquinas Building 1920**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**  
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**  
MATERIAL QUANTITY: **1200**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **154**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile**  
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **154M**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile Mastic Pucks**  
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **154M**  
MATERIAL DESCRIPTION: **1'x1' White Ceiling Tile Mastic Pucks**  
MATERIAL LOCATION: **3rd Floor Corridors - Aquinas Building 1920**  
MATERIAL QUANTITY: **1200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **160M**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **160M**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Light Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms L302A, L302B, L304, L111 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **09/24/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **166M**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **166M**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT Mastic**  
MATERIAL LOCATION: **Basement Classroom by LULA Elevator - Longwood 1890 Building**  
MATERIAL QUANTITY: **420**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **171**

MATERIAL DESCRIPTION: **Pink Ceramic Tile Adhesive**

MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building**

MATERIAL QUANTITY: **2500**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **171**  
MATERIAL DESCRIPTION: **Pink Ceramic Tile Adhesive**  
MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room L025, Book Storage L008 - Longwood - 1890 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **143M**  
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building 1930**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **Troweled-on Plaster Walls**  
MATERIAL LOCATION: **Basement Corridor, Classroom L006 - Longwood 1890 Building**  
MATERIAL QUANTITY: **2500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **Troweled-on Plaster Walls**  
MATERIAL LOCATION: **Basement Corridor, Classroom L006 - Longwood 1890 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **170**

MATERIAL DESCRIPTION: **Pink Ceramic Tile Grout**

MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008  
- Longwood 1890 Building**

MATERIAL QUANTITY: **800**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **Pink Ceramic Tile Grout**  
MATERIAL LOCATION: **Basement Kitchen, Serving Room, Small Lunchroom, Dish Wash Room, Book Storage L008 - Longwood 1890 Building**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **142M**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT Mastic**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **142M**  
MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, Room H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **143**  
MATERIAL DESCRIPTION: **9"x9" Off White w/ Black Streaks VFT**  
MATERIAL LOCATION: **Janitor's Closet H233 & H231, Janitor's Closet near Room H122, Janitor's Closet H128 - Hackman Building - 1930**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **144M**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**

MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930**

MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **144M**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT Mastic**  
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building - 1930**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **146**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium - Hackman Building 1930**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT**  
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955**  
MATERIAL QUANTITY: **3500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **147**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT**  
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, E201, E202, Storage S203 - Edison Building 1955**  
MATERIAL QUANTITY: **3500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **147M**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955**  
MATERIAL QUANTITY: **3500**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **147M**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms E301, E302, Storage S303, Rooms E201, E202, Storage S203 - Edison Building 1955**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building  
1950**  
MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**  
MATERIAL LOCATION: **1st Floor Corridor, Entry Vestibule Doors 24 & 3, Rooms 140 and 138 - Notre Dame Building 1950**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Attic Plaster**  
MATERIAL LOCATION: **Attic - Longwood 1890 Building**  
MATERIAL QUANTITY: **5600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **Attic Plaster**  
MATERIAL LOCATION: **Attic - Longwood 1890 Building**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **161M**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building**  
MATERIAL QUANTITY: **1300**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **161M**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT Mastic**  
MATERIAL LOCATION: **Room L209, Office L105 & L104 (under the carpet) - Longwood 1890 Building**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **162**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **SURFACE** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Rooms L111, Office L112, Teacher's Lounge L113, Conference Room L110, Copy Room L115 - Longwood 1890 Building**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **168**

MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT**

MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034,  
Basement JC by Door 31 - Longwood 1890 Building**

MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT**  
MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Black & Gray Specks VFT**

MATERIAL LOCATION: **Rooms H303 & Entry Vestibule, H304 & Entry Vestibule, H217, H216, H214, Electrical Room next to Toilet H119, Room H117, and Room by Door 15 - Hackman Building 1930**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S) 43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic**  
MATERIAL LOCATION: **Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT & Mastic**  
MATERIAL LOCATION: **Rooms 148, ND 114, ND 1134, ND 106, ND 105, ND 104, ND 103 - Notre Dame Building 1950**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **167M**

MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT Mastic**

MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood  
1890 Building**

MATERIAL QUANTITY: **2500**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **167M**  
MATERIAL DESCRIPTION: **12"x12" Yellow Streaked VFT Mastic**  
MATERIAL LOCATION: **Basement Corridors, Hall by Room L006 and Hall by Mechanical Room L018 - Longwood 1890 Building**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **168M**

MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT Mastic**

MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034,  
Basement JC by Door 31 - Longwood 1890 Building**

MATERIAL QUANTITY: **1900**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 08/05/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **168M**  
MATERIAL DESCRIPTION: **12"x12" Maroon Streaked VFT Mastic**  
MATERIAL LOCATION: **Basement Corridors, Hall by Classroom L006, Hall by Mechanical Room L018, JC L034, Basement JC by Door 31 - Longwood 1890 Building**  
MATERIAL QUANTITY: **1900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Room 152 - Aquinas Building 1920**  
MATERIAL QUANTITY: **350**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **149**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **Room 152 - Aquinas Building 1920**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66061**    BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**    INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**    IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**  
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **12"x12" Black w/ White Specks VFT**  
MATERIAL LOCATION: **Basement Storage Room next to Laundry Room**  
MATERIAL QUANTITY: **100**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **155M**  
MATERIAL DESCRIPTION: **12"x12" Dark Gray w/ Black & Gray Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms 148, ND114, ND113, ND106, ND105, ND104, ND103**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **9"x9" Green w/ White Streaks VFT**  
MATERIAL LOCATION: **Room L209, Offices L105 & L104 (under carpet)**  
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **66061**      BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Roberto Rivera**  
SCHOOL NAME: **Chicago International  
Charter - Longwood  
(South)**      INSPECTION DATE: **8/5/2019**  
ADDRESS: **1309 W.95th St (9500S)  
43**      IDPH LICENSE NO: **100-06327**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**  
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building  
1930**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **08/05/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66061** BUILDING ID: **2420**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**  
SCHOOL NAME: **Chicago International Charter - Longwood (South)** REVIEW DATE: **9/24/2019**  
ADDRESS: **1309 W.95th St (9500S) 43** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **144**  
MATERIAL DESCRIPTION: **12"x12" Light Blue w/ Streaks VFT**  
MATERIAL LOCATION: **2nd Floor Restroom H219, Room H126, 1st Floor Corridor by Door 11 - Hackman Building 1930**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: 09/24/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*



# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-6000 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

4/20/2016

**ROBERTO RIVERA**  
855 WEST ADAMS STREET, STE 200  
CHICAGO, IL 60607


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

			<b>ASBESTOS PROFESSIONAL LICENSE</b>	
<b>ID NUMBER</b> 100 - 06327	<b>ISSUED</b> 4/20/2016	<b>EXPIRES</b> 05/15/2017	<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR	<b>TC EXPIRES</b> 1/20/2017  1/6/2017
<b>ROBERTO RIVERA</b> 855 WEST ADAMS STREET, ST CHICAGO, IL 60607 Environmental Health			<b>PROJECT MANAGER</b> 1/20/2017 <b>AIR SAMPLING PROFESSIONAL</b> <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
Nationally Accredited by PHAB

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/15/2019

Exam Date: 2/15/2019

Expiration Date: 2/15/2020

Certificate Number: BIR1902150525

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**ROBERTO RIVERA**  
 2942 W VAN BUREN ST  
 CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

			<b>ASBESTOS          PROFESSIONAL          LICENSE</b>		<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR		<b>TC EXPIRES</b> 2/22/2020  2/15/2020
<b>ID NUMBER</b> 100 - 06327	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020	PROJECT MANAGER AIR SAMPLING PROFESSIONAL		2/22/2020		
<b>ROBERTO RIVERA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
 EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2016



**OCCUPATIONAL TRAINING & SUPPLY, INC.**  
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060030

  
\_\_\_\_\_  
Kathy DeSalvo, Director

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JIGAR M SHAH**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>			<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 07342	<b>ISSUED</b> 4/19/2019	<b>EXPIRES</b> 05/15/2020	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/28/2020 3/15/2020 2/28/2020 2/22/2020
<b>JIGAR M SHAH</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed