

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3013
SCHOOL NAME: Youth Connection - El Cuarto Ano High School-
Association House
ADDRESS OF SCHOOL: 1116 N. Kedzie Ave, 4th Floor
CITY: Chicago, IL, 60651

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/4/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 124

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME(Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Youth Connection - El Cuarto Ano High School-Association House

1116 N. Kedzie Ave, 4th Floor
Chicago, IL, 60651

Unit: 66109
Building ID: 1121PA

IDPH ID Number: 14-016-2990-3013

REPORT DATE:

Prepared for:
Chicago Public Schools
42 West Madison Street
Chicago, IL 60602

Prepared by:

, ,

Phone

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66109 Region: IDPH ID:14-016-2990-3013

School: Youth Connection - El Cuarto Ano High School-Association Building ID: 1121PA

House

Address: 1116 N. Kedzie Ave, 4th Floor

Chicago, IL, 60651

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date:

Inspector:

Inspector IDPH License:

Management Planner:

Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: Youth Connection - El Cuarto Ano High School-Association House, Unit 66109
1116 N. Kedzie Ave, 4th Floor
Chicago, IL, 60651

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Youth Connection - El Cuarto Ano High School-Association House, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Youth Connection - El Cuarto Ano High School-Association House, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Youth Connection - El Cuarto Ano High School-Association House
Unit: 66109 Region:
Address: 1116 N. Kedzie Ave, 4th Floor
Chicago, IL, 60651
IDPH ID: 14-016-2990-3013 Building ID: 1121PA
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 124

3. LEA Designated Person

Contact: Phone:
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC:
Contact:
Address:
Phone: ' ' Fax:

5. Inspector

Inspector Name:

Inspector IDPH license # Signature:
Date:

6. Management Planner

Management Planner Name:

Management Planner IDPH license # Signature:
Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Youth Connection - El Cuarto Ano High School-Association House. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1121PA:

B. The following new homogenous areas have been identified for Building 1121PA:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

23	12 x 12 White with Beige and Tan Streaks Floor Tile
23A	12 x 12 White with Beige and Tan Streaks Floor Tile Mastic
25	Ceramic Tile Grout
25A	Ceramic Tile Adhesive
26	12 x 12 Tan with Tan Streaks Floor Tile
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic
27	12 x 12 White with Black Specs Floor Tile
27A	12 x 12 White with Black Specs Floor Tile Mastic
28	12 x 12 Black with White Specs Floor Tile
28A	12 x 12 Black with White Specs Floor Tile Mastic
29	Insulation Above 1 x 1 Celing Tile Metal Pan
30	12 x 12 White with Tan Streaks Floor Tile
30A	12 x 12 White with Tan Streaks Floor Tile Mastic

The following areas were deemed to be inaccessible:

11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)
13	2' X 2' White Grooved Ceiling Tile
23A	12 x 12 White with Beige and Tan Streaks Floor Tile Mastic
25A	Ceramic Tile Adhesive
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic
27A	12 x 12 White with Black Specs Floor Tile Mastic
28A	12 x 12 Black with White Specs Floor Tile Mastic
30A	12 x 12 White with Tan Streaks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Youth Connection - El Cuarto Ano High School-Association House Building 1121PA Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA

Address 1116 N. Kedzie Ave, 4th Floor Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12" X 12" White w/ Rainbow Streaks Floor Tile	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404, 406, 408, 409, 410	NO_ACBM	MISC	N				No			
01A	12" X 12" White w/ Rainbow Streaks Floor Tile Mastic	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classrooms 404, 406, 408, 409, 410	NO_ACBM	MISC	N				No			
02	2' X 4' Ceiling Tile with Pinholes	1,300	SF	Throughout Facility	NO_ACBM	MISC	Y				No			
03	12" X 12" Gray with Light and Dark Streaks Floor Tile	800	SF	Room 404	NO_ACBM	MISC	N				No			
03A	12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic	800	SF	Room 404	NO_ACBM	MISC	N				No			
04	12" x 12" Off-White w/Beige Streaks Floor Tile	1,300	SF	Washrooms, Classrooms and Xerox Room	NO_ACBM	MISC	N				No			
04A	12"x12" Off-White w/Beige Streaks Floor Tile Mastic	1,300	SF	Washrooms, Classrooms, and Xerox Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	2' X 4' White Pinhole Ceiling Tile	800	SF	Throughout Facility	NO_ACBM	MISC	Y				No			
06	12" X 12" White w/Black Streaks Floor Tile	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	NO_ACBM	MISC	N				No			
06A	12" X 12" White w/Black Streaks Floor Tile Mastic	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	2' X 2' Ceiling Tile	500	SF	CLASSROOMS & CORRIDORS	NO_ACBM	MISC	Y				No			
08	9" X 9" Cream w/Black Streaks Floor Tile (ABATED)	0	SF	ROOM 405 STORAGE	ABATED	MISC					No			
08A	9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)	0	SF	ROOM 450 & STORAGE ROOM	ABATED	MISC					No			
09	Mudded Joint Packing- E/ F/ V	150	FITTING	450 Storage Room Above Ceiling and Mechanical Room	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
10	9" X 9" Gray w/White Strips Floor Tile (ABATED)	0	SF	Northeast Staircase and Classrooms	ABATED	MISC					No			
10A	9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)	0	SF	Northeast Staircase and Classrooms	ABATED	MISC					No			
11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)	0	SF	Kitchen and Reception	ABATED	TSI					No			
12	12" X 12" Off-White w/Beige Streaks Floor	1,800	SF	Corridor and Rooms	NO_ACBM	MISC	N				No			

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA

Address 1116 N. Kedzie Ave, 4th Floor Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile			424 and East Classes and Offices										
12A	12" X 12" Off-White w/Beige Streaks Floor Tile Mastic	1,800	SF	Corridor and Rooms 424 and East Classes and Offices	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	2' X 2' White Grooved Ceiling Tile	800	SF	4th Floor Hall by Elevator	NO_ACBM	MISC	Y				No			
14	12" X 12" White w/Black Streaks Floor Tile	400	SF	Corridor and Elevator	NO_ACBM	MISC	N				No			
14A	12" X 12" White w/Black Streaks Floor Tile Mastic	400	SF	Corridor and Elevator	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Above Suspended Ceilings and Mechanical Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
16	Drywall	10,000	SF	Throughout Classrooms and Corridors	NO_ACBM	MISC	N				No			
17	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors	NO_ACBM	MISC	N				No			
18	Plaster	7,000	SF	Stairwells, Walls, Ceilings, & Above Suspended Ceilings	NO_ACBM	SURFACE	N				No			
19	Drywall	8,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	NO_ACBM	MISC	N				No			
20	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	NO_ACBM	MISC	N				No			
21	Plaster	11,000	SF	Throughout Classrooms and Corridors	NO_ACBM	SURFACE	N				No			
22	Aircell Pipe Insulation- NOT OBSERVED	10	LF	405 Storage	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
23	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23A	12 x 12 White with Beige and Tan Streaks Floor Tile Mastic	4,500	SF	Corridor West End, Room 450 Storage, NE Staircase Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House Unit 66109 Building ID 1121PA

Address 1116 N. Kedzie Ave, 4th Floor Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
24	2 x 4 Grooved Lay-in Ceiling Panels	50	SF	Kitchen (Staff Lounge) and Reception in 4th Floor (Abated)	ABATED	MISC	Y				No			
25	Ceramic Tile Grout	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25A	Ceramic Tile Adhesive	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12 x 12 Tan with Tan Streaks Floor Tile	525	SF	Room 425	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic	525	SF	Room 425	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12 x 12 White with Black Specs Floor Tile	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27A	12 x 12 White with Black Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12 x 12 Black with White Specs Floor Tile	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28A	12 x 12 Black with White Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	Insulation Above 1 x 1 Ceiling Tile Metal Pan	1,800	SF	1st Floor Lunchroom Manager Office	ASSUMED	MISC	Y	NONE	0		No			LOW
30	12 x 12 White with Tan Streaks Floor Tile	200	SF	1st Floor Kitchen Manager Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30A	12 x 12 White with Tan Streaks Floor Tile Mastic	200	SF	1st Floor Kitchen Manager Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House **Unit** 66109 **Building ID** 1121PA
Address 1116 N. Kedzie Ave, 4th Floor **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date
Inspector Name
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
02	
03	
03A	
04	
04A	
05	
06	
06A	
07	
08	
08A	
09	
10	
10A	
11	
12	
12A	
13	
14	
14A	
15	

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House **Unit** 66109 **Building ID** 1121PA
Address 1116 N. Kedzie Ave, 4th Floor **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	
17	
18	
19	
20	
21	
22	
23	
23A	
24	
25	
25A	
26	
26A	
27	
27A	
28	
28A	
29	
30	
30A	

Table II

Management Planner's Review

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School- Association House
Unit 66109
Building ID 1121PA
Address 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12" X 12" White w/ Rainbow Streaks Floor Tile	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classroom 404, 406, 408, 409, 410	No ACBM	MISC	No		SF		
01A	12" X 12" White w/ Rainbow Streaks Floor Tile Mastic	2,500	SF	1921 Corridor, Bathroom, Kitchen & Classrooms 404, 406, 408, 409, 410	No ACBM	MISC	No		SF		
02	2' X 4' Ceiling Tile with Pinholes	1,300	SF	Throughout Facility	No ACBM	MISC	Yes		SF		
03	12" X 12" Gray with Light and Dark Streaks Floor Tile	800	SF	Room 404	No ACBM	MISC	No		SF		
03A	12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic	800	SF	Room 404	No ACBM	MISC	No		SF		
04	12" x 12" Off-White w/Beige Streaks Floor Tile	1,300	SF	Washrooms, Classrooms and Xerox Room	No ACBM	MISC	No		SF		
04A	12"x12" Off-White w/Beige Streaks Floor Tile Mastic	1,300	SF	Washrooms, Classrooms, and Xerox Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
05	2' X 4' White Pinhole Ceiling Tile	800	SF	Throughout Facility	No ACBM	MISC	Yes		SF		
06	12" X 12" White w/Black Streaks Floor Tile	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	No ACBM	MISC	No		SF		
06A	12" X 12" White w/Black Streaks Floor Tile Mastic	800	SF	CORRIDOR BY ROOM 450 & SERVICE ELEVATOR	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
07	2' X 2' Ceiling Tile	500	SF	CLASSROOMS & CORRIDORS	No ACBM	MISC	Yes		SF		
08	9" X 9" Cream w/Black Streaks Floor Tile (ABATED)	0	SF	ROOM 405 STORAGE	Abated	MISC			SF		
08A	9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)	0	SF	ROOM 450 & STORAGE ROOM	Abated	MISC			SF		
09	Mudded Joint Packing- E/ F/ V	150	FITTING	450 Storage Room Above Ceiling and Mechanical Room	Chrysotile	MISC	Yes	0	FITTING	6 ACBM with the potential for damage	
10	9" X 9" Gray w/White Strips Floor Tile (ABATED)	0	SF	Northeast Staircase and Classrooms	Abated	MISC			SF		
10A	9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)	0	SF	Northeast Staircase and Classrooms	Abated	MISC			SF		
11	Insulation Above 1'x1' Metal Pan Ceiling (ABATED)	0	SF	Kitchen and Reception	Abated	TSI			SF		
12	12" X 12" Off-White w/Beige Streaks Floor Tile	1,800	SF	Corridor and Rooms 424 and East Classes and Offices	No ACBM	MISC	No		SF		

Chicago Public Schools

School Youth Connection - El
Cuarto Ano High School-
Association House
Address 1116 N. Kedzie Ave, 4th Floor

Unit 66109
Chicago, IL, 60651

Building ID 1121PA
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
12A	12" X 12" Off-White w/Beige Streaks Floor Tile Mastic	1,800	SF	Corridor and Rooms 424 and East Classes and Offices	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
13	2' X 2' White Grooved Ceiling Tile	800	SF	4th Floor Hall by Elevator	No ACBM	MISC	Yes		SF		
14	12" X 12" White w/Black Streaks Floor Tile	400	SF	Corridor and Elevator	No ACBM	MISC	No		SF		
14A	12" X 12" White w/Black Streaks Floor Tile Mastic	400	SF	Corridor and Elevator	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
15	MJP E/F/V on Fiberglass Pipe Insulation	120	LF	Above Suspended Ceilings and Mechanical Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
16	Drywall	10,000	SF	Throughout Classrooms and Corridors	No ACBM	MISC	No		SF		
17	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors	No ACBM	MISC	No		SF		
18	Plaster	7,000	SF	Stairwells, Walls, Ceilings, & Above Suspended Ceilings	No ACBM	SURFACE	No		SF		
19	Drywall	8,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	No ACBM	MISC	No		SF		
20	Drywall Compound	1,000	SF	Throughout Classrooms and Corridors, 1st Floor Kitchen	No ACBM	MISC	No		SF		
21	Plaster	11,000	SF	Throughout Classrooms and Corridors	No ACBM	SURFACE	No		SF		
22	Aircell Pipe Insulation- NOT OBSERVED	10	LF	405 Storage	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	
23	12 x 12 White with Beige and Tan Streaks Floor Tile	4,500	SF	Corridor Wes End, Room 450 Storage, NE Staircase Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
23A	12 x 12 White with Beige and Tan Streaks Floor Tile Mastic	4,500	SF	Corridor West End, Room 450 Storage, NE Staircase Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
24	2 x 4 Grooved Lay-in Ceiling Panels	50	SF	Kitchen (Staff Lounge) and Reception in 4th Floor (Abated)	Abated	MISC	Yes		SF		
25	Ceramic Tile Grout	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
25A	Ceramic Tile Adhesive	600	SF	Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
26	12 x 12 Tan with Tan Streaks Floor Tile	525	SF	Room 425	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
26A	12 x 12 Tan with Tan Streaks Floor Tile Mastic	525	SF	Room 425	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House
Unit 66109
Building ID 1121PA
Address 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

''

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
27	12 x 12 White with Black Specs Floor Tile	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
27A	12 x 12 White with Black Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
28	12 x 12 Black with White Specs Floor Tile	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
28A	12 x 12 Black with White Specs Floor Tile Mastic	900	SF	1st Floor Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
29	Insulation Above 1 x 1 Ceiling Tile Metal Pan	1,800	SF	1st Floor Lunchroom Manager Office	Assumed	MISC	Yes	0	SF		
30	12 x 12 White with Tan Streaks Floor Tile	200	SF	1st Floor Kitchen Manager Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
30A	12 x 12 White with Tan Streaks Floor Tile Mastic	200	SF	1st Floor Kitchen Manager Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House
Unit 66109
Building ID 1121PA
Address 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

''

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date _____
Manager Planner Name _____
Manager IDPH License No/Expiration _____

HA Number	Management Comments
01	
01A	
02	
03	
03A	
04	
04A	
05	
06	
06A	
07	
08	
08A	
09	
10	
10A	
11	
12	
12A	
13	
14	
14A	
15	

Chicago Public Schools

School Youth Connection - El Cuarto Ano High School-Association House
Unit 66109
Building ID 1121PA
Address 1116 N. Kedzie Ave, 4th Floor Chicago, IL, 60651
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

''

Phone:

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
16	
17	
18	
19	
20	
21	
22	
23	
23A	
24	
25	
25A	
26	
26A	
27	
27A	
28	
28A	
29	
30	
30A	

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404, 406, 408, 409, 410**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile**
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classroom 404, 406, 408, 409, 410**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classrooms 404, 406, 408, 409, 410**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12" X 12" White w/ Rainbow Streaks Floor Tile Mastic**
MATERIAL LOCATION: **1921 Corridor, Bathroom, Kitchen & Classrooms 404, 406, 408, 409, 410**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **2' X 4' Ceiling Tile with Pinholes**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **2' X 4' Ceiling Tile with Pinholes**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile**
MATERIAL LOCATION: **Room 404**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **03A**
MATERIAL DESCRIPTION: **12" X 12" Gray with Light and Dark Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 404**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUIDLING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Washrooms, Classrooms and Xerox Room**

MATERIAL QUANTITY: **1300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige Streaks Floor Tile**
MATERIAL LOCATION: **Washrooms, Classrooms and Xerox Room**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Washrooms, Classrooms, and Xerox Room**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **12"x12" Off-White w/Beige Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Washrooms, Classrooms, and Xerox Room**
MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **2' X 4' White Pinhole Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **2' X 4' White Pinhole Ceiling Tile**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **06A**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **CORRIDOR BY ROOM 450 & SERVICE ELEVATOR**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **2' X 2' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **CLASSROOMS & CORRIDORS**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **2' X 2' Ceiling Tile**
MATERIAL LOCATION: **CLASSROOMS & CORRIDORS**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 405 STORAGE**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile (ABATED)**
MATERIAL LOCATION: **ROOM 405 STORAGE**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROOM 450 & STORAGE ROOM**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **9" X 9" Cream w/Black Streaks Floor Tile Mastic (ABATED)**
MATERIAL LOCATION: **ROOM 450 & STORAGE ROOM**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Joint Packing- E/ F/ V**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **450 Storage Room Above Ceiling and Mechanical Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Mudded Joint Packing- E/ F/ V**
MATERIAL LOCATION: **450 Storage Room Above Ceiling and Mechanical Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Northeast Staircase and Classrooms**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile (ABATED)**
MATERIAL LOCATION: **Northeast Staircase and Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Northeast Staircase and Classrooms**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **9" X 9" Gray w/White Strips Floor Tile Mastic (ABATED)**
MATERIAL LOCATION: **Northeast Staircase and Classrooms**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Insulation Above 1'x1' Metal Pan Ceiling (ABATED)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen and Reception**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Insulation Above 1'x1' Metal Pan Ceiling (ABATED)**
MATERIAL LOCATION: **Kitchen and Reception**
MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridor and Rooms 424 and East Classes and Offices**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile**
MATERIAL LOCATION: **Corridor and Rooms 424 and East Classes and Offices**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor and Rooms 424 and East Classes and Offices**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **12A**
MATERIAL DESCRIPTION: **12" X 12" Off-White w/Beige Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Corridor and Rooms 424 and East Classes and Offices**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Hall by Elevator**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **2' X 2' White Grooved Ceiling Tile**
MATERIAL LOCATION: **4th Floor Hall by Elevator**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridor and Elevator**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile**
MATERIAL LOCATION: **Corridor and Elevator**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor and Elevator**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **14A**
MATERIAL DESCRIPTION: **12" X 12" White w/Black Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Corridor and Elevator**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Above Suspended Ceilings and Mechanical Room**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Above Suspended Ceilings and Mechanical Room**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms and Corridors**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Classrooms and Corridors**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms and Corridors**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Classrooms and Corridors**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairwells, Walls, Ceilings, & Above Suspended Ceilings**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Stairwells, Walls, Ceilings, & Above Suspended Ceilings**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Classrooms and Corridors, 1st Floor Kitchen**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Classrooms and Corridors**

MATERIAL QUANTITY: **11000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Throughout Classrooms and Corridors**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation- NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **405 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation- NOT OBSERVED**
MATERIAL LOCATION: **405 Storage**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile**
MATERIAL LOCATION: **Corridor Wes End, Room 450 Storage, NE Staircase Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Corridor West End, Room 450 Storage, NE Staircase Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **23A**
MATERIAL DESCRIPTION: **12 x 12 White with Beige and Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Corridor West End, Room 450 Storage, NE Staircase Classrooms**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2 x 4 Grooved Lay-in Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen (Staff Lounge) and Reception in 4th Floor (Abated)**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2 x 4 Grooved Lay-in Ceiling Panels**
MATERIAL LOCATION: **Kitchen (Staff Lounge) and Reception in 4th Floor (Abated)**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Ceramic Tile Grout**
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **25A**
MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**
MATERIAL LOCATION: **Kitchen 4th Floor, 450 Storage Area, Kitchen 1st Floor, janitor Closet next to Elevators**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 425**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile**
MATERIAL LOCATION: **Room 425**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 425**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **26A**
MATERIAL DESCRIPTION: **12 x 12 Tan with Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 425**
MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano** INSPECTION DATE:
High School-Association House
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **27A**
MATERIAL DESCRIPTION: **12 x 12 White with Black Specs Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **12 x 12 Black with White Specs Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Cafeteria**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Insulation Above 1 x 1 Ceiling Tile Metal Pan**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Lunchroom Manager Office**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Insulation Above 1 x 1 Celing Tile Metal Pan**
MATERIAL LOCATION: **1st Floor Lunchroom Manager Office**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile**
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** INSPECTION DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66109** BUILDING ID: **1121PA**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER:
SCHOOL NAME: **Youth Connection - El Cuarto Ano High School-Association House** REVIEW DATE:
ADDRESS: **1116 N. Kedzie Ave, 4th Floor** IDPH LICENSE NO:

HOMOGENEOUS AREA: **30A**
MATERIAL DESCRIPTION: **12 x 12 White with Tan Streaks Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Kitchen Manager Office**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed