

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-55018
SCHOOL NAME:
ADDRESS OF SCHOOL: 7416 Ridge
CITY: Chicago, IL, 60645

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 588
IDPH INSPECTOR LICENSE NUMBER: 100-06327
IDPH LICENSED INSPECTOR NAME(Please Print): Roberto Rivera
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

7416 Ridge
Chicago, IL, 60645

Unit: 66134
Building ID: 55018

IDPH ID Number: 14-016-2990-55018

REPORT DATE:

Tuesday, October 01, 2019

Prepared for:

**Chicago Public Schools
42 West Madison Street
Chicago, IL 60602**

Prepared by:

GSG-Probe Consulting, Inc.

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 25, 2019

RE: , Unit 66134
7416 Ridge
Chicago, IL, 60645

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at , there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School:
Address: 7416 Ridge
IDPH ID: 14-016-2990-55018
Contact:

Unit: 66134
Chicago, IL, 60645
Building ID: 55018
Phone:

Region:

2. Description of Facility

Original Construction:
Total Square Footage:
Current Occupancy: 588

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Robert Christlieb
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 553-3197

4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren
Chicago, IL, 60612
Phone: 3123197575

Fax:

5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327

Signature:
Date: 11/25/2019

6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:
Date: 11/25/2019

7. Review Date:11/25/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the . This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 55018:

B. The following new homogenous areas have been identified for Building 55018:

M02	Terrazzo (Beige) Flooring
M03	Terrazzo (Green) Flooring
M04	Terrazzo Window Sill
M05	2' x 4' Pinhole Ceiling Tile
M06	1' x 1' Ceiling Tile with Grooves
M07	Drywall System
M08	12" x 12" White with Beige Specks VFT
M08A	12" x 12" White with Beige Specks VFT Mastic
M09	Black Sink
M10	Baseboard Mastic
M11	Carpet Mastic
M12	Science Lab Table Tops
M13	Fume Hood
M14	Sink Undercoating
M15	1' x 1' Ceiling Tile with Holes
M17	2' x 2' Smooth Ceiling Tile
M18	2' x 4' Smooth Ceiling Tile
M20	Terrazzo (Gray) Flooring
M21	1' x 1' Ceiling Tile with Grooves
M22	9" X 9" Light Brown VFT
M22A	9" x 9" Light Brown VFT Mastic
M23	9" x 9" Light Red VFT
M23A	9" x 9" Light Red VFT Mastic

M24	9" x 9" Gray with White Streaks VFT
M24A	9" x 9" Gray with White Streaks VFT Mastic
M25	9" x 9" Beige with Brown Streaks VFT
M25A	9" x 9" Beige with Brown Streaks VFT Mastic
M26	9" x 9" Green with Beige Streaks VFT
M26A	9" x 9" Green with Beige Streaks VFT Mastic
M27	9" x 9" Black with Beige and Green Streaks VFT
M27A	9" x 9" Black with Beige and Green Streaks VFT Mastic
M28	9" x 9" Gray with White Spots VFT
M28A	9" x 9" Gray with White Spots VFT Mastic
M29	9" x 9" Yellow VFT
M29A	9" x 9" Yellow VFT Mastic
M30	9" x 9" Brown with Beige Streaks VFT
M30A	9" x 9" Brown with Beige Streaks VFT Mastic
M31	9" x 9" Light Green VFT
M31A	9" x 9" Light Green VFT Mastic
M32	12" x 12" Beige with Specks VFT
M32A	12" x 12" Beige with Specks VFT Mastic
M33	12" x 12" Dark Blue with Black and Gray Specks VFT
M33A	12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic
M34	Baseboard Mastic
M35	Carpet Mastic
M36	Red Linoleum

M37	Terrazzo (Brown and Beige)
M38	Green Terrazzo
M39	2' x 4' Pinhole Ceiling Tile
M40	Drywall System
M41	Vibration Damper Cloth
M42	Black Counter Tops
M44	Fire Doors
S01	Hard Coat Plaster
S19	Hard Coat Plaster
T16	Aircell Pipe Insulation
T45	Aircell Heat Shields
T46	Aircell Pipe Insulation
T47	Mudded Joint Packing on Aircell Pipe Insulation
T48	Mudded Joint Packing on Fiberglass Pipe Insulation
T49	Mudded Joint Packing on Fiberglass Pipe Insulation

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

M02	Terrazzo (Beige) Flooring
M03	Terrazzo (Green) Flooring
M04	Terrazzo Window Sill
M05	2' x 4' Pinhole Ceiling Tile
M06	1' x 1' Ceiling Tile with Grooves
M07	Drywall System
M08	12" x 12" White with Beige Specks VFT
M08A	12" x 12" White with Beige Specks VFT Mastic
M09	Black Sink
M10	Baseboard Mastic
M11	Carpet Mastic
M12	Science Lab Table Tops
M13	Fume Hood
M14	Sink Undercoating
M15	1' x 1' Ceiling Tile with Holes
M17	2' x 2' Smooth Ceiling Tile
M18	2' x 4' Smooth Ceiling Tile
M20	Terrazzo (Gray) Flooring
M21	1' x 1' Ceiling Tile with Grooves
M22	9" X 9" Light Brown VFT
M22A	9" x 9" Light Brown VFT Mastic
M23	9" x 9" Light Red VFT
M23A	9" x 9" Light Red VFT Mastic
M24	9" x 9" Gray with White Streaks VFT
M24A	9" x 9" Gray with White Streaks VFT Mastic
M25	9" x 9" Beige with Brown Streaks VFT
M25A	9" x 9" Beige with Brown Streaks VFT Mastic
M26	9" x 9" Green with Beige Streaks VFT
M26A	9" x 9" Green with Beige Streaks VFT Mastic
M27	9" x 9" Black with Beige and Green Streaks VFT
M27A	9" x 9" Black with Beige and Green Streaks VFT Mastic
M28	9" x 9" Gray with White Spots VFT
M28A	9" x 9" Gray with White Spots VFT Mastic
M29	9" x 9" Yellow VFT
M29A	9" x 9" Yellow VFT Mastic
M30	9" x 9" Brown with Beige Streaks VFT
M30A	9" x 9" Brown with Beige Streaks VFT Mastic
M31	9" x 9" Light Green VFT
M31A	9" x 9" Light Green VFT Mastic
M32	12" x 12" Beige with Specks VFT
M32A	12" x 12" Beige with Specks VFT Mastic

M33	12" x 12" Dark Blue with Black and Gray Specks VFT
M33A	12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic
M34	Baseboard Mastic
M35	Carpet Mastic
M36	Red Linoleum
M37	Terrazzo (Brown and Beige)
M38	Green Terrazzo
M39	2' x 4' Pinhole Ceiling Tile
M40	Drywall System
M41	Vibration Damper Cloth
M42	Black Counter Tops
M44	Fire Doors
S01	Hard Coat Plaster
S19	Hard Coat Plaster
T16	Aircell Pipe Insulation
T45	Aircell Heat Shields
T46	Aircell Pipe Insulation
T47	Mudded Joint Packing on Aircell Pipe Insulation
T48	Mudded Joint Packing on Fiberglass Pipe Insulation
T49	Mudded Joint Packing on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Building 55018 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
M02	Terrazzo (Beige) Flooring		SF	Throughout 1920's Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M03	Terrazzo (Green) Flooring		SF	3rd, 2nd, 1st, and ground floor corridors, stairwells; rooms: 316, 305, 210, 201, 061A, 061D, 059, 041 - 1920's Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M04	Terrazzo Window Sill		LF	Throughout rooms and washrooms - 1920's Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M05	2' x 4' Pinhole Ceiling Tile		SF	Rooms: 323, 320, 2nd floor girls toilet, 1st floor boys toilet (122), 1st floor MDF room - 1920 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M06	1' x 1' Ceiling Tile with Grooves		SF	3rd and 2nd floor corridors, room 210, 1st floor locker room (125), rooms 062, 062A, 065 - 1920's Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M07	Drywall System		SF	Rooms: 327, 323, 320, 318, 312, 311, 128, 061A, 061D, 045, 3rd floor boys and girls toilets and unisex toilet, 2nd floor girls toilet, 1st floor boys toilet, 1st floor lockers (125), gym, 1st floor MDF - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M08	12" x 12" White with Beige Specks VFT		SF	Rooms: 310, 309 - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M08A	12" x 12" White with Beige Specks VFT Mastic		SF	Rooms: 310, 309 - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M09	Black Sink		SF	Rooms 312 (storage) - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M10	Baseboard Mastic		LF	Rooms 318, 317, 312, 311, 215, 065, 047, 046, 045, 1st floor boys toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(122) - 1920s Building										
M11	Carpet Mastic		SF	Rooms: 201, 131, 130, 128, 126, 061A, 061D, 059, 040B - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M12	Science Lab Table Tops		SF	Room 215 - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M13	Fume Hood		EA	Room 215 - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M14	Sink Undercoating		SF	Room 215 - 1920s Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M15	1' x 1' Ceiling Tile with Holes		SF	1st floor and ground floor corridors; Rooms: 045, 045A - 1920s Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M17	2' x 2' Smooth Ceiling Tile		SF	Rooms: 064, 062B, 061A - 1920s Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M18	2' x 4' Smooth Ceiling Tile		SF	Rooms: 047, 046 (kitchen) - 1920s Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M20	Terrazzo (Gray) Flooring		SF	Rooms: 106, 053, 052, 034, storage 029, 011, 009, 006, vestibule 002, stairwells A and B, boys toilet (105), 1st floor corridors - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M21	1' x 1' Ceiling Tile with Grooves		SF	Rooms: 112, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014B, 011, 002, balcony 006, 1st floor corridors - 1958 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M22	9" X 9" Light Brown VFT		SF	Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition										
M22A	9" x 9" Light Brown VFT Mastic		SF	Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M23	9" x 9" Light Red VFT		SF	Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		MODERATE
M23A	9" x 9" Light Red VFT Mastic		SF	Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M24	9" x 9" Gray with White Streaks VFT		SF	Rooms: 116A, 116B, 104, 103 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M24A	9" x 9" Gray with White Streaks VFT Mastic		SF	Rooms: 116A, 116B, 104, 103 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M25	9" x 9" Beige with Brown Streaks VFT		SF	Rooms 113 (copy room), 108C (vault) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M25A	9" x 9" Beige with Brown Streaks VFT Mastic		SF	Rooms 113 (copy room), 108C (vault) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M26	9" x 9" Green with Beige Streaks VFT		SF	Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M26A	9" x 9" Green with Beige Streaks VFT Mastic		SF	Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M27	9" x 9" Black with Beige and Green Streaks VFT		SF	Auditorium (012) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
M27A	9" x 9" Black with Beige and Green Streaks VFT Mastic		SF	Auditorium (012) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M28	9" x 9" Gray with White Spots VFT		SF	Balcony 006 (auditorium lobby) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M28A	9" x 9" Gray with White Spots VFT Mastic		SF	Balcony 006 (auditorium lobby) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
M29	9" x 9" Yellow VFT		SF	Storage room by balcony 006 (auditorium lobby) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M29A	9" x 9" Yellow VFT Mastic		SF	Storage room by balcony 006 (auditorium lobby) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M30	9" x 9" Brown with Beige Streaks VFT		SF	Lecture Hall 014 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M30A	9" x 9" Brown with Beige Streaks VFT Mastic		SF	Lecture Hall 014 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M31	9" x 9" Light Green VFT		SF	Room 028 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M31A	9" x 9" Light Green VFT Mastic		SF	Room 028 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M32	12" x 12" Beige with Specks VFT		SF	Unisex toilet 009 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M32A	12" x 12" Beige with Specks VFT Mastic		SF	Unisex toilet 009 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M33	12" x 12" Dark Blue with Black and Gray Specks VFT		SF	Lecture Hall 014, Room 051 (ante room) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M33A	12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic		SF	Lecture Hall 014, Room 051 (ante room) - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M34	Baseboard Mastic		LF	Rooms: 116A, 116B, 113, 112, 111, 110, 109, 108, 108A, 108B, 108C, 104, 103, 101, 102, Auditorium and balcony, lobby balcony storage.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				057, 053, 052, 051, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014, 014A, 014B, 009, 006, 006 balcony, 005, 004, 003 - 1958 Addition										
M35	Carpet Mastic		SF	Room 109, auditorium and balcony, 057, 053, 052, 030, 030A, 030C, 030D - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M36	Red Linoleum		SF	Room 033 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M37	Terrazzo (Brown and Beige)		SF	Rooms: 101, 102 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M38	Green Terrazzo		SF	Room 035 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M39	2' x 4' Pinhole Ceiling Tile		SF	Toilet 011 - 1958 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
M40	Drywall System		SF	JC 106, boys toilet 105, unisex toilet 009 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M41	Vibration Damper Cloth		SF	JC 106 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M42	Black Counter Tops		SF	Room 101 - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M44	Fire Doors		SF	Auditorium Stage - 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S01	Hard Coat Plaster		SF	Throughout 1920's Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
S19	Hard Coat Plaster		SF	Throughout 1958 Addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
T16	Aircell Pipe Insulation		LF	Room 130, gym (038), utility room 037, and basement - 1920s Building	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
T45	Aircell Heat Shields		SF	Auditorium Balcony - 1958 Addition	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
T46	Aircell Pipe Insulation		LF	Rooms: 117A, 116, 115 (library), 115D,	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				017 loading dock, auditorium stage - 1958 Addition										
T47	Mudded Joint Packing on Aircell Pipe Insulation		LF	Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
T48	Mudded Joint Packing on Fiberglass Pipe Insulation	250	LF	Throughout Basement	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
T49	Mudded Joint Packing on Fiberglass Pipe Insulation	100	LF	Throughout Basement - 1920s Building	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/25/2019
Inspector Name Roberto Rivera
100-06327 5/15/2020
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
M02	
M03	
M04	
M05	
M06	
M07	
M08	
M08A	
M09	
M10	
M11	
M12	
M13	
M14	
M15	
M17	
M18	
M20	
M21	
M22	
M22A	
M23	
M23A	

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
M24	
M24A	
M25	
M25A	
M26	
M26A	
M27	
M27A	
M28	
M28A	
M29	
M29A	
M30	
M30A	
M31	
M31A	
M32	
M32A	
M33	
M33A	
M34	
M35	
M36	
M37	
M38	
M39	
M40	
M41	
M42	

Chicago Public Schools

School Unit 66134 Building ID 55018

Address 7416 Ridge Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
M44	
S01	
S19	
T16	
T45	
T46	
T47	
T48	
T49	

Table II

Management Planner's Review

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
M02	Terrazzo (Beige) Flooring		SF	Throughout 1920's Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M03	Terrazzo (Green) Flooring		SF	3rd, 2nd, 1st, and ground floor corridors, stairwells; rooms: 316, 305, 210, 201, 061A, 061D, 059, 041 - 1920's Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M04	Terrazzo Window Sill		LF	Throughout rooms and washrooms - 1920's Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M05	2' x 4' Pinhole Ceiling Tile		SF	Rooms: 323, 320, 2nd floor girls toilet, 1st floor boys toilet (122), 1st floor MDF room - 1920 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M06	1' x 1' Ceiling Tile with Grooves		SF	3rd and 2nd floor corridors, room 210, 1st floor locker room (125), rooms 062, 062A, 065 - 1920's Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M07	Drywall System		SF	Rooms: 327, 323, 320, 318, 312, 311, 128, 061A, 061D, 045, 3rd floor boys and girls toilets and unisex toilet, 2nd floor girls toilet, 1st floor boys toilet, 1st floor lockers (125), gym, 1st floor MDF - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M08	12" x 12" White with Beige Specks VFT		SF	Rooms: 310, 309 - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M08A	12" x 12" White with Beige Specks VFT Mastic		SF	Rooms: 310, 309 - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M09	Black Sink		SF	Rooms 312 (storage) - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M10	Baseboard Mastic		LF	Rooms 318, 317, 312, 311, 215, 065, 047, 046, 045, 1st floor boys toilet (122) - 1920s Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M11	Carpet Mastic		SF	Rooms: 201, 131, 130, 128, 126, 061A, 061D, 059, 040B - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M12	Science Lab Table Tops		SF	Room 215 - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M13	Fume Hood		EA	Room 215 - 1920s Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
M14	Sink Undercoating		SF	Room 215 - 1920s Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M15	1' x 1' Ceiling Tile with Holes		SF	1st floor and ground floor corridors; Rooms: 045, 045A - 1920s Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M17	2' x 2' Smooth Ceiling Tile		SF	Rooms: 064, 062B, 061A - 1920s Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M18	2' x 4' Smooth Ceiling Tile		SF	Rooms: 047, 046 (kitchen) - 1920s	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building							
M20	Terrazzo (Gray) Flooring		SF	Rooms: 106, 053, 052, 034, storage 029, 011, 009, 006, vestibule 002, stairwells A and B, boys toilet (105), 1st floor corridors - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M21	1' x 1' Ceiling Tile with Grooves		SF	Rooms: 112, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014B, 011, 002, balcony 006, 1st floor corridors - 1958 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M22	9" X 9" Light Brown VFT		SF	Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M22A	9" x 9" Light Brown VFT Mastic		SF	Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M23	9" x 9" Light Red VFT		SF	Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
M23A	9" x 9" Light Red VFT Mastic		SF	Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M24	9" x 9" Gray with White Streaks VFT		SF	Rooms: 116A, 116B, 104, 103 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M24A	9" x 9" Gray with White Streaks VFT Mastic		SF	Rooms: 116A, 116B, 104, 103 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M25	9" x 9" Beige with Brown Streaks VFT		SF	Rooms 113 (copy room), 108C (vault) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M25A	9" x 9" Beige with Brown Streaks VFT Mastic		SF	Rooms 113 (copy room), 108C (vault) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M26	9" x 9" Green with Beige Streaks VFT		SF	Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
M26A	9" x 9" Green with Beige Streaks VFT Mastic		SF	Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M27	9" x 9" Black with Beige and Green Streaks VFT		SF	Auditorium (012) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M27A	9" x 9" Black with Beige and Green Streaks VFT Mastic		SF	Auditorium (012) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M28	9" x 9" Gray with White Spots VFT		SF	Balcony 006 (auditorium lobby) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M28A	9" x 9" Gray with White Spots VFT Mastic		SF	Balcony 006 (auditorium lobby) - 1958 Addition	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
M29	9" x 9" Yellow VFT		SF	Storage room by balcony 006 (auditorium lobby) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M29A	9" x 9" Yellow VFT Mastic		SF	Storage room by balcony 006 (auditorium lobby) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M30	9" x 9" Brown with Beige Streaks VFT		SF	Lecture Hall 014 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M30A	9" x 9" Brown with Beige Streaks VFT Mastic		SF	Lecture Hall 014 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M31	9" x 9" Light Green VFT		SF	Room 028 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M31A	9" x 9" Light Green VFT Mastic		SF	Room 028 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M32	12" x 12" Beige with Specks VFT		SF	Unisex toilet 009 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M32A	12" x 12" Beige with Specks VFT Mastic		SF	Unisex toilet 009 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M33	12" x 12" Dark Blue with Black and Gray Specks VFT		SF	Lecture Hall 014, Room 051 (ante room) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M33A	12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic		SF	Lecture Hall 014, Room 051 (ante room) - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M34	Baseboard Mastic		LF	Rooms: 116A, 116B, 113, 112, 111, 110, 109, 108, 108A, 108B, 108C, 104, 103, 101, 102, Auditorium and balcony, lobby balcony storage, 057, 053, 052, 051, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014, 014A, 014B, 009, 006, 006 balcony, 005, 004, 003 - 1958 Addition	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
M35	Carpet Mastic		SF	Room 109, auditorium and balcony, 057, 053, 052, 030, 030A, 030C, 030D - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M36	Red Linoleum		SF	Room 033 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
M37	Terrazzo (Brown and Beige)		SF	Rooms: 101, 102 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M38	Green Terrazzo		SF	Room 035 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M39	2' x 4' Pinhole Ceiling Tile		SF	Toilet 011 - 1958 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M40	Drywall System		SF	JC 106, boys toilet 105, unisex toilet 009 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M41	Vibration Damper Cloth		SF	JC 106 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M42	Black Counter Tops		SF	Room 101 - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M44	Fire Doors		SF	Auditorium Stage - 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S01	Hard Coat Plaster		SF	Throughout 1920's Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
S19	Hard Coat Plaster		SF	Throughout 1958 Addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
T16	Aircell Pipe Insulation		LF	Room 130, gym (038), utility room 037, and basement - 1920s Building	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T45	Aircell Heat Shields		SF	Auditorium Balcony - 1958 Addition	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
T46	Aircell Pipe Insulation		LF	Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T47	Mudded Joint Packing on Aircell Pipe Insulation		LF	Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T48	Mudded Joint Packing on Fiberglass Pipe Insulation	250	LF	Throughout Basement	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T49	Mudded Joint Packing on Fiberglass Pipe Insulation	100	LF	Throughout Basement - 1920s Building	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	11/25/2019
Manager Planner Name	Jigar Shah
100-07342	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
M02	
M03	
M04	
M05	
M06	
M07	
M08	
M08A	
M09	
M10	
M11	
M12	
M13	
M14	
M15	

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
 Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
M17	
M18	
M20	
M21	
M22	
M22A	
M23	
M23A	
M24	
M24A	
M25	
M25A	
M26	
M26A	
M27	
M27A	
M28	
M28A	
M29	
M29A	
M30	
M30A	
M31	
M31A	
M32	
M32A	

Chicago Public Schools

School
Address 7416 Ridge

Unit 66134
Chicago, IL, 60645

Building ID 55018
Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
M33	
M33A	
M34	
M35	
M36	
M37	
M38	
M39	
M40	
M41	
M42	
M44	
S01	
S19	
T16	
T45	
T46	
T47	
T48	
T49	

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M08**
MATERIAL DESCRIPTION: **12" x 12" White with Beige Specks VFT**
MATERIAL LOCATION: **Rooms: 310, 309 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M08**
MATERIAL DESCRIPTION: **12" x 12" White with Beige Specks VFT**
MATERIAL LOCATION: **Rooms: 310, 309 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M12**
MATERIAL DESCRIPTION: **Science Lab Table Tops**
MATERIAL LOCATION: **Room 215 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M12**

MATERIAL DESCRIPTION: **Science Lab Table Tops**

MATERIAL LOCATION: **Room 215 - 1920s Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M13**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **Room 215 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **EA**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **EA**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M13**
MATERIAL DESCRIPTION: **Fume Hood**
MATERIAL LOCATION: **Room 215 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **EA**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M26**
MATERIAL DESCRIPTION: **9" x 9" Green with Beige Streaks VFT**
MATERIAL LOCATION: **Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M26**
MATERIAL DESCRIPTION: **9" x 9" Green with Beige Streaks VFT**
MATERIAL LOCATION: **Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M27A**
MATERIAL DESCRIPTION: **9" x 9" Black with Beige and Green Streaks VFT Mastic**
MATERIAL LOCATION: **Auditorium (012) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M27A**

MATERIAL DESCRIPTION: **9" x 9" Black with Beige and Green Streaks VFT Mastic**

MATERIAL LOCATION: **Auditorium (012) - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M28**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Spots VFT**
MATERIAL LOCATION: **Balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M28**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Spots VFT**
MATERIAL LOCATION: **Balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M30**
MATERIAL DESCRIPTION: **9" x 9" Brown with Beige Streaks VFT**
MATERIAL LOCATION: **Lecture Hall 014 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M30**
MATERIAL DESCRIPTION: **9" x 9" Brown with Beige Streaks VFT**
MATERIAL LOCATION: **Lecture Hall 014 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M39**
MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile**
MATERIAL LOCATION: **Toilet 011 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M39**
MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile**
MATERIAL LOCATION: **Toilet 011 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M35**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Room 109, auditorium and balcony, 057, 053, 052, 030, 030A, 030C, 030D - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M35**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 109, auditorium and balcony, 057, 053, 052, 030, 030A, 030C, 030D - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M36**
MATERIAL DESCRIPTION: **Red Linoleum**
MATERIAL LOCATION: **Room 033 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M36**
MATERIAL DESCRIPTION: **Red Linoleum**
MATERIAL LOCATION: **Room 033 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **S19**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **S19**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M23**
MATERIAL DESCRIPTION: **9" x 9" Light Red VFT**
MATERIAL LOCATION: **Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66134	BUILDING ID:	55018
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:		REVIEW DATE:	11/25/2019		
ADDRESS:	7416 Ridge	IDPH LICENSE NO:	100-06327		
HOMOGENEOUS AREA:	M23				
MATERIAL DESCRIPTION:	9" x 9" Light Red VFT				
MATERIAL LOCATION:	Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition				
MATERIAL QUANTITY:		MATERIAL UNITS:		SF	
DAMAGE QUANTITY:	0	DAMAGE UNITS:		SF	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M24**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Streaks VFT**
MATERIAL LOCATION: **Rooms: 116A, 116B, 104, 103 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M24**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Streaks VFT**
MATERIAL LOCATION: **Rooms: 116A, 116B, 104, 103 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M31**
MATERIAL DESCRIPTION: **9" x 9" Light Green VFT**
MATERIAL LOCATION: **Room 028 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M31**
MATERIAL DESCRIPTION: **9" x 9" Light Green VFT**
MATERIAL LOCATION: **Room 028 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M09**
MATERIAL DESCRIPTION: **Black Sink**
MATERIAL LOCATION: **Rooms 312 (storage) - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M09**
MATERIAL DESCRIPTION: **Black Sink**
MATERIAL LOCATION: **Rooms 312 (storage) - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M14**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Room 215 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M14**
MATERIAL DESCRIPTION: **Sink Undercoating**
MATERIAL LOCATION: **Room 215 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T16**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 130, gym (038), utility room 037, and basement - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T16**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Room 130, gym (038), utility room 037, and basement - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M25**
MATERIAL DESCRIPTION: **9" x 9" Beige with Brown Streaks VFT**
MATERIAL LOCATION: **Rooms 113 (copy room), 108C (vault) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M25**
MATERIAL DESCRIPTION: **9" x 9" Beige with Brown Streaks VFT**
MATERIAL LOCATION: **Rooms 113 (copy room), 108C (vault) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M32A**
MATERIAL DESCRIPTION: **12" x 12" Beige with Specks VFT Mastic**
MATERIAL LOCATION: **Unisex toilet 009 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M32A**

MATERIAL DESCRIPTION: **12" x 12" Beige with Specks VFT Mastic**

MATERIAL LOCATION: **Unisex toilet 009 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M37**
MATERIAL DESCRIPTION: **Terrazzo (Brown and Beige)**
MATERIAL LOCATION: **Rooms: 101, 102 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M37**
MATERIAL DESCRIPTION: **Terrazzo (Brown and Beige)**
MATERIAL LOCATION: **Rooms: 101, 102 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M29A**
MATERIAL DESCRIPTION: **9" x 9" Yellow VFT Mastic**
MATERIAL LOCATION: **Storage room by balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M29A**
MATERIAL DESCRIPTION: **9" x 9" Yellow VFT Mastic**
MATERIAL LOCATION: **Storage room by balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T46**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T46**
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M26A**
MATERIAL DESCRIPTION: **9" x 9" Green with Beige Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M26A**
MATERIAL DESCRIPTION: **9" x 9" Green with Beige Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms: 017 (loading dock), 005, 004, 003 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M06**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Grooves**

MATERIAL LOCATION: **3rd and 2nd floor corridors, room 210, 1st floor locker room (125), rooms 062, 062A, 065 - 1920's Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M06**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Grooves**
MATERIAL LOCATION: **3rd and 2nd floor corridors, room 210, 1st floor locker room (125), rooms 062, 062A, 065 - 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M07**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Rooms: 327, 323, 320, 318, 312, 311, 128, 061A, 061D, 045, 3rd floor boys and girls toilets and unisex toilet, 2nd floor girls toilet, 1st floor boys toilet, 1st floor lockers (125), gym, 1st floor MDF - 1920s Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M07**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Rooms: 327, 323, 320, 318, 312, 311, 128, 061A, 061D, 045, 3rd floor boys and girls toilets and unisex toilet, 2nd floor girls toilet, 1st floor boys toilet, 1st floor lockers (125), gym, 1st floor MDF - 1920s Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M10**
MATERIAL DESCRIPTION: **Baseboard Mastic**
MATERIAL LOCATION: **Rooms 318, 317, 312, 311, 215, 065, 047, 046, 045, 1st floor boys toilet (122) - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M10**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Rooms 318, 317, 312, 311, 215, 065, 047, 046, 045, 1st floor boys toilet (122) - 1920s Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M22**

MATERIAL DESCRIPTION: **9" X 9" Light Brown VFT**

MATERIAL LOCATION: **Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	66134	BUILDING ID:	55018
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:		REVIEW DATE:	11/25/2019		
ADDRESS:	7416 Ridge	IDPH LICENSE NO:	100-06327		
HOMOGENEOUS AREA:	M22				
MATERIAL DESCRIPTION:	9" X 9" Light Brown VFT				
MATERIAL LOCATION:	Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition				
MATERIAL QUANTITY:		MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUIDLING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M22A**

MATERIAL DESCRIPTION: **9" x 9" Light Brown VFT Mastic**

MATERIAL LOCATION: **Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc. 2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M22A**

MATERIAL DESCRIPTION: **9" x 9" Light Brown VFT Mastic**

MATERIAL LOCATION: **Rooms: 116, 117A, library (115), 115A, 115B, 115C, 115D, 112, 111, 110, 109, 108, 108A, 108B, 108D, 033, 031, 031B, 025, 024, 023, 022, 021, 020, 019 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M31A**
MATERIAL DESCRIPTION: **9" x 9" Light Green VFT Mastic**
MATERIAL LOCATION: **Room 028 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M31A**
MATERIAL DESCRIPTION: **9" x 9" Light Green VFT Mastic**
MATERIAL LOCATION: **Room 028 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M32**
MATERIAL DESCRIPTION: **12" x 12" Beige with Specks VFT**
MATERIAL LOCATION: **Unisex toilet 009 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M32**
MATERIAL DESCRIPTION: **12" x 12" Beige with Specks VFT**
MATERIAL LOCATION: **Unisex toilet 009 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T45**
MATERIAL DESCRIPTION: **Aircell Heat Shields**
MATERIAL LOCATION: **Auditorium Balcony - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T45**
MATERIAL DESCRIPTION: **Aircell Heat Shields**
MATERIAL LOCATION: **Auditorium Balcony - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M03**

MATERIAL DESCRIPTION: **Terrazzo (Green) Flooring**

MATERIAL LOCATION: **3rd, 2nd, 1st, and ground floor corridors, stairwells; rooms: 316, 305, 210, 201, 061A, 061D, 059, 041 - 1920's Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **MODERATE** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M03**

MATERIAL DESCRIPTION: **Terrazzo (Green) Flooring**

MATERIAL LOCATION: **3rd, 2nd, 1st, and ground floor corridors, stairwells; rooms: 316, 305, 210, 201, 061A, 061D, 059, 041 - 1920's Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M15**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Holes**
MATERIAL LOCATION: **1st floor and ground floor corridors; Rooms: 045, 045A - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M15**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Holes**
MATERIAL LOCATION: **1st floor and ground floor corridors; Rooms: 045, 045A - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M21**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Grooves**

MATERIAL LOCATION: **Rooms: 112, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014B, 011, 002, balcony 006, 1st floor corridors - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M21**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile with Grooves**

MATERIAL LOCATION: **Rooms: 112, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014B, 011, 002, balcony 006, 1st floor corridors - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M24A**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms: 116A, 116B, 104, 103 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M24A**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms: 116A, 116B, 104, 103 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M25A**
MATERIAL DESCRIPTION: **9" x 9" Beige with Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 113 (copy room), 108C (vault) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M25A**
MATERIAL DESCRIPTION: **9" x 9" Beige with Brown Streaks VFT Mastic**
MATERIAL LOCATION: **Rooms 113 (copy room), 108C (vault) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M27**
MATERIAL DESCRIPTION: **9" x 9" Black with Beige and Green Streaks VFT**
MATERIAL LOCATION: **Auditorium (012) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M27**
MATERIAL DESCRIPTION: **9" x 9" Black with Beige and Green Streaks VFT**
MATERIAL LOCATION: **Auditorium (012) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M40**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **JC 106, boys toilet 105, unisex toilet 009 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M40**
MATERIAL DESCRIPTION: **Drywall System**
MATERIAL LOCATION: **JC 106, boys toilet 105, unisex toilet 009 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M42**
MATERIAL DESCRIPTION: **Black Counter Tops**
MATERIAL LOCATION: **Room 101 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M42**
MATERIAL DESCRIPTION: **Black Counter Tops**
MATERIAL LOCATION: **Room 101 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M44**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **Auditorium Stage - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M44**
MATERIAL DESCRIPTION: **Fire Doors**
MATERIAL LOCATION: **Auditorium Stage - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T48**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout Basement**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T48**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **S01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **S01**
MATERIAL DESCRIPTION: **Hard Coat Plaster**
MATERIAL LOCATION: **Throughout 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M05**

MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Rooms: 323, 320, 2nd floor girls toilet, 1st floor boys toilet (122), 1st floor MDF room - 1920 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M05**

MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Rooms: 323, 320, 2nd floor girls toilet, 1st floor boys toilet (122), 1st floor MDF room - 1920 Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M08A**
MATERIAL DESCRIPTION: **12" x 12" White with Beige Specks VFT Mastic**
MATERIAL LOCATION: **Rooms: 310, 309 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M08A**
MATERIAL DESCRIPTION: **12" x 12" White with Beige Specks VFT Mastic**
MATERIAL LOCATION: **Rooms: 310, 309 - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M18**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Rooms: 047, 046 (kitchen) - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M18**
MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**
MATERIAL LOCATION: **Rooms: 047, 046 (kitchen) - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUIDLING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M20**

MATERIAL DESCRIPTION: **Terrazzo (Gray) Flooring**

MATERIAL LOCATION: **Rooms: 106, 053, 052, 034, storage 029, 011, 009, 006, vestibule 002, stairwells A and B, boys toilet (105), 1st floor corridors - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M20**

MATERIAL DESCRIPTION: **Terrazzo (Gray) Flooring**

MATERIAL LOCATION: **Rooms: 106, 053, 052, 034, storage 029, 011, 009, 006, vestibule 002, stairwells A and B, boys toilet (105), 1st floor corridors - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M23A**
MATERIAL DESCRIPTION: **9" x 9" Light Red VFT Mastic**
MATERIAL LOCATION: **Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: REVIEW DATE: **11/25/2019**

ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M23A**

MATERIAL DESCRIPTION: **9" x 9" Light Red VFT Mastic**

MATERIAL LOCATION: **Library (115), Rooms: 117A, 116, 115, 115A, 115B, 115C, 030, 030A, 030C, 030D - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M29**
MATERIAL DESCRIPTION: **9" x 9" Yellow VFT**
MATERIAL LOCATION: **Storage room by balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M29**
MATERIAL DESCRIPTION: **9" x 9" Yellow VFT**
MATERIAL LOCATION: **Storage room by balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M33A**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Lecture Hall 014, Room 051 (ante room) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M33A**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue with Black and Gray Streaks VFT Mastic**
MATERIAL LOCATION: **Lecture Hall 014, Room 051 (ante room) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUIDLING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M34**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Rooms: 116A, 116B, 113, 112, 111, 110, 109, 108, 108A, 108B, 108C, 104, 103, 101, 102, Auditorium and balcony, lobby balcony storage, 057, 053, 052, 051, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014, 014A, 014B, 009, 006, 006 balcony, 005, 004, 003 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

MATERIAL CATEGORY: **MISC** FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M34**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Rooms: 116A, 116B, 113, 112, 111, 110, 109, 108, 108A, 108B, 108C, 104, 103, 101, 102, Auditorium and balcony, lobby balcony storage, 057, 053, 052, 051, 033, 031, 030, 030A, 030C, 030D, 028, 025, 024, 023, 022, 021, 020, 019, 014, 014A, 014B, 009, 006, 006 balcony, 005, 004, 003 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M38**
MATERIAL DESCRIPTION: **Green Terrazzo**
MATERIAL LOCATION: **Room 035 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M38**
MATERIAL DESCRIPTION: **Green Terrazzo**
MATERIAL LOCATION: **Room 035 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M41**
MATERIAL DESCRIPTION: **Vibration Damper Cloth**
MATERIAL LOCATION: **JC 106 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M41**
MATERIAL DESCRIPTION: **Vibration Damper Cloth**
MATERIAL LOCATION: **JC 106 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T47**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**
MATERIAL LOCATION: **Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T47**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Aircell Pipe Insulation**

MATERIAL LOCATION: **Rooms: 117A, 116, 115 (library), 115D, 017 loading dock, auditorium stage - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **T49**
MATERIAL DESCRIPTION: **Mudded Joint Packing on Fiberglass Pipe Insulation**
MATERIAL LOCATION: **Throughout Basement - 1920s Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **TSI** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **T49**

MATERIAL DESCRIPTION: **Mudded Joint Packing on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement - 1920s Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M02**
MATERIAL DESCRIPTION: **Terrazzo (Beige) Flooring**
MATERIAL LOCATION: **Throughout 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M02**
MATERIAL DESCRIPTION: **Terrazzo (Beige) Flooring**
MATERIAL LOCATION: **Throughout 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M04**
MATERIAL DESCRIPTION: **Terrazzo Window Sill**
MATERIAL LOCATION: **Throughout rooms and washrooms - 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M04**
MATERIAL DESCRIPTION: **Terrazzo Window Sill**
MATERIAL LOCATION: **Throughout rooms and washrooms - 1920's Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M11**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rooms: 201, 131, 130, 128, 126, 061A, 061D, 059, 040B - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M11**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rooms: 201, 131, 130, 128, 126, 061A, 061D, 059, 040B - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M17**
MATERIAL DESCRIPTION: **2' x 2' Smooth Ceiling Tile**
MATERIAL LOCATION: **Rooms: 064, 062B, 061A - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M17**
MATERIAL DESCRIPTION: **2' x 2' Smooth Ceiling Tile**
MATERIAL LOCATION: **Rooms: 064, 062B, 061A - 1920s Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M28A**
MATERIAL DESCRIPTION: **9" x 9" Gray with White Spots VFT Mastic**
MATERIAL LOCATION: **Balcony 006 (auditorium lobby) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M28A**

MATERIAL DESCRIPTION: **9" x 9" Gray with White Spots VFT Mastic**

MATERIAL LOCATION: **Balcony 006 (auditorium lobby) - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M33**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue with Black and Gray Specks VFT**
MATERIAL LOCATION: **Lecture Hall 014, Room 051 (ante room) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M33**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue with Black and Gray Specks VFT**
MATERIAL LOCATION: **Lecture Hall 014, Room 051 (ante room) - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Roberto Rivera**
SCHOOL NAME: INSPECTION DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **M30A**
MATERIAL DESCRIPTION: **9" x 9" Brown with Beige Streaks VFT Mastic**
MATERIAL LOCATION: **Lecture Hall 014 - 1958 Addition**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/25/2019

Chicago Public Schools

GSG-Probe Consulting, Inc.
2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66134** BUILDING ID: **55018**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**
SCHOOL NAME: REVIEW DATE: **11/25/2019**
ADDRESS: **7416 Ridge** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **M30A**

MATERIAL DESCRIPTION: **9" x 9" Brown with Beige Streaks VFT Mastic**

MATERIAL LOCATION: **Lecture Hall 014 - 1958 Addition**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____ Date: **11/25/2019**

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-6000 • www.dph.illinois.gov

4/20/2016

ROBERTO RIVERA
855 WEST ADAMS STREET, STE 200
CHICAGO, IL 60607


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 06327	ISSUED 4/20/2016	EXPIRES 05/15/2017	ENDORSEMENTS SUPERVISOR/WORKER INSPECTOR	TC EXPIRES 1/20/2017 1/6/2017
ROBERTO RIVERA 855 WEST ADAMS STREET, ST CHICAGO, IL 60607 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL 1/20/2017	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Roberto Rivera

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/15/2019

Exam Date: 2/15/2019

Expiration Date: 2/15/2020

Certificate Number: BIR1902150525

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ROBERTO RIVERA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 06327

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 06327	ISSUED 4/19/2019	EXPIRES 05/15/2020	SUPERVISOR/WORKER INSPECTOR		2/22/2020 2/15/2020	
ROBERTO RIVERA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL		2/22/2020	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.						

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

2016



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Roberto Rivera

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: BIR1601060030



Kathy DeSalvo, Director

2019



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280695

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/19/2019


ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 07342	ISSUED 4/19/2019	EXPIRES 05/15/2020		INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/28/2020 3/15/2020 2/28/2020 2/22/2020
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed