

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-3006  
SCHOOL NAME: Youth Connection - Olive Harvey Middle College  
High School  
ADDRESS OF SCHOOL: 10001 Woodlawn  
CITY: Chicago, IL, 60628

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 6/24/2016

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 108  
IDPH INSPECTOR LICENSE NUMBER: 100-11070  
IDPH LICENSED INSPECTOR NAME(Please Print): Mallory Jones  
IDPH MP LICENSE NUMBER: 100-00440  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Shawn Brown

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: N

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Youth Connection - Olive Harvey Middle College High School**

10001 Woodlawn  
Chicago, IL, 60628

Unit: 66621  
Building ID: 1121V

IDPH ID Number: 14-016-2990-3006

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 23, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 66621                      Region:                      IDPH ID:14-016-2990-3006

School: Youth Connection - Olive Harvey Middle College High School                      Building ID: 1121V

Address: 10001 Woodlawn

Chicago, IL, 60628

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/22/2019

Inspector: Mallory Jones

Inspector IDPH License: 100-11070

Management Planner: Shawn Brown

Management Planner IDPH License: 100-00440

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

Shawn Brown  
100-00440

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 23, 2019

RE: Youth Connection - Olive Harvey Middle College High School, Unit 66621  
10001 Woodlawn  
Chicago, IL, 60628

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Youth Connection - Olive Harvey Middle College High School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Youth Connection - Olive Harvey Middle College High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Youth Connection - Olive Harvey Middle College High School  
Address: 10001 Woodlawn  
IDPH ID: 14-016-2990-3006  
Contact: Unit: 66621 Chicago, IL, 60628  
Building ID: 1121V  
Phone: Region:

### 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 108

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880 Fax: 630-790-0882

### 5. Inspector

Inspector Name: Mallory Jones

Inspector IDPH license # 100-11070  
Signature:  
Date: 9/23/2019

### 6. Management Planner

Management Planner Name: Shawn Brown

Management Planner IDPH license # 100-00440  
Signature:  
Date: 10/22/2019

### 7. Review Date:10/22/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 10/1/2019  
Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Youth Connection - Olive Harvey Middle College High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1121V:

08	5'x5' Ceiling Panels
10	2'x4' White Ceiling Tile

B. The following new homogenous areas have been identified for Building 1121V:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12x12 White w/Brown Specks Vinyl Floor Tile
01A	12x12 White w/Brown Specks Vinyl Floor Tile Mastic
03	Drywall
04	Drywall Tape/Joint Compound
05	4" Light Brown Baseboard
05A	4" Light Brown Baseboard Mastic
06	4" Dark Brown Baseboard
06A	4" Dark Brown Baseboard Mastic
07	Brown & White Specked Terrazzo
08	5'x5' Ceiling Panels
09	Brown Mosaic Ceramic Tile Grout
09A	Brown Mosaic Ceramic Tile Mastic
10	2'x4' White Ceiling Tile
BB-1	4" Dark Gray Vinyl Baseboard

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Shawn Brown, IDPH License # 100-00440. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Youth Connection - Olive Harvey Middle College High School Building 1121V Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---



# Chicago Public Schools

School Youth Connection - Olive Harvey Middle College High School Unit 66621 Building ID 1121V  
Address 10001 Woodlawn Region

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/23/2019</b>
Inspector Name <b>Mallory Jones</b>
<b>100-11070</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
01	
01A	
02	Removed During Renovation
03	
04	
05	
05A	
06	
06A	
07	
08	Not Observed - 2'x4' Ceiling Tile Observed
09	Not Observed - Epoxy Painted Floor
09A	Not Observed - Epoxy-Painted Floor
10	
BB-1	Building 7 Demolished

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Youth Connection - Olive  
Harvey Middle College  
High School

**Unit** 66621

**Building ID** 1121V

**Address** 10001 Woodlawn

Chicago, IL, 60628

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12x12 White w/Brown Specks Vinyl Floor Tile	8,000	SF	Throughout All Rooms in School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01A	12x12 White w/Brown Specks Vinyl Floor Tile Mastic	8,000	SF	Throughout All Rooms in School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	18"x4' White Pinholed Ceiling Tile ABATED	0		Rooms L104, L105, L109, L111, L112, L113, L114	Abated	MISC					
03	Drywall	7,500	SF	Rooms L104, L105, L109, L110, L111, L112, L113, L114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	Drywall Tape/Joint Compound	7,500	SF	Rooms L104, L105, L109, L110, L111, L112, L113, L114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	4" Light Brown Baseboard	440	LF	L109 - L114	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
05A	4" Light Brown Baseboard Mastic	440	LF	L109 - L114	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06	4" Dark Brown Baseboard	480	LF	L104 and L105	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06A	4" Dark Brown Baseboard Mastic	480	LF	L104 and L105	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
07	Brown & White Specked Terrazzo	3,000	SF	Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	5'x5' Ceiling Panels	3,000	SF	Corridor Ceilings	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Brown Mosaic Ceramic Tile Grout			Men's and Women's Bathrooms	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
09A	Brown Mosaic Ceramic Tile Mastic			Men's and Women's Bathroom	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
10	2'x4' White Ceiling Tile	11,000	SF	All Rooms Throughout School & Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
BB-1	4" Dark Gray Vinyl Baseboard			Building 7- Rooms 7A-7L, 706A, 707, 708	Assumed	MISC					

# Chicago Public Schools

**School** Youth Connection - Olive  
 Harvey Middle College  
 High School  
**Address** 10001 Woodlawn  
**Unit** 66621  
 Chicago, IL, 60628  
**Building ID** 1121V  
**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.  
 174 N. Brandon Drive Glendale Heights, IL, 60139  
 Phone: 630-790-0880 Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/22/2019
Manager Planner Name	Shawn Brown
100-00440	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
02	
03	
04	
05	
05A	
06	
06A	
07	
08	
09	
09A	



# Chicago Public Schools

**School** Youth Connection - Olive  
Harvey Middle College  
High School

**Unit** 66621

**Building ID** 1121V

**Address** 10001 Woodlawn

Chicago, IL, 60628

**Region**

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
10	
BB-1	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66621**    BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School**    INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout All Rooms in School**  
MATERIAL QUANTITY: **8000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **01**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Throughout All Rooms in School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout All Rooms in School**

MATERIAL QUANTITY: **8000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **01A**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout All Rooms in School**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **18"x4' White Pinholed Ceiling Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L104, L105, L109, L111, L112, L113, L114**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Removed During Renovation**

Inspector's Signature: \_\_\_\_\_ Date: **09/23/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **02**  
MATERIAL DESCRIPTION: **18"x4' White Pinholed Ceiling Tile ABATED**  
MATERIAL LOCATION: **Rooms L104, L105, L109, L111, L112, L113, L114**  
MATERIAL QUANTITY: **0** MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**

MATERIAL QUANTITY: **7500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/23/2019



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **03**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66621**    BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School**    INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Drywall Tape/Joint Compound**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**  
MATERIAL QUANTITY: **7500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Drywall Tape/Joint Compound**  
MATERIAL LOCATION: **Rooms L104, L105, L109, L110, L111, L112, L113, L114**  
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66621**    BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School**    INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **4" Light Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **L109 - L114**  
MATERIAL QUANTITY: **440**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **05**  
MATERIAL DESCRIPTION: **4" Light Brown Baseboard**  
MATERIAL LOCATION: **L109 - L114**  
MATERIAL QUANTITY: **440** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **66621**    BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School**    INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn**    IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **4" Light Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **L109 - L114**  
MATERIAL QUANTITY: **440**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **05A**  
MATERIAL DESCRIPTION: **4" Light Brown Baseboard Mastic**  
MATERIAL LOCATION: **L109 - L114**  
MATERIAL QUANTITY: **440** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **4" Dark Brown Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **L104 and L105**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **06**  
MATERIAL DESCRIPTION: **4" Dark Brown Baseboard**  
MATERIAL LOCATION: **L104 and L105**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **4" Dark Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **L104 and L105**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **06A**  
MATERIAL DESCRIPTION: **4" Dark Brown Baseboard Mastic**  
MATERIAL LOCATION: **L104 and L105**  
MATERIAL QUANTITY: **480** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Brown & White Specked Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **07**  
MATERIAL DESCRIPTION: **Brown & White Specked Terrazzo**  
MATERIAL LOCATION: **Corridors**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **5'x5' Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor Ceilings**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed - 2'x4' Ceiling Tile Observed**

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **08**  
MATERIAL DESCRIPTION: **5'x5' Ceiling Panels**  
MATERIAL LOCATION: **Corridor Ceilings**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's and Women's Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed - Epoxy Painted Floor**

Inspector's Signature: \_\_\_\_\_

Date: 09/23/2019



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **09**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **Men's and Women's Bathrooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Men's and Women's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

COMMENTS: **Not Observed - Epoxy-Painted Floor**

Inspector's Signature: \_\_\_\_\_

Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **09A**  
MATERIAL DESCRIPTION: **Brown Mosaic Ceramic Tile Mastic**  
MATERIAL LOCATION: **Men's and Women's Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **All Rooms Throughout School & Corridors**  
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**  
MATERIAL LOCATION: **All Rooms Throughout School & Corridors**  
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/22/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUIDLING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Mallory Jones**  
SCHOOL NAME: **Youth Connection - Olive Harvey  
Middle College High School** INSPECTION DATE: **9/23/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building 7- Rooms 7A-7L, 706A, 707, 708**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Building 7 Demolished**

Inspector's Signature: \_\_\_\_\_ Date: 09/23/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66621** BUILDING ID: **1121V**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Shawn Brown**  
SCHOOL NAME: **Youth Connection -  
Olive Harvey Middle  
College High School** REVIEW DATE: **10/22/2019**  
ADDRESS: **10001 Woodlawn** IDPH LICENSE NO: **100-11070**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard**  
MATERIAL LOCATION: **Building 7- Rooms 7A-7L, 706A, 707, 708**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: 10/22/2019

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*



# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY L. JONES  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR10

Certificate Number:



**PUBLIC HEALTH & SAFETY inc.**

Environmental and Occupational Services  
37 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Penoff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
		SUPERVISOR/WORKER	4/9/2019
		INSPECTOR	3/19/2019
<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>	
100 - 11070	3/6/2019	05/15/2020	
<b>MALLORY JONES</b> 524 HOMELAND ROAD MATTESON, IL 60443		PROJECT MANAGER	4/9/2019
Environmental Health		AIR SAMPLING PROFESSIONAL	
		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/18/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903BIR03

Certificate Number:



**PUBLIC HEALTH & SAFETY** Inc.

Environmental and Occupational Services  
37 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2901

Director of Training

Nicholas J. Penelf

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that SHAWN L. BROWN  
has completed the Asbestos Management Planner Refresher course and passed the examination  
on 03/18/2019 with a minimum score of 70% or better. Training was in accordance with U.S.  
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model  
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

03/18/2019

Course Dates:

03/18/2020

Expires:

1903MPR01

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
371 S. Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081  
Fax: 312-421-2501

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-011

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>	
ID NUMBER	ISSUED	EXPIRES	INSPECTOR	3/19/2019
100 - 02950	3/6/2019	05/15/2020	PROJECT MANAGER	4/9/2019
<b>KEITH CLOUGH</b>			AIR SAMPLING PROFESSIONAL	<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.
524 HOMELAND RD	MATTESON, IL 60443	Environmental Health		

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---



# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed