

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2201
SCHOOL NAME: Fermi School
ADDRESS OF SCHOOL: 1415 E. 70th St.
CITY: Chicago, IL, 60637

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **2/16/2010**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/8/2013 ENROLLMENT 258
IDPH INSPECTOR LICENSE NUMBER: 100-10882
IDPH LICENSED INSPECTOR NAME (Please Print): Beinville Brooks
IDPH MP LICENSE NUMBER: 100-05171
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Stephen Diblik

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



4/8/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Fermi School

1415 E. 70th St.
Chicago, IL, 60637

Unit: 23191
Building ID: 3320

IDPH ID Number: 14-016-2990-2201

REPORT DATE:

Monday, April 08, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

March 18, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23191 Region: 05 IDPH ID: 14-016-2990-2201

School: Fermi School Building ID: 3320

Address: 1415 E. 70th St.

Chicago, IL, 60637

Building Contact: Hickey, John Contact Phone: 3127315649

Current Building Owners: Chicago Public Schools

Review Date: 4/8/2013

Inspector: Beinville Brooks Inspector IDPH License: 100-10882
Management Planner: Stephen Diblik Management Planner IDPH License: 100-05171

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Stephen Diblik
100-05171

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 18, 2013

RE: Fermi School, Unit 23191
1415 E. 70th St.
Chicago, IL, 60637

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Fermi School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Fermi School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Fermi School
Address: 1415 E. 70th St.
IDPH ID: 14-016-2990-2201
Contact: Hickey, John

Unit: 23191
Chicago, IL, 60637
Building ID: 3320
Phone: 3127315649

Region: 05

2. Description of Facility

Original Construction:
Total Square Footage: 76300
Current Occupancy: 258

Additional Construction:
No of Floors:

3. LEA Designated Person

Contact: Ms. Lynn Crivello
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

Phone: (773) 553-3113

4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Beinville Brooks


Inspector IDPH license # 100-10882


Signature:
Date: 3/18/2013

6. Management Planner

Management Planner Name: Stephen Diblik

Management Planner IDPH license # 100-05171


Signature:
Date: 4/8/2013

7. Review Date: 4/8/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 4/8/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Fermi School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3320:

05A	12x12 cream floor tile
14	1x1 ceiling tile mastic
B	mag block water tank
G	preform pipe insulation
H	aircell pipe fittings

B. The following new homogenous areas have been identified for Building 3320:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04D	Mastic for blue carpet
04E	Carpet Mastic
05A	12x12 cream floor tile
FT-1	12x12 beige floor tile
FTM-1	mastic 12x12 beige

The following areas were deemed to be inaccessible:

08A	12x12 cream floor tile mastic
14	1x1 ceiling tile mastic
A	mag block boiler insulation
B	mag block water tank
C	mag block condensation tank insulation
D	mag block expansion tank insulation
E	mag block heat exchanges insulation
F	mag block breeching
FTM-1	mastic 12x12 beige
G	preform pipe insulation
H	aircell pipe fittings
I	fiberglass fittings
J	aircell lagging
K	cardboard lag
L	cardboard runs
M	fitting on preform
N	fittings on fiberglass runs
O	boiler door insulation
P	boiler gasket
Q	vibration dampener cloth

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Beinville Brooks, IDPH License # 100-10882. The Management Plan was updated by Stephen Diblik, IDPH License # 100-05171. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Fermi School Building 3320 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04A	9x9 dk brwn FT	350	SF	1959 building-assistant principal's office	CHR	MISC	N					ACBM with the potential for damage		
04B	9x9 light brown floor tile	3,000	SF	1959 building-kitchen, lunchroom, locker room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04C	9x9 brown floor tile - Partially covered by carpet	20,000	SF	1959-main/principal off,rms 101-108, 110 & adj crdr, rms 200-208 & adj crdr, 2nd flr book rm	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04D	Mastic for blue carpet	350	SF	1959 building - assistant principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04E	Carpet Mastic	400	SF	1959- Main/ Principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	12x12 brown floor tile	2,400	SF	1959 building-lunch room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12x12 cream floor tile	100	SF	1959 dishwashing room	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
06	lab tables	63	SF	room 223	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07A	mastic under 9x9 dark brown floor tile			1959 building-assistant principal's office	ABATED	MISC						ACBM with the potential for damage		
07B	mastic under 9x9 light brown floor tile			1959 building-kitchen, lunchroom, locker room	ABATED	MISC						ACBM with the potential for damage		
07C	9x9 brown floor tile mastic			1959-main/principal off,rms 101-108, 110 & adj crdr, rms 200-208 & adj crdr, 2nd flr book rm	ABATED	MISC		None						Low
08	12x12 brown floor tile mastic	2,400	SF	1959 building-lunch room	NO_ACBM	MISC								
08A	12x12 cream floor tile mastic	100	SF	1959 dishwashing room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09A	9x9 dark brown floor tile	24,800	SF	1966 bldg-all classrooms except room 111, teachers lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09B	9x9 light brown floor tile			1966-all corridors	ABATED	MISC		Unknown						Low
09C	9x9 cream floor tile			1966-room 111	ABATED	MISC								
10	light brown base board	13,000	SF	1959 building-	NO_ACBM	MISC						ACBM with the		

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				classrooms and office area								potential for damage		
11A	mastic under 9x9 dark brown floor tile	24,800	SF	1966 bldg-all classrooms except room 111, teachers lounge	CHR	MISC	N	Unknown						Low
11B	mastic under 9x9 light brown floor tile			1966-corridors	ABATED	MISC								
11C	9x9 cream floor tile mastic			1966-room 111	ABATED	MISC								
12	mastic under light brown base board	13,000	LF	1959-classrooms and office area	NO_ACBM	MISC								
13	1x1 ceiling tile	30,500	SF	1959 building-throughout-classrooms, office area, lunchroom, hallway	NO_ACBM	MISC								
14	1x1 ceiling tile mastic	30,500	SF	1959 building-throughout-classrooms, office area, lunchroom, hallway	CHR	MISC	Y	NONE	0		Yes	ACBM with potential for significant damage		LOW
15	1x1 ceiling tile mastic	34,000	SF	1966-throughout-classrooms, teachers lounge, bathrooms, hallways	NO_ACBM	MISC								
16	lab table mastic	63	SF	1966-room 223	NO_ACBM	MISC								
17	brown base board	3,200	LF	1966-1st & 2nd floor classrooms	NO_ACBM	MISC								
18	mastic under brown baseboard	3,200	SF	1966-1st & 2nd floor classrooms	NO_ACBM	MISC		None						
19	drywall	30,500	SF	1959-above 1x1 ceiling panels	NO_ACBM	MISC								
20	drywall	34,000	SF	1966-above 1x1 ceiling panels	NO_ACBM	MISC								
21	interior window glazing - ABATED			Throughout 1959 building	ABATED	MISC		None						Low
22	window glazing - ABATED			Throughout 1966 building	ABATED	MISC		None						
23	black baseboard	60	LF	room 223	NO_ACBM	MISC								
24	black baseboard mastic			room 223	ABATED	MISC								
25	stairwell tread			1959 stairwells	ABATED	MISC		None						
26	stairwell tread mastic	200	SF	1959 stairwells	NO_ACBM	MISC								
A	mag block boiler insulation	1,500	SF	boiler room	AMO	TSI	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
B	mag block water tank	100	SF	boiler room	CHR	TSI	Y	NONE	0		Yes	ACBM with potential		LOW

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												for significant damage		
C	mag block condensation tank insulation	60	SF	boiler room	AMO	TSI	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
D	mag block expansion tank insulation	75	SF	boiler room	AMO	TSI	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
E	mag block heat exchanges insulation	14	SF	boiler room	AMO	TSI	Y	NONE	0		No	ACBM with potential for significant damage		MODERATE
F	mag block breeching	300	SF	boiler room	AMO	TSI	Y	NONE	0		No	ACBM with potential for significant damage		LOW
FT-1	12x12 beige floor tile	31,000	SF	All classrooms 1st & 2nd floor except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-1	mastic 12x12 beige	31,000	SF	All classrooms 1st and 2nd floors except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G	preform pipe insulation	190	SF	mechanical area	AMO	TSI	Y	NONE	0		Yes	ACBM with potential for significant damage		MODERATE
H	aircell pipe fittings	65	LF	1959-girls/boys toilet room pipe chase, 1st floor above ceiling in corridor	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
I	fiberglass fittings	80	LF	basement-crawlspace 1959	CHR	TSI	Y	UNKNO WN	0		No	ACBM with the potential for damage		LOW
J	aircell lagging	60	LF	1959 pipe chase, 1st & 2nd floor toilet rooms, janitor's closet, 1st floor corridor above ceiling	CHR	TSI	Y	UNKNO WN	0		No	ACBM with the potential for damage		LOW
K	cardboard lag	15	LF	1959 1st & 2nd floor boys and girls restroom pipe chase	CHR	TSI	Y	UNKNO WN	0		No	ACBM with the potential for damage		LOW
L	cardboard runs	12	FITTING	1959 1st and 2nd floor pipe chase boys and girls toilet pipe chase	CHR	TSI	Y	UNKNO WN	0		No	ACBM with the potential for damage		LOW
M	fitting on preform	18	LF	1959 boiler room	CHR	TSI	Y	UNKNO	0		No	ACBM with the		LOW

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
								WN				potential for damage		
N	fittings on fiberglass runs	105	LF	1966 teachers lunchroom above ceiling, crawl space, pipe chase boys and girls	ACT	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	boiler door insulation	12	SF	boiler room	CHR	TSI	Y	UNKNO WN	0		No	ACBM with potential for significant damage		LOW
P	boiler gasket	12	LF	boiler room	CHR	TSI	Y	UNKNO WN	0		No	ACBM with the potential for damage		LOW
Q	vibration dampener cloth	6	SF	boiler room	NO_ACBM	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 3/18/2013
Inspector Name Beinville Brooks
100-10882 5/15/2013
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
04A	Material Not Observed 2013
04B	
04C	
04D	
04E	
05	
05A	
06	
07A	Abated in 2010
07B	Abated in 2010
07C	
08	
08A	
09A	
09B	
09C	
10	
11A	Not Observed.
11B	
11C	
12	
13	
14	
15	

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
A	Patched and Repaired 2012.
B	Patched and Repaired 2012.
C	Patched and Repaired 2012.
D	Patched and Repaired 2012.
E	Patched and Repaired 2012.
F	Patched and Repaired 2012.
FT-1	
FTM-1	
G	
H	Patched and Repaired 2012.
I	
J	Patched and Repaired 2012.
K	Patched and Repaired 2012.
L	Patched and Repaired 2012.
M	Patched and Repaired 2012.
N	
O	Patched and Repaired 2012.
P	

Chicago Public Schools

School Fermi School Unit 23191 Building ID 3320

Address 1415 E. 70th St. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
Q	

Table II

Management Planner's Review

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04A	9x9 dk brwn FT	350	SF	1959 building-assistant principal's office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
04B	9x9 light brown floor tile	3,000	SF	1959 building-kitchen, lunchroom, locker room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04C	9x9 brown floor tile - Partially covered by carpet	20,000	SF	1959-main/principal off,rms 101-108, 110 & adj crdr, rms 200-208 & adj crdr, 2nd flr book rm	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04D	Mastic for blue carpet	350	SF	1959 building - assistant principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
04E	Carpet Mastic	400	SF	1959- Main/ Principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05	12x12 brown floor tile	2,400	SF	1959 building-lunch room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
05A	12x12 cream floor tile	100	SF	1959 dishwashing room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
06	lab tables	63	SF	room 223	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07A	mastic under 9x9 dark brown floor tile			1959 building-assistant principal's office	Abated	MISC				6 ACBM with the potential for damage	
07B	mastic under 9x9 light brown floor tile			1959 building-kitchen, lunchroom, locker room	Abated	MISC				6 ACBM with the potential for damage	
07C	9x9 brown floor tile mastic			1959-main/principal off,rms 101-108, 110 & adj crdr, rms 200-208 & adj crdr, 2nd flr book rm	Abated	MISC					
08	12x12 brown floor tile mastic	2,400	SF	1959 building-lunch room	No ACBM	MISC			SF		
08A	12x12 cream floor tile mastic	100	SF	1959 dishwashing room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09A	9x9 dark brown floor tile	24,800	SF	1966 bldg-all classrooms except room 111, teachers lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09B	9x9 light brown floor tile			1966-all corridors	Abated	MISC					
09C	9x9 cream floor tile			1966-room 111	Abated	MISC					
10	light brown base board	13,000	SF	1959 building-classrooms and office area	No ACBM	MISC			SF	6 ACBM with the potential for damage	
11A	mastic under 9x9 dark brown floor tile	24,800	SF	1966 bldg-all classrooms except room 111, teachers lounge	Chrysotile	MISC	No		SF		
11B	mastic under 9x9 light brown floor tile			1966-corridors	Abated	MISC					
11C	9x9 cream floor tile mastic			1966-room 111	Abated	MISC					
12	mastic under light brown base board	13,000	LF	1959-classrooms and office area	No ACBM	MISC			LF		
13	1x1 ceiling tile	30,500	SF	1959 building-throughout-classrooms, office area, lunchroom, hallway	No ACBM	MISC			SF		
14	1x1 ceiling tile mastic	30,500	SF	1959 building-throughout-classrooms, office area, lunchroom, hallway	Chrysotile	MISC	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
15	1x1 ceiling tile mastic	34,000	SF	1966-throughout-classrooms, teachers	No ACBM	MISC			SF		

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				lounge, bathrooms, hallways							
16	lab table mastic	63	SF	1966-room 223	No ACBM	MISC			SF		
17	brown base board	3,200	LF	1966-1st & 2nd floor classrooms	No ACBM	MISC			LF		
18	mastic under brown baseboard	3,200	SF	1966-1st & 2nd floor classrooms	No ACBM	MISC			SF		
19	drywall	30,500	SF	1959-above 1x1 ceiling panels	No ACBM	MISC			SF		
20	drywall	34,000	SF	1966-above 1x1 ceiling panels	No ACBM	MISC			SF		
21	interior window glazing - ABATED			Throughout 1959 building	Abated	MISC					
22	window glazing - ABATED			Throughout 1966 building	Abated	MISC					
23	black baseboard	60	LF	room 223	No ACBM	MISC			LF		
24	black baseboard mastic			room 223	Abated	MISC					
25	stairwell tread			1959 stairwells	Abated	MISC					
26	stairwell tread mastic	200	SF	1959 stairwells	No ACBM	MISC			SF		
A	mag block boiler insulation	1,500	SF	boiler room	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
B	mag block water tank	100	SF	boiler room	Chrysotile	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
C	mag block condensation tank insulation	60	SF	boiler room	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
D	mag block expansion tank insulation	75	SF	boiler room	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
E	mag block heat exchanges insulation	14	SF	boiler room	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
F	mag block breeching	300	SF	boiler room	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
FT-1	12x12 beige floor tile	31,000	SF	All classrooms 1st & 2nd floor except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
FTM-1	mastic 12x12 beige	31,000	SF	All classrooms 1st and 2nd floors except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
G	preform pipe insulation	190	SF	mechanical area	Amosite	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
H	aircell pipe fittings	65	LF	1959-girls/boys toilet room pipe chase, 1st floor above ceiling in corridor	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
I	fiberglass fittings	80	LF	basement-crawlspace 1959	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
J	aircell lagging	60	LF	1959 pipe chase, 1st & 2nd floor toilet	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
 Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				rooms, janitor's closet, 1st floor corridor above ceiling							
K	cardboard lag	15	LF	1959 1st & 2nd floor boys and girls restroom pipe chase	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
L	cardboard runs	12	FITTING	1959 1st and 2nd floor pipe chase boys and girls toilet pipe chase	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Operations and Maintenance
M	fitting on preform	18	LF	1959 boiler room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
N	fittings on fiberglass runs	105	LF	1966 teachers lunchroom above ceiling, crawl space, pipe chase boys and girls	Actinolite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
O	boiler door insulation	12	SF	boiler room	Chrysotile	TSI	Yes	0	SF	5 ACBM with potential for significant damage	Operations and Maintenance
P	boiler gasket	12	LF	boiler room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
Q	vibration dampener cloth	6	SF	boiler room	No ACBM	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
 Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/8/2013
Manager Planner Name	Stephen Diblik
100-05171	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
04A	Material may be under carpet
04B	
04C	
04D	
04E	
05	
05A	
06	
07A	
07B	
07C	
08	
08A	
09A	
09B	
09C	
10	
11A	Material Not Observed
11B	
11C	
12	
13	

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
 Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
A	Repaired in 2012
B	Repaired in 2012
C	Repaired in 2012
D	Repaired in 2012
E	Repaired in 2012
F	Repaired in 2012
FT-1	
FTM-1	
G	
H	Repaired in 2012
I	
J	Repaired in 2012
K	Repaired in 2012
L	Repaired in 2012

Chicago Public Schools

School Fermi School
Address 1415 E. 70th St.

Unit 23191
Chicago, IL, 60637

Building ID 3320
Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
M	Repaired in 2012
N	Repaired in 2012
O	Repaired in 2012
P	
Q	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **9x9 dk brwn FT**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 building-assistant principal's office**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Not Observed 2013**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **04A**
MATERIAL DESCRIPTION: **9x9 dk brwn FT**
MATERIAL LOCATION: **1959 building-assistant principal's office**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Material may be under carpet

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **9x9 light brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 building-kitchen, lunchroom, locker room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **04B**
MATERIAL DESCRIPTION: **9x9 light brown floor tile**
MATERIAL LOCATION: **1959 building-kitchen, lunchroom, locker room**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **9x9 brown floor tile - Partially covered by carpet**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1959-main/principal off,rms 101-108, 110 & adj crrdr, rms 200-208 & adj crrdr, 2nd flr book rm**

MATERIAL QUANTITY: **20000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **04C**
MATERIAL DESCRIPTION: **9x9 brown floor tile - Partially covered by carpet**
MATERIAL LOCATION: **1959-main/principal off,rms 101-108, 110 & adj crrdr, rms 200-208 & adj crrdr, 2nd flr book rm**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **Mastic for blue carpet**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 building - assistant principal's office**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **04D**
MATERIAL DESCRIPTION: **Mastic for blue carpet**
MATERIAL LOCATION: **1959 building - assistant principal's office**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1959- Main/ Principal's office**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **04E**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **1959- Main/ Principal's office**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 building-lunch room**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **12x12 brown floor tile**
MATERIAL LOCATION: **1959 building-lunch room**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 cream floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 dishwashing room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **05A**
MATERIAL DESCRIPTION: **12x12 cream floor tile**
MATERIAL LOCATION: **1959 dishwashing room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **lab tables**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **room 223**
MATERIAL QUANTITY: **63** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **lab tables**

MATERIAL LOCATION: **room 223**

MATERIAL QUANTITY: **63**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **mastic under 9x9 dark brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1959 building-assistant principal's office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated in 2010**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **07A**
MATERIAL DESCRIPTION: **mastic under 9x9 dark brown floor tile**
MATERIAL LOCATION: **1959 building-assistant principal's office**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **mastic under 9x9 light brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 building-kitchen, lunchroom, locker room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Abated in 2010**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **07B**
MATERIAL DESCRIPTION: **mastic under 9x9 light brown floor tile**
MATERIAL LOCATION: **1959 building-kitchen, lunchroom, locker room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **9x9 brown floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1959-main/principal off,rms 101-108, 110 & adj crrdr, rms 200-208 & adj crrdr, 2nd flr book rm**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **07C**
MATERIAL DESCRIPTION: **9x9 brown floor tile mastic**
MATERIAL LOCATION: **1959-main/principal off,rms 101-108, 110 & adj crrdr, rms 200-208 & adj crrdr, 2nd flr book rm**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 building-lunch room**

MATERIAL QUANTITY: **2400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12x12 brown floor tile mastic**
MATERIAL LOCATION: **1959 building-lunch room**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12x12 cream floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 dishwashing room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12x12 cream floor tile mastic**
MATERIAL LOCATION: **1959 dishwashing room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **9x9 dark brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 bldg-all classrooms except room 111, teachers lounge**
MATERIAL QUANTITY: **24800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **09A**
MATERIAL DESCRIPTION: **9x9 dark brown floor tile**
MATERIAL LOCATION: **1966 bldg-all classrooms except room 111, teachers lounge**
MATERIAL QUANTITY: **24800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09B**
MATERIAL DESCRIPTION: **9x9 light brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1966-all corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **09B**

MATERIAL DESCRIPTION: **9x9 light brown floor tile**

MATERIAL LOCATION: **1966-all corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09C**
MATERIAL DESCRIPTION: **9x9 cream floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-room 111**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **09C**

MATERIAL DESCRIPTION: **9x9 cream floor tile**

MATERIAL LOCATION: **1966-room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **light brown base board**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 building-classrooms and office area**

MATERIAL QUANTITY: **13000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **light brown base board**
MATERIAL LOCATION: **1959 building-classrooms and office area**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **mastic under 9x9 dark brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **1966 bldg-all classrooms except room 111, teachers lounge**

MATERIAL QUANTITY: **24800**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **mastic under 9x9 dark brown floor tile**
MATERIAL LOCATION: **1966 bldg-all classrooms except room 111, teachers lounge**
MATERIAL QUANTITY: **24800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Material Not Observed

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **mastic under 9x9 light brown floor tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-corridors**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **11B**

MATERIAL DESCRIPTION: **mastic under 9x9 light brown floor tile**

MATERIAL LOCATION: **1966-corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **9x9 cream floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **9x9 cream floor tile mastic**
MATERIAL LOCATION: **1966-room 111**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **mastic under light brown base board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959-classrooms and office area**

MATERIAL QUANTITY: **13000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **mastic under light brown base board**
MATERIAL LOCATION: **1959-classrooms and office area**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **1x1 ceiling tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 building-throughout-classrooms, office area, lunchroom, hallway**

MATERIAL QUANTITY: **30500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUILDING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **1x1 ceiling tile**
MATERIAL LOCATION: **1959 building-throughout-classrooms, office area, lunchroom, hallway**
MATERIAL QUANTITY: **30500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **1x1 ceiling tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 building-throughout-classrooms, office area, lunchroom, hallway**
MATERIAL QUANTITY: **30500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **1x1 ceiling tile mastic**
MATERIAL LOCATION: **1959 building-throughout-classrooms, office area, lunchroom, hallway**
MATERIAL QUANTITY: **30500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **1x1 ceiling tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-throughout-classrooms, teachers lounge, bathrooms, hallways**

MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **1x1 ceiling tile mastic**
MATERIAL LOCATION: **1966-throughout-classrooms, teachers lounge, bathrooms, hallways**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **lab table mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-room 223**

MATERIAL QUANTITY: **63**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **lab table mastic**

MATERIAL LOCATION: **1966-room 223**

MATERIAL QUANTITY: **63**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **brown base board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-1st & 2nd floor classrooms**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **brown base board**
MATERIAL LOCATION: **1966-1st & 2nd floor classrooms**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **mastic under brown baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-1st & 2nd floor classrooms**

MATERIAL QUANTITY: **3200**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **mastic under brown baseboard**
MATERIAL LOCATION: **1966-1st & 2nd floor classrooms**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959-above 1x1 ceiling panels**

MATERIAL QUANTITY: **30500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **drywall**
MATERIAL LOCATION: **1959-above 1x1 ceiling panels**
MATERIAL QUANTITY: **30500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **drywall**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966-above 1x1 ceiling panels**

MATERIAL QUANTITY: **34000**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **drywall**
MATERIAL LOCATION: **1966-above 1x1 ceiling panels**
MATERIAL QUANTITY: **34000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **interior window glazing - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Throughout 1959 building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **interior window glazing - ABATED**

MATERIAL LOCATION: **Throughout 1959 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **window glazing - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1966 building**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **window glazing - ABATED**

MATERIAL LOCATION: **Throughout 1966 building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 223**

MATERIAL QUANTITY: **60**


MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **black baseboard**

MATERIAL LOCATION: **room 223**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **room 223**

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **black baseboard mastic**

MATERIAL LOCATION: **room 223**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **stairwell tread**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **See Comments**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 stairwells**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **stairwell tread**

MATERIAL LOCATION: **1959 stairwells**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

See Comments

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **stairwell tread mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 stairwells**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **stairwell tread mastic**
MATERIAL LOCATION: **1959 stairwells**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **mag block boiler insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **mag block boiler insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **mag block water tank**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **mag block water tank**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **mag block condensation tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **mag block condensation tank insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **mag block expansion tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **mag block expansion tank insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **mag block heat exchanges insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **14**


MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **mag block heat exchanges insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **mag block breeching**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **mag block breaching**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All classrooms 1st & 2nd floor except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors**

MATERIAL QUANTITY: **31000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **FT-1**
MATERIAL DESCRIPTION: **12x12 beige floor tile**
MATERIAL LOCATION: **All classrooms 1st & 2nd floor except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors**
MATERIAL QUANTITY: **31000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **mastic 12x12 beige**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All classrooms 1st and 2nd floors except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors**

MATERIAL QUANTITY: **31000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **FTM-1**
MATERIAL DESCRIPTION: **mastic 12x12 beige**
MATERIAL LOCATION: **All classrooms 1st and 2nd floors except 207, 215, 218, 220, main office, all corridors on 1st and 2nd floors**
MATERIAL QUANTITY: **31000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature:

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **preform pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **mechanical area**

MATERIAL QUANTITY: **190**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **preform pipe insulation**
MATERIAL LOCATION: **mechanical area**
MATERIAL QUANTITY: **190** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **aircell pipe fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959-girls/boys toilet room pipe chase, 1st floor above ceiling in corridor**
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **aircell pipe fittings**
MATERIAL LOCATION: **1959-girls/boys toilet room pipe chase, 1st floor above ceiling in corridor**
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **fiberglass fittings**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **basement-crawlspace 1959**

MATERIAL QUANTITY: **80**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **I**
MATERIAL DESCRIPTION: **fiberglass fittings**
MATERIAL LOCATION: **basement-crawlspace 1959**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **aircell lagging**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1959 pipe chase, 1st & 2nd floor toilet rooms, janitor's closet, 1st floor corridor above ceiling**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **J**
MATERIAL DESCRIPTION: **aircell lagging**
MATERIAL LOCATION: **1959 pipe chase, 1st & 2nd floor toilet rooms, janitor's closet, 1st floor corridor above ceiling**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **cardboard lag**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 1st & 2nd floor boys and girls restroom pipe chase**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **K**
MATERIAL DESCRIPTION: **cardboard lag**
MATERIAL LOCATION: **1959 1st & 2nd floor boys and girls restroom pipe chase**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **cardboard runs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 1st and 2nd floor pipe chase boys and girls toilet pipe chase**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: DAMAGE UNITS: **FITTING**
COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **cardboard runs**
MATERIAL LOCATION: **1959 1st and 2nd floor pipe chase boys and girls toilet pipe chase**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **FITTING**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **fitting on preform**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1959 boiler room**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **fitting on preform**
MATERIAL LOCATION: **1959 boiler room**
MATERIAL QUANTITY: **18** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **fittings on fiberglass runs**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Actinolite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1966 teachers lunchroom above ceiling, crawl space, pipe chase boys and girls**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **fittings on fiberglass runs**
MATERIAL LOCATION: **1966 teachers lunchroom above ceiling, crawl space, pipe chase boys and girls**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **boiler door insulation**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Patched and Repaired 2012.**

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **boiler door insulation**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Repaired in 2012

Management Planner's Signature: _____

Stephen Diblik

Date: 04/08/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **boiler gasket**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **boiler gasket**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Beinville Brooks**
SCHOOL NAME: **Fermi School** INSPECTION DATE: **3/18/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **vibration dampener cloth**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **No ACBM** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **boiler room**

MATERIAL QUANTITY: **6**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 03/18/2013

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23191** BUIDLING ID: **3320**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Stephen Diblik**
SCHOOL NAME: **Fermi School** REVIEW DATE: **4/8/2013**
ADDRESS: **1415 E. 70th St.** IDPH LICENSE NO: **100-10882**

HOMOGENEOUS AREA: **Q**
MATERIAL DESCRIPTION: **vibration dampener cloth**
MATERIAL LOCATION: **boiler room**
MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____

Stephen Diblik

Date: **04/08/2013**


Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Abatement Contractor/Supervisor Refresher/Project Supervisor Refresher

Occupational Training and Supply, Inc. certifies that

Beinville Brooks


has successfully completed the 8 hour Asbestos Contractor/Supervisor Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: ASR1205070842


Exam Date: 5/7/2012

Course Date: 5/7/2012

Expiration Date: 5/7/2013


Kathy Desaino, Director

2012



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER **ISSUED** **EXPIRES**
100 - 10682 2/15/2012 05/15/2012

BEINVILLE S BROOKS
PO BOX 1373
CALUMET, IL 60409

Environmental Health



ENDORSEMENTS
SUPERVISOR/WORKER
INSPECTOR

TC EXPIRES
5/9/2012
12/1/2012

PROJECT MANAGER 5/9/2012
AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Steve Diblik

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the **Illinois Department of Public Health** and the **Indiana Department of Environmental Management** for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin **Department of Health Services** under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1301110170

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 1/11/2013

Examination Date: 1/11/2013

Expiration Date: 1/11/2014

Issue Date: 1/11/2013



Duplicate Original

Kathy DeSalvo, Director

2013

Stephen Diblik

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager and Air Sampling Professional



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 05171

ISSUED
4/4/2012

EXPIRES
05/15/2013

STEPHEN C DIBLIK
300 W. Adams Street, Suite 120
Chicago, IL 60606

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

1/13/2013

MANAGEMENT PLANNER

1/19/2013

PROJECT MANAGER

12/15/2012

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Stephen Diblik

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250732

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo
Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed