

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 15-016-2990-AE12
SCHOOL NAME: Chicago International Charter - Loomis Primary
ADDRESS OF SCHOOL: 9535 South Loomis Street
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 2/6/2010

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/15/2013 ENROLLMENT 565
IDPH INSPECTOR LICENSE NUMBER: 100-19038
IDPH LICENSED INSPECTOR NAME (Please Print): Eric Valadez
IDPH MP LICENSE NUMBER: 100-01786
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Guillermo Garcia

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



5/15/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Chicago International Charter - Loomis Primary

9535 South Loomis Street
Chicago, IL, 60643

Unit: 66075
Building ID: 4914

IDPH ID Number: 15-016-2990-AE12

REPORT DATE:

Wednesday, May 15, 2013

Prepared for:

Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:

GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone (312) 733-6262

Fax (312) 733-5612

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

April 5, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

GSG Consultants, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1,2,6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66075 Region: IDPH ID: 15-016-2990-AE12

School: Chicago International Charter - Loomis Primary Building ID: 4914

Address: 9535 South Loomis Street
Chicago, IL, 60643

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 5/15/2013

Inspector: Eric Valadez Inspector IDPH License: 100-19038
Management Planner: Guillermo Garcia Management Planner IDPH License: 100-01786

If you have any questions or comments, please contact us at (312) 733-6262

Sincerely,
GSG Consultants, Inc.



Guillermo Garcia
100-01786

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 05, 2013

RE: Chicago International Charter - Loomis Primary, Unit 66075
9535 South Loomis Street
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at Chicago International Charter - Loomis Primary , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Chicago International Charter - Loomis Primary, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Chicago International Charter - Loomis Primary Unit: 66075 Region:
Address: 9535 South Loomis Street Chicago, IL, 60643
IDPH ID: 15-016-2990-AE12 Building ID: 4914
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 565

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603


4. Managing Environmental Consultant

MEC: GSG Consultants, Inc.
Contact: Arturo Saenz
Address 855 W. Adams St., Ste. 200
Phone: (312) 733-6262 Fax: (312) 733-5612

5. Inspector

Inspector Name: Eric Valadez


Inspector IDPH license # 100-19038

Signature: 
Date: 4/5/2013

6. Management Planner

Management Planner Name: Guillermo Garcia

Management Planner IDPH license # 100-01786

Signature: 
Date: 5/15/2013

7. Review Date: 5/15/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 5/15/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

GSG Consultants, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago International Charter - Loomis Primary. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4914:

B. The following new homogenous areas have been identified for Building 4914:

11	12 x 12 VFT Purple Mixed Speckled
12	12 x 12 VFT Orange Mixed Speckled
12M	12 x 12 Purple Mixed Speckled Mastic
13	12 x 12 Mastic Orange Mixed Speckled
14	12 x 12 VFT Blue Mixed Speckled
15	12 x 12 Mastic Blue Mixed Speckled
16	12 x 12 VFT Red Mixed Speckled
17	12 x 12 Mastic Red Mixed Speckled
18	12 X 12 VFT Green Mixed Speckled
19	12 x 12 Green Mixed Speckled Mastic
20	12 x 12 VFT Yellow Mixed Speckled
21	12 x 12 Mastic Yellow Mixed Speckled
22	12 x 12 VFT Tan Mixed Speckled
23	12 x 12 Mastic Tan Mixed Speckled
24	2 x 2 CT White
25	Carpet Mastic
26	2 x 4 CT Smooth White

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12"x12" Light Brown Mix Floor Tile Patterns
02	Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns
03	4" Light Brown Baseboard
04	4" Light Brown Baseboard Adhesive
05	2'x4' Lay In Ceiling Panels
06	Brown and Black Carpet Adhesive
07	Ceramic Floor Tile Grout
08	Ceramic Floor Tile Adhesive
09	Terrazzo
10	Whiteboard Adhesive
11	12 x 12 VFT Purple Mixed Speckled
12	12 x 12 VFT Orange Mixed Speckled
12M	12 x 12 Purple Mixed Speckled Mastic
13	12 x 12 Mastic Orange Mixed Speckled
14	12 x 12 VFT Blue Mixed Speckled
15	12 x 12 Mastic Blue Mixed Speckled
16	12 x 12 VFT Red Mixed Speckled
17	12 x 12 Mastic Red Mixed Speckled
18	12 X 12 VFT Green Mixed Speckled
19	12 x 12 Green Mixed Speckled Mastic
20	12 x 12 VFT Yellow Mixed Speckled
21	12 x 12 Mastic Yellow Mixed Speckled
22	12 x 12 VFT Tan Mixed Speckled
23	12 x 12 Mastic Tan Mixed Speckled
24	2 x 2 CT White
25	Carpet Mastic
26	2 x 4 CT Smooth White
MCA	Metal Pan Ceiling - REMOVED
MCB	Metal Pan Ceiling - REMOVED
MCC	1'x1' Fissured Ceiling Tile and Mastic
MMB (1)	Blackboards - ABATED
MMD	Black Baseboard (Removed)
MME	Black Baseboard Adhesive (Removed)
MMF	Gray Baseboard - Removed
MMG	Gray Baseboard Adhesive - Removed
MMJ	Beige Baseboard - Removed
MMK	Beige Baseboard Adhesive - Removed
MMM	Vibration Dampers
MMN	Terrazzo - ABATED
MMO	Brown Carpet Adhesive - Removed
MMS (1)	Insulation in Fire Doors
MMT	Floor Filler
MMU	Elevator Brake Shoes

MMV (1)	Fire Brick in Boilers
MXA	Drywall
MXB	Drywall Compound
SFA	Soundproofing
SPA	Wall Plaster
SPB	Ceiling Plaster
TJD	White Tar Wrap
TPA	Fiberglass Pipe Insulation on Domestic Water Pipes
TPB	Fiberglass Insulation on Mechanical Pipes

The following areas were deemed to be inaccessible:

04	4" Light Brown Baseboard Adhesive
05	2'x4' Lay In Ceiling Panels
06	Brown and Black Carpet Adhesive
08	Ceramic Floor Tile Adhesive
10	Whiteboard Adhesive
MMD	Black Baseboard (Removed)
MMT	Floor Filler
MMU	Elevator Brake Shoes
MXB	Drywall Compound
SFA	Soundproofing
TJB	Joint Insulation on Fiberglass Insulated Mechanical Pipes

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Eric Valadez, IDPH License # 100-19038. The Management Plan was updated by Guillermo Garcia, IDPH License # 100-01786. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Chicago International Charter - Loomis Primary Building 4914 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914

Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" Light Brown Mix Floor Tile Patterns	37,800	SF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns	37,800	SF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	4" Light Brown Baseboard	3,800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04	4" Light Brown Baseboard Adhesive	3,800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	2'x4' Lay In Ceiling Panels	40,472	SF	Throughout Building with the Exception of Mechanical Areas	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
06	Brown and Black Carpet Adhesive	1,080	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07	Ceramic Floor Tile Grout	2,672	SF	Washrooms Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Ceramic Floor Tile Adhesive	2,672	SF	Washrooms Throughout Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Terrazzo	1,100	SF	Stairways and First Floor Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Whiteboard Adhesive	2,200	SF	Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12 x 12 VFT Purple Mixed Speckled	600	SF	Rms. 309, 212, 201, 122, 113 and 100, 3rd, 2nd, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12 x 12 VFT Orange Mixed Speckled	1,050	SF	3rd, 2nd, 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914

Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridor Rm 095 and LunchRoom								potential for damage		
12M	12 x 12 Purple Mixed Speckled Mastic	600	SF	Rms 309, 212, 201, 122, 113 and 100, 3rd, 2nd and 1st Flr Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12 x 12 Mastic Orange Mixed Speckled	1,050	SF	3rd, 2nd, 1st Floor Corridor Rm 095 and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12 x 12 VFT Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12 x 12 Mastic Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12 x 12 VFT Red Mixed Speckled	600	SF	Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No			LOW
17	12 x 12 Mastic Red Mixed Speckled	600	SF	Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		
18	12 X 12 VFT Green Mixed Speckled	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	12 x 12 Green Mixed Speckled Mastic	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12 x 12 VFT Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12 x 12 Mastic Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12 x 12 VFT Tan Mixed Speckled	2,100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12 x 12 Mastic Tan Mixed Speckled	2,100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914
 Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
24	2 x 2 CT White	5,000	SF	3rd, 2nd, 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Carpet Mastic	700	SF	Rm 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2 x 4 CT Smooth White	500	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MCA	Metal Pan Ceiling - REMOVED			Throughout Building	ASSUMED	MISC	N				No			
MCB	Metal Pan Ceiling - REMOVED			Throughout Building	ASSUMED	MISC	N				No			
MCC	1'x1' Fissured Ceiling Tile and Mastic	23,000	SF	Throughout Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
MFA	9"x9" Floor Tile - ABATED		SF	Throughout Building	CHR	MISC	N				No			
MFB	12"x12" Floor Tile - ABATED		SF	Throughout Building	CHR	MISC	N				No			
MM1	Baseboard Mastic - ABATED		LF	Throughout Building	CHR	MISC	N				No			
MMA	9"x9" Floor Tile Mastic - ABATED		SF	Throughout Building	CHR	MISC	N				No			
MMB	12"x12" Floor Tile Mastic - ABATED		SF	Throughout Building	CHR	MISC	N				No			
MMB (1)	Blackboards - ABATED		SF	Classrooms	ASSUMED	MISC	N				No			
MMC	Residual Mastic - ABATED		SF	Throughout Building	CHR	MISC	N				No			
MMD	Black Baseboard (Removed)			Throughout Building	ASSUMED	MISC					No			
MME	Black Baseboard Adhesive (Removed)			Throughout Facility	ASSUMED						No			
MMF	Gray Baseboard - Removed			Throughout Building	ASSUMED	MISC					No			
MMG	Gray Baseboard Adhesive - Removed			Throughout Building	ASSUMED	MISC					No			
MMH	Brown Baseboard - ABATED		LF	Throughout Building	CHR	MISC					No			
MMJ	Beige Baseboard - Removed			Throughout Facility	ASSUMED	MISC					No			
MMK	Beige Baseboard Adhesive - Removed			Throughout Building	ASSUMED	MISC					No			
MML	Terrazzo Mastic - ABATED			Stairways	ABATED	MISC					No			
MMM	Vibration Dampers	15	SF	Mechanical Room	ASSUMED	MISC		NONE	0		No	ACBM with the potential for damage		LOW
MMN	Terrazzo - ABATED			Stairways	ASSUMED	MISC					No			
MMO	Brown Carpet Adhesive - Removed			Throughout Building	ASSUMED	MISC					No			

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914

Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
MMQ	Soundproof Panels - ABATED				ABATED	MISC					No			
MMS (1)	Insulation in Fire Doors	288	SF	Entrances	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
MMT	Floor Filler	23,000	SF	Throughout Building	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
MMU	Elevator Brake Shoes	10	SF	Ground Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MMV	Incinerator Bricks	50	SF	Incinerator	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MMV (1)	Fire Brick in Boilers	200	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MXA	Drywall	46,000	SF	Throughout Building	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
MXB	Drywall Compound	12,000	SF	Throughout Building	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
SFA	Soundproofing	40,000	SF	Throughout Building	ASSUMED	SURFACE					No	ACBM with the potential for damage		LOW
SPA	Wall Plaster			Throughout Building	ASSUMED	SURFACE	N				No			
SPB	Ceiling Plaster	38,000	SF	Throughout Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
SPC	Popcorn Ceiling - ABATED		SF	Chapel	CHR	SURFACE	N				No			
SPC (1)	Popcorn Ceiling - ABATED			Chapel	CHR	MISC					No			
TBA	Insulation on East Boiler	250	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
TBB	Insulation on West Boiler	250	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
TGA	Boiler Gaskets	50	LF	Boiler Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
TJA	Joint Insulation on Fiberglass Insulated Domestic Water Pipes	10	LF	Boiler Room and Tunnel from Aquinus Building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
TJB	Joint Insulation on Fiberglass Insulated Mechanical Pipes	22	LF	Boiler Room, Mechanical Room and Tunnel from Aquinus Building	CHR	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
TJC	Black Tar Wrap	25	LF	Boiler Room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
TJD	White Tar Wrap	40	SF	Boiler Room	ASSUMED	TSI					No	ACBM with the potential for damage		LOW
TPA	Fiberglass Pipe Insulation on Domestic Water Pipes	450	LF	Throughout Building Including: Boiler Room,	ASSUMED	TSI	Y				No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914

Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Mechanical Room, Tunnel to Aquinus Building and Pipe Chases										
TPB	Fiberglass Insulation on Mechanical Pipes	325	LF	Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases	ASSUMED	TSI	Y				No	ACBM with the potential for damage		MODERATE
TTA	Insulation on Tank	150	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
TTD	Duct Insulation	500	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914
Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 4/5/2013
Inspector Name Eric Valadez
100-19038 5/15/2014
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
11	No Drawing
12	No Drawing
12M	No Drawing
13	No Drawing
14	No Drawing
15	No Drawing
16	No Drawing
17	No Drawing
18	No Drawing
19	No Drawing
20	No Drawing
21	No Drawing
22	No Drawing
23	No Drawing

Chicago Public Schools

School Chicago International Charter - Loomis Primary Unit 66075 Building ID 4914

Address 9535 South Loomis Street Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
24	No Drawing
25	No Drawing
26	
MCA	
MCB	
MCC	
MFA	
MFB	
MM1	
MMA	
MMB	
MMB (1)	
MMC	
MMD	
MME	
MMF	
MMG	
MMH	
MMJ	
MMK	
MML	
MMM	
MMN	
MMO	
MMQ	
MMS (1)	
MMT	
MMU	
MMV	

Chicago Public Schools

School Chicago International Charter - Loomis Primary **Unit** 66075 **Building ID** 4914
Address 9535 South Loomis Street **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262 Fax: (312) 733-5612

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
MMV (1)	
MXA	
MXB	
SFA	
SPA	
SPB	
SPC	
SPC (1)	
TBA	
TBB	
TGA	
TJA	
TJB	
TJC	
TJD	
TPA	
TPB	
TTA	
TTD	

Table II

Management Planner's Review

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" Light Brown Mix Floor Tile Patterns	37,800	SF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
02	Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns	37,800	SF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
03	4" Light Brown Baseboard	3,800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
04	4" Light Brown Baseboard Adhesive	3,800	LF	Throughout Building with the exception of the washrooms, kitchen and mechanical rooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
05	2'x4' Lay In Ceiling Panels	40,472	SF	Throughout Building with the Exception of Mechanical Areas	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
06	Brown and Black Carpet Adhesive	1,080	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
07	Ceramic Floor Tile Grout	2,672	SF	Washrooms Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
08	Ceramic Floor Tile Adhesive	2,672	SF	Washrooms Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
09	Terrazzo	1,100	SF	Stairways and First Floor Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
10	Whiteboard Adhesive	2,200	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
11	12 x 12 VFT Purple Mixed Speckled	600	SF	Rms. 309, 212, 201, 122, 113 and 100. 3rd, 2nd, and 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
12	12 x 12 VFT Orange Mixed Speckled	1,050	SF	3rd, 2nd, 1st Floor Corridor Rm 095 and LunchRoom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
12M	12 x 12 Purple Mixed Speckled Mastic	600	SF	Rms 309, 212, 201, 122, 113 and 100. 3rd, 2nd and 1st Flr Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
13	12 x 12 Mastic Orange Mixed Speckled	1,050	SF	3rd, 2nd, 1st Floor Corridor Rm 095 and Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
14	12 x 12 VFT Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
15	12 x 12 Mastic Blue Mixed Speckled	350	SF	Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
16	12 x 12 VFT Red Mixed Speckled	600	SF	Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF		Operations and Maintenance
17	12 x 12 Mastic Red Mixed Speckled	600	SF	Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18	12 X 12 VFT Green Mixed Speckled	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
19	12 x 12 Green Mixed Speckled Mastic	600	SF	Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
20	12 x 12 VFT Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
21	12 x 12 Mastic Yellow Mixed Speckled	600	SF	Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
22	12 x 12 VFT Tan Mixed Speckled	2,100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
23	12 x 12 Mastic Tan Mixed Speckled	2,100	SF	Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
24	2 x 2 CT White	5,000	SF	3rd, 2nd, 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
25	Carpet Mastic	700	SF	Rm 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
26	2 x 4 CT Smooth White	500	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
MCA	Metal Pan Ceiling - REMOVED			Throughout Building	Assumed	MISC	No				
MCB	Metal Pan Ceiling - REMOVED			Throughout Building	Assumed	MISC	No				
MCC	1'x1' Fissured Ceiling Tile and Mastic	23,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
MFA	9"x9" Floor Tile - ABATED		SF	Throughout Building	Chrysotile	MISC	No		SF		
MFB	12"x12" Floor Tile - ABATED		SF	Throughout Building	Chrysotile	MISC	No		SF		
MM1	Baseboard Mastic - ABATED		LF	Throughout Building	Chrysotile	MISC	No		LF		
MMA	9"x9" Floor Tile Mastic - ABATED		SF	Throughout Building	Chrysotile	MISC	No		SF		
MMB	12"x12" Floor Tile Mastic - ABATED		SF	Throughout Building	Chrysotile	MISC	No		SF		
MMB (1)	Blackboards - ABATED		SF	Classrooms	Assumed	MISC	No		SF		
MMC	Residual Mastic - ABATED		SF	Throughout Building	Chrysotile	MISC	No		SF		
MMD	Black Baseboard (Removed)			Throughout Building	Assumed	MISC					Operations and Maintenance
MME	Black Baseboard Adhesive (Removed)			Throughout Facility	Assumed						Operations and Maintenance
MMF	Gray Baseboard - Removed			Throughout Building	Assumed	MISC					
MMG	Gray Baseboard Adhesive - Removed			Throughout Building	Assumed	MISC					
MMH	Brown Baseboard - ABATED		LF	Throughout Building	Chrysotile	MISC			LF		
MMJ	Beige Baseboard - Removed			Throughout Facility	Assumed	MISC					
MMK	Beige Baseboard Adhesive - Removed			Throughout Building	Assumed	MISC					
MML	Terrazzo Mastic - ABATED			Stairways	Abated	MISC					

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
MMM	Vibration Dampers	15	SF	Mechanical Room	Assumed	MISC		0	SF	6 ACBM with the potential for damage	Operations and Maintenance
MMN	Terrazzo - ABATED			Stairways	Assumed	MISC					
MMO	Brown Carpet Adhesive - Removed			Throughout Building	Assumed	MISC					
MMQ	Soundproof Panels - ABATED				Abated	MISC					
MMS (1)	Insulation in Fire Doors	288	SF	Entrances	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Operations and Maintenance
MMT	Floor Filler	23,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
MMU	Elevator Brake Shoes	10	SF	Ground Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
MMV	Incinerator Bricks	50	SF	Incinerator	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
MMV (1)	Fire Brick in Boilers	200	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
MXA	Drywall	46,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
MXB	Drywall Compound	12,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Operations and Maintenance
SFA	Soundproofing	40,000	SF	Throughout Building	Assumed	SURFACE			SF	6 ACBM with the potential for damage	Operations and Maintenance
SPA	Wall Plaster			Throughout Building	Assumed	SURFACE	No				Operations and Maintenance
SPB	Ceiling Plaster	38,000	SF	Throughout Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
SPC	Popcorn Ceiling - ABATED		SF	Chapel	Chrysotile	SURFACE	No		SF		Operations and Maintenance
SPC (1)	Popcorn Ceiling - ABATED			Chapel	Chrysotile	MISC					
TBA	Insulation on East Boiler	250	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
TBB	Insulation on West Boiler	250	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance
TGA	Boiler Gaskets	50	LF	Boiler Room	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
TJA	Joint Insulation on Fiberglass Insulated Domestic Water Pipes	10	LF	Boiler Room and Tunnel from Aquinus Building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
TJB	Joint Insulation on Fiberglass Insulated Mechanical Pipes	22	LF	Boiler Room, Mechanical Room and Tunnel from Aquinus Building	Chrysotile	MISC	Yes	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
TJC	Black Tar Wrap	25	LF	Boiler Room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Operations and Maintenance
TJD	White Tar Wrap	40	SF	Boiler Room	Assumed	TSI			SF	6 ACBM with the potential for damage	Operations and Maintenance
TPA	Fiberglass Pipe Insulation on Domestic Water Pipes	450	LF	Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases	Assumed	TSI	Yes		LF	6 ACBM with the potential for damage	Operations and Maintenance
TPB	Fiberglass Insulation on Mechanical Pipes	325	LF	Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases	Assumed	TSI	Yes		LF	6 ACBM with the potential for damage	Operations and Maintenance
TTA	Insulation on Tank	150	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
TTD	Duct Insulation	500	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Operations and Maintenance

Review Date	5/15/2013
Manager Planner Name	Guillermo Garcia

HA Number	Management Comments
01	
02	

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

100-01786	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06	
07	
08	
09	
10	
11	
12	
12M	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
MCA	

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
MCB	
MCC	
MFA	
MFB	
MM1	
MMA	
MMB	
MMB (1)	
MMC	
MMD	
MME	
MMF	
MMG	
MMH	
MMJ	
MMK	
MML	
MMM	
MMN	
MMO	
MMQ	
MMS (1)	
MMT	
MMU	
MMV	
MMV (1)	

Chicago Public Schools

School Chicago International
Charter - Loomis Primary

Unit 66075

Building ID 4914

Address 9535 South Loomis Street

Chicago, IL, 60643

Region

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) GSG Consultants, Inc.

855 W. Adams St., Ste. 200

Phone: (312) 733-6262

Fax: (312) 733-5612

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
MXA	
MXB	
SFA	
SPA	
SPB	
SPC	
SPC (1)	
TBA	
TBB	
TGA	
TJA	
TJB	
TJC	
TJD	
TPA	
TPB	
TTA	
TTD	

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile Patterns**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**

MATERIAL QUANTITY: **37800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **12"x12" Light Brown Mix Floor Tile Patterns**
MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**
MATERIAL QUANTITY: **37800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**

MATERIAL QUANTITY: **37800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Adhesive Associated with 12"x12" Light Brown Mix Floor Tile w/Blue and Orange Tile Patterns**
MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**
MATERIAL QUANTITY: **37800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **4" Light Brown Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **4" Light Brown Baseboard**
MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **4" Light Brown Baseboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **4" Light Brown Baseboard Adhesive**
MATERIAL LOCATION: **Throughout Building with the exception of the washrooms, kitchen and mechanical rooms**
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**
MATERIAL LOCATION: **Throughout Building with the Exception of Mechanical Areas**
MATERIAL QUANTITY: **40472** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Panels**
MATERIAL LOCATION: **Throughout Building with the Exception of Mechanical Areas**
MATERIAL QUANTITY: **40472** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Brown and Black Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Brown and Black Carpet Adhesive**
MATERIAL LOCATION: **Library**
MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Washrooms Throughout Building**

MATERIAL QUANTITY: **2672**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Grout**
MATERIAL LOCATION: **Washrooms Throughout Building**
MATERIAL QUANTITY: **2672** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Washrooms Throughout Building**

MATERIAL QUANTITY: **2672**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **Ceramic Floor Tile Adhesive**
MATERIAL LOCATION: **Washrooms Throughout Building**
MATERIAL QUANTITY: **2672** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stairways and First Floor Hall**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Terrazzo**
MATERIAL LOCATION: **Stairways and First Floor Hall**
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Whiteboard Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **2200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Whiteboard Adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MCA**
MATERIAL DESCRIPTION: **Metal Pan Ceiling - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MCA**
MATERIAL DESCRIPTION: **Metal Pan Ceiling - REMOVED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MCB**
MATERIAL DESCRIPTION: **Metal Pan Ceiling - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MCB**
MATERIAL DESCRIPTION: **Metal Pan Ceiling - REMOVED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MCC**
MATERIAL DESCRIPTION: **1'x1' Fissured Ceiling Tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **23000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MCC**
MATERIAL DESCRIPTION: **1'x1' Fissured Ceiling Tile and Mastic**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **23000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MFA**
MATERIAL DESCRIPTION: **9"x9" Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MFA**
MATERIAL DESCRIPTION: **9"x9" Floor Tile - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MFB**
MATERIAL DESCRIPTION: **12"x12" Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  _____ Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MFB**
MATERIAL DESCRIPTION: **12"x12" Floor Tile - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MM1**
MATERIAL DESCRIPTION: **Baseboard Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MM1**
MATERIAL DESCRIPTION: **Baseboard Mastic - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMA**
MATERIAL DESCRIPTION: **9"x9" Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMA**
MATERIAL DESCRIPTION: **9"x9" Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMB**
MATERIAL DESCRIPTION: **12"x12" Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  _____ Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMB**
MATERIAL DESCRIPTION: **12"x12" Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMB (1)**
MATERIAL DESCRIPTION: **Blackboards - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMB (1)**
MATERIAL DESCRIPTION: **Blackboards - ABATED**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMC**
MATERIAL DESCRIPTION: **Residual Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMC**
MATERIAL DESCRIPTION: **Residual Mastic - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMD**
MATERIAL DESCRIPTION: **Black Baseboard (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMD**
MATERIAL DESCRIPTION: **Black Baseboard (Removed)**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MME**
MATERIAL DESCRIPTION: **Black Baseboard Adhesive (Removed)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MME**
MATERIAL DESCRIPTION: **Black Baseboard Adhesive (Removed)**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMF**
MATERIAL DESCRIPTION: **Gray Baseboard - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMF**
MATERIAL DESCRIPTION: **Gray Baseboard - Removed**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMG**
MATERIAL DESCRIPTION: **Gray Baseboard Adhesive - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMG**
MATERIAL DESCRIPTION: **Gray Baseboard Adhesive - Removed**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMH**
MATERIAL DESCRIPTION: **Brown Baseboard - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMH**
MATERIAL DESCRIPTION: **Brown Baseboard - ABATED**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMJ**
MATERIAL DESCRIPTION: **Beige Baseboard - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMJ**
MATERIAL DESCRIPTION: **Beige Baseboard - Removed**
MATERIAL LOCATION: **Throughout Facility**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMK**
MATERIAL DESCRIPTION: **Beige Baseboard Adhesive - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMK**
MATERIAL DESCRIPTION: **Beige Baseboard Adhesive - Removed**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MML**
MATERIAL DESCRIPTION: **Terrazzo Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MML**

MATERIAL DESCRIPTION: **Terrazzo Mastic - ABATED**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMM**
MATERIAL DESCRIPTION: **Vibration Dampers**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMM**
MATERIAL DESCRIPTION: **Vibration Dampers**
MATERIAL LOCATION: **Mechanical Room**
MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMN**
MATERIAL DESCRIPTION: **Terrazzo - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMN**
MATERIAL DESCRIPTION: **Terrazzo - ABATED**
MATERIAL LOCATION: **Stairways**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMO**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive - Removed**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMO**
MATERIAL DESCRIPTION: **Brown Carpet Adhesive - Removed**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMQ**
MATERIAL DESCRIPTION: **Soundproof Panels - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMQ**
MATERIAL DESCRIPTION: **Soundproof Panels - ABATED**
MATERIAL LOCATION:
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMS (1)**
MATERIAL DESCRIPTION: **Insulation in Fire Doors**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Entrances**

MATERIAL QUANTITY: **288**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMS (1)**
MATERIAL DESCRIPTION: **Insulation in Fire Doors**
MATERIAL LOCATION: **Entrances**
MATERIAL QUANTITY: **288** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMT**
MATERIAL DESCRIPTION: **Floor Filler**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **23000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMT**
MATERIAL DESCRIPTION: **Floor Filler**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **23000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMU**
MATERIAL DESCRIPTION: **Elevator Brake Shoes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMU**
MATERIAL DESCRIPTION: **Elevator Brake Shoes**
MATERIAL LOCATION: **Ground Floor**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMV**
MATERIAL DESCRIPTION: **Incinerator Bricks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Incinerator**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMV**
MATERIAL DESCRIPTION: **Incinerator Bricks**
MATERIAL LOCATION: **Incinerator**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MMV (1)**
MATERIAL DESCRIPTION: **Fire Brick in Boilers**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MMV (1)**
MATERIAL DESCRIPTION: **Fire Brick in Boilers**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MXA**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **46000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MXA**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **46000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **MXB**
MATERIAL DESCRIPTION: **Drywall Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **MXB**
MATERIAL DESCRIPTION: **Drywall Compound**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **12000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SFA**
MATERIAL DESCRIPTION: **Soundproofing**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **SFA**
MATERIAL DESCRIPTION: **Soundproofing**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SPA**
MATERIAL DESCRIPTION: **Wall Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **SPA**
MATERIAL DESCRIPTION: **Wall Plaster**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SPB**
MATERIAL DESCRIPTION: **Ceiling Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **SPB**
MATERIAL DESCRIPTION: **Ceiling Plaster**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **38000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SPC**
MATERIAL DESCRIPTION: **Popcorn Ceiling - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Chapel**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:  Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **SPC**
MATERIAL DESCRIPTION: **Popcorn Ceiling - ABATED**
MATERIAL LOCATION: **Chapel**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **SPC (1)**
MATERIAL DESCRIPTION: **Popcorn Ceiling - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Chapel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **SPC (1)**

MATERIAL DESCRIPTION: **Popcorn Ceiling - ABATED**

MATERIAL LOCATION: **Chapel**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TBA**
MATERIAL DESCRIPTION: **Insulation on East Boiler**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TBA**
MATERIAL DESCRIPTION: **Insulation on East Boiler**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TBB**
MATERIAL DESCRIPTION: **Insulation on West Boiler**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TBB**
MATERIAL DESCRIPTION: **Insulation on West Boiler**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TGA**
MATERIAL DESCRIPTION: **Boiler Gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TGA**
MATERIAL DESCRIPTION: **Boiler Gaskets**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TJA**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Domestic Water Pipes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room and Tunnel from Aquinus Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TJA**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Domestic Water Pipes**
MATERIAL LOCATION: **Boiler Room and Tunnel from Aquinus Building**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TJB**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Mechanical Pipes**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room, Mechanical Room and Tunnel from Aquinus Building**

MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TJB**
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Mechanical Pipes**
MATERIAL LOCATION: **Boiler Room, Mechanical Room and Tunnel from Aquinus Building**
MATERIAL QUANTITY: **22** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TJC**
MATERIAL DESCRIPTION: **Black Tar Wrap**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **25**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TJC**
MATERIAL DESCRIPTION: **Black Tar Wrap**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TJD**
MATERIAL DESCRIPTION: **White Tar Wrap**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TJD**
MATERIAL DESCRIPTION: **White Tar Wrap**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TPA**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation on Domestic Water Pipes**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TPA**
MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation on Domestic Water Pipes**
MATERIAL LOCATION: **Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TPB**
MATERIAL DESCRIPTION: **Fiberglass Insulation on Mechanical Pipes**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases**

MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TPB**
MATERIAL DESCRIPTION: **Fiberglass Insulation on Mechanical Pipes**
MATERIAL LOCATION: **Throughout Building Including: Boiler Room, Mechanical Room, Tunnel to Aquinus Building and Pipe Chases**
MATERIAL QUANTITY: **325** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 05/15/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TTA**
MATERIAL DESCRIPTION: **Insulation on Tank**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TTA**
MATERIAL DESCRIPTION: **Insulation on Tank**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **TTD**
MATERIAL DESCRIPTION: **Duct Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUIDLING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **TTD**
MATERIAL DESCRIPTION: **Duct Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Mixed Speckled**
MATERIAL LOCATION: **Rms. 309, 212, 201, 122, 113 and 100. 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12 x 12 VFT Purple Mixed Speckled**
MATERIAL LOCATION: **Rms. 309, 212, 201, 122, 113 and 100. 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12 x 12 Mastic Yellow Mixed Speckled**
MATERIAL LOCATION: **Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12 x 12 Mastic Yellow Mixed Speckled**
MATERIAL LOCATION: **Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2 x 2 CT White**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2 x 2 CT White**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2 x 4 CT Smooth White**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2 x 4 CT Smooth White**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/15/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12 x 12 VFT Blue Mixed Speckled**
MATERIAL LOCATION: **Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **12 x 12 VFT Blue Mixed Speckled**
MATERIAL LOCATION: **Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12 x 12 Mastic Blue Mixed Speckled**
MATERIAL LOCATION: **Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12 x 12 Mastic Blue Mixed Speckled**
MATERIAL LOCATION: **Rm 303, 206, 116, 125 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12 X 12 VFT Green Mixed Speckled**
MATERIAL LOCATION: **Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International
Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **12 X 12 VFT Green Mixed Speckled**
MATERIAL LOCATION: **Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled**
MATERIAL LOCATION: **Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12 x 12 VFT Tan Mixed Speckled**
MATERIAL LOCATION: **Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12 x 12 Mastic Red Mixed Speckled**
MATERIAL LOCATION: **Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **12 x 12 Mastic Red Mixed Speckled**
MATERIAL LOCATION: **Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12 x 12 VFT Red Mixed Speckled**
MATERIAL LOCATION: **Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY:
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12 x 12 VFT Red Mixed Speckled**
MATERIAL LOCATION: **Rm. 128, 305, 208, 118, 115, 096 and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rm 110**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: 04/05/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Carpet Mastic**
MATERIAL LOCATION: **Rm 110**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12 x 12 VFT Orange Mixed Speckled**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor Rm 095 and LunchRoom**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12 x 12 VFT Orange Mixed Speckled**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor Rm 095 and LunchRoom**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 05/15/2013

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **12 x 12 Purple Mixed Speckled Mastic**
MATERIAL LOCATION: **Rms 309, 212, 201, 122, 113 and 100. 3rd, 2nd and 1st Flr Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **12 x 12 Purple Mixed Speckled Mastic**
MATERIAL LOCATION: **Rms 309, 212, 201, 122, 113 and 100. 3rd, 2nd and 1st Flr Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12 x 12 Mastic Orange Mixed Speckled**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor Rm 095 and Lunchroom**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **12 x 12 Mastic Orange Mixed Speckled**
MATERIAL LOCATION: **3rd, 2nd, 1st Floor Corridor Rm 095 and Lunchroom**
MATERIAL QUANTITY: **1050** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12 x 12 Green Mixed Speckled Mastic**
MATERIAL LOCATION: **Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc. 2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12 x 12 Green Mixed Speckled Mastic**
MATERIAL LOCATION: **Rm. 101, 304, 207, 121, 114 and 3rd, 2nd, and 1st Floor Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12 x 12 VFT Yellow Mixed Speckled**
MATERIAL LOCATION: **Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12 x 12 VFT Yellow Mixed Speckled**
MATERIAL LOCATION: **Rms 308, 211, 117, 112, 126 and 3rd, 2nd and 1st Corridor**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Eric Valadez**
SCHOOL NAME: **Chicago International
Charter - Loomis
Primary** INSPECTION DATE: **4/5/2013**
ADDRESS: **9535 South Loomis
Street** IDPH LICENSE NO: **100-19038**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12 x 12 Mastic Tan Mixed Speckled**
MATERIAL LOCATION: **Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Barely Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
No Drawing

Inspector's Signature: _____



Date: **04/05/2013**

Chicago Public Schools

GSG Consultants, Inc.
2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66075** BUILDING ID: **4914**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Guillermo Garcia**
SCHOOL NAME: **Chicago International Charter - Loomis Primary** REVIEW DATE: **5/15/2013**
ADDRESS: **9535 South Loomis Street** IDPH LICENSE NO: **100-19038**

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12 x 12 Mastic Tan Mixed Speckled**
MATERIAL LOCATION: **Rm 090, 202, Lunchroom and 3rd, 2nd, 1st Floor Corridor**
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **05/15/2013**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that ERIC M. VALADEZ
has completed the Contractor/Supervisor Recertification course and passed the examination
on 02/09/2013 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC
18-2.



N. Penneff

02/09/2013

Course Dates:

07/09/2014

Expires:

1302CSR36

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penneff

Doctor of Public Health

FORM # A-008

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Approved by the Illinois Department of Public Health and Indiana Department of Environmental Management

This is to certify that GUILLERMO GARCIA
has completed the Contractor/Supervisor Recertification course and passed the examination
on 06/22/2012 with a minimum score of 70% or better. Training was in accordance with U.S.
E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools; Model
Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA and Indiana Rule 326 IAC
18-2.



Nicholas J. Penneff

06/22/2012

Course Dates:

06/22/2013

Expires:

1206CSR01

Certificate Number:

Phone Number: (312) 491-0081

Director of Training

Nicholas J. Penneff

Doctor of Public Health

FORM # A-008



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER
100 - 01786

ISSUED
7/24/2012

EXPIRES
09/15/2013

GUILLERMO GARCIA
855 W ADAMS ST SUITE 100
CHICAGO, IL 60607

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	03/30/13
MANAGEMENT PLANNER	03/30/13
PROJECT MANAGER	02/28/13
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
 This license issued under authority of the State of Illinois
 Department of Public Health
 This license is valid only when accompanied by a valid
 training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed