

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: UNKNOWN
SCHOOL NAME: UNO - Archer Heights South
ADDRESS OF SCHOOL: 4248 W 47th St.
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED


If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/4/2013 ENROLLMENT 636
IDPH INSPECTOR LICENSE NUMBER: 100-08904
IDPH LICENSED INSPECTOR NAME (Please Print): Douglas McCormick
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Ms. Lynn Crivello PHONE: (773) 553-3113



9/4/2013

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

UNO - Archer Heights South

4248 W 47th St.
Chicago, IL, 60632

Unit: 66396
Building ID: 3345

IDPH ID Number: UNKNOWN

REPORT DATE:

Wednesday, September 04, 2013

Prepared for:

**Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

August 15, 2013

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2013 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66396 Region: 04 IDPH ID: UNKNOWN

School: UNO - Archer Heights South Building ID: 3345

Address: 4248 W 47th St.

Chicago, IL, 60632

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 9/4/2013

Inspector: Douglas McCormick

Inspector IDPH License: 100-08904

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 15, 2013

RE: UNO - Archer Heights South, Unit 66396
4248 W 47th St.
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2013 asbestos three year re-inspection has been completed at UNO - Archer Heights South , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at UNO - Archer Heights South, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Ms. Lynn Crivello, the designated Local Education Authority's Designated Person at (773) 553-3113 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: UNO - Archer Heights South Unit: 66396 Region: 04
Address: 4248 W 47th St. Chicago, IL, 60632
IDPH ID: UNKNOWN Building ID: 3345
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 636

3. LEA Designated Person

Contact: Ms. Lynn Crivello Phone: (773) 553-3113
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Douglas McCormick


Inspector IDPH license # 100-08904

Signature:
Date: 8/15/2013

6. Management Planner

Management Planner Name: Todd Huffer

Management Planner IDPH license # 100-09870

Signature: 
Date: 9/4/2013

7. Review Date: 9/4/2013

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 9/4/2013

Name: Ms. Lynn Crivello

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the UNO - Archer Heights South. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3345:

B. The following new homogenous areas have been identified for Building 3345:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Drywall
10	12" X 12" Dark Green Mix Floor Tile
10M	12" X 12" Dark Green Mix Floor Tile Mastic
11	12" X 12" White with Green Specks Floor Tile
11M	12" X 12" White with Green Specks Floor Tile Mastic
14	Carpet Adhesive for Green/Yellow Striped Carpet Tile
16	4" Light Green baseboards
17	Mastic used for baseboards
18	2' X 2' White Ceiling Tiles
19	2' X 4' Drop Face White with Pin Dots Ceiling Tile
2	Drywall Joint Compound
20	Sinks
8	12" X 12" Light Green Mix Floor Tile
8M	12" X 12" Light Green Mix Floor Tile Mastic
9	12" X 12" Green Mix Floor Tile
9M	12" X 12" Green Floor Tile Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Douglas McCormick, IDPH License # 100-08904. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The UNO - Archer Heights South Building 3345 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School UNO - Archer Heights South Unit 66396 Building ID 3345
 Address 4248 W 47th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Drywall	14,000	SF	Throughout 2nd Floor	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
10	12" X 12" Dark Green Mix Floor Tile	50	SF	2nd Floor Halls and Engineers Office	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
10M	12" X 12" Dark Green Mix Floor Tile Mastic	50	SF	2nd Floor Halls and Engineers Office	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
11	12" X 12" White with Green Specks Floor Tile	15,000	SF	2nd Floor Halls, teachers offices, bathrooms, resource room, and multi-purpose room	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
11M	12" X 12" White with Green Specks Floor Tile Mastic	15,000	SF	2nd Floor halls, teachers offices, bathrooms ,resource room, and multi-purpose room	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
14	Carpet Adhesive for Green/Yellow Striped Carpet Tile	275	SF	2nd Floor Small Corner Offices	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
16	4" Light Green baseboards	5,520	LF	Throughout 2nd Floor	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
17	Mastic used for baseboards	10,920	LF	Throughout 2nd Floor	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
18	2" X 2" White Ceiling Tiles	28,000	SF	2nd Floor Halls, Vestibule, Teachers Offices	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
19	2" X 4" Drop Face White with Pin Dots Ceiling Tile	21,875	SF	2nd Floor Classrooms and Multi-Purpose room	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
2	Drywall Joint Compound	9,000	SF	Throughout 2nd Floor	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
20	Sinks	14		2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
8	12" X 12" Light Green Mix Floor Tile	23,325	SF	2nd Floor halls, Classrooms, Teacher office, Bathrooms	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
8M	12" X 12" Light Green Mix Floor Tile Mastic	23,325	SF	2nd Floor Halls, Classrooms, Teacher office, Bathrooms	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
9	12" X 12" Green Mix Floor Tile	1,250	SF	2nd Floor Halls , Engineers office	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW
9M	12" X 12" Green Floor Tile Mastic	1,250	SF	2nd Floor Halls,	ASSUMED	MISC	Y	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School UNO - Archer Heights South Unit 66396 Building ID 3345
 Address 4248 W 47th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
 Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Engineers office								potential for damage		

Chicago Public Schools

School UNO - Archer Heights South Unit 66396 Building ID 3345
Address 4248 W 47th St. Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **8/15/2013**
Inspector Name **Douglas McCormick**
100-08904 **5/15/2013**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
10M	
11	
11M	
14	
16	
17	
18	
19	
2	
20	
8	
8M	
9	
9M	

Table II

Management Planner's Review

Chicago Public Schools

School UNO - Archer Heights
South

Unit 66396

Building ID 3345

Address 4248 W 47th St.

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 762-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Drywall	14,000	SF	Throughout 2nd Floor	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
10	12" X 12" Dark Green Mix Floor Tile	50	SF	2nd Floor Halls and Engineers Office	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
10M	12" X 12" Dark Green Mix Floor Tile Mastic	50	SF	2nd Floor Halls and Engineers Office	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
11	12" X 12" White with Green Specks Floor Tile	15,000	SF	2nd Floor Halls, teachers offices, bathrooms, resource room, and multi-purpose room	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
11M	12" X 12" White with Green Specks Floor Tile Mastic	15,000	SF	2nd Floor Halls, teachers offices, bathrooms, resource room, and multi-purpose room	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
14	Carpet Adhesive for Green/Yellow Striped Carpet Tile	275	SF	2nd Floor Small Corner Offices	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
16	4" Light Green baseboards	5,520	LF	Throughout 2nd Floor	Assumed	MISC	Yes		LF	6 ACBM with the potential for damage	Operations and Maintenance
17	Mastic used for baseboards	10,920	LF	Throughout 2nd Floor	Assumed	MISC	Yes		LF	6 ACBM with the potential for damage	Operations and Maintenance
18	2' X 2' White Ceiling Tiles	28,000	SF	2nd Floor Halls, Vestibule, Teachers Offices	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
19	2' X 4' Drop Face White with Pin Dots Ceiling Tile	21,875	SF	2nd Floor Classrooms and Multi-Purpose room	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
2	Drywall Joint Compound	9,000	SF	Throughout 2nd Floor	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
20	Sinks	14		2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
8	12" X 12" Light Green Mix Floor Tile	23,325	SF	2nd Floor Halls, Classrooms, Teacher office, Bathrooms	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
8M	12" X 12" Light Green Mix Floor Tile Mastic	23,325	SF	2nd Floor Halls, Classrooms, Teacher office, Bathrooms	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
9	12" X 12" Green Mix Floor Tile	1,250	SF	2nd Floor Halls, Engineers office	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance
9M	12" X 12" Green Floor Tile Mastic	1,250	SF	2nd Floor Halls, Engineers office	Assumed	MISC	Yes		SF	6 ACBM with the potential for damage	Operations and Maintenance

Chicago Public Schools

School UNO - Archer Heights
South
Address 4248 W 47th St.

Unit 66396
Chicago, IL, 60632

Building ID 3345
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500

Phone: (312) 762-2900 **Fax:** (312) 762-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	9/4/2013
Manager Planner Name	Todd Huffer
100-09870	5/15/2013
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
10M	
11	
11M	
14	
16	
17	
18	
19	
2	

Chicago Public Schools

School UNO - Archer Heights
South
Address 4248 W 47th St.

Unit 66396
Chicago, IL, 60632

Building ID 3345
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500

Phone: (312) 762-2900 **Fax:** (312) 762-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
20	
8	
8M	
9	
9M	

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Drywall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY: **14000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **1**
MATERIAL DESCRIPTION: **Drywall**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" X 12" Dark Green Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Halls and Engineers Office**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **12" X 12" Dark Green Mix Floor Tile**
MATERIAL LOCATION: **2nd Floor Halls and Engineers Office**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **12" X 12" Dark Green Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Halls and Engineers Office**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **10M**
MATERIAL DESCRIPTION: **12" X 12" Dark Green Mix Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Halls and Engineers Office**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" X 12" White with Green Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Halls, teachers offices, bathrooms, resource room, and multi-purpose room**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **12" X 12" White with Green Specks Floor Tile**
MATERIAL LOCATION: **2nd Floor Halls, teachers offices, bathrooms, resource room, and multi-purpose room**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **12" X 12" White with Green Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor halls, teachers offices, bathrooms , resource room, and multi-purpose room**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **11M**
MATERIAL DESCRIPTION: **12" X 12" White with Green Specks Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor halls, teachers offices, bathrooms , resource room, and multi-purpose room**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Carpet Adhesive for Green/Yellow Striped Carpet Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Small Corner Offices**

MATERIAL QUANTITY: **275**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Carpet Adhesive for Green/Yellow Striped Carpet Tile**
MATERIAL LOCATION: **2nd Floor Small Corner Offices**
MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **4" Light Green baseboards**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout 2nd Floor**

MATERIAL QUANTITY: **5520**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **4" Light Green baseboards**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **5520** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Mastic used for baseboards**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **10920** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Mastic used for baseboards**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **10920** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **2' X 2' White Ceiling Tiles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Halls, Vestibule, Teachers Offices**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **2' X 2' White Ceiling Tiles**
MATERIAL LOCATION: **2nd Floor Halls, Vestibule, Teachers Offices**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **2' X 4' Drop Face White with Pin Dots Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Classrooms and Multi- Purpose room**
MATERIAL QUANTITY: **21875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **2' X 4' Drop Face White with Pin Dots Ceiling Tile**
MATERIAL LOCATION: **2nd Floor Classrooms and Multi- Purpose room**
MATERIAL QUANTITY: **21875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **2**
MATERIAL DESCRIPTION: **Drywall Joint Compound**
MATERIAL LOCATION: **Throughout 2nd Floor**
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room**

MATERIAL QUANTITY: **14** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Sinks**
MATERIAL LOCATION: **2 Classrooms (Art Room & Science Room) in 2nd Floors, and Multi Purpose Room**
MATERIAL QUANTITY: **14** MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" X 12" Light Green Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor halls, Classrooms, Teacher office, Bathrooms**

MATERIAL QUANTITY: **23325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **12" X 12" Light Green Mix Floor Tile**
MATERIAL LOCATION: **2nd Floor halls, Classrooms, Teacher office, Bathrooms**
MATERIAL QUANTITY: **23325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8M**
MATERIAL DESCRIPTION: **12" X 12" Light Green Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Halls, Classrooms, Teacher office, Bathrooms**

MATERIAL QUANTITY: **23325** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **8M**
MATERIAL DESCRIPTION: **12" X 12" Light Green Mix Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Halls, Classrooms, Teacher office, Bathrooms**
MATERIAL QUANTITY: **23325** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" X 12" Green Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Halls , Engineers office**

MATERIAL QUANTITY: **1250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **9**
MATERIAL DESCRIPTION: **12" X 12" Green Mix Floor Tile**
MATERIAL LOCATION: **2nd Floor Halls , Engineers office**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Douglas McCormick**
SCHOOL NAME: **UNO - Archer Heights South** INSPECTION DATE: **8/15/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9M**
MATERIAL DESCRIPTION: **12" X 12" Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Operations and Maintenance**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Halls, Engineers office**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **08/15/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **66396** BUIDLING ID: **3345**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **UNO - Archer Heights South** REVIEW DATE: **9/4/2013**
ADDRESS: **4248 W 47th St.** IDPH LICENSE NO: **100-08904**

HOMOGENEOUS AREA: **9M**
MATERIAL DESCRIPTION: **12" X 12" Green Floor Tile Mastic**
MATERIAL LOCATION: **2nd Floor Halls, Engineers office**
MATERIAL QUANTITY: **1250** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Operations and Maintenance

Comments:

Management Planner's Signature: _____



Date: **09/04/2013**

Chicago Public Schools

Carnow, Conibear and Associates

2013 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Douglas M. McCormick

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course and has passed the competency exam with a minimum score of 70%. This course is accredited by the Illinois Department of Public Health and the Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II. This training course complies with the requirements of TSCA Title II and is accredited by the state of Wisconsin Department of Health Services under CH.DHS159, Wisconsin Administration Code.

Asbestos Abatement Building Inspector Refresher

Certificate: BIRWI1210101791

Location: 12304 75th Street Kenosha, WI 53142

Course Date: 10/10/2012

Examination Date: 10/10/2012

Expiration Date: 10/10/2013


Issue Date: 10/10/2012



Kathy DeSalvo, Director


2012

Douglas McCormick
Illinois Licensed Asbestos Inspector, Project Manager, and
Air Sampling Professional

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER 100 - 08904	ISSUED 4/4/2012	EXPIRES 05/15/2013
---------------------------------	---------------------------	------------------------------

DOUGLAS M McCORMICK
2001 HABBERTON
PARK RIDGE, IL 60068



Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	10/13/2012
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	12/15/2012

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street • Willowbrook, IL 60527 • (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Building Inspector Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department
of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance
with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: BIR1212042317

Exam Date: 12/4/2012

Course Date: 12/4/2012


Expiration Date: 12/4/2013

Kathy DeSalvo, Director

2012



Todd Huffer

Illinois Licensed Asbestos Inspector, Management Planner,
Project Manager, and Air Sampling Professional

 **ASBESTOS PROFESSIONAL LICENSE**

ID NUMBER 100 - 09870	ISSUED 4/4/2012	EXPIRES 05/15/2013
---------------------------------	---------------------------	------------------------------

TODD T HUFFER
918 N WOLCOTT UNIT 6
CHICAGO, IL 60622

Environmental Health

ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/8/2012
MANAGEMENT PLANNER	1/19/2013
PROJECT MANAGER	9/8/2012
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

**CARNOW
CONIBEAR**



Occupational Training & Supply, Inc.

7233 Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training and Supply, Inc. certifies that

Todd Huffer

has successfully completed the 4 hour Asbestos Management Planner Refresher Course
and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 10 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Certificate: MPR1302250735

Exam Date: 2/25/2013

Course Date: 2/25/2013

Expiration Date: 2/25/2014


Kathy DeSalvo, Director

2013

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed