

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1920 | 2 | 69,617 | \$5,442,686 |
| Addition | 1961 | 2 | 48,594 | \$1,781,477 |
| Belmont-Cragin Pre-K | 1955 | 2 | 33,635 | \$1,459,309 |
| SITE | | | | \$184,816 |
| Campus Total | · | | 151,846 | \$8,868,287 |

Building: Main

Category: Building Exterior

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-------------|----------|------|------|---------|----------|
| ntranc | e | | | | | | |
| | Entrance Control - Audio and Video | 1 - Main | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | 8 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 1 - Main | 4 | EA | 6 | \$2,526 | |
| | Exterior Doors - Exterior FRP Door | 6 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 7 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 8 | 4 | EA | 6 | \$2,526 | |
| | Exterior Doors - Exterior FRP Door | 9 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior Stainless Steel Door | 2 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Exterior Steel Door | 10 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | 6 | 1 | EA | 5 | \$1,341 | |
| | Exterior Doors - Exterior Steel Door | Boiler Room | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | Garage | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | Garage | 1 | EA | 5 | \$3,942 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | Garage | 1 | EA | 5 | \$3,942 | |
| | Exterior Doors - Transom Lite | 1 - Main | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Transom Lite | 2 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 9 | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 1 - Main | 85 | LF | 6 | \$6,950 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

Category: Building Exterior

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-----------------|----------|------|--------|-----------------------------|----------|
| Entrand | | | | | | | |
| | Exterior Stairs - Concrete | 2 | 96 | LF | 6 | \$7,850 | |
| | Exterior Stairs - Concrete | 6 | 140 | LF | 6 | \$11,447 | |
| | Exterior Stairs - Concrete | 7 | 78 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 8 | 342 | LF | 6 | \$27,964 | |
| | Exterior Stairs - Concrete | Boiler Room | 36 | LF | 7 | \$0 | |
| | Exterior Stairs - Steel or Aluminum | 10 | 21 | LF | 5 | \$151 | |
| | Ramp Handrail - Wood_Ramp Handrail | 6 | 80 | LF | 5 | \$848 | |
| | Ramps - Wood Ramp | 6 | 40 | LF | 5 | \$13,583 | |
| | Stair Handrail - Steel_Stair Handrail | 10 | 8 | LF | 6 | \$69 | |
| | Stair Handrail - Steel_Stair Handrail | 7 | 10 | LF | 6 | \$87 | |
| | Stair Handrail - Steel_Stair Handrail | 8 | 68 | LF | 6 | \$589 | |
| | Stair Handrail - Steel_Stair Handrail | Boiler Room | 10 | LF | 5 | \$115 | |
| | Stair Handrail - Wood_Stair Handrail | 6 | 7 | LF | 5 | \$80 | |
| F | 10-m | | | | | | |
| Founda | | | 4 000 | . – | _ | ^ | |
| | Foundation - Concrete | Entire Building | 1,208 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 69,617 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 2 | EA | 7 | \$0 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 7 | \$0 | |
| Deef C | 1040 M | | | | | | |
| Roof S | | F | 25 | LF | 4 | \$140,799 | orocking |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar Liner | F | 25 65 | LF | 4 6 | \$62,054 | Clacking |
| | Coping - Metal | r H | 114 | LF | 6 | \$02,054 \$3,661 | |
| | | В | 584 | LF | 6 | \$3,001 \$18,757 | |
| | Coping - Stone Coping - Stone | C | 130 | LF | 6 | \$4,175 | |
| | Coping - Stone | D | 546 | LF | 6 | \$4,175 \$17,536 | |
| | Coping - Stone | E | 53 | LF | 6 | \$1,702 | |
| | Coping - Stone | F | 124 | LF | 6 | \$3,983 | |
| | Coping - Stone | G | 124 | LF | 6 | \$3,903 \$3,694 | |
| | Coping - Terra Cotta | D | 108 | LF | 6 | \$3,469 | |
| | Downspouts - Exterior Downspouts | C | 13 | LF | 7 | \$0,409 \$0 | |
| | Downspouts - Exterior Downspouts Downspouts - Interior Downspouts | В | 152 | LF | 6 | ەن \$5,051 | |
| | Downspouts - Interior Downspouts | D | 258 | LF | 6 | \$3,051 \$8,574 | |
| | Downspouts - Interior Downspouts | E | 20 | LF | 6 | \$665 | |
| | Downspouts - Interior Downspouts | F | 20 56 | LF | 6 | ۵ 003 \$1,861 | |
| | Downspouts - Interior Downspouts | G | 30 | LF | 6 | \$1,001 \$997 | |
| | Downspouls - Interior Downspouls | 0 | 50 | | 0 | 499 <i>1</i> | |



Category: Building Exterior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|----------------------------------|-----------------|----------|------|------|-----------|-----------------------------|
| Roof S | | | | | | | |
| | Downspouts - Interior Downspouts | Н | 28 | LF | 6 | \$931 | |
| | Parapet - 16" - 30" Height | D | 108 | LF | 6 | \$4,315 | |
| | Parapet - 16" - 30" Height | E | 53 | LF | 6 | \$2,118 | |
| | Parapet - 16" - 30" Height | G | 89 | LF | 6 | \$3,556 | |
| | Parapet - Parapet < 16" Height | С | 5 | LF | 4 | \$3,702 | cracked |
| | Parapet - Parapet < 16" Height | С | 125 | LF | 6 | \$2,663 | |
| | Parapet - Parapet < 16" Height | Н | 114 | LF | 6 | \$2,429 | |
| | Parapet - Parapet > 30" | В | 569 | LF | 6 | \$36,371 | |
| | Parapet - Parapet > 30" | В | 15 | LF | 5 | \$5,695 | |
| | Parapet - Parapet > 30" | D | 546 | LF | 6 | \$34,901 | |
| | Parapet - Parapet > 30" | F | 124 | LF | 6 | \$7,926 | |
| | Parapet - Parapet > 30" | G | 26 | LF | 6 | \$1,662 | |
| | Roof Structure - Concrete | В | 15,075 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | С | 1,209 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | D | 17,820 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | E | 345 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | F | 2,147 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | G | 1,899 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Н | 627 | SF | 7 | \$0 | |
| | Roof - Asphalt Gravel Ballast | В | 15 | SF | 4 | \$795 | leak reported per engineer |
| | Roof - Asphalt Gravel Ballast | В | 14,925 | SF | 6 | \$151,747 | |
| | Roof - Modified Bitumen | С | 1,209 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | D | 100 | SF | 4 | \$5,144 | leaks reported per engineer |
| | Roof - Modified Bitumen | D | 17,720 | SF | 6 | \$166,735 | |
| | Roof - Modified Bitumen | E | 345 | SF | 6 | \$3,246 | |
| | Roof - Modified Bitumen | F | 2,147 | SF | 5 | \$45,163 | |
| | Roof - Modified Bitumen | G | 1,899 | SF | 5 | \$39,946 | |
| | Roof - Modified Bitumen | Н | 627 | SF | 6 | \$5,900 | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 360 | SF | 6 | \$11,912 | |
| | Exterior Walls - Brick | Entire Building | 41,321 | SF | 7 | \$0 | |
| | Exterior Walls - Brick | Entire Building | 2,648 | SF | 4 | \$435,994 | cracked, deteriorated |
| | Exterior Walls - Brick | Entire Building | 250 | SF | 5 | \$5,952 | |
| | Exterior Walls - Stone-Cast | Entire Building | 1,840 | SF | 6 | \$12,367 | |
| Window | VS | | | | | | |
| | Guard - Guards perforated | Entire Building | 3,179 | SF | 7 | \$0 | |
| | | | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

Category: Building Exterior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Com | ments |
|-------------------------------------|-----------------|----------|------|------|-----------|-------|
| Vindows | | | | | | |
| Lintels - Steel | Entire Building | 75 | LF | 6 | \$2,177 | |
| Windows - Decorative | Entire Building | 608 | SF | 7 | \$0 | |
| Windows - Louver | Entire Building | 224 | SF | 5 | \$19,181 | |
| Windows - Sash Aluminum Double-pane | Entire Building | 4,496 | SF | 7 | \$0 | |
| | | | | | | |
| Building Exterior Subtotal: | | | | \$ | 1,381,383 | |

Building: Main

Category: Electrical System

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------------------------|----------|------|------|----------|----------|
| nerge | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 7 | \$0 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 13,151 | SF | 6 | \$3,949 | |
| | Emergency A/C Power - Gym | Entire Building | 9,555 | SF | 6 | \$3,553 | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 6,185 | SF | 6 | \$2,300 | |
| | Emergency A/C Power - Multipurpose Room | Entire Building | 2,580 | SF | 6 | \$959 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,659 | SF | 6 | \$617 | |
| | Emergency Generator- Outdoor- Diesel - 101 - 150 KW | Courtyard | 1 | EA | 5 | \$17,114 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 37 | EA | 6 | \$5,541 | |
| | Exit Signs - Gym | Entire Building | 7 | EA | 6 | \$1,102 | |
| | Exit Signs - Multipurpose Room | Entire Building | 4 | EA | 6 | \$599 | |
| | Security System - CCTV | Entire Building | 69,617 | SF | 6 | \$20,906 | |
| | Security System - Intrusion Detection | Entire Building | 69,617 | SF | 6 | \$17,919 | |
| ain Se | prvice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Electrical Service - 2001 to 3000 A 120/208/3PH | Electrical Room | 1 | EA | 7 | \$0 | |
| | PA System | Entire Building | 69,617 | SF | 6 | \$22,897 | |
| wer C | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 4 | \$19,397 | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 6 | \$1,196 | |
| | Lighting and Power Panels - 100 A | Entire Building | 6 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Entire Building / Mechanical Room | 3 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Mechanical Room | 5 | EA | 4 | \$32,889 | |
| | Main Distribution Panels - Less than 400 amp | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Cat | egory: | Electrical | System |
|-----|--------|------------|--------|
| 0 | | . . | |

| | bry. Lieutitai System | | | | | | |
|----------|--|---|----------|------|------|-----------------------|---|
| <u> </u> | Item - Type | Location | Quantity | Unit | Rank | | Comments |
| Electri | cal System Subtotal: | | | | | \$150,938 | |
| | | | | | | | |
| Buildi | ng: Main | | | | | | |
| Catego | ory: Safty System | | | | | | |
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Ala | rm | | | | | | |
| | Fire Alarm Panel | Main Office / 1st Floor | 1 | EA | 4 | \$49,477 | 20 + years old |
| | Fire Alarm_System | Main Office | 69,617 | SF | 6 | \$33,848 | |
| Safty S | System Subtotal: | | | | | \$83,324 | |
| Carty | | | | | | \$00,02 1 | |
| Duildi | na. Moin | | | | | | |
| | ng: Main | | | | | | |
| | ory: Mechanical System | | _ | | _ | _ | |
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Air Con | ditioning | D (| | = • | | \$ 00.405 | |
| | Condensing Unit- Roof Mounted - 11-20 tons | Roof | 1 | EA | 4 | \$20,185 | No longer used, and functionality not known |
| | Condensing Unit- Roof Mounted - 5-10 tons | Roof | 2 | EA | 4 | \$29,787 | No longer used, and functionality not known |
| Air Hane | dling Systems | | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001- 15000 cfm | Entire Building / Penthouse | 2 | EA | 2 | \$316,094 | AHUs have not been operational since 1999 |
| | Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - Less than | Mechanical Room Adjacent to Stage | 1 | EA | 5 | \$35,240 | |
| | 6000 cfm Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000- | Suspended Platforms Above Gym | 1 | EA | 2 | \$84 802 | Not operational since 1999 |
| | 8000 cfm | Suspended Flatforms Above Cym | I | LA | 2 | ψ0 4 ,002 | Not operational since 1999 |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001- | Suspended Platforms Above Gym | 2 | EA | 2 | \$215,653 | AHUs have been non-operational since 1999 |
| | 12000 cfm | | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Steam Coils and DX Cooling Coils - 12001-20000 cfm | Suspended Platform Above Gym | 1 | EA | 2 | \$129,540 | Not operational since 1999 |
| | Air Intake | Entire Building / South Façade | 2 | EA | 6 | \$11,529 | |
| | Air Intake | Mechanical Room Adjacent to Stage / North Facade | 1 | EA | 6 | \$5,765 | |
| | Air Intake | Suspended Platform Above Gym / North Façade | 1 | EA | 6 | \$5,765 | |
| | Air Intake | Suspended Platforms Above Gym / | 2 | EA | 6 | \$11,529 | |
| | Air Istoleo | South Façade | 4 | | c | | |
| | Air Intake | Suspended Platforms Above Gym / South Façade | 1 | EA | 6 | \$5,765 | |
| | Auxiliarian 40004 45000 afra | Entire Building / Penthouse | 2 | EA | 4 | \$0 | |
| | Auxiliaries - 10001-15000 cfm | Little Building / Fentilouse | 2 | LA | - | ψυ | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-----------------------------------|----------|------|------|-----------|---|
| Air Han | dling Systems | | | | | | |
| | Auxiliaries - 4000-8000 cfm | Suspended Platforms Above Gym | 1 | EA | 4 | \$0 | |
| | Auxiliaries - 8001-12000 cfm | Suspended Platforms Above Gym | 2 | EA | 4 | \$0 | |
| | Auxiliaries - Less than 6000 cfm | Mechanical Room Adjacent to Stage | 1 | EA | 5 | \$0 | |
| | Fan Coil Unit- Floor Mounted - Electric | Main Office | 1 | EA | 4 | \$11,039 | 25+ years old. |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM | Platform Suspended Above Gym | 3 | EA | 3 | \$115,550 | Not operational since 1999 |
| Boiler S | Systems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP | Boiler Room | 1 | EA | 3 | \$37,053 | Needs burner replacement |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler $$ - 201 - 300 HP | Boiler Room | 2 | EA | 5 | \$55,593 | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | \$1,078 | |
| | Combustion Dampers | Boiler Room | 1 | EA | 3 | \$6,553 | Failed open |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Condensate Pump | Boiler Room / Mechanical Room | 1 | EA | 6 | \$2,021 | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 4 | \$92,964 | Poor condition. Asbestos insulation. Pumps leak constantly. |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP | Boiler Room | 3 | EA | 5 | \$83,390 | Serves main and addition |
| | Piping - Condensate Pipe- Steel | Boiler Room | 600 | LF | 4 | \$108,717 | |
| | Piping - Steam Pipe- Steel | Boiler Room | 600 | LF | 5 | \$8,451 | |
| | Steam Traps | Boiler Room | 125 | EA | 5 | \$164,362 | |
| Heat Ex | changers | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room | 2 | EA | 6 | \$0 | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room / Mechanical Room | 1 | EA | 6 | \$0 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 104 | EA | 5 | \$182,500 | |
| | Fin Tube - Hot Water | Entire Building | 100 | LF | 5 | \$8,142 | |
| | Wall Heater - Electric | Entire Building | 4 | EA | 5 | \$2,146 | |
| Mechar | nical Plumbing | | | | | | |
| | Hot Water Pump - Less than 10 | Boiler Room | 2 | EA | 5 | \$22,990 | |
| | Hydronic Supply and Return - Steel | Entire Building | 1,200 | LF | 5 | \$249,747 | |
| Temper | rature Control | | | | | | |
| | Pneumatic System | Entire Building | 69,617 | SF | 3 | \$362,370 | Controls not functional |
| | Thermostats - Pneumatic | Entire Building | 44 | EA | 4 | \$32,438 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-----------------|----------|------|------|----------|---|
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Penthouse | 1 | EA | 3 | \$6,392 | Not operational since 1999 |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Penthouse | 2 | EA | 4 | \$12,784 | Original to the building. Poor condition. |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 7 | \$0 | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 3 | \$4,245 | Non-operational |
| | Exhaust Fans- Indoor - Greater than 8000 CFM | Penthouse | 1 | EA | 4 | \$11,390 | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Penthouse | 1 | EA | 4 | \$1,278 | Original to the building. Poor condition. |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 3 | EA | 4 | \$12,734 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | \$592 | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 3 | \$28,265 | Lacks fire supression |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | \$1,248 | |
| Mecha | anical System Subtotal: | | | | \$2 | ,498,504 | |

Building: Main

Category: Plumbing System

| iroup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------|----------|------|------|-----------|--------------------------|
| lot Wat | ter | | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 6 | \$310 | Serves main and addition |
| piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 69,617 | SF | 6 | \$13,937 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 69,617 | SF | 6 | \$16,924 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 69,617 | SF | 6 | \$12,942 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 69,617 | SF | 6 | \$10,951 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 69,617 | SF | 6 | \$12,942 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 69,617 | SF | 6 | \$9,955 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 69,617 | SF | 6 | \$9,955 | |
| | Sanitary Piping | Entire Building | 69,617 | SF | 6 | \$63,713 | |
| | Storm Piping | Entire Building | 69,617 | SF | 6 | \$60,727 | |
| | Vent Piping | Entire Building | 69,617 | SF | 6 | \$46,790 | |
| umps | | | | | | | |
| | Pumps - Sump-Duplex | Under Stairwell | 1 | EA | 6 | \$1,387 | |
| lumb | bing System Subtotal: | | | | | \$260,533 | |

Building: Main



5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| lten | п - Туре | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|----------|----------|------|------|---------|----------|
| | 008 (Art Room) | | | • | | | |
| | Units | | 2 | EA | 7 | \$0 | |
| | ework | | 24 | LF | 7 | \$0 | |
| Ceil | ing - Splined | | 755 | SF | 6 | \$615 | |
| | rs - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| Floo | or - Tile | | 755 | SF | 7 | \$0 | |
| Ligh | ting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | ker Board | | 12 | LF | 7 | \$0 | |
| Wa | ls - Plaster/Drywall | | 288 | SF | 7 | \$0 | |
| | ls - Structural Glazed Tile | | 640 | SF | 7 | \$0 | |
| | rk Sink | | 1 | EA | 7 | \$0 | |
| oom # | 101 (Regular Classroom) | | | | | | |
| | Units | | 1 | EA | 7 | \$0 | |
| Cas | ework | | 6 | LF | 6 | \$152 | |
| Ceil | ing - Splined | | 677 | SF | 7 | \$0 | |
| Doc | rs - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| Floo | or - Tile | | 677 | SF | 7 | \$0 | |
| Ligh | ting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Mar | ker Board | | 16 | LF | 7 | \$0 | |
| Wa | ls - Plaster/Drywall | | 1,086 | SF | 6 | \$2,997 | |
| oom # | 102 (Regular Classroom) | | | | | | |
| AC | Units | | 1 | EA | 7 | \$0 | |
| Cas | ework | | 6 | LF | 5 | \$1,254 | |
| Ceil | ing - Splined | | 709 | SF | 7 | \$0 | |
| Doc | rs - Transom Window | | 10 | SF | 7 | \$0 | |
| Doc | rs - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Floo | or - Tile | | 709 | SF | 7 | \$0 | |
| Ligh | ting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Mar | ker Board | | 16 | LF | 6 | \$343 | |
| Wa | ls - Plaster/Drywall | | 1,100 | SF | 7 | \$0 | |
| oom # | 103 (Regular Classroom) | | | | | | |
| | Units | | 1 | EA | 7 | \$0 | |
| Ceil | ing - Splined | | 709 | SF | 6 | \$578 | |
| Cha | lk Board | | 6 | LF | 4 | \$551 | |
| Doc | rs - Transom Window | | 10 | SF | 7 | \$0 | |
| Doc | rs - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Floo | or - Tile | | 785 | SF | 7 | \$0 | |
| | ting - Pendent/Surface | | 24 | EA | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| | m #103 (Regular Classroom) | | | | | Comments |
|-----------|-----------------------------|-------|----|---|---------|----------------------------|
| Ν | | | | | | |
| | Marker Board | 22 | LF | 7 | \$0 | |
| V | Nalls - Plaster/Drywall | 1,153 | SF | 5 | \$8,739 | |
| Classroor | n #104 (Regular Classroom) | | | | | |
| F | AC Units | 1 | EA | 7 | \$0 | |
| C | Casework | 6 | LF | 5 | \$1,254 | |
| C | Ceiling - Splined | 709 | SF | 6 | \$578 | |
| [| Doors - Transom Window | 10 | SF | 7 | \$0 | |
| [| Doors - Wood Doors inclu hw | 1 | EA | 5 | \$1,174 | |
| F | Floor - Tile | 709 | SF | 7 | \$0 | |
| L | ighting - Pendent/Surface | 21 | EA | 7 | \$0 | |
| Ν | Marker Board | 26 | LF | 7 | \$0 | |
| V | Nalls - Plaster/Drywall | 1,100 | SF | 6 | \$3,036 | |
| Classroor | n #105 (Regular Classroom) | | | | | |
| F | AC Units | 1 | EA | 7 | \$0 | |
| (| Casework | 6 | LF | 5 | \$1,254 | |
| (| Ceiling - Splined | 709 | SF | 7 | \$0 | |
| Γ | Doors - Transom Window | 10 | SF | 7 | \$0 | |
| Γ | Doors - Wood Doors inclu hw | 1 | EA | 5 | \$1,174 | |
| F | Floor - Tile | 709 | SF | 7 | \$0 | |
| L | ighting - Pendent/Surface | 20 | EA | 7 | \$0 | |
| L | ighting - Pendent/Surface | 1 | EA | 6 | \$124 | |
| Ν | Marker Board | 32 | LF | 7 | \$0 | |
| V | Nalls - Plaster/Drywall | 1,100 | SF | 6 | \$3,036 | |
| Classroor | n #106 (Regular Classroom) | | | | | |
| F | AC Units | 1 | EA | 7 | \$0 | |
| (| Casework | 6 | LF | 6 | \$152 | |
| (| Ceiling - Splined | 677 | SF | 7 | \$0 | |
| (| Chalk Board | 40 | LF | 4 | \$3,672 | |
| ٢ | Doors - Transom Window | 10 | SF | 7 | \$0 | |
| ٢ | Doors - Wood Doors inclu hw | 1 | EA | 5 | \$1,174 | |
| F | Floor - Tile | 677 | SF | 7 | \$0 | |
| l | .ighting - Pendent/Surface | 18 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3 | EA | 6 | \$372 | |
| | Walls - Plaster/Drywall | 1,086 | SF | 7 | \$0 | covered with wood paneling |

5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| | Item - Type | Location | Quantity | l Ini+ | Pank | Cost | Comments |
|---------|--------------------------------------|----------|-----------|--------|-------|----------------|----------|
| - | bom #107 (Office) | LUCAUUI | Qualitity | Unit | nalik | Cost | Comments |
| Classic | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | | 7 | \$0 \$0 | |
| | Ceiling - Splined | | 438 | SF | 7 | \$0 \$0 | |
| | Doors - Wood Doors inclu hw | | 430 | EA | 6 | \$0 \$301 | |
| | Floor - Tile | | 438 | SF | 7 | \$301 \$0 | |
| | Lighting - Pendent/Surface | | 438 | EA | 7 | \$0 \$0 | |
| | Marker Board | | 9 10 | | 7 | \$0 \$0 | |
| | Walls - Plaster/Drywall | | 924 | SF | 5 | \$0 \$7,003 | |
| | Waiis - Plaster/Drywaii | | 924 | SF | Э | \$7,003 | |
| Classro | oom #201 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | LF | 7 | \$0 | |
| | Ceiling - Splined | | 667 | SF | 7 | \$0 | |
| | Ceiling - Splined | | 10 | SF | 6 | \$11 | |
| | Chalk Board | | 26 | LF | 4 | \$2,387 | |
| | Doors - Transom Window | | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 677 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 18 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,086 | SF | 6 | \$2,997 | |
| Classro | oom #202A & 202B (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 12 | LF | 7 | \$0 | |
| | Ceiling - Splined | | 709 | SF | 7 | \$0 | |
| | Doors - Transom Window | | 20 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 709 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 2 | EA | 6 | \$248 | |
| | Marker Board | | 35 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,100 | SF | 6 | \$3,036 | |
| Classro | oom #203A & 203B (Regular Classroom) | | | | | | |
| 5100010 | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | LF | 7 | \$0 \$0 | |
| | Ceiling - Splined | | 709 | SF | 7 | \$0 \$0 | |
| | Doors - Transom Window | | 20 | SF | 7 | \$0 \$0 | |
| | | | 20 | 0 | ' | φU | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--------------------------------------|----------|----------|------|------|---------|----------|
| - | oom #203A & 203B (Regular Classroom) | | , | | | | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 5 | \$2,348 | |
| | Floor - Tile | | 709 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 2 | EA | 6 | \$248 | |
| | Marker Board | | 19 | LF | 5 | \$963 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,100 | SF | 6 | \$3,036 | |
| assro | oom #204 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 14 | LF | 5 | \$2,927 | |
| | Ceiling - Splined | | 709 | SF | 7 | \$0 | |
| | Doors - Transom Window | | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 709 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,100 | SF | 5 | \$8,337 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| assro | oom #205 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 14 | LF | 5 | \$2,927 | |
| | Ceiling - Splined | | 709 | SF | 7 | \$0 | |
| | Chalk Board | | 16 | LF | 4 | \$1,469 | |
| | Doors - Transom Window | | 16 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 709 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,100 | SF | 5 | \$8,337 | |
| | Work Sink | | 1 | EA | 5 | \$1,508 | |
| assro | oom #207 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | LF | 6 | \$152 | |
| | Ceiling - Splined | | 677 | SF | 7 | \$0 | |
| | Chalk Board | | 16 | LF | 4 | \$1,469 | |
| | Doors - Transom Window | | 10 | SF | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|------------------------------|----------|----------|------|------|---------|-----------|
| | oom #207 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile/Sheet | | 677 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 2 | EA | 6 | \$248 | |
| | Lighting - Pendent/Surface | | 19 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 6 | \$343 | |
| | Walls - Plaster/Drywall | | 1,086 | SF | 6 | \$2,997 | |
| assro | oom #208 (Science) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 157 | LF | 6 | \$3,965 | |
| | Ceiling - Splined | | 1,069 | SF | 6 | \$871 | |
| | Doors - Wood Doors inclu hw | | 3 | EA | 6 | \$903 | |
| | Floor - Tile | | 1,069 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 33 | EA | 7 | \$0 | |
| | Marker Board | | 6 | LF | 7 | \$0 | |
| | Storage/ Closet | | 198 | SF | 6 | \$1,436 | no access |
| | Walls - Plaster/Drywall | | 1,313 | SF | 6 | \$3,624 | |
| | Work Sink | | 3 | EA | 5 | \$4,523 | |
| | Work Sink | | 4 | EA | 6 | \$1,516 | |
| assro | om #209 (Special Education) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Splined | | 355 | SF | 7 | \$0 | |
| | Doors - Transom Window | | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 355 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 9 | EA | 7 | \$0 | |
| | Marker Board | | 14 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 550 | SF | 7 | \$0 | |
| assro | om #210 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 25 | LF | 6 | \$631 | |
| | Ceiling - Splined | | 926 | SF | 7 | \$0 | |
| | Doors - Transom Window | | 20 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 3 | EA | 5 | \$3,522 | |
| | Floor - Tile | | 926 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 27 | EA | 7 | \$0 | |
| | Marker Board | | 12 | LF | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|----------|----------|------|------|-----------|----------|
| lassroom #210 (Regular Classroom) | | | | | | |
| Storage/ Closet | | 60 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall | | 1,192 | SF | 5 | \$9,034 | |
| Work Sink | | 2 | EA | 7 | \$0 | |
| lassroom #211 (Science) | | | | | | |
| AC Units | | 2 | EA | 7 | \$0 | |
| Casework | | 18 | LF | 6 | \$455 | |
| Ceiling - Splined | | 894 | SF | 7 | \$0 | |
| Doors - Transom Window | | 20 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | | 3 | EA | 5 | \$3,522 | |
| Floor - Tile | | 894 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | | 27 | EA | 6 | \$3,345 | |
| Marker Board | | 10 | LF | 7 | \$0 | |
| Storage/ Closet | | 8 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall | | 1,148 | SF | 5 | \$8,701 | |
| lassroom #215 (Special Program) | | | | | | |
| AC Units | | 1 | EA | 7 | \$0 | |
| Casework | | 6 | LF | 7 | \$0 | |
| Ceiling - Splined | | 438 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| Floor - Tile | | 438 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | | 1 | EA | 6 | \$124 | |
| Lighting - Pendent/Surface | | 8 | EA | 7 | \$0 | |
| Marker Board | | 16 | LF | 6 | \$343 | |
| Walls - Plaster/Drywall | | 924 | SF | 5 | \$7,003 | |
| Classrooms Subtotal: | | | | | \$147,664 | |

Building: Main

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|-------------------------------|-----------------------------------|----------|------|------|---------------|
| Administrative Suites/Offices | | | | | |
| Ceiling - Plaster/Drywall | 003C Office Basement (45 on Plan) | 360 | SF | 6 | \$1,246 |
| Doors - Wood Doors inclu hw | 003C Office Basement (45 on Plan) | 1 | EA | 6 | \$301 |
| Floor - Tile/Sheet | 003C Office Basement (45 on Plan) | 360 | SF | 7 | \$0 |
| Lighting - Lay-in | 003C Office Basement (45 on Plan) | 3 | EA | 7 | \$0 |
| Lighting - Lay-in | 003C Office Basement (45 on Plan) | 1 | EA | 5 | \$162 |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|-----------------------------------|----------|------|------|----------|--|
| Admini | strative Suites/Offices | | | | | | |
| | Power Distribution | 003C Office Basement (45 on Plan) | 2 | EA | 6 | \$4,250 | |
| | Walls - Plaster/Drywall | 003C Office Basement (45 on Plan) | 688 | SF | 7 | \$0 | |
| | AC Unit | 007 Engineer's Office | 1 | EA | 7 | \$0 | |
| | Ceiling - Splined | 007 Engineer's Office | 300 | SF | 4 | \$3,132 | missing and badly damaged spline ceiling |
| | Doors - Wood Doors inclu hw | 007 Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 007 Engineer's Office | 300 | SF | 6 | \$656 | |
| | Lighting - Lay-in | 007 Engineer's Office | 4 | EA | 5 | \$649 | |
| | Power Distribution | 007 Engineer's Office | 5 | EA | 7 | \$0 | |
| | Walls - Masonry | 007 Engineer's Office | 255 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 007 Engineer's Office | 350 | SF | 6 | \$966 | |
| | Ceiling - Plaster/Drywall | 009E Kitchen Office | 356 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 009E Kitchen Office | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | 009E Kitchen Office | 356 | SF | 7 | \$0 | Room is used for Kitchen storage too |
| | Lighting - Pendent/Surface | 009E Kitchen Office | 5 | EA | 7 | \$0 | |
| | Power Distribution | 009E Kitchen Office | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 009E Kitchen Office | 240 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 009E Kitchen Office | 520 | SF | 7 | \$0 | |
| | Ceiling - Splined | 100 Northwest Main Office | 244 | SF | 7 | \$0 | |
| | Ceiling - Splined | 100 Northwest Main Office | 109 | SF | 7 | \$0 | |
| | Doors - Transom Window | 100 Northwest Main Office | 20 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 100 Northwest Main Office | 3 | EA | 7 | \$0 | |
| | Floor - Carpet | 100 Northwest Main Office | 353 | SF | 5 | \$1,812 | |
| | Lighting - Lay-in | 100 Northwest Main Office | 6 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 100 Northwest Main Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | 100 Northwest Main Office | 4 | EA | 7 | \$0 | |
| | Storage/ Closet | 100 Northwest Main Office | 9 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 100 Northwest Main Office | 837 | SF | 6 | \$2,310 | some walls have wood paneling on them |
| | AC Unit | 100A Office | 1 | EA | 7 | \$0 | |
| | Ceiling - Splined | 100A Office | 370 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 100A Office | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 100A Office | 370 | SF | 5 | \$1,899 | |
| | Lighting - Lay-in | 100A Office | 2 | EA | 5 | \$324 | |
| | Lighting - Lay-in | 100A Office | 6 | EA | 7 | \$0 | |
| | Power Distribution | 100A Office | 8 | EA | 6 | \$16,999 | |
| | Walls - Plaster/Drywall | 100A Office | 796 | SF | 7 | \$0 | |
| | AC Unit | 100 | 1 | EA | 7 | \$0 | |
| | Ceiling - Splined | 100 | 720 | SF | 6 | \$587 | |
| | | | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|-----------------------------------|----------|------|------|----------|------------------------|
| istrative Suites/Offices | | | | | | |
| Doors - Transom Window | 100 | 18 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 100 | 2 | EA | 6 | \$602 | |
| AC Unit | 100F Office | 1 | EA | 7 | \$0 | |
| Ceiling - Splined | 100F Office | 300 | SF | 6 | \$245 | |
| Doors - Wood Doors inclu hw | 100F Office | 1 | EA | 7 | \$0 | |
| Floor - Carpet | 100F Office | 300 | SF | 5 | \$1,540 | |
| Lighting - Lay-in | 100F Office | 8 | EA | 7 | \$0 | |
| Power Distribution | 100F Office | 5 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 100F Office | 700 | SF | 6 | \$1,932 | |
| Floor - Carpet | 100 | 720 | SF | 6 | \$1,534 | |
| Ceiling - Lay-in | 100H Principal's Office | 233 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 100H Principal's Office | 2 | EA | 7 | \$0 | |
| Floor - Carpet | 100H Principal's Office | 233 | SF | 5 | \$1,196 | |
| Lighting - Lay-in | 100H Principal's Office | 3 | EA | 7 | \$0 | |
| Power Distribution | 100H Principal's Office | 4 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 100H Principal's Office | 520 | SF | 6 | \$1,435 | Wood paneling on walls |
| AC Unit | 100l Nurse's Office | 1 | EA | 7 | \$0 | |
| Ceiling - Lay-in | 100I Nurse's Office | 158 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 100I Nurse's Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 100I Nurse's Office | 158 | SF | 5 | \$811 | |
| Lighting - Lay-in | 100I Nurse's Office | 4 | EA | 7 | \$0 | |
| Power Distribution | 100I Nurse's Office | 4 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 100I Nurse's Office | 427 | SF | 6 | \$1,178 | |
| AC Unit | 100K Assistant Principal's Office | 1 | EA | 7 | \$0 | |
| Ceiling - Lay-in | 100K Assistant Principal's Office | 254 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 100K Assistant Principal's Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 100K Assistant Principal's Office | 254 | SF | 6 | \$541 | |
| Lighting - Lay-in | 100K Assistant Principal's Office | 6 | EA | 7 | \$0 | |
| Power Distribution | 100K Assistant Principal's Office | 6 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 100K Assistant Principal's Office | 756 | SF | 6 | \$2,086 | |
| Lighting - Lay-in | 100 | 15 | EA | 7 | \$0 | |
| Power Distribution | 100 | 10 | EA | 6 | \$21,249 | |
| Walls - Plaster/Drywall | 100 | 1,069 | SF | 6 | \$2,950 | |
| Ceiling - Lay-in | 122 Concession Room | 44 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 122 Concession Room | 134 | SF | 6 | \$464 | |
| Doors - Wood Doors inclu hw | 122 Concession Room | 1 | EA | 7 | \$0 | |
| Floor - Tile | 122 Concession Room | 178 | SF | 6 | \$389 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-------------------------------|----------|------|------|---------|---------------------------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Lighting - Lay-in | 122 Concession Room | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 122 Concession Room | 1 | EA | 7 | \$0 | |
| | Power Distribution | 122 Concession Room | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 122 Concession Room | 420 | SF | 6 | \$1,159 | some walls have wood paneling on them |
| | Work SInk | 122 Concession Room | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 123A Gym Office (132 on plan) | 250 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 123A Gym Office (132 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 123A Gym Office (132 on plan) | 250 | SF | 6 | \$533 | |
| | Lighting - Lay-in | 123A Gym Office (132 on plan) | 3 | EA | 7 | \$0 | |
| | Power Distribution | 123A Gym Office (132 on plan) | 5 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 123A Gym Office (132 on plan) | 582 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 206A North Office | 98 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 206A North Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 206A North Office | 98 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 206A North Office | 1 | EA | 7 | \$0 | |
| | Power Distribution | 206A North Office | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 206A North Office | 385 | SF | 7 | \$0 | |
| | AC Unit | 206A South Office | 1 | EA | 7 | \$0 | |
| | Ceiling - Lay-in | 206A South Office | 235 | SF | 7 | \$0 | |
| | Doors - Transom Window | 206A South Office | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 206A South Office | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 206A South Office | 235 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 206A South Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 206A South Office | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 206A South Office | 744 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 206B North Office | 235 | SF | 7 | \$0 | |
| | Doors - Transom Window | 206B North Office | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 206B North Office | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 206B North Office | 235 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 206B North Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 206B North Office | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 206B North Office | 744 | SF | 6 | \$2,053 | |
| | Ceiling - Lay-in | 206B South Office | 98 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 206B South Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 206B South Office | 98 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 206B South Office | 1 | EA | 7 | \$0 | |
| | Power Distribution | 206B South Office | 2 | EA | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|----------------------------------|----------|------|------|----------|-------------|
| lmini | istrative Suites/Offices | | | | | | |
| | Walls - Plaster/Drywall | 206B South Office | 385 | SF | 6 | \$1,063 | |
| | Ceiling - Splined | 208A Office /Prep Room | 148 | SF | 7 | \$0 | |
| | Doors - Side-lite | 208A Office /Prep Room | 10 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 208A Office /Prep Room | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 208A Office /Prep Room | 148 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 208A Office /Prep Room | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 208A Office /Prep Room | 2 | EA | 6 | \$248 | |
| | Walls - Concrete Block | 208A Office /Prep Room | 117 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 208A Office /Prep Room | 447 | SF | 7 | \$0 | |
| | Ceiling - Splined | 210B Prep Room in CR 210 | 106 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 210B Prep Room in CR 210 | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 210B Prep Room in CR 210 | 106 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 210B Prep Room in CR 210 | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 210B Prep Room in CR 210 | 299 | SF | 6 | \$825 | |
| | Ceiling - Splined | 211A Prep Room in CR 211 | 106 | SF | 7 | \$0 | |
| | Doors - Side-lite | 211A Prep Room in CR 211 | 15 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 211A Prep Room in CR 211 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 211A Prep Room in CR 211 | 106 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 211A Prep Room in CR 211 | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 211A Prep Room in CR 211 | 340 | SF | 6 | \$938 | |
| | Ceiling - Plaster/Drywall | Bsmt Nurse's Office (35 on plan) | 165 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Bsmt Nurse's Office (35 on plan) | 2 | EA | 5 | \$2,348 | |
| | Floor - Tile | Bsmt Nurse's Office (35 on plan) | 165 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Bsmt Nurse's Office (35 on plan) | 2 | EA | 7 | \$0 | |
| | Power Distribution | Bsmt Nurse's Office (35 on plan) | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Bsmt Nurse's Office (35 on plan) | 140 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | Bsmt Nurse's Office (35 on plan) | 315 | SF | 7 | \$0 | |
| mna | asia | | | | | | |
| | Bleacher Seating | 123 (158 on plan) | 475 | EA | 6 | \$13,748 | |
| | Ceiling - Lay-in | 123 (158 on plan) | 13,650 | SF | 6 | \$40,991 | Metal Panel |
| | Doors - Wood Doors inclu hw | 123 (158 on plan) | 8 | EA | 6 | \$2,408 | |
| | Floor - Concrete | 123 (158 on plan) | 4,950 | SF | 7 | \$0 | |
| | Floor - Wood | 123 (158 on plan) | 9,555 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 123 (158 on plan) | 55 | EA | 6 | \$6,814 | |
| | Lighting - Pendent/Surface | 123 (158 on plan) | 30 | EA | 5 | \$5,477 | |
| | Scoreboards | 123 (158 on plan) | 1 | EA | 6 | \$2,244 | |
| | Sound System | 123 (158 on plan) | 1 | EA | 6 | \$41,654 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------------------------|----------|------|------|----------|-----------------|
| Symna | sia | | | | | | |
| | Stage | 123 (158 on plan) | 2,040 | SF | 5 | \$30,631 | |
| | Stage Curtain | 123 (158 on plan) | 1 | EA | 6 | \$0 | |
| | Stage Lighting System | 123 (158 on plan) | 1 | EA | 6 | \$12,369 | |
| | Storage/ Closet | 123 (158 on plan) | 300 | SF | 6 | \$2,175 | |
| | Walls - Masonry | 123 (158 on plan) | 18,250 | SF | 6 | \$57,415 | |
| litcher | 1 | | | | | | |
| | Ceiling - Lay-in | 009A Cooking/Kitchen | 108 | SF | 6 | \$324 | |
| | Ceiling - Plaster/Drywall | 009A Cooking/Kitchen | 622 | SF | 6 | \$2,152 | |
| | Doors - Transom Window | 009A Cooking/Kitchen | 60 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 009A Cooking/Kitchen | 4 | EA | 5 | \$4,696 | |
| | Floor - Tile | 009A Cooking/Kitchen | 730 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 009A Cooking/Kitchen | 14 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 009A Cooking/Kitchen | 130 | SF | 6 | \$409 | |
| | Walls - Tile Ceramic/ Porcelain | 009A Cooking/Kitchen | 862 | SF | 6 | \$1,948 | chips @ corners |
| ocker | /Shower Room | | | | | | |
| | Accessories | 009F Kitchen Staff Basement | 183 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | 009F Kitchen Staff Basement | 183 | SF | 6 | \$633 | |
| | Doors - Wood Doors inclu hw | 009F Kitchen Staff Basement | 2 | EA | 6 | \$602 | |
| | Floor Drain | 009F Kitchen Staff Basement | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 009F Kitchen Staff Basement | 183 | SF | 7 | \$0 | |
| | Lavatory | 009F Kitchen Staff Basement | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 009F Kitchen Staff Basement | 2 | EA | 5 | \$365 | |
| | Walls - Plaster/Drywall | 009F Kitchen Staff Basement | 250 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 009F Kitchen Staff Basement | 526 | SF | 7 | \$0 | |
| | Water Closet | 009F Kitchen Staff Basement | 1 | EA | 7 | \$0 | |
| | Accessories | Basement in Corridor 001D | 81 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement in Corridor 001D | 81 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Basement in Corridor 001D | 1 | EA | 5 | \$1,174 | |
| | Floor Drain | Basement in Corridor 001D | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | Basement in Corridor 001D | 81 | SF | 7 | \$0 | |
| | Lavatory | Basement in Corridor 001D | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Basement in Corridor 001D | 2 | EA | 7 | \$0 | |
| | Urinals | Basement in Corridor 001D | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Basement in Corridor 001D | 146 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement in Corridor 001D | 278 | SF | 7 | \$0 | |
| | Water Closet | Basement in Corridor 001D | 1 | EA | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| ıp Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|-------------------------------|----------|------|------|----------|----------|
| h & Multipurpose Room | | | | | | |
| Ceiling - Plaster/Drywall | 001 Faculty Luncroom Basement | 560 | SF | 6 | \$1,938 | |
| Doors - Wood Doors inclu hw | 001 Faculty Luncroom Basement | 2 | EA | 5 | \$2,348 | |
| Floor - Tile | 001 Faculty Luncroom Basement | 560 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 001 Faculty Luncroom Basement | 3 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 001 Faculty Luncroom Basement | 937 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 006 Multipurpose Room | 4,580 | SF | 6 | \$13,754 | |
| Ceiling - Plaster/Drywall | 006 Multipurpose Room | 1,000 | SF | 6 | \$3,461 | |
| Doors - Wood Doors inclu hw | 006 Multipurpose Room | 4 | EA | 6 | \$1,204 | |
| Floor - Carpet | 006 Multipurpose Room | 2,000 | SF | 7 | \$0 | |
| Floor - Tile | 006 Multipurpose Room | 2,580 | SF | 7 | \$0 | |
| Lighting - Lay-in | 006 Multipurpose Room | 22 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | 006 Multipurpose Room | 6 | EA | 7 | \$0 | |
| Stage | 006 Multipurpose Room | 1,260 | SF | 6 | \$7,279 | |
| Storage/ Closet | 006 Multipurpose Room | 400 | SF | 6 | \$2,900 | |
| Walls - Plaster/Drywall | 006 Multipurpose Room | 2,290 | SF | 6 | \$6,320 | |
| Walls - Structural Glazed Tile | 006 Multipurpose Room | 1,890 | SF | 6 | \$5,946 | |
| AC Unit | 009 Dining East Basement | 5 | EA | 6 | \$2,478 | |
| Ceiling - Splined | 009 Dining East Basement | 2,475 | SF | 6 | \$2,017 | |
| Floor - Tile | 009 Dining East Basement | 2,475 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 009 Dining East Basement | 40 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 009 Dining East Basement | 612 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tile | 009 Dining East Basement | 852 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | 009 Dining East Basement | 260 | SF | 7 | \$0 | |
| AC Unit | 009 West Cafeteria Basement | 5 | EA | 6 | \$2,478 | |
| Ceiling - Splined | 009 West Cafeteria Basement | 2,475 | SF | 6 | \$2,017 | |
| Doors - Wood Doors inclu hw | 009 West Cafeteria Basement | 1 | EA | 6 | \$301 | |
| Floor - Tile | 009 West Cafeteria Basement | 2,475 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 009 West Cafeteria Basement | 63 | EA | 7 | \$0 | |
| Walls - Concrete Block | 009 West Cafeteria Basement | 192 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall | 009 West Cafeteria Basement | 640 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tile | 009 West Cafeteria Basement | 892 | SF | 7 | \$0 | |
| Ceiling - Splined | Servery Basement | 675 | SF | 6 | \$550 | |
| Doors - Wood Doors inclu hw | Servery Basement | 4 | EA | 5 | \$4,696 | |
| Floor - Tile | Servery Basement | 675 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | Servery Basement | 6 | EA | 7 | \$0 | |
| Serving Line | Servery Basement | 52 | LF | 7 | \$0 | |
| Walls - Plaster/Drywall | Servery Basement | 195 | SF | 6 | \$538 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--|----------|------|------|----------|--|
| unch 8 | & Multipurpose Room | | | | | | |
| | Walls - Structural Glazed Tile | Servery Basement | 340 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | Servery Basement | 60 | SF | 7 | \$0 | |
| lechan | nical/ Service Rooms | | | | | | |
| | Boiler Room | Entire Building | 1,544 | SF | 6 | \$11,062 | 007 Basement |
| | Janitor's Closet | Entire Building | 40 | SF | 5 | \$645 | 002A Basement |
| | Mechanical/ Service Rooms | Entire Building | 916 | SF | 6 | \$6,562 | Mechanical 301 3rd Floor |
| | Mechanical/ Service Rooms | Entire Building | 450 | SF | 5 | \$7,259 | 37/39/40 150 each Basement No Access |
| | Mechanical/ Service Rooms | Entire Building | 50 | SF | 7 | \$0 | Kitchenette 100E |
| | Mechanical/ Service Rooms | Entire Building | 75 | SF | 7 | \$0 | Electrical 007B |
| | Mechanical/ Service Rooms | Entire Building | 125 | SF | 6 | \$896 | Laundry Room 004A |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | 124A Gym Stage Storage |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | Basketball 123E Gymnasium |
| | Storage Room | Entire Building | 185 | SF | 6 | \$1,325 | 007A & 007F |
| | Storage Room | Entire Building | 640 | SF | 6 | \$4,585 | 005D Basement |
| | Storage Room | Entire Building | 225 | SF | 5 | \$3,629 | 007A Engineers storage (formerly Drying Roor |
| | Storage Room | Entire Building | 70 | SF | 6 | \$502 | 005B Basement |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | 123D Gymnasium |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | 123C Gym Storage |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | 124B Gym Stage Storage |
| | Storage Room | Entire Building | 75 | SF | 6 | \$537 | 005A Basement |
| | Storage Room | Entire Building | 1,643 | SF | 5 | \$26,502 | 004, 001, 002, 003 Basement |
| | Storage Room | Entire Building | 300 | SF | 6 | \$2,149 | 123F Gymnasium |
| | Storage Room | Entire Building | 53 | SF | 6 | \$380 | 100D |
| | Storage Room | Entire Building | 95 | SF | 7 | \$0 | 100G |
| | Storage Room | Entire Building | 145 | SF | 6 | \$1,039 | 005C Basement |
| | Storage Room | Entire Building | 1,080 | SF | 5 | \$17,421 | Resource Storage |
| | Storage Room | Entire Building | 410 | SF | 5 | \$6,613 | - |
| | Vaults | Entire Building | 85 | SF | 5 | \$1,371 | 100C 1st Floor |
| estroc | om | | | | | | |
| | Accessories | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 80 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 80 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 1 | EA | 5 | \$1,174 | |
| | Floor Drain | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 1 | EA | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|--|----------|------|------|----------|----------------------------|
| Restroc | om | | | | | | |
| | Floor - Terrazzo | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 80 | SF | 7 | \$0 | |
| | Lavatory | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 2 | EA | 7 | \$0 | |
| | Urinals | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 146 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 278 | SF | 7 | \$0 | |
| | Water Closet | 001A Unisex Toilet in Faculty Lounge (32 on plan) | 1 | EA | 7 | \$0 | |
| | Accessories | 003B Basement | 135 | SF | 6 | \$1,245 | |
| | Ceiling - Plaster/Drywall | 003B Basement | 135 | SF | 6 | \$467 | |
| | Floor Drain | 003B Basement | 2 | EA | 5 | \$4,188 | |
| | Floor - Terrazzo | 003B Basement | 135 | SF | 5 | \$5,081 | |
| | Lavatory | 003B Basement | 1 | EA | 5 | \$1,590 | |
| | Lighting - Lay-in | 003B Basement | 3 | EA | 5 | \$487 | |
| | Showers | 003B Basement | 3 | EA | 5 | \$3,515 | |
| | Urinals | 003B Basement | 2 | EA | 5 | \$2,688 | |
| | Walls - Plaster/Drywall | 003B Basement | 120 | SF | 6 | \$331 | |
| | Walls - Structural Glazed Tile | 003B Basement | 280 | SF | 6 | \$881 | |
| | Water Closet | 003B Basement | 1 | EA | 5 | \$1,344 | |
| | Accessories | 003D Staff Basement | 130 | SF | 5 | \$2,573 | damaged and not functional |
| | Ceiling - Plaster/Drywall | 003D Staff Basement | 130 | SF | 5 | \$1,192 | |
| | Doors - Wood Doors inclu hw | 003D Staff Basement | 1 | EA | 6 | \$301 | |
| | Floor Drain | 003D Staff Basement | 2 | EA | 5 | \$4,188 | |
| | Floor - Terrazzo | 003D Staff Basement | 130 | SF | 5 | \$4,893 | |
| | Lavatory | 003D Staff Basement | 1 | EA | 4 | \$7,342 | damaged and not functional |
| | Lighting - Lay-in | 003D Staff Basement | 2 | EA | 6 | \$238 | |
| | Showers | 003D Staff Basement | 3 | EA | 4 | \$14,161 | damaged and not funational |
| | Urinals | 003D Staff Basement | 2 | EA | 4 | \$15,339 | damaged and not functional |
| | Walls - Plaster/Drywall | 003D Staff Basement | 100 | SF | 5 | \$758 | |
| | Walls - Structural Glazed Tile | 003D Staff Basement | 250 | SF | 5 | \$12,702 | |
| | Water Closet | 003D Staff Basement | 1 | EA | 4 | \$7,669 | damaged and not functional |
| | Accessories | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 150 | SF | 6 | \$1,384 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|--|----------|------|------|---------|----------|
| Restroc | om | | | | | | |
| | Ceiling - Plaster/Drywall | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 150 | SF | 6 | \$519 | |
| | Doors - Wood Doors inclu hw | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 1 | EA | 7 | \$0 | |
| | Floor Drain | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 150 | SF | 6 | \$328 | |
| | Lavatory | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 2 | EA | 5 | \$324 | |
| | Showers | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 1 | EA | 5 | \$1,172 | |
| | Walls - Plaster/Drywall | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 200 | SF | 6 | \$552 | |
| | Walls - Structural Glazed Tile | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 300 | SF | 6 | \$944 | |
| | Water Closet | 123A-1 Unisex Toilet in Gym Office (134 on plan) | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor East Boys (109 on plan) | 300 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor East Boys (109 on plan) | 300 | SF | 7 | \$0 | |
| | Doors - Transom Window | 1st Floor East Boys (109 on plan) | 20 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor East Boys (109 on plan) | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor East Boys (109 on plan) | 2 | EA | 7 | \$0 | |
| | Floor Drain | 1st Floor East Boys (109 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 1st Floor East Boys (109 on plan) | 300 | SF | 7 | \$0 | |
| | Hand Dryer | 1st Floor East Boys (109 on plan) | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor East Boys (109 on plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor East Boys (109 on plan) | 4 | EA | 7 | \$0 | |
| | Partitions | 1st Floor East Boys (109 on plan) | 2 | EA | 7 | \$0 | |
| | Urinals | 1st Floor East Boys (109 on plan) | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor East Boys (109 on plan) | 298 | SF | 6 | \$822 | |
| | Walls - Structural Glazed Tile | 1st Floor East Boys (109 on plan) | 554 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor East Boys (109 on plan) | 2 | EA | 7 | \$0 | |
| | Accessories | 1st Floor Girls (125 on plan) | 342 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor Girls (125 on plan) | 342 | SF | 7 | \$0 | |
| | Doors - Transom Window | 1st Floor Girls (125 on plan) | 18 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor Girls (125 on plan) | 2 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor Girls (125 on plan) | 1 | EA | 6 | \$301 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|-----------------------------------|----------|------|------|---------|----------|
| Restro | om | | | | | | |
| | Floor Drain | 1st Floor Girls (125 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 1st Floor Girls (125 on plan) | 342 | SF | 7 | \$0 | |
| | Hand Dryer | 1st Floor Girls (125 on plan) | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor Girls (125 on plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor Girls (125 on plan) | 7 | EA | 7 | \$0 | |
| | Partitions | 1st Floor Girls (125 on plan) | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor Girls (125 on plan) | 315 | SF | 6 | \$869 | |
| | Walls - Structural Glazed Tile | 1st Floor Girls (125 on plan) | 576 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor Girls (125 on plan) | 6 | EA | 7 | \$0 | |
| | Accessories | 1st Floor West Boys (130 on plan) | 227 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor West Boys (130 on plan) | 227 | SF | 5 | \$2,081 | |
| | Doors - Wood Doors inclu hw | 1st Floor West Boys (130 on plan) | 1 | EA | 7 | \$0 | |
| | Floor Drain | 1st Floor West Boys (130 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 1st Floor West Boys (130 on plan) | 227 | SF | 7 | \$0 | |
| | Hand Dryer | 1st Floor West Boys (130 on plan) | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor West Boys (130 on plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor West Boys (130 on plan) | 5 | EA | 7 | \$0 | |
| | Partitions | 1st Floor West Boys (130 on plan) | 3 | EA | 7 | \$0 | |
| | Urinals | 1st Floor West Boys (130 on plan) | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor West Boys (130 on plan) | 210 | SF | 6 | \$580 | |
| | Walls - Structural Glazed Tile | 1st Floor West Boys (130 on plan) | 455 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor West Boys (130 on plan) | 3 | EA | 7 | \$0 | |
| | Accessories | 2nd Floor East Boys (205 on plan) | 300 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor East Boys (205 on plan) | 300 | SF | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor East Boys (205 on plan) | 20 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor East Boys (205 on plan) | 2 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor East Boys (205 on plan) | 1 | EA | 6 | \$301 | |
| | Floor Drain | 2nd Floor East Boys (205 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 2nd Floor East Boys (205 on plan) | 300 | SF | 7 | \$0 | |
| | Hand Dryer | 2nd Floor East Boys (205 on plan) | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 2nd Floor East Boys (205 on plan) | 1 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor East Boys (205 on plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor East Boys (205 on plan) | 4 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor East Boys (205 on plan) | 2 | EA | 7 | \$0 | |
| | Urinals | 2nd Floor East Boys (205 on plan) | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor East Boys (205 on plan) | 298 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor East Boys (205 on plan) | 554 | SF | 7 | \$0 | |
| | | , | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Main

| Acce Ceili Door Floo Floo | er Closet essories ing - Plaster/Drywall rs - Wood Doors inclu hw r Drain | 2nd Floor East Boys (205 on plan) Basement Boys West Basement Boys West | 2 148 | EA | 7 | \$0 | |
|--|---|---|----------|-----|---|---------|--|
| Acce Ceili Door Floo Floo Han | essories ing - Plaster/Drywall rs - Wood Doors inclu hw | Basement Boys West Basement Boys West | | | 7 | \$0 | |
| Ceili Door Floo Floo Han | ng - Plaster/Drywall rs - Wood Doors inclu hw | Basement Boys West | 148 | ~ - | | ΨŬ | |
| Door Floo Floo Han | rs - Wood Doors inclu hw | - | | SF | 7 | \$0 | |
| Floo Floo Hand | | | 148 | SF | 6 | \$512 | |
| Floo Hand | r Drain | Basement Boys West | 1 | EA | 6 | \$301 | |
| Hand | | Basement Boys West | 1 | EA | 7 | \$0 | |
| | r - Terrazzo | Basement Boys West | 148 | SF | 7 | \$0 | |
| Lava | d Dryer | Basement Boys West | 2 | EA | 7 | \$0 | |
| | atory | Basement Boys West | 1 | EA | 7 | \$0 | |
| Light | ting - Pendent/Surface | Basement Boys West | 1 | EA | 6 | \$124 | |
| Light | ting - Pendent/Surface | Basement Boys West | 2 | EA | 7 | \$0 | |
| Parti | itions | Basement Boys West | 1 | EA | 6 | \$297 | |
| Urina | als | Basement Boys West | 3 | EA | 7 | \$0 | |
| Wall | ls - Plaster/Drywall | Basement Boys West | 244 | SF | 6 | \$673 | |
| Wall | ls - Structural Glazed Tile | Basement Boys West | 346 | SF | 7 | \$0 | |
| Wate | er Closet | Basement Boys West | 1 | EA | 7 | \$0 | |
| Acce | essories | Basement Girls West | 342 | SF | 7 | \$0 | |
| Ceili | ng - Plaster/Drywall | Basement Girls West | 342 | SF | 6 | \$1,184 | |
| Door | rs - Transom Window | Basement Girls West | 18 | SF | 7 | \$0 | |
| Door | rs - Wood Doors inclu hw | Basement Girls West | 2 | EA | 7 | \$0 | |
| Door | rs - Wood Doors inclu hw | Basement Girls West | 1 | EA | 6 | \$301 | |
| Floo | r Drain | Basement Girls West | 1 | EA | 7 | \$0 | |
| Floo | r - Terrazzo | Basement Girls West | 342 | SF | 7 | \$0 | |
| Hand | d Dryer | Basement Girls West | 2 | EA | 7 | \$0 | |
| Lava | atory | Basement Girls West | 2 | EA | 7 | \$0 | |
| Light | ting - Pendent/Surface | Basement Girls West | 7 | EA | 7 | \$0 | |
| Parti | itions | Basement Girls West | 6 | EA | 7 | \$0 | |
| Wall | ls - Plaster/Drywall | Basement Girls West | 318 | SF | 6 | \$878 | |
| Wall | ls - Structural Glazed Tile | Basement Girls West | 576 | SF | 7 | \$0 | |
| Wate | er Closet | Basement Girls West | 6 | EA | 7 | \$0 | |
| Acce | essories | Boiler Room | 33 | SF | 6 | \$304 | |
| Ceili | ng - Plaster/Drywall | Boiler Room | 33 | SF | 5 | \$302 | |
| Door | rs - Wood Doors inclu hw | Boiler Room | 1 | EA | 6 | \$301 | |
| Floo | r Drain | Boiler Room | 1 | EA | 7 | \$0 | |
| Floo | r - Concrete | Boiler Room | 33 | SF | 6 | \$17 | |
| Lava | atory | Boiler Room | 1 | EA | 6 | \$320 | |
| Light | ting - Pendent/Surface | Boiler Room | 1 | EA | 5 | \$183 | |
| | ls - Plaster/Drywall | Boiler Room | 164 | SF | 5 | \$1,243 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

\$593,598

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|------------------------------|----------|------|------|-------|----------|
| Restro | om | | | | | | |
| | Water Closet | Boiler Room | 1 | EA | 7 | \$0 | |
| | Accessories | Northwest Main Office Toilet | 40 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Northwest Main Office Toilet | 40 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Northwest Main Office Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Northwest Main Office Toilet | 40 | SF | 7 | \$0 | |
| | Lavatory | Northwest Main Office Toilet | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Northwest Main Office Toilet | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Northwest Main Office Toilet | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Northwest Main Office Toilet | 104 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Northwest Main Office Toilet | 156 | SF | 7 | \$0 | |
| | Water Closet | Northwest Main Office Toilet | 1 | EA | 7 | \$0 | |

Rooms (Other Than Classrooms) Subtotal:

Building: Main

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|------------------------------------|----------|------|------|----------|----------|
| Corrido | r | | | | | | |
| | Ceiling - Plaster/Drywall | 001D In Faculty Lunchroom Basement | 119 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | 001D In Faculty Lunchroom Basement | 5 | EA | 5 | \$5,870 | |
| | Floor - Tile/Sheet | 001D In Faculty Lunchroom Basement | 119 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 001D In Faculty Lunchroom Basement | 1 | EA | 4 | \$541 | |
| | Walls - Concrete Block | 001D In Faculty Lunchroom Basement | 140 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 001D In Faculty Lunchroom Basement | 203 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 001D In Faculty Lunchroom Basement | 84 | SF | 7 | \$0 | |
| | Ceiling - Splined | 009B Receving Corridor Basement | 205 | SF | 6 | \$592 | |
| | Doors - Transom Window | 009B Receving Corridor Basement | 60 | EA | 7 | \$0 | |
| | Doors - Wood Doors include hw | 009B Receving Corridor Basement | 2 | EA | 5 | \$2,348 | |
| | Floor - Tile/Sheet | 009B Receving Corridor Basement | 205 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 009B Receving Corridor Basement | 2 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 009B Receving Corridor Basement | 242 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | 009B Receving Corridor Basement | 376 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 3,466 | SF | 5 | \$24,683 | |
| | Doors - Side-lite | 1st Floor | 42 | EA | 7 | \$0 | |
| | Doors - Store Front | 1st Floor | 4 | EA | 7 | \$0 | |
| | Doors - Store Front | 1st Floor | 4 | EA | 6 | \$4,833 | |
| | Doors - Transom Window | 1st Floor | 70 | EA | 7 | \$0 | |



Category: Building Interior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| р | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|--|-------------------|----------|------|------|----------|----------|
| idor | r | | | | | | |
| | Doors - Wood Doors include hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| | Drinking Fountains - Single Fountain | 1st Floor | 1 | EA | 6 | \$276 | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 1st Floor | 2,298 | SF | 7 | \$0 | |
| | Floor - Terrazzo | 1st Floor | 1,790 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor | 38 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | 1st Floor | 97 | LF | 7 | \$0 | |
| | Student Lockers - One Tier | 1st Floor | 81 | EA | 5 | \$11,352 | |
| | Walls - Masonry | 1st Floor | 1,469 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,682 | SF | 6 | \$7,456 | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,564 | SF | 7 | \$0 | |
| | Ceiling - Splined | 2nd Floor | 2,622 | SF | 5 | \$18,672 | |
| | Doors - Wood Doors include hw | 2nd Floor | 4 | EA | 6 | \$1,204 | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 2nd Floor | 2,622 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 2nd Floor | 156 | EA | 5 | \$21,864 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,647 | SF | 5 | \$12,153 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 2,719 | SF | 7 | \$0 | |
| | Ceiling - Splined | Basement Corridor | 2,631 | SF | 5 | \$18,736 | |
| | Floor - Terrazzo | Basement Corridor | 2,631 | SF | 5 | \$99,025 | |
| | Lighting - Lay-in | Basement Corridor | 12 | EA | 6 | \$1,428 | |
| | Student Lockers | Basement Corridor | 10 | EA | 6 | \$0 | |
| | Walls - Masonry | Basement Corridor | 3,575 | SF | 6 | \$11,247 | |
| | Walls - Plaster/Drywall | Basement Corridor | 100 | SF | 6 | \$443 | |
| | Ceiling - Splined | Basement | 2,496 | SF | 6 | \$7,210 | |
| | Doors - Steel Doors incl hw | Basement | 2 | EA | 5 | \$2,758 | |
| | Doors - Wood Doors include hw | Basement | 7 | EA | 6 | \$2,107 | |
| | Doors - Wood Doors include hw | Basement | 6 | EA | 7 | \$0 | |
| | Doors - Wood Doors include hw | Basement | 2 | EA | 5 | \$2,348 | |
| | Drinking Fountains - Single Fountain | Basement | 1 | EA | 5 | \$1,180 | |
| | Drinking Fountains - Single Water Cooler | Basement | 1 | EA | 5 | \$3,007 | |
| | Floor - Terrazzo | Basement | 1,029 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | Basement | 2,307 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Basement | 10 | EA | 7 | \$0 | |



Category: Building Interior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------------------------|----------|------|------|----------|----------|
| Corrido | | | | | | | |
| | Lighting - Pendent/Surface | Basement | 13 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Basement | 48 | LF | 6 | \$445 | |
| | Walls - Plaster/Drywall | Basement | 1,052 | SF | 6 | \$4,664 | |
| | Walls - Structural Glazed Tile | Basement | 1,588 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | Basement | 190 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Kitchen Corridor Basement | 78 | SF | 6 | \$483 | |
| | Ceiling - Splined | Kitchen Corridor Basement | 72 | SF | 6 | \$208 | |
| | Doors - Wood Doors include hw | Kitchen Corridor Basement | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Kitchen Corridor Basement | 150 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Kitchen Corridor Basement | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Kitchen Corridor Basement | 204 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Kitchen Corridor Basement | 510 | SF | 7 | \$0 | |
| Safety | | | | | | | |
| arety | Camera Viewing Station | Assistant Principal Offices | 2 | EA | 6 | \$1,365 | |
| | Security Cameras | Assistant Principal Offices | 18 | EA | 5 | \$12,379 | |
| | Security Cameras | Assistant Principal Offices | 35 | EA | 7 | \$0 | |
| | | . looiotant i inoipai omooo | | -/ (| | ψυ | |
| Stairs | | | | | | | |
| | Ceiling - Splined | #1 South | 580 | SF | 7 | \$0 | |
| | Floor - Terrazzo | #1 South | 296 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | #1 South | 146 | SF | 7 | \$0 | |
| | Handrails | #1 South | 14 | LF | 7 | \$0 | |
| | Lighting - Lay-in | #1 South | 16 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #1 South | 284 | LF | 7 | \$0 | |
| | Walls - Masonry | #1 South | 2,431 | SF | 7 | \$0 | |
| | Ceiling - Exposed | #10 South East | 300 | SF | 6 | \$446 | |
| | Floor - Terrazzo | #10 South East | 300 | SF | 5 | \$11,291 | |
| | Handrails | #10 South East | 30 | LF | 6 | \$260 | |
| | Lighting - Lay-in | #10 South East | 3 | EA | 5 | \$487 | |
| | Stairs - Terrazzo | #10 South East | 35 | LF | 6 | \$325 | |
| | Walls - Masonry | #10 South East | 1,550 | SF | 6 | \$4,876 | |
| | Ceiling - Plaster/Drywall | #2 SE | 602 | SF | 7 | \$0 | |
| | Floor - Terrazzo | #2 SE | 219 | SF | 7 | \$0 | |
| | Floor - Terrazzo | #2 SE | 73 | SF | 5 | \$3,249 | |
| | Floor - Tile/Sheet | #2 SE | 38 | SF | 7 | \$0 | |
| | Handrails | #2 SE | 48 | LF | 7 | \$0 | |
| | Lighting - Lay-in | #2 SE | 9 | EA | 7 | \$0 | |



Category: Building Interior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|--------------------------|----------|------|------|---------|----------|
| Stairs | | | | | | | |
| | Stairs - Terrazzo | #2 SE | 297 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | #2 SE | 1,276 | SF | 6 | \$3,522 | |
| | Walls - Structural Glazed Tile | #2 SE | 1,276 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | #6 Basement to 2nd Floor | 420 | SF | 6 | \$3,075 | |
| | Floor - Terrazzo | #6 Basement to 2nd Floor | 420 | SF | 6 | \$3,526 | |
| | Handrails | #6 Basement to 2nd Floor | 80 | LF | 6 | \$693 | |
| | Lighting - Lay-in | #6 Basement to 2nd Floor | 4 | EA | 6 | \$476 | |
| | Lighting - Lay-in | #6 Basement to 2nd Floor | 1 | EA | 5 | \$162 | |
| | Stairs - Terrazzo | #6 Basement to 2nd Floor | 250 | LF | 6 | \$2,320 | |
| | Walls - Masonry | #6 Basement to 2nd Floor | 840 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | #6 Basement to 2nd Floor | 840 | SF | 7 | \$0 | |
| | Ceiling - Exposed | #7 Basement to 1st Floor | 300 | SF | 6 | \$446 | |
| | Floor - Terrazzo | #7 Basement to 1st Floor | 300 | SF | 6 | \$2,518 | |
| | Handrails | #7 Basement to 1st Floor | 30 | LF | 6 | \$260 | |
| | Lighting - Lay-in | #7 Basement to 1st Floor | 2 | EA | 4 | \$672 | |
| | Stairs - Terrazzo | #7 Basement to 1st Floor | 35 | LF | 6 | \$325 | |
| | Walls - Masonry | #7 Basement to 1st Floor | 1,550 | SF | 6 | \$4,876 | |
| | Ceiling - Splined | #8 Northwest | 200 | SF | 6 | \$578 | |
| | Floor - Terrazzo | #8 Northwest | 62 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | #8 Northwest | 35 | SF | 7 | \$0 | |
| | Handrails | #8 Northwest | 32 | LF | 6 | \$277 | |
| | Lighting - Lay-in | #8 Northwest | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #8 Northwest | 119 | LF | 7 | \$0 | |
| | Walls - Masonry | #8 Northwest | 690 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | #8 Northwest | 690 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | #9 Southwest | 706 | SF | 7 | \$0 | |
| | Floor - Terrazzo | #9 Southwest | 292 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | #9 Southwest | 180 | SF | 7 | \$0 | |
| | Handrails | #9 Southwest | 80 | LF | 7 | \$0 | |
| | Lighting - Lay-in | #9 Southwest | 11 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #9 Southwest | 297 | LF | 7 | \$0 | |
| | Stairs - Tile | #9 Southwest | 114 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | #9 Southwest | 1,819 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | #9 Southwest | 1,819 | SF | 7 | \$0 | |
| | | | | | | | |

Building Interior Subtotal:

\$326,741



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Total Building Cost

Building: Addition

| 0 | Itana Tuna | Lengtion | 0 | 11 | Daul | A t | 0 |
|---------|---|-------------------------------|----------|------|------|------------|----------|
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entran | | | | | _ | * - | |
| | Entrance Control - Audio and Video | 4 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 3 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 4 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 5 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Transom Lite | 3 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 4 | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 3 | 45 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 4 | 30 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 5 | 56 | LF | 7 | \$0 | |
| Found | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 663 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 48,594 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 3 | EA | 7 | \$0 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 6 | \$1,155 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 7 | \$0 | |
| Roof S | ystem | | | | | | |
| | Coping - Stone | А | 654 | LF | 5 | \$71,619 | |
| | Downspouts - Interior Downspouts | А | 228 | LF | 6 | \$7,577 | |
| | Parapet - 16" - 30" Height | А | 654 | LF | 6 | \$26,130 | |
| | Roof Structure - Concrete | А | 16,198 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | A | 16,198 | SF | 6 | \$152,413 | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building / East Façade | 360 | SF | 6 | \$11,912 | |
| | Exterior Walls - Brick | Entire Building | 15,107 | SF | 7 | \$0 | |
| | Exterior Walls - Brick | Entire Building | 77 | SF | 4 | \$12,678 | cracked |
| | Exterior Walls - Brick | Entire Building | 153 | SF | 6 | \$1,389 | |
| | Exterior Walls - Stone-Cast | Entire Building | 900 | SF | 6 | \$6,049 | |
| Windo | ws | | | | | | |
| | Guard - Guards perforated | Entire Building | 4,904 | SF | 7 | \$0 | |
| | Lintels - Steel | Entire Building | 981 | LF | 6 | \$28,477 | |
| | Windows - Decorative | Entire Building | 144 | SF | 6 | \$1,075 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Category: Building Exterior | | |
|-------------------------------------|-----------------|----------------------------------|
| Group Item - Type | Location | Quantity Unit Rank Cost Comments |
| Windows | | |
| Windows - Sash Aluminum Double-pane | Entire Building | 9,000 SF 6 \$67,181 |
| Building Exterior Subtotal: | | \$392,699 |

Building: Addition

Category: Electrical System

| - | | | | | | - | • |
|----------|--|-----------------------------------|----------|------|------|----------|----------|
| • | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Emerge | ency System | | | | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 8,090 | SF | 6 | \$2,429 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 757 | SF | 6 | \$281 | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 1 | EA | 6 | \$203 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 12 | EA | 6 | \$1,797 | |
| | Security System - CCTV | Entire Building | 48,594 | SF | 6 | \$14,593 | |
| | Security System - Intrusion Detection | Entire Building | 48,594 | SF | 6 | \$12,508 | |
| Main Se | ervice | | | | | | |
| | PA System | Entire Building | 48,594 | SF | 6 | \$15,983 | |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 6 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Entire Building | 5 | EA | 6 | \$1,496 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Mechanical Room | 3 | EA | 4 | \$19,733 | |
| Electr | ical System Subtotal: | | | | | \$69,023 | |
| Buildi | ng: Addition | | | | | | |
| Categ | ory: Safty System | | | | | | |
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Ala | ırm | | | | | | |
| | Fire Alarm_System | Entire Building | 48,594 | SF | 6 | \$23,626 | |
| Safty | System Subtotal: | | | | | \$23,626 | |
| | | | | | | | |
| Buildi | ng: Addition | | | | | | |
| Categ | ory: Mechanical System | | | | | | |
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| | •• | | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------|----------|------|------|-----------|---|
| Air Han | dling Systems | | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 21 - 30 tons | Roof | 1 | EA | 5 | \$25,152 | |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | \$2,051 | |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 2 | EA | 4 | \$48,643 | Units appear > 20 years of age. Beginning to corrode. |
| Boiler S | ystems | | | | | | |
| | Hot Water Pump | Entire Building | 1 | EA | 5 | \$4,704 | |
| | Hot Water Pump | Entire Building | 1 | EA | 4 | \$12,358 | Motor removed. In process of repair, but currentl inoperable. |
| | Piping - Condensate Pipe- Steel | 1st Floor | 200 | LF | 4 | \$36,239 | |
| | Piping - Steam Pipe- Steel | 1st Floor | 200 | LF | 5 | \$2,817 | |
| | Steam Traps | 1st Floor | 40 | EA | 5 | \$52,596 | |
| | Vacuum Pump | 1st Floor | 1 | EA | 7 | \$0 | |
| | Water Fill System | Entire Building | 1 | EA | 5 | \$5,828 | |
| Heat Ex | changers | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | 1st Floor / Mechanical Room | 1 | EA | 6 | \$0 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 24 | EA | 5 | \$42,115 | |
| | Fin Tube - Hot Water | Entire Building | 1,078 | LF | 6 | \$10,174 | |
| | Wall Heater - Electric | Entire Building | 1 | EA | 5 | \$537 | |
| Mechan | ical Plumbing | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 700 | LF | 6 | \$53,744 | |
| Temper | ature Control | | | | | | |
| | Electric Thermostat | Entire Building / 3rd Floor | 1 | EA | 7 | \$0 | |
| | Pneumatic System | Entire Building | 48,594 | SF | 5 | \$167,470 | |
| | Thermostats | Entire Building | 37 | EA | 6 | \$0 | |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 1 | EA | 6 | \$592 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 1 | EA | 4 | \$4,245 | > 20 years of age. Poor condition. |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 2 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof | 1 | EA | 4 | \$1,942 | > 20 years of age. Poor condition. |
| Mecha | inical System Subtotal: | | | | | \$472,391 | |



Building: Addition

Category: Plumbing System

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--|-----------------|----------|------|-----------|----------|----------|
| ping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 48,594 | SF | 6 | \$9,729 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 48,594 | SF | 6 | \$11,813 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 48,594 | SF | 6 | \$9,034 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 48,594 | SF | 6 | \$7,644 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 48,594 | SF | 6 | \$9,034 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 48,594 | SF | 6 | \$6,949 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 48,594 | SF | 6 | \$6,949 | |
| | Sanitary Piping | Entire Building | 48,594 | SF | 6 | \$44,473 | |
| | Storm Piping | Entire Building | 48,594 | SF | 6 | \$42,389 | |
| | Vent Piping | Entire Building | 48,594 | SF | 6 | \$32,660 | |
| umps | | | | | | | |
| | Pumps - Ejector-Simplex | Basement | 1 | EA | 6 | \$745 | |
| lumbi | ing System Subtotal: | | | | \$181,418 | | |

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------|----------|------|------|---------|-----------------------------|
| Classro | om #10 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 28 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 1,025 | SF | 6 | \$3,547 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Tile | | 1,025 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 25 | EA | 7 | \$0 | |
| | Storage/ Closet | | 55 | SF | 7 | \$0 | |
| | Walls - Concrete Block | | 286 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 560 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 280 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 7 | \$0 | |
| Classro | om #108 (Computer Lab) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 30 | LF | 6 | \$758 | damaged hardware and finish |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 775 | SF | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Category: Classrooms | tegory: Classroo | oms |
|----------------------|------------------|-----|
|----------------------|------------------|-----|

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------|----------|------|------|--------------------|---------------------------|
| - | bom #108 (Computer Lab) | | | | | 0001 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 8 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 6 | | damaged finish |
| Classra | oom #109 (Computer Lab) | | | | | | 0 |
| Classic | AC Units | | 2 | EA | 6 | \$991 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 6 | \$991 \$2,682 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$2,002 \$1,174 | |
| | Floor - Tile | | 775 | SF | 7 | \$1,174 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 \$0 | |
| | Marker Board | | 8 | LF | 7 | \$0 \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 6 | \$1,311 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$1,311 \$0 | |
| | Wireless System | | 473 | EA | 6 | \$372 | |
| | | | | LA | 0 | ψ012 | |
| Classro | oom #11 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 6 | \$2,682 | |
| | Chalk Board | | 28 | LF | 4 | \$2,571 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 775 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #110 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Chalk Board | | 40 | LF | 4 | \$3,672 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 4 | \$3,413 | damaged veneer and finish |
| | Floor - Tile | | 775 | SF | 5 | \$3,480 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 6 | \$1,311 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Classroom Hill (Regular Classroom) F 6 S2.942 AC Units 55 6 \$2.942 | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---------|--------------------------------|----------|----------|------|------|---------|---------------------------|
| AC Units 4C Units 50 50 50 Calling Phaskr/Dynall 60 57 6 52.342 Datas Board 40 LF 4 53.672 disoblet material Datas Phaskr/Dynall 860 SF 7 S0 Upting - Prodent/Burline 20 LF 7 S0 Mainer Board 20 LF 7 S0 Mainer Board 20 LF 7 S0 Walls - Flaster/Dynall C00 SF 7 S0 Classoon #112 (Regular Classroom) T EA 7 S0 Class Board 10 LF 4 S3.672 obsolete material Doos - Vood Doors indu hw 1 EA 7 S0 S0 Doos - Vood Doors indu hw 1 EA 7 S0 S0 Doos - Vood Doors indu hw 1 EA 7 S0 S0 Upting - Phaskr/Dynall Calling - Phaskr/Dynall Calling - Phaskr/Dynal <td< th=""><th></th><th></th><th></th><th></th><th></th><th></th><th></th><th></th></td<> | | | | | | | | |
| Chaik SoardChaik SoardF4\$3.87.13damaged veneer and linishBoars - Wood Doors inclu hw88SF7\$00Hour - Tile80SF7\$00Ughting - Penden/Surface20LF7\$00Marker Board20LF7\$00Walls - Plaster/Dynall500SF7\$00Walls - Snuchtrid Glazes Tile500SF7\$00Closson H12 (Regular Classon)577\$00\$000000000000000000000000000000000000 | | | | 1 | EA | 7 | \$0 | |
| DoorsWood Doors inclu hw1FA4\$3,41damaged veneer and finishFloar - Tile858F730Ughting - Pendert/Surface20LF730Walls - Plastor/Dynall200SF730Walls - Structural Glazed Tile200SF730Charles Constructural Glazed Tile50SF730Charles Constructural Glazed Tile775SF730Colling - Plaster/Dynall775SF6\$1,61Doors - Wood Doors inclu hw1LF4\$3,022dooleter materialDoors - Wood Doors inclu hw1SF7\$0\$1Ling - Plaster/Dynall775SF6\$1,61Doors - Wood Doors inclu hw1SF7\$0\$1Harter Board75SF6\$1,61\$1Ughting - Pendert/Surface75SF7\$0\$1Ughting - Pendert/Surface75SF7\$0\$1Calles - Tile7SF7\$0\$1\$1\$1AC Units7SF7\$0\$1\$1\$1\$1\$1Colling - Plaster/Dynall75SF7\$0\$1 </td <td></td> <td>Ceiling - Plaster/Drywall</td> <td></td> <td>850</td> <td>SF</td> <td>6</td> <td>\$2,942</td> <td></td> | | Ceiling - Plaster/Drywall | | 850 | SF | 6 | \$2,942 | |
| Floor - Tile850SF790Lighting - Pendent/Surface21EX790Walle - Plaster/Dynall500SF790Class-concettal Classed Tile500SF790Classe - Plaster/Dynall75SF790Chile Board75SF790Chile Board75SF790Chile Board75SF790Concettal Classed Tile75SF790Concettal Classed Tile77SF790Doors - Wood Doors incle We77SF790Doors - Wood Doors incle We77SF790Valle - Plaster/Dynall21EX790Walle - Structural Classed Tile77SF790Walle - Structural Classed Tile77SF790Walle - Structural Classed Tile77SF790Walle - Structural Classed Tile77SF790Concet H19 (Classed Tile28SF790Doors - Wood Doors incle We76SF790Doors - Wood Doors incle We75SF790Walle - Structural Classed Tile7909090 <td></td> <td>Chalk Board</td> <td></td> <td>40</td> <td>LF</td> <td>4</td> <td>\$3,672</td> <td>obsolete material</td> | | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| Lighting - Pendern/Surface2124780Marker Board205F780Walls - Structural Glazed Tile5005F780Classer Jetter ClaycolCalling - Plaster/Dynall775F780Calling - Plaster/Dynall775F780Chark Board775F780Chark Board775F681,000Doors - Wood Doors inclu hw775F681,000Doors - Wood Doors Inclu hw775F681,000Lighting - Pendern/Surface775F7800Marker Board201F7800Marker Board281F7800Calling - Plaster/Dynall2657800Calling - Plaster/Dynall2657800Marker Board8 | | Doors - Wood Doors inclu hw | | 1 | EA | 4 | \$3,413 | damaged veneer and finish |
| Marker Board20LF7\$0Walls - Plaster/Dywall500577\$00Clastroom H12 (Regular Classroom)1EA7\$0Childs1EA7\$0\$10Childs Card Tile1EA7\$00Childs Doors Inclu Iw1EA4\$3.672obsolve materialDoors - Wood Doors Inclu Iw1EA4\$3.672obsolve materialBiological Plaster/Dywall1EA4\$3.672obsolve materialDoors - Wood Doors Inclu Iw1EA4\$3.672obsolve materialBiological Plaster/Dywall2EA6\$1.924\$1.924Marker Board21EA7\$00\$1.924Walls - Plaster/Dywall27\$0\$1.924\$1.924Walls - Plaster/Dywall28F7\$0.92Colling - Plaster/Dywall76\$57\$0Colling - Plaster/Dywall76\$57\$0Colling - Plaster/Dywall76\$7\$0\$1.924Colling - Plaster/Dywall7\$2\$0\$1.924Colling - Plaster/Dywall7\$5\$1.924\$1.924Colling - Plaster/Dywall7\$5\$1.924\$1.924Colling - Plaster/Dywall7\$0\$1.924\$1.924Colling - Plaster/Dywall7\$2\$2.924\$1.924Colling - Plaster/Dywall\$2\$7\$0\$1.924 | | Floor - Tile | | 850 | SF | 7 | \$0 | |
| Walls - Plaster/Dynall 500 SF 7 500 Walls - Structural Glazed Tile Structural Glazed Tile Structural Glazed Tile Structural Glazed Tile Ac Units 1 EA 7 \$50 7 \$50 Celling - Plaster/Drynall 775 SF 7 \$50 7 \$50 Chark Board 775 SF 7 \$50 | | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile S0 S7 7 \$00 Caling - Plaster/Dryvall AC Units 1 EA 7 55 7 500 Chile Board 40 LF 4 \$\$3.672 obsoleter material Dors · Wood Dors inclu hw 1 EA 4 \$\$3.672 obsoleter material Dors · Wood Dors inclu hw 1 EA 4 \$\$3.672 obsoleter material Dors · Wood Dors inclu hw 1 EA 4 \$\$3.672 obsoleter material Dors · Wood Dors inclu hw 1 EA 4 \$\$3.672 obsoleter material Marker Board 20 LF 7 \$00 omaged vencer & finish Walls - Plaster/Dryvall 27 S 7 \$00 Walls - Structural Glazed Tile 7 \$00 omaged vencer & finish Caling - Plaster/Dryvall 27 S 7 \$00 Caling - Plaster/Dryvall 7 S 7 \$00 Dors - Vood Dors inclu hw 1 EA 7 \$00 Lighting - | | Marker Board | | 20 | LF | 7 | \$0 | |
| Classroom #112 (Regular Classroom) 1 EA 7 So Ceiling - Plaster/Drywall 77 SF 7 So Chalk Board 40 475 SF 7 Soo Chalk Board 40 4 S3.672 obsolete material Doors - Wood Doors inclu hw 1 EA 4 S3.672 obsolete material Doors - Wood Doors inclu hw 1 EA 4 S3.672 obsolete material Doors - Wood Doors inclu hw 1 EA 4 S3.672 obsolete material Marker Board 21 EA 7 So Marker Board 7 So Walls - Structural Glazed Tile 475 SF 7 So Caling - Plaster/Drywall 75 SF 7 So Caling - Plaster/Drywall 767 SF 7 So Colinis 2 EA 7 So | | Walls - Plaster/Drywall | | 500 | SF | 7 | \$0 | |
| AC Units 1 EA 7 \$0 Caling - Plaster/Drywall 75 SF 7 \$0 Chaik Board 40 LF 4 \$3,672 obsolete material Doors - Wood Doors inclu hw 1 EA 4 \$3,413 damaged veneer & finish Floor - Tile 75 SF 6 \$1,696 Lighting - Pendent/Surface 21 EA 7 \$0 Walls - Plaster/Drywall 20 LF 7 \$0 Walls - Bructural Gazed Tile 27 SF 7 \$0 Classroom #113 (Office) 475 SF 7 \$0 Classroom #13 (Office) 7 SF 7 \$0 Coling - Plaster/Drywall 76 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Coling - Plaster/Drywall 76 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Hoor - Ti | | Walls - Structural Glazed Tile | | 500 | SF | 7 | \$0 | |
| Ceiling - Plaster/Dyvail778F780Chaik Board4453.672danaged veneer & finishDoors Wood Doors inclu hw7758F6\$1.694Floor - Tile7758F7\$0Marker Board20LF7\$0Walls - Plaster/Dyvall4758F7\$0Walls - Structural Glazed Tile4758F7\$0Constructural Glazed TileColspan="3">Constructural Glazed TileColspan="3">Colspan="3"Colspan="3">Colspan="3">Colspan="3">Colspan="3">Colspan="3"Colspan="3">Colspan="3"Colspan="3">Colspan="3">Colspan="3">Colspan="3"Colspan="3">Colspan="3"AC UnitsColspan="3"Colspan="3"Colspan="3"Colspan="3"Colspan="3"Colspan="3"Colspan="3"AC UnitsColspan="3"AC UnitsColspan="3"AC UnitsColspan="3"AC UnitsColspan="3"AC UnitsColspan= 3AC Units <td>Classre</td> <td>oom #112 (Regular Classroom)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | Classre | oom #112 (Regular Classroom) | | | | | | |
| Chail Board 40 LF 4 \$3,872 obsolete material Doors - Wood Doors inclu hw 1 EA 4 \$3,872 desceed at finish Lighting - Pendent/Surface 27 5 6 \$1,693 Marker Board 20 LF 7 50 Walls - Plaster/Dryvall 475 SF 7 50 Walls - Structural Glazed Tile 475 SF 7 50 Clastroom #13 (Office) 28 SF 7 50 Ceiling - Plaster/Dryvall 767 SF 7 50 Coors - Wood Doors inclu hw 767 SF 7 50 Ceiling - Plaster/Dryvall 767 SF 7 50 Doors - Wood Doors inclu hw 767 SF 7 50 Colory - Tile 28 7 50 5 7 50 Doors - Nood Doors inclu hw 767 SF 7 50 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | | AC Units | | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hw 1 EA 4 \$\$3,413 admaged veneer & finish Floor - Tile 775 SF 6 \$1,696 Lighting - Pendent/Surface 20 LF 7 \$0 Marker Board 475 SF 7 \$00 Walls - Plaster/Dryvall 475 SF 7 \$00 Walls - Structural Glazed Tile 475 SF 7 \$00 Cassroom#110 Office 2 EA 6 \$991 Ceiling - Plaster/Dryvall 775 SF 7 \$00 Doors - Wood Doors inclu hw 1 EA 6 \$991 Ceiling - Plaster/Dryvall 775 SF 7 \$00 Doors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile Structural Glazed Tile 3 ST 7 \$0 Gaing - Plaster/Dryvall 8 F 7 \$00 \$00 \$00 \$00 \$00 \$00 \$00 \$00 <td< td=""><td></td><td>Ceiling - Plaster/Drywall</td><td></td><td>775</td><td>SF</td><td>7</td><td>\$0</td><td></td></td<> | | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| Floor - Tile 775 SF 6 \$1,696 Lighting - Pendent/Surface 20 LF 7 \$00 Marker Board 20 LF 7 \$00 Walls - Plaster/Dywall 475 SF 7 \$00 Walls - Structural Glazed Tile 475 SF 7 \$00 Classroom #113 (Office) K Clunix 2 EA 6 \$991 Ceiling - Plaster/Dywall 76 SF 7 \$00 Doors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile 7 \$00 \$100 <td></td> <td>Chalk Board</td> <td></td> <td>40</td> <td>LF</td> <td>4</td> <td>\$3,672</td> <td>obsolete material</td> | | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Walls - Plaster/Drywall 475 SF 7 \$0 Walls - Structural Glazed Tile 475 SF 7 \$0 Classroom#113 (Office) Classroom#113 (Office) A C Units 2 EA 6 \$991 Ceiling - Plaster/Drywall 76 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 6 \$991 \$1 \$1 \$1 \$2 7 \$0 Malls - Blaster/Drywall 76 SF 7 \$0 \$0 \$1 \$1 \$4 7 \$0 Malls - Blaster/Drywall 7 S4 7 \$0 \$0 \$1 | | Doors - Wood Doors inclu hw | | 1 | EA | 4 | \$3,413 | damaged veneer & finish |
| Marker Board 20 LF 7 \$0 Walls - Plaster/Drywall 475 SF 7 \$0 Valls - Structural Glazed Tile 475 SF 7 \$0 Classer/Drywall 475 SF 7 \$0 Classer/Drywall 6 \$991 AC Units 2 EA 6 \$991 Doors - Wood Doors inclu hw 1 EA 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 7 \$0 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Plaster/Drywall 470 SF 7 \$0 Clastroettite 470 SF 7 \$0 Clastroettite 470 SF 7 \$0 <t< td=""><td></td><td>Floor - Tile</td><td></td><td>775</td><td>SF</td><td>6</td><td>\$1,696</td><td></td></t<> | | Floor - Tile | | 775 | SF | 6 | \$1,696 | |
| Walls - Plaster/Dryvall 475 5F 7 \$00 Walls - Structural Glazed Tile 475 5F 7 \$00 Classroom #113 (Office) AC Units 2 EA 6 \$991 Ceiling - Plaster/Dryvall 767 SF 7 \$00 Floor - Tile 767 SF 7 \$00 Floor Tile 7 SS 7 \$00 Strage/Closet 8 SF 6 \$58 Walls - Structural Glazed Tile 470 SF 7 \$00 Classroom#14 (Regular Classroom) 48 SF 6 \$58 Ceiling - Plaster/Dryvall SS SF 7 \$00 Coors - Wood Doors inclu hw 1 | | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile475SF7\$0Classroom #113 (Office)AC Units2EA6\$991Ceiling - Plaster/Drywall767SF7\$0Doors - Wood Doors inclu hw1EA7\$0Floor - Tile767SF7\$0Lighting - Pendent/Surface28SF6\$58Storage/ Closet8SF6\$58Walls - Plaster/Drywall470SF7\$0Utable - Plaster/Drywall470SF7\$0Valls - Structural Glazed Tile470SF7\$0Clastroom1EA7\$0AC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA7\$0Hat Regular Classroom1EA7\$0Coiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA7\$0Doors - Wood Doors inclu hw1EA7\$0Coiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA7\$0Lighting - Pendent/Surface850SF7\$0Marker Board40LF7\$0 | | Marker Board | | 20 | LF | 7 | \$0 | |
| Classroom #13 (Office) 2 EA 6 \$991 AC Units 2 FA 6 \$991 Ceiling - Plaster/Drywall 767 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 767 SF 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 6 \$58 Walls - Plaster/Drywall 470 SF 7 \$0 Valls - Structural Glazed Tile 470 SF 7 \$0 Classroom AC Units 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Doors - Tile 850 SF 7 \$0 Lighting - Pendent/Surface 850 SF | | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| AC Units 2 EA 6 \$991 Ceiling - Plaster/Drywall 767 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 767 SF 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 6 \$58 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Structural Glazed Tile 470 SF 7 \$0 Classroom #114 (Regular Classroom) 470 SF 7 \$0 Ceiling - Plaster/Drywall 470 SF 7 \$0 AC Units 1 EA 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 5 \$1,174 Floor - Tile 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 < | | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall 767 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 767 SF 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 6 \$58 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Structural Glazed Tile 470 SF 7 \$0 Classroom #114 (Regular Classroom) 470 SF 7 \$0 AC Units 1 EA 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 850 SF 7 \$0 Diors - Wood Doors inclu hw 1 EA 7 \$0 Lighting - Pendent/Surface 24 EA 7 | Classre | oom #113 (Office) | | | | | | |
| Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 767 SF 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 6 \$58 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Structural Glazed Tile 470 SF 7 \$0 Classroom) Ceiling - Plaster/Drywall 5F 7 \$0 Colinig - Plaster/Drywall 5F 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Doors - Wood Doors inclu hw 1 EA 5 \$1,174 Floor - Tile 850 SF 7 \$0 Lighting - Pendent/Surface 24 EA 7 \$0 Marker Board 40 LF 7 \$0 | | AC Units | | 2 | EA | 6 | \$991 | |
| Floor - Tile 767 SF 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Storage/ Closet 8 SF 6 \$58 Walls - Plaster/Drywall 470 SF 7 \$0 Walls - Structural Glazed Tile 470 SF 7 \$0 Classroom/ AC Units 1 EA 7 \$0 Ceiling - Plaster/Drywall 850 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 850 SF 7 \$0 Lighting - Pendent/Surface 1 EA 7 \$0 Marker Board 40 LF 7 \$0 | | Ceiling - Plaster/Drywall | | 767 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface21EA7\$0Storage/ Closet8SF6\$58Walls - Plaster/Drywall470SF7\$0Walls - Structural Glazed Tile470SF7\$0Classroom#114 (Regular Classroom)AC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| Storage/ Closet8SF6\$58Walls - Plaster/Drywall470SF7\$0Walls - Structural Glazed Tile470SF7\$0Classroom// Legular Classroom/AC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Floor - Tile | | 767 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall470SF7\$0Walls - Structural Glazed Tile470SF7\$0ClassroomAC UnitsIEA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile470SF7\$0ClassroomAC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Storage/ Closet | | 8 | SF | 6 | \$58 | |
| Classroom #114 (Regular Classroom)AC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Walls - Plaster/Drywall | | 470 | SF | 7 | \$0 | |
| AC Units1EA7\$0Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Walls - Structural Glazed Tile | | 470 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall850SF7\$0Doors - Wood Doors inclu hw1EA5\$1,174Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | Classro | oom #114 (Regular Classroom) | | | | | | |
| Doors - Wood Doors inclu hw 1 EA 5 \$1,174 Floor - Tile 850 SF 7 \$0 Lighting - Pendent/Surface 24 EA 7 \$0 Marker Board 40 LF 7 \$0 | | AC Units | | 1 | EA | 7 | \$0 | |
| Floor - Tile850SF7\$0Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Ceiling - Plaster/Drywall | | 850 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface24EA7\$0Marker Board40LF7\$0 | | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Marker Board40LF7\$0 | | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | | | | 24 | | 7 | | |
| Walls - Plaster/Drywall500SF7\$0 | | Marker Board | | 40 | LF | 7 | \$0 | |
| | | Walls - Plaster/Drywall | | 500 | SF | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Catego | ory: Classrooms | | | | | | |
|---------|--------------------------------|----------|----------|------|------|---------|-------------------------|
| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | om #114 (Regular Classroom) | | | | | | |
| | Walls - Structural Glazed Tile | | 500 | SF | 7 | \$0 | |
| Classro | om #115 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 6 | \$2,682 | minor peeling paint |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 4 | \$3,413 | damaged veneer & finish |
| | Floor - Tile | | 775 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 425 | SF | 6 | \$1,173 | tape/adhesive residue |
| | Walls - Structural Glazed Tile | | 425 | SF | 7 | \$0 | |
| Classro | om #116 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 6 | \$2,682 | |
| | Chalk Board | | 40 | LF | 6 | \$892 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 775 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | om #117 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Chalk Board | | 44 | LF | 4 | \$4,039 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 50 | SF | 5 | \$288 | cracks throughout |
| | Floor - Tile | | 800 | SF | 6 | \$1,750 | - |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 6 | \$1,311 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | om #118 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Classroom #16 (Regular Classroom) U I <thi< th=""> <thi< th=""> I <t< th=""><th></th><th>Item - Type</th><th>Location</th><th>Quantity</th><th>Unit</th><th>Rank</th><th>Cost</th><th>Comments</th></t<></thi<></thi<> | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---------|--------------------------------|----------|----------|------|------|---------|---------------------------|
| boos - Wood Doors indu hw 1 EA 5 \$1.174 Floor - Tile 75 87 30 Lighting - Pendent/Surface 21 EA 7 30 Wate - Roard 20 LF 7 30 Wate - Structural Glazed Tile 20 LF 7 30 Character Structural Glazed Tile 20 LF 7 30 Character Structural Glazed Tile 20 LF 7 30 Character Structural Glazed Tile 20 LF 7 30 Coling - Ploster/Dynall 200 S 7 30 Coling - Ploster/Dynall 200 S 7 30 Colans - Nood Doors inclu hw 1 EA 6 3200 Lighting - Pendent/Surface 20 E 6 \$310 Glasser Structural Glazed Tile S 6 \$310 Character Dynall 200 S 6 \$1.80 Wate - Structural Glazed Tile S | | | | | | | | |
| Floor - Time7757750Lighting - Pendent/Surface20LF750Markar Board20LF750Walls - Pleater/Dynall475576\$1.11Walls - Structural Glazad Titie475576\$1.11Chills47557730AC Units5873\$6.06not functioningCasseror18ater/Dynall5873\$6.06Chills Roard40LF4\$5.372obsidee materialConsor Incl. Inc.186\$1.81\$1.81\$1.81\$1.81Doors - Nood Doors incl. Inc.186\$1.81\$1.81\$1.81\$1.81Marker Board20LF7\$0.91\$1.81\$1.81\$1.81\$1.81\$1.81Marker Board20LF7\$0.91\$1.81 <td></td> <td>Chalk Board</td> <td></td> <td>20</td> <td>LF</td> <td>4</td> <td>\$1,836</td> <td>obsolete material</td> | | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| Lighting - Penders@urlade21EA7S0Marker Board475SF6\$1.311Walls - Pister/Dywall475SF6\$1.311Celling - Pinater/Dywall475SF7\$00Celling - Pinater/Dywall860SF7\$00Chilk Reard480SF7\$00Doors - Wood Doors inclu hw1EA8\$100Lighting - Pendert/Dywall680SF6\$13.80Lighting - Pendert/Burlade680SF6\$13.80Lighting - Pendert/Burlade20LF7\$00Marker Board20LF7\$00Walls - Structural Glazed Tile20LF7\$00Walls - Structural Glazed Tile20LF7\$00Calling - Spinad592SF7\$00Doors - Wood Doors inclu hw1EA7\$00Calling - Spinad592SF7\$00Doors - Wood Doors inclu hw1EA7\$00Lighting - Pindert/Burda15EA7\$00Doors - Wood Doors inclu hw15EA7\$00Lighting - Pinater/Burd16SF7\$00Marker Board100SF7\$00Marker Board100SF7\$00Marker Board100SF7\$00Marker Board100SF7\$00Marker Board <t< td=""><td></td><td>Doors - Wood Doors inclu hw</td><td></td><td>1</td><td>EA</td><td>5</td><td>\$1,174</td><td></td></t<> | | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Marker Dard20LF7800Walls - Paster/Dynall475876813.1AC Units1878080AC Units1878080Caling - Paster/Dynall188780Child Beard1888780Control - Paster/Dynall188888Doors - Vood Doors inch tw18685.0130Doors - Vood Doors inch tw18685.0230Harker Doard2018685.0230Marker Doard2018685.0230Marker Doard201878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Structure/ Cleard The1878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall2001878030Walls - Pitter/Dynall< | | Floor - Tile | | 775 | SF | 7 | \$0 | |
| Walls - Plaster/Dynall 475 8° 6 \$13.31 Walls - Plaster/Dynall 40 8° 7 \$000000000000000000000000000000000000 | | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile4755750ClassroomAC UnitsAC UnitsNo functioningCelling - Plastar/Dyvall65575.086Chilk Board40LF4\$3.672Corso Vood Doors inclu Iw40LF4\$5.202Floor - Tile650SF6\$1.86Floor - Tile600SF6\$1.86Marker Board201LF7\$00Walls - Plaster/Dyvall500SF6\$1.381Walls - Plaster/Dyvall500SF6\$1.381Walls - Plaster/Dyvall500SF6\$1.381Walls - Plaster/Dyvall500SF7\$00Classroom H2 (Regular Classroom)577\$00Casework15LF7\$00Casework59SF7\$00Corso - Wood Doors inclu Iw59SF7\$00Foor - Tile592SF7\$00Doors - Wood Doors inclu Iw59SF7\$00Hort - Tile592SF7\$00Marker Board100SF7\$00Marker Board100SF7\$00Marker Board100SF7\$00Walls - Structural Glazed Tile50SF7\$00Walls - Structural Glazed Tile50SF7\$00Walls - Structural Glazed Tile16SF7< | | Marker Board | | 20 | LF | 7 | \$0 | |
| Classroom #19 (Regular Classroom) I EA S S S AC Units 1 EA 3 \$6,086 In functioning Caling - Plaster/Dnyvall 60 LF 4 S3.672 obsolete material Chark Board 1 EA 6 S3.01 damaged veneer and finish Floor - Tile EA 6 S3.02 damaged veneer and finish Floor - Tile EA 6 S3.040 damaged veneer and finish Marker Board 20 LF 7 S0 Valls - Structural Glazed Tile 5 5 5 S Caserorm #12A (Regular Classroom) 1 EA 5 S1,320 Caserorm #12A (Regular Classroom) 1 EA 5 S1 S1 Caserorm #12A (Regular Classroom) 1 EA 7 S0 Caserorm #12A (Regular Classroom) 1 EA 7 S0 Cors - Wood Doors inclu hw 1 EA 7 S0 Doors - Wo | | Walls - Plaster/Drywall | | 475 | SF | 6 | \$1,311 | |
| AC Units 1 EA 3 \$\$0.08 not functioning Caling -Plaster/Dywall 80 SF 7 \$0.0 Chaik Board 40 LF 7 \$0.00 Doors -Wood Doors inclu hw 1 EA 6 \$3.07 dootsdete material Floor - Tile 800 SF 6 \$3.00 damaged veneer and finish Floor - Tile 800 SF 6 \$3.00 dootsdete material Walls - Plaster/Dywall 20 LF 7 \$0.0 second Walls - Structural Glazed Tile 500 SF 7 \$0.0 second Caling - Splined 502 SF 4 \$1.00 second Doors - Wood Doors inclu hw 1 EA 7 \$0.0 Floor - Tile Second 15 EA 7 \$0.0 Doors - Wood Doors inclu hw 1 EA 7 \$0.0 Floor - Tile Second 15 EA 7 \$0.0 Using for and 15 EA 7 \$0.0 Second | | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| AC Units 1 EA 3 \$\$0.08 not functioning Caling -Plaster/Dywall 80 SF 7 \$0.0 Chaik Board 40 LF 7 \$0.00 Doors -Wood Doors inclu hw 1 EA 6 \$3.07 dootsdete material Floor - Tile 800 SF 6 \$3.00 damaged veneer and finish Floor - Tile 800 SF 6 \$3.00 dootsdete material Walls - Plaster/Dywall 20 LF 7 \$0.0 second Walls - Structural Glazed Tile 500 SF 7 \$0.0 second Caling - Splined 502 SF 4 \$1.00 second Doors - Wood Doors inclu hw 1 EA 7 \$0.0 Floor - Tile Second 15 EA 7 \$0.0 Doors - Wood Doors inclu hw 1 EA 7 \$0.0 Floor - Tile Second 15 EA 7 \$0.0 Using for and 15 EA 7 \$0.0 Second | Classro | oom #119 (Regular Classroom) | | | | | | |
| Chaik Board40LF4\$38.72obsolete materialDoors - Wood Doors inclu hw1EA6\$33.01damaged veneer and finishFloor - Tile850\$576\$2.002Ughting - Pendem/Surface20LF7\$0Walls - Plaster/Dryvall500\$576\$1.880Walls - Plaster/Dryvall500\$577\$0Walls - Structural Glazed Tile500\$577\$0Casework500\$577\$0Casework15LF7\$00\$0Clighting - Pendem/Surface15LF7\$00Lighting - Pendem/Surface52\$577\$0Lighting - Pendem/Surface15LF7\$00Lighting - Pendem/Surface16SF7\$00Storage/ Closet68SF7\$00Walls - Plaster/Dryvall640SF7\$00Ughting - Pendem/Surface16SF7\$00Walls - Storage/ Closet68SF7\$00Walls - Storage/ Closet68SF7\$00Casework16LF7\$00Casework16 | | | | 1 | EA | 3 | \$6,086 | not functioning |
| Doors - Wood Doors inclu hw 1 EA 6 \$301 damaged veneer and finish Floor - Tile 650 57 6 \$1,260 Lighting - PendentSurface 21 EA 6 \$2,602 Marker Board 200 LF 7 \$50 Walls - Plaster/Drywall 500 SF 6 \$1,300 Walls - Structural Glazed Tile 500 SF 6 \$1,300 Walls - Structural Glazed Tile 500 SF 6 \$51,000 Casswork 510 LF 7 \$00 Ceiling - Splined 528 7 \$0 \$000000000000000000000000000000000000 | | Ceiling - Plaster/Drywall | | 850 | SF | 7 | \$0 | |
| Floor - Tile 650 SF 6 \$1,860 Lighting - Pendent/Surface 21 EA 6 \$2,602 Marker Board 20 EF 7 50 Walls - Plaster/Drywall 500 SF 6 \$1,380 Walls - Plaster/Drywall 500 SF 7 \$0 Classroom #12A (Regular Classroom) Lighting - Pendent/Surface Casework 15 LF 7 \$0 Casework 15 LF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 52 SF 7 \$0 Gling - Splined 52 SF 7 \$0 Marker Board 16 LF 7 \$0 Storage/ Closet 68 SF 7 \$0 Walls - Plaster/Drywall 60 SF 7 \$0 Walls - Structural Glazed Tile 1 EA 7 \$0 | | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| Lighting - Pendent/Surface 21 FA 6 \$2,602 Marker Board 20 F 7 \$00 Walls - Plaster/Dywall 500 \$F 6 \$1,380 Walls - Structural Glazed Tile 500 \$F 7 \$00 Classroom/ Casework 51 \$F 7 \$00 Ceiling - Splined 52 \$F 4 \$6,100 obsolete material Coors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile 52 \$F 7 \$00 Marker Board 52 \$F 7 \$00 Marker Board 52 \$F 7 \$00 Lighting - Pendent/Surface 52 \$F 7 \$00 Storage/ Closet 68 \$F 7 \$00 Walls - Structural Glazed Tile 64 \$F 7 \$0 Walls - Structural Glazed Tile 64 \$F 7 \$0 Casework 64 \$F 7 \$0 \$0 < | | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| Marker Board10LF7\$0Walls - Plaster/Drywall500SF6\$13,30Walls - Structural Glazed Tile500SF6\$13,30CaseworkCasework592SF7\$0Ceiling - Splined592SF7\$0Doors - Wood Doors inclu hw1EA7\$0Floor - Tile154F7\$0Lighting - Pendent/Surface592SF7\$0Marker Board640SF7\$0Valls - Plaster/Drywall640SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile16LF7\$0Casework160SF7\$0\$1Casework540SF7\$0\$1Casework640SF7\$0\$1Casework160SF7\$0\$1Casework160SF7\$0\$1Coing - Splined540SF6\$51,30\$1Doors - Wood Doors inclu hw1EA7\$0\$1Lighting - Pendent/Surface54SF6\$1,302\$1Lighting - Pendent/Surface54SF6\$1,302\$1Lighting - Pendent/Surface54SF6\$1,302\$1Lighting - Pendent/Surface54SF6\$1,302\$1 <td< td=""><td></td><td>Floor - Tile</td><td></td><td>850</td><td>SF</td><td>6</td><td>\$1,860</td><td></td></td<> | | Floor - Tile | | 850 | SF | 6 | \$1,860 | |
| Walls - Plaster/Drywall 500 SF 6 \$1,380 Walls - Structural Glazed Tile 500 SF 7 \$00 Classroom) Casework 15 LF 7 \$00 Ceiling - Spined 51 4 \$6,180 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile 592 SF 7 \$00 Gasework 15 LF 7 \$00 Floor - Tile 592 SF 7 \$00 Marker Board 15 LF 7 \$00 Marker Board 64 SF 7 \$00 Marker Board 64 SF 7 \$00 Marker Board 64 SF 7 \$00 Walls - Structural Glazed Tile 64 SF 7 \$00 Marker Board 64 SF 7 \$0 \$00 Castorage/ Closet 1 EA | | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | |
| Walls - Structural Glazed Tile 50 SF 7 \$0 Classroom #12A (Regular Classroom) 5 LF 7 \$0 Casework 15 LF 7 \$0 Ceiling - Splined 592 SF 4 \$61,80 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$0 \$6 Floor - Tile 592 SF 7 \$0 \$6 Marker Board 20 LF 7 \$0 \$6 Storage/ Closet 640 SF 7 \$0 \$6 Walls - Structural Glazed Tile 640 SF 7 \$0 \$6 Marker Board 54 SF 7 \$0 \$6 Storage/ Closet 640 SF 7 \$0 \$6 Valls - Structural Glazed Tile 640 SF 7 \$0 \$6 Classroom #12E 5 7 \$0 \$6 \$6 \$7 \$0 Cassework 1 EA 7 \$0 \$6 \$6 \$6 | | Marker Board | | 20 | LF | 7 | \$0 | |
| Classroom #124 (Regular Classroom) Casework 15 LF 7 \$00 Ceiling - Splined 592 SF 4 \$6,160 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile 592 SF 7 \$00 Lighting - Pendent/Surface 15 EA 7 \$00 Marker Board 16 LF 7 \$00 Storage/ Closet 6 SF 7 \$00 Walls - Plaster/Drywall 640 SF 7 \$00 Walls - Structural Glazed Tile 640 SF 7 \$00 Ceiling - Splined 640 SF 7 \$00 AC Units 640 SF 7 \$00 Casework 16 LF 7 \$00 Ceiling - Splined 590 SF 4 \$6,159 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$00 Floor - Tile 595 SF 6 \$1,302 \$1,302 | | Walls - Plaster/Drywall | | 500 | SF | 6 | \$1,380 | |
| Casework 15 LF 7 \$0 Ceiling - Splined 592 SF 4 \$6,180 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 592 SF 7 \$0 Lighting - Pendent/Surface 15 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 6 SF 7 \$0 Walls - Structural Glazed Tile 160 SF 7 \$0 Valls - Structural Glazed Tile 160 SF 7 \$0 Classroom #12B A C Units 1 EA 7 \$0 Ceiling - Splined 590 SF 4 \$6,6159 obsolete material Doors - Wood Doors inclu hw 1 EA 7 \$0 Ceiling - Splined 590 SF 4 \$6,6159 obsolete material Doors - Wood Doors inclu hw 1 EA | | | | 500 | SF | 7 | \$0 | |
| Ceiling - Splined592SF4\$6,180obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile592SF7\$0Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0Storage/ Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile100SF7\$0Classroom #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile591SF6\$1,302\$1Lighting - Pendent/Surface15EA7\$0Lighting - Pendent/Surface20LF7\$0 | Classro | oom #12A (Regular Classroom) | | | | | | |
| Doors - Wood Doors inclu hw1EA7\$0Floor - Tile592SF7\$0Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0Storage / Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile640SF7\$0Classroom #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF6\$1,302Doors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Casework | | 15 | LF | 7 | \$0 | |
| Floor - Tile592SF7\$0Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0Storage/ Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile10SF7\$0Classrow #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$61,59obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board15EA7\$0Marker Board15EA7\$0 | | Ceiling - Splined | | 592 | SF | 4 | \$6,180 | obsolete material |
| Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0Storage/ Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile100SF7\$0ClassrowA C Units57\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors · Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| Marker Board20LF7\$0Storage/ Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile160SF7\$0Classroom #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Floor - Tile | | 592 | SF | 7 | \$0 | |
| Storage/ Closet6SF7\$0Walls - Plaster/Drywall640SF7\$0Walls - Structural Glazed Tile160SF7\$0Classroom #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$66,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Lighting - Pendent/Surface | | 15 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall Walls - Structural Glazed Tile640SF7\$0Classroom #12BE7\$0AC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159Doors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Marker Board | | 20 | LF | 7 | \$0 | |
| Walls - Structural Glazed Tile160SF7\$0Classroom #12BAC Units1EA7\$0AC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Storage/ Closet | | 6 | SF | 7 | \$0 | |
| Classroom #12BAC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Walls - Plaster/Drywall | | 640 | SF | 7 | \$0 | |
| AC Units1EA7\$0Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Walls - Structural Glazed Tile | | 160 | SF | 7 | \$0 | |
| Casework16LF7\$0Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | Classro | oom #12B | | | | | | |
| Ceiling - Splined590SF4\$6,159obsolete materialDoors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | AC Units | | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hw1EA7\$0Floor - Tile595SF6\$1,302Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | Casework | | 16 | LF | 7 | \$0 | |
| Floor - Tile 595 SF 6 \$1,302 Lighting - Pendent/Surface 15 EA 7 \$0 Marker Board 20 LF 7 \$0 | | Ceiling - Splined | | 590 | SF | 4 | \$6,159 | obsolete material |
| Lighting - Pendent/Surface15EA7\$0Marker Board20LF7\$0 | | | | 1 | EA | 7 | \$0 | |
| Marker Board 20 LF 7 \$0 | | Floor - Tile | | 595 | SF | 6 | \$1,302 | |
| | | Lighting - Pendent/Surface | | 15 | EA | 7 | \$0 | |
| Storage/ Closet 5 SF 6 \$36 | | Marker Board | | 20 | LF | 7 | \$0 | |
| | | Storage/ Closet | | 5 | SF | 6 | \$36 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------|----------|------|------|---------|-------------------------------|
| Classro | oom #12B | | | | | | |
| | Walls - Plaster/Drywall | | 500 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 250 | SF | 6 | \$787 | |
| Classro | oom #13 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 775 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #14 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 40 | SF | 4 | \$519 | cracked tile & damaged finish |
| | Floor - Tile | | 735 | SF | 6 | \$1,608 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 4 | LF | 6 | \$86 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #15 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 500 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 500 | SF | 7 | \$0 | |
| Classro | oom #16 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | | | | | | | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

Category: Classrooms

| Group Item - Type Location Quarty Unit Rank Cot Comment Cellars On #16 (Regult Classrop) 7 50 5 7 50 Cellars On #16 (Regult Classrop) 1 EA 5 51.174 6 Cellar Search 7 50 5 <t< th=""><th></th><th>Item - Type</th><th>Location</th><th>Quantity</th><th>Unit</th><th>Rank</th><th>Cost</th><th>Comments</th></t<> | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---------|--------------------------------|----------|----------|------|------|---------|---------------------------|
| Celling - Plaster/Dynall 470 47 57 50 Chalk Board 1 EA 5 51.174 Doors - Wood Doors inclu hw 1 EA 7 50 Lighting - Pordont/Surface 21 EA 7 50 Marker Board 20 LF 6 \$420 non-standard installation Walls - Flaster/Dynall 207 SF 7 \$00 Walls - Structural Glazea Tile 27 S0 | - | | Ebballon | Quantity | onne | Rank | 0051 | Commente |
| Chaik Koard 4 5 <td< td=""><td>0103310</td><td></td><td></td><td>775</td><td>SF</td><td>7</td><td>\$0</td><td></td></td<> | 0103310 | | | 775 | SF | 7 | \$0 | |
| Doors Wood Doors incluitive 1 EA 5 \$1,11 Picor - Tile 27 58 7 80 Lighting - Pendont/Surface 21 EA 7 80 Walls - Blost/Dynall 20 LF 6 54.20 Walls - Structural Glazed Tile 27 58 7 80 AC Unis L K 7 80 Casework 47 LF 7 80 Colling - Platetr/Dynall K 7 80 Doors - Wood Doors incluitive 1 EA 7 80 Colling - Platetr/Dynall 70 SF 7 80 Doors - Wood Doors incluitive 1 EA 7 80 Gas Line 28 F 7 80 Gas Ling 29 F 7 80 Marker Board 20 L F 7 80 Walls - Structural Glazed Tile 29 K 7 80 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>obsolete material</td> | | | | | | | | obsolete material |
| Floor - Tile 76 97 97 90 Lighting - Pendent/Surface 20 12 12 6 9424 Marker Board 20 15 7 950 7 950 Walls - Pisster/Dynall 476 57 7 950 7 950 Constructured Giazad Tile 7 950 7 950 Constructured Giazad Tile 7 950 Giazad Tile 7 950 7 950 7 950 23 57 7 950 7 950 7 950 7 950 7 | | | | | | | | |
| Lighting - Pendent/Surface 21 EA 7 \$90 Marker Board 20 LF 6 \$9428 Walls - Phaster/Dywall 475 SF 7 \$90 Classer T EA 7 \$90 Classer T EA 7 \$90 AC Unis Caling A T EA 7 \$90 Casework AT EA 7 \$90 \$90 Doors - Wood Doors inclu hw T EA 7 \$90 \$90 Gas Line Z EA 7 \$90 \$ | | | | | | | | |
| Marker Dand 20 LF 6 %420 non-standard installation Walls - Plaster/Dywall 475 5F 7 800 Clease-orter Clease Trip AC Units 1 EA 7 50 Caling - Plaster/Dywall 1 EA 7 50 Cosework 1 EA 7 50 Cose Noot Sinclu Nu 1 EA 7 50 Cose Noot Sinclu Nu 1 EA 7 50 Gas Line 2 EA 7 50 Gaster/Dywall 20 EF 7 50 Marker Board 20 EA 7 50 Stronger Closer 20 EF 7 50 Walls - Plaster/Dywall 20 EF 7 50 Walls - Plaster/Dywall 20 EA 7 50 Walls - Plaster/Dywall 20 EA 7 50 Walls - Plaster/Dywall 20 E | | | | | | | | |
| Walls - Paster/Dynall 475 SF 7 SD Walls - Structural Glazed Tile 475 SF 7 SD Cassworth 1 EA 7 SD Cassworth 470 SF 7 SD Cassworth 470 SF 7 SD Cassworth 470 SF 7 SD Doors - Wood Doors inclu hw 1 EA 7 SD Gas Line 70 SF 7 SD Gas Line 70 SF 7 SD Marker Board 21 EA 7 SD Marker Board 5 SF 7 SD Marker Board 5 SF 7 SD Walls - Paster/Dynall 70 SF 7 SD Walls - Structural Glazed Tile 5 7 SD SD Walls - Structural Glazed Tile 7 SD SD SD Walls - Structural Glazed Tile | | | | | | | | non-standard installation |
| Walls - Structural Glazed Tile 47 57 50 Calescorth AC Units 4 4 7 50 A Calonis 4 4 4 7 50 Calescorth 47 47 57 50 Calonis 77 57 7 50 Coors inclu hw 77 57 50 Floor - Tile 770 57 7 500 Gas Line 7 50 5 7 500 Lighting - Pendent/Surface 20 4 7 50 Storage/Closet 20 4 7 50 Valls - Plaster/Drywall 70 57 7 500 Walls - Plaster/Drywall 70 57 7 500 Walls - Plaster/Drywall 7 57 50 5 Valls - Structural Glazed Tile 20 5 7 500 Walls - Plaster/Drywall 7 57 50 5 5 5 5 5 5 Doors - Wood Doors inclu hw 1 < | | | | | | | | |
| Classroom #174 (Science) I EA 7 S0 AC Units 47 1 FA 7 S0 Caleinov // Calling - Plaster/Dryvall 77 S7 S0 Doors - Wood Doors inclu tw 1 EA 7 S0 Floor - Wood Doors inclu tw 1 EA 7 S0 Floor - Tile 70 SF 7 S0 Gas Line 20 LF 7 S0 Gas Context Stratege 21 EA 7 S0 Marker Board 20 LF 7 S0 Walls - Plaster/Drywall 70 SF 7 S0 Walls - Plaster/Drywall 70 SF 7 S0 Walls - Plaster/Drywall 70 SF 7 S0 Wark Sink 3 EA 7 S0 Calling - Plaster/Drywall 70 SF 7 S0 Colling - Plaster/Drywall 70 SF 7 S0 < | | • | | | | | | |
| AC Units 1 EA 7 \$0 Casework 47 LF 7 \$0 Caling - Plaster/Dynall 770 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 770 SF 7 \$0 Gas Line 2 EA 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 25 SF 7 \$0 Walls - Plaster/Drynall 710 SF 7 \$0 Walls - Structural Glazed Tile 230 SF 7 \$0 Walls - Structural Glazed Tile 230 SF 7 \$0 Valls - Structural Glazed Tile 28 ZA 7 \$0 Octinis Structural Glazed Tile 3 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 \$1 Doors - Wood Doors inclu hw 1 EA 7 <td></td> <td></td> <td></td> <td></td> <td>0.</td> <td></td> <td>ψu</td> <td></td> | | | | | 0. | | ψu | |
| Casiwork 47 47 7 \$9 Ceiling - Plaster/Drywall 71 \$7 \$9 Doors - Vood Doors inclu Nuv 1 84 7 \$90 Floor - Tile 70 \$7 \$7 \$90 Gas Line 2 EA 7 \$90 Lighting - Pendent/Surface 20 EA 7 \$90 Marker Board 20 EF 7 \$90 Storage / Closet 5 F 7 \$90 Walls - Structural Glazed Tile 200 F 7 \$90 Walls - Structural Glazed Tile 200 F 7 \$90 Work Sink 20 F 7 \$90 Ceiling - Plaster/Drywall 70 \$F 7 \$90 Core - Tile 20 F 7 \$90 Core - Tile 70 \$F 7 \$90 Doors - Wood Doors inclu Nur 1 EA 7 \$90 Floor - Tile 70 \$F 6 \$1,681 Doors - Wood Doors inclu Nur | Classro | | | | | | | |
| Ceiling - Plaster/Dryvall 70 SF 7 \$\$0 Doors - Wood Doors inclu hw 1 EA 7 \$\$0 Floor - Tile 700 SF 7 \$\$0 Gas Line 2 EA 7 \$\$0 Lighting - Pendent/Surface 21 EA 7 \$\$0 Marker Board 20 LF 7 \$\$0 Storage/Closet 5 SF 7 \$\$0 Walls - Plaster/Dryvall 230 SF 7 \$\$0 Walls - Structural Glazed Tile 230 SF 7 \$\$0 Work Sink 23 SF 7 \$\$0 Celling - Plaster/Dryvall 700 SF 7 \$\$0 Doors - Wood Doors inclu hw 3 SF 7 \$\$0 Celling - Plaster/Dryvall 700 SF 7 \$\$0 Doors - Wood Doors inclu hw 1 EA 7 \$\$0 Doors - Wood Doors inclu hw 1 EA 7 \$\$0 Doors - Wood Doors inclu hw 1 EA 7 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<> | | | | | | | | |
| Door - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 770 \$F 7 \$0 Gas Line 2 EA 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 5 7 \$0 Walls - Plaster/Dynall 700 \$F 7 \$0 Walls - Structural Glazed Tile 200 \$F 7 \$0 Walls - Structural Glazed Tile 200 \$F 7 \$0 Vork Sink 20 \$F 7 \$0 Ceiling - Plaster/Dynall 700 \$F 7 \$0 Coling - Plaster/Dynall 7 \$F 7 \$0 Doors - Wood Doors inclu hw 1 \$E 7 \$0 Floor - Tile Storage/ Closet 7 \$0 \$0 Marker Board 12 \$F 7 \$0 \$0 Marker Board 58 \$F 7 \$0 \$0 <tr< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr<> | | | | | | | | |
| Floor - Tile 770 SF 7 S0 Gas Line 2 EA 7 S0 Lighting - Pendetn/Surface 20 LF 7 S0 Marker Board 20 LF 7 S0 Valles - Plaster/Drywall 710 SF 7 S0 Walles - Structural Glazed Tile 20 LF 7 S0 Walle - Structural Glazed Tile 20 SF 7 S0 Marker Board 20 SF 7 S0 Otester 20 SF 7 S0 Marker Board 20 SF 7 S0 Doors - Wood Doors inclu hw 1 EA 7 S0 Floor - Tile 7 S0 S0 S0 S0 S0 Marker Board 12 EA 7 S0 S0 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<> | | | | | | | | |
| Gas Line 2 EA 7 \$0 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 20 LF 7 \$0 Storage/ Closet 5 F 7 \$0 Walls - Plaster/Dywall 70 SF 7 \$0 Walls - Structural Glazed Tile 23 SF 7 \$0 Work Sink 3 SF 7 \$0 Classrom#17B A C Units Structural Glazed Tile \$1 EA 7 \$0 Ceiling - Plaster/Dywall 770 SF 7 \$0 \$0 Doors + WOD Doors inclu hw 1 EA 7 \$1 \$1 Floors - Tile 770 SF 6 \$1 </td <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td> | | | | - | | | | |
| Lighting - Pendent/Surface 21 EA 7 50 Marker Board 20 LF 7 \$0 Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Dywall 200 SF 7 \$0 Walls - Structural Glazed Tile 200 SF 7 \$0 Work Sink 200 SF 7 \$0 Classroom#T/E A C Units 5 SF 7 \$0 Ceiling - Plaster/Dywall 70 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 70 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 23 SF 7 \$0 Marker Board 24 FA 7 \$0 Marker Board 25 F 7 \$0 Walls - Plaster/Drywall 70 \$5 | | | | | | | | |
| Marker Board 20 LF 7 \$0 Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Drywall 230 SF 7 \$0 Walls - Structural Glazed Tile 230 SF 7 \$0 Work Sink 3 EA 7 \$0 Classroom #17B AC Units 7 S0 Ceiling - Plaster/Drywall 7 \$1 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 70 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 12 EA 7 \$0 Storage/ Closet 21 EA 7 \$0 Marker Board 12 EA 7 \$0 Walls - Plaster/Drywall 21 EA 7 \$0 Walls - Structural Glazed Tile 23 SF 7 \$0 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | | | | | | | | |
| Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Drywall 710 SF 7 \$0 Walls - Plaster/Drywall 230 SF 7 \$0 Work Sink 3 EA 7 \$0 Classroom #17B AC Units 7 \$0 Coiling - Plaster/Drywall 770 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 770 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 12 LF 7 \$0 Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Drywall 20 SF 7 \$0 Walls - Plaster/Drywall SF 7 \$0 \$0 Walls - Plaster/Drywall SF 7 \$0 \$0 Walls - Plaster/Drywall SF 7 \$0 \$0 | | | | | | | | |
| Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0Work Sink3EA7\$0Classroom #17BA C Units2EA7\$0Doors - Wood Doors inclu hw770SF7\$0Ploor - Tile770SF7\$0Lighting - Pendent/Surface21EA7\$0Marker Board21EA7\$0Storage/ Closet5SF7\$0Walls - Plaster/Drywall710SF7\$0Walls - Plaster/Drywall710SF7\$0Classroom #18 (Regular Classroom)11EA7\$0Classroom #18 (Regular Classroom)11EA5\$7\$0A C Units1EA5\$2,654Claing - Plaster/Drywall1EA\$4\$3,672obolete material | | | | | | | | |
| Walls - Structural Glazed Tile Work Sink230SF7\$0Classroom #17BAC Units2EA7\$0Ceiling - Plaster/Drywall770SF7\$0Doors - Wood Doors inclu hw770SF7\$0Floor - Tile70SF6\$11,685Lighting - Pendent/Surface71EA7\$0Marker Board12LF7\$0Storage/ Closet5SF7\$0Walls - Structural Glazed Tile20SF7\$0Marker Classroom710SF6\$496CluitsCluitsSF7\$00AC UnitsEdSF7\$00Classroom #18 (Regular Classroom)2SF6\$496Ceiling - Plaster/Drywall1EA6\$496Caling - Plaster/Drywall2SF7\$00ChuitsST57\$00ChuitsST57\$00Caling - Plaster/Drywall257\$00ChuitsST56\$496Caling - Plaster/Drywall576\$2,654ChuitsST56\$2,654Caling - Plaster/Drywall40LF4\$3,672ChuitsST6\$2,654ChuitsST6\$2,654ChuitsST6\$2,654Chuits6\$2,654 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | | | | | | | | |
| Work Sink387\$0Classroom #TBAC Units2247\$0Ceiling - Plaster/Drywall77057\$0Doors - Wood Doors inclu hw127\$0Floor - Tile77056\$16.85Lighting - Pendent/Surface2127\$0Marker Board2127\$0Storage/Closet557\$0Walls - Plaster/Drywall2105\$7\$0Walls - Structural Glazed Tile710\$57\$0ClassroomAC Units1EA6\$496Ceiling - Plaster/Drywall76\$5\$6\$2,654Ceiling - Plaster/Drywall76\$7\$6\$2,654Ceiling - Plaster/Drywall76\$7\$6\$2,654AC Units6\$4,96\$4,96\$3,672obsoleter material | | - | | | | | | |
| Classroom #17B AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 770 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 770 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 12 LF 7 \$0 Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Drywall 710 SF 7 \$0 Walls - Structural Glazed Tile 710 SF 7 \$0 ClassroomJ AC Units Ceiling - Plaster/Drywall \$1 SF 7 \$0 Classroom #18 (Regular Classroom) 5 7 \$0 \$1 \$2,65 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Chalk Board 40 LF 4 \$3,672 obsolete material | | | | | | | | |
| AC Units2EA7\$0Ceiling - Plaster/Drywall770SF7\$0Doors - Wood Doors inclu hw1EA7\$0Floor - Tile770SF6\$1,685Lighting - Pendent/Surface21EA7\$0Marker Board12LF7\$0Storage/ Closet5SF7\$0Valls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0ClassroomAC Units1EA6\$496Ceiling - Plaster/Drywall767SF6\$2,654Ceiling - Plaster/Drywall767SF6\$2,654Chak Board40LF4\$3,672obsolete material | | Work Sink | | 3 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywall 770 SF 7 \$0 Doors - Wood Doors inclu hw 1 EA 7 \$0 Floor - Tile 770 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 12 LF 7 \$0 Storage/ Closet 5 SF 7 \$0 Walls - Plaster/Drywall 710 SF 7 \$0 Walls - Structural Glazed Tile 710 SF 7 \$0 Ceasroom #18 (Regular Classroom) 21 EA 7 \$0 AC Units Ceiling - Plaster/Drywall 767 SF 6 \$496 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Chalk Board 40 LF 4 \$3,672 obsolete material | Classro | oom #17B | | | | | | |
| Doors - Wood Doors inclu hw1EA7\$0Floor - Tile770SF6\$1,685Lighting - Pendent/Surface21EA7\$0Marker Board12LF7\$0Storage/ Closet5SF7\$0Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0ClassroomAC Units1EA6\$496Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | AC Units | | 2 | EA | 7 | \$0 | |
| Floor - Tile 770 SF 6 \$1,685 Lighting - Pendent/Surface 21 EA 7 \$0 Marker Board 12 LF 7 \$0 Storage/Closet 5 SF 7 \$0 Walls - Plaster/Drywall 710 SF 7 \$0 Walls - Structural Glazed Tile 700 SF 7 \$0 Classroom/ AC Units AC Units 1 EA 6 \$496 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Chalk Board 40 LF 4 \$3,672 obsolete material | | Ceiling - Plaster/Drywall | | 770 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface21EA7\$0Marker Board12LF7\$0Storage/ Closet5SF7\$0Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0ClassroomAC Units1EA6\$496Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| Marker Board12LF7\$0Storage/ Closet5SF7\$0Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0Classroom #18 (Regular Classroom)AC UnitsSF6\$496Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | Floor - Tile | | 770 | SF | 6 | \$1,685 | |
| Storage/ Closet5SF7\$0Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0Classroom #18 (Regular Classroom)AC Units1EA6\$496Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall710SF7\$0Walls - Structural Glazed Tile230SF7\$0Classroom #18 (Regular Classroom)AC Units1EA6\$496Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | Marker Board | | 12 | LF | 7 | \$0 | |
| Walls - Structural Glazed Tile230SF7\$0Classroom #18 (Regular Classroom)AC UnitsAC UnitsCeiling - Plaster/DrywallChalk BoardChalk BoardChalk Board | | Storage/ Closet | | 5 | SF | 7 | \$0 | |
| Classroom #18 (Regular Classroom)AC UnitsCeiling - Plaster/DrywallChalk BoardChalk Board | | Walls - Plaster/Drywall | | 710 | SF | 7 | \$0 | |
| AC Units 1 EA 6 \$496 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Chalk Board 40 LF 4 \$3,672 obsolete material | | Walls - Structural Glazed Tile | | 230 | SF | 7 | \$0 | |
| AC Units 1 EA 6 \$496 Ceiling - Plaster/Drywall 767 SF 6 \$2,654 Chalk Board 40 LF 4 \$3,672 obsolete material | Classro | oom #18 (Regular Classroom) | | | | | | |
| Ceiling - Plaster/Drywall767SF6\$2,654Chalk Board40LF4\$3,672obsolete material | | | | 1 | EA | 6 | \$496 | |
| Chalk Board 40 LF 4 \$3,672 obsolete material | | Ceiling - Plaster/Drywall | | 767 | SF | 6 | | |
| Doors - Wood Doors inclu hw 1 EA 5 \$1,174 | | | | 40 | LF | 4 | | obsolete material |
| | | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |

5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Category: Clas | srooms |
|----------------|--------|
|----------------|--------|

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------|----------|------|------|---------|---------------------------|
| Classro | oom #18 (Regular Classroom) | | | | | | |
| | Floor - Tile | | 767 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #19 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 800 | SF | 7 | \$0 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 800 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 40 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #212 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 775 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| | Floor - Tile | | 775 | SF | 5 | \$3,480 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 475 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 475 | SF | 7 | \$0 | |
| Classro | oom #213 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 850 | SF | 6 | \$2,942 | |
| | Chalk Board | | 40 | LF | 4 | \$3,672 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| | Floor - Tile | | 850 | SF | 5 | \$3,817 | |
| | Lighting - Pendent/Surface | | 21 | EA | 7 | \$0 | |
| | Marker Board | | 40 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 500 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | | 500 | SF | 7 | \$0 | |

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

Category: Classrooms

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|----------|----------|------|------|-----------|--|
| assroom #214 (Office) | | | | | | |
| AC Units | | 1 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywall | | 380 | SF | 7 | \$0 | |
| Chalk Board | | 5 | LF | 6 | \$112 | |
| Doors - Wood Doors inclu h | N | 1 | EA | 6 | \$301 | |
| Floor - Tile | | 380 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | | 9 | EA | 7 | \$0 | |
| Marker Board | | 10 | LF | 7 | \$0 | |
| Walls - Plaster/Drywall | | 679 | SF | 7 | \$0 | |
| assroom #216 (Music Room) | | | | | | |
| AC Units | | 1 | EA | 7 | \$0 | |
| Ceiling - Splined | | 830 | SF | 6 | \$677 | |
| Chalk Board | | 10 | LF | 4 | \$918 | obsolete material |
| Doors - Steel Doors incl hw | | 3 | EA | 6 | \$903 | |
| Floor - Tile | | 30 | SF | 5 | \$173 | damaged & broken tile and base |
| Floor - Tile | | 800 | SF | 6 | \$1,750 | |
| Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| Marker Board | | 16 | LF | 7 | \$0 | |
| Storage/ Closet | | 163 | SF | 6 | \$1,182 | |
| Walls - Plaster/Drywall | | 1,057 | SF | 6 | \$2,917 | |
| assroom #218 (Music Room) | | | | | | |
| AC Units | | 2 | EA | 7 | \$0 | |
| Casework | | 57 | LF | 5 | \$11,918 | damaged & missing hardware on doors |
| Ceiling - Splined | | 1,475 | SF | 6 | \$1,202 | dirty & damaged |
| Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| Doors - Wood Doors inclu h | N | 3 | EA | 5 | \$3,522 | |
| Floor - Carpet | | 1,025 | SF | 5 | \$5,262 | stained, warped and separating @ seams |
| Floor - Tile | | 450 | SF | 6 | \$985 | |
| Lighting - Pendent/Surface | | 28 | EA | 6 | \$3,469 | |
| Marker Board | | 16 | LF | 7 | \$0 | |
| Storage/ Closet | | 163 | SF | 6 | \$1,182 | |
| Walls - Plaster/Drywall | | 100 | SF | 5 | \$511 | vinyl wall cover peeling off |
| Walls - Plaster/Drywall | | 1,373 | SF | 6 | \$3,789 | |
| assrooms Subtotal: | | | | | \$198.190 | |

Classrooms Subtotal:

\$198,190

Building: Addition



Group Item - Type

Category: Rooms (Other Than Classrooms)

Northwest Middle School

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Cost Comments

Quantity Unit Rank

SF

ΕA

150

2

7

7

\$0

\$0

Administrative Suites/Offices Ceiling - Plaster/Drvwall 011A Resource Center (N-104 on plan) 280 SF 7 \$0 Doors - Wood Doors inclu hw 011A Resource Center (N-104 on plan) ΕA 5 \$1.174 1 Floor - Tile 011A Resource Center (N-104 on plan) SF 280 7 \$0 Lighting - Pendent/Surface 011A Resource Center (N-104 on plan) ΕA 7 \$0 3 7 Power Distribution 011A Resource Center (N-104 on plan) 8 ΕA \$0 Walls - Plaster/Drvwall 011A Resource Center (N-104 on plan) 318 SF 7 \$0 7 Walls - Structural Glazed Tile 011A Resource Center (N-104 on plan) SF 318 \$0 SF Ceiling - Splined 011B (N106 on plan) 99 6 \$81 Doors - Wood Doors inclu hw 7 \$0 011B (N106 on plan) 1 ΕA Floor - Tile SF 7 011B (N106 on plan) 99 \$0 Lighting - Pendent/Surface 7 \$0 011B (N106 on plan) 1 ΕA 7 Power Distribution 011B (N106 on plan) 8 ΕA \$0 SF 5 \$682 Walls - Plaster/Drywall 011B (N106 on plan) 90 7 Walls - Structural Glazed Tile 011B (N106 on plan) SF \$0 180 Ceiling - Plaster/Drywall 014A Assistant Principal's Office (N-109 380 SF 7 \$0 on plan) Doors - Wood Doors inclu hw 014A Assistant Principal's Office (N-109 1 ΕA 7 \$0 on plan) Floor - Tile 014A Assistant Principal's Office (N-109 380 SF 7 \$0 on plan) Lighting - Pendent/Surface 014A Assistant Principal's Office (N-109 ΕA 6 \$743 6 on plan) Power Distribution 014A Assistant Principal's Office (N-109 6 ΕA 7 \$0 on plan) SF \$0 Walls - Plaster/Drywall 014A Assistant Principal's Office (N-109 740 7 on plan) AC Unit 113A Principal's Office (N-209 on plan) ΕA 7 \$0 1 7 Ceiling - Plaster/Drywall 113A Principal's Office (N-209 on plan) 380 SF \$0 Doors - Wood Doors inclu hw 7 113A Principal's Office (N-209 on plan) 2 ΕA \$0 Floor - Tile 113A Principal's Office (N-209 on plan) 380 SF 6 \$831 Lighting - Pendent/Surface 113A Principal's Office (N-209 on plan) 4 ΕA 7 \$0 113A Principal's Office (N-209 on plan) ΕA 7 \$0 **Power Distribution** 12 SF 7 Walls - Plaster/Drywall 113A Principal's Office (N-209 on plan) 703 \$0 Ceiling - Plaster/Drywall SF 7 \$0 120 Teacher's Lounge (N-201 on floor 150 plan) Doors - Wood Doors inclu hw 120 Teacher's Lounge (N-201 on floor ΕA 5 \$1.174 1 plan)

plan)

plan)

Location

Floor - Tile

Lighting - Pendent/Surface

120 Teacher's Lounge (N-201 on floor

120 Teacher's Lounge (N-201 on floor



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|---------|---|
| Adminis | strative Suites/Offices | | | | | | |
| | Power Distribution | 120 Teacher's Lounge (N-201 on floor plan) | 5 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 120 Teacher's Lounge (N-201 on floor plan) | 477 | SF | 6 | \$1,316 | vinyl wall covering is damaged |
| | Ceiling - Splined | 216A Practice/Storage | 118 | SF | 6 | \$96 | |
| | Doors - Side-lite | 216A Practice/Storage | 12 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 216A Practice/Storage | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 216A Practice/Storage | 118 | SF | 5 | \$606 | worn & stained |
| | Lighting - Pendent/Surface | 216A Practice/Storage | 2 | EA | 7 | \$0 | |
| | Power Distribution | 216A Practice/Storage | 2 | EA | 7 | \$0 | |
| | Storage/ Closet | 216A Practice/Storage | 45 | SF | 6 | \$326 | |
| | Walls - Plaster/Drywall | 216A Practice/Storage | 300 | SF | 5 | \$2,274 | paneling on two walls |
| | Ceiling - Splined | 216B Practice Room (currently being used as office/storage) | 142 | SF | 6 | \$116 | stained & discolored; obsolete material |
| | Doors - Side-lite | 216B Practice Room (currently being used as office/storage) | 12 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 216B Practice Room (currently being used as office/storage) | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 216B Practice Room (currently being used as office/storage) | 142 | SF | 5 | \$729 | stained and worn |
| | Lighting - Pendent/Surface | 216B Practice Room (currently being used as office/storage) | 2 | EA | 6 | \$248 | |
| | Power Distribution | 216B Practice Room (currently being used as office/storage) | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 216B Practice Room (currently being used as office/storage) | 512 | SF | 6 | \$1,413 | damaged vinyl wall covering |
| | Ceiling - Plaster/Drywall | 217 Office (N-315 on plan) | 157 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 217 Office (N-315 on plan) | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | 217 Office (N-315 on plan) | 157 | SF | 6 | \$344 | |
| | Lighting - Pendent/Surface | 217 Office (N-315 on plan) | 2 | EA | 7 | \$0 | |
| | Power Distribution | 217 Office (N-315 on plan) | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 217 Office (N-315 on plan) | 449 | SF | 6 | \$1,239 | vinyl wall covering is damaged |
| | Work SInk | 217 Office (N-315 on plan) | 1 | EA | 5 | \$1,508 | |
| | Ceiling - Splined | 218A Practice Room | 118 | SF | 6 | \$96 | |
| | Doors - Steel Doors incl hw | 218A Practice Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 218A Practice Room | 118 | SF | 4 | \$1,085 | worn and stained |
| | Lighting - Pendent/Surface | 218A Practice Room | 2 | EA | 7 | \$0 | |
| | Power Distribution | 218A Practice Room | 2 | EA | 7 | \$0 | |
| | Storage/ Closet | 218A Practice Room | 45 | SF | 5 | \$726 | |
| | Walls - Plaster/Drywall | 218A Practice Room | 300 | SF | 5 | \$2,274 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|--|----------|------|------|----------|-------------------------------|
| strative Suites/Offices | | | | | | |
| Ceiling - Splined | 218B Practice Room (currently used as an office) | 142 | SF | 6 | \$116 | discolored & dirty |
| Doors - Side-lite | 218B Practice Room (currently used as an office) | 12 | SF | 6 | \$201 | |
| Doors - Steel Doors incl hw | 218B Practice Room (currently used as an office) | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 218B Practice Room (currently used as an office) | 142 | SF | 5 | \$729 | stained & worn |
| Lighting - Pendent/Surface | 218B Practice Room (currently used as an office) | 12 | EA | 6 | \$1,487 | |
| Power Distribution | 218B Practice Room (currently used as an office) | 2 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 218B Practice Room (currently used as an office) | 512 | SF | 6 | \$1,413 | damaged vinyl wall covering |
| Ceiling - Plaster/Drywall | 219 Office (N-316 on plan) | 180 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 219 Office (N-316 on plan) | 1 | EA | 5 | \$1,174 | |
| Floor - Tile | 219 Office (N-316 on plan) | 180 | SF | 6 | \$394 | |
| Lighting - Pendent/Surface | 219 Office (N-316 on plan) | 2 | EA | 7 | \$0 | |
| Power Distribution | 219 Office (N-316 on plan) | 4 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 219 Office (N-316 on plan) | 489 | SF | 6 | \$1,350 | damaged vinyl wall covering |
| Ceiling - Splined | 221 Office (N-319 on plan) | 139 | SF | 6 | \$113 | |
| Doors - Side-lite | 221 Office (N-319 on plan) | 12 | SF | 6 | \$201 | |
| Doors - Steel Doors incl hw | 221 Office (N-319 on plan) | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 221 Office (N-319 on plan) | 139 | SF | 5 | \$714 | stained & worn |
| Lighting - Pendent/Surface | 221 Office (N-319 on plan) | 2 | EA | 7 | \$0 | |
| Power Distribution | 221 Office (N-319 on plan) | 4 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 221 Office (N-319 on plan) | 441 | SF | 6 | \$1,217 | damaged vinyl wall covering |
| Ceiling - Splined | 223B office | 108 | SF | 6 | \$88 | |
| Doors - Side-lite | 223B office | 32 | SF | 6 | \$535 | |
| Doors - Wood Doors inclu hw | 223B office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 223B office | 108 | SF | 4 | \$993 | worn, warped & stained carpet |
| Lighting - Pendent/Surface | 223B office | 2 | EA | 7 | \$0 | |
| Power Distribution | 223B office | 6 | EA | 6 | \$12,749 | |
| Walls - Plaster/Drywall | 223B office | 262 | SF | 7 | \$0 | |
| Ceiling - Splined | 223C 'Conference Room' (currently used as a library collections storage | 108 | SF | 6 | \$88 | |
| Doors - Wood Doors inclu hw | 223C 'Conference Room' (currently used as a library collections storage | 1 | EA | 5 | \$1,174 | |
| Floor - Tile | 223C 'Conference Room' (currently used as a library collections storage | 108 | SF | 6 | \$236 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|----------|----------|
| Admini | strative Suites/Offices | | | | | | |
| | Lighting - Pendent/Surface | 223C 'Conference Room' (currently used as a library collections storage | 2 | EA | 6 | \$248 | |
| | Power Distribution | 223C 'Conference Room' (currently used as a library collections storage | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 223C 'Conference Room' (currently used as a library collections storage | 300 | SF | 6 | \$828 | |
| | Ceiling - Plaster/Drywall | 223D Library Work Room | 297 | SF | 6 | \$1,028 | |
| | Doors - Wood Doors inclu hw | 223D Library Work Room | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | 223D Library Work Room | 297 | SF | 5 | \$1,334 | |
| | Lighting - Pendent/Surface | 223D Library Work Room | 7 | EA | 7 | \$0 | |
| | Power Distribution | 223D Library Work Room | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 223D Library Work Room | 698 | SF | 6 | \$1,926 | |
| | Work SInk | 223D Library Work Room | 1 | EA | 5 | \$1,508 | |
| | Ceiling - Splined | 223E "Library Work Room" (currently being used as a library book storage room) | 108 | SF | 6 | \$88 | |
| | Doors - Wood Doors inclu hw | 223E "Library Work Room" (currently being used as a library book storage room) | 1 | EA | 5 | \$1,174 | |
| | Floor - Carpet | 223E "Library Work Room" (currently being used as a library book storage room) | 108 | SF | 6 | \$230 | |
| | Lighting - Pendent/Surface | 223E "Library Work Room" (currently being used as a library book storage room) | 2 | EA | 7 | \$0 | |
| | Power Distribution | 223E "Library Work Room" (currently being used as a library book storage room) | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 223E "Library Work Room" (currently being used as a library book storage room) | 255 | SF | 6 | \$704 | |
| | Ceiling - Splined | 224A Workroom | 155 | SF | 6 | \$126 | |
| | Doors - Wood Doors inclu hw | 224A Workroom | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 224A Workroom | 155 | SF | 6 | \$339 | |
| | Lighting - Pendent/Surface | 224A Workroom | 4 | EA | 7 | \$0 | |
| | Power Distribution | 224A Workroom | 10 | EA | 7 | \$0 | |
| | Storage/ Closet | 224A Workroom | 5 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 224A Workroom | 483 | SF | 7 | \$0 | |
| Library | | | | | | | |
| | Casework | 223 Northwest (N-301 on plan) | 550 | LF | 6 | \$13,890 | |
| | Ceiling - Splined | 223 Northwest (N-301 on plan) | 4,126 | | 6 | \$3,363 | |
| | N/COT | | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------------------|----------|------|------|---------|--|
| Library | | | | | | | |
| | Doors - Wood Doors inclu hw | 223 Northwest (N-301 on plan) | 2 | EA | 5 | \$2,348 | |
| | Doors - Wood Doors inclu hw | 223 Northwest (N-301 on plan) | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 223 Northwest (N-301 on plan) | 4,126 | SF | 6 | \$9,027 | |
| | Lighting - Pendent/Surface | 223 Northwest (N-301 on plan) | 80 | EA | 6 | \$9,912 | |
| | Storage/ Closet | 223 Northwest (N-301 on plan) | 224 | SF | 6 | \$1,624 | |
| | Walls - Plaster/Drywall | 223 Northwest (N-301 on plan) | 2,969 | SF | 7 | \$0 | |
| | Casework | 224 Belmont Cragin | 275 | LF | 6 | \$6,945 | |
| | Ceiling - Splined | 224 Belmont Cragin | 1,115 | SF | 6 | \$909 | |
| | Doors - Wood Doors inclu hw | 224 Belmont Cragin | 2 | EA | 7 | \$0 | |
| | Floor - Tile | 224 Belmont Cragin | 1,115 | SF | 6 | \$2,440 | |
| | Lighting - Pendent/Surface | 224 Belmont Cragin | 28 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 224 Belmont Cragin | 1,651 | SF | 6 | \$4,557 | |
| MDF_I |)F | | | | | | |
| | AC Unit | Room 120B | 1 | EA | 6 | \$496 | |
| | Doors - Steel Doors incl hw | Room 120B | 1 | EA | 6 | \$301 | |
| | Finishes | Room 120B | 155 | SF | 5 | \$2,502 | |
| | Ventilation and Cooling | Room 120B | 1 | EA | 7 | \$0 | |
| Mecha | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | | 32 | SF | 6 | \$229 | basement JC @ girls' toilet room |
| | Janitor's Closet | | 32 | SF | 6 | \$229 | 1st floor JC @ girls' toilet room |
| | Janitor's Closet | | 21 | SF | 6 | \$150 | 2nd floor JC @ girls' toilet room |
| | Mechanical/ Service Rooms | | 51 | SF | 6 | \$365 | Rm 121 |
| | Mechanical/ Service Rooms | | 284 | SF | 7 | \$0 | 021 Mechanical |
| | Mechanical/ Service Rooms | | 32 | SF | 6 | \$229 | Rm 222 |
| | Storage Room | | 550 | SF | 6 | \$3,940 | 220 storage |
| Restro | om | | | | | | |
| | Accessories | 10A (N-102A on plan | 67 | SF | 7 | \$0 | mirror, soap dispenser, toilet paper dispenser |
| | Ceiling - Plaster/Drywall | 10A (N-102A on plan | 67 | SF | 6 | \$232 | |
| | Doors - Wood Doors inclu hw | 10A (N-102A on plan | 1 | EA | 7 | \$0 | |
| | Floor Drain | 10A (N-102A on plan | 1 | EA | 3 | \$3,354 | not functioning (standing water) |
| | Floor - Tile Ceramic/ Porcelain | 10A (N-102A on plan | 67 | SF | 7 | \$0 | |
| | Lavatory | 10A (N-102A on plan | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 10A (N-102A on plan | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 10A (N-102A on plan | 103 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 10A (N-102A on plan | 83 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 10A (N-102A on plan | 41 | SF | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

| b Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|---|----------|------|------|---------|---|
| oom | | | | | | |
| Water Closet | 10A (N-102A on plan | 1 | EA | 7 | \$0 | |
| Accessories | 1st Floor Girls (N-213) on plan | 230 | SF | 6 | \$2,121 | soap dispenser |
| Ceiling - Plaster/Drywall | 1st Floor Girls (N-213) on plan | 230 | SF | 6 | \$796 | |
| Doors - Side-lite | 1st Floor Girls (N-213) on plan | 16 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 1st Floor Girls (N-213) on plan | 1 | EA | 6 | \$301 | stained and damaged |
| Floor Drain | 1st Floor Girls (N-213) on plan | 1 | EA | 7 | \$0 | |
| Floor - Terrazzo | 1st Floor Girls (N-213) on plan | 230 | SF | 7 | \$0 | |
| Hand Dryer | 1st Floor Girls (N-213) on plan | 2 | EA | 7 | \$0 | |
| Lavatory | 1st Floor Girls (N-213) on plan | 2 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | 1st Floor Girls (N-213) on plan | 3 | EA | 6 | \$372 | |
| Partitions | 1st Floor Girls (N-213) on plan | 5 | EA | 6 | \$1,485 | |
| Walls - Structural Glazed Tile | 1st Floor Girls (N-213) on plan | 320 | SF | 7 | \$0 | |
| Water Closet | 1st Floor Girls (N-213) on plan | 5 | EA | 6 | \$1,680 | |
| Accessories | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 25 | SF | 6 | \$231 | mirror, soap dispenser, toilet paper holder |
| Ceiling - Plaster/Drywall | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 25 | SF | 6 | \$87 | |
| Doors - Wood Doors inclu hw | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 1 | EA | 5 | \$1,174 | |
| Floor - Tile Ceramic/ Porcelain | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 25 | SF | 7 | \$0 | |
| Lavatory | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 1 | EA | 7 | \$0 | |
| Lighting - Wall Mounted | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 1 | EA | 6 | \$124 | insufficient illumination |
| Walls - Plaster/Drywall | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 46 | SF | 6 | \$127 | |
| Walls - Structural Glazed Tile | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 93 | SF | 7 | \$0 | |
| Water Closet | 1st Floor Unisex in Work Room 120 (N- 201) on plan | 1 | EA | 5 | \$1,344 | not functioning properly; stained |
| Accessories | 2nd Floor Girls (N-313) on plan | 230 | SF | 6 | \$2,121 | soap dispenser |
| Ceiling - Plaster/Drywall | 2nd Floor Girls (N-313) on plan | 230 | SF | 6 | \$796 | |
| Doors - Wood Doors inclu hw | 2nd Floor Girls (N-313) on plan | 1 | EA | 5 | \$1,174 | |
| Floor Drain | 2nd Floor Girls (N-313) on plan | 1 | EA | 7 | \$0 | |
| Floor - Terrazzo | 2nd Floor Girls (N-313) on plan | 230 | SF | 7 | \$0 | |
| Hand Dryer | 2nd Floor Girls (N-313) on plan | 2 | EA | 7 | \$0 | |
| Lavatory | 2nd Floor Girls (N-313) on plan | 2 | EA | 6 | \$639 | |
| Lighting - Pendent/Surface | 2nd Floor Girls (N-313) on plan | 4 | EA | 6 | \$496 | |
| Partitions | 2nd Floor Girls (N-313) on plan | 4 | EA | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Addition

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------------|------------------------------------|----------|------|------|---------|---------------------|
| Restroom | | | | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor Girls (N-313) on plan | 320 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor Girls (N-313) on plan | 3 | EA | 6 | \$1,008 | |
| | Water Closet | 2nd Floor Girls (N-313) on plan | 1 | EA | 4 | \$7,669 | Ouf of Service |
| | Accessories | Ground Floor Girls (N-113) on plan | 230 | SF | 6 | \$2,121 | soap dispenser |
| | Ceiling - Plaster/Drywall | Ground Floor Girls (N-113) on plan | 230 | SF | 6 | \$796 | |
| | Doors - Side-lite | Ground Floor Girls (N-113) on plan | 16 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Ground Floor Girls (N-113) on plan | 1 | EA | 5 | \$1,174 | stained and damaged |
| | Floor Drain | Ground Floor Girls (N-113) on plan | 1 | EA | 7 | \$0 | |
| | Floor - Terrazzo | Ground Floor Girls (N-113) on plan | 230 | SF | 7 | \$0 | |
| | Hand Dryer | Ground Floor Girls (N-113) on plan | 2 | EA | 7 | \$0 | |
| | Lavatory | Ground Floor Girls (N-113) on plan | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Ground Floor Girls (N-113) on plan | 3 | EA | 6 | \$372 | |
| | Partitions | Ground Floor Girls (N-113) on plan | 5 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Ground Floor Girls (N-113) on plan | 320 | SF | 7 | \$0 | |
| | Water Closet | Ground Floor Girls (N-113) on plan | 5 | EA | 6 | \$1,680 | |

Rooms (Other Than Classrooms) Subtotal:

\$155,069

Building: Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | |
|---------|--------------------------------------|-----------|----------|------|------|----------|----------|--|--|--|
| Corrido | Corridor | | | | | | | | | |
| | Ceiling - Splined | 1st Floor | 3,071 | SF | 6 | \$8,871 | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 6 | EA | 6 | \$1,806 | | | | |
| | Drinking Fountains - Single Fountain | 1st Floor | 4 | EA | 7 | \$0 | | | | |
| | Floor - Terrazzo | 1st Floor | 3,071 | SF | 7 | \$0 | | | | |
| | Lighting - Lay-in | 1st Floor | 29 | EA | 7 | \$0 | | | | |
| | Student Lockers - One Tier | 1st Floor | 296 | EA | 5 | \$41,486 | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,453 | SF | 6 | \$6,441 | | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,907 | SF | 7 | \$0 | | | | |
| | Ceiling - Splined | 2nd Floor | 3,071 | SF | 6 | \$8,871 | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 6 | EA | 6 | \$1,806 | | | | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 4 | EA | 7 | \$0 | | | | |
| | Floor - Terrazzo | 2nd Floor | 3,071 | SF | 7 | \$0 | | | | |
| | Lighting - Lay-in | 2nd Floor | 29 | EA | 7 | \$0 | | | | |
| | Student Lockers - One Tier | 2nd Floor | 296 | EA | 5 | \$41,486 | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,453 | SF | 6 | \$6,441 | | | | |



Building: Addition

Category: Building Interior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-------------------------------|----------|------|------|----------|---------------------------|
| Corrido | r | | | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 2,907 | SF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor North | 817 | SF | 6 | \$2,360 | |
| | Drinking Fountains - Single Fountain | 3rd Floor North | 2 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 3rd Floor North | 267 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor North | 550 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 3rd Floor North | 10 | EA | 6 | \$1,190 | |
| | Walls - Plaster/Drywall | 3rd Floor North | 483 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Floor North | 996 | SF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor South | 871 | SF | 6 | \$2,516 | |
| | Doors - Steel Doors incl hw | 3rd Floor South | 2 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Fountain | 3rd Floor South | 2 | EA | 6 | \$551 | |
| | Floor - Terrazzo | 3rd Floor South | 871 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 3rd Floor South | 9 | EA | 6 | \$1,071 | |
| | Student Lockers - One Tier | 3rd Floor South | 38 | EA | 5 | \$5,326 | |
| | Walls - Plaster/Drywall | 3rd Floor South | 350 | SF | 6 | \$1,552 | |
| | Walls - Structural Glazed Tile | 3rd Floor South | 643 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Elevated link @ central stair | 421 | SF | 5 | \$5,304 | peeling plaster and paint |
| | Doors - Wood Doors include hw | Elevated link @ central stair | 2 | EA | 6 | \$602 | |
| | Floor - Terrazzo | Elevated link @ central stair | 421 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Elevated link @ central stair | 5 | EA | 6 | \$619 | |
| | Walls - Plaster/Drywall | Elevated link @ central stair | 280 | SF | 6 | \$1,241 | |
| | Walls - Structural Glazed Tile | Elevated link @ central stair | 561 | SF | 7 | \$0 | |
| | Ceiling - Splined | Ground Floor / Basement | 3,071 | SF | 6 | \$8,871 | |
| | Doors - Steel Doors incl hw | Ground Floor / Basement | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Single Fountain | Ground Floor / Basement | 1 | EA | 6 | \$276 | |
| | Floor - Terrazzo | Ground Floor / Basement | 3,071 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Ground Floor / Basement | 29 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Ground Floor / Basement | 282 | EA | 6 | \$26,180 | |
| | Walls - Plaster/Drywall | Ground Floor / Basement | 1,453 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Ground Floor / Basement | 2,907 | SF | 6 | \$9,145 | |
| | Ceiling - Splined | North Vestibule @ Library | 106 | SF | 6 | \$306 | |
| | Doors - Wood Doors include hw | North Vestibule @ Library | 2 | EA | 5 | \$2,348 | Damaged veneer and finish |
| | Floor - Tile/Sheet | North Vestibule @ Library | 106 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | North Vestibule @ Library | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | North Vestibule @ Library | 378 | SF | 7 | \$0 | |
| Stairs | | | | | | | |
| Julio | Ceiling - Plaster/Drywall | Central | 122 | SF | 7 | \$0 | |
| | | | | | | , - | |



Building: Addition

Category: Building Interior

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| 0 | ry: Building Interior | | | | | | |
|---------------------|--------------------------------|-------------------|----------|-------------------|------|-------------|----------|
| Group l | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Stairs | | | | | | | |
| (| Ceiling - Splined | Central | 555 | SF | 6 | \$1,603 | |
| F | Floor - Terrazzo | Central | 408 | SF | 7 | \$0 | |
| ŀ | Handrails | Central | 104 | LF | 7 | \$0 | |
| L | Lighting - Pendent/Surface | Central | 10 | EA | 6 | \$1,239 | |
| 5 | Stairs - Terrazzo | Central | 220 | LF | 7 | \$0 | |
| ١ | Walls - Plaster/Drywall | Central | 642 | SF | 6 | \$1,772 | |
| ١ | Walls - Structural Glazed Tile | Central | 1,280 | SF | 7 | \$0 | |
| (| Ceiling - Plaster/Drywall | North | 122 | SF | 7 | \$0 | |
| (| Ceiling - Splined | North | 555 | SF | 6 | \$1,603 | |
| F | Floor - Terrazzo | North | 408 | SF | 7 | \$0 | |
| H | Handrails | North | 104 | LF | 7 | \$0 | |
| L | Lighting - Pendent/Surface | North | 10 | EA | 6 | \$1,239 | |
| 5 | Stairs - Terrazzo | North | 220 | LF | 7 | \$0 | |
| ١ | Walls - Plaster/Drywall | North | 662 | SF | 6 | \$1,827 | |
| ١ | Walls - Structural Glazed Tile | North | 1,326 | SF | 7 | \$0 | |
| (| Ceiling - Plaster/Drywall | South Stair | 122 | SF | 6 | \$893 | |
| (| Ceiling - Splined | South Stair | 555 | SF | 6 | \$1,603 | |
| F | Floor - Terrazzo | South Stair | 408 | SF | 7 | \$0 | |
| ŀ | Handrails | South Stair | 104 | LF | 7 | \$0 | |
| L | Lighting - Pendent/Surface | South Stair | 10 | EA | 7 | \$0 | |
| 5 | Stairs - Terrazzo | South Stair | 220 | LF | 7 | \$0 | |
| ١ | Walls - Plaster/Drywall | South Stair | 662 | SF | 6 | \$1,827 | |
| ١ | Walls - Structural Glazed Tile | South Stair | 1,326 | SF | 7 | \$0 | |
| ertical C | Conveyance | | | | | | |
| E | Elevator - Freight Elevator | | 1 | EA | 5 | \$86,984 | |
| uildin | g Interior Subtotal: | | | | | \$289,062 | |
| otal B | uilding Cost | | | | \$ | 1,781,477 | |
| | U | | | | | | |
| Buildin | g: Belmont-Cragin Pre-K | | | | | | |
| | ry: Building Exterior | | | | | | |
| Catego | | | | | | | |
| - | | Location | Quantity | Unit | Rank | Cost | Comments |
| roup l | item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| iroup l intrance | item - Type | Location CPC 1 | Quantity | Unit EA | Rank | Cost \$0 | Comments |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|--------------------------------|----------|------|------|------------------------|---------------|
| Entrand | ce | | | | | | |
| | Exterior Doors - Exterior Steel Door | CPC 2 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | CPC 1 | 3 | EA | 6 | \$940 | |
| | Exterior Doors - Store Front | CPC 1 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | CPC 3 | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | CPC 1 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | CPC 2 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | CPC 3 | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | CPC 3 | 2 | EA | 6 | \$627 | |
| re Es | cape | | | | | | |
| | Fire Escape | South Façade | 28 | LF | 5 | \$29,401 | |
| ounda | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 674 | LF | 7 | \$0 | |
| | Superstructure - Metal Deck/ Concrete Topping | Entire Building | 33,635 | SF | 7 | \$0 | |
| ghtin | g | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 1 | EA | 7 | \$0 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 2 | EA | 6 | \$577 | |
| oof S | ystem | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | J | 35 | LF | 6 | \$33,414 | |
| | Coping - Stone | I | 404 | LF | 7 | \$0 | |
| | Coping - Stone | J | 139 | LF | 6 | \$4,464 | |
| | Downspouts - Interior Downspouts | I | 72 | LF | 6 | \$2,393 | |
| | Downspouts - Interior Downspouts | J | 27 | LF | 5 | \$5,975 | |
| | Downspouts - Interior Downspouts | J | 54 | LF | 6 | \$1,795 | |
| | Parapet - Parapet < 16" Height | I | 404 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | J | 139 | LF | 6 | \$2,962 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | I | 9,633 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | J | 2,412 | SF | 7 | \$0 | |
| | Roof - EPDM/ Synthetic Rubber | I | 9,633 | SF | 5 | \$186,378 | TPO |
| | Roof - Modified Bitumen | J | 2,412 | SF | 5 | \$50,737 | |
| Valls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building / North Façade | 675 | SF | 6 | \$22,336 | |
| | Exterior Walls - Brick | Entire Building | 2,696 | SF | 6 | \$21,088 | |
| | Exterior Walls - Brick | Entire Building | 9,980 | SF | 7 | \$0 | |
| | Exterior Walls - Brick | Entire Building / South East | 40 | SF | 4 | C C C OC | step cracking |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

Category: Building Exterior

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--------------------------------|----------|------|------|----------|---------------------|
| indows | | | | | | |
| Lintels - Steel | Entire Building | 48 | LF | 4 | \$21,733 | warped and corroded |
| Lintels - Steel | Entire Building | 254 | LF | 5 | \$85,843 | |
| Windows - Casement Steel Double-pane | Entire Building | 1,424 | SF | 6 | \$10,630 | |
| Windows - Casement Steel Double-pane | Entire Building / South Façade | 64 | SF | 5 | \$6,278 | |
| Windows - Decorative | Entire Building | 232 | SF | 6 | \$1,732 | |
| Windows - Louver | Entire Building / East Façade | 5 | SF | 6 | \$37 | |

Building Exterior Subtotal:

\$499,859

Building: Belmont-Cragin Pre-K

| Category: Ele | ctrical | System |
|---------------|---------|--------|
|---------------|---------|--------|

| nk Cost | Comments |
|-----------|--|
| | |
| 2 \$1,158 | Not functional or worth repairing |
| 2 \$3,273 | No batteries or other source of backup power |
| 2 \$1,735 | No batteries or other source of backup power |
| | |
| \$3,570 | |
| | |
| 7 \$0 | |
| \$6,578 | |
| 5 \$O | |
| t | ہ چی \$16,313 |

Electrical System Subtotal:

Building: Belmont-Cragin Pre-K

Category: Safty System

| ıp Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------|----------------------------|----------|------|------|----------|---------------------------------------|
| Alarm | | | | | | |
| Fire Alarm Panel | Entire Building / Basement | 1 | EA | 4 | \$49,477 | Non-serviceable, but still functional |
| Fire Alarm_System | Entire Building | 33.635 | SF | 4 | \$66,856 | |

LY SYSLEI Subiola

Building: Belmont-Cragin Pre-K



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| ıp | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-----------------|----------|------|------|----------|---|
| lanc | lling Systems | | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water Coils - 2000 30000 cfm | - Basement | 1 | EA | 5 | \$70,185 | |
| | Air Intake | Basement | 1 | EA | 4 | \$17,616 | Outside air damper actuator linkage disconnect |
| | Auxiliaries | Basement | 1 | EA | 4 | \$0 | Unit is on/off - controls do not work |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons | g Roof | 2 | EA | 5 | \$50,304 | |
| er S | vstems | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 3001 - 4000 MBH | Boiler Room | 1 | EA | 5 | \$60,632 | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | \$374 | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH | Boiler Room | 1 | EA | 5 | \$81,580 | |
| | Water Fill System | Boiler Room | 1 | EA | 5 | \$5,828 | |
| ting | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EA | 2 | \$15,354 | Units are greater than 20 years of age, not functional, and not cost effective to be repaired |
| | Fin Tube - Hot Water | Entire Building | 276 | LF | 5 | \$22,473 | |
| npera | ature Control | | | | | | |
| | Electric Thermostat | Entire Building | 2 | EA | 7 | \$0 | |
| | Electric Thermostat | Entire Building | 1 | EA | 4 | \$0 | |
| tilati | on | | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 2 | EA | 6 | \$1,185 | |

Building: Belmont-Cragin Pre-K

Category: Plumbing System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-----------------|----------|------|------|----------|--------------------------|
| Hot Water | | | | | | |
| Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 5 | \$2,249 | |
| Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 3 | \$19,938 | Not working and corroded |
| Piping | | | | | | |
| Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 33,635 | SF | 4 | \$24,049 | |
| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 33,635 | SF | 4 | \$48,579 | |
| Domestic Piping-Cold Water Risers | Entire Building | 33,635 | SF | 4 | \$26,935 | |
| Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 33,635 | SF | 4 | \$18,277 | |
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | 33.635 | SF | 4 | \$43,288 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-----------------|----------|------|------|-----------|----------|
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 33,635 | SF | 4 | \$28,859 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 33,635 | SF | 4 | \$16,353 | |
| | Sanitary Piping | Entire Building | 33,635 | SF | 5 | \$0 | |
| | Storm Piping | Entire Building | 33,635 | SF | 5 | \$0 | |
| | Vent Piping | Entire Building | 33,635 | SF | 5 | \$0 | |
|) | ing Cratam Criptotol | | | | | ¢000 507 | |
| amur | ing System Subtotal: | | | | | \$228,527 | |

Building: Belmont-Cragin Pre-K

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|----------|----------|------|------|---------|-------------------------------------|
| Classro | om #001/002 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 6 | \$1,264 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | damaged veneer, finish and hardware |
| | Floor - Tile | | 850 | SF | 6 | \$1,860 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 900 | SF | 6 | \$2,638 | |
| Classro | om #004 (Art Room) | | | | | | |
| | Ceiling - Exposed | | 420 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | | 420 | SF | 6 | \$919 | |
| | Lighting - Pendent/Surface | | 7 | EA | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 7 | \$0 | |
| Classro | om #005 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 8 | LF | 4 | \$734 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed lenses |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 900 | SF | 6 | \$2,638 | |
| Classro | om #006 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

| uildi | ing: Belmont-Cragin Pre-K | | | | | | |
|--------|-----------------------------|----------|----------|------|------|---------|-----------------------------|
| ateg | jory: Classrooms | | | | | | |
| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| lassro | oom #006 (Pre School) | | | | | | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | damaged veneer and finish |
| | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed and cracked lenses |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 880 | SF | 6 | \$2,580 | |
| assro | oom #007 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed & chipped lenses |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 900 | SF | 6 | \$2,638 | |
| issro | oom #008 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 850 | SF | 6 | \$1,860 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed lenses |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 900 | SF | 6 | \$2,638 | |
| assro | oom #009 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer & finish |
| | Floor - Tile | | 850 | SF | 6 | \$1,860 | |
| | Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed & chipped lenses |
| | Storage/ Closet | | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | | 900 | SF | 7 | \$0 | |
| assro | oom #010 (Pre School) | | | | | | |
| | Ceiling - Exposed | | 850 | SF | 7 | \$0 | |
| | Chalk Board | | 12 | LF | 4 | \$1,102 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged veneer and finish |
| | Floor - Tile | | 850 | SF | 7 | \$0 | |
| | | | | | | | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

| ıp Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|----------|----------|------|------|---------|---------------------------|
| sroom #010 (Pre School) | | | | | | |
| Lighting - Pendent/Surface | | 21 | EA | 6 | \$2,602 | yellowed & cracked lenses |
| Storage/ Closet | | 10 | SF | 6 | \$73 | |
| Walls - Concrete Block | | 900 | SF | 6 | \$2,638 | |

Building: Belmont-Cragin Pre-K

| b Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|-----------------------------|----------|------|------|---------|-------------------------------------|
| nistrative Suites/Offices | | | | | | |
| Ceiling - Exposed | 003 Office | 400 | SF | 6 | \$595 | |
| Doors - Wood Doors inclu hw | 003 Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 003 Office | 400 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 003 Office | 7 | EA | 7 | \$0 | |
| Power Distribution | 003 Office | 8 | EA | 7 | \$0 | |
| Storage/ Closet | 003 Office | 10 | SF | 6 | \$73 | |
| Walls - Concrete Block | 003 Office | 726 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 120 | 415 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 120 | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 120 | 415 | SF | 4 | \$3,816 | warped, worn and zippering at seams |
| Lighting - Lay-in | 120 | 4 | EA | 7 | \$0 | |
| Power Distribution | 120 | 22 | EA | 7 | \$0 | |
| Walls - Concrete Block | 120 | 629 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 122 Library | 875 | SF | 6 | \$3,028 | some water damage |
| Doors - Wood Doors inclu hw | 122 Library | 2 | EA | 6 | \$602 | |
| Floor - Tile | 122 Library | 875 | SF | 6 | \$1,914 | mismatched tiles and minor cracks |
| Lighting - Pendent/Surface | 122 Library | 6 | EA | 6 | \$743 | |
| Power Distribution | 122 Library | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | 122 Library | 522 | SF | 6 | \$1,530 | |
| Walls - Plaster/Drywall | 122 Library | 522 | SF | 6 | \$1,441 | |
| Ceiling - Plaster/Drywall | 124 Teachers' Resource Room | 900 | SF | 6 | \$3,115 | |
| Doors - Wood Doors inclu hw | 124 Teachers' Resource Room | 2 | EA | 6 | \$602 | |
| Floor - Tile | 124 Teachers' Resource Room | 60 | SF | 4 | \$778 | cracked and chipped throughout |
| Floor - Tile | 124 Teachers' Resource Room | 840 | SF | 6 | \$1,838 | |
| Lighting - Pendent/Surface | 124 Teachers' Resource Room | 6 | EA | 6 | \$743 | |
| Power Distribution | 124 Teachers' Resource Room | 40 | EA | 7 | \$0 | |
| Storage/ Closet | 124 Teachers' Resource Room | 60 | SF | 5 | \$968 | damaged floor and wall |



Building: Belmont-Cragin Pre-K

Category: Rooms (Other Than Classrooms)

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|---|----------|------|------|----------|---|
| Adminis | strative Suites/Offices | | | | | | |
| | Walls - Concrete Block | 124 Teachers' Resource Room | 360 | SF | 6 | \$1,055 | |
| | Walls - Concrete Block | 124 Teachers' Resource Room | 150 | SF | 5 | \$1,810 | water damage |
| | Walls - Plaster/Drywall | 124 Teachers' Resource Room | 510 | SF | 5 | \$3,865 | |
| | AC Unit | 1st Floor Administrative Office (North) | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor Administrative Office (North) | 210 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor Administrative Office (North) | 1 | EA | 7 | \$0 | |
| | Floor - Wood | 1st Floor Administrative Office (North) | 210 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor Administrative Office (North) | 8 | EA | 6 | \$991 | |
| | Power Distribution | 1st Floor Administrative Office (North) | 6 | EA | 7 | \$0 | |
| | Walls - Masonry | 1st Floor Administrative Office (North) | 215 | SF | 7 | \$0 | |
| | Walls - Masonry | 1st Floor Administrative Office (North) | 215 | SF | 7 | \$0 | wood-faced masonry |
| | AC Unit | Main Office | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Main Office | 230 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Main Office | 1 | EA | 6 | \$301 | |
| | Floor - Wood | Main Office | 230 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Main Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | Main Office | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Main Office | 431 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Maint. / Engineer's Office | 72 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Maint. / Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Maint. / Engineer's Office | 72 | SF | 6 | \$158 | |
| | Lighting - Pendent/Surface | Maint. / Engineer's Office | 2 | EA | 5 | \$365 | insufficient illumination |
| | Power Distribution | Maint. / Engineer's Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Maint. / Engineer's Office | 213 | SF | 6 | \$624 | |
| | Walls - Masonry | Maint. / Engineer's Office | 90 | SF | 7 | \$0 | |
| Gymna | sia | | | | | | |
| | Ceiling - Exposed | 2nd Floor | 6,600 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 4 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 5 | \$4,696 | damaged hardware and finish |
| | Floor - Tile | 2nd Floor | 2,200 | SF | 6 | \$4,813 | |
| | Floor - Tile | 2nd Floor | 80 | SF | 4 | \$1,038 | cracked and chipped |
| | Floor - Wood | 2nd Floor | 4,320 | SF | 6 | \$30,456 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 2nd Floor | 10 | EA | 7 | \$0 | |
| | Scoreboards | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Stage-Stairs - Wood | 2nd Floor | 170 | LF | 4 | \$15,240 | Note: These are not stage stairs but rather stairs up to classrooms; damaged landing and treads; insufficient railing |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|---------------|----------|------|------|---------|--|
| ymna | sia | | | | | | |
| | Storage/ Closet | 2nd Floor | 75 | SF | 6 | \$544 | |
| | Walls - Concrete Block | 2nd Floor | 6,000 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,300 | SF | 7 | \$0 | |
| echar | nical/ Service Rooms | | | | | | |
| | Boiler Room | | 850 | SF | 7 | \$0 | |
| | Janitor's Closet | | 90 | SF | 6 | \$645 | |
| | Mechanical/ Service Rooms | | 1,050 | SF | 6 | \$7,523 | |
| | Storage Room | | 90 | SF | 6 | \$645 | under stair |
| estro | om | | | | | | |
| | Accessories | 1st Floor | 210 | SF | 6 | \$1,937 | mirror, toilet paper holder, soap dispenser |
| | Accessories | 1st Floor | 210 | SF | 6 | \$1,937 | damaged & missing, mirror, toilet paper holder |
| | Ceiling - Exposed | 1st Floor | 210 | SF | 6 | \$312 | |
| | Ceiling - Exposed | 1st Floor | 210 | SF | 6 | \$312 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | \$1,174 | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 210 | SF | 6 | \$444 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 100 | SF | 5 | \$1,842 | damaged & missing tile |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 110 | SF | 6 | \$233 | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | \$0 | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor | 3 | EA | 6 | \$959 | |
| | Lavatory | 1st Floor | 4 | EA | 5 | \$6,359 | damaged finish |
| | Lighting - Pendent/Surface | 1st Floor | 5 | EA | 6 | \$619 | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 1st Floor | 2 | EA | 5 | \$339 | rusted and not functioning |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 7 | \$0 | |
| | Partitions | 1st Floor | 4 | EA | 5 | \$3,003 | rusted partitions |
| | Partitions | 1st Floor | 6 | EA | 5 | \$4,505 | rusted partitions |
| | Urinals | 1st Floor | 3 | EA | 6 | \$1,008 | |
| | Walls - Concrete Block | 1st Floor | 663 | SF | 6 | \$1,944 | |
| | Walls - Concrete Block | 1st Floor | 663 | SF | 5 | \$6,807 | peeling paint |
| | Water Closet | 1st Floor | 6 | EA | 6 | \$2,016 | |
| | Water Closet | 1st Floor | 4 | EA | 6 | \$1,344 | |
| | Accessories | 2nd Floor Men | 134 | SF | 6 | \$1,236 | mirror, soap dispenser, toilet paper holder |
| | Ceiling - Plaster/Drywall | 2nd Floor Men | 134 | SF | 7 | \$0 | •••••• |



Building: Belmont-Cragin Pre-K

Category: Rooms (Other Than Classrooms)

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-----------------|----------|------|------|---------|---|
| Restro | om | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor Men | 2 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Men | 134 | SF | 6 | \$284 | |
| | Hand Dryer | 2nd Floor Men | 1 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor Men | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor Men | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 2nd Floor Men | 1 | EA | 6 | \$124 | |
| | Partitions | 2nd Floor Men | 3 | EA | 5 | \$2,253 | rusted partitions |
| | Urinals | 2nd Floor Men | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 2nd Floor Men | 374 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor Men | 2 | EA | 6 | \$672 | |
| | Accessories | 2nd Floor Women | 223 | SF | 6 | \$2,057 | mirror, soap dispenser, toilet paper holder |
| | Ceiling - Plaster/Drywall | 2nd Floor Women | 223 | SF | 6 | \$772 | |
| | Doors - Wood Doors inclu hw | 2nd Floor Women | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Women | 223 | SF | 6 | \$472 | |
| | Hand Dryer | 2nd Floor Women | 1 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor Women | 3 | EA | 5 | \$4,769 | |
| | Lighting - Pendent/Surface | 2nd Floor Women | 3 | EA | 6 | \$372 | |
| | Lighting - Wall Mounted | 2nd Floor Women | 2 | EA | 5 | \$339 | not functioning |
| | Partitions | 2nd Floor Women | 3 | EA | 5 | \$2,253 | rusting |
| | Walls - Concrete Block | 2nd Floor Women | 429 | SF | 6 | \$1,258 | |
| | Walls - Masonry | 2nd Floor Women | 108 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor Women | 3 | EA | 7 | \$0 | |

Rooms (Other Than Classrooms) Subtotal:

\$152,384

Building: Belmont-Cragin Pre-K

Category: Building Interior

| up Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-----------|----------|------|------|----------|------------------------------|
| ridor | | | | | | |
| Ceiling - Exposed | 1st Floor | 2,150 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | \$0 | |
| Doors - Store Front | 1st Floor | 8 | EA | 7 | \$0 | |
| Drinking Fountains - Single Water Cooler | 1st Floor | 3 | EA | 6 | \$950 | |
| Floor - Tile/Sheet | 1st Floor | 50 | SF | 4 | \$741 | cracked & chipped throughout |
| Floor - Tile/Sheet | 1st Floor | 2,100 | SF | 6 | \$1,141 | |
| Lighting - Pendent/Surface | 1st Floor | 26 | EA | 6 | \$3,221 | |
| Student Lockers - One Tier | 1st Floor | 131 | EA | 5 | \$18,360 | |



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Building: Belmont-Cragin Pre-K

Category: Building Interior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|--|----------|------|------|-----------|---|
| orridor | | | | | | |
| Walls - Concrete Block | 1st Floor | 2,688 | SF | 7 | \$0 | |
| Walls - Masonry | 1st Floor | 321 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 2nd Floor | 775 | SF | 6 | \$2,327 | some water stains/damage |
| Doors - Wood Doors include hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| Drinking Fountains - Single Water Cooler | 2nd Floor | 1 | EA | 6 | \$317 | |
| Floor - Tile/Sheet | 2nd Floor | 775 | SF | 5 | \$3,480 | |
| Lighting - Lay-in | 2nd Floor | 9 | EA | 5 | \$1,460 | insufficient illumination |
| Walls - Concrete Block | 2nd Floor | 1,293 | SF | 6 | \$3,790 | |
| Walls - Masonry | 2nd Floor | 249 | SF | 5 | \$10,290 | |
| airs | | | | | | |
| Ceiling - Exposed | East | 157 | SF | 6 | \$233 | |
| Floor - Tile | East | 73 | SF | 5 | \$328 | cracked, chipped, missing and damaged tiles |
| Handrails | East | 69 | LF | 4 | \$10,366 | missing railing |
| Lighting - Wall Mounted | East | 2 | EA | 5 | \$339 | not functioning |
| Stairs - Rubber | East | 63 | LF | 5 | \$1,262 | damaged surface and nosing |
| Walls - Concrete Block | East | 75 | SF | 5 | \$1,056 | cracks throughout |
| Walls - Concrete Block | East | 1,475 | SF | 6 | \$4,324 | |
| Stairs - Rubber | West | 241 | LF | 6 | \$2,592 | Note: Other stairway materials were captured the corridors. |
| uilding Interior Subtotal: | | | | | \$66,880 | |
| otal Building Cost | | | | \$ | 1,459,309 | |
| TE | | | | | | |
| ategory: Site | | | | | | |
| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| /il/Drainage | | | | | | |
| Civil/ Drainage - Catch Basin | Main- Entire Site / Parking Lot- North | 2 | EA | 7 | \$0 | |
| Civil/ Drainage - Site Drain | Main- Entire Site | 7 | EA | 5 | \$9,655 | |
| Civil/ Drainage - Site Manhole | Main- Entire Site | 6 | EA | 7 | \$0 | |
| ncing | | | | | | |
| Fencing - Chain Link | Main- Entire Site | 72 | LF | 7 | \$0 | generator |
| Fencing - Chain Link | Main- Entire Site / Parking Lot | 59 | LF | 5 | \$3,598 | |
| Fencing - Guard Rail | Main- Entire Site / North East | 69 | LF | 6 | \$797 | |
| Fencing - Iron and Concrete Post | Main- Entire Site / North West | 100 | LF | 4 | \$19,976 | iron and masonry- spalling, cracking, broken |
| DRTHWEST | Page 59 of 63 | | | | | Assessment Date: 9/ |



Category: Site

SITE

Northwest Middle School

5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

Cost Comments

Group Item - Type Fencing Fencing - New Standard Ornamental Main- Entire Site 307 1 F 6 \$9.794 Main- Entire Site / Site South 5 LF 5 \$712 Fencing - New Standard Ornamental LF Fencing - New Standard Ornamental Main- Entire Site / Site South 1 4 \$0 Main- Entire Site / Site South 253 LF 7 \$0 Fencing - New Standard Ornamental Landscape \$0 Landscape - Grass Main- Entire Site 19.270 SF 7 Landscape - Hardscape- Concrete Leased Site / Site North 180 SF 5 \$1.683 Main- Entire Site Landscape - Hardscape- Concrete 2.707 SF 7 \$0 Main- Entire Site / Site West SF 6 \$14,379 Landscape - Hardscape- Concrete 2.366 Landscape - Hardscape- Concrete Main- Entire Site / Site West 672 SF 5 \$7.371 Leased Site FA 7 \$0 Parkway trees 11 Parkway trees Leased Site / Site North 1 ΕA 4 \$2,624 stump 7 Main- Entire Site 27 ΕA \$0 Parkway trees 7 Planting Beds/ Area Main- Entire Site 2.354 SF \$0 site south, site east SF Retaining Wall - Concrete Main- Entire Site 2,205 6 \$51,680 **Trash Receptacles** Main- Entire Site 2 ΕA 6 \$625 Parking Lot Surface - Asphalt Leased Site- South 8,534 SF 5 \$44,543 Leased Site- South SF 7 Surface - Asphalt 19,090 \$0 Surface - Asphalt Main Site- North and Central 32,663 SF 7 \$0 Service Garage SF Service Garage - Built-in East ovm facade 989 6 \$9.080 Sidewalks Sidewalks - Internal Walks Main- Entire Site 9.520 LF 7 \$0 Sidewalks - Perimeter Sidewalks Leased Site SF 6 \$8,299 4.175 Signage ΕA 7 \$0 Flag Pole - Flag Pole Main- Entire Site 1 Marquee - Free Standing Back Lighted Leased Site-North 1 ΕA 7 \$0 Marquee - Free Standing Back lighted w/ LED Main- Entire Site 1 EA 6 \$0 Site Subtotal: \$184,816

Location

Total Site Cost

\$184,816

Quantity Unit Rank



5252 W Palmer St Chicago, IL 60639

Campus Total ^{2 3}

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

\$8,868,287

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



5252 W Palmer St Chicago, IL 60639

Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | | | | | | <u> </u> | | | 1 | | | 4 |
| Art Room | Art Room | | 008 | NA | 755 | 1 | 4 | 8 | 70 | | 40 | Ν | N | Ν |
| Office | Special Program | | 107 | R-101 | 438 | 1 | 0 | 6 | 56 | 12 | | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 101 | 123 | 677 | 1 | 0 | 4 | 130 | 25 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 102 | 122 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 103 | 121 | 785 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 104 | 112 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 105 | 108 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 106 | 106 | 677 | 1 | 0 | 4 | 130 | 25 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 201 | 220 | 677 | 1 | 0 | 4 | 130 | 25 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 202A & 202B | 219 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 203A & 203B | 215 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 204 | 214 | 709 | 1 | 0 | 4 | 130 | 25 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 205 | 214 | 709 | 1 | 0 | 4 | 158 | 30 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 207 | 203 | 677 | 1 | 0 | 6 | 130 | 25 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 210 | 213 | 986 | 1 | 0 | 4 | 204 | 40 | 40 | Ν | Y | Ν |
| Science | Science | | 208 | 205 | 1,267 | 1 | 0 | 4 | 232 | 45 | 40 | Ν | Y | Ν |
| Science | Regular Classroom | | 211 | 209 | 902 | 1 | 0 | 4 | 204 | 40 | 40 | Ν | Y | Ν |
| Special Education | Regular Classroom | | 209 | 216 | 355 | 1 | 0 | 4 | 84 | 15 | | Ν | Y | Ν |
| Special Program | | | 215 | R-201 | 438 | 1 | 0 | 6 | 56 | 12 | | Ν | Y | Ν |
| Addition | | | | | | | | | | | | | | |
| Computer Lab | Regular Classroom | | 108 | N-203 | 775 | 1 | 26 | 58 | 160 | 60 | 40 | Ν | Y | Ν |
| Computer Lab | Regular Classroom | | 109 | N-204 | 775 | 1 | 32 | 72 | 160 | 60 | 40 | Ν | Y | Ν |
| Music Room | Music Room | | 216 | N-321 | 830 | 1 | 1 | 8 | 80 | 30 | 40 | N | Y | Ν |
| Music Room | Music Room | | 218 | N-320 | 1,475 | 0 | 1 | 6 | 160 | 60 | 50 | N | N | Ν |
| Office | Regular Classroom | | 113 | N-208 | 775 | 1 | 0 | 26 | 160 | 60 | 40 | Ν | N | Ν |
| Office | Regular Classroom | | 214 | N-308 | 380 | 1 | 0 | 7 | 80 | 30 | 40 | N | Y | Ν |
| Regular Classroom | Faculty Lounge | | 10 | N-101 | 1,080 | 1 | 0 | 9 | 220 | 80 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | | 11 | N-103 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 110 | N-205 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 111 | N-206 | 850 | 1 | 0 | 7 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 112 | N-207 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 114 | N-217 | 850 | 1 | 0 | 6 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 115 | N-216 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 116 | N-215 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 117 | N-114 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | N | Y | Ν |
| Regular Classroom | Regular Classroom | | 118 | N-211 | 775 | 1 | 1 | 7 | 160 | 60 | 40 | N | Y | Ν |

Classroom Summary



Classroom Summary

Northwest Middle School

5252 W Palmer St Chicago, IL 60639 Co-locating on this campus are BELMONT-CRAGIN and NORTHWEST

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Addition | | | | • | | | | | | • | | | | |
| Regular Classroom | Regular Classroom | | 119 | N-210 | 850 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 12A | N-105 | 598 | 1 | 5 | 10 | 160 | 60 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 13 | N-107 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 14 | N-108 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | | 15 | N-110 | 850 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | | 16 | N-111 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | | 18 | N-117 | 767 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | N |
| Regular Classroom | Regular Classroom | | 19 | N-118 | 800 | 1 | 0 | 6 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 212 | N-307 | 775 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 213 | N-309 | 850 | 1 | 0 | 7 | 160 | 60 | 40 | Ν | Y | Ν |
| Science | Science | | 17A | N-114 | 775 | 1 | 2 | 10 | 160 | 60 | 40 | Ν | Y | Ν |
| | | | 12B | N-105 | 595 | 1 | 0 | 5 | 80 | 30 | 0 | Ν | Y | N |
| | | | 17B | N-114 | 775 | 1 | 32 | 41 | 160 | 60 | 50 | Ν | Y | Y |
| Belmont-Cragin F | Pre-K | | | | | | | | | | | | | |
| Art Room | Other Instructional Use | | 004 | | 420 | 1 | 0 | 4 | 60 | 15 | 40 | Ν | Y | Ν |
| Pre School | Other Instructional Use | | 001/002 | | 860 | 1 | 1 | 8 | 120 | 30 | 40 | Ν | N | N |
| Pre School | Other Instructional Use | | 005 | | 860 | 1 | 1 | 8 | 120 | 30 | 40 | Ν | Y | N |
| Pre School | Other Instructional Use | | 006 | | 860 | 1 | 0 | 8 | 120 | 30 | 40 | Ν | Y | N |
| Pre School | Other Instructional Use | | 007 | | 860 | 1 | 0 | 8 | 120 | 30 | 40 | Ν | N | N |
| Pre School | Other Instructional Use | | 008 | | 860 | 1 | 0 | 8 | 120 | 30 | 40 | Ν | Y | N |
| Pre School | Other Instructional Use | | 009 | | 860 | 1 | 0 | 9 | 120 | 30 | 0 | Ν | Y | N |
| Pre School | Other Instructional Use | | 010 | | 860 | 1 | 0 | 8 | 120 | 30 | 40 | Ν | Y | N |