2642 W 15th Pl Chicago, IL 60608

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1903	3	38,751	\$2,851,240
SITE				\$205,983
Campus Total			38,751	\$3,057,223

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Entrance Control - Audio and Video	1	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	1	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	2	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	2nd floor east fire escape / 2nd Floor	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	2nd floor west fire escape / 2nd Floor	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	3rd floor east fire escape / 3rd Floor	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	3rd floor west fire escape / 3rd Floor	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	5 / Entire Building	2	EA	6	\$961	peeling paint, scratches, dents
	Exterior Doors - Exterior Steel Door	6 / Entire Building	3	EΑ	6	\$1,442	peeling paint, dents, scratches
	Exterior Doors - Exterior Wood Door	3	1	EA	5	\$1,341	
	Exterior Doors - Exterior Wood Door	4 / Entire Building	1	EA	6	\$481	paint peeling, scratches, dents
	Exterior Stairs - Concrete	1 / Entire Building	18	LF	6	\$1,472	chipped nosings
	Exterior Stairs - Concrete	6 / Entire Building	9	LF	6	\$736	
Fire Esc	саре						
	Fire Escape	Entire Building / East Façade	60	LF	6	\$37,906	
	Fire Escape	Entire Building / West Façade	59	LF	5	\$61,951	corrosion
Founda	ition						
	Foundation - Masonry	Entire Building	470	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	38,751	SF	7	\$0	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lighting	9						
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	4	\$5,150	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	5	\$1,282	
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	\$3,465	
Roof Sy	/stem						
	Chimney - Brick Chimney- Stainless Steel Liner	A	70	LF	7	\$0	
	Coping - Clay Tile	Α	8	LF	5	\$784	chipped pieces of clay tile
	Coping - Clay Tile	A	172	LF	6	\$5,524	
	Coping - Clay Tile	В	224	LF	6	\$7,194	sealant cracking between pieces
	Coping - Clay Tile	С	36	LF	6	\$1,156	sealant between pieces cracking
	Coping - Terra Cotta	Α	116	LF	6	\$3,726	sealant between terra cotta pieces cracking
	Downspouts - Exterior Downspouts	A	124	LF	5	\$10,013	
	Downspouts - Exterior Downspouts	A	1	LF	4	\$135	gap in west downspout
	Downspouts - Exterior Downspouts	В	35	LF	5	\$2,826	
	Parapet - 16" - 30" Height	A	150	LF	5	\$25,952	
	Parapet - 16" - 30" Height	A / Entire Building	146	LF	4	\$98,644	bulging spalled brick
	Parapet - Parapet < 16" Height	В	160	LF	5	\$14,801	
	Parapet - Parapet < 16" Height	B / Central Courtyard	64	LF	4	\$37,195	open severely deteriorated joints
	Parapet - Parapet > 30"	С	17	LF	5	\$5,580	
	Parapet - Parapet > 30"	С	19	LF	4	\$16,978	open severely deteriorated joints
	Roof Structure - Heavy Timber	A	8,624	SF	7	\$0	
	Roof Structure - Heavy Timber	В	3,568	SF	7	\$0	
	Roof Structure - Heavy Timber	С	725	SF	7	\$0	
	Roof - Metal	A	64	SF	5	\$1,764	
	Roof - Modified Bitumen	A	8,560	SF	5	\$180,062	bubbling cracking at seams
	Roof - Modified Bitumen	В	3,268	SF	5	\$68,743	bubbling cracking at seams
	Roof - Modified Bitumen	B / West	300	SF	4	\$10,352	ponding
	Roof - Modified Bitumen	С	725	SF	5	\$15,251	bubbling cracking at seams
Walls							
	Cheek-Wall - Stone	Entire Building	20	SF	5	\$476	
	Cornice - Metal Projecting	Entire Building	512	LF	5	\$77,031	corroded, causing damage to interior spaces
	Exterior Walls - Brick	Entire Building	17,965	SF	5	\$319,326	deteriorated mortar joints and multiple areas of interior leaks at classroom
	Exterior Walls - Brick	Entire Building	10	SF	4	\$1,647	bulging
	Exterior Walls - Stone-Cut	Entire Building	3,544	SF	5		some open joints
Windov	vs.						
	Guard - Guards perforated	Entire Building	1,046	SF	6	\$13,357	

2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Windows						
Lintels - Brick	Entire Building	97	LF	7	\$0	north, east, west elevations
Lintels - Steel	Entire Building	279	LF	7	\$0	
Lintels - Steel	Entire Building / North Façade	4	LF	4	\$1,811	deflection
Lintels - Steel	Entire Building / North Façade	12	LF	7	\$0	
Lintels - Stone	Entire Building / South Façade	131	LF	7	\$0	
Windows - Louver	Entire Building / North Façade	20	SF	6	\$149	
Windows - Sash Aluminum Double-pane	Entire Building	2,840	SF	6	\$21,199	

Building Exterior Subtotal:

\$1,108,867

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Mechanical Room	1	EA	6	\$408	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,668	SF	6	\$2,303	No issues with lights according to engineer
	Emergency A/C Power - Gym	Entire Building / 3rd Floor	1,907	SF	6	\$709	No issues with lights according to engineer
	Emergency A/C Power - Lunchrooms	Entire Building / Basement	932	SF	6	\$347	No issues with lights according to engineer
	Emergency Battery Packs - Corridors and Stairs	Entire Building	10	EA	6	\$2,025	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	4	\$579	
	Emergency Battery Packs - Gym	Entire Building / 3rd Floor	1	EA	6	\$203	
	Emergency Battery Packs - Lunchrooms	Entire Building / Basement	1	EA	6	\$203	
	Exit Signs - Corridors and Stairs	Entire Building	23	EA	6	\$3,444	
	Exit Signs - Gym	Entire Building / 3rd Floor	3	EA	6	\$472	
	Exit Signs - Lunchroom	Entire Building / Basement	2	EA	6	\$299	
	Security System - Intrusion Detection	Entire Building	38,751	SF	6	\$9,975	
Main S	ervice						
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	6	\$2,921	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Mechanical Room	1	EA	7	\$0	
	PA System	Entire Building	38,751	SF	6	\$12,745	
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	15	EA	6	\$4,487	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	3	EA	6	\$1,583	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	Greater than 40 years of age



2642 W 15th PI Chicago, IL 60608

Building: Main

Category: Electrical System

Group Item - Type Location Quantity Unit Rank Cost Comments

Electrical System Subtotal: \$43,432

Building: Main

Category: Safty System

roup Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
ire Alarm							
Fire Alarm Pan	el	Mechanical Room	1	EA	4	\$49,477	
Fire Alarm Stro	be Lights	Mechanical Room / Entire Building	38,751	SF	4	\$52,643	
Fire Alarm_Sys	stem	Mechanical Room / Entire Building	38,751	SF	4	\$77,025	No strobes are installed, and panel is greater than 20 years of age and cannot be upgraded
Fire Pump Cor	ntroller	Mechanical Room	1	EA	4	\$23,389	No controller, its is a fire pump switch
ump Room Assembly	,						
Fire Pump - Le	ss than 25hp	Mechanical Room	1	EA	5	\$5,674	System leaks
Jockey Pump		Mechanical Room	1	EA	4	\$5,981	Pump is more than 30 years old
prinkler System							
Dry Sprinkler S	System	Entire Building	38,751	SF	4	\$52,643	There are significant system leaks
Sprinkler Head	s	Entire Building	38,751	SF	4	\$19,949	Heads are old
Sprinkler Pipin	g	Entire Building	38,751	SF	5	\$27,153	

Safty System Subtotal: \$313,934

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up- Multi Zone- Hot Water Coils - 25001 - 35000 cfm	Entire Building / Basement	1	EA	5	\$78,608	Engineer stated fan now runs well and can maintain all space temperatures
	Air Intake	Entire Building / 1st Floor	1	EA	2	\$17,616	There is space for 2 OA intakes. One is sealed with a window.
	Auxiliaries - 25001 - 35000 cfm	Entire Building / Basement	1	EA	5	\$16,577	Deteriorated housing walls, dampers need to be replaced/repaired
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Entire Building	100	LF	4	\$0	Return pulled through a door to the adjacent hall
	Zone Dampers	Entire Building / Basement	24	EA	4	\$115,025	Many actuators are disconnected. Dampers are deteriorated.
Boiler S	Systems						
	Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH	Boiler Room	7	EA	6	\$14,325	
	Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH	Boiler Room	6	EA	6	\$12,278	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler :	Systems						
	Combustion Dampers	Boiler Room	1	EA	7	\$0	
	Hot Water Pump	Boiler Room	2	EA	6	\$748	
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - Less than 500 MBH	Boiler Room	6	EA	6	\$5,987	
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - Less than 500 MBH	Boiler Room	7	EA	6	\$6,985	
Heating	g Devices						
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	5	\$7,019	
	Unit Heater - Electric	Mechanical Room	2	EA	6	\$556	
	Unit Heater - Hot Water	Boiler Room	1	EΑ	5	\$1,532	
	Wall Heater - Electric	Entire Building	10	EA	5	\$5,366	
Mecha	nical Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	250	LF	6	\$19,194	
Tempe	rature Control						
	Pneumatic System	Entire Building	38,751	SF	4	\$201,707	Pneumatic system is old. Original to building, and some controls do not work according to engineer.
	Thermostats - Pneumatic	Entire Building	24	EA	6	\$0	
Ventila	tion						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Mechanical Room	1	EA	7	\$0	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Lower Roof	2	EA	4	\$8,489	Fan greater than 15 years old
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	2	EA	4	\$8,489	Fan greater than 15 years old
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	3	\$4,245	Fan cover is off. Fan is inoperative
	Type I Exhaust Hood- Kitchen	Entire Building / Basement	1	EA	3	\$28,265	No fire suppression system

Mechanical System Subtotal:

\$553,010

Building: Main

Category: Plumbing System

	, , , , , , , , , , , , , , , , , , ,						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	ater						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	\$2,249	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	38,751	SF	6	\$7,758	Engineer said there were no longer leaks or clamps installed



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	38,751	SF	6	\$9,420	Engineer said there were no longer leaks or clamps installed
	Domestic Piping-Cold Water Risers	Entire Building	38,751	SF	6	\$7,204	Engineer said there were no longer leaks or clamps installed
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	38,751	SF	6	\$6,096	Engineer said there were no longer leaks or clamps installed
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	38,751	SF	6	\$7,204	Engineer said there were no longer leaks or clamps installed
	Domestic Piping-Hot Water Return Lines	Entire Building	38,751	SF	6	\$5,541	Engineer said there were no longer leaks or clamps installed
	Domestic Piping-Hot Water Return Risers	Entire Building	38,751	SF	6	\$5,541	Engineer said there were no longer leaks or clamps installed
	Sanitary Piping	Entire Building	38,751	SF	6	\$35,465	
	Storm Piping	Entire Building	38,751	SF	6	\$33,802	
	Vent Piping	Entire Building	38,751	SF	6	\$26,045	

Plumbing System Subtotal:

\$146,325

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #101 (Regular Classroom)						
	Ceiling - Splined	1st Floor	870	SF	6	\$709	Broken plaster and acoustical ceiling tiles apart
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	\$1,174	Subtantial damage
	Floor - Wood	1st Floor	870	SF	6	\$6,133	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	20	LF	6	\$428	
	Storage/ Closet	1st Floor	173	SF	5	\$2,791	Peeling paint
	Walls - Plaster/Drywall	1st Floor	2,026	SF	6	\$5,592	
Classro	oom #102 (Kindergarten)						
	Ceiling - Splined	1st Floor	853	SF	6	\$695	Broken plaster and acoustical ceiling tiles apart
	Chalk Board	1st Floor	12	LF	4	\$1,102	Partially covered
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	853	SF	6	\$854	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	



2642 W 15th Pl Chicago, IL 60608

Building: Main

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sroom #102 (Kindergarten)						
Marker Board	1st Floor	20	LF	6	\$428	
Storage/ Closet	1st Floor	171	SF	6	\$1,240	
Walls - Plaster/Drywall	1st Floor	1,455	SF	6	\$4,016	
sroom #104 (Kindergarten)						
Ceiling - Splined	1st Floor	850	SF	6	\$693	
Doors - Transom Window	1st Floor	9	SF	6	\$152	
Doors - Wood Doors inclu h	1st Floor	1	EA	5	\$1,174	
Floor - Tile/Sheet	1st Floor	850	SF	6	\$851	
Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
Marker Board	1st Floor	22	LF	6	\$471	
Storage/ Closet	1st Floor	84	SF	5	\$1,355	
Walls - Plaster/Drywall	1st Floor	1,465	SF	5	\$11,103	Water infiltration
Work Sink	1st Floor	1	EA	6	\$379	
sroom #105 (Computer Lab)						
Ceiling - Splined	1st Floor	875	SF	6	\$713	
Chalk Board	1st Floor	14	LF	4	\$1,285	
Doors - Transom Window	1st Floor	9	SF	6	\$152	
Doors - Wood Doors inclu h	1st Floor	1	EΑ	5	\$1,174	
Floor - Wood	1st Floor	875	SF	6	\$6,169	Discoloration and wear
Lighting - Pendent/Surface	1st Floor	14	EΑ	7	\$0	
Marker Board	1st Floor	13	LF	6	\$278	
Storage/ Closet	1st Floor	174	SF	5	\$2,807	Paint damage/extreme peeling
Walls - Plaster/Drywall	1st Floor	1,466	SF	6	\$4,046	
ssroom #201 (Regular Classroo	n)					
Ceiling - Splined	2nd Floor	870	SF	6	\$709	Broken plaster and acoustical ceiling tiles apa
Chalk Board	2nd Floor	12	LF	4	\$1,102	Obsolete material
Doors - Transom Window	2nd Floor	9	SF	6	\$152	
Doors - Wood Doors inclu h	2nd Floor	1	EA	6	\$301	
Floor - Wood	2nd Floor	870	SF	6	\$6,133	Discoloration and peelnig finish
Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
Marker Board	2nd Floor	22	LF	6	\$471	
Storage/ Closet	2nd Floor	173	SF	6	\$1,254	
Walls - Plaster/Drywall	2nd Floor	2,026	SF	5	\$15,355	Peeling paint and cracks
ssroom #202 (Regular Classroo	n)					
Ceiling - Splined	2nd Floor	875	SF	6	\$713	Water stains and broken acoustical ceiling tile



2642 W 15th Pl Chicago, IL 60608

Building: Main

•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #202 (Regular Classroom)						
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	\$1,174	Significant wear
	Floor - Wood	2nd Floor	875	SF	5	\$12,800	Large gaps between seams and discoloration
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	6	\$471	
	Storage/ Closet	2nd Floor	171	SF	6	\$1,240	
	Walls - Plaster/Drywall	2nd Floor	1,455	SF	5	\$11,027	Chipping and peeling paint
Classro	oom #203 (Library)						
	Casework	2nd Floor	28	LF	6	\$707	
	Ceiling - Plaster/Drywall	2nd Floor	488	SF	6	\$1,689	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	488	SF	6	\$3,440	Substantial wear and discoloration
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	6	\$129	
	Walls - Plaster/Drywall	2nd Floor	1,106	SF	6	\$3,052	Peeling paint and cracks
Classro	oom #204 (Regular Classroom)						
	Ceiling - Plaster/Drywall		875	SF	6	\$3,028	
	Chalk Board		44	LF	4	\$4,039	Partially covered
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EΑ	6	\$301	
	Floor - Wood		875	SF	5	\$12,800	Substantial wear and discoloration
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		13	LF	6	\$278	
	Storage/ Closet		174	SF	5	\$2,807	Peeling paint throughout
	Walls - Plaster/Drywall		1,426	SF	5	\$10,808	Peeling paint and cracks throughout
	Walls - Plaster/Drywall		40	SF	4	\$588	Significant water damage near north west corner
Classro	oom #205 (Regular Classroom)						
	Ceiling - Splined	2nd Floor	875	SF	6	\$713	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	875	SF	5	\$12,800	Significant wear and large gap between seams
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	6	\$471	
	Storage/ Closet	2nd Floor	174	SF	6	\$1,262	
	DAIDON	David 0 414					A



2642 W 15th Pl Chicago, IL 60608

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #205 (Regular Classroom)						
	Walls - Plaster/Drywall	2nd Floor	1,466	SF	5	\$11,111	Significant paint peeling
Classro	n #205 (Regular Classroom) /alls - Plaster/Drywall n #301 (Regular Classroom) asework eiling - Splined eiling - Splined halk Board oors - Transom Window oors - Wood Doors inclu hw loor - Wood ighting - Pendent/Surface larker Board torage/ Closet /alls - Plaster/Drywall n #302 (Regular Classroom) eiling - Splined halk Board oors - Transom Window oors - Wood Doors inclu hw loor - Wood ighting - Pendent/Surface larker Board torage/ Closet /alls - Plaster/Drywall loor - Wood ighting - Pendent/Surface larker Board torage/ Closet /alls - Plaster/Drywall n #304 (Regular Classroom)						
	Casework	3rd Floor	8	LF	5	\$1,673	Inside storage space
	Ceiling - Splined	3rd Floor	26	SF	4	\$365	Loose and broken acoustical ceiling tiles
	Ceiling - Splined	3rd Floor	820	SF	6	\$668	
	Chalk Board	3rd Floor	52	LF	4	\$4,774	Partially covered
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	846	SF	6	\$5,964	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	13	LF	6	\$278	
	Storage/ Closet	3rd Floor	173	SF	6	\$1,254	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	\$3,974	Chipping paint
Classro	oom #302 (Regular Classroom)						
	Ceiling - Splined	3rd Floor	875	SF	6	\$713	
	Chalk Board	3rd Floor	13	LF	4	\$1,193	Obsolete material
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Floor - Wood	3rd Floor	875	SF	5	\$12,800	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	22	LF	6	\$471	
	Storage/ Closet	3rd Floor	175	SF	5	\$2,823	Significant peeling paint and water infiltration damage
	Walls - Plaster/Drywall	3rd Floor	1,466	SF	5	\$11,111	amago
Classro	oom #304 (Regular Classroom)						
	Ceiling - Splined	3rd Floor	10	SF	4	\$141	Loose and broken acoustical ceiling tiles
	Ceiling - Splined	3rd Floor	865	SF	6	\$705	
	Chalk Board	3rd Floor	22	LF	4	\$2,020	Partially covered
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	Considerable wear
	Floor - Wood	3rd Floor	875	SF	5	\$12,800	Substantial wear, cracks and discoloration
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	22	LF	6	\$471	
	Storage/ Closet	3rd Floor	174	SF	5	\$2,807	Water damage and cracks
	Walls - Plaster/Drywall	3rd Floor	1,416	SF	6	\$3,908	-
	Walls - Plaster/Drywall	3rd Floor	50	SF	4		Severe water damage near N/W corner



2642 W 15th PI Chicago, IL 60608

Building: Main

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments

Classrooms Subtotal: \$262,413

Building: Main

Administrative Suites/Offices Ceiling - Exposed Basement - Counselor's Office 139 SF 5 \$382 Peeling pair pair pair pair pair pair pair pair	int
Doors - Wood Doors inclu hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Basement - Counselor's Office Basement - Counselor's Office Basement - Counselor's Office Walls - Walls - Masonry Basement - Counselor's Office Walls - Walls - Masonry Basement - Multipurpose room Basement - Multipurpose r	int
Floor - Tile/Sheet Lighting - Pendent/Surface Basement - Counselor's Office Basement - Multipurpose room	III K
Lighting - Pendent/Surface Walls - Concrete Block Basement - Counselor's Office Walls - Masonry Basement - Counselor's Office Basement - Multipurpose room Basement - Multipur	
Walls - Concrete Block Walls - Masonry Basement - Counselor's Office 234 SF 6 \$686 Walls - Masonry Basement - Counselor's Office 234 SF 5 \$9,671 Ceiling - Exposed Basement - Multipurpose room 330 SF 5 \$906 Peeling pai Doors - Wood Doors inclu hw Basement - Multipurpose room 1 EA 6 \$301 Floor - Tile/Sheet Basement - Multipurpose room 330 SF 6 \$330 Lighting - Pendent/Surface Basement - Multipurpose room 5 EA 6 \$619 Missing lar Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	
Walls - Masonry Basement - Counselor's Office 234 SF 5 \$9,671 Ceiling - Exposed Basement - Multipurpose room 330 SF 5 \$906 Peeling pai Doors - Wood Doors inclu hw Basement - Multipurpose room 1 EA 6 \$301 Floor - Tile/Sheet Basement - Multipurpose room 330 SF 6 \$330 Lighting - Pendent/Surface Basement - Multipurpose room 5 EA 6 \$619 Missing lar Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	
Ceiling - Exposed Basement - Multipurpose room 330 SF 5 \$906 Peeling pair Doors - Wood Doors inclu hw Basement - Multipurpose room 1 EA 6 \$301 Floor - Tile/Sheet Basement - Multipurpose room 330 SF 6 \$330 Lighting - Pendent/Surface Basement - Multipurpose room 5 EA 6 \$619 Missing lar Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	
Doors - Wood Doors inclu hwBasement - Multipurpose room1EA6\$301Floor - Tile/SheetBasement - Multipurpose room330SF6\$330Lighting - Pendent/SurfaceBasement - Multipurpose room5EA6\$619Missing larWalls - MasonryBasement - Multipurpose room657SF6\$2,067AC UnitBasement1EA6\$496Ceiling - ExposedBasement152SF6\$226	
Floor - Tile/Sheet Basement - Multipurpose room 330 SF 6 \$330 Lighting - Pendent/Surface Basement - Multipurpose room 5 EA 6 \$619 Missing lar Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	int
Lighting - Pendent/Surface Basement - Multipurpose room 5 EA 6 \$619 Missing lar Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	
Walls - Masonry Basement - Multipurpose room 657 SF 6 \$2,067 AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	
AC Unit Basement 1 EA 6 \$496 Ceiling - Exposed Basement 152 SF 6 \$226	mp lense
Ceiling - Exposed Basement 152 SF 6 \$226	
, T	
Doors - Steel Doors incl hw Basement 1 EA 6 \$301	
Floor - Epoxy/ Painted Basement 152 SF 6 \$80	
Lighting - Pendent/Surface Basement 2 EA 6 \$248	
Walls - Concrete Block Basement 160 SF 6 \$469	
Walls - Masonry Basement 459 SF 5 \$18,969	
AC Unit Mezzanine - Main office 1 EA 6 \$496	
Ceiling - Plaster/Drywall Mezzanine - Main office 307 SF 6 \$1,062	
Doors - Wood Doors inclu hw Mezzanine - Main office 1 EA 6 \$301	
Floor - Carpet Mezzanine - Main office 307 SF 6 \$654	
Lighting - Pendent/Surface Mezzanine - Main office 5 EA 7 \$0	
Walls - Plaster/Drywall Mezzanine - Main office 178 SF 6 \$583	
Walls - Plaster/Drywall Mezzanine - Main office 356 SF 6 \$983 Wood parti	ition walls
AC Unit Mezzanine - Principals Office 1 EA 6 \$496	
Ceiling - Exposed Mezzanine - Principals Office 163 SF 5 \$448 Paint peelir	ng
Doors - Wood Doors inclu hw Mezzanine - Principals Office 1 EA 6 \$301	
Floor - Carpet Mezzanine - Principals Office 163 SF 6 \$347	
Lighting - Pendent/Surface Mezzanine - Principals Office 4 EA 6 \$496 Missing lar	and the same
Walls - Plaster/Drywall Mezzanine - Principals Office 236 SF 6 \$651 Wooden w	mp ienses



2642 W 15th Pl Chicago, IL 60608

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Walls - Plaster/Drywall	Mezzanine - Principals Office	118	SF	6	\$386	
Gymna	sia						
~,·····	Ceiling - Plaster/Drywall	3rd Floor	1,907	SF	6	\$10.526	Tin Ceiling, Significant paint damage
	Doors - Transom Window	3rd Floor	27	SF	6	\$457	3, 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
	Doors - Wood Doors inclu hw	3rd Floor	3	EΑ	5	\$3,522	
	Floor - Wood	3rd Floor	1,907	SF	4	\$55,195	Substantial wear, dents, cracks, discoloration and
							gaps between seams
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	7	\$0	
	Storage/ Closet	3rd Floor	174	SF	5	\$2,807	Substantial damage in walls & floor
	Walls - Plaster/Drywall	3rd Floor	2,024	SF	6	\$5,586	Wear damage and peeling paint
Library							
	Ceiling - Plaster/Drywall	Basement	846	SF	6	\$2,928	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	\$301	
	Floor - Carpet	Basement	846	SF	6	\$1,803	
	Lighting - Pendent/Surface	Basement	9	EΑ	7	\$0	
	Walls - Masonry	Basement	1,018	SF	6	\$3,203	
Lunch	& Multipurpose Room						
	Ceiling - Exposed	Basement	932	SF	6	\$1,386	
	Doors - Steel Doors incl hw	Basement	3	EΑ	6	\$903	
	Floor - Epoxy/ Painted	Basement	932	SF	6	\$493	
	Lighting - Pendent/Surface	Basement	15	EA	7	\$0	
	Lighting - Wall Mounted	Basement	1	EΑ	7	\$0	
	Serving Line	Basement	15	LF	7	\$0	
	Walls - Masonry	Basement	1,158	SF	6	\$3,643	Chipped paint
	Ceiling - Exposed	Boys Play Room	1,106	SF	6	\$1,645	
	Doors - Steel Doors incl hw	Boys Play Room	1	EΑ	6	\$301	
	Floor - Epoxy/ Painted	Boys Play Room	1,106	SF	6	\$585	
	Lighting - Pendent/Surface	Boys Play Room	14	EΑ	6	\$1,735	
	Walls - Masonry	Boys Play Room	1,774	SF	6	\$5,581	Chipped paint
Mechar	nical/ Service Rooms						
	Janitor's Closet	1st Flr Janitors Closet	7	SF	6	\$50	
	Janitor's Closet	2nd Flr Janitors Closet	7	SF	6	\$50	
	Janitor's Closet	3rd Flr Janitors Closet	7	SF	6	\$50	
	Mechanical/ Service Rooms	Basement - Engine room	270	SF	6	\$1,934	
	Mechanical/ Service Rooms	Basement - Pump Room	140	SF	6	\$1,003	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Outcg	ory: Rooms (Other Than Classrooms)						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	nical/ Service Rooms						
	Boiler Room	Basement - Boiler Room	1,169	SF	5	\$18,856	
	Storage Room	Basement - Storage near boiler room	140	SF	6	\$1,003	
Restro	om						
	Accessories	1st Floor - Mens Toilet	54	SF	6	\$498	Mirror, paper towel dispenser and toilet paper holder
	Ceiling - Plaster/Drywall	1st Floor - Mens Toilet	54	SF	6	\$187	
	Doors - Wood Doors inclu hw	1st Floor - Mens Toilet	1	EΑ	6	\$301	
	Floor Drain	1st Floor - Mens Toilet	1	EA	6	\$1,059	
	Floor - Tile	1st Floor - Mens Toilet	54	SF	6	\$118	
	Lavatory	1st Floor - Mens Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor - Mens Toilet	1	EA	7	\$0	
	Partitions	1st Floor - Mens Toilet	1	EA	6	\$297	
	Walls - Plaster/Drywall	1st Floor - Mens Toilet	315	SF	6	\$869	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Mens Toilet	60	SF	6	\$136	
	Water Closet	1st Floor - Mens Toilet	1	EΑ	6	\$336	
	Ceiling - Plaster/Drywall	1st Floor - Womens Toilet	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	1st Floor - Womens Toilet	1	EA	6	\$301	
	Floor Drain	1st Floor - Womens Toilet	1	EΑ	6	\$1,059	
	Floor - Tile	1st Floor - Womens Toilet	60	SF	5	\$269	
	Lavatory	1st Floor - Womens Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor - Womens Toilet	1	EA	7	\$0	
	Partitions	1st Floor - Womens Toilet	2	EΑ	6	\$594	
	Walls - Plaster/Drywall	1st Floor - Womens Toilet	296	SF	6	\$817	
	Water Closet	1st Floor - Womens Toilet	2	EA	6	\$672	
	Accessories	2nd Floor	108	SF	6	\$996	
	Ceiling - Plaster/Drywall	2nd Floor	75	SF	6	\$260	
	Ceiling - Plaster/Drywall	2nd Floor	108	SF	6	\$374	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile	2nd Floor	75	SF	6	\$164	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	108	SF	6	\$229	Damage tiles
	Lavatory	2nd Floor	1	EA	6	\$320	-
	Lavatory	2nd Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	\$0	
	Partitions	2nd Floor	2	EA	6	\$594	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	om						
	Urinals	2nd Floor	2	EA	6	\$672	
	Walls - Plaster/Drywall	2nd Floor	80	SF	6	\$221	
	Walls - Plaster/Drywall	2nd Floor	66	SF	6	\$182	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	210	SF	6	\$474	Damage tiles near lavatory
	Walls - Tile Ceramic/ Porcelain	2nd Floor	219	SF	6	\$495	
	Water Closet	2nd Floor	1	EA	6	\$336	
	Water Closet	2nd Floor	2	EA	6	\$672	
	Accessories	Basement	615	SF	6	\$5,672	One broken paper dispenser
	Ceiling - Exposed	Basement	615	SF	6	\$915	
	Ceiling - Exposed	Basement	615	SF	6	\$915	
	Doors - Steel Doors incl hw	Basement	2	EA	6	\$602	
	Doors - Steel Doors incl hw	Basement	2	EA	6	\$602	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor Drain	Basement	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement	615	SF	6	\$1,302	Cracked tiles near south wall
	Floor - Tile Ceramic/ Porcelain	Basement	615	SF	6	\$1,302	Broken tiles near lavatories
	Hand Dryer	Basement	2	EA	6	\$460	
	Lavatory	Basement	2	EA	6	\$639	
	Lavatory	Basement	2	EA	6	\$639	
	Lighting - Pendent/Surface	Basement	12	EA	6	\$1,487	Missing lamp lense
	Lighting - Pendent/Surface	Basement	10	EA	7	\$0	
	Partitions	Basement	12	EA	6	\$3,563	
	Partitions	Basement	2	EA	6	\$594	
	Urinals	Basement	8	EA	6	\$2,688	
	Walls - Masonry	Basement	925	SF	5		Step cracking
	Walls - Masonry	Basement	925	SF	6	\$2,910	
	Water Closet	Basement	12	EA	6	\$4,032	
	Water Closet	Basement	3	EA	6	\$1,008	
	Accessories	Mezzanine - Office Toilet	44	SF	6	\$406	Mirror, soap dispenser, paper towel dispenser and toilet paper holder.
	Ceiling - Plaster/Drywall	Mezzanine - Office Toilet	44	SF	6	\$152	
	Doors - Wood Doors inclu hw	Mezzanine - Office Toilet	1	EA	6	\$301	
	Floor Drain	Mezzanine - Office Toilet	1	EA	6	\$1,059	
	Floor - Tile	Mezzanine - Office Toilet	44	SF	6	\$96	
	Lavatory	Mezzanine - Office Toilet	1	EA	6	\$320	
	Lighting - Pendent/Surface	Mezzanine - Office Toilet	1	EA	7	\$0	
	Partitions	Mezzanine - Office Toilet	1	EA	6	\$297	
	Walls - Plaster/Drywall	Mezzanine - Office Toilet	197	SF	6	\$544	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Rooms (Other Than Classrooms)

Group Item -	Туре	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
Walls	- Plaster/Drywall	Mezzanine - Office Toilet	98	SF	6	\$321	Wood partition wall
Water	Closet	Mezzanine - Office Toilet	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$259,533

Building: Main

Category: Building Interior

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rrido	•						
	Ceiling - Plaster/Drywall	1st Floor	835	SF	6	\$5,170	
	Floor - Epoxy/ Painted	1st Floor	835	SF	6	\$442	
	Lighting - Pendent/Surface	1st Floor	7	EA	6	\$867	
	Walls - Plaster/Drywall	1st Floor	357	SF	6	\$1,583	
	Ceiling - Splined	2nd Floor	1,660	SF	6	\$4,795	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	\$602	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	6	\$276	
	Floor - Epoxy/ Painted	2nd Floor	1,660	SF	6	\$878	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,436	SF	6	\$6,366	Peeling paint and water damage near south windows
	Ceiling - Splined	3rd Floor	1,660	SF	6	\$4,795	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	\$602	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	6	\$276	
	Floor - Wood	3rd Floor	1,660	SF	5	\$24,284	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,436	SF	5	\$10,596	Chipped corners near exit doors and cracking throughout
	Ceiling - Exposed	Basement - East Corridor / Basement	710	SF	5	\$1,949	Water filtration damage
	Doors - Transom Window	Basement - East Corridor / Basement	40	EA	6	\$677	
	Doors - Wood Doors include hw	Basement - East Corridor / Basement	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	Basement - East Corridor / Basement	710	SF	6	\$345	
	Lighting - Pendent/Surface	Basement - East Corridor / Basement	11	EA	6	\$1,363	Missing lenses
	Walls - Masonry	Basement - East Corridor / Basement	958	SF	5	\$39,591	Water damage
	Ceiling - Exposed	Basement - East Entry / Basement	325	SF	6	\$483	Chipping paint
	Doors - Steel Doors incl hw	Basement - East Entry / Basement	1	EA	6	\$301	
	Floor - Epoxy/ Painted	Basement - East Entry / Basement	325	SF	6	\$172	
	Lighting - Pendent/Surface	Basement - East Entry / Basement	4	EA	7	\$0	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Building Interior

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	••	Location	Quantity	Oilit	IVALIK	COSI	Comments
Ooma	Stairs - Concrete Stairs	Basement - East Entry / Basement	59	LF	6	\$489	
	Walls - Masonry	Basement - East Entry / Basement	616	SF	6	\$1,938	
	Ceiling - Exposed	Basement - West Corridor / Basement	308	SF	6	\$458	
	Floor - Epoxy/ Painted	Basement - West Corridor / Basement		SF	6	\$163	
			308			\$372	
	Lighting - Pendent/Surface	Basement - West Corridor / Basement	3	EA	6		
	Walls - Masonry	Basement - West Corridor / Basement	474	SF	6	\$1,491	
	Ceiling - Exposed	Basement - West Entry / Basement	325	SF	6	\$483	
	Doors - Steel Doors incl hw	Basement - West Entry / Basement	1	EA	6	\$301	
	Floor - Epoxy/ Painted	Basement - West Entry / Basement	325	SF	6	\$172	
	Lighting - Pendent/Surface	Basement - West Entry / Basement	4	EA	7	\$0	
	Stairs - Concrete Stairs	Basement - West Entry / Basement	59	LF	6	\$489	
	Walls - Masonry	Basement - West Entry / Basement	616	SF	6	\$1,938	
Stairs							
	Ceiling - Plaster/Drywall	East Stairs	398	SF	6	\$2,914	
	Floor - Epoxy/ Painted	East Stairs	398	SF	6	\$211	Chip paint
	Handrails	East Stairs	48	LF	6	\$416	
	Lighting - Pendent/Surface	East Stairs	2	EA	7	\$0	
	Lighting - Wall Mounted	East Stairs	4	EA	6	\$496	Peel paint
	Stairs - Concrete	East Stairs	124	LF	6	\$1,028	•
	Walls - Plaster/Drywall	East Stairs	854	SF	6	\$2,357	3 Stl and 4 Wd doors in vest. area
	Ceiling - Plaster/Drywall	Main Entrance Stairs / 1st Floor	690	SF	6	\$5,052	
	Floor - Epoxy/ Painted	Main Entrance Stairs / 1st Floor	690	SF	6		Metal piece on the ground
	Handrails	Main Entrance Stairs / 1st Floor	90	LF	6	\$780	
	Lighting - Pendent/Surface	Main Entrance Stairs / 1st Floor	4	EA	7	\$0	
	Stairs - Wood	Main Entrance Stairs / 1st Floor	322	LF	7	\$0	
	Walls - Plaster/Drywall	Main Entrance Stairs / 1st Floor	815	SF	6	\$2,249	
	Ceiling - Plaster/Drywall	Main/North Stairs	310	SF	6	\$2,270	
	Floor - Epoxy/ Painted	Main/North Stairs	359	SF	6	\$190	
	Handrails	Main/North Stairs	156	LF	6	\$1,352	
	Lighting - Pendent/Surface	Main/North Stairs	8	EA	7	\$0	
	Stairs - Concrete	Main/North Stairs	1,950	LF	6	\$16,173	
	Walls - Plaster/Drywall	Main/North Stairs	2,151	SF	6	\$5,937	
	Ceiling - Plaster/Drywall	West Stairs	398	SF	6	\$2,914	
	Floor - Epoxy/ Painted	West Stairs	398	SF	6	\$2,314	
	Handrails	West Stairs	48	LF	6	\$416	
	Lighting - Pendent/Surface	West Stairs	40	EA	7	\$0	
	Lighting - Wall Mounted	West Stairs	4	EA	7 7	\$0 \$0	
	Lighting - waii Mounted	WEST STAILS	4	EA	,	Φ0	



2642 W 15th Pl Chicago, IL 60608

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Stairs - Concrete	West Stairs	124	LF	6	\$1,028	Ероху
	Walls - Plaster/Drywall	West Stairs	854		6	\$2,357	3 Stl door and 4 wd doors in vestibule area
Buildi	ng Interior Subtotal:				\$	163,724	

Total Building Cost \$2,851,240

SITE

Category: Site

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Drainage						
Civil/ Drainage - Site Drain	Entire Site / North West	1	EA	6	\$310	
Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	\$10,449	
Fencing						
Fencing - Chain Link	Entire Site	439	LF	5	\$26,774	all chain link bent, corroded
Fencing - Old Standard Ornamental	Entire Site	330	LF	6	\$17,083	
Landscape						
Landscape - Hardscape- Concrete	Entire Site	384	SF	6	\$1,982	
Play Area - Asphalt/ Hardscape	Entire Site / Site West	5,037	SF	5	\$22,977	cracking, sink/potholes
Parking Lot						
Surface - Asphalt	North	9,375	SF	4	\$74,003	lines faded, cracks, potholes; per engineer to be replaced summer 2014
Playground						
Equipment - School Age 5-12	Entire Site	1	EA	6	\$3,546	
Surface - Square Rubber Mats	Entire Site	2,695	SF	6	\$14,529	some warping, overall good condition
Sidewalks						
Sidewalks - Perimeter Sidewalks	Entire Site	4,120	SF	6	\$8,189	south, west
Sidewalks - Perimeter Sidewalks	Entire Site / Site West	2,000	SF	4	\$26,140	broken up, trip hazards, south side has 4x4 holes where trees were planted
Site Subtotal:					\$205,983	

Total Site Cost \$205,983



2642 W 15th Pl Chicago, IL 60608

Campus Total ^{2 3} \$3,057,223

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



2642 W 15th Pl Chicago, IL 60608

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main		-		!				· · · · · · · · · · · · · · · · · · ·						+
Computer Lab	Regular Classroom	1st Floor	105	105	1,049	1	18	44	135	67	40	N	N	N
Kindergarten	Regular Classroom	1st Floor	102	102	1,024	1	7	26	192	96	40	Υ	Υ	N
Kindergarten	Kindergarten	1st Floor	104	104	934	1	6	26	192	96	40	N	Υ	N
Library	Regular Classroom	2nd Floor	203	203	488	1	8	19	75	33	40	Υ	Υ	N
Regular Classroom	Regular Classroom	1st Floor	101	101	1,043	1	4	26	135	67	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,043	1	4	26	135	67	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,046	1	7	16	144	72	40	Υ	Υ	N
Regular Classroom	Regular Classroom		204	204	1,049	1	9	26	144	72	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,049	1	7	28	135	72	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	1,019	1	8	22	85	42	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	1,050	1	7	24	144	72	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,049	1	9	26	144	72	40	Υ	Υ	N