

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1958 | 1 | 26,642 |
| Branch 1_Rosenwald | 1951 | 1 | 11,838 |
| Branch 2_Rosenwald Carroll | 1996 | 2 | 47,154 |
| Campus Total | | | 85,634 |

| Catego | ry : Exterior | В | | | | | |
|----------|--------------------------------------|----------|----------|-----|------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | | | | | | | |
| | Exterior Doors - Exterior FRP Door | 1 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | 1 | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 1 | 1 | EA | 7 | 10+ years | |
| | Entrance Control - Audio and Video | 2 | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Side lite | 2 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | 2 | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 2 | 4 | EA | 6 | 10+ years | |
| | Power Door Operator and Controls | 2 | 1 | EA | 4 | 0-1 year | Does not operate |
| | Entrance Control - Audio | 3 | 1 | EA | 6 | 6-10 years | - |
| | Exterior Doors - Exterior FRP Door | 3 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | 3 | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 3 | 1 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 3 | 18 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 3 | 12 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | 4 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 4 | 8 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | 5 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | 6 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 6 | 8 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 7 | 1 | EA | 4 | 2-5 years | Door frame showing significant signs of wear and damage |
| | Exterior Stairs - Concrete | 7 | 52 | LF | 7 | 10+ years | Ŭ |



| - | schools | | | | | | 2929 W 83rd STREET, Chicago, IL 6065 |
|----------|--|-----------------|----------|-----|------|-------------|--------------------------------------|
| Catego | ry : Exterior | | В | | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Stair Handrail - Steel_Stair Handrail | 7 | 12 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Mechanical | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | Vault | 1 | EA | 5 | 2-5 years | |
| Foundati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 271 | LF | 7 | 10+ years | |
| | Superstructure - Metal Deck/ Concrete Topping | Entire Building | 26,642 | SF | 7 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 7 | EA | 7 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 12 | EA | 7 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 1 | EA | 5 | 2-5 years | |
| Roof Sys | stem | | | | | | |
| | Coping - Metal | A | 110 | LF | 5 | 6-10 years | |
| | Downspouts - Exterior Downspouts | A | 80 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | A | 4,785 | SF | 5 | 6-10 years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | А | 4,785 | SF | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | В | 20 | LF | 6 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | В | 2 | LF | 5 | 6-10 years | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | В | 18 | LF | 5 | 6-10 years | |
| | Coping - Metal | В | 654 | LF | 5 | 6-10 years | |
| | Downspouts - Interior Downspouts | В | 88 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | B | 654 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | B | 10,000 | SF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | В | 7,072 | SF | 5 | 6-10 years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | В | 17,072 | SF | 7 | 10+ years | |
| Walls | | | | | | | |
| | Canopy - Metal | Entire Building | 267 | SF | 5 | 6-10 years | |
| | Exterior Walls - Brick | Entire Building | 8,965 | SF | 6 | 10+ years | |
| Windows | 3 | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 320 | SF | 6 | 10+ years | |
| | Guard - Guards wire guard | Entire Building | 3,520 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 614 | LF | 6 | 10+ years | |
| | Windows - Casement Aluminum Double- | Entire Building | 3,520 | SF | 6 | 10+ years | |



| Alla | Schools | | | | | | 2929 W 83rd STREET, Chicago, IL 6065 |
|-----------|--|-----------------|----------|---------|--------|--------------------------|---|
| Catego | ry : Exterior | | В | uilding | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| broup | pane | Location | Quantity | | Nank | Replacement | ooninients |
| | Windows - Louver | Entire Building | 108 | SF | 6 | 10+ years | |
| Catego | ry : Electrical | | В | uilding | : Main | | |
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerge | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 7 | 10+ years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 3 | EA | 6 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Duilding | 20,042 | 01 | 0 | 0-10 years | |
| Main Se | | | | | | | |
| | Main Electrical Service - 1600 A 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | PA System | Entire Building | 26,642 | SF | 5 | 2-5 years | PA system is working, however, needs to be repaired. Some areas in the building don't work at various times. |
| Power D | vistribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 4 | 2-5 years | Panel is in poor condition and is |
| | Lighting and Power Panels - Above 100 A | Entire Building | 5 | EA | 6 | 6-10 years | significantly deteriorated |
| Catego | ry : Fire Protection | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alaı | m | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 7 | 10+ years | |
| | Fire Alarm Strobe Lights | Entire Building | 26,642 | SF | 7 | 10+ years | |
| | Fire Alarm_System | Entire Building | 26,642 | SF | 7 | 10+ years | |
| | | Entro Dananig | 20,012 | 0. | | let youro | |
| Catego | ry : Mechanical | | В | uilding | : Main | December | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Air Cond | litioning | | | | | | |
| | Chiller-Air Cooled-Screw Type-Ground Mounted - 101 - 200 tons | Site - East | 1 | EA | 6 | 10+ years | |



| Calego | ry : Mechanical | | | | | | |
|----------------|---|-----------------|----------|------------|------|-------------|----------|
| | | | | uilding | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| Air Hand | ling Systems | | | | | | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - Less than | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| | 6000 cfm Air Intake | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| Boiler Sv | rstems | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Glycol Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Tube- Force Draft- Hot Water Boiler - 1001 - 2000 MBH | | - | | - | , | |
| Gas Boo | ster | | | | | | |
| | Gas Booster | Boiler Room | 1 | EA | 6 | 10+ years | |
| Heating | Devieee | | | | | | |
| Heating [| | Fating Duilding | 5 | F A | 0 | 0.40 | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Unit Heater - Electric | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Unit Heater - Hot Water | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Wall Heater - Electric | Entire Building | 8 | EA | 5 | 6-10 years | |
| Mechani | cal Plumbing | | | | | | |
| | Chilled Water Pump - Less than 10 | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Dual Temperature Pump - Less than 10 | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Hot Water Pump - Less than 10 | Boiler Room | 3 | EA | 6 | 6-10 years | |
| | Hydronic Supply and Return - Steel | Entire Building | 364 | LF | 6 | 6-10 years | |
| T | ture Control | | | | | | |
| <u>rempera</u> | ture Control | Entiro Building | 06.640 | <u>е</u> г | e | 6 10 10000 | |
| | DDC System | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Thermostats - DDC | Entire Building | 26 | EA | 6 | 6-10 years | |
| Unit Vent | tilation | | | | | | |
| | Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 24 | EA | 6 | 6-10 years | |
| Ventilatio | n | | | | | | |
| <u> </u> | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |



| | Schools | | | | | | 2929 W 83rd STREET, Chicago, IL 60652 |
|----------|---|------------------|----------|---------|--------|--------------------------|---------------------------------------|
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 6-10 years | |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | er | | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | Boiler Room | 1 | EA | 6 | 6-10 years | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water Risers | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 26,642 | SF | 6 | 6-10 years | |
| | Sanitary Piping | Entire Building | 26,642 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 26,642 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 26,642 | SF | 6 | 10+ years | |
| Pumps | | | | | | | |
| - | Pumps - Ejector-Duplex | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Pumps - Sump-Duplex | Mechanical Room | 1 | EA | 6 | 10+ years | |
| Catego | ry : Room | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | rative Suites/Offices | | | | | | |
| | Ceiling - Splined | Counselor Office | 260 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Counselor Office | 200 | EA | 6 | 10+ years | |
| | Floor - Tile | Counselor Office | 260 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Counselor Office | 200 | EA | 7 | | |
| | Power Distribution | Counselor Office | 30 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Counselor Office | 289 | SF | 7 | 10+ years | |
| | Waiis - CUliciele Diuck | | 289 | SF | 1 | 10+ years | |



| | | | | | . Ma'::: | | 2929 W 8310 STREET, Chicago, IL 60652 |
|--------|-----------------------------|--------------------|----------|---------|----------|-------------|---------------------------------------|
| Catego | ry : Room | | В | uilding | : Main | - | |
| • | | | • | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Masonry | Counselor Office | 180 | SF | 7 | 10+ years | |
| | Work SInk | Counselor Office | 1 | EA | 7 | 10+ years | |
| | Ceiling - Splined | Engineer's Office | 91 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Engineer's Office | 91 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Engineer's Office | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Engineer's Office | 10 | EA | 7 | 10+ years | |
| | Storage/ Closet | Engineer's Office | 50 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Engineer's Office | 239 | SF | 7 | 10+ years | |
| | Walls - Masonry | Engineer's Office | 16 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Gym Storage | 91 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Gym Storage | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Gym Storage | 91 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Gym Storage | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Gym Storage | 10 | EA | 7 | 10+ years | |
| | Storage/ Closet | Gym Storage | 91 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Gym Storage | 239 | SF | 7 | 10+ years | |
| | Walls - Masonry | Gym Storage | 16 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Main Office | 213 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Main Office | 3 | ĒA | 6 | 10+ years | |
| | Floor - Tile | Main Office | 213 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Main Office | 3 | EA | 7 | 10+ years | |
| | Power Distribution | Main Office | 16 | EA | 7 | 10+ years | |
| | Storage/ Closet | Main Office | 73 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Main Office | 302 | SF | 7 | 10+ years | |
| | Walls - Masonry | Main Office | 108 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Principal's Office | 201 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 201 | EA | 6 | 10+ years | |
| | Floor - Tile | Principal's Office | 201 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Principal's Office | 201 | EA | 7 | 10+ years | |
| | Power Distribution | Principal's Office | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Principal's Office | 362 | SF | 7 | - | |
| | Walls - Masonry | Principal's Office | 14 | SF | 7 | 10+ years | |
| | | • | | SF | | 10+ years | |
| | Ceiling - Splined | Teachers Lounge | 259 | | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Teachers Lounge | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Teachers Lounge | 259 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Teachers Lounge | 4 | EA | 7 | 10+ years | |
| | Power Distribution | Teachers Lounge | 12 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Teachers Lounge | 498 | SF | 7 | 10+ years | |
| | Work SInk | Teachers Lounge | 1 | EA | 7 | 10+ years | |
| Gymnas | | | | | | | |
| | Ceiling - Exposed | 1st Floor | 2,979 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |



| Catego | Category : Room Building : Main | | | | | 2929 W 8310 3TREET, Chicago, ie 60032 | |
|---------|---------------------------------|------------------------|----------|-------|--------|---------------------------------------|----------|
| Galege | | | | unung | · Main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _ | Doors - Wood Doors inclu hw | 1st Floor | 4 | EA | 5 | 10+ years | |
| | Floor - Wood | 1st Floor | 2,979 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 5 | 10+ years | |
| | Stage | 1st Floor | 175 | SF | 5 | 10+ years | |
| | Stage Curtain | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Stage-Stairs - Wood | 1st Floor | 20 | LF | 6 | 10+ years | |
| | Storage/ Closet | 1st Floor | 144 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,631 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 646 | SF | 7 | 10+ years | |
| Library | | | | | | | |
| - | Casework | 106 | 40 | LF | 6 | 10+ years | |
| | Ceiling - Exposed | 106 | 672 | SF | 7 | 10+ years | |
| | Ceiling - Splined | 106 | 175 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 106 | 6 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 106 | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 106 | 847 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 106 | 16 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 106 | 121 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 106 | 816 | SF | 6 | 10+ years | |
| | Walls - Masonry | 106 | 144 | SF | 7 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Splined | Basement | 2,043 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Basement | 2,043 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 30 | EA | 7 | 10+ years | |
| | Serving Line | Basement | 16 | LF | 7 | 10+ years | |
| | Storage/ Closet | Basement | 211 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Basement | 1,887 | SF | 7 | 10+ years | |
| MDF ID | F | | | | | | |
| — | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Finishes | 1st Floor | 103 | SF | 7 | 10+ years | |
| | Other Cooling Unit | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Window AC Unit | 1st Floor | 1 | EA | 7 | 10+ years | |
| Mechan | ical/ Service Rooms | | | | | | |
| | Boiler Room | Building Support Rooms | 572 | SF | 5 | 10+ years | |
| | Janitor's Closet | Building Support Rooms | 35 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Building Support Rooms | 239 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Building Support Rooms | 140 | SF | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | | | |
|---------|--|------------------------|----------|----------|--------|-------------------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Mechanical/ Service Rooms | Building Support Rooms | 120 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | Building Support Rooms | 400 | SF | 5 | 10+ years | | | |
| Restroo | m | | | | | | | | |
| | Accessories | 101A | 36 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 101A | 36 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 101A | 1 | EA | 6 | 6-10 years | | | |
| | Floor - Tile | 101A | 36 | SF | 6 | 6-10 years | | | |
| | Lavatory | 101A | 1 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 101A | 1 | EA | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 101A | 63 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 101A | 105 | SF | 6 | 10+ years | | | |
| | Water Closet | 101A | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 103A | 20 | SF | 5 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 103A | 20 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 103A | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 103A | 20 | SF | 7 | 10+ years | | | |
| | Lavatory | 103A | 1 | ĒA | 6 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 103A | 1 | EA | 6 | 6-10 years | | | |
| | Walls - Concrete Block | 103A | 123 | SF | 7 | 10+ years | | | |
| | Water Closet | 103A | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 1st Floor | 48 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 48 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 6-10 years | | | |
| | Floor - Tile | 1st Floor | 48 | SF | 5 | 6-10 years | | | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 6-10 years | | | |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | 6-10 years | | | |
| | Partitions | 1st Floor | 1 | EA | 5 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 119 | SF | 7 | 10+ years | | | |
| | Walls - Masonry | 1st Floor | 125 | SF | 7 | 10+ years | | | |
| | Water Closet | 1st Floor | 125 | EA | 7 | 10+ years | | | |
| | Accessories | 1st Floor | 226 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 220 | SF | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 220 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1st Floor | 220 | EA | 7 | | | | |
| | | 1st Floor | 2 | EA | 6 | 10+ years 6-10 years | | | |
| | Lavatory Lighting - Pendent/Surface | 1st Floor | 23 | EA | 6 7 | • | | | |
| | | | | EA EA | | 6-10 years | | | |
| | Partitions | 1st Floor | 2 | | 5 | 6-10 years | | | |
| | Urinals Walls Concrete Black | 1st Floor | 4 | EA | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 1st Floor | 456 | SF | 7 | 10+ years | | | |
| | Water Closet | 1st Floor | 2 | EA | 7 | 6-10 years | | | |
| | Accessories | 1st Floor | 226 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 206 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 20 | SF | 5 | 10+ years | | | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile Ceramic/ Porcelain 1st Floor 226 SF 6-10 years 7 1st Floor ΕA 7 Floor Drain 1 10+ years Lavatorv 1st Floor 2 FΑ 7 6-10 years Lighting - Pendent/Surface 3 ΕA 1st Floor 6 6-10 years 5 5 Partitions 1st Floor ΕA 6-10 years SF Walls - Concrete Block 456 1st Floor 6 10+ years Water Closet 1st Floor 5 ΕA 7 6-10 years SF Accessories Gym Boys' 48 5 6-10 years SF Ceiling - Splined Gym Boys' 48 6 10+ years ΕA Doors - Wood Doors inclu hw Gym Boys' 1 6 6-10 years Floor - Tile Gvm Bovs' 48 SF 5 10+ vears Lavatory Gym Boys' 1 ΕA 5 6-10 years Lighting - Pendent/Surface Gym Boys' 1 ΕA 6 6-10 years ΕA 5 Partitions Gym Boys' 1 6-10 years Walls - Concrete Block Gym Boys' SF 7 227 10+ years Water Closet Gym Boys' ΕA 1 6 6-10 years 48 SF 7 Accessories Gym Girls' 6-10 years SF Ceiling - Splined Gym Girls' 48 6 10+ years Doors - Wood Doors inclu hw Gvm Girls' ΕA 1 5 6-10 vears Gym Girls' SF Floor - Tile 48 5 6-10 years Lavatory Gym Girls' 1 ΕA 5 6-10 years Lighting - Pendent/Surface Gym Girls' 6 1 ΕA 6-10 years Gym Girls' 5 Partitions 1 EΑ 6-10 years 227 SF Walls - Concrete Block Gym Girls' 5 10+ years Water Closet Gym Girls' ΕA 6 1 6-10 years SF Accessories Principal's Toilet 53 7 6-10 vears SF Ceiling - Lay-in Principal's Toilet 53 7 10+ years Doors - Wood Doors inclu hw Principal's Toilet 2 ΕA 6 10+ years SF 7 Floor - Tile Principal's Toilet 53 10+ years Lavatory Principal's Toilet 1 ΕA 7 10+ years Lighting - Pendent/Surface Principal's Toilet 1 FΑ 7 10+ years Partitions Principal's Toilet 1 ΕA 7 10+ years SF 7 Walls - Concrete Block Principal's Toilet 212 10+ years Water Closet Principal's Toilet FΑ 7 1 10+ years

Category : Classroom

Building : Main

| Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------------|---|---|--|---|--|--|
| m #100 (Regular Classroom) | | | | | | |
| Casework | 1st Floor | 33 | LF | 5 | 10+ years | |
| Ceiling - Exposed | 1st Floor | 720 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| Floor - Tile | 1st Floor | 720 | SF | 6 | 10+ years | |
| Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Item - Type m #100 (Regular Classroom) Casework Ceiling - Exposed Doors - Wood Doors inclu hw Floor - Tile | Item - TypeLocationIm #100 (Regular Classroom)Ist FloorCasework1st FloorCeiling - Exposed1st FloorDoors - Wood Doors inclu hw1st FloorFloor - Tile1st Floor | Item - TypeLocationQuantityIm #100 (Regular Classroom)1st Floor33Casework1st Floor33Ceiling - Exposed1st Floor720Doors - Wood Doors inclu hw1st Floor1Floor - Tile1st Floor720 | Item - TypeLocationQuantityUOMIm #100 (Regular Classroom)1st Floor33LFCasework1st Floor33LFCeiling - Exposed1st Floor720SFDoors - Wood Doors inclu hw1st Floor1EAFloor - Tile1st Floor720SF | Item - TypeLocationQuantityUOMRankIm #100 (Regular Classroom)Casework1st Floor33LF5Ceiling - Exposed1st Floor720SF7Doors - Wood Doors inclu hw1st Floor1EA6Floor - Tile1st Floor720SF6 | Item - TypeLocationQuantityUOMRankRecommend ReplacementIm #100 (Regular Classroom)Casework1st Floor33LF510+ yearsCeiling - Exposed1st Floor720SF710+ yearsDoors - Wood Doors inclu hw1st Floor1EA610+ yearsFloor - Tile1st Floor720SF610+ years |



| Catego | ry : Classroom | | R | uilding | | | |
|----------|-----------------------------|-----------|----------|-----------|------|-------------|----------|
| Jacogo | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| noup | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 6 | 10+ years | |
| Classroo | m #101 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | 10+ years | |
| | Ceiling - Exposed | 1st Floor | 740 | SF | 7 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 71 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 5 | 10+ years | |
| | Floor - Tile | 1st Floor | 811 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 17 | EA | 6 | 10+ years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 14 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 504 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 200 | SF | 7 | 10+ years | |
| Classroo | m #102 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 10+ years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 19 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 7 | 10+ years | |
| Classroo | m #103 (Regular Classroom) | | | | | | |
| | Ceiling - Exposed | 1st Floor | 574 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 574 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 10 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 130 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 84 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 620 | SF | 6 | 10+ years | |
| Classroo | m #104 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 8 | LF | 4 | 2-5 years | |



| Category : Classroom | | | B | uilding | : Main | | |
|----------------------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 7 | 10+ years | |
| Classroo | m #105 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 10+ years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | | EA | 5 | 10+ years | |
| | Floor - Tile | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Marker Board | 1st Floor | 6 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 5 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 6 | 10+ years | |
| | Wallo Maoonly | | 100 | 01 | Ū | ior youro | |
| Classroo | m #107 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 6-10 years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 7 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 6 | 10+ years | |
| Classroo | m #109 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 6-10 years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 10+ years | |
| | Floor - Tile | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 13 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 100 | EA | 5 | 2-5 years | |
| | WORK OILK | 13(1100) | I | LA | 5 | 2-J years | |



| Category : Classroom | | | B | uilding | Main | | |
|----------------------|---|--|---|--|---|---|----------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| lassroc | m #110 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 10+ years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 7 | 10+ years | |
| | Walls - Masonly | 151 F1001 | 100 | SF | 1 | 10+ years | |
| lassroc | m #111 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 33 | LF | 6 | 6-10 years | |
| | Ceiling - Exposed | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 720 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | ĒA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 13 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 746 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 100 | SF | 6 | 10+ years | |
| Catego | ry : Interior | | В | uilding | Main | | |
| | ., | | | | | Recommend | |
| | | | | | | | |
| | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| iroup | | | | | | | Comments |
| iroup | Ceiling - Splined | 1st East | 598 | SF | 7 | 10+ years | |
| iroup | | | | | | | |
| Group | Ceiling - Splined | 1st East | 598 | SF | 7 | 10+ years 0-1 year | Water spot/damaged and major cra |
| iroup | Ceiling - Splined Ceiling - Splined | 1st East 1st East | 598 250 4 | SF SF | 7 4 | 10+ years 0-1 year 10+ years | Water spot/damaged and major cra |
| iroup | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet | 1st East 1st East 1st East | 598 250 | SF SF EA | 7 4 6 | 10+ years 0-1 year 10+ years 10+ years | Water spot/damaged and major cra |
| iroup | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface | 1st East 1st East 1st East 1st East | 598 250 4 848 13 | SF SF EA SF | 7 4 6 7 | 10+ years 0-1 year 10+ years 10+ years 10+ years | Water spot/damaged and major cr |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block | 1st East 1st East 1st East 1st East 1st East 1st East 1st East | 598 250 4 848 13 1,008 | SF SF EA SF EA SF | 7 4 6 7 7 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st East | 598 250 4 848 13 1,008 687 | SF SF EA SF EA SF SF | 7 4 6 7 7 7 7 7 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Ceiling - Splined | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st West | 598 250 4 848 13 1,008 687 1,749 | SF SF EA SF EA SF SF SF | 7 4 6 7 7 7 7 6 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Ceiling - Splined Doors - Side-lite | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st West 1st West | 598 250 4 848 13 1,008 687 1,749 14 | SF SF EA SF EA SF SF SF SF | 7 4 6 7 7 7 7 6 6 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st West 1st West 1st West | 598 250 4 848 13 1,008 687 1,749 14 6 | SF SF EA SF EA SF SF SF EA | 7 4 6 7 7 7 7 6 6 6 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st West 1st West 1st West 1st West | 598 250 4 848 13 1,008 687 1,749 14 6 8 | SF SF EA SF EA SF SF SF EA SF | 7 4 6 7 7 7 6 6 6 6 6 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |
| Group Corridor | Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Masonry Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw | 1st East 1st East 1st East 1st East 1st East 1st East 1st East 1st West 1st West 1st West | 598 250 4 848 13 1,008 687 1,749 14 6 | SF SF EA SF EA SF SF SF EA | 7 4 6 7 7 7 7 6 6 6 | 10+ years 0-1 year 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | Water spot/damaged and major cra |



| Catego | ry : Interior | | В | uilding | : Main | | |
|--------|-------------------------------|---------------------|----------|---------|--------|-------------|----------|
| | • | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Concrete Block | 1st West | 409 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st West | 1,346 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Gym Corridor | 201 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Gym Corridor | 2 | EA | 6 | 10+ years | |
| | Doors - Wood Doors include hw | Gym Corridor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | Gym Corridor | 201 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Gym Corridor | 5 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Gym Corridor | 330 | SF | 7 | 10+ years | |
| | Walls - Masonry | Gym Corridor | 128 | SF | 7 | 10+ years | |
| Safety | | | | | | | |
| , | Camera Viewing Station | Throughout Building | 1 | EA | 7 | 10+ years | |
| | Security Cameras | Throughout Building | 5 | EA | 7 | 10+ years | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | North | 40 | SF | 7 | 10+ years | |
| | Floor - Tile | North | 40 | SF | 6 | 10+ years | |
| | Handrails | North | 48 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | North | 2 | EA | 7 | 10+ years | |
| | Stairs - Tile | North | 84 | LF | 6 | 10+ years | |
| | Walls - Masonry | North | 296 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | North | 200 | SF | 7 | 10+ years | |
| | Ceiling - Splined | South | 75 | SF | 6 | 10+ years | |
| | Floor - Tile | South | 32 | SF | 6 | 10+ years | |
| | Handrails | South | 54 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | South | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | South | 1 | EA | 7 | 10+ years | |
| | Stairs - Tile | South | 77 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | South | 540 | SF | 7 | 10+ years | |



Category : Exterior Building : Branch 1_Rosenwald Recommend Location UOM **Replacement** Comments Item - Type Quantity Rank Group Entrance 2 ΕA 6 Exterior Doors - Exterior Steel Door 1 - Main 10+ years 45 LF 6 Exterior Stairs - Concrete 1 - Main 10+ years 6 LF **Exterior Stairs - Stone** 1 - Main 6 10+ years Stair Handrail - Steel Stair Handrail 1 - Main 10 LF 6 10+ years Exterior Doors - Exterior Steel Door 3 1 ΕA 6 6-10 years Exterior Stairs - Concrete 3 LF 18 6 10+ years LF Exterior Stairs - Stone 3 3 6 10+ years Exterior Doors - Exterior Steel Door 4 1 ΕA 6 6-10 vears Exterior Stairs - Concrete 4 18 LF 6 10+ years 4 3 LF Exterior Stairs - Stone 6 10+ vears 5 2 Exterior Doors - Exterior Steel Door EΑ 6 10+ years Exterior Doors - Transom Lite 5 6 10+ years 1 EΑ 5 Exterior Stairs - Stone 78 LF 7 10+ years 5 LF Stair Handrail - Steel Stair Handrail 10 6 10+ years Exterior Doors - Exterior Steel Door **Boiler Room** EΑ 6 10+ years 1 Foundation Foundation - Concrete LF 7 Entire Building 523 10+ years Superstructure - Concrete 11,838 SF Entire Building 7 10+ years Liahtina Exterior Lighting - Parapet or Roof Mounted Entire Building 4 ΕA 7 6-10 years Exterior Lighting - Wall Mounted Entire Building 16 ΕA 6 6-10 years Exterior Lighting - Wall Mounted Entire Building 2 ΕA Two of the unit on the western side of 4 1-2 years building are burned out and the fixtrures need replaced. Roof System Access Ladder - Metal С ΕA 7 1 10+ years Chimney - Brick Chimney- Concrete/ Mortar С 50 LF 6 10+ years Liner LF Coping - Clay Tile С 6 73 10+ years Copina - Stone С LF 117 6 10+ years **Downspouts - Exterior Downspouts** С 56 LF 6 6-10 years Downspouts - Exterior Downspouts LF С 28 4 1-2 years Several downspouts are rusted out and need to be replaced Parapet - 16" - 30" Height С LF 190 6 10+ years Roof - Modified Bitumen С SF 6 6-10 years 11.838 С 5 Roof Hatch - Wood 1 EΑ 2-5 years С 7 Roof Structure - Heavy Timber 11,838 SF 10+ years



| Catego | ry : Exterior | В | uilding | : Branc | h 1_Rosenwald | | |
|-----------------------|---|-----------------|----------|---------|---------------|---------------|---|
| | | | | | _ | Recommend | |
| Group Walls | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Canopy - Concrete/ Stucco | Entire Building | 92 | SF | 5 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 4,860 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 1,252 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 58 | SF | 4 | 0-1 year | severely deteriorated mortar and cracked bricks |
| Windows | | | | | | | |
| | Guard - Guards wire guard | Entire Building | 1,119 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 201 | LF | 5 | 6-10 years | rusted/corroded |
| | Windows - Louver | Entire Building | 33 | SF | 6 | 6-10 years | |
| | Windows - Louver | Entire Building | 9 | SF | 5 | 2-5 years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 1,119 | SF | 6 | 6-10 years | |
| Catego | ry : Electrical | | В | uilding | : Branc | h 1_Rosenwald | ł |
| _ | | | | | | Recommend | _ |
| Group | 21 | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emergen | cy System | | | | | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 11,838 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 11,838 | SF | 6 | 6-10 years | |
| Main Ser | vice | | | | | | |
| | PA System | Entire Building | 11,838 | SF | 4 | 0-1 year | PA system is obsolete |
| Power Di | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 3 | 1-2 years | Panel is live front and is substantially deteriorated |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 6 | 6-10 years | |
| Catego | ry : Fire Protection | | В | uilding | : Branc | h 1_Rosenwald | ł |
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Aları | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 3 | 0-1 year | Fire Alarm Panel needs to be updated to modern panel |
| | Fire Alarm_System | Entire Building | 11,838 | SF | 4 | 0-1 year | Fire alarm system is more than 20 years of age |



| <u> </u> | chools | | | | | | 2929 W 83rd STREET, Chicago, IL 60652 | | |
|------------|--|-----------------|----------|-------------------------------|---------|--------------------------|---|--|--|
| Catego | ry : Fire Protection | | В | uilding | : Branc | h 1_Rosenwald | k statistick statisti statistick statistick statistick statistick statistick statistick | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | | |
| oroup | item - Type | Location | Quantity | | Nank | Replacement | Comments | | |
| Catego | y : Mechanical | | В | Building : Branch 1_Rosenwald | | | | | |
| O | Home Trunc | Leastian | Quentitu | | Denk | Recommend | Commonto | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Boiler Sy | | | | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP | Boiler Room | 2 | EA | 5 | 6-10 years | | | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 10+ years | | | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 10+ years | | | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | 10+ years | | | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP | Boiler Room | 2 | EA | 5 | 6-10 years | | | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 100 | LF | 5 | 6-10 years | | | |
| | Piping - Steam Pipe- Steel | Boiler Room | 100 | LF | 5 | 6-10 years | | | |
| | Steam Traps | Boiler Room | 14 | EA | 5 | 6-10 years | | | |
| | Vacuum Pump | Boiler Room | 1 | EA | 6 | 10+ years | | | |
| -leating I | Devices | | | | | | | | |
| - | Radiators - Steam | Entire Building | 6 | EA | 5 | 6-10 years | | | |
| | Fin Tube - Steam | Entire Building | 34 | LF | 6 | 6-10 years | | | |
| Tempera | ture Control | | | | | | | | |
| • | Electric Controls | Entire Building | 11,838 | SF | 6 | 6-10 years | | | |
| | Electric Thermostat | Entire Building | 6 | EA | 6 | 6-10 years | | | |
| Unit Ven | ilation | | | | | | | | |
| | Unit Ventilators- Floor Mounted- Steam Heating Coils Only | Entire Building | 6 | EA | 5 | 6-10 years | | | |
| Ventilatio | n | | | | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Boiler Room | 2 | EA | 6 | 6-10 years | | | |
| Catego | y : Plumbing | | В | uilding | : Branc | h 1_Rosenwald | ł | | |
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Hot Wate | r | | | | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | Boiler Room | 1 | EA | 6 | 6-10 years | | | |
| Piping | | | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 11,838 | SF | 4 | 2-5 years | Pipes are galvanized, more than 40 years of age and there are many pip clamps and water pressure and flow | | |



| atego | ry : Plumbing | | В | uilding | : Brancl | h 1_Rosenwald | 1 |
|-------|--|-----------------|----------|---------|----------|--------------------------|--|
| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| roup | nem - Type | Location | Quantity | | IVALIK | Replacement | is not achieved to the farthest fixture |
| | Domestic Piping-Cold Water Risers | Entire Building | 11,838 | SF | 4 | 2-5 years | Pipes are galvanized, more than 40 |
| | | | | | | | years of age and there are many pi |
| | | | | | | | clamps and water pressure and flor is not achieved to the farthest fixtur |
| | Domestic Piping-Cold Water from Risers to | Entire Building | 11,838 | SF | 4 | 2-5 years | Pipes are galvanized, more than 4 |
| | Fixtures | Entito Ballanig | 11,000 | 0. | • | 2 0 90010 | years of age and there are many p |
| | | | | | | | clamps and water pressure and flo |
| | Demostic Dining Hat Water Herizontal Lines | Entire Duilding | 11,838 | SF | 4 | | is not achieved to the farthest fixtur |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 11,838 | 55 | 4 | 2-5 years | Pipes are galvanized, more than 40 years of age and there are many p |
| | | | | | | | clamps and water pressure and flo |
| | | | | | | | is not achieved to the farthest fixtu |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 11,838 | SF | 4 | 6-10 years | Pipes are galvanized, more than 4 |
| | | | | | | | years of age and there are many p clamps and water pressure and flo |
| | | | | | | | is not achieved to the farthest fixtu |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 11,838 | SF | 4 | 2-5 years | Pipes are galvanized, more than 4 |
| | | | | | | | years of age and there are many p |
| | | | | | | | clamps and water pressure and flo is not achieved to the farthest fixtu |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 11,838 | SF | 4 | 2-5 years | Pipes are galvanized, more than 4 |
| | Fixtures | Ũ | | | | , | years of age and there are many p |
| | | | | | | | clamps and water pressure and flo |
| | Sanitary Piping | Entire Building | 11,838 | SF | 6 | 10+ years | is not achieved to the farthest fixtu |
| | Storm Piping | Entire Building | 11,838 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 11,838 | SF | 6 | 10+ years | |
| atego | ry : Room | | В | uildina | : Brancl | h 1_Rosenwald | 1 |
| | | | | 3 | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |

| Group | ltem - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
|----------|-----------------------------|-----------------------|----------|-----|------|-------------|----------|
| Administ | trative Suites/Offices | | | | | | |
| | Ceiling - Splined | 101 Office/Store Room | 50 | SF | 5 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 101 Office/Store Room | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 101 Office/Store Room | 50 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 101 Office/Store Room | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | 101 Office/Store Room | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 101 Office/Store Room | 31 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 101 Office/Store Room | 229 | SF | 7 | 10+ years | |
| | AC Unit | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 248 | SF | 5 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 1st Floor | 248 | SF | 5 | 6-10 years | |



| Catego | ategory : Room | | | uilding | : Branc | h 1_Rosenwald | 1 |
|---------|--------------------------------|------------------------|----------|----------|---------|------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 1st Floor | 5 | EA | 5 | 6-10 years | |
| | Power Distribution | 1st Floor | 8 | EA | 5 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 45 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 555 | SF | 7 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 143 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 1st Floor | 143 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 5 | 6-10 years | |
| | Power Distribution | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 295 | SF | 7 | 10+ years | |
| | Work SInk | 1st Floor | 1 | ĒA | 5 | 10+ years | |
| | Ceiling - Splined | 2nd Floor | 210 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 5 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 210 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 210 | EA | 5 | 6-10 years | |
| | Power Distribution | 2nd Floor | 12 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 559 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 8 | SF | 5 | 10+ years | |
| Mechan | ical/ Service Rooms | | | | | | |
| | Boiler Room | Building Service Rooms | 520 | SF | 5 | 10+ years | |
| | Janitor's Closet | Building Service Rooms | 36 | SF | 5 | 10+ years | |
| | Storage Room | Building Service Rooms | 12 | SF | 5 | 10+ years | |
| | Storage Room | Building Service Rooms | 60 | SF | 5 | 10+ years | |
| Restroo | m | | | | | | |
| | Accessories | 01A | 20 | SF | 5 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 01A | 20 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | 01A | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile/Sheet | 01A | 20 | SF | 5 | 6-10 years | |
| | Lavatory | 01A | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 01A | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 01A | 40 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 01A | 83 | SF | 7 | 10+ years | |
| | Water Closet | 01A | 1 | EA | 6 | 6-10 years | |
| | Accessories | 02A | 20 | SF | 5 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 02A | 20 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | 02A 02A | 20 | EA | 5 | 10+ years | |
| | Floor - Tile | 02A 02A | 20 | SF | 5 6 | 10+ years | |
| | | 02A 02A | | EA | - | - | |
| | Lavatory | | 1 | | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | 02A | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 02A 02A | 40 83 | SF SF | 5 5 | 10+ years 10+ years | |
| | Walls - Structural Glazed Tile | | | | | | |



Building : Branch 1_Rosenwald Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Water Closet 02A EΑ 6-10 vears 7 1 03A 16 SF 7 6-10 vears Accessories Ceiling - Plaster/Drywall 03A 16 SF 7 10+ years Doors - Wood Doors inclu hw 03A ΕA 1 6 10+ years SF Floor - Tile 03A 16 6 10+ years Lavatory 03A 1 EΑ 6 10+ years Lighting - Lay-in 03A ΕA 7 1 10+ years Walls - Concrete Block SF 03A 36 7 10+ years Walls - Structural Glazed Tile 03A 71 SF 7 10+ vears Water Closet 03A 1 EΑ 7 10+ vears Accessories 04A 24 SF 7 6-10 years Ceiling - Plaster/Drywall 04A 24 SF 7 10+ years Doors - Wood Doors inclu hw ΕA 6 04A 1 10+ years SF 6 Floor - Tile 04A 24 10+ years ΕA Lavatory 04A 1 6 10+ years Lighting - Lay-in 7 04A 1 EΑ 10+ years Walls - Concrete Block 50 SF 7 04A 10+ years SF Walls - Structural Glazed Tile 04A 93 7 10+ years ΕA Water Closet 04A 1 7 10+ vears Accessories 05A 20 SF 7 6-10 years Ceiling - Plaster/Drywall 05A 20 SF 7 10+ years Doors - Wood Doors inclu hw 05A 1 EΑ 6 10+ years Floor - Tile 20 SF 6 05A 10+ years Lavatory 05A 1 FΑ 6 10+ years Lighting - Lay-in 05A EΑ 7 1 10+ years Walls - Concrete Block SF 05A 40 7 10+ vears SF Walls - Structural Glazed Tile 05A 83 7 10+ years Water Closet 05A 1 ΕA 7 10+ years SF Accessories 06A 20 7 6-10 years Ceiling - Plaster/Drywall 06A 20 SF 7 10+ years Doors - Wood Doors inclu hw 10+ years 06A 1 ΕA 6 Floor - Tile 06A 20 SF 6 10+ vears FΑ 06A 6 Lavatory 1 10+ years Lighting - Lay-in 06A 1 EΑ 7 10+ years Walls - Concrete Block SF 7 06A 40 10+ years Walls - Structural Glazed Tile SF 7 06A 83 10+ years Water Closet 06A 1 EΑ 6 10+ years SF 7 6-10 years Accessories 1st Floor 170 SF Ceiling - Plaster/Drywall 1st Floor 150 7 10+ years Ceiling - Plaster/Drywall SF 1st Floor 20 5 10+ vears Doors - Wood Doors inclu hw 1st Floor 2 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain 170 SF 6 1st Floor 10+ vears Floor Drain 1st Floor EA 7 10+ years 1 Lavatory 1st Floor 1 EA 6 10+ years



| Catego | ry : Room | | В | uildina | : Branc | h 1_Rosenwald | k |
|----------|---------------------------------|-----------------------|----------|---------|----------|---------------|--------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor | 1 | EA | 4 | 0-1 year | Door is missing |
| | Urinals | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 162 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 30 | SF | 5 | 10+ years | Long cracked on the wall |
| | Walls - Structural Glazed Tile | 1st Floor | 280 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 2 | SF | 5 | 0-1 year | missing tile |
| | Water Closet | 1st Floor | 1 | EA | 6 | 10+ years | - |
| | Accessories | 1st Floor | 170 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 100 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 70 | SF | 4 | 1-2 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 170 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 192 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 288 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor Unisex East | 28 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Unisex East | 28 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Unisex East | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor Unisex East | 28 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor Unisex East | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor Unisex East | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | 1st Floor Unisex East | 1 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor Unisex East | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor Unisex East | 100 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor Unisex East | 55 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Unisex East | 1 | EA | 7 | 10+ years | |
| | Accessories | Boiler Toilet | 50 | SF | 5 | 2-5 years | |
| | Ceiling - Plaster/Drywall | Boiler Toilet | 50 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Boiler Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | Boiler Toilet | 50 | SF | 5 | 6-10 years | |
| | Lavatory | Boiler Toilet | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Boiler Toilet | 1 | EA | 7 | 10+ years | |
| | Partitions | Boiler Toilet | 1 | EA | 4 | 0-1 year | missing door |
| | Walls - Concrete Block | Boiler Toilet | 279 | SF | 7 | 10+ years | |
| | Water Closet | Boiler Toilet | 1 | EA | 7 | 10+ years | |
| Catego | ry : Classroom | | В | uilding | : Brancl | h 1_Rosenwald | t |
| | | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #01 (Regular Classroom) | | | | | | |



| Catego | ry : Classroom | В | uilding | : Brancl | h 1_Rosenwald | k | |
|----------|-----------------------------|-----------|----------|----------|---------------|-------------|----------|
| Ū | | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 1st Floor | 62 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 1,045 | SF | 5 | 6-10 years | |
| | Chalk Board | 1st Floor | 4 | LF | 4 | 0-1 year | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 1st Floor | 1,045 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 29 | EA | 5 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 2-5 years | |
| | Walls - Concrete Block | 1st Floor | 793 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 250 | SF | 7 | 10+ years | |
| Classroc | om #02 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 62 | LF | 5 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 975 | SF | 5 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | ĒA | 5 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 1st Floor | 975 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 26 | ĒA | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 42 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 543 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 250 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 250 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 5 | 6-10 years | |
| Classroc | om #03 (Regular Classroom) | | | | | | |
| 21000100 | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 40 | LF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 1,000 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 16 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 10 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,000 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 14 | SF | 7 | 10+ years | |
| | Student Lockers - One Tier | 1st Floor | 12 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,027 | SF | 7 | 10+ years | |
| Classror | om #04 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 50 | LF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 950 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 16 | LF | 4 | 2-5 years | |
| | | | 10 | <u> </u> | | 20,000 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |



| Category : Classroom | | | | Building : Branch 1_Rosenwald | | | | |
|----------------------|-----------------------------|-----------|----------|-------------------------------|---------|---------------|--------------------|--|
| Ŭ | | | | Ŭ | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| - | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | 10+ years | | |
| | Storage/ Closet | 1st Floor | 14 | SF | 7 | 10+ years | | |
| | Student Lockers - One Tier | 1st Floor | 12 | EA | 6 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 808 | SF | 7 | 10+ years | | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | | |
| Classroo | m #05 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 5 | 2-5 years | | |
| | Casework | 1st Floor | 50 | LF | 6 | 10+ years | | |
| | Ceiling - Splined | 1st Floor | 994 | SF | 7 | 10+ years | | |
| | Ceiling - Splined | 1st Floor | 6 | SF | 5 | 2-5 years | water spot/damaged | |
| | Chalk Board | 1st Floor | 16 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 1,000 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | 10+ years | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 1st Floor | 30 | SF | 7 | 10+ years | | |
| | Student Lockers - One Tier | 1st Floor | 12 | EA | 6 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 1,027 | SF | 6 | 10+ years | | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | | |
| Classroo | m #06 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 1st Floor | 45 | LF | 7 | 10+ years | | |
| | Ceiling - Splined | 1st Floor | 1,000 | SF | 7 | 10+ years | | |
| | Chalk Board | 1st Floor | 6 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 1,000 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | 10+ years | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 1st Floor | 30 | SF | 7 | 10+ years | | |
| | Student Lockers - One Tier | 1st Floor | 12 | EA | 6 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 1,027 | SF | 6 | 10+ years | | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | | |
| Catego | ry : Interior | | В | uilding | : Branc | h 1_Rosenwald | 1 | |
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |

| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
|----------|-----------------------------|----------|----------|-----|------|-------------|----------|
| Corridor | | | | | | | |
| | Ceiling - Splined | East | 600 | SF | 6 | 10+ years | |
| | Doors - Side-lite | East | 18 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | East | 2 | EA | 6 | 10+ years | |
| | Doors - Transom Window | East | 6 | SF | 6 | 10+ years | |



| Catego | ry : Interior | | Building : Branch 1_Rosenwald | | | | |
|--------|--------------------------------------|---------------------|-------------------------------|-----|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors include hw | East | 2 | EA | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | East | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | East | 120 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | East | 480 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | East | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | East | 368 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | East | 140 | SF | 7 | 10+ years | |
| | Ceiling - Splined | West | 953 | SF | 7 | 10+ years | |
| | Ceiling - Splined | West | 60 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | West | 2 | EA | 6 | 10+ years | |
| | Doors - Wood Doors include hw | West | 4 | EA | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | West | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | West | 40 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | West | 963 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | West | 14 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | West | 1,011 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | West | 738 | SF | 7 | 10+ years | |
| Safetv | | | | | | | |
| | Camera Viewing Station | Throughout Building | 1 | EA | 7 | 10+ years | |
| | Security Cameras | Throughout Building | 4 | EA | 7 | 10+ years | |



| Catego | ry : Exterior | | E | Building : Branch 2_Rosenwald Carroll | | | | |
|----------|---|-----------------|----------|---------------------------------------|------|-------------|----------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments | |
| Group | 7 1 | Location | Quantity | UUW | Rank | Replacement | Comments | |
| Intrance | | · • • · | | | | | | |
| | Exterior Doors - Side lite | 1 - Main | 4 | EA | 6 | 10+ years | | |
| | Exterior Doors - Store Front | 1 - Main | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | 1 - Main | 5 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | 2 | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | 2 | 3 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | 3 | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | 3 | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | 4 | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | 4 | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | 5 | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | 5 | - 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | 6 | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | 6 | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | Yard Storage | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | Yard Storage | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | Taru Storage | 2 | EA | 0 | TOT years | | |
| oundati | on | | | | | | | |
| | Foundation - Concrete | Entire Building | 796 | LF | 7 | 10+ years | | |
| | Superstructure - Metal Deck/ Concrete | Entire Building | 47,204 | SF | 7 | 10+ years | | |
| | Topping | Linio Banang | ,201 | 01 | · | ior years | | |
| ighting | | | | | | | | |
| 99 | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 7 | EA | 7 | 6-10 years | | |
| oof Svs | stom | | | | | | | |
| 001 Sys | Access Ladder - Metal | D | 4 | ۳. | 7 | 10 | | |
| | | D | 1 | EA | 7 | 10+ years | | |
| | Chimney - Metal Flue | D | 35 | LF | 6 | 10+ years | | |
| | Coping - Metal | D | 792 | LF | 6 | 10+ years | | |
| | Downspouts - Interior Downspouts | D | 310 | LF | 6 | 10+ years | | |
| | Roof - Modified Bitumen | D | 26,408 | SF | 6 | 6-10 years | | |
| | Roof Hatch - Metal | D | 1 | EA | 7 | 10+ years | | |
| | Roof Structure - Steel / Metal Deck/ | D | 26,408 | SF | 7 | 10+ years | | |
| | Concrete Topping | | | | | | | |
| Valls | | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 19,981 | SF | 7 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 640 | SF | 6 | 10+ years | | |
| | | 6 | 0.10 | | - | , | | |
| Vindows | | | | | | | | |
| | Lintels - Steel | Entire Building | 611 | LF | 6 | 10+ years | | |
| | | | | | | | | |
| | | | | | | | | |

Category · Exterior



| Catego | ory : Exterior | | B | Building : Branch 2_Rosenwald Carroll | | | | | |
|----------|---|-----------------|----------|---------------------------------------|-----------|---------------|-----------|--|--|
| 3 | | | U | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 4,025 | SF | 6 | 10+ years | | | |
| atead | ory : Electrical | | В | uildina | : Branc | h 2_Rosenwald | d Carroll | | |
| | ., | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| merge | ncy System | | | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 10+ years | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 7,227 | SF | 6 | 10+ years | | | |
| | Emergency A/C Power - Gym | Entire Building | 4,050 | SF | 6 | 10+ years | | | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 2,223 | SF | 6 | 10+ years | | | |
| | Emergency A/C Power - Multipurpose | Entire Building | 1,641 | SF | 6 | 10+ years | | | |
| | Room | | ., | - | - | | | | |
| | Emergency Battery Packs - Corridors and | Entire Building | 36 | EA | 6 | 10+ years | | | |
| | Stairs | | | | | | | | |
| | Emergency Battery Packs - Gym | Entire Building | 6 | EA | 6 | 10+ years | | | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 5 | EA | 6 | 10+ years | | | |
| | Emergency Battery Packs - Multipurpose Room | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 18 | EA | 6 | 10+ years | | | |
| | Exit Signs - Gym | Entire Building | 4 | EA | 6 | 10+ years | | | |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Exit Signs - Multipurpose Room | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Security System - CCTV | Entire Building | 47,154 | SF | 6 | 6-10 years | | | |
| | Security System - Intrusion Detection | Entire Building | 47,154 | SF | 6 | 6-10 years | | | |
| ∕lain Se | rvice | | | | | | | | |
| | Main Electrical Service - 1200 A 277/480/3PH | Electrical Room | 1 | EA | 7 | 10+ years | | | |
| | Main Electrical Service - 800 A and 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | | | |
| | Independent Electrical Service for emergency power | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | PA System | Entire Building | 47,154 | SF | 6 | 6-10 years | | | |
| Power D | Distribution | | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 7 | 10+ years | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 12 | EA | 7 | 10+ years | | | |
| | Main Distribution Panels - Less than 400 | Entire Building | 1 | EA | 7 | 10+ years | | | |
| | amp | | | | - | | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 3 | EA | 6 | 10+ years | | | |
| | | | Ũ | | • | | | | |
| | | | | | | | | | |



| Catego | ry : Fire Protection | | Building : Branch 2_Rosenwald Carroll | | | | | |
|-------------------|---|----------------------------|---------------------------------------|------------|--------|------------------------|----------|--|
| _ | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Fire Alaı | m | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 10+ years | | |
| | Fire Alarm Strobe Lights | Entire Building | 47,154 | SF | 6 | 10+ years | | |
| | Fire Alarm_System | Entire Building | 47,154 | SF | 6 | 10+ years | | |
| | Fire Pump Controller | Entire Building | 1 | EA | 6 | 10+ years | | |
| | | | | | - | , see geene | | |
| Pump R | oom Assembly | | | | | | | |
| | Fire Pump - 25-50 hp | Boiler Room | 1 | EA | 6 | 10+ years | | |
| | Jockey Pump | Boiler Room | 1 | EA | 6 | 10+ years | | |
| Sprinkle | r System | | | | | | | |
| | Sprinkler Heads | Entire Building | 47,154 | SF | 7 | 10+ years | | |
| | Sprinkler Piping | Entire Building | 47,154 | SF | 7 | 10+ years | | |
| | Wet Sprinkler System | Entire Building | 47,154 | SF | 7 | 10+ years | | |
| | | 0 | , | | | · | | |
| Catego | ry : Mechanical | В | d Carroll | | | | | |
| _ | | | • | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Air Conc | | | | | | | | |
| | Condensing Unit- Roof Mounted - 11-20 | Roof | 7 | EA | 5 | 6-10 years | | |
| | tons | | _ | | _ | | | |
| | Condensing Unit- Roof Mounted - 11-20 | Roof | 3 | EA | 5 | 6-10 years | | |
| | tons | | | | | | | |
| Air Hand | Iling Systems | | | | | | | |
| | Indoor Return Fans- Centrifugal Inline - | Entire Building | 2 | EA | 6 | 10+ years | | |
| | 5000 - 10000 CFM | 2 | | | | - | | |
| | Indoor Return Fans- Centrifugal Inline - Less | Entire Building | 8 | EA | 6 | 10+ years | | |
| | than 5000 CFM | - | | | | - | | |
| | Air Handling Unit-Package Single Zone- | Mechanical Room | 10 | EA | 5 | 6-10 years | | |
| | Indoor- Hot Water and DX Cooling Coils - | | | | | | | |
| | 4000-8000 cfm | | | | | | | |
| | Air Intake | Mechanical Room | 8 | EA | 6 | 10+ years | | |
| | Air Intake | Mechanical Room | 2 | EA | 6 | 10+ years | | |
| | | | | | | | | |
| | vstems | | | F ^ | | 40 | | |
| Boiler Sy | | Dellas Deess | | EA | 6 | 10+ years | | |
| Boiler Sy | Boiler Auxiliary- Non Condensing Hot Water | Boiler Room | 4 | | U | , | | |
| Boiler S <u>y</u> | Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH | | 4 | | - | - | | |
| <u>Boiler Sy</u> | Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 10+ years | | |
| <u>Boiler S</u> | Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH Chemical Pot Feeder Combustion Dampers | Boiler Room Boiler Room | 1 | EA EA | 6 6 | 10+ years 10+ years | | |
| Boiler S | Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 10+ years | | |



| Catego | ry : Mechanical | | В | uilding | : Brancl | h 2_Rosenwald | d Carroll |
|------------|--|-----------------|----------|---------|----------|---------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH | | | | | | |
| Gas Boo | ster | | | | | | |
| | Gas Booster | Boiler Room | 2 | EA | 7 | 10+ years | |
| -leating | Devices | | | | | | |
| 0 | Cabinet Heaters - With Hot Water Coil | Entire Building | 8 | EA | 6 | 6-10 years | |
| | Fin Tube - Hot Water | Entire Building | 726 | LF | 6 | 6-10 years | |
| | Unit Heater - Hot Water | Entire Building | 4 | EA | 6 | 6-10 years | |
| Mechani | cal Plumbing | | | | | | |
| | Hydronic Supply and Return - Galvanized | Entire Building | 350 | LF | 6 | 10+ years | |
| | Hot Water Pump - 10 - 20 HP | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Hot Water Pump - Less than 10 | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Hot Water Pump - Less than 10 | Entire Building | 10 | EA | 6 | 6-10 years | |
| Cempera | ture Control | | | | | | |
| | DDC System | Entire Building | 47,154 | SF | 5 | 6-10 years | |
| | Thermostats - DDC | Entire Building | 25 | EA | 6 | 6-10 years | |
| /entilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 10+ years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 10+ years | |
| Catego | ry : Plumbing | | В | uilding | : Brancl | h 2_Rosenwald | d Carroll |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 6 | 10+ years | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 4 | 2-5 years | Unit is 20+ years of age will need to be replaced. |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 47,154 | SF | 6 | 10+ years | |
| | Domestic Piping-Cold Water Risers | Entire Building | 47,154 | SF | 6 | 10+ years | |



Category : Plumbing Building : Branch 2_Rosenwald Carroll Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments SF Domestic Piping-Cold Water from Risers to Entire Building 47,154 6 10+ years Fixtures **Domestic Piping-Hot Water Horizontal Lines** Entire Building 47,154 SF 6 10+ years Domestic Piping-Hot Water Return Lines Entire Building 47,154 SF 6 10+ years **Domestic Piping-Hot Water Return Risers** Entire Building 47,154 SF 6 10+ years Domestic Piping-Hot Water from Risers to SF Entire Building 47,154 6 10+ years Fixtures SF Sanitary Piping Entire Building 47,154 7 10+ years Storm Piping Entire Building 47,154 SF 7 10+ years SF Vent Piping Entire Building 47,154 7 10+ years Pumps Pumps - Domestic Booster Pump-Duplex Entire Building 1 ΕA 4 2-5 years Pumps are more than 20 years of age Pumps - Ejector-Duplex Entire Building 1 EΑ 6 10+ years Pumps - Sump-Duplex Entire Building ΕA 6 10+ years 1

Category : Room

Building : Branch 2_Rosenwald Carroll

| | | | | | | Recommend | |
|---------|-----------------------------|----------------------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Adminis | trative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 101 Main Office | 566 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 101 Main Office | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 101 Main Office | 566 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 101 Main Office | 9 | EA | 6 | 6-10 years | |
| | Power Distribution | 101 Main Office | 18 | EA | 5 | 10+ years | |
| | Storage/ Closet | 101 Main Office | 7 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 101 Main Office | 297 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 101 Main Office | 397 | SF | 5 | 10+ years | |
| | Ceiling - Lay-in | 103 Counselor Office | 159 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 103 Counselor Office | 2 | EA | 6 | 6-10 years | |
| | Floor - Tile | 103 Counselor Office | 159 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 103 Counselor Office | 3 | EA | 6 | 6-10 years | |
| | Power Distribution | 103 Counselor Office | 4 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | 103 Counselor Office | 229 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 103 Counselor Office | 229 | SF | 5 | 10+ years | |
| | Ceiling - Lay-in | 104 | 432 | SF | 5 | 6-10 years | |
| | Doors - Transom Window | 104 | 6 | SF | 5 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 104 | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 104 | 432 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 104 | 6 | EA | 5 | 6-10 years | |
| | Power Distribution | 104 | 16 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | 104 | 798 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 105 | 683 | SF | 5 | 6-10 years | |
| | Doors - Transom Window | 105 | 6 | SF | 5 | 6-10 years | |



| Catego | ry : Room | | В | uilding | : Branc | h 2_Rosenwald | I Carroll |
|--------|-----------------------------|--------------------------------|----------|----------|---------|---------------|-----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 105 | 1 | EA | 5 | 6-10 years | |
| | Floor - Carpet | 105 | 578 | SF | 5 | 6-10 years | |
| | Floor - Tile | 105 | 105 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 105 | 8 | EA | 6 | 6-10 years | |
| | Power Distribution | 105 | 12 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 105 | 856 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 105 | 115 | SF | 5 | 10+ years | |
| | Work SInk | 105 | 1 | EA | 5 | 10+ years | |
| | Ceiling - Lay-in | Assistant Principal's Office | 134 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Assistant Principal's Office | 1 | EA | 5 | 6-10 years | |
| | Floor - Carpet | Assistant Principal's Office | 134 | SF | 5 | 6-10 years | |
| | Lighting - Lay-in | Assistant Principal's Office | 2 | ĒA | 6 | 6-10 years | |
| | Power Distribution | Assistant Principal's Office | 6 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Assistant Principal's Office | 429 | SF | 5 | 10+ years | |
| | Ceiling - Lay-in | Conference Room in Main Office | 174 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Conference Room in Main Office | 1 | EA | 5 | 6-10 years | |
| | Floor - Carpet | Conference Room in Main Office | 174 | SF | 5 | 6-10 years | |
| | Lighting - Lay-in | Conference Room in Main Office | 3 | EA | 6 | 6-10 years | |
| | Power Distribution | Conference Room in Main Office | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Conference Room in Main Office | 4 95 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | Conference Room in Main Office | 410 | SF | 5 | - | |
| | | | | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Engineer's Office | 147 | | | 6-10 years | |
| | Doors - Steel Doors incl hw | Engineer's Office | 1 | EA SF | 5 5 | 6-10 years | |
| | Floor - Tile | Engineer's Office | 147 | | | 6-10 years | |
| | Lighting - Lay-in | Engineer's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Engineer's Office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Engineer's Office | 394 | SF | 5 | 10+ years | |
| | Ceiling - Lay-in | Gym Office | 112 | SF | 5 | 6-10 years | |
| | Ceiling - Lay-in | Gym Office | 10 | SF | 5 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Gym Office | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | Gym Office | 122 | SF | 5 | 6-10 years | |
| | Lighting - Lay-in | Gym Office | 2 | EA | 6 | 6-10 years | |
| | Power Distribution | Gym Office | 4 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | Gym Office | 334 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | Gym Office | 66 | SF | 5 | 10+ years | |
| | Ceiling - Lay-in | Kitchen Office | 98 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | Kitchen Office | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Kitchen Office | 98 | SF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen Office | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | Kitchen Office | 6 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | Kitchen Office | 303 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Principal's Office | 376 | SF | 6 | 6-10 years | |
| | Doors - Transom Window | Principal's Office | 6 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 2 | EA | 6 | 6-10 years | |
| | | · | | | | • | |



| Catego | ry : Room | | В | uilding | : Branc | h 2_Rosenwald | d Carroll |
|---------|--------------------------------------|--------------------------|----------|---------|---------|---------------|-----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Carpet | Principal's Office | 376 | SF | 5 | 6-10 years | |
| | Lighting - Lay-in | Principal's Office | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | Principal's Office | 4 | EA | 6 | 10+ years | |
| | Storage/ Closet | Principal's Office | 8 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | Principal's Office | 270 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Office | 316 | SF | 5 | 10+ years | |
| | Ceiling - Plaster/Drywall | Work Room in Main Office | 243 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | Work Room in Main Office | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Work Room in Main Office | 243 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | Work Room in Main Office | 4 | EA | 5 | 6-10 years | |
| | Power Distribution | Work Room in Main Office | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Work Room in Main Office | 606 | SF | 5 | 10+ years | |
| | Work SInk | Work Room in Main Office | 1 | EA | 5 | 6-10 years | |
| | | | | | | , | |
| Gymnas | | | | | | | |
| | Ceiling - Exposed | 1st Floor | 3,962 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 5 | 6-10 years | |
| | Floor - Tile | 1st Floor | 3,962 | SF | 6 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 12 | EA | 5 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 88 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 6,588 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,012 | SF | 5 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 831 | SF | 5 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile | 1st Floor | 831 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 6 | 6-10 years | |
| | Serving Line | 1st Floor | 9 | LF | 5 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 190 | SF | 5 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,154 | SF | 6 | 10+ years | |
| | | | | | | - | |
| Library | 2 | | | | | | |
| | Ceiling - Lay-in | 203 | 1,715 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 203 | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 203 | 1,715 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 203 | 119 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 203 | 431 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 203 | 359 | SF | 7 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,223 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2,223 | EA | 6 | 10+ years | |
| | | | 2 | -// | 0 | ioi youio | |



| Category : Room | | | | | Building : Branch 2_Rosenwald Carroll | | | | | |
|-----------------|---------------------------------|------------------------|----------|-----|---------------------------------------|--------------|----------|--|--|--|
| | | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| - | Floor - Tile | 1st Floor | 2,223 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 10+ years | | | | |
| | Serving Line | 1st Floor | 10 | LF | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 1st Floor | 1,537 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 205 Multipurpose Room | 1,633 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 205 Multipurpose Room | 8 | SF | 7 | 10+ years | | | | |
| | Doors - Transom Window | 205 Multipurpose Room | 6 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 205 Multipurpose Room | 2 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | 205 Multipurpose Room | 1,641 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 205 Multipurpose Room | 20 | EA | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 205 Multipurpose Room | 537 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 205 Multipurpose Room | 7,790 | SF | 7 | 10+ years | | | | |
| MDF ID | F | | | | | | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | |
| | Finishes | 2nd Floor | 58 | SF | 7 | 10+ years | | | | |
| | Other Cooling Unit | 2nd Floor | 1 | EA | 7 | 10+ years | | | | |
| Mechani | cal/ Service Rooms | | | | | | | | | |
| | Boiler Room | Building Service Rooms | 369 | SF | 7 | 10+ years | | | | |
| | Janitor's Closet | Building Service Rooms | 35 | SF | 5 | 10+ years | | | | |
| | Janitor's Closet | Building Service Rooms | 35 | SF | 5 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 220 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 136 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 35 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 563 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 360 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Building Service Rooms | 650 | SF | 7 | 10+ years | | | | |
| | Storage Room | Building Service Rooms | 121 | SF | 7 | 10+ years | | | | |
| | Storage Room | Building Service Rooms | 205 | SF | 7 | 10+ years | | | | |
| Restroor | n | | | | | | | | | |
| | Accessories | 1st Floor SW | 142 | SF | 7 | 6-10 years | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor SW | 142 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor SW | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor SW | 142 | SF | 6 | 10+ years | | | | |
| | Floor Drain | 1st Floor SW | 1 | ĒA | 7 | 10+ years | | | | |
| | Lavatory | 1st Floor SW | 1 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 1st Floor SW | 7 | EA | 7 | 10+ years | | | | |
| | Partitions | 1st Floor SW | 3 | EA | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 1st Floor SW | 466 | SF | 7 | 10+ years | | | | |
| | Water Closet | 1st Floor SW | 3 | EA | 7 | 10+ years | | | | |
| | | | 5 | L/\ | ' | i u i youi u | | | | |



| Catego | ry : Room | | В | uilding | : Branc | h 2_Rosenwald | d Carroll |
|--------|---------------------------------|-----------------|----------|---------|---------|---------------|-----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 1st Floor SW | 142 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor SW | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor SW | 142 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor SW | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor SW | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor SW | 9 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor SW | 1 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor SW | 3 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor SW | 466 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor SW | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor West | 38 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor West | 38 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor West | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor West | 38 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor West | 1 | EA | 6 | 10+ years | |
| | Lighting - Wall Mounted | 1st Floor West | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor West | 201 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor West | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor North | 146 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor North | 147 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor North | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor North | 146 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor North | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor North | 9 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor North | 2 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor North | 492 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor North | 142 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor North | 142 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor North | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor North | 142 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor North | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor North | 9 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor North | 2 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor North | 142 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor North | 2 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor North | 51 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor North | 51 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor North | 51 | SF | 7 | 10+ years | |
| | Lavatory | 2nd Floor North | 1 | ĒA | 7 | 10+ years | |



| Category : Room Building : Branch 2_Rosenwald Carroll | | | | | | | d Carroll |
|---|---------------------------------|-------------------|----------|-----|------|-------------|-----------|
| e alege | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Wall Mounted | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor North | 201 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor North | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor SW | 240 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor SW | 240 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor SW | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor SW | 240 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor SW | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor SW | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor SW | 11 | EA | 6 | 10+ years | |
| | Partitions | 2nd Floor SW | 5 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor SW | 675 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor SW | 5 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor SW | 142 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor SW | 142 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor SW | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor SW | 142 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor SW | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor SW | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor SW | 9 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor SW | 2 | EA | 5 | 10+ years | |
| | Urinals | 2nd Floor SW | 4 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor SW | 466 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor SW | 2 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor South | 40 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor South | 40 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor South | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor South | 25 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor South | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor South | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor South | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor South | 220 | SF | 7 | 10+ years | |
| | Accessories | Engineer's Toilet | 83 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineer's Toilet | 83 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Engineer's Toilet | 1 | EA | 6 | 6-10 years | |
| | Floor - Concrete | Engineer's Toilet | 83 | SF | 5 | 10+ years | |
| | Lavatory | Engineer's Toilet | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Engineer's Toilet | 1 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | Engineer's Toilet | 1 | EA | 6 | 6-10 years | |
| | Student Lockers - One Tier | Engineer's Toilet | 3 | EA | 5 | 6-10 years | |
| | Walls - Concrete Block | Engineer's Toilet | 258 | SF | 6 | 10+ years | |
| | Water Closet | Engineer's Toilet | 1 | EA | 7 | 6-10 years | |
| | Accessories | Kitchen Toilet | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Kitchen Toilet | 45 | SF | 7 | 10+ years | |



Category : Room Building : Branch 2_Rosenwald Carroll Recommend Item - Type Group Location Quantity UOM Rank **Replacement** Comments Doors - Steel Doors incl hw **Kitchen Toilet** ΕA 6 10+ years 1 Floor - Tile **Kitchen Toilet** 45 SF 7 10+ years Lavatory **Kitchen Toilet** 1 ΕA 6 10+ years Lighting - Wall Mounted **Kitchen Toilet** 7 1 ΕA 10+ years Student Lockers - One Tier 3 **Kitchen Toilet** EΑ 6 10+ years SF Walls - Structural Glazed Tile 245 7 **Kitchen Toilet** 10+ years Water Closet **Kitchen Toilet** ΕA 7 10+ years 1 SF Accessories Main Office Toilet 36 7 6-10 years SF Ceiling - Plaster/Drywall Main Office Toilet 36 7 10+ years Doors - Wood Doors inclu hw ΕA 7 Main Office Toilet 1 10+ years SF Floor - Tile Ceramic/ Porcelain Main Office Toilet 36 7 10+ years Lavatory Main Office Toilet 1 ΕA 6 10+ years Lighting - Wall Mounted Main Office Toilet 1 ΕA 7 10+ years SF Walls - Structural Glazed Tile Main Office Toilet 7 201 10+ years Water Closet Main Office Toilet ΕA 7 1 10+ years

Category : Classroom

Building : Branch 2_Rosenwald Carroll

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|-----------------------------|-----------|----------|-----|-------|--------------------------|----------|
| | m #106 (Store Room) | Location | Quantity | 001 | Marik | Replacement | Commenta |
| | Casework | 1st Floor | 50 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 6-10 years | |
| | Chalk Board | 1st Floor | 11 | LF | 4 | 0-1 year | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 847 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 4 | LF | 6 | 2-5 years | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | |
| Classroo | m #107 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 859 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 0-1 year | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 859 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Branc | Building : Branch 2_Rosenwald Carroll | | | | | |
|----------|-----------------------------|-----------|----------|----------|---------|---------------------------------------|----------|--|--|--|--|
| _ | | | | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | | |
| Classroo | m #108 (Regular Classroom) | | | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 5 | 6-10 years | | | | | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 6-10 years | | | | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 0-1 year | | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | | | | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | | | | |
| | Floor - Tile | 1st Floor | 847 | SF | 6 | 6-10 years | | | | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 5 | 6-10 years | | | | | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 2-5 years | | | | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 7 | 10+ years | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | | | | |
| Classroo | m #109 (Regular Classroom) | | | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 5 | 6-10 years | | | | | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 6-10 years | | | | | |
| | Chalk Board | 1st Floor | 11 | LF | 4 | 0-1 year | | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 6-10 years | | | | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 6-10 years | | | | | |
| | Floor - Tile | 1st Floor | 847 | SF | 6 | 10+ years | | | | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 5 | 6-10 years | | | | | |
| | Marker Board | 1st Floor | 4 | LF | 6 | 2-5 years | | | | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 6 | 10+ years | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | | | | |
| Classroo | m #110 (Regular Classroom) | | | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 5 | 6-10 years | | | | | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 6-10 years | | | | | |
| | Chalk Board | 1st Floor | 11 | LF | 4 | 0-1 year | | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | | | | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | | | | |
| | Floor - Tile | 1st Floor | 847 | SF | 6 | 6-10 years | | | | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 5 | 6-10 years | | | | | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 2-5 years | | | | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | | | | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 6 | 10+ years | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | | | | |
| Classroo | m #111 (Regular Classroom) | | | | | | | | | | |
| | Casework | 1st Floor | 50 | LF | 7 | 6-10 years | | | | | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 6-10 years | | | | | |
| | | | 311 | <u> </u> | - | | | | | | |



| Catego | ry : Classroom | В | Building : Branch 2_Rosenwald Carroll | | | | | |
|----------|-----------------------------|-----------|---------------------------------------|-----|------|-------------|-------------------------------------|--|
| | ., | | _ | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | |
| | Floor - Tile | 1st Floor | 847 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 14 | LF | 6 | 2-5 years | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | |
| Classroc | m #112 (Store Room) | | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | 6-10 years | | |
| | Ceiling - Lay-in | 1st Floor | 12 | SF | 7 | 10+ years | | |
| | Chalk Board | 1st Floor | 11 | LF | 4 | 0-1 year | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | |
| | Floor - Tile | 1st Floor | 847 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 11 | LF | 6 | 2-5 years | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 446 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | |
| Classroo | m #113 (Store Room) | | | | | | | |
| | Casework | 1st Floor | 30 | LF | 5 | 6-10 years | | |
| | Ceiling - Lay-in | 1st Floor | 847 | SF | 5 | 10+ years | | |
| | Chalk Board | 1st Floor | 16 | LF | 4 | 0-1 year | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | ĒA | 7 | 6-10 years | | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 6 | 6-10 years | | |
| | Floor - Tile | 1st Floor | 847 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 12 | ĒA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 10 | LF | 6 | 2-5 years | | |
| | Storage/ Closet | 1st Floor | 12 | SF | 7 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 496 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 456 | SF | 7 | 10+ years | | |
| Classroo | om #200 (Store Room) | | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 408 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 12 | SF | 4 | 2-5 years | Small section of ceiling is failing | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 420 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 10+ years | | |
| | | | | | | | | |



| Catego | ry : Classroom | ategory : Classroom | | | | | Building : Branch 2_Rosenwald Carroll | | | | | |
|----------|-----------------------------|---------------------|----------|-----|------|-------------|---------------------------------------|--|--|--|--|--|
| | | | | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | | | |
| lassroo | m #201 (Science Classroom) | | | | | | | | | | | |
| 01000100 | Casework | 2nd Floor | 34 | LF | 6 | 10+ years | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1.021 | SF | 7 | 10+ years | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 100 | SF | 5 | 6-10 years | | | | | | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | | | | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | | | |
| | Floor - Tile | 2nd Floor | 1,121 | SF | 6 | 10+ years | | | | | | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 10+ years | | | | | | |
| | Marker Board | 2nd Floor | 4 | LF | 7 | 6-10 years | | | | | | |
| | Storage/ Closet | 2nd Floor | 100 | SF | 7 | 10+ years | | | | | | |
| | Walls - Concrete Block | 2nd Floor | 780 | SF | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 236 | SF | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 230 | SF | 6 | 10+ years | | | | | | |
| | Work Sink | 2nd Floor | 20 | EA | 7 | 10+ years | | | | | | |
| | Work Sink | | I | LA | ' | 10+ years | | | | | | |
| Classroo | m #202 (Store Room) | | | | | | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 571 | SF | 7 | 6-10 years | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 10 | SF | 5 | 6-10 years | | | | | | |
| | Chalk Board | 2nd Floor | 6 | LF | 4 | 2-5 years | | | | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Floor - Tile | 2nd Floor | 581 | SF | 7 | 10+ years | | | | | | |
| | Lighting - Lay-in | 2nd Floor | 8 | EA | 7 | 10+ years | | | | | | |
| | Walls - Concrete Block | 2nd Floor | 475 | SF | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 380 | SF | 7 | 10+ years | | | | | | |
| lassroo | m #204 (Computer Lab) | | | | | | | | | | | |
| 2.000.00 | Casework | 2nd Floor | 20 | LF | 7 | 10+ years | - | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 985 | SF | 7 | 10+ years | | | | | | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | | | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 10 | EA | 6 | 10+ years | | | | | | |
| | Floor - Tile | 2nd Floor | 985 | SF | 7 | 10+ years | | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 6 | EA | 7 | 10+ years | | | | | | |
| | Walls - Concrete Block | 2nd Floor | 558 | SF | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 558 | SF | 7 | 10+ years | | | | | | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | | | | | | |
| Classroo | m #206 (Art Room) | | | | | | | | | | | |
| | Casework | 2nd Floor | 68 | LF | 7 | 10+ years | | | | | | |
| | Casework | 2nd Floor | 4 | LF | 6 | 2-5 years | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,123 | SF | 7 | 10+ years | | | | | | |



| Catego | ry : Classroom | | R | Building : Branch 2_Rosenwald Carroll | | | | | | |
|----------|-----------------------------|-----------|----------|---------------------------------------|------|-------------|-----------------------------------|--|--|--|
| Julogo | | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Ceiling - Lay-in | 2nd Floor | 12 | SF | 5 | 2-5 years | | | | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | | | | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 1,135 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | | | | |
| | Storage/ Closet | 2nd Floor | 33 | SF | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor | 756 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 437 | SF | 7 | 10+ years | | | | |
| Classroo | om #207 (Regular Classroom) | | | | | | | | | |
| | Casework | 2nd Floor | 30 | LF | 6 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 599 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 5 | 6-10 years | | | | |
| | Chalk Board | 2nd Floor | 18 | LF | 4 | 2-5 years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 605 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor | 1,114 | SF | 7 | 10+ years | | | | |
| Classroo | om #208 (Store Room) | | | | | | | | | |
| | Casework | 2nd Floor | 50 | LF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 797 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 50 | SF | 4 | 2-5 years | Section of roofing needs replaced | | | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | c . | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | |
| | Doors - Transom Window | 2nd Floor | 1 | SF | 6 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 6 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | | | | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | 6-10 years | | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor | 446 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 456 | SF | 7 | 10+ years | | | | |
| Classroo | om #209 (Regular Classroom) | | | | | | | | | |
| | Casework | 2nd Floor | 50 | LF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 5 | 2-5 years | | | | |
| | Chalk Board | 2nd Floor | 11 | LF | 4 | 2-5 years | | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | | | | |



| Catego | ry : Classroom | | B | 2929 W 83rd STREET, Chicago, IL 60652 Building : Branch 2_Rosenwald Carroll | | | | | |
|------------|--|------------------------|-----------|--|------|------------------------|----------|--|--|
| Jacogo | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| 5. 5 G P | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 450 | SF | 7 | 10+ years | | | |
| Classroo | om #210 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 5 | 2-5 years | | | |
| | Chalk Board | 2nd Floor | 11 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | ĒA | 7 | 10+ years | | | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 450 | SF | 7 | 10+ years | | | |
| 21/2/00/07 | om #211 (Regular Classroom) Casework Coiling Lavin | 2nd Floor | 50 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 832 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 15 | SF | 5 | 6-10 years | | | |
| | Chalk Board | 2nd Floor | 11 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | | | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 435 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 15 | SF | 5 | 10+ years | | | |
| Classroo | om #212 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 50 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 847 | SF | 7 | 10+ years | | | |
| | Chalk Board | 2nd Floor | 11 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | | | 0.47 | SF | 7 | | | | |
| | Floor - Tile | 2nd Floor | 847 | 55 | 7 | 10+ years | | | |
| | Floor - Tile Lighting - Lay-in | 2nd Floor 2nd Floor | 847 12 | EA | 7 | 10+ years 10+ years | | | |



| Catego | ry : Classroom | | В | Building : Branch 2_Rosenwald Carroll | | | | | |
|----------|-----------------------------|-----------|----------|---------------------------------------|---------|---------------|-------------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 450 | SF | 7 | 10+ years | | | |
| Classroo | m #213 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 50 | LF | 6 | 6-10 years | | | |
| | Ceiling - Lay-in | 2nd Floor | 817 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 30 | SF | 4 | 1-2 years | Ceiling tile is damaged | | |
| | Chalk Board | 2nd Floor | 11 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | | | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 450 | SF | 6 | 10+ years | | | |
| Classroo | m #214 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | | | |
| | Ceiling - Lay-in | 2nd Floor | 805 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 2nd Floor | 42 | SF | 5 | 6-10 years | | | |
| | Chalk Board | 2nd Floor | 7 | LF | 4 | 2-5 years | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 6 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 847 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 10 | ĒA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 14 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 450 | SF | 6 | 10+ years | | | |
| Catego | ry : Interior | | В | uildina | : Branc | h 2_Rosenwald | d Carroll | | |

| | | | | | | Recommend | |
|----------|-------------------------------|-----------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st North | 1,536 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st North | 18 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st North | 8 | EA | 6 | 6-10 years | |
| | Doors - Wood Doors include hw | 1st North | 12 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 1st North | 1,563 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st North | 20 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st North | 3 | EA | 7 | 6-10 years | |



Building : Branch 2 Rosenwald Carroll Category : Interior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Concrete Block 1st North 1.303 SF 10+ vears 7 Ceiling - Plaster/Drvwall 1.877 SF 1st South 6 10+ vears Doors - Steel Doors incl hw 1st South 4 EΑ 5 6-10 years Drinking Fountains - Single Fountain 1st South 3 ΕA 5 6-10 years SF 7 Floor - Tile/Sheet 1st South 80 10+ years Lighting - Lay-in 1st South 26 EΑ 6 10+ years Walls - Concrete Block 1st South SF 7 10+ years 3,945 Ceiling - Plaster/Drywall SF 1st West 744 5 10+ years Floor - Tile/Sheet 1st West 744 SF 5 10+ years Lighting - Lay-in 1st West 8 EΑ 6 6-10 years Walls - Concrete Block 1st West 1.296 SF 7 10+ vears Ceiling - Plaster/Drywall 2nd Middle 795 SF 7 10+ years Floor - Tile/Sheet 2nd Middle 795 SF 7 10+ years 7 Lighting - Lay-in 2nd Middle 7 EA 10+ years Walls - Concrete Block SF 7 2nd Middle 1,292 10+ years Ceiling - Plaster/Drywall SF 2nd North 947 6 10+ years Doors - Steel Doors incl hw ΕA 2nd North 2 6 10+ years Floor - Tile/Sheet 2nd North 947 SF 7 10+ years Lighting - Lav-in 2nd North 10 EΑ 7 10+ vears Walls - Concrete Block 2nd North 971 SF 7 10+ years Ceiling - Plaster/Drywall 2nd South 884 SF 6 10+ years Doors - Steel Doors incl hw 2nd South 3 EΑ 6 10+ years Drinking Fountains - Single Fountain 2 7 2nd South EΑ 10+ years SF Floor - Tile/Sheet 2nd South 884 7 10+ years Lighting - Lay-in ΕA 7 2nd South 13 10+ years Walls - Concrete Block 2nd South 2.559 SF 7 10+ vears SF Ceiling - Lay-in Admin. Corridor 175 6 6-10 years Doors - Steel Doors incl hw Admin. Corridor ΕA 6 6-10 years 1 SF 7 Floor - Tile/Sheet Admin. Corridor 175 6-10 years Lighting - Lay-in Admin. Corridor 3 ΕA 6 6-10 years Walls - Concrete Block Admin. Corridor 18 SF 6 10+ years SF Walls - Plaster/Drvwall Admin. Corridor 306 6 10+ vears Safety **Camera Viewing Station Throughout Building** 3 ΕA 7 10+ years **Throughout Building** 7 Security Cameras 12 EΑ 10+ years Stairs Floor - Concrete East 13 SF 5 6-10 years 5 LF Handrails East 58 6-10 years LF 6 Stairs - Concrete East 104 6-10 years Walls - Concrete Block 193 SF 6 10+ years East SF Walls - Plaster/Drywall East 120 5 10+ years Ceiling - Plaster/Drywall North Stair 258 SF 6 10+ years



| atego | ry : Interior | | В | uilding | : Branc | h 2_Rosenwald | d Carroll |
|---------|-------------------------------|-----------------------------------|----------|---------|---------|---------------|-----------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | North Stair | 39 | SF | 6 | 10+ years | |
| | Handrails | North Stair | 58 | LF | 5 | 6-10 years | |
| | Lighting - Lay-in | North Stair | 4 | EA | 5 | 6-10 years | |
| | Stairs - Concrete | North Stair | 150 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | North Stair | 696 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | North Stair | 231 | SF | 5 | 10+ years | |
| | Ceiling - Plaster/Drywall | North Stair Bsmt/1st | 322 | SF | 6 | 10+ years | |
| | Floor - Concrete | North Stair Bsmt/1st | 136 | SF | 5 | 10+ years | |
| | Handrails | North Stair Bsmt/1st | 64 | LF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | North Stair Bsmt/1st | 4 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | North Stair Bsmt/1st | 150 | LF | 5 | 10+ years | |
| | Walls - Concrete Block | North Stair Bsmt/1st | 1,180 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | South Stair @ Kitchen / Boiler Rm | 325 | SF | 5 | 10+ years | |
| | Floor - Concrete | South Stair @ Kitchen / Boiler Rm | 68 | SF | 5 | 10+ years | |
| | Handrails | South Stair @ Kitchen / Boiler Rm | 62 | LF | 5 | 6-10 years | |
| | Lighting - Pendent/Surface | South Stair @ Kitchen / Boiler Rm | 3 | EA | 5 | 6-10 years | |
| | Stairs - Concrete | South Stair @ Kitchen / Boiler Rm | 75 | LF | 5 | 10+ years | |
| | Walls - Concrete Block | South Stair @ Kitchen / Boiler Rm | 736 | SF | 5 | 10+ years | |
| | Floor - Concrete | West Stair | 13 | SF | 5 | 6-10 years | |
| | Handrails | West Stair | 58 | LF | 5 | 6-10 years | |
| | Stairs - Concrete | West Stair | 104 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | West Stair | 193 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | West Stair | 120 | SF | 5 | 10+ years | |
| ertical | Conveyance | | | | | | |
| Lucal V | Elevator - Hydraulic Elevator | | 1 | EA | 6 | 10+ years | |



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Civil/Drainage FΑ 7 Civil/ Drainage - Catch Basin Entire Site - Branch 1 4 10+ years 6 FΑ 7 Civil/ Drainage - Site Drain Entire Site - Branch 1 10+ years Civil/ Drainage - Catch Basin 6 Entire Site - Branch 2 EΑ 7 10+ years Civil/ Drainage - Site Manhole Entire Site - Branch 2 10 ΕA 7 10+ years Civil/ Drainage - Catch Basin Entire Site - Main 2 EΑ 7 10+ years Civil/ Drainage - Site Drain Entire Site - Main 5 ΕA 6 10+ years Civil/ Drainage - Site Manhole Entire Site - Main 7 EΑ 7 10+ years Fencina Fencing - Chain Link LF Entire Site - Branch 1 290 6 10+ years Fencing - Chain Link Entire Site - Branch 2 1,588 LF 6 6-10 years Fencing - New Standard Ornamental Entire Site - Branch 2 LF 6 10+ years 176 LF Fencing - New Standard Ornamental Entire Site - Main 761 7 10+ years LF Fencing - New Standard Ornamental Entire Site - Main 16 4 2-5 years A northern seciton of the exterior fencing has been damaged for serveral years and is falling over Landscape Landscape - Grass Entire Site - Branch 1 SF 7 10+ years 18.720 Lighting - Lighting Entire Site - Branch 1 12 EΑ 7 10+ years Parkway trees Entire Site - Branch 1 26 EΑ 6 10+ years Planting Beds/ Area Entire Site - Branch 1 1,125 SF 6 10+ years Trash Receptacles Entire Site - Branch 1 2 EΑ 7 10+ years Landscape - Grass Entire Site - Branch 2 SF 7 10+ years 69.530 SF Landscape - Hardscape- Concrete Entire Site - Branch 2 20,779 6 10+ years ΕA 7 Parkway trees Entire Site - Branch 2 46 10+ years Parkway trees Entire Site - Branch 2 1 FΑ 4 2-5 years Tree needs to be removed and replaced due to extensive damage Planting Beds/ Area Entire Site - Branch 2 390 SF 7 10+ years Trash Receptacles Entire Site - Branch 2 EΑ 6 6-10 years 1 SF Landscape - Grass Entire Site - Main 53,928 7 10+ years Landscape - Hardscape- Asphalt SF Entire Site - Main 9,372 7 10+ years Parkway trees Entire Site - Main 12 ΕA 6 10+ years Planting Beds/ Area Entire Site - Main 800 SF 6 10+ years Parking Lot Concrete Curbs Entire Site - Branch 1 LF 6 420 10+ years Lighting - Pole Mounted Entire Site - Branch 1 4 EΑ 6 10+ years SF 5 Surface - Asphalt Entire Site - Branch 1 10.430 2-5 years SF Trash Enclosure - Chain Links Entire Site - Branch 1 400 6 10+ years LF Concrete Curbs 6 Entire Site - Branch 2 1.017 10+ years



| ALL A | | | | uilding | | | 2929 W 83rd STREET, Chicago, IL 60652 |
|----------|--|------------------------|----------|---------|------|-------------|---------------------------------------|
| Catego | ry : Site | | В | | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Interior Plantings | Entire Site - Branch 2 | 11 | LF | 6 | 6-10 years | |
| | Surface - Asphalt | Entire Site - Branch 2 | 17,998 | SF | 6 | 6-10 years | |
| | Trash Enclosure - Chain Links | Entire Site - Branch 2 | 432 | SF | 6 | 10+ years | |
| | Vehicular Screening | Entire Site - Branch 2 | 60 | LF | 7 | 10+ years | |
| | Concrete Curbs | Entire Site - Main | 160 | LF | 6 | 10+ years | |
| | Concrete Curbs | Entire Site - Main | 50 | LF | 5 | 6-10 years | |
| | Surface - Asphalt | Entire Site - Main | 8,400 | SF | 6 | 10+ years | |
| | Surface - Asphalt | Entire Site - Main | 928 | SF | 5 | 6-10 years | |
| Playgrou | Ind | | | | | | |
| | Equipment - School Age 5-12 | Entire Site - Branch 1 | 1 | EA | 6 | 6-10 years | |
| | Surface - Square Rubber Mats | Entire Site - Branch 1 | 2,148 | SF | 4 | 1-2 years | Tiles show extensive damage and |
| | | | | | | | passed repair and will need to be |
| | | | | | | | replaced |
| Sidewall | < <u>s</u> | | | | | | |
| | Sidewalks - Internal Walks | Entire Site - Branch 1 | 521 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site - Branch 1 | 3,854 | SF | 6 | 10+ years | |
| | Sidewalks - Internal Walks | Entire Site - Branch 2 | 275 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site - Branch 2 | 13,146 | SF | 6 | 10+ years | |
| | Sidewalks - Internal Walks | Entire Site - Main | 170 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site - Main | 4,368 | SF | 6 | 10+ years | |
| Signage | | | | | | | |
| 0 0 | Flag Pole - Flag Pole | Entire Site - Branch 1 | 1 | EA | 7 | 10+ years | |
| | Monument - Building Mounted Cut Letter | Entire Site - Branch 1 | 1 | EA | 7 | 10+ years | |
| | Sign | | | | | | |
| | Flag Pole - Flag Pole | Entire Site - Branch 2 | 1 | EA | 7 | 10+ years | |
| | Flag Pole - Flag Pole | Entire Site - Branch 2 | 1 | EA | 6 | 10+ years | |
| | Marquee - Free Standing Back Lighted | Entire Site - Branch 2 | 1 | EA | 6 | 6-10 years | |
| | Monument - Building Mounted Cut Letter | Entire Site - Branch 2 | 1 | EA | 7 | 10+ years | |
| | Sign | | | | | | |
| | Flag Pole - Flag Pole | Entire Site - Main | 1 | EA | 7 | 10+ years | |
| | Marquee - Free Standing Back Lighted | Entire Site - Main | 1 | EA | 6 | 6-10 years | |
| | Monument - Building Mounted Cut Letter | Entire Site - Main | 1 | EA | 7 | 10+ years | |
| | Sign | | | | | | |
| | - | | | | | | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | | Deem | Floor Plan | A.r.o.o. | Glazed | Operable | Window | Smort |
|-----------------------------|---------------------|---------------|----------------|----------------|--------------|----------------|----------------|----------------|-----------------|
| Current Usage | Intended Usage | Room Location | Room Number | Room Number | Area (SF) | Window Area | Window Area | Window Stop | Smart- Board |
| Building : Main | Intended Usage | Room Location | Nullibei | Number | (37) | Alea | Alea | Stop | Duaru |
| Regular Classroom | Kindergarten | 1st Floor | 101 | 5 | 825 | 216 | 20 | N | N |
| Regular Classroom | Kindergarten | 1st Floor | 101 | N/A | 580 | 210 | 20 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 5 | 733 | 210 | 20 | N | N N |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 6 | 739 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 7 | 733 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 4 | 733 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 107 | 733 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 22 | 733 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 22 | 733 | 210 | 20 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 111 | 733 | 210 | 20 | N | Y |
| Regular Classicolli | Regular Classicolli | | 111 | 111 | 133 | 210 | 20 | IN | <u> </u> |
| Building : Branch 2_Rosenwa | ld Carroll | | | | | | | | |
| Art Room | Regular Classroom | 2nd Floor | 206 | 216 | 1,168 | 135 | 67 | N | Y |
| Computer Lab | Computer Lab | 2nd Floor | 204 | 200 | 985 | 100 | 60 | N | N |
| Regular Classroom | Music Room | 2nd Floor | 213 | 230 | 859 | 135 | 68 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 118 | 859 | 135 | 68 | N | Ň |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 119 | 859 | 135 | 68 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 120 | 859 | 135 | 68 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 121 | 859 | 135 | 68 | N | Ý |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 122 | 859 | 135 | 68 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 217 | 605 | 135 | 67 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 226 | 859 | 135 | 68 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 227 | 859 | 135 | 68 | N | Ý |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 228 | 859 | 135 | 68 | N | Ý |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 229 | 859 | 135 | 68 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 214 | 231 | 859 | 135 | 68 | N | N |
| Science Classroom | Science Classroom | 2nd Floor | 201 | 204 | 1,221 | 166 | 83 | N | N |
| Store Room | Regular Classroom | 1st Floor | 106 | 116 | 859 | 135 | 68 | N | N |
| Store Room | Regular Classroom | 1st Floor | 112 | 123 | 859 | 135 | 68 | N | N |
| Store Room | Regular Classroom | 1st Floor | 113 | 124 | 859 | 135 | 68 | N | N |
| Store Room | Regular Classroom | 2nd Floor | 200 | 207 | 420 | 136 | 68 | N | N |
| Store Room | Regular Classroom | 2nd Floor | 202 | 203 | 581 | 100 | 50 | N | N |
| Store Room | Regular Classroom | 2nd Floor | 208 | 225 | 859 | 100 | 60 | N | Y |
| | | | | | | | | | |
| Building : Branch 1_Rosenwa | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 01 | 101 | 1,045 | 231 | 115 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 02 | 102 | 1,017 | 231 | 115 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 03 | 103 | 1,014 | 231 | 115 | N | Y |



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart- Board |
|-------------------|-------------------|---------------|----------------|------------------------------|--------------|--------------------------|----------------------------|----------------|-----------------|
| Regular Classroom | Regular Classroom | 1st Floor | 04 | 104 | 964 | 308 | 154 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 05 | 105 | 1,030 | 231 | 115 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 06 | 106 | 1,030 | 231 | 115 | N | Y |