

Facility Assessment Report

Superstructure - Steel

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1998 | 2 | 36,864 |
| Campus Total | | | 36,864 |

Category: Exterior **Building: Main** Recommend Replacement Comments Item - Type Location Quantity **UOM** Rank Group Entrance Entrance Control - Audio and Video #1 - Main - S 1 EΑ 6 6-10 years Exterior Doors - Side lite #1 - Main - S 2 EΑ 7 10+ years Exterior Doors - Store Front #1 - Main - S 2 FΑ 7 10+ years Exterior Doors - Transom Lite #1 - Main - S FΑ 7 1 10+ years #2 - SE Exterior Doors - Exterior Steel Door 1 FΑ 7 10+ years Exterior Doors - Transom Lite #2 - SE 1 FΑ 7 10+ years Exterior Doors - Exterior Steel Door #3 - SE 1 EΑ 6 10+ years Exterior Doors - Transom Lite #3 - SE 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #4 - E EΑ 6 1 10+ years Entrance Control - Audio and Video #5 - E FΑ 6 6-10 years #5 - E 2 EΑ Exterior Doors - Store Front 6 10+ years Exterior Doors - Transom Lite #5 - E 1 FΑ 10+ years Exterior Doors - Exterior Steel Door #6 - NF FΑ 2-5 years 1 Exterior Doors - Store Front #7 - NW 2 FΑ 10+ years Exterior Doors - Transom Lite #7 - NW 1 EΑ 7 10+ years Exterior Doors - Exterior Steel Door #8 - SW EΑ 1 6 10+ years #8 - SW Exterior Doors - Transom Lite EΑ 6 10+ years Exterior Doors - Exterior Steel Door #9 - SW 1 EΑ 6 10+ years Exterior Doors - Transom Lite #9 - SW FΑ 6 1 10+ years Foundation Foundation - Concrete LF 7 **Entire Building** 795 10+ years

Entire Building

SF

38,342

7

10+ years



| Catego | ry : Exterior | | В | uilding | : Main | _ | |
|----------|--------------------------------------|-------------------|----------|---------|--------|-----------------------|---|
| Group | Itom - Typo | Location | Quantity | LIOM. | Pank | Recommend | Comments |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Lighting | Exterior Limbing Mounted | Entine Divilation | 40 | Ε, | 7 | 10 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 18 | EA | 7 | 10+ years | |
| Roof Sys | tem | | | | | | |
| | Access Ladder - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Chimney - Metal Flue | Main Roof | 20 | LF | 6 | 10+ years | |
| | Coping - Stone | Main Roof | 795 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Main Roof | 248 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Main Roof | 120 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | Main Roof | 675 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Main Roof | 21,985 | SF | 3 | 0-1 year | Active leaks throughout, numerous |
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | patches, worn surface. |
| | Roof Structure - Steel / Metal Deck/ | Main Roof | 21,985 | SF | 7 | 10+ years | |
| | Concrete Topping | | , | | | , | |
| Valls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 192 | SF | 7 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 24,645 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 2,120 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 10 | SF | 7 | 10+ years | |
| Vindows | | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 113 | SF | 7 | 10+ years | |
| | Curtain wall - Louver | Entire Building | 76 | SF | 7 | 10+ years | |
| | Guard - Guards perforated | Entire Building | 152 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 479 | LF | 7 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 2,838 | SF | 7 | 10+ years | |
| Catego | ry : Electrical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| • | cy System | Location | Quantity | COM | Raine | Ropidoomon | |
| -0 | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 10 | EA | 6 | 2-5 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 2 | EA | 4 | 0-1 year | Exit signs in 2nd floor stairway and outside room 202 need to be replaced |
| | Exit Signs - Gym | Entire Building | 3 | EA | 6 | 2-5 years | Торійови |
| | Exit Signs - Gym | Entire Building | 1 | EA | 4 | 0-1 year | Exit sign does not function. Needs to be replaced |
| | | | | | | | |
| | Exit Signs - Lunchroom | Entire Building | 8 | EA | 6 | 2-5 years | 20 Topiacou |

Campus Name: Keller Page : 2 of 18 Assessment Date: 07/29/2019



| Catego | ry : Electrical | | В | uilding | : Main | | oozo W room CTNEET, Omoago, 12 ooooo |
|---------|--|-----------------|----------|---------|--------|-------------|--------------------------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 7,534 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Gym | Entire Building | 3,521 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 236 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Multipurpose Room | Entire Building | 2,158 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 836 | SF | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 36,864 | SF | 7 | 10+ years | |
| | Security System - Intrusion Detection | Entire Building | 36,864 | SF | 7 | 10+ years | |
| Main Se | rvice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 7 | 10+ years | |
| | Main Electrical Service - 1600 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 10+ years | |
| | PA System | Entire Building | 36,864 | SF | 6 | 6-10 years | |
| Power D | listribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 9 | EA | 6 | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 6 | 10+ years | |

Category: Fire Protection Building: Main

| | | | | | | Recommend | |
|-----------|--------------------------|-----------------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alaı | m | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 10+ years | |
| | Fire Alarm Strobe Lights | Entire Building | 36,864 | SF | 6 | 10+ years | |
| | Fire Alarm_System | Entire Building | 36,864 | SF | 6 | 10+ years | |
| | Fire Pump Controller | Entire Building | 1 | EA | 6 | 10+ years | |
| Pump R | oom Assembly | | | | | | |
| - | Fire Pump - 25-50 hp | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Jockey Pump | 1st Floor | 1 | EA | 6 | 6-10 years | |
| Sprinkle | r System | | | | | | |
| | Sprinkler Heads | Entire Building | 36,864 | SF | 7 | 6-10 years | |
| | Sprinkler Piping | Entire Building | 36,864 | SF | 6 | 6-10 years | |
| | | | | | | | |

Campus Name: Keller Page : 3 of 18 Assessment Date: 07/29/2019



| Catego | ry : Fire Protection | | В | uilding | : Main | | |
|-----------|---|-----------------|----------|---------|--------|-------------|--|
| | , | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Wet Sprinkler System | Entire Building | 36,864 | SF | 6 | 6-10 years | |
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Cond | itioning | | | | | | |
| | Chemical Pot Feeder | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Chiller-Air Cooled- Recipricating-Roof Mounted - 101 - 200 tons | Entire Building | 1 | EA | 5 | 6-10 years | Maintenance issues with condensing fans. |
| | Glycol Feed | Entire Building | 1 | EA | 6 | 2-5 years | |
| Air Hand | ling Systems | | | | | | |
| | Outdoor Return Fans- Air Handling Unit Type - Less than 5000 CFM | 2nd Floor | 2 | EA | 6 | 6-10 years | They are not outdoor fans. |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 25 | EA | 6 | 6-10 years | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 15001- 20000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001- 30000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Air Intake | Mechanical Room | 2 | EA | 6 | 6-10 years | |
| | VAV Box | Mechanical Room | 4 | EA | 6 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm | Roof | 1 | EA | 6 | 6-10 years | |
| Boiler Sy | estems | | | | | | |
| - | Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Glycol Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 2 | EA | 4 | 2-5 years | One boiler does not work. Heat exchanger needs to be replaced. |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | 1st Floor | 3 | EA | 6 | 6-10 years | |

Campus Name: Keller Page : 4 of 18 Assessment Date: 07/29/2019



| Recommend Recommend Recommend Replacement Comments | Catego | ry : Mechanical | | I | Building | : Main | | |
|--|------------|---|-----------------|----------|----------|--------|-------------|---|
| Radiator Panels - Hot Water 1st Floor 84 EA 6 6-10 years Wall Heater - Electric Entire Building 1 EA 6 6-10 years Mechanical Plumbing 1 EA 5 6-10 years Mechanical Plumbing 1 EA 5 6-10 years Mechanical Plumbing 2 EA 5 6-10 years Mechanical Plumbing 2 EA 5 6-10 years Mechanical Plumbing 2 EA 6 6-10 years Mechanical Plumbing 2 EA 6 6-10 years Mechanical Plumbing 2 EA 6 6-10 years Mechanical Plump - Less than 10 Entire Building 600 LF 6 6-10 years Mechanical Plump - Less than 10 Entire Building 2 EA 6 6-10 years Mechanical Plump - Less than 10 Entire Building 36,884 SF 5 6-10 years Mechanical Plumbing Mechanica | | | | | | | Recommend | |
| Radiator Panels - Hot Water 1st Floor 84 EA 6 6-10 years Wall Heater - Electric Entire Building 1 EA 6 6-10 years Wall Heater - Electric Entire Building 3 EA 6 6-10 years Wall Heater - Electric Entire Building 3 EA 6 6-10 years Wall Heater - Electric Entire Building 3 EA 6 6-10 years Wall Heater - Electric Entire Building 600 EF 6 6-10 years Wall Heater Fleury East shan 10 Entire Building 600 EF 6 6-10 years Wall Heater Fleury East shan 10 Entire Building 2 EA 6 6-10 years Wall Heater Fleury Wall Heater Heater Wall Heater Wall Heater Wall Heater Wall Heater Wal | Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Unit Heater - Electric Entire Building 3 EA 6 6-10 years Mechanical Plumbing | - | | 1st Floor | 84 | EA | 6 | 6-10 years | |
| Machanical Plumbing | | Wall Heater - Electric | Entire Building | 1 | EA | 6 | 6-10 years | |
| Dual Temperature Pump - Less than 10 | | Unit Heater - Electric | Entire Building | 3 | EA | 6 | 6-10 years | |
| Dual Temperature Pump - Less than 10 | Machani | cal Plumbing | | | | | | |
| Hydronic Supply and Return - Steel Entire Building 2 | vicciiaiii | | Poilor Poom | 2 | ΕΛ | 5 | 6.10 years | |
| Hot Water Pump - Less than 10 | | | | | | | | |
| Chilled Water Pump - Less than 10 Entire Building 2 EA 6 6-10 years Femperature Control DDC System | | | | | | | | |
| Properative Control DDC System Entire Building 36,864 SF 5 6-10 years Ability to modify individual zon points could be added in front system. Thermostats - DDC Entire Building 36 EA 6 6-10 years Thermostats - DDC Entire Building 2 EA 4 0-1 year Thermostats in the second florestrooms are damaged | | | | | | | | |
| DDC System Entire Building 36,864 SF 5 6-10 years Ablity to modify individual zon points could be added in front system. Thermostats - DDC Entire Building 36 EA 6 6-10 years Thermostats in the second flor restrooms are damaged Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 3 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than 500 CFM Exhaust Fans- Roof Mounted - Less than 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 2 EA 7 10+ years Category: Plumbing Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers to Domestic Piping-Cold Water Risers to Domestic Piping-Cold Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Entire Building 36,864 SF | | Chilled Water Pump - Less than 10 | Entire Building | 2 | EA | 6 | 6-10 years | |
| Thermostats - DDC Entire Building 36 EA 6 6-10 years Thermostats - DDC Entire Building 2 EA 4 0-11 year Thermostats in the second flor restrooms are damaged Ventilation | Tempera | ature Control | | | | | | |
| Thermostats - DDC Entire Building 36 EA 6 6-10 years Thermostats - DDC Entire Building 2 EA 4 0-1 year Thermostats in the second flor restrooms are damaged Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 3 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 2 EA 6 6-10 years 500 CFM Exhaust Fans- Roof Mounted - Less than Entire Building 1 EA 6 6-10 years 500 CFM Type II Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 7 10+ years Category: Plumbing Building: Main Recommend Replacement Comments Group Item - Type Location Quantity UOM Rank Replacement Comments Figure Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water From Risers to Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | DDC System | Entire Building | 36,864 | SF | 5 | 6-10 years | Ability to modify individual zone se |
| Thermostats - DDC Entire Building 36 EA 6 6-10 years Thermostats - DDC Entire Building 2 EA 4 0-1 year Thermostats in the second flor restrooms are damaged Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 3 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category : Plumbing Building : Main Group Item - Type Location Quantity UOM Rank Replacement Comments Piping Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water From Risers to Entire Building 36,864 SF 6 6-10 years Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | | | | | | points could be added in front en |
| Thermostats - DDC Entire Building 2 EA 4 0-1 year Thermostats in the second flor restrooms are damaged Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 3 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 2 EA 6 6-10 years 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category: Plumbing Building: Main Group Item - Type Location Quantity UOM Rank Recommend Replacement Comments Piping Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water From Risers to Entire Building 36,864 SF 6 6-10 years | | | | | | | | system. |
| Ventilation Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 3 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 2 EA 6 6-10 years 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category: Plumbing Building: Main Recommend Replacement Comments Category: Plumbing 2 EA 7 10+ years Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years | | | | | | | | |
| Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building 1 EA 6 6-10 years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 2 EA 6 6-10 years 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category: Plumbing Building: Main Group Item - Type | | Thermostats - DDC | Entire Building | 2 | EA | 4 | 0-1 year | Thermostats in the second floor restrooms are damaged |
| CFM Exhaust Fans- Roof Mounted - 500 - 1500 Entire Building CFM Exhaust Fans- Roof Mounted - Less than Entire Building Exhaust Fans- Roof Mounted - Less than Entire Building Exhaust Fans- Roof Mounted - Less than Entire Building Exhaust Hood- Kitchen Type I Exhaust Hood- Kitchen Entire Building Entire Building Exhaust Hood- Warming Kitchen Exhaust Hood- Warming Kitchen Entire Building Exhaust Hood- Warming Kitchen Exhaust Hood- Warming Kitchen Exhaust Hood- Warming Kitchen Entire Building Exhaust Hood- Warming Kitchen Ex | √entilatio | on | | | | | | |
| CFM Exhaust Fans- Roof Mounted - Less than 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category: Plumbing Building: Main Group Item - Type Location Quantity UOM Rank Replacement Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR Entire Building 2 EA 7 10+ years Piping Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | Entire Building | 3 | EA | 6 | 6-10 years | |
| 500 CFM Type I Exhaust Hood- Kitchen Entire Building 1 EA 6 6-10 years Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category: Plumbing Building: Main Group Item - Type Location Quantity UOM Rank Replacement Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR Entire Building 2 EA 7 10+ years Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | Entire Building | 1 | EA | 6 | 6-10 years | |
| Type II Exhaust Hood- Warming Kitchen Entire Building 1 EA 6 6-10 years Category : Plumbing Building : Main Recommend Recommend Replacement Comments | | | Entire Building | 2 | EA | 6 | 6-10 years | |
| Category : Plumbing Building : Main Recommend Replacement Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR Entire Building Domestic Piping-Cold Water Horizontal Entire Building Domestic Piping-Cold Water Risers Entire Building Domestic Piping-Cold Water from Risers to Entire Building Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 6-10 years | |
| Item - Type | | | | 1 | EA | 6 | | |
| Item - Type | Catego | ry : Plumbing | | ı | Building | : Main | | |
| Gas Heater - 150000 - 300000 BTU/HR Entire Building 2 EA 7 10+ years Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | Location | | | | | Comments |
| Gas Heater - 150000 - 300000 BTU/HR Entire Building 2 EA 7 10+ years Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | • | | Location | Quantity | OOW | Italik | Replacement | Comments |
| Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | HOL WALE | | Entire Building | 2 | EA | 7 | 10+ years | |
| Domestic Piping-Cold Water Horizontal Entire Building 36,864 SF 6 6-10 years Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | Dining | | | | | | | |
| Lines Domestic Piping-Cold Water Risers Entire Building 36,864 SF 6 6-10 years Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years 6-10 years 6-10 years 6-10 years | Libini9 | Domestic Piping-Cold Water Horizontal | Entire Building | 36 864 | SF | 6 | 6-10 years | |
| Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | Zitaio Ballanig | 00,004 | O. | J | 5 to yours | |
| Domestic Piping-Cold Water from Risers to Entire Building 36,864 SF 6 6-10 years Fixtures Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | Domestic Piping-Cold Water Risers | Entire Building | 36,864 | SF | 6 | 6-10 years | |
| Domestic Piping-Hot Water Horizontal Lines Entire Building 36,864 SF 6 6-10 years Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | Domestic Piping-Cold Water from Risers to | | | | | | |
| Domestic Piping-Hot Water Return Lines Entire Building 36,864 SF 6 6-10 years | | | Entire Buildina | 36.864 | SF | 6 | 6-10 vears | |
| | | | | | | | • | |
| | | | <u> </u> | • | | | | |
| | | | | | | | | |

Assessment Date: 07/29/2019 Campus Name: Keller Page : 5 of 18



| Catego | ry : Plumbing | Building : Main | | | | | | |
|--------|---|------------------------------|----------|-----|------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 36,864 | SF | 6 | 6-10 years | | |
| | Sanitary Piping | Entire Building | 36,864 | SF | 6 | 6-10 years | | |
| | Storm Piping | Entire Building | 36,864 | SF | 6 | 6-10 years | | |
| | Vent Piping | Entire Building | 36,864 | SF | 6 | 6-10 years | | |
| Pumps | | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Mechanical Room Elevator pit | 1 | EA | 6 | 10+ years | | |
| | Pumps - Sump-Simplex | Mechanical Room Elevator pit | 1 | EA | 6 | 10+ years | | |

Building: Main Category: Room

| | | | | | | Recommend | |
|-----------|--|-------------------------------|----------|----------|------|-------------|--------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Administ | rative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 1st floor main office suite | 1,350 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st floor main office suite | 4 | EΑ | 6 | 6-10 years | |
| | Floor - Terrazzo | 1st floor main office suite | 169 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st floor main office suite | 1,181 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st floor main office suite | 26 | EA | 6 | 6-10 years | |
| | Power Distribution | 1st floor main office suite | 30 | EA | 6 | 10+ years | |
| | Storage/ Closet | 1st floor main office suite | 150 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st floor main office suite | 1,519 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st floor main office suite | 1,519 | SF | 6 | 10+ years | |
| | Work SInk | 1st floor main office suite | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd flr east end of corridor, | 275 | SF | 6 | 6-10 years | |
| | | engineer's office #208 | | | | | |
| | Ceiling - Lay-in | 2nd flr east end of corridor, | 6 | SF | 4 | 1-2 years | Water damage |
| | | engineer's office #208 | | | | | |
| | Doors - Wood Doors inclu hw | 2nd flr east end of corridor, | 2 | EA | 6 | 10+ years | |
| | | engineer's office #208 | | | | | |
| | Floor - Carpet | 2nd flr east end of corridor, | 183 | SF | 6 | 6-10 years | |
| | | engineer's office #208 | | | _ | | |
| | Floor - Tile | 2nd flr east end of corridor, | 100 | SF | 6 | 6-10 years | |
| | | engineer's office #208 | | | _ | | |
| | Lighting - Lay-in | 2nd flr east end of corridor, | 3 | EA | 6 | 6-10 years | |
| | B | engineer's office #208 | 4.0 | - 4 | • | 0.40 | |
| | Power Distribution | 2nd flr east end of corridor, | 12 | EA | 6 | 6-10 years | |
| | W II O | engineer's office #208 | 000 | 0.5 | • | 40 | |
| | Walls - Concrete Block | 2nd flr east end of corridor, | 333 | SF | 6 | 10+ years | |
| | \\\-\ -\\\\-\\\\-\\\\-\\\\\\\\\\\\\\\\ | engineer's office #208 | 000 | 0.5 | 0 | 40 | |
| | Walls - Plaster/Drywall | 2nd flr east end of corridor, | 333 | SF | 6 | 10+ years | |
| | Cailing Lawin | engineer's office #208 | 400 | C.E. | 0 | 0.40 | |
| | Ceiling - Lay-in | Gym Teacher's Office | 182 | SF SF | 6 | 6-10 years | |
| | Doors - Side-lite | Gym Teacher's Office | 72 | 21 | 6 | 10+ years | |

Campus Name: Keller Page : 6 of 18 Assessment Date: 07/29/2019



| Catego | ry : Room | | В | uilding | : Main | | • | | |
|----------|--------------------------------------|------------------------------------|----------|---------|--------|-------------|--|--|--|
| _ | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Doors - Transom Window | Gym Teacher's Office | 6 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Gym Teacher's Office | 2 | EΑ | 6 | 10+ years | | | |
| | Floor - Carpet | Gym Teacher's Office | 182 | SF | 6 | 6-10 years | | | |
| | Lighting - Lay-in | Gym Teacher's Office | 4 | EA | 7 | 6-10 years | | | |
| | Power Distribution | Gym Teacher's Office | 4 | EA | 6 | 6-10 years | | | |
| | Walls - Concrete Block | Gym Teacher's Office | 345 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | Room 118, Kitchen Manager's Office | 61 | SF | 6 | 6-10 years | | | |
| | Ceiling - Lay-in | Room 118, Kitchen Manager's Office | 8 | SF | 5 | 6-10 years | | | |
| | Doors - Wood Doors inclu hw | Room 118, Kitchen Manager's Office | 1 | EA | 6 | 6-10 years | | | |
| | Floor - Tile | Room 118, Kitchen Manager's Office | 69 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | Room 118, Kitchen Manager's Office | 1 | EA | 7 | 6-10 years | | | |
| | Power Distribution | Room 118, Kitchen Manager's Office | 4 | EA | 6 | 6-10 years | | | |
| | Walls - Concrete Block | Room 118, Kitchen Manager's Office | 264 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | Room 124, Teacher's Lounge | 194 | SF | 6 | 6-10 years | | | |
| | Doors - Wood Doors inclu hw | Room 124, Teacher's Lounge | 1 | EΑ | 6 | 10+ years | | | |
| | Floor - Tile | Room 124, Teacher's Lounge | 194 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | Room 124, Teacher's Lounge | 4 | EA | 7 | 6-10 years | | | |
| | Power Distribution | Room 124, Teacher's Lounge | 8 | EA | 6 | 6-10 years | | | |
| | Walls - Concrete Block | Room 124, Teacher's Lounge | 556 | SF | 6 | 10+ years | | | |
| | Work SInk | Room 124, Teacher's Lounge | 1 | EA | 7 | 6-10 years | | | |
| _Gymnas | ia | | | | | | | | |
| | Bleacher Seating | 1st Floor | 95 | EA | 6 | 6-10 years | | | |
| | Ceiling - Exposed | 1st Floor | 3,521 | SF | 6 | 6-10 years | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | 6-10 years | | | |
| | Doors - Store Front | 1st Floor | 1 | EΑ | 6 | 6-10 years | | | |
| | Floor - Sport Flooring | 1st Floor | 3,521 | SF | 7 | 6-10 years | | | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 8 | EA | 7 | 6-10 years | Lighting will be replaced by LED end of summer | | |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 195 | SF | 5 | 6-10 years | | | |
| | Walls - Concrete Block | 1st Floor | 6,442 | SF | 6 | 10+ years | | | |
| _Kitchen | | | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 542 | SF | 6 | 6-10 years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 6-10 years | | | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 542 | SF | 5 | 2-5 years | Concrete floor has cracks in 2 areas | | |



| Category : Room | | В | uilding | : Main | | | |
|-----------------|--------------------------------------|--------------------|----------|--------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 1st Floor | 6 | EA | 7 | 6-10 years | |
| | Walls - Masonry | 1st Floor | 892 | SF | 6 | 10+ years | |
| Library | | | | | | | |
| • | Casework | 1st Floor | 82 | LF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 2,205 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 1st Floor | 2,205 | SF | 4 | 1-2 years | |
| | Lighting - Lay-in | 1st Floor | 24 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 3,093 | SF | 6 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 134 | 450 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 134 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 134 | 450 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 134 | 6 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 134 | 535 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 134 | 267 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | 1st Floor | 2,158 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | ĒA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 2,150 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 8 | SF | 5 | 1-2 years | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 6 | ĒΑ | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EΑ | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 5,614 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Servery, 1st Floor | 290 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | Servery, 1st Floor | 6 | SF | 5 | 1-2 years | |
| | Doors - Wood Doors inclu hw | Servery, 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Servery, 1st Floor | 290 | SF | 6 | 10+ years | |
| | Floor - Tile | Servery, 1st Floor | 290 | SF | 5 | 1-2 years | |
| | Lighting - Lay-in | Servery, 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Serving Line | Servery, 1st Floor | 12 | LF | 7 | 6-10 years | |
| | | | | SF | 6 | • | |
| | Walls - Masonry | Servery, 1st Floor | 535 | SF. | ь | 10+ years | |
| MDF_ID | | | | | | | |
| | Doors - Wood Doors inclu hw | Room 122 | 1 | EA | 6 | 6-10 years | |
| | Finishes | Room 122 | 127 | SF | 7 | 6-10 years | |
| | Other Cooling Unit | Room 122 | 1 | EA | 7 | 6-10 years | |
| Mechani | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 28 | SF | 7 | 6-10 years | |
| | Mechanical/ Service Rooms | 1st Floor | 408 | SF | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------------|--------------------------------|---------------|----------|---------|--------|-------------|-------------------------|
| | | | | | | Recommend | |
| 3roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage Room | 1st Floor | 60 | SF | 7 | 6-10 years | Room 117 in Kitchen |
| | Storage Room | 1st Floor | 1,016 | SF | 5 | 2-5 years | cracks in wall/ceiling |
| | Vaults | 1st Floor | 210 | SF | 7 | 10+ years | |
| | Boiler Room | 2nd Floor | 1,461 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 56 | SF | 5 | 6-10 years | mising lighting fixture |
| rep Ro | om | | | | | | |
| • | Casework | 2nd flr #205 | 18 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd flr #205 | 277 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd flr #205 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd flr #205 | 277 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd flr #205 | 3 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd fir #205 | 603 | SF | 6 | 10+ years | |
| | Walls - Gollerete Block | 211d 111 #203 | 003 | Oi | O | 10+ years | |
| Restroor | | 4 at Flace | 200 | | | 2.5.42272 | |
| | Accessories | 1st Floor | 209 | SF | 7 | 2-5 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 209 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 209 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor | 3 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 5 | EA | 6 | 6-10 years | |
| | Partitions | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Urinals | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 1st Floor | 541 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | Accessories | 1st Floor | 209 | SF | 7 | 2-5 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 209 | SF | 6 | 6-10 years | |
| | Floor - Terrazzo | 1st Floor | 209 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EΑ | 7 | 10+ years | |
| | Lavatory | 1st Floor | 3 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 5 | EA | 6 | 6-10 years | |
| | Partitions | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | 1st Floor | 541 | SF | 6 | 10+ vears | |
| | Water Closet | 1st Floor | 4 | ĒΑ | 6 | 6-10 years | |
| | Accessories | 1st Floor | 62 | SF | 7 | 2-5 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 62 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 62 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Lavatory Lighting - Lay-in | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 1st Floor | • | SF | _ | • | |
| | Water Closet | | 284 | | 6 | 10+ years | |
| | | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Accessories | 1st Floor | 44 | SF | 7 | 2-5 years | |



| Catego | Category : Room | | Building : Main | | | | | |
|--------|--------------------------------|-------------|-----------------|-----|------|-------------|----------|--|
| _ | | | | _ | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Ceiling - Plaster/Drywall | 1st Floor | 44 | SF | 6 | 6-10 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 1st Floor | 44 | SF | 6 | 10+ years | | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 2-5 years | | |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 6 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 1st Floor | 242 | SF | 6 | 10+ years | | |
| | Water Closet | 1st Floor | 1 | EA | 6 | 6-10 years | | |
| | Accessories | 2nd Floor | 209 | SF | 7 | 2-5 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 209 | SF | 6 | 6-10 years | | |
| | Floor - Terrazzo | 2nd Floor | 209 | SF | 6 | 10+ years | | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 2nd Floor | 3 | EA | 6 | 6-10 years | | |
| | Lighting - Lay-in | 2nd Floor | 5 | EA | 6 | 6-10 years | | |
| | Partitions | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Urinals | 2nd Floor | 2 | EA | 6 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 541 | SF | 6 | 10+ years | | |
| | Water Closet | 2nd Floor | 2 | EΑ | 6 | 6-10 years | | |
| | Accessories | 2nd Floor | 209 | SF | 7 | 2-5 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 209 | SF | 6 | 6-10 years | | |
| | Floor - Terrazzo | 2nd Floor | 209 | SF | 6 | 10+ years | | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 2nd Floor | 3 | EΑ | 6 | 6-10 years | | |
| | Lighting - Lay-in | 2nd Floor | 5 | EΑ | 6 | 6-10 years | | |
| | Partitions | 2nd Floor | 4 | EA | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 541 | SF | 6 | 10+ years | | |
| | Water Closet | 2nd Floor | 4 | EA | 6 | 6-10 years | | |
| | Accessories | 2nd Floor | 62 | SF | 7 | 2-5 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 62 | SF | 6 | 6-10 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 2nd Floor | 62 | SF | 6 | 10+ years | | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 2nd Floor | 1 | EΑ | 6 | 6-10 years | | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 6 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 284 | SF | 6 | 10+ years | | |
| | Water Closet | 2nd Floor | 1 | EA | 6 | 6-10 years | | |
| | Accessories | 2nd Floor | 44 | SF | 7 | 2-5 years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 44 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 2nd Floor | 44 | SF | 6 | 10+ years | | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Lavatory | 2nd Floor | 1 | EA | 6 | 2-5 years | | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 6 | 6-10 years | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 242 | SF | 6 | 10+ years | | |
| | vvans - Structural Glazeu Tile | 2110 1 1001 | 242 | J- | U | TOT years | | |

Campus Name: Keller Page : 10 of 18 Assessment Date: 07/29/2019



| Category : Room | | В | uilding | | | | |
|-----------------|---------------------------------|-----------------------|----------|-----------|-----------|---------------------------|----------|
| | Hans Toma | Laadiaa | 0 | LIOM | D I- | Recommend | 0 |
| roup | Item - Type Water Closet | Location 2nd Floor | Quantity | UOM EA | Rank 6 | Replacement 6-10 years | Comments |
| | | In the Server Area | 1 | SF | _ | | |
| | Accessories | | 44 | | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In the Server Area | 44 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | In the Server Area | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | In the Server Area | 44 | SF | 6 | 6-10 years | |
| | Floor Drain | In the Server Area | 1 | EA | 7 | 10+ years | |
| | Lavatory | In the Server Area | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | In the Server Area | 1 | EA | 7 | 6-10 years | |
| | Walls - Tile Ceramic/ Porcelain | In the Server Area | 125 | SF | 6 | 10+ years | |
| | Water Closet | In the Server Area | 1 | EA | 6 | 6-10 years | |
| atego | ry : Classroom | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| lassroc | m #107 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 859 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 6 | SF | 5 | 1-2 years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 865 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 767 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 256 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 6-10 years | |
| lassroc | m #108 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 860 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 5 | SF | 5 | 1-2 years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 865 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 2-5 years | |
| | Storage/ Closet | 1st Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 766 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 256 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|-----------|-----------------------------|------------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 837 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 2-5 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 766 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 256 | SF | 6 | 6-10 years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | m #202 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 2-5 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 511 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 511 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | m #203 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 511 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 511 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Work Silik | 2110 F1001 | 1 | EA | , | 6-10 years | |
| _Classroo | m #204 (Science Classroom) | 0-451 | | | | 0.40 | |
| | Casework | 2nd Floor | 52 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 1,150 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 5 | 1-2 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |

Campus Name: Keller Page : 12 of 18 Assessment Date: 07/29/2019



| Category : Classroom | | В | uilding | : Main | | - | |
|----------------------|-----------------------------------|------------------------|----------|--------|------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile/Sheet | 2nd Floor | 1,156 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 607 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 607 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 3 | ĒΑ | 7 | 6-10 years | |
| _Classroc | om #208 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 839 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 5 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 845 | SF | 6 | 6-10 years | |
| | | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in Marker Board | 2nd Floor | 24 | LF | 6 | • | |
| | | | | | - | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,154 | SF | 6 | 6-10 years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroc | om #209 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 845 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 5 | SF | 5 | 1-2 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 4 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,154 | SF | 6 | 6-10 years | |
| | Work Sink | 2nd Floor | 1 | ĒΑ | 7 | 6-10 years | |
| Classroc | om #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 845 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 845 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor 2nd Floor | 24 | LF | 6 | | |
| | | 2nd Floor 2nd Floor | | SF | - | 6-10 years | |
| | Walls - Concrete Block | | 1,154 | | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EΑ | 7 | 6-10 years | |

Campus Name: Keller Page : 13 of 18 Assessment Date: 07/29/2019



| Catego | ry : Classroom | | В | | | | |
|------------------|---|---|---|----------------------------|---|--|----------|
| _ | | | | _ | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| lassroc | om #211 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 845 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 1 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 845 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 4 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,154 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EΑ | 7 | 6-10 years | |
| | WOIN CHIN | 2110 1 1001 | • | | • | o io youro | |
| atego | ry : Interior | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| orridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,857 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors include hw | 1st Floor | 4 | EA | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Terrazzo | 1st Floor | 2,857 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 54 | EΑ | 6 | 6-10 years | |
| | Student Lockers - One Tier | 1st Floor | 150 | EΑ | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 4,120 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 2,800 | SF | 6 | 6-10 years | |
| | Ceiling | | • | SF | 4 | - | |
| | | | | | | 1-2 years | |
| | | 2nd Floor | 57 | | | 10 | |
| | Doors - Wood Doors include hw | 2nd Floor | 4 | EA | 6 | 10+ years | |
| | Doors - Wood Doors include hw Drinking Fountains - Double Fountain | 2nd Floor 2nd Floor | 4 | EA EA | 6 7 | 6-10 years | |
| | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo | 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 | EA EA SF | 6 7 6 | 6-10 years 10+ years | |
| | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in | 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 54 | EA EA SF EA | 6 7 6 6 | 6-10 years 10+ years 6-10 years | |
| | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 54 150 | EA EA SF EA | 6 7 6 6 | 6-10 years 10+ years 6-10 years 6-10 years | |
| | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in | 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 54 | EA EA SF EA | 6 7 6 6 | 6-10 years 10+ years 6-10 years | |
| eafaty. | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 54 150 | EA EA SF EA | 6 7 6 6 | 6-10 years 10+ years 6-10 years 6-10 years | |
| Safety | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 4 1 2,857 54 150 4,120 | EA SF EA EA SF | 6 7 6 6 6 6 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years | |
| Safety | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station | 2nd Floor | 4 1 2,857 54 150 4,120 | EA SF EA EA SF | 6 7 6 6 6 6 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years | |
| Safety | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station Security Cameras | 2nd Floor Entire building Entire building | 4 1 2,857 54 150 4,120 | EA SF EA SF | 6 7 6 6 6 6 7 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years | |
| lafety | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station | 2nd Floor | 4 1 2,857 54 150 4,120 | EA SF EA EA SF | 6 7 6 6 6 6 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years | |
| • | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station Security Cameras | 2nd Floor Entire building Entire building | 4 1 2,857 54 150 4,120 | EA SF EA SF | 6 7 6 6 6 6 7 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years | |
| Safety Stairs | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station Security Cameras | 2nd Floor Entire building Entire building | 4 1 2,857 54 150 4,120 | EA SF EA SF | 6 7 6 6 6 6 7 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years | |
| , | Doors - Wood Doors include hw Drinking Fountains - Double Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Walls - Concrete Block Camera Viewing Station Security Cameras Security Cameras | 2nd Floor Entire building Entire building Entire building | 4 1 2,857 54 150 4,120 4 10 5 | EA SF EA SF | 6 7 6 6 6 6 7 7 7 | 6-10 years 10+ years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years | |



| Catego | ry : Interior | | Building : Main | | | | | |
|-----------|--|----------|-----------------|-----|------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Lighting - Lay-in | East | 12 | EA | 6 | 6-10 years | | |
| | Stairs - Terrazzo | East | 30 | LF | 6 | 10+ years | | |
| | Walls - Concrete Block | East | 3,047 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | West | 1,037 | SF | 6 | 6-10 years | | |
| | Floor - Terrazzo | West | 910 | SF | 6 | 10+ years | | |
| | Handrails | West | 128 | LF | 7 | 10+ years | | |
| | Lighting - Lay-in | West | 12 | EA | 6 | 6-10 years | | |
| | Stairs - Terrazzo | West | 30 | LF | 6 | 10+ years | | |
| | Walls - Concrete Block | West | 3,047 | SF | 6 | 10+ years | | |
| _Vertical | Conveyance | | | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | | 1 | EA | 6 | 10+ years | | |

Campus Name: Keller Page : 15 of 18 Assessment Date: 07/29/2019



Category : Site Building : Site

| Category : Site | | | В | uilding | | | |
|-----------------|---|--------------------|----------|----------|--------|-------------|--------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Athletic | | | | | | | |
| | Surface - Asphalt | North | 6,296 | SF | 6 | 6-10 years | |
| | | | | | | | |
| Civil/Dra | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 4 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 4 | EA | 6 | 10+ years | |
| | | | | | | | |
| Fencing | Fencing - Old Standard Ornamental | North | 728 | LF | 6 | 10+ years | |
| | Fencing - Old Standard Ornamental | North | 4 | LF | 5 | 2-5 years | |
| | r ending - Old Standard Omamental | NOITH | 7 | LI | 3 | 2-5 years | |
| Landsca | pe | | | | | | |
| | Benches | Entire Site | 4 | EA | 7 | 6-10 years | |
| | Benches | Entire Site | 2 | EA | 5 | 1-2 years | bench is leaning and no longer level |
| | Landscape - Grass | Entire Site | 20,464 | SF | 5 | 1-2 years | |
| | Landscape - Hardscape- Concrete | Entire Site | 850 | SF | 6 | 6-10 years | |
| | Landscape - Hardscape- Pavers | Entire Site | 1,350 | SF | 7 | 10+ years | |
| | Parkway trees | Entire Site | 21 | EA | 7 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 2,839 | SF | 6 | 6-10 years | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 8,906 | SF | 6 | 6-10 years | |
| | Trash Receptacles | Entire Site | 2 | EA | 6 | 6-10 years | |
| Parking | Lot | | | | | | |
| T arking | Concrete Curbs | Parking Lot- North | 335 | LF | 7 | 10+ years | |
| | Interior Plantings | Parking Lot- North | 30 | LF | 6 | 10+ years | |
| | Lighting - Pole Mounted | Parking Lot- North | 2 | EA | 6 | 6-10 years | |
| | Surface - Asphalt | Parking Lot- North | 5,847 | SF | 6 | 10+ years | |
| | Vehicular Screening | Parking Lot- North | 51 | LF | 4 | 1-2 years | Has been removed |
| | | | | | | | |
| Playgrou | | N. d | | | | 10 | |
| | Equipment - Combo 3-12 Surface - Poured Surface | North | 2.525 | EA SF | 7 7 | 10+ years | |
| | Surface - Poured Surface | North | 2,535 | SF | , | 10+ years | |
| Sidewall | KS. | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 314 | LF | 7 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 6,020 | SF | 7 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 125 | SF | 5 | 2-5 years | |
| 0: | | | | | | | |
| Signage | Flag Pole - Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | riay role - riay role | Little Site | ı | EA | 1 | 10+ years | |
| | | | | | | | |



Category : Site

Annie Keller Regional Gifted Center 3020 W 108th STREET, Chicago, IL 60655

| Category . Site | | | | | | | | | |
|-----------------|--|-------------|----------|-----------|------|-------------|----------|--|--|
| | | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Monument - Building Mounted Cut Letter | Entire Site | 1 | EA | 7 | 10+ years | | | |
| | Sign | | | | | | | | |
| | Monument - Sign-Lighted | Entire Site | 1 | EA | 7 | 10+ years | | | |

Building . Site

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Keller Page: 17 of 18 Assessment Date: 07/29/2019

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- | | |
|-------------------|-------------------|---------------|--------|--------------------|-------|------------------|--------------------|--------|--------|--|--|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board | | |
| Building : Main | | | | | | | | | | | |
| Computer Lab | Computer Lab | 2nd Floor | 208 | 2-16 | 845 | 124 | 62 | N | Υ | | |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 1-14 | 865 | 127 | 64 | N | Υ | | |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 1-15 | 865 | 124 | 62 | N | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 841 | 124 | 62 | N | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 2-07 | 841 | 127 | 64 | N | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 2-08 | 841 | 127 | 64 | N | Υ | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 2-15 | 845 | 127 | 64 | N | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 2-14 | 845 | 127 | 64 | N | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 2-13 | 845 | 124 | 62 | N | N | | |
| Science Classroom | Science Classroom | 2nd Floor | 204 | 2-09 | 1,156 | 146 | 70 | N | Υ | | |