

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 2003 | 3 | 85,500 |
| Campus Total | | | 85,500 |

Category : Exterior Building : Main

| uicgo | cgory : Exterior | | Building . Main | | | | | |
|--------|---------------------------------------|-------------|-----------------|-------|-------|-------------|----------|--|
| oup | Itom Type | Location | Quantity | UOM | Rank | Recommend | Comments | |
| • | Item - Type | Location | Quantity | UOIVI | Kalik | Replacement | Comments | |
| trance | | //4 BA=: B1 | 4 | | | 40 | | |
| | Entrance Control - Audio and Video | #1 Main - N | 1 | EΑ | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #1 Main - N | 5 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #1 Main - N | 10 | EA | 6 | 10+ years | | |
| | Power Door Operator and Controls | #1 Main - N | 1 | EA | 7 | 10+ years | | |
| | Exterior Doors - Store Front | #10 - NW | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #10 - NW | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #2 - NE | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #2 - NE | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | #3 Exit - E | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | #4 - E | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | #4 - E | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #5 Exit - E | 2 | EA | 6 | 10+ years | | |
| | Exterior Stairs - Concrete | #5 Exit - E | 42 | LF | 6 | 10+ years | | |
| | Ramp Handrail - Steel_Ramp Handrail | #5 Exit - E | 186 | LF | 6 | 10+ years | | |
| | Ramps - Concrete | #5 Exit - E | 84 | LF | 6 | 10+ years | | |
| | Stair Handrail - Steel Stair Handrail | #5 Exit - E | 22 | LF | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #6 - S | 3 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #6 - S | 3 | EA | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #7 Exit - W | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Exterior Steel Door | #8 - W | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Side lite | #8 - W | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #8 - W | 1 | EA | 6 | 10+ years | | |
| | Exterior Doors - Store Front | #9 - W | 2 | EA | 6 | 10+ years | | |
| | Exterior Doors - Transom Lite | #9 - W | 2 | EA | 6 | 10+ years | | |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------|--|-------------------|------------|----------|--------|--------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| oundat | on. | | | | | | |
| Oundat | Foundation - Concrete | Entire Building | 1,018 | LF | 7 | 10+ years | |
| | Superstructure - Metal Deck/ Concrete | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Topping | Littilo Ballallig | 30,000 | O. | • | 101 youro | |
| iahtina | | | | | | | |
| 0 0 | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 16 | EA | 6 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 24 | EA | 6 | 10+ years | |
| Roof Sys | stem | | | | | | |
| - | Access Ladder - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | Main Roof | 769 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Main Roof | 404 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Main Roof | 558 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Main Roof | 50 | LF | 5 | 0-1 year | Cracking and chipping throughou |
| | Parapet - Parapet > 30" | Main Roof | 164 | LF | 5 | 0-1 year | Cracking and chipping throughou |
| | Roof - Modified Bitumen | Main Roof | 20,277 | SF | 6 | 10+ years | oraning and ompring and agree |
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | Main Roof | 20,277 | SF | 7 | 10+ years | |
| | Concrete Topping | Wall 1001 | 20,211 | Oi. | , | 101 years | |
| | Access Ladder - Metal | NE Low Roof | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | NE Low Roof | 335 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | NE Low Roof | 215 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | NE Low Roof | 226 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | NE Low Roof | 25 | LF | 5 | 1-2 years | Cracking and chipping. |
| | Parapet - Parapet > 30" | NE Low Roof | 84 | LF | 5 | 1-2 years 1-2 years | Cracking and chipping. Cracking and chipping. |
| | Roof - Modified Bitumen | | 7,472 | SF | 6 | 6-10 years | Ponding observed. |
| | | NE Low Roof | | | 7 | | Ponding observed. |
| | Roof Hatch - Metal | NE Low Roof | 1 7,472 | EA SF | 7 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | NE Low Roof | 7,472 | ЭF | 1 | 10+ years | |
| | Concrete Topping | NIM Law Doof | 4 | Ε. | 7 | 40 | |
| | Access Ladder - Metal | NW Low Roof | 1 | EA LF | 7 | 10+ years | |
| | Chimney - Metal Flue | NW Low Roof | 48 | | 6 | 10+ years | |
| | Coping - Stone | NW Low Roof | 333 | LF | 6 | 10+ years | 01: |
| | Coping - Stone | NW Low Roof | 2 | LF | 5 | 1-2 years | Chipped. |
| | Downspouts - Interior Downspouts | NW Low Roof | 215 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | NW Low Roof | 251 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | NW Low Roof | 84 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | NW Low Roof | 7,472 | SF | 4 | 1-2 years | Ponding, roof deteriorating throughout. |
| | Roof Hatch - Metal | NW Low Roof | 1 | EA | 7 | 10+ years | - |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | NW Low Roof | 7,472 | SF | 6 | 10+ years | |





| Catego | ry : Exterior | | В | uilding | : Main | | |
|---------|---|-----------------|----------|---------|--------|--------------------------|-----------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 23,500 | SF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 11,750 | SF | 4 | 0-1 year | Cracking and chipping throughout. |
| | Exterior Walls - Stone-Cast | Entire Building | 6,641 | SF | 6 | 10+ years | craceming and emphasize |
| | Exterior Walls - Stone-Cast | Entire Building | 15 | SF | 3 | 0-1 year | Missing stone |
| Windows | 3 | | | | | | |
| | Guard - Guards perforated | Entire Building | 2,200 | SF | 6 | 10+ years | |
| | Guard - Guards perforated | Entire Building | 450 | SF | 5 | 2-5 years | |
| | Lintels - Steel | Entire Building | 982 | ĹF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 6,125 | SF | 6 | 10+ years | |
| Catego | ry : Electrical | | В | uilding | : Main | | |
| | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | ncy System | | | | | | |
| Lineige | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Corridors and | Entire Building | 37 | EA | 6 | 6-10 years | |
| | Stairs | - | | | | - | |
| | Emergency Battery Packs - Gym | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Multipurpose Room | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 18 | EA | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 15,217 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 4,208 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Multipurpose | Entire Building | 4,208 | SF | 6 | • | |
| | Room | Entire Building | 4,900 | SF | b | 10+ years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 824 | SF | 6 | 10+ years | |
| | Security System - CCTV | Entire Building | 85,500 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 85,500 | SF | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 31 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 3 | EA | 6 | 6-10 years | |
| | Exit Signs - Multipurpose Room | Entire Building | 4 | EA | 6 | 6-10 years | |
| Main Se | rvice | | | | | | |
| | Main Electrical Service - 1600 A 277/480/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 7 | 10+ years | |
| | Independent Electrical Service for | Electrical Room | 1 | EA | 7 | 10+ years | |





| | -1 . · · | | - | | | | 707 W Morse AVENUE, Chicago, IL 6 |
|------------|--|----------------------------------|----------|-------------|--------|--------------------------|-----------------------------------|
| Categor | y : Electrical | | В | uilding | : Main | | |
| _ | | | 0 | | | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | PA System | Entire Building | 85,500 | SF | 6 | 6-10 years | |
| Power Di | stribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EΑ | 6 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EΑ | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EΑ | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EΑ | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A | Entire Building Entire Building | 1 | EA | 6 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building Entire Building | 1 | EA | 6 | | |
| | | | 1 | EA | 6 | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | ı | EA | 0 | 10+ years | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 1 | EA | 6 | 10+ years | |
| | amp | <u> </u> | | | | , | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 2 | EA | 6 | 10+ years | |
| | amp | g | _ | _, , | Ū | .o. you.o | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | |
| C-1 | Fire Brotestion | | В | به ما الداد | . Main | | |
| Categor | y : Fire Protection | | В | uilding | : wain | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alarr | n | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | Located in engineer's office |
| | Fire Alarm Strobe Lights | Entire Building | 85,500 | SF | 6 | 6-10 years | • |
| | Fire Alarm_System | Entire Building | 85,500 | SF | 6 | 6-10 years | |
| | Fire Pump Controller | Entire Building | 1 | EA | 6 | 6-10 years | |
| | The Fump Controller | Little Building | • | | J | o ro years | |
| Pump Ro | om Assembly | | | | | | |
| | Fire Pump - Less than 25hp | 1st Floor Pump Room | 1 | EA | 6 | 10+ years | |
| | Jockey Pump | 1st Floor Pump Room | 1 | EA | 6 | 6-10 years | |
| Sprinkler | System | | | | | | |
| <u> </u> | Sprinkler Heads | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Sprinkler Piping | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Wet Sprinkler System | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Trot Opinidor Oyotom | Little Dulluling | 00,000 | 01 | , | ioi yeais | |
| Categor | y : Mechanical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Croup | | Location | Quantity | COIVI | Naiik | Replacement | Comments |
| Air Condi | | | | | | | |





| | ry : Mechanical | | В | uilding | : Main | | |
|-----------|--|----------------------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons | Entire Building | 1 | EA | 4 | 1-2 years | 2 section unit, half of the compressors have failed, unit is almost 20 years old. |
| | Glycol Feed | Entire Building | 1 | EA | 6 | 6-10 years | • |
| | Pressure Fill System | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 2-5 years | Serves the MDF room CRAC unit, surface corrosion present |
| _Air Hand | ling Systems | | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | East Mechanical Room | 1 | EA | 6 | 6-10 years | AHU-2, serves the 2nd and 3rd floors |
| | Air Intake | East Mechanical Room | 1 | EΑ | 6 | 6-10 years | |
| | Induction Fan | East Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | VAV Box | East Mechanical Room | 3 | EA | 6 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm | East Mechanical Room | 1 | EA | 6 | 6-10 years | AHU-4, serves the gym. |
| | Air Intake | East Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 3 | EA | 6 | 6-10 years | Served by AHU-3 |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 26 | EA | 6 | 6-10 years | Served by AHU-2 |
| | Fan Power Box - Fan Power Box with Hot Water Coil | Entire Building | 16 | EA | 6 | 6-10 years | Served by AHU-1 |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | RF-1 for AHU-1 |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | RF-3 for AHU-3 |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | RF-2 for AHU-2 |
| | Make Up Air Unit- Roof Mounted- Gas Heating - 6000 - 10,000 cfm | Roof | 1 | EA | 6 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm | West Mechanical Room | 1 | EA | 6 | 6-10 years | AHU-1, serves the first floor. |
| | Air Intake | West Mechanical Room | 1 | EΑ | 6 | 6-10 years | |
| | Induction Fan | West Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | VAV Box | West Mechanical Room | 5 | EA | 6 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm | West Mechanical Room | 1 | EA | 6 | 6-10 years | AHU-3, serves the dining room and servery |
| | Air Intake | West Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Induction Fan | West Mechanical Room | 1 | ΕA | 6 | 6-10 years | |





| s |
|------------------------------|
| • |
| |
| |
| |
| |
| |
| |
| ounted in ductwork, |
| rops in space for floor leve |
| lation pumps associated |
| . Refer to mechanical |
| roup for additional pumps. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| tion pumps |
| |
| |
| |
| (a) EDD |
| (3) FPB controlled by a |
| a ^t |







| Catego | Category : Plumbing | | | uilding | : Main | | |
|-------------------|--|-----------------|----------|---------|--------|--------------------------|-------------------|
| Group Hot Wate | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 7 | 10+ years | |
| _Piping | | | | | | | |
| . • | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Cold Water Risers | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Sanitary Piping | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Storm Piping | Entire Building | 85,500 | SF | 7 | 10+ years | |
| | Vent Piping | Entire Building | 85,500 | SF | 7 | 10+ years | |
| Pumps | | | | | | | |
| • | Pumps - Domestic Booster Pump-Duplex | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Pumps - Sump-Simplex | 1st Floor | 1 | EA | 6 | 6-10 years | Elevator pit pump |

Category : Room **Building: Main**

| | | | | | | Recommend | |
|----------|-----------------------------|----------------------------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Administ | rative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 2nd Floor - 204A | 150 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - 204A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor - 204A | 150 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor - 204A | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 2nd Floor - 204A | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor - 204A | 140 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor - 204A | 180 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor - Faculty Lounge | 181 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Faculty Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor - Faculty Lounge | 181 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor - Faculty Lounge | 2 | EΑ | 7 | 10+ years | |
| | Power Distribution | 2nd Floor - Faculty Lounge | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor - Faculty Lounge | 413 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor 203A | 110 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor 203A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor 203A | 110 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor 203A | 1 | EΑ | 7 | 10+ years | |

Campus Name: New Field Page: 7 of 30 Assessment Date: 12/30/2019







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution 2nd Floor 203A 4 EΑ 10+ vears 7 140 SF 7 Walls - Concrete Block 2nd Floor 203A 10+ years Ceiling - Lav-in 2nd Floor 209 110 SF 7 10+ years Doors - Wood Doors inclu hw EΑ 7 2nd Floor 209 1 10+ years SF Floor - Tile 2nd Floor 209 110 7 10+ years 7 Lighting - Lay-in 2nd Floor 209 EΑ 10+ years 1 Power Distribution 2nd Floor 209 EΑ 7 10+ years 4 SF Walls - Concrete Block 2nd Floor 209 140 7 10+ years SF Ceiling - Lay-in 2nd Floor 211 110 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 211 FΑ 7 10+ years 1 Floor - Tile 2nd Floor 211 110 SF 7 10+ years Lighting - Lay-in 2nd Floor 211 EΑ 7 10+ years 1 Power Distribution 6 EΑ 7 2nd Floor 211 10+ years SF 7 Walls - Concrete Block 2nd Floor 211 140 10+ years SF 7 Ceiling - Lav-in Administrative Office 294 10+ years Doors - Wood Doors inclu hw FΑ 7 Administrative Office 1 10+ years 294 SF 7 Floor - Carpet Administrative Office 6-10 years Lighting - Lay-in Administrative Office 4 EΑ 7 10+ years Power Distribution Administrative Office 6 EΑ 7 10+ years Storage/ Closet Administrative Office 25 SF 7 10+ years Walls - Concrete Block Administrative Office 169 SF 7 10+ years SF 7 Walls - Plaster/Drywall Administrative Office 169 10+ years SF 7 Ceiling - Lay-in Assistant Principal's Office, Room 164 10+ years 106B Doors - Wood Doors inclu hw Assistant Principal's Office, Room EΑ 7 1 10+ years 106B Floor - Carpet Assistant Principal's Office, Room 164 SF 7 6-10 years 106B Lighting - Lay-in Assistant Principal's Office, Room 2 EΑ 7 10+ years 106B Power Distribution Assistant Principal's Office, Room 6 FΑ 7 10+ years 106B SF Walls - Concrete Block 7 Assistant Principal's Office, Room 94 10+ years 106B SF Walls - Plaster/Drywall Assistant Principal's Office, Room 94 7 10+ years 106B Ceiling - Lay-in Business Office, Room 106 595 SF 7 10+ years Doors - Side-lite Business Office, Room 106 SF 18 7 10+ years Doors - Wood Doors inclu hw Business Office. Room 106 1 EΑ 7 10+ years SF Floor - Carpet Business Office. Room 106 595 7 6-10 years Lighting - Lay-in Business Office. Room 106 10 EΑ 7 10+ years Power Distribution Business Office, Room 106 FΑ 7 12 10+ years Walls - Concrete Block Business Office, Room 106 342 SF 7 10+ years SF Walls - Plaster/Drywall Business Office, Room 106 342 7 10+ years





| Catego | ry : Room | | В | uilding | : Main | | |
|--------|--------------------------------------|-------------------------------|----------|----------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | Engineer's Office, Room 121 | 205 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Office, Room 121 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Engineer's Office, Room 121 | 205 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Engineer's Office, Room 121 | 3 | EA | 7 | 10+ years | |
| | Power Distribution | Engineer's Office, Room 121 | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Engineer's Office, Room 121 | 242 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Gym Teacher's Office | 117 | SF | 7 | 10+ years | |
| | Doors - Side-lite | Gym Teacher's Office | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Gym Teacher's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Gym Teacher's Office | 117 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Gym Teacher's Office | 2 | ĒΑ | 7 | 10+ years | |
| | Power Distribution | Gym Teacher's Office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Gym Teacher's Office | 138 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Kitchen Manager's Office | 64 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Kitchen Manager's Office | 4 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | Kitchen Manager's Office | 18 | SF | 7 | 10+ years | water damage |
| | Doors - Wood Doors inclu hw | Kitchen Manager's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Kitchen Manager's Office | 68 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Kitchen Manager's Office | 1 | EA | 7 | 10+ years | |
| | Power Distribution | Kitchen Manager's Office | 4 | EA | 7 | , | |
| | | | | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Kitchen Manager's Office | 83 | | | 10+ years | |
| | Ceiling - Lay-in | Office, Room 104 | 127 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Office, Room 104 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Office, Room 104 | 127 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Office, Room 104 | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Office, Room 104 | 12 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Office, Room 104 | 80 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Office, Room 104 | 146 | SF | 7 | 10+ years | |
| | Work SInk | Office, Room 104 | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Principal's Office, Room 106A | 164 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Office, Room 106A | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | Principal's Office, Room 106A | 164 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | Principal's Office, Room 106A | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Principal's Office, Room 106A | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Principal's Office, Room 106A | 94 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Office, Room 106A | 94 | SF | 7 | 10+ years | |
| \ | :_ | | | | | | |
| Symnas | Ceiling - Exposed | 1st Floor | 4,208 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4,206 | EA | 7 | • | |
| | Floor - Sport Flooring | | 4,208 | SF | 7 7 | 10+ years | |
| | | 1st Floor | | | | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 16 | EΑ | 7 | 10+ years | |
| | Scoreboards Sound System | 1st Floor 1st Floor | 1 | EA EA | 7 7 | 10+ years | |
| | | | | L ∧ | 7 | 10+ years | |







| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---|---|----------|---------|--------|-------------|---------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage/ Closet | 1st Floor | 163 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 5,670 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 1,417 | SF | 7 | 10+ years | |
| | | | | | | | |
| itchen | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,665 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 3 | SF | 5 | 1-2 years | Tile separated. |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 1,668 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 111 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,968 | SF | 7 | 10+ years | |
| | | | | | | | |
| ibrary | Cooperate | Ond Floor Doors 207 | 400 | 1.5 | 7 | 40 | |
| | Casework | 2nd Floor Room 207 | 120 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor Room 207 | 3,406 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor Room 207 | 28 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Room 207 | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor Room 207 | 3,406 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor Room 207 | 46 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor Room 207 | 3,298 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Room 207 | 200 | SF | 7 | 10+ years | |
| unah 9 | Multipurpose Room | | | | | | |
| unch & | Ceiling - Exposed | 1st Floor | 2,942 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 2,942 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | | EA | | • | |
| | | 1st Floor | 2 400 | SF | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | | 2,492 | | 7 | 10+ years | Ob in a in a second |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 2 | SF | 4 | 0-1 year | Chipping away |
| | Floor - Tile | 1st Floor | 2,494 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 22 | EA | 7 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Serving Line | 1st Floor | 54 | LF | 7 | 10+ years | |
| | Stage | 1st Floor | 395 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 5,885 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 2,942 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Teachers Lounge - 207A | 330 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Teachers Lounge - 207A | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | Teachers Lounge - 207A | 330 | SF | 7 | 10+ years | |
| | | T 1 0074 | 1 | EΑ | 7 | 10+ years | |
| | Lighting - Lay-in | Teachers Lounge - 207A | 4 | | , | TOT years | |
| | Lighting - Lay-in Walls - Concrete Block | Teachers Lounge - 207A Teachers Lounge - 207A | 120 | SF | 7 | 10+ years | |





| Category : Room | | Building : Main | | | • | | |
|-----------------|-----------------------------|-----------------------------------|----------|-----|------|-------------|-------------------------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _MDF_ID | F | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Finishes | 2nd Floor | 183 | SF | 7 | 10+ years | |
| | Other Cooling Unit | 2nd Floor | 1 | EA | 7 | 6-10 years | Computer room air conditioner |
| Mechan | ical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Janitor's Closet | 1st Floor | 36 | SF | 7 | 10+ years | |
| | Janitor's Closet | 1st Floor | 4 | SF | 4 | 0-1 year | Broken floor tiles |
| | Mechanical/ Service Rooms | 1st Floor | 532 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 350 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 30 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 30 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 260 | SF | 7 | 10+ years | |
| | Boiler Room | 2nd Floor | 600 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 48 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 48 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 110 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 2,150 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 92 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 2,077 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 150 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 72 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 72 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 48 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 92 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 80 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 80 | SF | 7 | 10+ years | |
| Prep Ro | om | | | | | | |
| • | Casework | 204 - 2nd Floor Science Prep Room | 20 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 204 - 2nd Floor Science Prep Room | 157 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 204 - 2nd Floor Science Prep Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 204 - 2nd Floor Science Prep Room | 157 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 204 - 2nd Floor Science Prep Room | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 204 - 2nd Floor Science Prep Room | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 204 - 2nd Floor Science Prep Room | 147 | SF | 7 | 10+ years | |
| Restroo | m | | | | | | |
| | Accessories | 1st Floor | 64 | SF | 7 | 10+ years | |
| | | | | | | | |







| Catego | Category : Room | | В | uilding | : Main | | | | |
|--------|--|------------------------------|----------|----------|--------|-------------|--|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Ceiling - Lay-in | 1st Floor | 64 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 64 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 86 | SF | 7 | 10+ years | | | |
| | Water Closet | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1st Floor | 1 | ĒΑ | 7 | 10+ years | | | |
| | Lavatory | 1st Floor | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 4 | EA | 7 | 10+ years | | | |
| | Partitions | 1st Floor | 4 | ΕA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 60 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 178 | SF | 7 | 10+ years | | | |
| | Water Closet | 1st Floor | 4 | EA | 7 | 10+ years | | | |
| | Accessories | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor | 202 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | 1st Floor | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 4 | EA | 7 | 10+ years | | | |
| | Partitions | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| | Urinals | 1st Floor | 2 | EA | 7 | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 60 | SF | 7 | 10+ years | | | |
| | Walls - Flaster/Drywaii Walls - Structural Glazed Tile | 1st Floor | 178 | SF | 7 | 10+ years | | | |
| | | | | | | 10+ years | | | |
| | Water Closet | 1st Floor | 2 | EA SF | 7 | 10+ years | | | |
| | Accessories | 2nd Floor - next to Elevator | 128 | SF SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor - next to Elevator | 124 | | 7 | 10+ years | \\/_t=================================== | | |
| | Ceiling - Lay-in | 2nd Floor - next to Elevator | 4 | SF | 4 | 0-1 year | Water damage | | |
| | Doors - Wood Doors inclu hw | 2nd Floor - next to Elevator | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor - next to Elevator | 128 | SF | 7 | 10+ years | | | |
| | Floor Drain | 2nd Floor - next to Elevator | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | 2nd Floor - next to Elevator | 1 | EΑ | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor - next to Elevator | 1 | EA | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 2nd Floor - next to Elevator | 169 | SF | 7 | 10+ years | | | |
| | Water Closet | 2nd Floor - next to Elevator | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 2nd Floor - next to Elevator | 207 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor - next to Elevator | 207 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | 2nd Floor - next to Elevator | 207 | SF | 7 | 10+ years | | | |
| | Floor Drain | 2nd Floor - next to Elevator | 2 | EA | 7 | 10+ years | | | |
| | Lavatory | 2nd Floor - next to Elevator | 3 | EΑ | 7 | 10+ years | | | |

Campus Name: New Field Page : 12 of 30 Assessment Date: 12/30/2019





| Catego | ry : Room | | Building : Main | | | | | | | |
|--------|---|------------------------------|-----------------|-----|------|-------------|----------|--|--|--|
| | | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Lighting - Lay-in | 2nd Floor - next to Elevator | 4 | EA | 7 | 10+ years | | | | |
| | Partitions | 2nd Floor - next to Elevator | 2 | EA | 7 | 10+ years | | | | |
| | Urinals | 2nd Floor - next to Elevator | 2 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor - next to Elevator | 39 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor - next to Elevator | 200 | SF | 7 | 10+ years | | | | |
| | Water Closet | 2nd Floor - next to Elevator | 2 | EA | 7 | 10+ years | | | | |
| | Accessories | 2nd Floor - next to Elevator | 213 | SF | 7 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor - next to Elevator | 213 | SF | 7 | 10+ years | | | | |
| | Floor - Terrazzo | 2nd Floor - next to Elevator | 213 | SF | 7 | 10+ years | | | | |
| | Floor Drain | 2nd Floor - next to Elevator | 2 | EA | 7 | 10+ years | | | | |
| | Lavatory | 2nd Floor - next to Elevator | 3 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor - next to Elevator | 4 | EA | 7 | 10+ years | | | | |
| | Partitions | 2nd Floor - next to Elevator | 3 | EA | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor - next to Elevator | 200 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor - next to Elevator | 45 | SF | 7 | 10+ years | | | | |
| | Water Closet | 2nd Floor - next to Elevator | 4 | EA | 7 | 10+ years | | | | |
| | Accessories | 2nd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | | | | |
| | Floor - Terrazzo | 2nd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | | | | |
| | Floor Drain | 2nd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | | | | |
| | Lavatory | 2nd Floor - next to Stairs W | 3 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor - next to Stairs W | 4 | EA | 7 | 10+ years | | | | |
| | Partitions | 2nd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | | | | |
| | Urinals | 2nd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor - next to Stairs W | 39 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor - next to Stairs W | 200 | SF | 7 | 10+ years | | | | |
| | Water Closet | 2nd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | | | | |
| | Accessories | 2nd Floor - next to Stairs W | 213 | SF | 7 | 10+ years | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor - next to Stairs W | 213 | SF | 7 | 10+ years | | | | |
| | Floor - Terrazzo | 2nd Floor - next to Stairs W | 213 | SF | 7 | 10+ years | | | | |
| | Floor Drain | 2nd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | | | | |
| | Lavatory | 2nd Floor - next to Stairs W | 3 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | 2nd Floor - next to Stairs W | 4 | EA | 7 | 10+ years | | | | |
| | Partitions | 2nd Floor - next to Stairs W | 4 | EA | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor - next to Stairs W | 45 | SF | 7 | 10+ years | | | | |
| | Walls - Structural Glazed Tile | 2nd Floor - next to Stairs W | 200 | SF | 7 | 10+ years | | | | |
| | Water Closet | 2nd Floor - next to Stairs W | 4 | EA | 7 | 10+ years | | | | |
| | Accessories | 2nd Floor - next to Stairs W | 128 | SF | 7 | 10+ years | | | | |
| | Ceiling - Lay-in | 2nd Floor - next to Stairs W | 128 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor - next to Stairs W | 1 | EA | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor - next to Stairs W | 128 | SF | 7 | 10+ years | | | | |
| | Floor Drain | 2nd Floor - next to Stairs W | 1 | EA | 7 | 10+ years | | | | |
| | Lavatory | 2nd Floor - next to Stairs W | 1 | EA | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor - next to Stairs W | 1 | EA | 7 | 10+ years | | | | |
| | • | | | | | , | | | | |

Campus Name: New Field Page: 13 of 30 Assessment Date: 12/30/2019





| Catego | ry : Room | | В | uilding | : Main | | . 5 : |
|--------|--|------------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Structural Glazed Tile | 2nd Floor - next to Stairs W | 169 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor - next to Stairs W | 1 | EΑ | 7 | 10+ years | |
| | Accessories | 3rd Floor - next to Elevator | 207 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - next to Elevator | 207 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor - next to Elevator | 207 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - next to Elevator | 2 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor - next to Elevator | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor - next to Elevator | 4 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor - next to Elevator | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor - next to Elevator | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor - next to Elevator | 39 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor - next to Elevator | 200 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - next to Elevator | 2 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor - next to Elevator | 213 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - next to Elevator | 213 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor - next to Elevator | 213 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - next to Elevator | 2 | ĒΑ | 7 | 10+ years | |
| | Lavatory | 3rd Floor - next to Elevator | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor - next to Elevator | 4 | ΕA | 7 | 10+ years | |
| | Partitions | 3rd Floor - next to Elevator | 4 | ΕA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor - next to Elevator | 45 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor - next to Elevator | 200 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - next to Elevator | 4 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor - next to Stairs W | 207 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor - next to Stairs W | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor - next to Stairs W | 4 | EΑ | 7 | 10+ years | |
| | Partitions | 3rd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor - next to Stairs W | 39 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor - next to Stairs W | 200 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor - next to Stairs W | 2 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor Next to Stairs W | 213 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor Next to Stairs W | 213 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor Next to Stairs W | 213 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor Next to Stairs W | 2 2 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor Next to Stairs W | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor Next to Stairs W | 4 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor Next to Stairs W | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor Next to Stairs W | 45 | SF | 7 | 10+ years | |
| | Walls - Flaster/Drywall Walls - Structural Glazed Tile | 3rd Floor Next to Stairs W | 200 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor Next to Stairs W | 200 | EA | 7 | • | |
| | vvaler Ciusel | JIU FIOOI NEXT to Stalls W | 4 | EA | , | 10+ years | |







Category: Room **Building: Main** Recommend Replacement Comments Group Item - Type Location Quantity **UOM** Rank 3rd Floor Staff by Elevator Accessories 128 SF 10+ vears 7 3rd Floor Staff by Elevator 128 SF 7 Ceiling - Lav-in 10+ years Doors - Wood Doors inclu hw 3rd Floor Staff by Elevator FΑ 7 10+ years 1 Floor - Tile 3rd Floor Staff by Elevator SF 7 128 10+ years Floor Drain 3rd Floor Staff by Elevator 1 EΑ 7 10+ years 3rd Floor Staff by Elevator 7 Lavatory 1 EΑ 10+ years Lighting - Lay-in 3rd Floor Staff by Elevator EΑ 7 1 10+ years Walls - Structural Glazed Tile SF 3rd Floor Staff by Elevator 169 7 10+ years Water Closet 3rd Floor Staff by Elevator 1 EΑ 7 10+ years SF Accessories In Business Office 35 7 10+ years SF Ceiling - Lav-in In Business Office 35 7 10+ years Doors - Wood Doors inclu hw In Business Office 1 EΑ 7 10+ years Floor - Tile In Business Office 35 SF 7 10+ years Floor Drain 7 In Business Office 1 EΑ 10+ years 7 Lavatory In Business Office 1 EΑ 10+ years Lighting - Lay-in FΑ 7 In Business Office 1 10+ years Walls - Plaster/Drywall SF 7 In Business Office 54 10+ years Water Closet In Business Office 1 EΑ 7 10+ years SF Accessories In Room 101 44 7 10+ years SF Ceiling - Lay-in In Room 101 44 7 10+ years Doors - Wood Doors inclu hw In Room 101 1 EΑ 7 10+ years SF 7 10+ years Floor - Tile In Room 101 44 Floor Drain EΑ 7 In Room 101 1 10+ years 7 Lavatory In Room 101 1 FΑ 10+ years Lighting - Lay-in FΑ 7 In Room 101 1 10+ years Walls - Structural Glazed Tile SF In Room 101 72 7 10+ years Water Closet In Room 101 EΑ 7 10+ years 1 In Room 103 44 SF 7 Accessories 10+ years SF Ceiling - Lay-in In Room 103 44 7 10+ years Doors - Wood Doors inclu hw In Room 103 1 EΑ 7 10+ years Floor - Tile SF In Room 103 44 7 10+ years Floor Drain In Room 103 1 EΑ 7 10+ years 7 Lavatory In Room 103 1 FΑ 10+ years Lighting - Lay-in In Room 103 FΑ 7 1 10+ years Walls - Structural Glazed Tile SF 7 In Room 103 72 10+ years EΑ 7 Water Closet In Room 103 1 10+ years SF Accessories In Room 105 44 7 10+ years SF Ceiling - Lay-in In Room 105 44 7 10+ years Doors - Wood Doors inclu hw In Room 105 1 EΑ 7 10+ years Floor - Tile SF In Room 105 44 6 6-10 years Lavatory In Room 105 1 EΑ 7 10+ years FΑ 7 Lighting - Lay-in In Room 105 1 10+ years Walls - Structural Glazed Tile In Room 105 72 SF 7 10+ years Water Closet In Room 105 EΑ 7 10+ years







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Accessories In Room 108 44 SF 10+ vears 7 In Room 108 40 SF 7 Ceiling - Lav-in 10+ years Ceiling - Lay-in In Room 108 4 SF 4 0-1 year Water damage Doors - Wood Doors inclu hw In Room 108 1 EΑ 7 10+ years SF Floor - Tile In Room 108 44 6 6-10 years Floor Drain EΑ 7 In Room 108 1 10+ years In Room 108 EΑ 7 10+ years Lavatory 1 Lighting - Lay-in In Room 108 1 EΑ 7 10+ years Walls - Structural Glazed Tile In Room 108 72 SF 7 10+ years Water Closet In Room 108 1 EΑ 7 10+ years Accessories In Room 109 44 SF 7 10+ years Ceiling - Lay-in In Room 109 44 SF 7 10+ years Doors - Wood Doors inclu hw In Room 109 1 EΑ 7 10+ years SF 7 Floor - Tile In Room 109 44 10+ years Floor Drain EΑ 7 In Room 109 1 10+ years 7 Lavatory In Room 109 1 FΑ 10+ years Lighting - Lay-in In Room 109 1 EΑ 7 10+ years Walls - Structural Glazed Tile In Room 109 72 SF 7 10+ years Water Closet In Room 109 1 EΑ 7 10+ years Accessories In Room 110 44 SF 7 10+ years Ceiling - Lay-in In Room 110 44 SF 7 10+ years Doors - Wood Doors inclu hw 7 In Room 110 1 EΑ 10+ years Floor - Tile SF 7 In Room 110 44 10+ years 7 Floor Drain In Room 110 1 FΑ 10+ years In Room 110 FΑ 7 Lavatory 1 10+ years Lighting - Lav-in In Room 110 1 EΑ 7 10+ years Walls - Structural Glazed Tile 72 SF In Room 110 7 10+ years Water Closet In Room 110 EΑ 7 1 10+ years SF Accessories In Room 111 44 7 10+ years Ceiling - Lay-in In Room 111 44 SF 7 10+ years Doors - Wood Doors inclu hw In Room 111 1 EΑ 7 10+ years Floor - Tile In Room 111 44 SF 7 10+ years Floor Drain FΑ 7 In Room 111 1 10+ years In Room 111 FΑ 7 Lavatory 1 10+ years 7 Lighting - Lay-in In Room 111 1 EΑ 10+ years Walls - Structural Glazed Tile 72 SF 7 In Room 111 10+ years Water Closet In Room 111 1 EΑ 7 10+ years SF Accessories In Room 112 44 7 10+ years SF Ceiling - Lay-in In Room 112 44 7 10+ years Doors - Wood Doors inclu hw EΑ In Room 112 1 7 10+ years SF Floor - Tile In Room 112 44 7 10+ years Floor Drain FΑ 7 In Room 112 1 10+ years Lavatory In Room 112 EΑ 7 10+ years Lighting - Lay-in In Room 112 EΑ 7 10+ years






| Catego | ry : Room | | В | uilding | : Main | | • |
|--------|---------------------------------|-----------------------------|----------|---------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Structural Glazed Tile | In Room 112 | 72 | SF | 7 | 10+ years | |
| | Water Closet | In Room 112 | 1 | EA | 7 | 10+ years | |
| | Accessories | In Room 113 | 44 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | In Room 113 | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Room 113 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | In Room 113 | 44 | SF | 7 | 10+ years | |
| | Floor Drain | In Room 113 | 1 | EA | 7 | 10+ years | |
| | Lavatory | In Room 113 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | In Room 113 | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | In Room 113 | 72 | SF | 7 | 10+ years | |
| | Water Closet | In Room 113 | 1 | EA | 7 | 10+ years | |
| | Accessories | Men's Room in the Kitchen | 35 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Men's Room in the Kitchen | 27 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Men's Room in the Kitchen | 8 | SF | 4 | 0-1 year | Water damage |
| | Doors - Steel Doors incl hw | Men's Room in the Kitchen | 1 | EA | 7 | 10+ years | • |
| | Floor - Concrete Epoxy/ Painted | Men's Room in the Kitchen | 35 | SF | 7 | 10+ years | |
| | Floor Drain | Men's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Lavatory | Men's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Men's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Men's Room in the Kitchen | 65 | SF | 7 | 10+ years | |
| | Water Closet | Men's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Accessories | Women's Room in the Kitchen | 35 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Women's Room in the Kitchen | 35 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Women's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Women's Room in the Kitchen | 35 | SF | 7 | 10+ years | |
| | Floor Drain | Women's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Lavatory | Women's Room in the Kitchen | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | Women's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Women's Room in the Kitchen | 65 | SF | 7 | 10+ years | |
| | Water Closet | Women's Room in the Kitchen | 1 | EA | 7 | 10+ years | |
| atego | ry : Classroom | | R | uilding | : Main | | |

| J | , | | | | | Recommend | |
|----------|-----------------------------|-----------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroc | m #101 (Pre School) | | | | | | |
| | Casework | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,044 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 26 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,044 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 11 | EΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,350 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | | | |
|----------|-----------------------------|------------|----------|----------|--------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | | | | | | | | | |
| Classroo | om #102 (Kindergarten) | | | | | | | | |
| | Casework | 1st Floor | 10 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 750 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 750 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 1st Floor | 914 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| Classrae | om #102 (Pro Sahaal) | | | | | | | | |
| Classio | om #103 (Pre School) | 1 at Floor | | 1.5 | 7 | 10 | | | |
| | Casework | 1st Floor | 57 | LF SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 1,044 | | 7 | 10+ years | | | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 6-10 years | | | |
| | Floor - Tile | 1st Floor | 1,044 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 57 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 1,350 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| Classroo | om #105 (Pre School) | | | | | | | | |
| | Casework | 1st Floor | 57 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 943 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 943 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 7 | 6-10 years | | | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 57 | SF | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 1st Floor | 1,140 | SF | 7 | 10+ years | | | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| 01 | W400 (16) | | | | | | | | |
| Classroo | om #108 (Kindergarten) | | | | | | | | |
| | Casework | 1st Floor | 28 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 970 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 970 | SF | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | | | |







| Category : Classroom | | В | uilding | : Main | | | |
|----------------------|-----------------------------|-----------|----------|--------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 65 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,174 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| | | | | | | • | |
| Classroo | m #109 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 943 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 943 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 57 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,139 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | ĒΑ | 7 | 10+ years | |
| | | | _ | | • | .o. yea.e | |
| lassroo | m #110 (Pre School) | | | . – | | | |
| | Casework | 1st Floor | 65 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 970 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 970 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 65 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,174 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| Classroo | m #111 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,044 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,044 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 57 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,174 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1,174 | EA | 7 | 10+ years | |
| Naa | #440 (Drs Cabaal) | | | | | • | |
| Jassroo | m #112 (Pre School) | 4 . 🗔 | | | | 40 | |
| | Casework | 1st Floor | 28 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,174 | SF | 7 | 10+ years | |







| Catego | ry : Classroom | | В | uilding | : Main | | 707 W Morse Avenue, Chicago, il 60626 |
|-----------|-----------------------------|-----------|----------|---------|---------|-------------|---------------------------------------|
| Outogo | i i ciacci com | | | anamg | · Maiii | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,174 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 65 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,350 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| _Classroo | om #113 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 57 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 864 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 864 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 57 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 991 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| _Classroo | om #201 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 945 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 945 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 770 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 245 | SF | 7 | 10+ years | |
| _Classroo | om #202 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,335 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 28 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,335 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 15 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,149 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 257 | SF | 7 | 10+ years | |
| | | | | | | | |







| Categoi | ry : Classroom | | В | uilding | : Main | | 707 W WOISE AVENUE, CHICAGO, IL 60020 |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|---------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #203 (Computer Lab) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,380 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 26 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,380 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,205 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 245 | SF | 7 | 10+ years | |
| _Classroo | m #204 (Art Room) | | | | | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,335 | SF | 7 | 6-10 years | |
| | Doors - Side-lite | 2nd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,335 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,149 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 257 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | 10+ years | |
| Classroo | m #208 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 945 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 945 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 758 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 257 | SF | 6 | 10+ years | |
| Classroo | m #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 945 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 945 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 501 | SF | 7 | 10+ years | |
| | 2.00. | | 001 | ٥. | • | 12 / 300.0 | |







| Classroom #212 (Regular Classroom) End of Place Classroom #212 (Regular Classroom) End of Place Classroom #212 (Regular Classroom) End of Place End of Place | Catego | ry : Classroom | | В | uilding | : Main | | |
|--|-----------|---|-----------|----------|---------|--------|-----------|---------------|
| Walls - Piaster/Dywall Znd Floor S14 SF 7 10+ years | | | | | | | | |
| Classroom #212 (Regular Classroom) | Group | | | Quantity | | Rank | | Comments |
| Casework | | Walls - Plaster/Drywall | 2nd Floor | 514 | SF | 7 | 10+ years | |
| Casework | | | | | | | | |
| Celling - Lay-in 2nd Floor 945 SF 7 10+ years Doors - Side-lite 2nd Floor 13 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years To | _Classroc | , | | | | | | |
| Doors - Side-lite 2nd Floor 13 | | | | | | | | |
| Doors - Wood Doors inclu hw Znd Floor 1 | | Ceiling - Lay-in | | | | | | |
| Floor - Tile | | | | | | | - | |
| Lighting - Lay-in 2nd Floor 32 EA 7 6-10 years Walls - Concrete Block 2nd Floor 257 SF 7 10+ years Walls - Concrete Block 2nd Floor 257 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 257 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 257 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 380 LF 7 10+ years 2nd Floor 28 SF 7 2nd Ploor 2nd Floor 2nd Floor | | | | | | | | |
| Marker Board 2 nd Floor 32 LF 7 7 6-10 years Walls - Concrete Block 2nd Floor 758 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 257 SF 7 10+ years Classroom #213. (Art Room). 2nd Floor 80 LF 7 10+ years Ceiling - Lay-in 2nd Floor 1,380 SF 7 10+ years Doors - Side-lite 2nd Floor 28 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 28 SF 7 10+ years Floor - Tile 2nd Floor 1,380 SF 7 6-10 years Lighting - Lay-in 2nd Floor 13 EA 7 6-10 years Lighting - Lay-in 2nd Floor 32 LF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,205 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,205 SF 7 10+ years Work Sink 2nd Floor 2 EA 7 10+ years Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Colling - Lay-in 3rd Floor 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 12 SF 7 10+ years | | | | | | | | |
| Walls - Concrete Block | | | | | | | , | |
| Walls - Plaster/Drywall 2nd Floor 257 SF 7 10+ years | | | | | | | | |
| Classroom #213 (Art Room) Casework 2nd Floor 80 | | | | | | | 10+ years | |
| Casework | | Walls - Plaster/Drywall | 2nd Floor | 257 | SF | 7 | 10+ years | |
| Casework | Classroo | om #213 (Art Room) | | | | | | |
| Celiling - Lay-in | | • | 2nd Floor | 80 | LF | 7 | 10+ vears | |
| Doors - Side-lite | | | | | SF | | | |
| Doors - Wood Doors inclu hw | | | | | | | | |
| Floor - Tile | | | | | | | • | |
| Lighting - Lay-in | | | | | | - | | |
| Marker Board 2nd Floor 32 LF 7 10+ years Walls - Concrete Block 2nd Floor 1,205 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 245 SF 7 10+ years Work Sink 2nd Floor 2 EA 7 10+ years Classroom#301 (Regular Classroom) Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 933 SF 7 10+ years Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Water damage Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Walls - Clore to Floor years For 7 10+ years Year | | | | | | | • | |
| Walls - Concrete Block Walls - Plaster/Drywall 2nd Floor 1,205 SF 7 10+ years 245 SF 7 10+ years 10+ years 245 SF 7 10+ ye | | | | | | | | |
| Walls - Plaster/Drywall Work Sink 2nd Floor 245 SF 7 10+ years Classroom #301 (Regular Classroom) 7 10+ years Casework Ceiling - Lay-in 3rd Floor Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 14 EA 7 10+ years Floor - Tile 3rd Floor 15 EA 7 10+ years Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Walls - Concrete Block 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 250 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Walls - Lay-in 3rd Floor 250 SF 7 10+ years Walls - Lay-in 3rd Floor 250 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 20 SF 4 0-1 year Water damage Water damage Doors - Side-lite 3rd Floor 3rd Floor 13 SF 7 10+ years Water damage | | | | | | - | - | |
| Classroom #301 (Regular Classroom) Casework | | | | | | | | |
| Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 933 SF 7 10+ years Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Tile 3rd Floor 945 SF 7 10+ years Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Classword Ceiling - Lay-in 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 925 | | | | | | | - | |
| Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 933 SF 7 10+ years Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Tile 3rd Floor 945 SF 7 10+ years Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Classword Ceiling - Lay-in 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 925 | 0.1 | W004 (D | | | | | | |
| Ceiling - Lay-in 3rd Floor 933 SF 7 10+ years Ceiling - Lay-in 3rd Floor 12 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Tile 3rd Floor 945 SF 7 10+ years Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Classroom #302 (Regular Classroom) Casework Ceiling - Lay-in 3rd Floor 3rd Floor 3rd Floor 20 SF 7 10+ years Ceiling - Lay-in Doors - Side-lite 3rd Floor 20 SF 4 0-1 year Water damage | _Classroc | | | | | | | |
| Ceiling - Lay-in Doors - Side-lite 3rd Floor 12 SF 4 0-1 year Water damage Water damage Doors - Side-lite Doors - Side-lite 3rd Floor 13 SF 7 10+ years 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years 10+ years Floor - Tile Side SF 7 10+ years 3rd Floor 13 EA 7 10+ years Lighting - Lay-in Agriculture 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block Walls - Plaster/Drywall 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Casework Caling - Lay-in Srd Floor 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in Srd Floor 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 3rd Floor 13 SF 7 10+ years | | | | | | | • | |
| Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | • | |
| Doors - Wood Doors inclu hw 3rd Floor 1 EA 7 10+ years Floor - Tile 3rd Floor 945 SF 7 10+ years Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years Water damage Doors - Side-lite 3rd Floor 3rd Flo | | | | | | | , | Water damage |
| Floor - Tile | | | | | | | • | |
| Lighting - Lay-in 3rd Floor 13 EA 7 10+ years Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | = | | | • | |
| Marker Board 3rd Floor 32 LF 7 6-10 years Walls - Concrete Block 3rd Floor 765 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Classroom #302 (Regular Classroom) Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | • | |
| Walls - Concrete Block Walls - Plaster/Drywall 3rd Floor 765 SF 7 10+ years 250 SF 7 10+ years Classroom #302 (Regular Classroom) 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in Ceiling - Lay-in Doors - Side-lite 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | | |
| Walls - Plaster/Drywall 3rd Floor 250 SF 7 10+ years Classroom #302 (Regular Classroom) Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | • | |
| Classroom #302 (Regular Classroom) Casework 3rd Floor 36 LF 7 10+ years Ceiling - Lay-in 3rd Floor 925 SF 7 10+ years Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | 3rd Floor | | | | | |
| Casework3rd Floor36LF710+ yearsCeiling - Lay-in3rd Floor925SF710+ yearsCeiling - Lay-in3rd Floor20SF40-1 yearWater damageDoors - Side-lite3rd Floor13SF710+ years | | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 7 | 10+ years | |
| Casework3rd Floor36LF710+ yearsCeiling - Lay-in3rd Floor925SF710+ yearsCeiling - Lay-in3rd Floor20SF40-1 yearWater damageDoors - Side-lite3rd Floor13SF710+ years | _Classroo | om #302 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in3rd Floor925SF710+ yearsCeiling - Lay-in3rd Floor20SF40-1 yearWater damageDoors - Side-lite3rd Floor13SF710+ years | | ί ο , | 3rd Floor | 36 | LF | 7 | 10+ vears | |
| Ceiling - Lay-in 3rd Floor 20 SF 4 0-1 year Water damage Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | | |
| Doors - Side-lite 3rd Floor 13 SF 7 10+ years | | | | | | | | Water damage |
| • | | Doors - Side-lite | | | | | | Trator damage |
| Solo Mode Book Made III. | | | | | | | • | |
| | | 2 | 0.0 | • | | • | , | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------------|-----------|----------|------------|--------|-------------|--------------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 765 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 7 | 10+ years | |
| Classroo | m #303 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 26 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 20 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | | 3rd Floor | , | | | • | |
| | Lighting - Lay-in Marker Board | 3rd Floor | 13 32 | EA LF | 7 | 10+ years | |
| | | 3rd Floor | | | 7 | 6-10 years | |
| | Walls - Concrete Block | | 950 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 500 | SF | 7 | 10+ years | |
| Classroo | m #304 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 933 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 12 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 515 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 500 | SF | 7 | 10+ years | |
| Classroo | m #305 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 950 | SF | 7 | 10+ years | |
| | | 3rd Floor | 500 | SF SF | 7 | | |
| | Walls - Plaster/Drywall | 31U F100f | 500 | 3 F | 1 | 10+ years | |
| Classroo | m #306 (Special Education) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 945 | SF | 7 | 10+ years | |







| Catego | ry : Classroom | | В | uilding | : Main | | • |
|----------|-----------------------------------|------------|----------|---------|--------|-------------|----------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 4 | 0-1 year | Handle broken. |
| | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 765 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 6 | 6-10 years | |
| Classroc | om #307 (Special Education) | | | | | | |
| Classioo | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 688 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 12 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 700 | SF | 7 | 10+ years | |
| | | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Lighting - Lay-in Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 400 | SF | 7 | 10+ years | |
| | | 3rd Floor | 500 | SF | 7 | • | |
| | Walls - Plaster/Drywall | 314 F1001 | 500 | SF | , | 10+ years | |
| Classroc | om #308 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 765 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 7 | 10+ years | |
| Classroc | om #309 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,376 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 10 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 950 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 500 | SF | 7 | 10+ years | |
| | vvalio i lastel/Diywali | 314 1 1001 | 300 | Oi. | , | 10+ years | |







| Category : Classroom | | | В | uilding | | | |
|----------------------|-----------------------------------|-------------|----------|---------|------|-------------|--------------|
| | | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroc | om #310 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | ĒΑ | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 515 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 500 | SF | 7 | 10+ years | |
| Classroo | om #311 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,376 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | 3 |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | ĒΑ | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 950 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 500 | SF | 7 | 10+ years | |
| Classroo | om #312 (Other Instructional Use) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 929 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 16 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 945 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | ĒΑ | 7 | 10+ years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 765 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 7 | 10+ years | |
| lassroc | om #313 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,364 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 16 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 13 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,380 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | | | | | - | - , | |
| | | | | | | | |





Category : Classroom

| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------|--------------------------------------|----------------------------|----------|----------|--------|--------------------------|---------------|
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,200 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 250 | SF | 7 | 10+ years | |
| ategoi | ry : Interior | | В | uilding | : Main | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| orridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 5,567 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 11 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 5,567 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 54 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | 1st Floor | 6,012 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 4,209 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 16 | SF | 4 | 0-1 year | Water damage. |
| | Doors - Steel Doors incl hw | 2nd Floor | 6 | EA | 7 | 10+ years | - |
| | Drinking Fountains - Single Fountain | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 2nd Floor | 4,225 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 43 | ĒΑ | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 4,259 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4,225 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 6 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd Floor | 4,225 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | | | | | | |
| | | 3rd Floor | 43 | EA SF | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 4,295 | SF | 7 | 10+ years | |
| afety | | | | | | | |
| | Camera Viewing Station | Entire Building | 1 | EΑ | 7 | 10+ years | |
| | Security Cameras | Entire Building | 7 | EA | 7 | 10+ years | |
| | Security Cameras | Entire Building | 7 | EA | 7 | 10+ years | |
| | Security Cameras | Entire Building | 6 | EA | 7 | 10+ years | |
| | Security Cameras | Exterior | 7 | EA | 7 | 10+ years | |
| airs | | | | | | | |
| | Ceiling - Plaster/Drywall | Staircase C | 400 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Staircase C | 400 | SF | 7 | 6-10 years | |
| | Handrails | Staircase C | 161 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Staircase C | 4 | EΑ | 7 | 6-10 years | |
| | Stairs - Terrazzo | Staircase C | 194 | LF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Staircase C | 435 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Staircase C Staircase E | 400 | SF | 7 | 10+ years | |

Building: Main

Campus Name: New Field Page : 26 of 30 Assessment Date: 12/30/2019





| Category : Interior | | | В | uilding | | | | |
|---------------------|--------------------------------|-------------|----------|---------|------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Floor - Terrazzo | Staircase E | 400 | SF | 7 | 6-10 years | | |
| | Handrails | Staircase E | 161 | LF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Staircase E | 4 | EA | 7 | 6-10 years | | |
| | Stairs - Terrazzo | Staircase E | 194 | LF | 7 | 6-10 years | | |
| | Walls - Structural Glazed Tile | Staircase E | 435 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | Staircase W | 400 | SF | 7 | 10+ years | | |
| | Floor - Terrazzo | Staircase W | 400 | SF | 7 | 6-10 years | | |
| | Handrails | Staircase W | 161 | LF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Staircase W | 4 | EA | 7 | 6-10 years | | |
| | Stairs - Terrazzo | Staircase W | 194 | LF | 7 | 10+ years | | |
| | Walls - Structural Glazed Tile | Staircase W | 435 | SF | 7 | 10+ years | | |
| Vertical | Conveyance | | | | | | | |
| | Elevator - Hydraulic Elevator | | 1 | EA | 6 | 10+ years | | |

Campus Name: New Field Page : 27 of 30 Assessment Date: 12/30/2019



Category : Site Building : Site

| Catego | y . Site | | | unung | . Oite | | |
|-----------|---------------------------------------|--|----------|-------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Civil/Dra | nage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 11 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Drain | Entire Site | 3 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 7 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Marinole | Little Site | , | LA | O | 10+ years | |
| Fencing | | | | | | | |
| J | Fencing - New Standard Ornamental | Entire Site | 2,080 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 25 | LF | 4 | 0-1 year | Missing piece and bent. |
| | | | | | | | |
| _Landsca | | F .: 0: | | | | | |
| | Benches | Entire Site | 2 | EA | 6 | 10+ years | |
| | Irrigation | Entire Site | 2,750 | SF | 5 | 2-5 years | |
| | Landscape - Grass | Entire Site | 2,750 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 11,500 | SF | 6 | 10+ years | |
| | Parkway trees | Entire Site | 18 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 10,550 | SF | 6 | 10+ years | |
| | Retaining Wall - Concrete | Entire Site | 2,560 | SF | 6 | 10+ years | |
| | Retaining Wall - Masonry | Entire Site | 1,000 | SF | 5 | 0-1 year | Cracking and chipping throughout. |
| | Trash Receptacles | Entire Site | 4 | EA | 6 | 10+ years | Cracking and cripping unoughout. |
| | Trasii Neceptacies | Littile Oile | 7 | L/\ | O | 101 years | |
| Parking I | ot | | | | | | |
| · · | Concrete Curbs | Remote parking lot at SE corner of N Clark St and W Farwell Ave | 490 | LF | 6 | 10+ years | |
| | Interior Plantings | Remote parking lot at SE corner of N Clark St and W Farwell Ave | 36 | LF | 6 | 10+ years | |
| | Lighting - Pole Mounted | Remote parking lot at SE corner of N Clark St and W Farwell Ave | 4 | EA | 6 | 10+ years | |
| | Surface - Asphalt | Remote parking lot at SE corner of | 12,750 | SF | 4 | 0-1 year | Ponding, cracks, holes |
| | Vehicular Screening | N Clark St and W Farwell Ave Remote parking lot at SE corner of | 490 | LF | 6 | 10+ years | |
| | verilicular Screening | N Clark St and W Farwell Ave | | | O | 10+ years | |
| | Surface - Asphalt | SW corner | 1,850 | SF | 6 | 10+ years | |
| | Trash Compactor | SW corner | 1 | EA | 6 | 10+ years | |
| | Trash Enclosure - Masonry | SW corner | 540 | SF | 6 | 10+ years | |
| | Trash Enclosure - Masonry | SW corner | 540 | SF | 5 | 1-2 years | Spalling |
| | Vehicular Screening | SW corner | 24 | LF | 6 | 10+ years | - r - · · · · · · · · · · · · · · · · · |
| | • • • • • • • • • • • • • • • • • • • | | | | - | - , | |
| _Playgrou | | | | | | | |
| | Equipment - School Age 5-12 | NE Courtyard | 1 | EA | 5 | 2-5 years | Broken rope in circle. |
| | Surface - Poured Surface | NE Courtyard | 3,600 | SF | 6 | 2-5 years | Ponding - where ponding was |
| | Equipment - Pre K 3-5 | NW Courtyard | 1 | EA | 6 | 10+ years | observed surface is deteriorating. |
| | Equipment 110100 | county and | ' | L/ \ | O | ioi youio | |

Campus Name: New Field Page : 28 of 30 Assessment Date: 12/30/2019



New Field Elementary School 1707 W Morse AVENUE, Chicago, IL 60626

| Category : Site | | | В | uilding | | | |
|-----------------|---------------------------------|-----------------|----------|---------|------|-------------|--------------------------|
| | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Surface - Poured Surface | NW Courtyard | 3,600 | SF | 6 | 2-5 years | Ponding. |
| Sidewalk | S | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 465 | LF | 6 | 2-5 years | Ponding, cracks |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 8,675 | SF | 6 | 10+ years | - |
| _Signage | | | | | | | |
| | Flag Pole - Flag Pole | North Courtyard | 1 | EA | 6 | 10+ years | |
| | Monument - Sign | North Courtyard | 1 | EA | 5 | 1-2 years | Spalling/ cracking brick |

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: New Field Page: 29 of 30 Assessment Date: 12/30/2019

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

| Classicolli Sullillary | | | | Floor Plan | | Glazed | Operable | | |
|-------------------------|-------------------|---------------|--------|------------|-------|--------|----------|--------|--------|
| | | | Room | Room | Area | Window | Window | Window | Smart- |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | <u>-</u> | · | | | | | | | |
| Art Room | Kindergarten | 2nd Floor | 213 | 2-11 | 1,380 | 162 | 87 | N | N |
| Art Room | Science | 2nd Floor | 204 | 2-33 | 1,335 | 144 | 72 | N | Υ |
| Computer Lab | Computer Lab | 2nd Floor | 203 | 2-18 | 1,380 | 144 | 72 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 102 | 1-53 | 750 | 84 | 42 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 108 | 1-29 | 970 | 112 | 56 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 109 | 1-01 | 943 | 84 | 42 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 111 | 1-04 | 1,044 | 84 | 42 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 113 | 1-07 | 864 | 84 | 42 | N | N |
| Other Instructional Use | Regular Classroom | 3rd Floor | 312 | 3-03 | 945 | 108 | 54 | N | N |
| Pre School | Pre School | 1st Floor | 101 | 1-38 | 1,044 | 84 | 42 | N | N |
| Pre School | Pre School | 1st Floor | 103 | 1-35 | 1,044 | 84 | 42 | N | N |
| Pre School | Pre School | 1st Floor | 105 | 1-32 | 943 | 84 | 42 | N | N |
| Pre School | Pre School | 1st Floor | 110 | 1-26 | 970 | 112 | 56 | N | N |
| Pre School | Pre School | 1st Floor | 112 | 1-23 | 1,174 | 112 | 56 | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 2-23 | 945 | 108 | 54 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 2-30 | 1,335 | 144 | 72 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 2-01 | 945 | 108 | 54 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 2-02 | 945 | 108 | 54 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 2-03 | 945 | 108 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 3-15 | 945 | 108 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 3-21 | 945 | 144 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 3-14 | 1,380 | 144 | 72 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 3-22 | 945 | 144 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 3-13 | 1,380 | 144 | 72 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 3-01 | 945 | 144 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 3-11 | 1,380 | 144 | 72 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 310 | 3-02 | 945 | 144 | 54 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 311 | 3-10 | 1,380 | 144 | 72 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 313 | 3-09 | 1,380 | 144 | 72 | N | N |
| Special Education | Regular Classroom | 3rd Floor | 306 | 3-23 | 945 | 144 | 54 | N | N |
| Special Education | Regular Classroom | 3rd Floor | 307 | 3-12 | 700 | 72 | 36 | N | N |