

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1913 | 4 | 219,500 |
| Addition 1 | 1930 | 3 | 33,906 |
| Addition 2 | 1930 | 3 | 37,798 |
| Campus Total | | | 291,204 |

| Catego | ategory : Exterior | | | Building : Main | | | |
|----------|---|-----------------|----------|-----------------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | 9 | | | | | | |
| | Entrance Control - Audio and Video | 10 - Main | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior AMP Door | 10 - Main | 4 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 10 - Main | 2 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | 4 | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 4 | 10 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | 4 | 10 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 4 | 300 | LF | 6 | 10+ years | |
| | Power Door Operator and Controls | 4 | 1 | EA | 7 | 6-10 years | |
| | Ramp Handrail - Steel_Ramp Handrail | 4 | 120 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 4 | 120 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | 4 | 80 | LF | 6 | 10+ years | |
| _Foundat | ion | | | | | | |
| | Foundation - Concrete | Entire Building | 1,314 | LF | 7 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 218,186 | SF | 7 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 558 | SF | 6 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 282 | SF | 6 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 1,032 | SF | 6 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 4 | EA | 6 | 6-10 years | |
| | | | | | | | |



| Category : Exterior | | | B | uilding | | | |
|---------------------|--|-----------------|----------|---------|--------|-------------|-------------------|
| - | | | | Ū | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Exterior Lighting - Wall Mounted | Entire Building | 20 | EA | 6 | 6-10 years | |
| | | | | | | | |
| Roof Sys | stem | | | | | | |
| | Access Ladder - Metal | E | 2 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | E | 196 | LF | 6 | 10+ years | |
| | Coping - Metal | E | 300 | LF | 6 | 2-5 years | |
| | Coping - Metal | E | 727 | LF | 5 | 2-5 years | |
| | Coping - Terra Cotta | E | 269 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | E | 196 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | Ē | 10 | LF | 5 | 0-1 year | Damaged downspout |
| | Downspouts - Exterior Downspouts | Ē | 30 | LF | 5 | 0-1 year | Broken downspout |
| | Downspouts - Interior Downspouts | Ē | 480 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Ē | 1,242 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | E | 150 | LF | 4 | 0-1 year | Bowed parapet |
| | Roof - Modified Bitumen | E | 39,719 | SF | 5 | 2-5 years | Dowed paraper |
| | Roof Hatch - Metal | E | 2 | EA | 7 | 10+ years | |
| | Roof Structure - Steel with Clay Tile Arch | E | 39,719 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | E F | 1 | EA | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | F | 50 | LF | 5 | 6-10 years | |
| | Roof - Modified Bitumen | F | 17,368 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | F | 17,368 | SF | 5 7 | • | |
| | | G | | LF | | 10+ years | |
| | Coping - Metal | | 200 | LF | 5 | 2-5 years | |
| | Coping - Terra Cotta | G | 138 | | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | G | 338 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | G | 7,372 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | G | 7,372 | SF | 7 | 10+ years | |
| | Coping - Stone | Н | 94 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | H | 35 | LF | 6 | 6-10 years | |
| | Parapet - Parapet > 30" | H | 94 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | H | 2,914 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | Н | 2,914 | SF | 7 | 10+ years | |
| | Coping - Terra Cotta | l | 286 | LF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | l | 40 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | l | 40 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | | 158 | LF | 7 | 10+ years | |
| | Parapet - Parapet > 30" | | 128 | LF | 7 | 10+ years | |
| | Roof - Metal | | 5,184 | SF | 7 | 10+ years | |
| | Roof - Modified Bitumen | | 1,320 | SF | 7 | 6-10 years | |
| | Roof Structure - Steel with Clay Tile Arch | I | 6,504 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | J | 2 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | J | 88 | LF | 6 | 10+ years | |
| | Coping - Metal | J | 217 | LF | 6 | 10+ years | |
| | Coping - Terra Cotta | J | 24 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | J | 40 | LF | 6 | 10+ years | |



| Jaicgo | ry : Exterior | | В | uilding | : Main | | |
|---------|---|-----------------|----------|---------|--------|-------------|---|
| - | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Parapet - 16" - 30" Height | J | 329 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | J | 9,564 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | J | 9,564 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | К | 4 | EA | 7 | 10+ years | |
| | Coping - Clay Tile | К | 24 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | К | 50 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | К | 24 | LF | 6 | 10+ years | |
| | Roof - Metal | К | 300 | SF | 6 | 6-10 years | |
| | Roof - Modified Bitumen | К | 8,076 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | К | 8,376 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | L | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | L | 94 | LF | 6 | 10+ years | |
| | Downspouts - Exterior Downspouts | L | 35 | LF | 6 | 6-10 years | |
| | Parapet - Parapet > 30" | L | 94 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | L | 2,914 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel with Clay Tile Arch | L | 2,914 | SF | 7 | 10+ years | |
| | | | | | | | |
| Valls | Cheek-Wall - Stone | Entiro Duilding | 64 | SF | 6 | 10 | |
| | | Entire Building | - | LF | | 10+ years | |
| | Cornice - Metal Projecting | Entire Building | 1,330 | SF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 30,096 | | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 559 | SF | 5 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 600 | SF | 5 | 10+ years | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 768 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 3,440 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 200 | SF | 5 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 10 | SF | 3 | 1-2 years | Cracked or missing a stone |
| | Exterior Walls - Terra Cotta | Entire Building | 6,751 | SF | 6 | 10+ years | |
| | Exterior Walls - Terra Cotta | Entire Building | 1,175 | SF | 5 | 10+ years | |
| Vindows | S | | | | | | |
| | Guard - Guards perforated | Entire Building | 10,162 | SF | 6 | 10+ years | |
| | Guard - Guards perforated | Entire Building | 300 | SF | 5 | 10+ years | Several guards are flapping in the wind because they are bent at the frames |
| | Lintels - Brick | Entire Building | 22 | LF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 2,778 | LF | 6 | 10+ years | |
| | Lintels - Stone | Entire Building | 40 | LF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 24,915 | SF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 1,445 | SF | 6 | 10+ years | |
| atego | ry : Electrical | | В | uilding | : Main | | |
| iroup | | Location | Quantity | UOM | Rank | Recommend | Comments |

| | Public Schools | | | | | 5900 | 0 N Glenwood AVENUE, Chicago, IL 6066 |
|-----------|--|-----------------|----------|---------|--------|--------------------------|---|
| | | | | | | Replacement | |
| mergen | icy System | | | | | | |
| | Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building | 13,061 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 41,541 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 8,466 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 11,500 | SF | 6 | 10+ years | Building has AC generator, EM pan |
| | Emergency A/C Power - Multipurpose | Entire Building | 1,344 | SF | 6 | 10+ years | |
| | Room | | | | | | |
| | Emergency A/C Power - Pool | Entire Building | 3,160 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 3,144 | SF | 6 | 10+ years | |
| | Exit Signs - Auditoium | Entire Building | 10 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 37 | EA | 6 | 6-10 years | Building served by AC generator |
| | Exit Signs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | 6 9 6 |
| | Exit Signs - Lunchroom | Entire Building | 9 | EA | 6 | 6-10 years | |
| | Exit Signs - Pool | Entire Building | 3 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Pool | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 219,500 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 219,500 | SF | 6 | 6-10 years | |
| lain Ser | vice | | | | | | |
| | PA System | Entire Building | 219,500 | SF | 6 | 6-10 years | Connected to north and south addition |
| | Main Electrical Service - Greater than 3000 A 120/208/3PH | Mechanical Room | 1 | EA | 6 | 6-10 years | Serves main building, north and south building |
| ower Di | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 5 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 40 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 3 | EA | 7 | 10+ years | |
| | Transformers - 120/240 - 120/208 | Entire Building | 2 | EA | 6 | 6-10 years | |
| atego | ry : Fire Protection | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| ire Aları | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Fire Alarm_System | Entire Building | 219,500 | SF | 6 | 10+ years | Connected to addition 1 building, fir alarm panel in addition 1 |



Group

Nicholas Senn High School

5900 N Glenwood AVENUE, Chicago, IL 60660 Category : Mechanical **Building : Main** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Air Conditioning Condensing Unit- Roof Mounted - 11-20 ΕA Roof 1 6 6-10 years Serves main building, pool area tons Condensing Unit- Roof Mounted - Less Roof 2 EΑ 6 6-10 years Serves office than 5 tons FΑ 6 Condensing Unit- Roof Mounted - Less Roof 1 6-10 years Serves Computer room than 5 tons Air Handling Systems Fan Coil Unit- Celing Mounted - Electric Entire Building 2 ΕA 6 At vestibule ceiling, electric only, no 10+ years condenser Fan Coil Unit- Celing Mounted - Electric Entire Building 2 FΑ 5 6-10 years In room 168, light control, split system. office Fan Coil Unit- Celing Mounted - Electric Entire Building 2 ΕA 5 6-10 vears In office, pool area, split system Air Handling Unit- Built Up- Multi Zone- Dual Mechanical Room 1 ΕA 5 6-10 years AHU 6, serves classrooms and Temperature Coils - 25001 - 35000 cfm corridor 5 Air Intake Mechanical Room 1 ΕA 6-10 years ΕA 5 6-10 years Auxiliaries - 25001 - 35000 cfm Mechanical Room 1 LF Return Duct Work - Masonry and Ducts-100 6 Mechanical Room 10+ years From corridor Missing or Existing Shaft Zone Dampers Mechanical Room 9 FΑ 5 6-10 years Some dampers are manually operated Air Handling Unit- Built Up-Multi Zone-Mechanical Room 1 EΑ 5 10+ years AHU 7, serves north portion of Double Delivery-Dual Temperature Coils building 15000 - 30000 cfm ΕA Air Handling Unit- Built Up-Multi Zone-Mechanical Room 1 5 10+ years AHU 3, serves south end of building Double Delivery-Dual Temperature Coils -15000 - 30000 cfm Air Handling Unit- Built Up-Multi Zone-Mechanical Room FΑ 5 AHU 2, serves main building 1 10+ years Double Delivery-Dual Temperature Coils classrooms 30001 - 45000 cfm Air Intake Mechanical Room 3 ΕA 5 6-10 years 2 ΕA 5 6-10 years Auxiliaries - 15000 - 30000 cfm Mechanical Room Auxiliaries - 30001 - 45000 cfm Mechanical Room 1 EΑ 5 10+ years Return Duct Work - Masonry and Ducts-Mechanical Room 100 LF 6 10+ vears Missing or Existing Shaft Return Duct Work - Masonry and Ducts-LF 100 6 From corridor Mechanical Room 10+ vears

Missing or Existing Shaft

Missing or Existing Shaft

Missing or Existing Shaft

Zone Dampers

Return Duct Work - Masonry and Ducts-

Return Duct Work - Masonry and Ducts-

Mechanical Room

Mechanical Room

Mechanical Room

LF

LF

EΑ

6

5

5

10+ years

6-10 years

6-10 years

From corridors

operated

Some dampers are manually

50

50

112



| Catego | ry : Mechanical | | R | uilding | : Main | 000 | DN Glenwood AVENUE, Chicago, IL 60660 |
|------------|--|-----------------|----------|---------|--------|-------------|---|
| Oalcyo | | | | unung | . Mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Air Handling Unit- Built Up- Single Zone- Hot Water and Chilled Water Coils - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | AHU 9, serves auditorium in main building |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Auxiliaries - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room | 50 | LF | 5 | 6-10 years | from auditorium, thru corridor |
| | Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | AHU 10 Serves serving area and engineer's office area |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Auxiliaries - 8001 - 15000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room | 100 | LF | 6 | 10+ years | From corridor |
| | Zone Dampers | Mechanical Room | 3 | EA | 5 | 6-10 years | |
| | Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM | Roof | 4 | EA | 6 | 10+ years | Serve main building air handlers, in line |
| | Outdoor Return Fans- inline Centrifugal - 10001 - 20000 CFM | Roof | 1 | EA | 6 | 10+ years | Serves main building air handler |
| | Dehumidification Unit- Outdoor- Hot Water Heating- DX Cooling with Remote Mounted Compressor - 4001 - 8000 cfm | Roof | 1 | EA | 6 | 6-10 years | Serves pool, Dectron |
| Heating | | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EA | 6 | 10+ years | Behind grill, replaced steam radiators |
| | Fin Tube - Hot Water | Entire Building | 94 | LF | 6 | 10+ years | |
| | Wall Heater - Electric | Entire Building | 6 | EA | 5 | 6-10 years | |
| | Unit Heater - Electric | Entire Site | 2 | EA | 5 | 6-10 years | In restrooms |
| Mechani | cal Plumbing | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 1,800 | LF | 6 | 10+ years | Hot water and chilled water pipes, dual temp |
| | Dual Temperature Pump - Less than 10 | Entire Building | 6 | EA | 6 | 6-10 years | Serve air handlers, circulators |
| Tempera | ature Control | | | | | | |
| | DDC System | Entire Building | 219,500 | SF | 5 | 6-10 years | Software not upgraded, computer is old. serves main, addition 1, addition 2 |
| | Electric Thermostat | Entire Building | 8 | EA | 5 | 6-10 years | — |
| | Thermostats - DDC | Entire Building | 120 | EA | 7 | 10+ years | |
| | Thermostats - DDC | Entire Building | 4 | EA | 6 | 6-10 years | |
| Ventilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|--------|---|-----------------|----------|---------|--------|--------------------------|---|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Exhaust Fans- Indoor - Greater than 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 7 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 4 | 2-5 years | Corroded, noisy |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 3 | 0-1 year | Missing hood, being repaired or replaced |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 6 | EA | 6 | 10+ years | |
| | Lab Exhaust Hood | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Roof Mounted Duct Work | Entire Building | 714 | LF | 6 | 10+ years | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 10+ years | With fire suppression |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 10+ years | At serving line, no fire supression |

| Category | : | Plumbing |
|----------|---|----------|
| | | |

| Catego | Category : Plumbing | | В | uilding | : Main | | |
|------------------------|---|-----------------|----------|---------|--------|--------------------------|-----------------------------|
| Group Piping | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| - iping | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 219,500 | SF | 6 | 10+ years | There are a few pipe clamps |
| | Domestic Piping-Cold Water Risers | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 219,500 | SF | 6 | 10+ years | There are a few pipeclamps |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Sanitary Piping | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 219,500 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 219,500 | SF | 6 | 10+ years | |
| Pool Sys | tems | | | | | | |
| , | Pool Drain Piping | Mechanical Room | 30 | LF | 6 | 10+ years | |
| | Pool Filtration System including Pump | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Pool Hot Water Heater - Gas Fired | Mechanical Room | 1 | EA | 6 | 10+ years | |
| | Pool Supply and Return Piping | Mechanical Room | 80 | LF | 6 | 10+ years | |
| Pumps | | | | | | | |
| | Pumps - Sump-Simplex | Basement | 1 | EA | 6 | 10+ years | Under elevator |



Building : Main Category : Room Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Administrative Suites/Offices AC Unit 117A Counselor Office 1 ΕA 5 2-5 years Ceiling - Lay-in 117A Counselor Office 767 SF 7 6-10 years Doors - Transom Window SF 6-10 years 117A Counselor Office 11 6 Doors - Wood Doors inclu hw ΕA 7 6-10 years 117A Counselor Office 1 3 FΑ Doors - Wood Doors inclu hw 117A Counselor Office 6 6-10 years Doors - Wood Doors inclu hw 117A Counselor Office 1 FΑ 5 6-10 years SF Floor - Tile 117A Counselor Office 700 6 6-10 years SF Floor - Tile 117A Counselor Office 67 6 10+ vears Lighting - Lay-in 117A Counselor Office 24 EΑ 7 6-10 years Power Distribution 26 7 117A Counselor Office EA 6-10 years Storage/ Closet 117A Counselor Office 76 SF 7 6-10 years Walls - Plaster/Drywall SF 7 6-10 years 117A Counselor Office 1.020 SF Ceiling - Lay-in 117B Counselor Office 182 7 6-10 years Doors - Transom Window SF 117B Counselor Office 6 6-10 years 11 Doors - Wood Doors inclu hw 117B Counselor Office FΑ 7 10+ years 1 SF Floor - Tile 117B Counselor Office 182 6 6-10 years 7 Lighting - Lay-in 117B Counselor Office 4 EA 6-10 years 6 7 Power Distribution 117B Counselor Office EΑ 6-10 years Walls - Plaster/Drywall 535 SF 7 6-10 years 117B Counselor Office SF Ceiling - Lay-in 117F 100 7 10+ years Doors - Side-lite 117F 8 SF 7 10+ vears Doors - Wood Doors inclu hw 117F FΑ 7 10+ vears 1 Floor - Carpet 117F SF 7 100 6-10 years Lighting - Lay-in 117F 2 ΕA 7 10+ years **Power Distribution** 117F 8 ΕA 7 10+ years SF 7 Walls - Plaster/Drywall 117F 430 10+ years Ceiling - Lay-in SF 7 117c 100 10+ years Doors - Side-lite SF 117c 8 7 10+ years ΕA Doors - Wood Doors inclu hw 117c 1 7 10+ vears Floor - Carpet 117c 100 SF 7 6-10 years Lighting - Lav-in 2 ΕA 7 10+ vears 117c Power Distribution 117c 8 EΑ 7 10+ years Walls - Plaster/Drywall 117c 430 SF 7 10+ years Ceiling - Lay-in 123A Conference Room 280 SF 7 10+ years 123A Conference Room SF 7 Doors - Transom Window 11 10+ years Doors - Wood Doors inclu hw 123A Conference Room 2 FΑ 7 10+ years Floor - Tile 123A Conference Room SF 7 280 10+ years Lighting - Lay-in 123A Conference Room 6 ΕA 7 6-10 years Power Distribution 6 ΕA 7 123A Conference Room 10+ years Walls - Plaster/Drywall 630 SF 7 123A Conference Room 10+ years AC Unit 123B Counselor Office 1 EΑ 7 6-10 years Ceiling - Lay-in 123B Counselor Office 558 SF 6 6-10 years Doors - Transom Window SF 123B Counselor Office 11 6 6-10 years



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|-----------------------------|---------------------------------|----------|---------|--------|-------------|---------------|
| outogo | | | | anang | . mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 123B Counselor Office | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 123B Counselor Office | 558 | SF | 4 | 1-2 years | |
| | Lighting - Lay-in | 123B Counselor Office | 15 | EA | 7 | 6-10 years | |
| | Power Distribution | 123B Counselor Office | 14 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 123B Counselor Office | 870 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 123C | 120 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 123C | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 123C | 1 | ĒA | 7 | 10+ years | |
| | Floor - Carpet | 123C | 120 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 123C | 2 | ĒA | 7 | 10+ years | |
| | Power Distribution | 123C | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 123C | 430 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 123D | 96 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 123D | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 123D | 1 | ĒA | 7 | 10+ years | |
| | Floor - Carpet | 123D | 96 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 123D | 2 | EA | 7 | 10+ years | |
| | Power Distribution | 123D | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 123D | 435 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 123E Reception Area | 120 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 123E Reception Area | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 123E Reception Area | 120 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 123E Reception Area | 4 | EA | 7 | 10+ years | |
| | Power Distribution | 123E Reception Area | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 123E Reception Area | 400 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 125 - Dean's Office | 210 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 125 - Dean's Office | 42 | SF | 6 | 10+ years | |
| | Doors - Store Front | 125 - Dean's Office | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 125 - Dean's Office | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 125 - Dean's Office | 210 | SF | 5 | 6-10 years | |
| | Lighting - Lay-in | 125 - Dean's Office | 12 | EA | 6 | 6-10 years | |
| | Power Distribution | 125 - Dean's Office | 11 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 125 - Dean's Office | 225 | SF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 125 - Dean's Office | 232 | SF | 4 | 1-2 years | |
| | AC Unit | 129 discipline office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 129 discipline office | 291 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 129 discipline office | 201 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 129 discipline office | 291 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 129 discipline office | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | 129 discipline office | 8 | EA | 7 | 10+ years | |
| | Storage/ Closet | 129 discipline office | 81 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 129 discipline office | 595 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 130 South Office in Main Office | 69 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 130 South Office in Main Office | 6 | SF | 4 | 0-1 year | Damaged tiles |
| | | | 0 | 01 | Ŧ | 0 i you | |



| Catego | ry : Room | | B | uilding | · Main | 3900 | JIN GIERWood AVENUE, Chicago, IL 60660 |
|--------|---------------------------------------|--|----------|----------|--------|------------------------|--|
| Catego | ry . Room | | | unung | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| oreup | Doors - Side-lite | 130 South Office in Main Office | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 130 South Office in Main Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 130 South Office in Main Office | 75 | SF | 7 | 10+ years | |
| | Power Distribution | 130 South Office in Main Office | 2 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 130 South Office in Main Office | 103 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 130 South Office in Main Office | 198 | SF | 5 | 10+ years | |
| | AC Unit | 131 South Office in Main Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 131 South Office in Main Office | 117 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 131 South Office in Main Office | 25 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 131 South Office in Main Office | 2 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 131 South Office in Main Office | 117 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 131 South Office in Main Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 131 South Office in Main Office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 131 South Office in Main Office | 377 | SF | 7 | 10+ years | |
| | AC Unit | 131B South Office in Main Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 131B South Office in Main Office | 196 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 131B South Office in Main Office | 50 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 131B South Office in Main Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 131B South Office in Main Office | 196 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 131B South Office in Main Office | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 131B South Office in Main Office | 5 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 131B South Office in Main Office | 461 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 131B South Office in Main Office | 6 | SF | 5 | 0-1 year | Cracks in plaster |
| | AC Unit | 132 Office in Main Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 132 Office in Main Office | 71 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 132 Office in Main Office | 9 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 132 Office in Main Office | 10 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 132 Office in Main Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 132 Office in Main Office | 80 | SF | 7 | 10+ years | |
| | Power Distribution | 132 Office in Main Office | 3 | EA SF | 7 | 10+ years | |
| | Walls - Metal Panel | 132 Office in Main Office | 80 | | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 132 Office in Main Office | 165 | SF | 7 | 10+ years | |
| | AC Unit | 133 Office in Main Office | 1 | EA SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 133 Office in Main Office | 63 12 | SF | 6 4 | 10+ years | Water demage |
| | Ceiling - Lay-in Doors - Side-lite | 133 Office in Main Office 133 Office in Main Office | 50 | SF | 4 7 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | | 50 | EA | | 10+ years | |
| | Floor - Tile/Sheet | 133 Office in Main Office 133 Office in Main Office | 75 | SF | 7 7 | 10+ years 10+ years | |
| | Power Distribution | 133 Office in Main Office | 3 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 133 Office in Main Office | 77 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 133 Office in Main Office | 161 | SF | 7 | 10+ years | |
| | AC Unit | 134 Office in Main Office | 101 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 134 Office in Main Office | 125 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 134 Office in Main Office | 20 | SF | 7 | 10+ years | |
| | | | 20 | 0 | ' | IUT years | |



| Catego | ry : Room | | B | uilding | · Main | 3300 | UN GIERWood AVENDE, Chicago, IL 60660 |
|--------|---|--|----------|----------|--------|------------------------|---------------------------------------|
| outego | | | | anang | · Main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 134 Office in Main Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 134 Office in Main Office | 125 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 134 Office in Main Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 134 Office in Main Office | 6 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 134 Office in Main Office | 120 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 134 Office in Main Office | 297 | SF | 6 | 10+ years | |
| | AC Unit | 135 Main Office | 3 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 135 Main Office | 940 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 135 Main Office | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 135 Main Office | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 135 Main Office | 2 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 135 Main Office | 940 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 135 Main Office | 26 | EA | 6 | 6-10 years | |
| | Power Distribution | 135 Main Office | 10 | EA | 7 | 10+ years | |
| | Storage/ Closet | 135 Main Office | 55 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 135 Main Office | 1,221 | SF | 6 | 10+ years | |
| | AC Unit | 135A North Office in Main Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 135A North Office in Main Office | 174 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 135A North Office in Main Office | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 135A North Office in Main Office | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 135A North Office in Main Office | 174 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 135A North Office in Main Office | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | 135A North Office in Main Office | 4 | EA | 6 | 10+ years | |
| | Storage/ Closet | 135A North Office in Main Office | 15 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 135A North Office in Main Office | 490 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 135A North Office in Main Office | 10 | SF | 5 | 0-1 year | Water damage |
| | Work SInk | 135A North Office in Main Office | 1 | EA | 7 | 10+ years | |
| | AC Unit | 137 Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 137 Principal's Office | 338 | SF | 6 | 10+ years | |
| | Doors - Transom Window Doors - Wood Doors inclu hw | 137 Principal's Office | 11 | SF EA | 7 | 10+ years | |
| | Doors - Wood Doors Inclu hw | 137 Principal's Office | 1 2 | EA | 7 6 | 10+ years | |
| | | 137 Principal's Office | 2 338 | SF | - | 10+ years | |
| | Floor - Tile/Sheet | 137 Principal's Office | | EA | 7 7 | 10+ years | |
| | Lighting - Lay-in Power Distribution | 137 Principal's Office | 12 8 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 137 Principal's Office 137 Principal's Office | 15 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 137 Principal's Office | 782 | SF | 6 | 10+ years 10+ years | |
| | AC Unit | 139 conference room | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 139 conference room | 465 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 139 conference room | 403 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 139 conference room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 139 conference room | 465 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 139 conference room | 403 | EA | 7 | 6-10 years | |
| | Power Distribution | 139 conference room | 8 | EA | 7 | 10+ years | |
| | | | 0 | LA | ' | IUT years | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Walls - Plaster/Drvwall 139 conference room 676 SF 5 10+ vears Ceiling - Plaster/Drvwall SF 6 190G Kitchen Office 155 10+ years Doors - Wood Doors inclu hw 190G Kitchen Office FΑ 6 10+ years 1 Floor - Tile SF 7 190G Kitchen Office 155 10+ years 7 Lighting - Pendent/Surface 190G Kitchen Office 3 EΑ 6-10 years **Power Distribution** 8 7 190G Kitchen Office EΑ 10+ years Storage/ Closet SF 5 10+ years 190G Kitchen Office 145 Walls - Plaster/Drvwall SF 190G Kitchen Office 583 5 10+ vears AC Unit 196 teacher's lounge 1 EΑ 7 6-10 years SF Ceiling - Lay-in 6 10+ vears 196 teacher's lounge 1.253 Ceiling - Lav-in SF 196 teacher's lounge 15 4 0-1 vear Water damage Doors - Wood Doors inclu hw 196 teacher's lounge 3 EΑ 6 10+ years Floor - Terrazzo 236 SF 6 10+ years 196 teacher's lounge SF 5 Floor - Tile 196 teacher's lounge 1,032 10+ years Lighting - Lay-in ΕA 6 6-10 years 196 teacher's lounge 30 Power Distribution 2 FΑ 6 196 teacher's lounge 10+ years SF 5 Storage/ Closet 196 teacher's lounge 210 6-10 years SF Walls - Plaster/Drywall 196 teacher's lounge 1.600 6 10+ years Ceiling - Lav-in SF 196A office in teacher's lounge 12 4 0-1 vear Water damage Ceiling - Plaster/Drywall SF 196A office in teacher's lounge 64 6 10+ years Doors - Store Front 196A office in teacher's lounge 1 ΕA 6 10+ years 6 10+ years Doors - Wood Doors inclu hw 196A office in teacher's lounge 1 EΑ SF 76 6 Floor - Terrazzo 196A office in teacher's lounge 10+ years 2 7 Lighting - Lay-in 196A office in teacher's lounge FΑ 6-10 years 4 ΕA 6 10+ years Power Distribution 196A office in teacher's lounge Walls - Plaster/Drywall SF 196A office in teacher's lounge 300 6 10+ vears 7 AC Unit 231 Health Office EA 6-10 years 1 Ceiling - Lay-in 231 Health Office 265 SF 6 10+ years Doors - Transom Window SF 7 231 Health Office 9 10+ years Doors - Wood Doors inclu hw 231 Health Office 1 ΕA 7 10+ years SF Floor - Wood 231 Health Office 265 7 10+ vears Lighting - Lav-in 231 Health Office 6 EΑ 7 6-10 years 10+ years Power Distribution 231 Health Office 4 FΑ 6 Walls - Plaster/Drvwall 231 Health Office 768 SF 5 10+ years Work SInk 7 231 Health Office 1 EΑ 10+ years SF 6 Ceiling - Lay-in 231A Exam Room in Health Office 132 10+ years Doors - Wood Doors inclu hw 231A Exam Room in Health Office 1 EΑ 7 10+ years Floor - Wood 132 SF 231A Exam Room in Health Office 5 10+ years Lighting - Lay-in 231A Exam Room in Health Office 2 EΑ 7 6-10 years 2 Power Distribution 231A Exam Room in Health Office ΕA 6 10+ vears SF Walls - Plaster/Drywall 231A Exam Room in Health Office 544 6 10+ years FΑ 7 6-10 vears AC Unit 231B Office in Health Office 1 Ceiling - Lay-in 231B Office in Health Office 129 SF 6 10+ years SF Ceiling - Lay-in 231B Office in Health Office 3 4 0-1 year Water damage



| Catego | ry : Room | | B | uilding | • Main | 0000 | |
|--------|-----------------------------|------------------------------|------------|----------|--------|-------------|--------------|
| oulogo | | | | anang | · man | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| 0.000 | Doors - Wood Doors inclu hw | 231B Office in Health Office | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 231B Office in Health Office | 132 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 231B Office in Health Office | 2 | ĒA | 7 | 6-10 years | |
| | Power Distribution | 231B Office in Health Office | 2 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 231B Office in Health Office | 484 | SF | 7 | 10+ years | |
| | AC Unit | 258 Office | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 258 Office | 900 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 258 Office | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 258 Office | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 258 Office | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 258 Office | 15 | EA | 7 | 6-10 years | |
| | Power Distribution | 258 Office | 10 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 258 Office | 968 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 258A Office | 100 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 258A Office | 100 | EA | 7 | 10+ years | |
| | Floor - Wood | 258A Office | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 258A Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 258A Office | 4 | EA | 7 | 10+ years | |
| | | 258A Office | 4 968 | SF | | | |
| | Walls - Plaster/Drywall | 258A Office | 968 120 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | | | | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 258B Office | 1 | EA SF | 7 | 10+ years | |
| | Floor - Wood | 258B Office | 120 | | 6 | 10+ years | |
| | Lighting - Lay-in | 258B Office | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | 258B Office | 8 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 258B Office | 378 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor A/V Room | 72 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor A/V Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor A/V Room | 72 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor A/V Room | 9 | EA | 7 | 10+ years | |
| | Power Distribution | 2nd Floor A/V Room | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor A/V Room | 236 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor Control Room | 72 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Control Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor Control Room | 72 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor Control Room | 1 | EA | 7 | 10+ years | |
| | Power Distribution | 2nd Floor Control Room | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Control Room | 236 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 325A - Practice Room | 84 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 325A - Practice Room | 1 | SF | 4 | 0-1 year | Damaged tile |
| | Doors - Wood Doors inclu hw | 325A - Practice Room | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 325A - Practice Room | 85 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 325A - Practice Room | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 325A - Practice Room | 135 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 325B - Practice Room | 85 | SF | 6 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|-----------------------------|----------------------------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 325B - Practice Room | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 325B - Practice Room | 85 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 325B - Practice Room | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 325B - Practice Room | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 325B - Practice Room | 135 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 325C - Practice Room | 85 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 325C - Practice Room | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 325C - Practice Room | 85 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 325C - Practice Room | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | 325C - Practice Room | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 325C - Practice Room | 135 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 325D - Practice Room | 85 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 325D - Practice Room | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 325D - Practice Room | 85 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 325D - Practice Room | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | 325D - Practice Room | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 325D - Practice Room | 135 | SF | 6 | 10+ years | |
| | AC Unit | 369 - Naval Academy Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 369 - Naval Academy Office | 725 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 369 - Naval Academy Office | 1 | EA | 7 | 6-10 years | |
| | Floor - Wood | 369 - Naval Academy Office | 725 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 369 - Naval Academy Office | 21 | EA | 6 | 6-10 years | |
| | Power Distribution | 369 - Naval Academy Office | 16 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 369 - Naval Academy Office | 897 | SF | 6 | 10+ years | |
| | AC Unit | 371 Students Services | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 371 Students Services | 740 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 371 Students Services | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 371 Students Services | 740 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 371 Students Services | 21 | EA | 7 | 6-10 years | |
| | Power Distribution | 371 Students Services | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 371 Students Services | 1,420 | SF | 7 | 10+ years | |
| | AC Unit | 373 - Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 373 - Principal's Office | 225 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 373 - Principal's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 373 - Principal's Office | 225 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 373 - Principal's Office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | 373 - Principal's Office | 4 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 373 - Principal's Office | 711 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 375 - Special Education | 225 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 375 - Special Education | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 375 - Special Education | 225 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 375 - Special Education | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | 375 - Special Education | 14 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 375 - Special Education | 711 | SF | 6 | 10+ years | |



| Catego | ry : Room | | B | uilding | · Main | 000 | Th Glenwood AVENDE, Chicago, IE 00000 |
|--------|-----------------------------|-------------------------|----------|---------|--------|-------------|---------------------------------------|
| Galego | | | | anang | · Main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 377A - Teacher's Lounge | 650 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 377A - Teacher's Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 377A - Teacher's Lounge | 650 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 377A - Teacher's Lounge | 14 | EA | 7 | 6-10 years | |
| | Power Distribution | 377A - Teacher's Lounge | 18 | EA | 6 | 10+ years | |
| | Storage/ Closet | 377A - Teacher's Lounge | 65 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 377A - Teacher's Lounge | 467 | SF | 7 | 10+ years | |
| | Work SInk | 377A - Teacher's Lounge | 1 | EA | 7 | 10+ years | |
| | AC Unit | 377B - Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 377B - Office | 180 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 377B - Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 377B - Office | 180 | SF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | 377B - Office | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 377B - Office | 20 | EA | 6 | 10+ years | |
| | Storage/ Closet | 377B - Office | 8 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 377B - Office | 489 | SF | 6 | 10+ years | |
| | AC Unit | 379 Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 379 Office | 576 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 379 Office | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 379 Office | 576 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 379 Office | 15 | EA | 7 | 6-10 years | |
| | Power Distribution | 379 Office | 17 | EA | 6 | 10+ years | |
| | Storage/ Closet | 379 Office | 22 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 379 Office | 1,217 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 379A - Office | 176 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 379A - Office | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 379A - Office | 176 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 379A - Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 379A - Office | 6 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 379A - Office | 531 | SF | 6 | 10+ years | |
| | AC Unit | 379B - Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 379B - Office | 177 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 379B - Office | 3 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 379B - Office | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 379B - Office | 180 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 379B - Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 379B - Office | 6 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 379B - Office | 489 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Gym office | 237 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Gym office | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Gym office | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | Gym office | 237 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Gym office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | Gym office | 8 | EA | 7 | 10+ years | |



| atego | ry : Room | | B | uilding | : Main | | |
|----------|---------------------------------|--------------------------|----------|---------|--------|-------------|---|
| alego | | | | anang | . mani | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | Gym office | 1,000 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Gym office | 30 | SF | 4 | 0-1 year | Complete failure of plaster due to excessive water damage |
| | Ceiling - Lay-in | Kitchenette | 90 | SF | 7 | 10+ years | |
| | Floor - Tile | Kitchenette | 90 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Kitchenette | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Kitchenette | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Kitchenette | 300 | SF | 7 | 10+ years | |
| | Work SInk | Kitchenette | 1 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Pool Office | 65 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Pool Office | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | Pool Office | 65 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Pool Office | 1 | EA | 5 | 6-10 years | No switch |
| | Power Distribution | Pool Office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Pool Office | 485 | SF | 6 | 10+ years | |
| uditoriu | m & Theater | | | | | | |
| | Ceiling - Exposed | 180 Harold Ramis Theatre | 1,311 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 180 Harold Ramis Theatre | 12 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 180 Harold Ramis Theatre | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 180 Harold Ramis Theatre | 1,311 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 180 Harold Ramis Theatre | 26 | EA | 6 | 6-10 years | |
| | Stage | 180 Harold Ramis Theatre | 334 | SF | 6 | 10+ years | |
| | Stage Curtain | 180 Harold Ramis Theatre | 2 | EA | 5 | 6-10 years | |
| | Stage Lighting System | 180 Harold Ramis Theatre | 1 | EA | 5 | 6-10 years | |
| | Stage-Stairs - Wood | 180 Harold Ramis Theatre | 18 | LF | 6 | 10+ years | |
| | Storage/ Closet | 180 Harold Ramis Theatre | 207 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 180 Harold Ramis Theatre | 2,802 | SF | 6 | 10+ years | |
| | Balcony Seating | 1st Floor | 218 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 13,161 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 22 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 3,630 | SF | 6 | 6-10 years | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 7,631 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 1,900 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 51 | EA | 6 | 6-10 years | There was an issue with the Auditorium lights at the assessmentions |
| | Lighting - Pendent/Surface | 1st Floor | 79 | EA | 6 | 6-10 years | time |
| | Lighting - Wall Mounted | 1st Floor | 36 | EA | 7 | 6-10 years | |
| | Main Floor Seating | 1st Floor | 557 | EA | 7 | 10+ years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 1,963 | SF | 6 | 10+ years | |
| | Stage Curtain | 1st Floor | 9 | EA | 5 | 6-10 years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 6-10 years | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Stage-Stairs - Wood 1st Floor 70 LF 6 10+ vears Walls - Plaster/Drvwall 10.572 SF 6 1st Floor 10+ years Gymnasia **Bleacher Seating** Small Gym 120 ΕA 7 10+ years Ceiling - Plaster/Drywall SF 7 Small Gvm 8.535 10+ vears Doors - Wood Doors inclu hw Small Gvm 5 EΑ 7 10+ years SF Floor - Wood Small Gym 8,535 7 10+ years Lighting - Pendent/Surface Small Gvm EΑ 7 10+ vears 40 Scoreboards Small Gym 1 EA 7 10+ years Storage/ Closet Small Gym SF 7 169 10+ years Walls - Plaster/Drywall Small Gym 2,200 SF 7 10+ years Kitchen SF Ceiling - Lay-in 189 - Servery (on plan) 2,376 6 10+ years Ceiling - Lay-in 189 - Servery (on plan) 24 SF 4 0-1 year Missing tiles Ceiling - Plaster/Drywall 189 - Servery (on plan) SF 5 86 10+ years 189 - Servery (on plan) ΕA 6 10+ years Doors - Wood Doors inclu hw 13 SF Floor - Tile Quarry 189 - Servery (on plan) 6 2.486 10+ years Lighting - Lay-in 189 - Servery (on plan) 56 FΑ 6 6-10 years SF Walls - Concrete Block 189 - Servery (on plan) 430 7 10+ years SF Walls - Masonry 189 - Servery (on plan) 900 10+ years 6 SF Walls - Plaster/Drywall 189 - Servery (on plan) 620 6 10+ years 189 - Servery (on plan) SF Walls - Tile Ceramic/ Porcelain 230 6 10+ years Ceiling - Lay-in 189A - Kitchen (on plan) 1,240 SF 6 10+ years Ceiling - Plaster/Drywall SF 6 189A - Kitchen (on plan) 585 10+ vears Doors - Steel Doors incl hw 189A - Kitchen (on plan) 2 EΑ 6 10+ years 189A - Kitchen (on plan) SF Doors - Transom Window 6 10+ years 11 Doors - Wood Doors inclu hw 189A - Kitchen (on plan) 2 FΑ 6 10+ vears SF Floor - Terrazzo 189A - Kitchen (on plan) 500 6 10+ years SF 6 Floor - Tile Quarry 189A - Kitchen (on plan) 1,325 10+ years Lighting - Pendent/Surface 189A - Kitchen (on plan) 36 EΑ 6 6-10 years Storage/ Closet SF 5 189A - Kitchen (on plan) 200 10+ years Walls - Concrete Block 189A - Kitchen (on plan) 430 SF 6 10+ years Walls - Masonrv 189A - Kitchen (on plan) 1.740 SF 6 10+ vears SF Walls - Plaster/Drvwall 208 6 10+ years 189A - Kitchen (on plan) 20 SF Walls - Plaster/Drvwall 189A - Kitchen (on plan) 4 0-1 vear Water damage Ceiling - Splined 190H - Dishwashing 370 SF 6 10+ years SF Ceiling - Splined 190H - Dishwashing 30 4 0-1 year Water damage SF 5 Floor - Terrazzo 190H - Dishwashing 400 10+ years 7 Lighting - Pendent/Surface 190H - Dishwashing 10 EΑ 6-10 years Walls - Masonry 190H - Dishwashing 500 SF 6 10+ years SF Walls - Masonry 190H - Dishwashing 200 4 0-1 year Cracked tiles Walls - Plaster/Drywall 190H - Dishwashing 175 SF 6 10+ years



| Cotonia S | | | | | . Ma':- | 0000 | ON Glenwood AVENUE, Chicago, IL 60660 |
|-----------|---------------------------------|-----------------------|----------|----------|---------|-------------|---------------------------------------|
| Catego | ry : Room | | В | uilding | : Main | _ | |
| 0 | No. The | L C | o | | D. 1 | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 190J - Canteen | 356 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 190J - Canteen | 6 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 190J - Canteen | 4 | EA | 6 | 10+ years | |
| | Floor - Tile Quarry | 190J - Canteen | 360 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 190J - Canteen | 9 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 190J - Canteen | 900 | SF | 5 | 10+ years | |
| Library | | | | | | | |
| | AC Unit | 225 Library | 3 | EA | 7 | 6-10 years | |
| | Casework | 225 Library | 676 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 225 Library | 3,922 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 225 Library | 2 | SF | 4 | 0-1 year | Water damage |
| | Doors - Transom Window | 225 Library | 24 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 225 Library | 6 | ĒA | 7 | 10+ years | |
| | Floor - Tile | 225 Library | 3,922 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 225 Library | 109 | ĒA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 225 Library | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 225 Library | 75 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 225 Library | 4,546 | SF | 6 | 10+ years | |
| | Walls Traster/Drywall | 220 Elorary | 4,040 | 01 | 0 | Tor years | |
| Locker/S | hower Room | | | | | | |
| | Accessories | 1st Floor Mens Pool | 694 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1st Floor Mens Pool | 36 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor Mens Pool | 964 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor Mens Pool | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Mens Pool | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Mens Pool | 694 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Mens Pool | 5 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Mens Pool | 5 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor Mens Pool | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Mens Pool | 17 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor Mens Pool | 1 | EA | 7 | - | |
| | Showers | 1st Floor Mens Pool | 9 | EA | 7 | 10+ years | |
| | | | | | | 10+ years | |
| | Student Lockers - One Tier | 1st Floor Mens Pool | 18 | EA | 7 | 10+ years | |
| | Student Lockers - Two Tier | 1st Floor Mens Pool | 48 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor Mens Pool | 1 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor Mens Pool | 1,460 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Mens Pool | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Womens Pool | 967 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1st Floor Womens Pool | 132 | LF | 5 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor Womens Pool | 400 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor Womens Pool | 967 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Womens Pool | 1 | EA SF | 7 | 10+ years | |
| | | 1st Floor Womens Pool | 967 | | 6 | | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor Drain 1st Floor Womens Pool 3 ΕA 10+ vears 7 1st Floor Womens Pool 10 ΕA 7 6-10 vears Hand Drver Lavatory 1st Floor Womens Pool 2 FΑ 7 10+ years Lighting - Pendent/Surface 1st Floor Womens Pool 17 7 EΑ 10+ years 2 Partitions 1st Floor Womens Pool EΑ 7 10+ years 3 7 Showers 1st Floor Womens Pool EΑ 10+ years Student Lockers - One Tier 1st Floor Womens Pool 26 ΕA 7 10+ years Student Lockers - Two Tier 1st Floor Womens Pool 48 EΑ 7 10+ years 1st Floor Womens Pool Walls - Tile Ceramic/ Porcelain 2.200 SF 7 10+ years Water Closet 1st Floor Womens Pool 2 FΑ 7 10+ vears Accessories Unisex pool 84 SF 7 6-10 years Benches, ped mounted Unisex pool 4 LF 7 10+ years Ceiling - Plaster/Drywall Unisex pool 84 SF 7 10+ years ΕA 7 Doors - Wood Doors inclu hw Unisex pool 1 10+ years Floor - Tile Ceramic/ Porcelain Unisex pool SF 7 84 10+ years Floor Drain Unisex pool FΑ 1 7 10+ years Hand Drver Unisex pool 1 EΑ 7 6-10 years Lavatory Unisex pool 1 EΑ 7 10+ years Lighting - Pendent/Surface 2 Unisex pool EΑ 7 10+ vears Showers Unisex pool 1 EΑ 7 10+ years Student Lockers - One Tier Unisex pool 2 ΕA 7 10+ years SF Walls - Tile Ceramic/ Porcelain Unisex pool 342 7 10+ years 7 Water Closet Unisex pool 1 EΑ 10+ years Lunch & Multipurpose Room AC Unit 115 Social Center 2 ΕA 7 6-10 years SF 7 Ceiling - Lay-in 115 Social Center 1,344 10+ years Doors - Transom Window SF 7 115 Social Center 22 10+ years Doors - Wood Doors inclu hw FΑ 7 115 Social Center 5 10+ years SF Floor - Tile 115 Social Center 1.344 7 10+ years Lighting - Lay-in 115 Social Center 24 EΑ 7 10+ years Storage/ Closet SF 115 Social Center 8 7 10+ vears Walls - Plaster/Drywall SF 115 Social Center 1,410 7 10+ years Ceiling - Lay-in 190 Cafeteria 11.497 SF 6 10+ years Ceiling - Lay-in 190 Cafeteria SF 4 0-1 year 3 Water damage Doors - Wood Doors inclu hw 6 190 Cafeteria 10 EA 10+ years SF Floor - Terrazzo 190 Cafeteria 200 6 10+ years Floor - Tile Quarry 11.300 SF 6 10+ years 190 Cafeteria Lighting - Lav-in 190 Cafeteria 220 FΑ 6 6-10 years Storage/ Closet SF 5 190 Cafeteria 120 10+ years Walls - Plaster/Drywall 5,000 SF 6 190 Cafeteria 10+ years _MDF_IDF Doors - Wood Doors inclu hw 261B 1 EΑ 7 10+ years



| Catego | ry : Room | | В | uilding | : Main | | |
|----------|--|-----------------------------------|------------|---------|--------|------------------------|----------|
| J | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Finishes | 261B | 105 | SF | 7 | 10+ years | |
| | Window AC Unit | 261B | 1 | EA | 7 | 10+ years | |
| lochoni | cal/ Service Rooms | | | | | | |
| lechann | Storage Room | 117E | 125 | SF | 7 | 10+ years | |
| | Air Intake Plenums | 117E 118A - South | 135 239 | SF | 7 | 10+ years 10+ years | |
| | Storage Room | | 239 176 | SF | 5 | | |
| | • | 131A Vault in Main Office | 38 | SF | | 10+ years | |
| | Janitor's Closet | 1st Floor | 30 14 | SF | 5 | 10+ years | |
| | Janitor's Closet | 1st Floor | | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 1,150 | | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 1,150 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 250 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 113 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Flr Pool Pump Room | 385 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 220 Storage | 200 | SF | 7 | 10+ years | |
| | Storage Room | 261A Second floor SW storage room | 74 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Flr SE Electrical Room | 96 | SF | 5 | 10+ years | |
| | Janitor's Closet | Janitor Closet | 15 | SF | 5 | 10+ years | |
| | Janitor's Closet | Janitor closet #2 West | 32 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | Pool Mechanical Room and Laundry | 465 | SF | 7 | 10+ years | |
| 2001 & N | atatorium | | | | | | |
| | Ceiling - Lay-in | 118 | 1,647 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 118 | 1,513 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 118 | 4 | EA | 7 | 6-10 years | |
| | Lighting - Metal Halide/ High Pressure | 118 | 12 | EA | 7 | 6-10 years | |
| | Sodium | 110 | 12 | EA | 1 | 0-10 years | |
| | | 110 | 1 5 1 0 | oг | 7 | 10, 10000 | |
| | Pool Basin | 118 | 1,513 | SF | 7 | 10+ years | |
| | Pool Deck | 118 | 1,647 | SF | 7 | 10+ years | |
| | Pool Deck Drains | 118 | 6 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 118 | 1,506 | SF | 7 | 10+ years | |
| | Walls - Vinyl Coated Gypsum Panel | 118 | 1,506 | SF | 7 | 10+ years | |
| rep Roo | om | | | | | | |
| | Casework | 350A - Prep Room | 25 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 350A - Prep Room | 292 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 350A - Prep Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 350A - Prep Room | 292 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 350A - Prep Room | 3 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | 350A - Prep Room | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 350A - Prep Room | 529 | SF | 7 | 10+ years | |
| | Work Sink | 350A - Prep Room | 1 | EA | 7 | 10+ years | |
| | Casework | 352A Prep Room | 27 | LF | 7 | 10+ years | |
| | | | 21 | L1 | ' | ior years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|----------|--|-------------------------------------|----------|----------|--------|-------------|--------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 352A Prep Room | 131 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 352A Prep Room | 1 | EA | 6 | 10+ years | Vault type door - locked |
| | Floor - Tile | 352A Prep Room | 131 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 352A Prep Room | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 352A Prep Room | 459 | SF | 7 | 10+ years | |
| | Work Sink | 352A Prep Room | 1 | EA | 7 | 10+ years | |
| | Casework | 356A Prep Room | 36 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 356A Prep Room | 216 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 356A Prep Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 356A Prep Room | 216 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 356A Prep Room | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 356A Prep Room | 657 | SF | 7 | 10+ years | |
| | Work Sink | 356A Prep Room | 1 | EA | 7 | 10+ years | |
| | Casework | 358A | 36 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 358A | 216 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 358A | 210 | EA | 7 | 10+ years | |
| | Floor - Tile | 358A | 216 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 358A | 4 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 358A | 657 | SF | | 10+ years | |
| | Work Sink | 358A | 1 | EA | 6 7 | | |
| | | | 50 | | 7 | 10+ years | |
| | | 364A Prep Room | | SF | | 10+ years | |
| | Ceiling - Plaster/Drywall | 364A Prep Room | 228 | | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 364A Prep Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 364A Prep Room | 228 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 364A Prep Room | 3 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 364A Prep Room | 639 | SF | 7 | 10+ years | |
| | Work Sink | 364A Prep Room | 1 | EA | 7 | 10+ years | |
| | Casework | 366B | 50 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 366B | 144 | SF | 7 | 10+ years | |
| | Floor - Tile | 366B | 144 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 366B | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 366B | 534 | SF | 7 | 10+ years | |
| | Work Sink | 366B | 1 | EA | 7 | 10+ years | |
| Restroor | n | | | | | | |
| | Accessories | 125A Unisex Toilet in Dean's Office | 69 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 125A Unisex Toilet in Dean's Office | 69 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 125A Unisex Toilet in Dean's Office | 1 | EA | 5 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | 125A Unisex Toilet in Dean's Office | 69 | SF | 6 | 10+ years | |
| | Hand Dryer | 125A Unisex Toilet in Dean's Office | 1 | EA | 7 | 10+ years | |
| | Lavatory | 125A Unisex Toilet in Dean's Office | 1 | EA | 6 | 10+ years | |
| | Lavalory Lighting - Pendent/Surface | 125A Unisex Toilet in Dean's Office | 1 | EA | | | |
| | 5 5 | | 1 | EA EA | 6 | 6-10 years | |
| | Partitions | 125A Unisex Toilet in Dean's Office | 1 | | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 125A Unisex Toilet in Dean's Office | 316 | SF | 5 | 6-10 years | |
| | | | | | | | |



| Catego | ry : Room | | В | uilding | • Main | | The Cleriwood AVENOL, Chicago, in 00000 |
|--------|---------------------------------|--------------------------------------|----------|------------|--------|-------------|---|
| oulego | | | 5 | unung | · mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | 125A Unisex Toilet in Dean's Office | 1 | EA | 6 | 6-10 years | |
| | Accessories | 137A Principal's Toilet | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 137A Principal's Toilet | 45 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 137A Principal's Toilet | .0 | ĒA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 137A Principal's Toilet | 15 | SF | 6 | 10+ years | |
| | Floor - Wood | 137A Principal's Toilet | 30 | SF | 7 | 10+ years | |
| | Lavatory | 137A Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 137A Principal's Toilet | 1 | EA | 7 | 6-10 years | |
| | Partitions | 137A Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 137A Principal's Toilet | 304 | SF | 6 | 10+ years | |
| | Water Closet | 137A Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Accessories | 190E Womens Lockers off Kitchen | 282 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 190E Womens Lockers off Kitchen | 282 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 190E Womens Lockers off Kitchen | 3 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | | 282 | SF | 6 | 10+ years | |
| | | 190E Womens Lockers off Kitchen | 202 | EA | 7 | , | |
| | Lavatory | 190E Womens Lockers off Kitchen | | EA | | 10+ years | |
| | Lighting - Pendent/Surface | 190E Womens Lockers off Kitchen | 3 | | 6 | 6-10 years | |
| | Lighting - Wall Mounted | 190E Womens Lockers off Kitchen | 1 | EA | 5 | 6-10 years | |
| | Student Lockers - One Tier | 190E Womens Lockers off Kitchen | 12 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 190E Womens Lockers off Kitchen | 1,301 | SF | 5 | 10+ years | |
| | Water Closet | 190E Womens Lockers off Kitchen | 1 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor Boys | 558 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Boys | 558 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor Boys | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boys | 558 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Boys | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor Boys | 4 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Boys | 8 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Boys | 5 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor Boys | 9 | EA | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor Boys | 1,240 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor Boys | 413 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Boys | 5 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor South - Single User Toilet | 42 | SF | 7 | 6-10 years | |
| | | Room in Girls Toilet Room | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor South - Single User Toilet | 42 | SF | 7 | 10+ years | |
| | o | Room in Girls Toilet Room | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor South - Single User Toilet | 1 | EA | 6 | 10+ years | |
| | | Room in Girls Toilet Room | | | | , - | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor South - Single User Toilet | 42 | SF | 6 | 10+ years | |
| | | Room in Girls Toilet Room | · | 2. | ÷ | , jouro | |
| | Lavatory | 1st Floor South - Single User Toilet | 1 | EA | 7 | 10+ years | |
| | ······ | | | _ <i>.</i> | | , | |



| Catego | ory : Room | | В | uilding | : Main | | |
|--------|---------------------------------|--------------------------------------|----------|---------|--------|-------------|----------|
| | . , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | , | Room in Girls Toilet Room | | | | • | |
| | Lighting - Pendent/Surface | 1st Floor South - Single User Toilet | 1 | EA | 7 | 6-10 years | |
| | | Room in Girls Toilet Room | | | | - | |
| | Walls - Concrete Block | 1st Floor South - Single User Toilet | 151 | SF | 6 | 10+ years | |
| | | Room in Girls Toilet Room | | | | | |
| | Walls - Structural Glazed Tile | 1st Floor South - Single User Toilet | 151 | SF | 7 | 10+ years | |
| | | Room in Girls Toilet Room | | | | | |
| | Water Closet | 1st Floor South - Single User Toilet | 1 | EA | 6 | 10+ years | |
| | | Room in Girls Toilet Room | | ~- | _ | | |
| | Accessories | 1st Floor South at Auditorium | 450 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor South at Auditorium | 450 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor South at Auditorium | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor South at Auditorium | 450 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor South at Auditorium | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor South at Auditorium | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor South at Auditorium | 3 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor South at Auditorium | 8 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor South at Auditorium | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor South at Auditorium | 1,260 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor South at Auditorium | 1,260 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor South at Auditorium | 6 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor West | 220 | SF | 5 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor West | 220 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor West | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor West | 220 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor West | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor West | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor West | 3 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor West | 5 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor West | 4 | EA | 7 | 10+ years | |
| | Showers | 1st Floor West | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor West | 139 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor West | 418 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor West | 4 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor Boys East | 477 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boys East | 477 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor Boys East | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Boys East | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boys East | 477 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor Boys East | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Boys East | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor Boys East | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Boys East | 9 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor Boys East | 4 | EA | 7 | 10+ years | |



| Catarra | | | | | . Main | 530 | on Clerwood Avende, Chicago, ie 00000 |
|---------|---------------------------------|-------------------------------------|----------|--------------|--------|-------------|---------------------------------------|
| Catego | ry : Room | | В | uilding | : Main | Deservation | |
| 0 | Hans Town | Leastler | 0 | | Daula | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Urinals | 2nd Floor Boys East | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor Boys East | 351 | SF | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor Boys East | 351 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor Boys East | 4 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor Boys West | 371 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boys West | 371 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor Boys West | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Boys West | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boys West | 371 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor Boys West | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Boys West | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor Boys West | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Boys West | 5 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Boys West | 3 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor Boys West | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor Boys West | 385 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor Boys West | 335 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor Boys West | 3 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor East | 261 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor East | 261 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor East | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor East | 1 | EA | 7 | 10+ years | |
| | | | - | SF | | | |
| | Floor - Tile Hand Dryer | 2nd Floor East 2nd Floor East | 261 | EA | 6 | 10+ years | |
| | 5 | | 1 | | 7 | 6-10 years | |
| | Lavatory | 2nd Floor East | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor East | 5 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor East | 5 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor East | 606 | SF | 6 | 10+ years | |
| | Walls - Masonry | 2nd Floor East | 202 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor East | 5 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor East - Single User Toilet | 42 | SF | 7 | 6-10 years | |
| | | Room in Girls Toilet Room | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor East - Single User Toilet | 42 | SF | 7 | 10+ years | |
| | | Room in Girls Toilet Room | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor East - Single User Toilet | 1 | EA | 6 | 10+ years | |
| | | Room in Girls Toilet Room | | | | | |
| | Floor - Concrete Epoxy/ Painted | 2nd Floor East - Single User Toilet | 42 | SF | 5 | 10+ years | |
| | | Room in Girls Toilet Room | | | | , | |
| | Lavatory | 2nd Floor East - Single User Toilet | 1 | EA | 7 | 10+ years | |
| | ,, , | Room in Girls Toilet Room | | | | - , | |
| | Lighting - Pendent/Surface | 2nd Floor East - Single User Toilet | 1 | EA | 7 | 6-10 years | |
| | gg + 61146112 6411466 | Room in Girls Toilet Room | • | _ / ` | | 5 10 90010 | |
| | Partitions | 2nd Floor East - Single User Toilet | 1 | EA | 7 | 10+ years | |
| | | Room in Girls Toilet Room | | L/\ | ' | ioi youio | |
| | | | | | | | |



| Catago | | | B | uilding | · Main | 5900 | The Glerwood AVENDE, Chicago, ie 60000 |
|--------|--------------------------------|--|----------|---------|--------|-------------|--|
| Catego | ry : Room | | В | unaing | : Main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Group | Walls - Concrete Block | 2nd Floor East - Single User Toilet | 139 | SF | 6 | 10+ years | Comments |
| | | Room in Girls Toilet Room | | ~- | | | |
| | Walls - Structural Glazed Tile | 2nd Floor East - Single User Toilet Room in Girls Toilet Room | 139 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor East - Single User Toilet Room in Girls Toilet Room | 1 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor East Single User Unisex in Teachers Work Room | 56 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor East Single User Unisex in Teachers Work Room | 56 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor East Single User Unisex in Teachers Work Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor East Single User Unisex in Teachers Work Room | 56 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor East Single User Unisex in Teachers Work Room | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor East Single User Unisex in Teachers Work Room | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor East Single User Unisex in Teachers Work Room | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor East Single User Unisex in Teachers Work Room | 420 | SF | 5 | 6-10 years | |
| | Water Closet | 2nd Floor East Single User Unisex in Teachers Work Room | 1 | EA | 6 | 6-10 years | |
| | Accessories | 2nd Floor East Womens in Teachers Work Room | 190 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor East Womens in Teachers Work Room | 414 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor East Womens in Teachers Work Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor East Womens in Teachers Work Room | 190 | SF | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor East Womens in Teachers Work Room | 224 | SF | 6 | 6-10 years | |
| | Floor Drain | 2nd Floor East Womens in Teachers Work Room | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor East Womens in Teachers Work Room | 2 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor East Womens in Teachers Work Room | 1 | EA | 6 | 6-10 years | |
| | Partitions | 2nd Floor East Womens in Teachers Work Room | 2 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor East Womens in Teachers Work Room | 288 | SF | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|--|----------|---------|--------|-------------|----------|
| 0 | ., | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Masonry | 2nd Floor East Womens in Teachers Work Room | 288 | SF | 5 | 6-10 years | |
| | Water Closet | 2nd Floor East Womens in Teachers Work Room | 2 | EA | 6 | 6-10 years | |
| | Accessories | 2nd Floor West | 349 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 349 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor West | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor West | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor West | 349 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor West | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor West | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor West | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor West | 6 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor West | 7 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor West | 495 | SF | 6 | 10+ years | |
| | Walls - Masonry | 2nd Floor West | 165 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor West | 7 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor West - Multi User Toilet | 121 | SF | 7 | 6-10 years | |
| | | Room in Boys Toilet Room | | | | - | |
| | Ceiling - Plaster/Drywall | 2nd Floor West - Multi User Toilet | 121 | SF | 7 | 10+ years | |
| | 0 | Room in Boys Toilet Room | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor West - Multi User Toilet | 1 | EA | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | , | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor West - Multi User Toilet | 121 | SF | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | • | |
| | Lavatory | 2nd Floor West - Multi User Toilet | 1 | EA | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor West - Multi User Toilet | 2 | EA | 7 | 6-10 years | |
| | | Room in Boys Toilet Room | | | | - | |
| | Partitions | 2nd Floor West - Multi User Toilet | 2 | EA | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | | |
| | Walls - Masonry | 2nd Floor West - Multi User Toilet | 265 | SF | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | - | |
| | Walls - Plaster/Drywall | 2nd Floor West - Multi User Toilet | 265 | SF | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | - | |
| | Water Closet | 2nd Floor West - Multi User Toilet | 2 | EA | 7 | 10+ years | |
| | | Room in Boys Toilet Room | | | | - | |
| | Accessories | 2nd Floor West - Single User Toilet | 50 | SF | 7 | 6-10 years | |
| | | Room in Girls Toilet Room | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor West - Single User Toilet | 50 | SF | 6 | 10+ years | |
| | 2 | Room in Girls Toilet Room | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor West - Single User Toilet | 1 | EA | 6 | 10+ years | |
| | | Room in Girls Toilet Room | | | | | |
| | Floor - Concrete Epoxy/ Painted | 2nd Floor West - Single User Toilet | 50 | SF | 5 | 10+ years | |
| | | Ŭ | | | | 2 | |



Building : Main Category : Room Recommend **Replacement** Comments Group Item - Type Location Quantity UOM Rank Room in Girls Toilet Room ΕA 2nd Floor West - Single User Toilet 1 6 Lavatorv 10+ years Room in Girls Toilet Room ΕA Lighting - Pendent/Surface 2nd Floor West - Single User Toilet 1 7 6-10 years Room in Girls Toilet Room Partitions 2nd Floor West - Single User Toilet 1 EΑ 7 10+ years Room in Girls Toilet Room Walls - Concrete Block 2nd Floor West - Single User Toilet 124 SF 6 10+ years Room in Girls Toilet Room SF Walls - Structural Glazed Tile 2nd Floor West - Single User Toilet 124 6 10+ years Room in Girls Toilet Room Water Closet 2nd Floor West - Single User Toilet 1 EΑ 7 10+ years Room in Girls Toilet Room Accessories **3rd Floor Boys East** 245 SF 7 6-10 years Ceiling - Plaster/Drywall **3rd Floor Boys East** SF 7 245 10+ years Doors - Side-lite **3rd Floor Boys East** SF 7 14 10+ years ΕA 7 Doors - Wood Doors inclu hw 3rd Floor Boys East 1 10+ years Floor - Tile Ceramic/ Porcelain 3rd Floor Boys East 245 SF 7 10+ years Floor Drain 3rd Floor Boys East ΕA 7 10+ vears 1 Lavatory **3rd Floor Boys East** 3 EΑ 7 10+ years Lighting - Pendent/Surface **3rd Floor Boys East** 5 ΕA 7 6-10 years 3 7 Partitions **3rd Floor Boys East** ΕA 10+ years 7 ΕA 7 Urinals **3rd Floor Boys East** 10+ years SF 7 Walls - Concrete Block **3rd Floor Boys East** 392 10+ years 3rd Floor Boys East 392 SF 6 Walls - Masonry 10+ years Water Closet 3rd Floor Boys East 3 ΕA 7 10+ vears SF Accessories **3rd Floor Boys West** 245 7 6-10 years Ceiling - Plaster/Drywall **3rd Floor Boys West** 245 SF 7 10+ years **3rd Floor Boys West** SF Doors - Side-lite 14 7 10+ years Doors - Wood Doors inclu hw **3rd Floor Boys West** 1 ΕA 7 10+ years SF Floor - Tile Ceramic/ Porcelain **3rd Floor Boys West** 245 7 10+ vears Floor Drain 3rd Floor Boys West 1 ΕA 7 10+ vears 3rd Floor Boys West 3 7 FΑ Lavatory 10+ vears Lighting - Pendent/Surface **3rd Floor Boys West** 5 FΑ 7 6-10 years 3 7 Partitions **3rd Floor Boys West** EΑ 10+ years **3rd Floor Boys West** 7 ΕA 7 Urinals 10+ years Walls - Concrete Block SF **3rd Floor Boys West** 392 7 10+ years Water Closet **3rd Floor Boys West** ΕA 3 7 10+ years SF Accessories 3rd Floor East 231 7 6-10 years SF Ceiling - Plaster/Drvwall 3rd Floor East 231 7 10+ vears Doors - Wood Doors inclu hw 3rd Floor East ΕA 7 10+ years 1 Floor - Tile 231 SF 7 3rd Floor East 10+ vears Floor Drain 3rd Floor East EA 7 10+ years 1 7 Hand Dryer 3rd Floor East 1 EA 6-10 years



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|--|----------|---------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lavatory | 3rd Floor East | 2 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor East | 7 | EA | 5 | 6-10 years | |
| | Partitions | 3rd Floor East | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor East | 354 | SF | 7 | 10+ years | |
| | Walls - Masonry | 3rd Floor East | 354 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor East | 4 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 27 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 27 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 1 | EA | 5 | 2-5 years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 27 | SF | 7 | 10+ years | |
| | Lavatory | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 1 | EA | 5 | 6-10 years | |
| | Lighting - Wall Mounted | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 1 | EA | 4 | 2-5 years | Missing lens |
| | Walls - Concrete Block | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 80 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 160 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor East - Single User Toilet Room in Boys Toilet Room | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 24 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 24 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 24 | SF | 5 | 10+ years | |
| | Lavatory | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 1 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 1 | EA | 5 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 119 | SF | 6 | 10+ years | |
| | Walls - Masonry | 3rd Floor East - Single User Toilet Room in Girls Toilet Room | 60 | SF | 6 | 10+ years | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments 3rd Floor East - Single User Toilet ΕA Water Closet 6 10+ years 1 Room in Girls Toilet Room Accessories 3rd Floor West 231 SF 7 6-10 years Ceiling - Plaster/Drywall 231 SF 3rd Floor West 6 10+ years Doors - Wood Doors inclu hw **3rd Floor West** 2 EΑ 6 10+ years SF Floor - Tile 3rd Floor West 231 6 10+ years Floor Drain 3rd Floor West ΕA 7 10+ years 1 Hand Dryer 3rd Floor West 1 ΕA 7 6-10 years Lavatory 3rd Floor West 2 ΕA 6 10+ years Lighting - Pendent/Surface 7 **3rd Floor West** ΕA 7 6-10 years Partitions 3rd Floor West 4 ΕA 7 10+ vears Walls - Concrete Block 3rd Floor West 354 SF 6 10+ years Walls - Structural Glazed Tile 3rd Floor West 354 SF 6 10+ years ΕA 6 Water Closet 3rd Floor West 4 10+ years Accessories 24 SF 7 3rd Floor West Unisex 6-10 years Ceiling - Plaster/Drywall 24 SF **3rd Floor West Unisex** 6 10+ years Doors - Wood Doors inclu hw ΕA 7 3rd Floor West Unisex 1 10+ years SF Floor - Tile Ceramic/ Porcelain 3rd Floor West Unisex 24 7 10+ years ΕA 3rd Floor West Unisex 1 7 10+ years Lavatorv Lighting - Pendent/Surface **3rd Floor West Unisex** 1 EΑ 7 10+ years Walls - Masonry 3rd Floor West Unisex 56 SF 7 10+ years Walls - Plaster/Drywall SF 7 **3rd Floor West Unisex** 56 10+ years Water Closet ΕA 7 3rd Floor West Unisex 1 10+ years

Category : Classroom

| Calegory . Classicolli | | D | unung | . wam | | |
|--|-----------|----------|-------|-------|--------------------------|----------|
| Group Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Classroom #158/160 (Weight) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 1,822 | SF | 6 | 10+ years | |
| Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| Floor - Weight/ Fitness Room Floor Matting | 1st Floor | 1,822 | SF | 6 | 6-10 years | |
| Lighting - Lay-in | 1st Floor | 55 | EA | 6 | 6-10 years | |
| Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| Wall Mirrors | 1st Floor | 132 | SF | 7 | 10+ years | |
| Walls - Plaster/Drywall | 1st Floor | 1,120 | SF | 6 | 10+ years | |
| Classroom #162 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 1st Floor | 730 | SF | 7 | 10+ years | |
| Chalk Board | 1st Floor | 40 | LF | 4 | 2-5 years | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 1st Floor | 730 | SF | 7 | 10+ years | |
| Lighting - Lay-in | 1st Floor | 21 | EA | 7 | 6-10 years | |
| Marker Board | 1st Floor | 24 | LF | 7 | 6-10 years | |

Building · Main



| Category : Classroom | | | R | 5900 N Glenwood AVENU Building : Main | | | | |
|----------------------|-----------------------------|-----------|----------|--|----------|-------------|---------------|--|
| Calego | | | B | unung | . Walli | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Croup | Walls - Plaster/Drywall | 1st Floor | 1,120 | SF | 7 | 10+ years | Comments | |
| | Walls Thatel/Drywall | 13111001 | 1,120 | 01 | , | Tor years | | |
| Classroo | om #166 (Dance Room) | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,488 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | 1st Floor | 100 | SF | 7 | 10+ years | | |
| | Floor - Wood | 1st Floor | 1,388 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 42 | ĒA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,804 | SF | 7 | 10+ years | | |
| | | | 1,001 | 0. | • | ior youro | | |
| Classroo | om #172 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 525 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 1st Floor | 3 | SF | 4 | 0-1 year | Buckled tiles | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | 1st Floor | 528 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,025 | SF | 6 | 10+ years | | |
| Classro | om #174 (Regular Classroom) | | | | | | | |
| Classion | | det Eleer | 520 | SF | <u>^</u> | 10 | | |
| | Ceiling - Lay-in | 1st Floor | 528 | | 6 | 10+ years | | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 528 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 945 | SF | 6 | 10+ years | | |
| Classroo | om #176 (Regular Classroom) | | | | | | | |
| | Casework | 1st Floor | 7 | LF | 5 | 10+ years | | |
| | Ceiling - Lay-in | 1st Floor | 730 | SF | 6 | 10+ years | | |
| | Chalk Board | 1st Floor | 68 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | 1st Floor | 730 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 21 | ĒA | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,120 | SF | 5 | 10+ years | | |
| Classro | om #219 (Regular Classroom) | | | | | | | |
| 01033100 | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 1,030 | SF | 7 | 10+ years | | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 20 | EA | 7 | 10+ years | | |
| | | 211011001 | 1 | | ' | io+ years | | |



| Category : Classroom | | Building : Main | | | | | | | |
|----------------------|-----------------------------|-----------------|-----------|-----|------|-------------|----------|--|--|
| | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor - Wood | 2nd Floor | 1,030 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 27 | EA | 6 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 33 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,441 | SF | 7 | 10+ years | | | |
| Classroo | m #221 (Computer Lab) | | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Casework | 2nd Floor | 14 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,500 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 48 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 2nd Floor | 1,500 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 7 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 50 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,490 | SF | 7 | 10+ years | | | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | | | |
| Classroo | m #222 (Faculty Lounge) | | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 2nd Floor | 705 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 7 | 10+ years | | | |
| | Floor - Wood | 2nd Floor | 705 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,140 | SF | 6 | 10+ years | | | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| Classroo | m #230 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 6 | 10+ years | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,145 | SF | 7 | 10+ years | | | |
| | Chalk Board | 2nd Floor | 26 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 2nd Floor | 21 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 2nd Floor | 1,145 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 32 | EA | 7 | 6-10 years | | | |
| | Storage/ Closet | 2nd Floor | 65 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,293 | SF | 6 | 10+ years | | | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| lassroo | m #233 (Regular Classroom) | | | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | | | |



| Category : Classroom | | R | uilding | • Main | 5900 | | | |
|----------------------|-----------------------------|-----------|----------|--------|-------|-------------|----------|--|
| Jacyo | · y . 0/035/00/11 | | D | anung | . wan | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| oroup | Ceiling - Lay-in | 2nd Floor | 1,130 | SF | 6 | 10+ years | | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 1,130 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 34 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 10 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,441 | SF | 6 | 10+ years | | |
| | | | | | | | | |
| Classroo | m #234 (Computer Lab) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Ceiling - Lay-in | 2nd Floor | 1,030 | SF | 6 | 10+ years | | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 1,030 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 27 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 36 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,440 | SF | 6 | 10+ years | | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| Classroo | m #236 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 5 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 6 | 10+ years | | |
| | Chalk Board | 2nd Floor | 28 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 2nd Floor | 21 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 730 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,160 | SF | 6 | 10+ years | | |
| Classroo | m #260 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 730 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 21 | ĒA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 7 | 10+ years | | |
| Classroo | m #261 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | | 2nd Floor | 16 | LF | 7 | 10+ years | | |



| | schools | | | | | 5900 | N Glenwood AVENUE, Chicago, IL 60660 |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|--------------------------------------|
| Catego | ry : Classroom | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 7 | 10+ years | |
| | - | | | | | - | |
| Classroo | om #262 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 7 | 10+ years | |
| | Walls Traster/Drywall | 21011001 | 1,120 | 01 | ' | Tor years | |
| Classroo | om #264 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| | Walls Traster/Drywall | 21011001 | 1,120 | 01 | 0 | Tor years | |
| Classroo | om #266 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 30 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 7 | 10+ years | |
| | | | 1,120 | 0 | 1 | ior years | |
| Classroo | om #272 (Band Room) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | | | - | | • | , | |



| ALM S | | | | | | 5900 | N Glenwood AVENUE, Chicago, IL 60660 |
|----------------------|-----------------------------|-----------|----------|--------|------|-------------|--------------------------------------|
| Category : Classroom | | B | uilding | : Main | | | |
| _ | | | - | | | Recommend | • · · · |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 2nd Floor | 1,424 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 1,424 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 45 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,672 | SF | 6 | 10+ years | |
| Classroo | om #273 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 727 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 3 | SF | 4 | 0-1 year | Water damage |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 40 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classro | om #275 (Regular Classroom) | | | | | | |
| Classion | | | | | - | 10 | |
| | Casework | 2nd Floor | 7 | LF | 5 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 724 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 4 | 0-1 year | Water damage/buckled tiles |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 44 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classroo | om #276 (Computer Lab) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 727 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 3 | SF | 4 | 0-1 year | Water damage |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ËA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 38 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classro | om #277 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 727 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 3 | SF | 4 | 0-1 year | Water damage |
| | | | C C | | - | , | |



| Category : Classroom | | | P | uilding | : Main | | 0 N Glenwood AVENUE, Chicago, IL 60660 |
|----------------------|-----------------------------|-----------|----------|---------|--------|--------------------------|--|
| Julogo | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| oreup | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 36 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classroo | m #278 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 28 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classroo | m #280 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 930 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 21 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 930 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 32 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classroo | om #281 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,120 | SF | 6 | 10+ years | |
| Classroo | om #319 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,130 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,130 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |



| Category : Classroom | | В | uilding | | | | |
|----------------------|-----------------------------|-----------|----------|-----|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | 3rd Floor | 1,439 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 5 | 2-5 years | |
| Classroo | om #320 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 120 | LF | 7 | 10+ years | |
| | Ceiling - Splined | 3rd Floor | 1,050 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,050 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,484 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 5 | 2-5 years | |
| Classroo | om #322 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 730 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 730 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 23 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 28 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,140 | SF | 7 | 10+ years | |
| Classroo | om #325 (Music Room) | | | | | | |
| | Casework | 3rd Floor | 80 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 2,395 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2,000 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 2,395 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 43 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 3,213 | SF | 6 | 10+ years | |
| Classroo | om #326 (Computer Lab) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,495 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,495 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 42 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 32 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,093 | SF | 7 | 10+ years | |
| | Wireless System | 3rd Floor | 1,033 | EA | 7 | 10+ years | |



| | ry : Classroom | | D | uilding | ·Main | 3900 | 0 N Glenwood AVENUE, Chicago, IL 6066 |
|----------|-----------------------------|-----------|----------|---------|---------|-------------|---------------------------------------|
| Calego | | | В | unung | . Walli | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| oroup | Casework | 3rd Floor | 7 | LF | 5 | 10+ years | Comments |
| | Ceiling - Lay-in | 3rd Floor | 721 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 9 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 60 | LF | 4 | 2-5 years | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 3rd Floor | 730 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,140 | SF | 6 | 10+ years | |
| Classroo | m #330 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 730 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 32 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 730 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 14 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,140 | SF | 6 | 10+ years | |
| Classroo | m #332 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 8 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 730 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 730 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 30 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,140 | SF | 7 | 10+ years | |
| Classroc | om #334 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 18 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 37 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 730 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,140 | SF | 6 | 10+ years | |
| lassroc | m #335 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 5 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,121 | SF | 6 | 10+ years | |



| Catogo | | | В | uilding | · Main | 5900 | ON Glenwood AVENUE, Chicago, IL 60660 |
|----------|------------------------------|-----------|---------------|--------------|--------|-------------|---------------------------------------|
| Catego | ry : Classroom | | В | unung | . wain | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Group | Ceiling - Lay-in | 3rd Floor | guantity 9 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 9 14 | LF | 4 | 2-5 years | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 1,130 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 27 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 22 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,200 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 139 | SF | 5 | 10+ years | Water damage |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | Water damage |
| | Wileless System | 510 1001 | I | LA | 1 | 0-10 years | |
| Classroo | m #350 (Science Lab Level 1) | | | | | | |
| | Casework | 3rd Floor | 111 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,300 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 1,300 | SF | 6 | 10+ years | |
| | Gas Line | 3rd Floor | 16 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 17 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | |
| | Science Lab Fume Hood | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,313 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 8 | EA | 7 | 10+ years | |
| Classroo | m #351 (Regular Classroom) | | | | | | |
| 01235100 | Casework | 3rd Floor | 19 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 3rd Floor | 920 | SF | 7 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 520 8 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 920 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,133 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1,133 | EA | 7 | 10+ years | |
| | | | | _ / (| • | ior youro | |
| Classroo | m #352 (Science Lab Level 3) | | | . – | | 10 | |
| | Casework | 3rd Floor | 52 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 990 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 990 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 29 | EA | 7 | 6-10 years | |



| Catego | ry : Classroom | | R | uilding | • Main | 0000 |) N Glenwood AVENUE, Chicago, IL 60660 |
|----------|---|------------------------|-------------|--------------|--------|--------------------------|--|
| Jaleyo | | | D | unung | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Oroup | Marker Board | 3rd Floor | 36 | LF | 7 | 6-10 years | Comments |
| | Walls - Plaster/Drywall | 3rd Floor | 1,001 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 3 | EA | 7 | 10+ years | |
| | | | C | L / (| • | for yourd | |
| Classroo | om #353/355 (Art Room) | | | | | | |
| | Casework | 3rd Floor | 46 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,840 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 7 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,840 | SF | 7 | 10+ years | |
| | Kiln | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 48 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 120 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,888 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 7 | 10+ years | |
| Classro | om #356 (Science Lab Level 1) | | | | | | |
| | | 3rd Floor | 209 | LF | 7 | 10 | |
| | Casework | | 209 937 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in Doors - Wood Doors inclu hw | 3rd Floor | | EA | 7 | 10+ years | |
| | | 3rd Floor | 2 | | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA SF | 7 7 | 10+ years | |
| | Floor - Tile Gas Line | 3rd Floor 3rd Floor | 937 | EA | | 10+ years | |
| | | | 16 | | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor 3rd Floor | 36 | LF EA | 7 7 | 6-10 years | |
| | Science Lab Fume Hood | | 1 | | | 10+ years | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall Work Sink | 3rd Floor 3rd Floor | 1,157 10 | SF EA | 6 7 | 10+ years | |
| | WORK SINK | 310 1001 | 10 | EA | / | 10+ years | |
| Classroo | om #358 (Science Lab Level 3) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 37 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,216 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,216 | SF | 7 | 10+ years | |
| | | | 4 | | 6 | 10+ years | |
| | Gas Line | 3rd Floor | 1 | EA | | | |
| | Lighting - Lay-in | 3rd Floor | 24 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in Marker Board | 3rd Floor 3rd Floor | 24 12 | EA LF | 7 7 | 6-10 years 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 24 | EA | 7 | 6-10 years | |



Category : Classroom

| Catego | ory : Classroom | | Б | ullaing | : Main | | | |
|---------|-------------------------------|-----------|----------|---------|--------|---------------------------------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | | | | | | | | |
| Classro | om #361 (Art Room) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 3rd Floor | 60 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 1,584 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 1,584 | SF | 7 | 10+ years | | |
| | Instructional Surface | 3rd Floor | 7 | LF | 7 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 30 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 44 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,455 | SF | 7 | 10+ years | | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| Classro | om #363 (Regular Classroom) | | | | | | | |
| 0103310 | Casework | 3rd Floor | 6 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 816 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 816 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 24 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 15 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,051 | SF | 7 | 10+ years | | |
| | | | ., | • | | , , , , , , , , , , , , , , , , , , , | | |
| Classro | om #364 (Science Lab Level 3) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 3rd Floor | 60 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 1,032 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile/Sheet | 3rd Floor | 1,032 | SF | 7 | 10+ years | | |
| | Gas Line | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 41 | LF | 7 | 6-10 years | | |
| | Science Lab Fume Hood | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,183 | SF | 7 | 10+ years | | |
| | Work Sink | 3rd Floor | 3 | EA | 7 | 10+ years | | |
| Classro | om #366 (Science Lab Level 3) | | | | | | | |
| 2 | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 3rd Floor | 84 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 1,050 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 204 | SF | 7 | 10+ years | | |
| | Dears Weed Dears include | 2rd Floor | 201 | | . 7 | 101 youro | | |

Building : Main

Doors - Wood Doors inclu hw

ΕA

7

2

10+ years

3rd Floor



|) | ry : Classroom | | D | uilding | • Main | 5900 | ON Glenwood AVENUE, Chicago, IL 60660 |
|----------|-----------------------------|------------------------|----------|---------|--------|-------------|---------------------------------------|
| Jaleyo | | | | unung | . wall | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Oroup | Eye Wash Station | 3rd Floor | 1 | EA | 6 | 10+ years | ooninients |
| | Floor - Tile | 3rd Floor | 1,050 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 1,000 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,228 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 3 | EA | 7 | 10+ years | |
| | WOIR SIIR | 314 1 1001 | 5 | LA | 1 | IU+ years | |
| Classroo | om #367 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 725 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 725 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 17 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 879 | SF | 6 | 10+ years | |
| Classro | om #372 (Regular Classroom) | | | | | | |
| 01035100 | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 750 | SF | 6 | - | |
| | Doors - Wood Doors inclu hw | 3rd Floor | | EA | | 10+ years | |
| | | | 1 | SF | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor 3rd Floor | 750 | EA | 5 7 | 10+ years | |
| | Lighting - Lay-in | | 21 | | | 6-10 years | |
| | Marker Board | 3rd Floor | 25 | SF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,061 | SF | 7 | 10+ years | |
| Classroo | om #374 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 700 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 50 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | - |
| | Floor - Wood | 3rd Floor | 750 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 24 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,063 | SF | 6 | 10+ years | |
| Classroo | om #376 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 5 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 747 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 3 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 21 | EA | 7 | 6-10 years | |
| | Lighting - Fendent/Sunace | | 21 | EA | 1 | 0-10 years | |



| Category : Classroom | | | В | uilding | : Main | | |
|----------------------|---|-----------------------------------|----------|---------|--------|---|---------------------------------------|
| 34 | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 22 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,063 | SF | 6 | 10+ years | |
| Classroo | om #378 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 729 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 21 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | i i i i i i i i i i i i i i i i i i i |
| | Floor - Wood | 3rd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 20 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 24 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,063 | SF | 6 | 10+ years | |
| 01 | | | | | | | |
| Jassroo | om #380 (Regular Classroom) Casework | 3rd Floor | 7 | LF | 5 | 10, 10, 10, 10, 10, 10, 10, 10, 10, 10, | |
| | | | | | | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 930 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 930 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 32 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 40 | LF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,115 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 5 | SF | 4 | 0-1 year | Water damage |
| Classroc | om #425 (Band Room) | | | | | | |
| | Casework | 4th Floor | 10 | LF | 5 | 10+ years | |
| | Ceiling - Splined | 4th Floor | 2,447 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 4th Floor | 8 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 4th Floor | 2 | EA | 5 | 10+ years | |
| | Floor - Wood | 4th Floor | 2,132 | SF | 6 | 10+ years | |
| | Instrument Storage Casework | 4th Floor | 63 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 4th Floor | 63 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 4th Floor | 315 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 4th Floor | 1,595 | SF | 6 | 10+ years | |
|) aterro | ry : Interior | | R | uilding | • Main | - | |
| Jaiego | | | D | anung | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | ~- | | | |
| | Ceiling - Lay-in | 129B Link from 129 to Main Office | 96 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 129B Link from 129 to Main Office | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | 129B Link from 129 to Main Office | 2 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 129B Link from 129 to Main Office | 96 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 129B Link from 129 to Main Office | 2 | EA | 6 | 6-10 years | |



Building : Main Category : Interior Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Walls - Plaster/Drvwall 129B Link from 129 to Main Office 406 SF 10+ vears 6 Walls - Plaster/Drvwall 129B Link from 129 to Main Office SF 5 0-1 year 6 Cracks in plaster Ceiling - Lay-in 1st Floor Vestibule 1.800 SF 6 10+ years Doors - Transom Window 90 SF 6 1st Floor Vestibule 10+ years Doors - Wood Doors include hw 1st Floor Vestibule 20 EΑ 6 10+ years SF Floor - Terrazzo 1st Floor Vestibule 1,800 6 10+ years Lighting - Lay-in ΕA 7 6-10 years **1st Floor Vestibule** 19 Walls - Plaster/Drywall SF 1st Floor Vestibule 1.733 7 10+ years SF Ceiling - Lay-in 1st South 1.945 6 10+ years Ceiling - Lav-in SF 1st South 4 0-1 vear 6 Water damage SF Ceiling - Plaster/Drvwall 1st South 325 6 10+ vears Drinking Fountains - Single Fountain 1st South EA 7 10+ years 1 Floor - Terrazzo 1st South 2,276 SF 5 10+ years 6 Lighting - Lay-in 1st South 17 EΑ 6-10 years Lighting - Pendent/Surface 1st South 6 6 6-10 years EΑ Stairs - Concrete Stairs 18 LF 6 1st South 10+ years SF Walls - Plaster/Drvwall 1st South 3.470 6 10+ vears SF Walls - Plaster/Drywall 1st South 100 4 0-1 year Water damage Ceiling - Lay-in SF 1st West 5.929 6 10+ vears Ceiling - Lay-in SF 1st West 21 4 0-1 year Water damage Drinking Fountains - Single Water Cooler 1st West ΕA 7 10+ years 1 SF 5 Floor - Terrazzo 1st West 5,950 10+ years 6 Lighting - Lay-in 1st West 53 EA 6-10 years Lighting - Pendent/Surface 1st West 9 FΑ 6 6-10 years Student Lockers - One Tier 236 ΕA 6 10+ years 1st West Walls - Plaster/Drywall SF 1st West 7.460 6 10+ vears SF 5 Walls - Plaster/Drywall 1st West 8 0-1 year Water damage Ceiling - Lay-in 1st floor East corridor 6.058 SF 6 10+ years Ceiling - Lay-in SF 1st floor East corridor 6 4 0-1 year Damaged tiles Doors - Steel Doors incl hw 1st floor East corridor 2 ΕA 7 10+ years Doors - Wood Doors include hw 1st floor East corridor 6 FΑ 6 10+ vears Doors - Wood Doors include hw 1st floor East corridor 6 ΕA 6 10+ vears 7 10+ years Drinking Fountains - Single Water Cooler 1st floor East corridor 1 FΑ Floor - Terrazzo 1st floor East corridor SF 5 10+ vears 6.064 6 Lighting - Lay-in 1st floor East corridor 17 EΑ 6-10 years Lighting - Pendent/Surface ΕA 6 1st floor East corridor 6 6-10 years 1st floor East corridor LF Stairs - Concrete Stairs 18 6 10+ years Student Lockers - One Tier 1st floor East corridor 250 EΑ 6 10+ years Walls - Plaster/Drvwall 1st floor East corridor 2.795 SF 6 10+ years SF Walls - Structural Glazed Tile 1st floor East corridor 5.590 6 10+ vears SF Ceiling - Lay-in 2nd East 6.069 7 10+ years Drinking Fountains - Single Water Cooler 2nd East FΑ 7 2 10+ vears Floor - Tile/Sheet 2nd East 6.069 SF 7 10+ years 7 Lighting - Lay-in 2nd East 79 EΑ 6-10 years



| Catego | ry : Interior | | B | uilding | · Main | 0000 | The Gleriwood AVENDE, Chicago, ie 00000 |
|--------|--|-----------------------------|----------------|---------|--------|-------------|---|
| Catego | ry . Interior | | | unung | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Group | Student Lockers - One Tier | 2nd East | 360 | EA | 7 | 10+ years | Comments |
| | Walls - Plaster/Drywall | 2nd East | 9,984 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd South | 2,276 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd South | 2,276 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd South | 30 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 2nd South | 240 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd South | 4,177 | SF | 7 | • | |
| | | 2nd West | 4,177 4,023 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | | | | | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 2nd West | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd West | 4,023 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd West | 57 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 2nd West | 205 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd West | 6,517 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd East | 4,023 | SF | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 3rd East | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd East | 4,023 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd East | 67 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd East | 360 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd East | 4,367 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd North (small corridor) | 1,320 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd North (small corridor) | 1,320 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd North (small corridor) | 17 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd North (small corridor) | 102 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd North (small corridor) | 2,640 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd South | 1,952 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd South | 1,952 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd South | 30 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | 3rd South | 242 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd South | 2,946 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd West | 4,297 | SF | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | 3rd West | 2 | ĒA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd West | 4,297 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd West | 55 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | 3rd West | 212 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd West | 4,288 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Corridor in Main Office 135 | 300 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Corridor in Main Office 135 | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | Corridor in Main Office 135 | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | Corridor in Main Office 135 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Corridor in Main Office 135 | 300 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Corridor in Main Office 135 | 20 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | Corridor in Main Office 135 | | SF | 7 | , | |
| | | | 300 852 | SF | | 10+ years | |
| | Walls - Plaster/Drywall | Corridor in Main Office 135 | 002 | ЗГ | 6 | 10+ years | |



| Catego | ry : Interior | | | | | | |
|---------|--|-----------------|----------|--------------|------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Safety | | | | | | | |
| | Camera Viewing Station | Entire Building | 2 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 5 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire Building | 55 | EA | 7 | 6-10 years | |
| Otalina | | | | | | | |
| Stairs | Ceiling - Lay-in | North East | 18 | SF | 4 | 0-1 year | Water damage |
| | Ceiling - Plaster/Drywall | North East | 282 | SF | 6 | 10+ years | Water damage |
| | Floor - Concrete Epoxy/ Painted | North East | 234 | SF | 5 | 10+ years | |
| | Floor - Tile | North East | 187 | SF | 5 | 10+ years | |
| | Handrails | North East | 218 | LF | 5 | 10+ years | |
| | Lighting - Lay-in | North East | 3 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | North East | 12 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | North East | 341 | LF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | North East | 2,098 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | North West | 488 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | North West | 306 | SF | 5 | 10+ years | |
| | Floor - Tile | North West | 265 | SF | 6 | 10+ years | |
| | Handrails | North West | 165 | LF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | North West | 8 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | North West | 440 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | North West | 3,734 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | South East | 200 | SF | 7 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | South East | 234 | SF | 7 | 10+ years | |
| | Floor - Tile | South East | 187 | SF | 7 | 10+ years | |
| | Handrails | South East | 218 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | South East | 210 | EA | 6 | 6-10 years | |
| | Lighting - Metal Halide/ High Pressure | South East | 1 | EA | 7 | 6-10 years | |
| | Sodium | | | _ / (| • | e le jeure | |
| | Lighting - Wall Mounted | South East | 12 | EA | 6 | 6-10 years | |
| | Stairs - Concrete | South East | 341 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | South East | 2,098 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | South West | 297 | SF | 6 | 10+ years | |
| | Floor - Epoxy/ Painted | South West | 426 | SF | 7 | 10+ years | |
| | Floor - Tile | South West | 346 | SF | 7 | 10+ years | |
| | Handrails | South West | 151 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | South West | 9 | EA | 7 | 6-10 years | |
| | Stairs - Concrete | South West | 436 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | South West | 3,152 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | West | 910 | SF | 7 | 10+ years | |
| | Floor - Asphalt | West | 487 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | West | 306 | SF | 7 | 10+ years | |
| | Floor - Tile | West | 646 | SF | 7 | 10+ years | |
| | Handrails | West | 306 | LF | 7 | 10+ years | |



Building : Main Category : Interior Recommend Group Item - Type Quantity UOM Rank **Replacement** Comments Location Lighting - Pendent/Surface 6-10 years West 22 ΕA 7 Stairs - Asphalt West 977 LF 7 10+ years Walls - Concrete Block 170 SF 10+ years West 7 SF Walls - Plaster/Drywall West 3,740 7 10+ years Vertical Conveyance Wheelchair Lift - Chair Lift ΕA 7 1st Floor 1 10+ years



Category : Exterior

Recommend Location Replacement Item - Type Quantity UOM Comments Group Rank Entrance 2 FΑ Exterior Doors - Exterior Steel Door 1 6 6-10 years 2 ΕA 6 Exterior Doors - Transom Lite 10+ years 1 LF 5 Exterior Stairs - Stone 1 160 10+ years Exterior Doors - Exterior Steel Door 11 2 ΕA 6 10+ years Exterior Doors - Exterior Steel Door 12 2 EΑ 6 6-10 years Exterior Stairs - Concrete 70 LF 5 12 10+ years LF Exterior Stairs - Stone 12 8 5 10+ years Entrance Control - Audio and Video 2 1 ΕA 6 6-10 years Exterior Doors - Exterior Steel Door 2 3 ΕA 6 6-10 years Exterior Doors - Transom Lite 2 3 FΑ 6 10+ vears 2 LF Exterior Stairs - Concrete 80 6 10+ years 2 16 LF Skim coat repair on spalled concrete Exterior Stairs - Concrete 4 0-1 year has failed Power Door Operator and Controls 2 1 EA 7 6-10 years Ramp Handrail - Steel_Ramp Handrail 2 88 LF 6 10+ years LF Ramps - Concrete 2 44 5 1-2 years Ramp is beginning to spall Stair Handrail - Steel Stair Handrail 2 30 LF 6 10+ vears 3 Exterior Doors - Exterior Steel Door 3 FΑ 6 6-10 years Exterior Doors - Transom Lite 3 3 6 10+ years EΑ 3 LF 10+ years Exterior Stairs - Stone 40 6 Exterior Doors - Exterior Steel Door ΕA 6 6-10 years NW - Auto Storage 1 LF Exterior Stairs - Stone NW - Auto Storage 3 6 10+ years FΑ Exterior Doors - Overhead Rolling/ Garage NW - AutoShop 6 1 10+ years Door Exterior Doors - Exterior Steel Door North - Boiler Room EΑ 5 1-2 years Rusted metal frames 1 **Exterior Stairs - Concrete** North - Boiler Room 25 1 F 6 10+ years Stair Handrail - Steel Stair Handrail 35 LF 10+ years North - Boiler Room 6 Entrance Control - Audio and Video North - Clinic Loading 1 EΑ 6 6-10 years 5 6-10 years Exterior Doors - Overhead Rolling/ Garage North - Clinic Loading 1 EΑ Door jamb covers are missing Door ΕA Exterior Doors - Side lite North - Clinic Loading 2 6 10+ vears Exterior Doors - Transom Lite North - Clinic Loading 1 FΑ 6 10+ vears LF North - Clinic Loading 25 6 Exterior Stairs - Concrete 10+ years Exterior Doors - Exterior Steel Door North - Electrical Outbuilding ΕA 6 4 10+ years Exterior Doors - Overhead Rolling/ Garage North - Mechanical Room 1 EΑ 6 10+ years Door Ramp Handrail - Steel Ramp Handrail North - Mechanical Room 30 LF 5 0-1 year Damaged ramp and handrail LF Ramps - Concrete North - Mechanical Room 15 6 10+ vears Exterior Doors - Exterior Steel Door North - Storage ΕA 5 1-2 years 1 Exterior Doors - Overhead Rolling/ Garage 6 10+ years North - Storage 1 ΕA Door Exterior Doors - Exterior Steel Door EA 6 10+ years Roof D 1

Building : Addition 1



Group

Lighting

Nicholas Senn High School 5900 N Glenwood AVENUE, Chicago, IL 60660

Building : Addition 1 Category : Exterior Recommend **Replacement** Comments Item - Type Location Quantity UOM Rank Foundation Foundation - Concrete Entire Building 915 LF 7 10+ years Foundation - Concrete LF 0-1 year Entire Building 16 4 Stairs to basement are missing treads and are dangerous SF Superstructure - Concrete 33.906 7 Entire Building 10+ years Exterior Lighting - Parapet or Roof Mounted 5 ΕA Entire Building 6 6-10 years Exterior Lighting - Wall Mounted Entire Building 15 ΕA 6 6-10 years Roof System 7 Access Ladder - Metal A 2 EΑ 10+ years 120 LF 5 2-5 years Coping - Metal А LF Coping - Stone А 484 6 10+ years LF Coping - Terra Cotta A 147 6 10+ years LF **Downspouts - Exterior Downspouts** A 3 4 1-2 years Missing downspout LF Downspouts - Interior Downspouts А 340 6 10+ years Parapet - 16" - 30" Height А 751 LF 6 10+ vears Parapet - 16" - 30" Height 10 LF 4 0-1 year Open joints and displaced masonry А parapet SF 5 Roof - Modified Bitumen A 20,642 2-5 years ΕA 7 10+ years Roof Hatch - Metal A 1 Roof Hatch - Metal А 1 ΕA 5 1-2 years Closing arm is damaged Roof Structure - Steel with Clay Tile Arch А 20.642 SF 7 10+ years LF Chimney - Brick Chimney- Concrete/ Mortar в 10+ years 60 6 Liner LF Chimney - Brick Chimney- Concrete/ Mortar В 30 5 10+ years Liner LF Coping - Terra Cotta В 175 6 10+ years Downspouts - Interior Downspouts В LF 6 10+ years 114 Parapet - 16" - 30" Height В LF 137 6 10+ years Parapet - Parapet < 16" Height В 38 LF 6 10+ years Parapet - Parapet > 30" В LF 194 6 10+ years В SF Roof - Modified Bitumen 2.448 5 2-5 years SF Roof Structure - Steel with Clav Tile Arch В 2.448 7 10+ vears D LF Coping - Metal 140 6 10+ years Coping - Stone D 249 LF 6 10+ years D LF 6 Downspouts - Interior Downspouts 43 10+ years Parapet - 16" - 30" Height D 55 LF 6 10+ years Parapet - 16" - 30" Height D LF 6 30 10+ years Parapet - Parapet > 30" D 194 LF 6 10+ years Roof - Modified Bitumen SF D 9,932 5 2-5 years



| Category : Exterior | | | Building : Addition 1 | | | | | |
|---------------------|--|-----------------|-----------------------|---------|----------|-------------|---|--|
| _ | | | | _ | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Roof Structure - Steel with Clay Tile Arch | D | 9,932 | SF | 7 | 10+ years | | |
| , | | | | | | | | |
| /alls | Cheek-Wall - Stone | Entire Building | 48 | SF | 6 | 10+ years | | |
| | | • | | LF | - | | | |
| | Cornice - Metal Projecting | Entire Building | 790 | | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 21,956 | SF | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 30 | SF | 5 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 1,560 | SF | 5 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 200 | SF | 3 | 0-1 year | Loose brick, cracks in masonry | |
| | Exterior Walls - Stone-Cut | Entire Building | 3,422 | SF | 6 | 10+ years | | |
| | Exterior Walls - Stone-Cut | Entire Building | 300 | SF | 5 | 10+ years | | |
| | Exterior Walls - Stone-Cut | Entire Building | 320 | SF | 5 | 10+ years | | |
| | Exterior Walls - Terra Cotta | Entire Building | 3,298 | SF | 6 | 10+ years | | |
| | Exterior Walls - Terra Cotta | Entire Building | 200 | SF | 5 | 10+ years | | |
| | | Entro Banang | 200 | 01 | Ũ | lot youro | | |
| /indows | | | | | | | | |
| | Guard - Guards perforated | Entire Building | 4,654 | SF | 6 | 10+ years | | |
| | Guard - Guards perforated | Entire Building | 150 | SF | 5 | 10+ years | | |
| | Lintels - Steel | Entire Building | 1,016 | LF | 6 | 10+ years | | |
| | Lintels - Terra Cotta | Entire Building | 140 | LF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 12,861 | SF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 600 | SF | 6 | 10+ years | | |
| `atoqo | ry : Electrical | | B | uildina | : Additi | on 1 | | |
| Jaiego | | | J | unung | . Auuni | Recommend | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| merger | ncy System | | | | | | | |
| | Automatic Transfer Switch | 1st Floor | 3 | EA | 7 | 10+ years | Serves generator, main, addition 1 addition 2 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 14,997 | SF | 6 | 10+ years | | |
| | Emergency A/C Power - Students Toilets | Entire Building | 748 | SF | 6 | 10+ years | Served by AC generator | |
| | Exit Signs - Corridors and Stairs | Entire Building | 16 | EA | 6 | 6-10 years | | |
| | Emergency Battery Packs - Corridors and | Entire Building | 4 | EA | 6 | 6-10 years | | |
| | Stairs | - | | | | | | |
| | Security System - CCTV | Entire Building | 33,906 | SF | 5 | 6-10 years | | |
| | Security System - Intrusion Detection | Entire Building | 33,906 | SF | 5 | 6-10 years | | |
| | | North Courtyard | · 1 | EA | 6 | 6-10 years | Serves main, addition 1 and addition | |
| | Emergency Generator- Outdoor- Diesel - | | | | | | | |
| | Emergency Generator- Outdoor- Diesel - 101 - 150 KW | North Courtyard | | | | | 2 | |
| ain Se | 101 - 150 KW | North Courtyard | | | | | | |



Building : Addition 1

| Catego | ry : Electrical | В | Building : Addition 1 | | | | |
|---------|---|-----------------|-----------------------|-----|------|-------------|------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 11 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 10 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 2 | EA | 7 | 10+ years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 7 | 10+ years | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 1 | EA | 7 | 10+ years | |
| | amp | | | | | | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 1 | EA | 4 | 2-5 years | Older disconnect panel |
| | amp | | | | | | |
| | Main Distribution Panels - Less than 400 | Entire Building | 1 | EA | 7 | 10+ years | |
| | amp | | | | | | |

| Category : Fire Protection | Bu | Building : Addition 1 | | | | |
|---|------------------------------------|-----------------------|----------|--------|------------------------|--|
| Crown Kom Tune | Lesstien | Quantitu | | Denk | Recommend | Commente |
| Group Item - Type Fire Alarm | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alarm Panel | Entire Building | 1 | EA | 6 | 10+ years | Serves main, addition 1 and addition 2 |
| Fire Alarm Strobe Lights Fire Alarm_System | Entire Building Entire Building | 33,906 33,906 | SF SF | 6 6 | 10+ years 10+ years | Connected to addition 1 |

Category : Mechanical

| Category : Mechanical | | | B | Building : Addition 1 | | | | |
|-----------------------|---|-----------------|----------|-----------------------|------|--------------------------|---------------------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| Air Conc | litioning | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | Serves office | |
| | Chiller-Water Cooled- Cetrifugal - 201-300 tons | Roof | 2 | EA | 6 | 10+ years | Serves main, addition 1,addition 2 | |
| | Cooling Tower - Closed Cell | Roof | 2 | EA | 6 | 10+ years | | |
| | Glycol Feed | Roof | 1 | EA | 6 | 10+ years | Manually fed | |
| | Pipes - Chilled Water Pipe- Steel | Roof | 320 | LF | 6 | 10+ years | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Site North | 1 | EA | 6 | 6-10 years | Serves computer room | |
| Air Hand | ling Systems | | | | | | | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - Less than 6000 cfm | 3rd Floor | 1 | EA | 6 | 10+ years | AHU 11, Serves room 336 | |
| | Air Intake | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Fan Coil Unit- Celing Mounted - Electric | Entire Building | 2 | EA | 5 | 6-10 years | Serve offices, split system | |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - | Mechanical Room | 1 | EA | 6 | 6-10 years | AHU 1, serves north addition 1 tunnel | |



Building : Addition 1 Category : Mechanical Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Greater than 35000 cfm ΕA Air Intake Mechanical Room 6 10+ vears 1 Auxiliaries - Greater than 35000 cfm Mechanical Room 1 FΑ 6 6-10 years 8 ΕA Reheat Boxes - Reheat Boxes with Hot Mechanical Room 6 10+ years Water Coil LF Return Duct Work - Masonry and Ducts-Mechanical Room 100 6 From corridor 10+ years Missing or Existing Shaft Zone Dampers Mechanical Room 36 EΑ 6 10+ years Some dampers are manually controlled Air Handling Unit-Package Single Zone-Mezzanine FΑ 6 AHU 8. serves north addition 1 1 10+ years Indoor- Hot Water and Chilled Water Coils -4000-8000 cfm Air Intake Mezzanine ΕA 6 1 10+ years Supply Air Intake Mezzanine 1 EΑ 6 10+ years Damper for intake air Outdoor Return Fans- inline Centrifugal -Roof 1 ΕA 6 10+ years Serves air handler 10001 - 20000 CFM Boiler Systems **Boiler Room** Boiler Auxiliary- Condensing Hot Water -5 ΕA 6 10+ years Serve main, addition 1 and addition 2 3001 - 4000 HP **Chemical Pot Feeder Boiler Room** 1 EΑ 6 10+ years Condensing- Hot Water Boiler - 3001 - 4000 **Boiler Room** 5 EΑ 6 10+ vears Serves main, addition 1, addition 2 MBH Dual Temperature Pump **Boiler Room** 2 ΕA 6 10+ vears **Glycol Feed System** Boiler Room 1 EΑ 6 10+ years Heating Devices Unit Heater - Electric 1st Floor ΕA 6 1 10+ years Unit Heater - Hot Water 1st Floor 3 FΑ 6 10+ vears Cabinet Heaters - With Hot Water Coil 4 Entire Building FΑ 6 10+ years Behind grill Entire Building 44 LF 6 Fin Tube - Hot Water 10+ years ΕA Wall Heater - Electric Entire Building 2 5 6-10 years 6 ΕA Wall Heater - Electric Entire Building 4 2-5 years Deteriorated Mechanical Plumbing Condenser Pump - 21 - 50 HP Boiler Room 2 EΑ 6 10+ vears Serves chiller Hydronic Supply and Return - Steel LF Entire Building 600 6 10+ years Dual Temperature Pump - Less than 10 Entire Building 3 ΕA 6 10+ years Serves 3 AHUs, circulators Temperature Control Electric Thermostat Entire Building 3 ΕA 6 6-10 vears Thermostats - DDC Entire Building 36 EΑ 6 6-10 years



| Catego | ry : Mechanical | | В | uilding | : Additi | on 1 | |
|---------------|--|---------------------------|----------|---------|----------|----------------------------|-------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| /entilatic | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Roof | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Roof | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Indoor - Greater than 8000 | Roof | 1 | EA | 6 | 10+ years | |
| | CFM | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 | Roof | 6 | EA | 6 | 10+ years | |
| | CFM | | | | | | |
| | Roof Mounted Duct Work | Roof | 328 | LF | 7 | 10+ years | |
| Catego | ry : Plumbing | | в | uilding | : Additi | on 1 | |
| j | , , , , , , , , , , , , , , , , , , , | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - Hot Wate | er | | | | | - | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 2 | EA | 6 | 10+ years | Serves main, addition 1, addition 2 |
| | Hot Water Storage Tank_Gas - 501 - 1000 | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Gallons | | | | - | , , , , , , , , , , | |
| Piping | | | | | | | |
| 1 0 | Domestic Piping-Cold Water Horizontal | Entire Building | 33,906 | SF | 7 | 10+ years | |
| | Lines | 3 | , | - | | , | |
| | Domestic Piping-Cold Water Risers | Entire Building | 33,906 | SF | 6 | 10+ years | |
| | Domestic Piping-Cold Water from Risers to | Entire Building | 33,906 | SF | 7 | 10+ years | |
| | Fixtures | 5 | , | | | , | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 33,906 | SF | 6 | 10+ years | There are a few pipe clamps |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 33,906 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 33,906 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 33,906 | SF | 7 | 10+ years | |
| | Fixtures | C C | | | | | |
| | Sanitary Piping | Entire Building | 33,906 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 33,906 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 33,906 | SF | 6 | 10+ years | |
| oumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Pumps - Sump-Duplex | Entire Building | 1 | EA | 6 | 10+ years | |
| Catego | ry : Room | | В | uilding | : Additi | on 1 | |
| | - | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| dminist | rative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 144 Clinic Reception Room | 148 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 144 Clinic Reception Room | 1 | EA | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Additi | on 1 | |
|--------|--|---------------------------|--------------|---------|----------|------------------------|--------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 144 Clinic Reception Room | 148 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 144 Clinic Reception Room | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 144 Clinic Reception Room | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 144 Clinic Reception Room | 573 | SF | 7 | 10+ years | |
| | AC Unit | 145 - Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 145 - Office | 683 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 145 - Office | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 145 - Office | 4 | EA | 6 | 10+ years | |
| | Floor - Wood | 145 - Office | 683 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 145 - Office | 17 | EA | 7 | 6-10 years | |
| | Power Distribution | 145 - Office | 12 | EA | 7 | 10+ years | |
| | Storage/ Closet | 145 - Office | 201 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 145 - Office | 1,572 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 145A - Office | 200 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 145A - Office | 2 | EA | 6 | 10+ years | |
| | Floor - Wood | 145A - Office | 200 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 145A - Office | 5 | ĒA | 6 | 6-10 years | |
| | Power Distribution | 145A - Office | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 145A - Office | 575 | SF | 6 | 10+ years | |
| | AC Unit | 145B - Office | 1 | ĒA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 145B - Office | 216 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 145B - Office | 1 | ĒA | 7 | 10+ years | |
| | Floor - Wood | 145B - Office | 216 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 145B - Office | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 145B - Office | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 145B - Office | 568 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 145C - Office | 117 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 145C - Office | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 145C - Office | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 145C - Office | 117 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 145C - Office | 1 | EA | 5 | 6-10 years | |
| | Power Distribution | 145C - Office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 145C - Office | 532 | SF | 7 | 10+ years | |
| | AC Unit | 147 Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 147 Office | 200 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 147 Office | 3 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 147 Office | 2 | EA | 6 | 10+ years | Water damage |
| | Floor - Wood | 147 Office | 203 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 147 Office | 203 | EA | 6 | 6-10 years | |
| | Power Distribution | 147 Office | 10 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 147 Office | 542 | SF | 7 | 10+ years | |
| | | 147 Office | 542 1,308 | SF | 6 | 10+ years | |
| | Ceiling - Splined Doors - Steel Doors incl hw | 148 Office | 1,308 | EA | 6 | 10+ years 10+ years | |
| | Doors - Wood Doors inclu hw | 148 Office | 2 | EA | 6 | • | |
| | | | Z | EA | U | 10+ years | |



| Catego | ry : Room | | Building : Addition 1 | | | | | | |
|--------|---------------------------------|--------------------------------|-----------------------|-----|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor - Wood | 148 Office | 818 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 148 Office | 21 | EA | 6 | 6-10 years | | | |
| | Power Distribution | 148 Office | 26 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 148 Office | 1,983 | SF | 7 | 10+ years | | | |
| | Ceiling - Splined | 148A Office | 117 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 148A Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 148A Office | 117 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 148A Office | 6 | EA | 7 | 10+ years | | | |
| | Power Distribution | 148A Office | 6 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 148A Office | 346 | SF | 7 | 10+ years | | | |
| | Ceiling - Splined | 148B Office | 185 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 148B Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 148B Office | 185 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 148B Office | 6 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 148B Office | 12 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 148B Office | 373 | SF | 7 | 10+ years | | | |
| | Ceiling - Splined | 148C Office | 201 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 148C Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 148C Office | 195 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 148C Office | 6 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 148C Office | 16 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | 148C Office | 6 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 148C Office | 394 | SF | 7 | 10+ years | | | |
| | Ceiling - Splined | 148D - Office | 172 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 148D - Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 148D - Office | 172 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 148D - Office | 8 | EA | 6 | 6-10 years | | | |
| | Power Distribution | 148D - Office | 16 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 148D - Office | 357 | SF | 7 | 10+ years | | | |
| | Ceiling - Exposed | 193A Break Room in Boiler Room | 216 | SF | 5 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 193A Break Room in Boiler Room | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 193A Break Room in Boiler Room | 216 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 193A Break Room in Boiler Room | 2 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 193A Break Room in Boiler Room | 6 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | 193A Break Room in Boiler Room | 75 | SF | 5 | 10+ years | | | |
| | Walls - Masonry | 193A Break Room in Boiler Room | 945 | SF | 6 | 10+ years | | | |
| | Work SInk | 193A Break Room in Boiler Room | 1 | EA | 7 | 10+ years | | | |
| | AC Unit | 195 - Engineers Office | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 195 - Engineers Office | 328 | SF | 5 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 195 - Engineers Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 195 - Engineers Office | 328 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 195 - Engineers Office | 12 | ĒA | 7 | 6-10 years | | | |
| | Power Distribution | 195 - Engineers Office | 16 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 195 - Engineers Office | 638 | SF | 6 | 10+ years | | | |



| Catego | ry : Room | | В | uilding | : Additi | | Th Glenwood AVENOE, Chicago, ie 00000 |
|--------|--------------------------------------|------------------------------------|----------|---------|----------|-------------|---------------------------------------|
| e | · , · · · · · · · · · · · · · | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Unit | 195A Engineer's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 195A Engineer's Office | 194 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 195A Engineer's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 195A Engineer's Office | 194 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 195A Engineer's Office | 6 | EA | 5 | 6-10 years | |
| | Power Distribution | 195A Engineer's Office | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 195A Engineer's Office | 369 | SF | 6 | 10+ years | |
| | AC Unit | 238B IT Work Room | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 238B IT Work Room | 684 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 238B IT Work Room | 2 | EA | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | 238B IT Work Room | 684 | SF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | 238B IT Work Room | 4 | EA | 5 | 6-10 years | |
| | Power Distribution | 238B IT Work Room | 34 | EA | 7 | 10+ years | |
| | Storage/ Closet | 238B IT Work Room | 32 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 238B IT Work Room | 1,400 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 339 Office | 512 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 339 Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 339 Office | 512 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 339 Office | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 339 Office | 4 | EA | 7 | 10+ years | |
| | Walls - Masonry | 339 Office | 174 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 339 Office | 1,398 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Behavioral Health Office in Clinic | 61 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Behavioral Health Office in Clinic | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Behavioral Health Office in Clinic | 61 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Behavioral Health Office in Clinic | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Behavioral Health Office in Clinic | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Behavioral Health Office in Clinic | 320 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Dental Clinic | 458 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Dental Clinic | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Dental Clinic | 458 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Dental Clinic | 9 | EA | 7 | 6-10 years | |
| | Power Distribution | Dental Clinic | 20 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Dental Clinic | 1,090 | SF | 7 | 10+ years | |
| | Work SInk | Dental Clinic | 4 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Exam Room 1 in Clinic | 106 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Exam Room 1 in Clinic | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Exam Room 1 in Clinic | 106 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Exam Room 1 in Clinic | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Exam Room 1 in Clinic | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Exam Room 1 in Clinic | 327 | SF | 7 | 10+ years | |
| | Work SInk | Exam Room 1 in Clinic | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Exam Room 2 in Clinic | 106 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Exam Room 2 in Clinic | 1 | EA | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Additi | on 1 | |
|---------|-----------------------------|------------------------|----------|---------|----------|-------------|----------|
| _ | | | | _ | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | Exam Room 2 in Clinic | 106 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Exam Room 2 in Clinic | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Exam Room 2 in Clinic | 6 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Exam Room 2 in Clinic | 327 | SF | 7 | 10+ years | |
| | Work SInk | Exam Room 2 in Clinic | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Laboratory in Clinic | 125 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Laboratory in Clinic | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | Laboratory in Clinic | 125 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Laboratory in Clinic | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | Laboratory in Clinic | 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Laboratory in Clinic | 505 | SF | 7 | 10+ years | |
| | Work SInk | Laboratory in Clinic | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | Staff Room in Clinic | 74 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Staff Room in Clinic | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Staff Room in Clinic | 74 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Staff Room in Clinic | 2 | ĒA | 7 | 6-10 years | |
| | Power Distribution | Staff Room in Clinic | - 8 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Staff Room in Clinic | 340 | SF | 7 | 10+ years | |
| | | | | | | 2 | |
| DF_ID | | | | | | | |
| | Doors - Steel Doors incl hw | 238A | 1 | EA | 7 | 10+ years | |
| | Finishes | 238A | 155 | SF | 5 | 10+ years | |
| | Window AC Unit | 238A | 2 | EA | 7 | 6-10 years | |
| echani | cal/ Service Rooms | | | | | | |
| | Boiler Room | 1st Floor | 3,834 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 102 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 559 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 2,073 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 3,175 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 423 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 343 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 2,307 | SF | 5 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 2,307 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor 2nd Floor | 1,260 | SF | 5 | 10+ years | |
| | Storage Room | 2nd Floor 2nd Floor | 901 | SF | 5 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 14 | SF | 5 | 10+ years | |
| | Storage Room | 3rd Floor | 14 | SF | 5 5 | 10+ years | |
| | Air Tunnel | Basement | 2,730 | SF | 5 5 | | |
| | Storage Room | Storage in Clinic | 2,730 | SF | 5 7 | 10+ years | |
| | Storage Room | Storage in Clinic | 04 | эг | 1 | 10+ years | |
| estroor | n | | | | | | |
| | Accessories | 1st Floor | 256 | SF | 7 | 6-10 years | |



| Catego | ry : Room | | В | uilding | : Additi | on 1 | |
|--------|---------------------------------|------------------|------------|---------|----------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 1st Floor | 256 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 256 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 255 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 54 | SF | 7 | 10+ vears | |
| | Walls - Plaster/Drywall | 1st Floor | 415 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 1 | ĒA | 7 | 10+ years | |
| | Accessories | 1st Floor Unisex | 50 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Unisex | 50 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Unisex | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor Unisex | 50 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor Unisex | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor Unisex | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Unisex | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor Unisex | 59 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor Unisex | 233 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Unisex | 200 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 256 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 256 256 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 200 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 256 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor | 200 | EA | | • | |
| | | | 1 | | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor | • | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 255 | SF | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor | 54 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 415 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor | 256 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 256 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 256 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor | 2 | EA | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Additi | | The Gleriwood Avenue, Chicago, ie oooo |
|----------|--|---------------------------|----------|---------|----------|------------------------|--|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 255 | SF | 7 | 10+ years | |
| | Walls - Masonry | 3rd Floor | 54 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 415 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Accessories | Engineer's Toilet in 195 | 47 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineer's Toilet in 195 | 47 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Toilet in 195 | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Engineer's Toilet in 195 | 47 | SF | 5 | 10+ years | |
| | Floor Drain | Engineer's Toilet in 195 | 1 | ĒA | 7 | 10+ years | |
| | Lavatory | Engineer's Toilet in 195 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Engineer's Toilet in 195 | 1 | EA | 5 | 6-10 years | |
| | Showers | Engineer's Toilet in 195 | 1 | EA | 5 | 10+ years | |
| | Walls - Plaster/Drywall | Engineer's Toilet in 195 | 181 | SF | 5 | 10+ years | |
| | Water Closet | Engineer's Toilet in 195 | 1 | EA | 6 | 10+ years | |
| | Accessories | Engineer's Toilet in 195A | 48 | SF | 5 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineer's Toilet in 195A | 48 | SF | 5 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Toilet in 195A | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Engineer's Toilet in 195A | 48 | SF | 5 | 10+ years | |
| | Floor Drain | Engineer's Toilet in 195A | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Engineer's Toilet in 195A | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | Engineer's Toilet in 195A | 1 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Engineer's Toilet in 195A | 1 | EA | 7 | 6-10 years | |
| | Showers | Engineer's Toilet in 195A | 1 | EA | 5 | 10+ years | |
| | Walls - Plaster/Drywall | Engineer's Toilet in 195A | 184 | SF | 6 | 10+ years | |
| | Water Closet | Engineer's Toilet in 195A | 1 | EA | 7 | 10+ years | |
| | Accessories | Unisex Clinic Toilet | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Unisex Clinic Toilet | 54 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Clinic Toilet | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Clinic Toilet | 54 | SF | 7 | 10+ years | |
| | Floor Drain | Unisex Clinic Toilet | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Unisex Clinic Toilet | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Unisex Clinic Toilet | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Unisex Clinic Toilet | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Unisex Clinic Toilet | 148 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Unisex Clinic Toilet | 148 | SF | 7 | 10+ years | |
| | Walls - The Ceramic/ Porcelain Water Closet | Unisex Clinic Toilet | 140 | EA | 7 | 10+ years 10+ years | |
| | | | | | | , | |
| Catego | ry : Classroom | | В | uilding | : Additi | | |
| Group | Itom Tuno | Logation | Overtity | | Denk | Recommend | Commonto |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #146 (Store Room) | | | | | | |



| Catego | ry : Classroom | B | 5900 N Glenwood AVENUE, Chicago, IL 6 Building : Addition 1 | | | | | |
|-----------|---------------------------------|-----------|--|-------|------|-------------|----------|--|
| Jacogo | | | | anang | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Casework | 1st Floor | 9 | LF | 6 | 10+ years | | |
| | Ceiling - Splined | 1st Floor | 596 | SF | 6 | 10+ years | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | | |
| | Floor - Wood | 1st Floor | 596 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 9 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | | |
| Classroo | om #149 (Store Room) | | | | | | | |
| _01233100 | Ceiling - Splined | 1st Floor | 1,180 | SF | 6 | 10+ years | | |
| | Chalk Board | 1st Floor | 11 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 1st Floor | 33 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | 10+ years | | |
| | Floor - Concrete | 1st Floor | 1,180 | SF | 5 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 6 | 6-10 years | | |
| | Storage/ Closet | 1st Floor | 152 | SF | 5 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,778 | SF | 5 | 10+ years | | |
| | walls Thatenbrywall | 13(1100) | 1,770 | 01 | 0 | Tor years | | |
| Classroo | om #186 ROTC (Special Program) | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 497 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 497 | SF | 5 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 6 | EA | 7 | 6-10 years | | |
| | Marker Board | 1st Floor | 5 | LF | 6 | 6-10 years | | |
| | Walls - Masonry | 1st Floor | 1,193 | SF | 6 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 216 | SF | 7 | 10+ years | | |
| Classroc | om #235 (Office) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | Ceiling - Lay-in | 2nd Floor | 217 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 11 | EA | 7 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 217 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 707 | SF | 5 | 10+ years | | |
| Classroo | om #239 (Office) | | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 512 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | 2nd Floor | 44 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | _ 1 | EA | 6 | 10+ years | | |
| | Floor - Tile/Sheet | 2nd Floor | 512 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | ĒA | 7 | 6-10 years | | |



| Catego | ry : Classroom | | В | uilding | : Additi | on 1 | |
|----------|-----------------------------|-----------|----------|---------|----------|-------------|---------------|
| | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Masonry | 2nd Floor | 174 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,398 | SF | 7 | 10+ years | |
| | , | | | | | | |
| Classroc | om #240 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 44 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 6 | | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | |
| | | | | SF | 0 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 1 | 10+ years | |
| Classroo | om #241 (Regular Classroom) | | | | | | |
| 51000100 | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 44 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 726 | SF | 7 | | |
| | | 2nd Floor | 21 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | | | SF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | / | 10+ years | |
| Classroo | om #242 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 671 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 33 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 671 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 19 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | |
| | · | | | | | · | |
| Classroc | om #243 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 6 | SF | 4 | 0-1 year | Damaged tiles |
| | Chalk Board | 2nd Floor | 44 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | B | Building : Addition 1 | | | | | |
|----------|--------------------------------|------------------------|-----------------------|----------|----------|-------------|--------------|--|
| Galego | | | | unung | . Additi | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| 0.000 | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 726 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | | |
| | Walle Thatel, Drywall | 21011001 | 1,000 | 01 | 0 | Tor yourd | | |
| Classroo | om #244 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 6 | 10+ years | | |
| | Chalk Board | 2nd Floor | 44 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | | |
| | Wallo T lablol/Drywall | 21011001 | 1,000 | 0. | 0 | ior youro | | |
| Classroo | om #245 (Special Program) | | | | | | | |
| | Casework | 2nd Floor | 18 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 367 | SF | 6 | 10+ years | | |
| | Chalk Board | 2nd Floor | 6 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 2nd Floor | 367 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 6 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 858 | SF | 7 | 10+ years | | |
| Closeros | om #246 East (Special Program) | | | | | | | |
| CIASSIUC | Casework | 2nd Floor | 11 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 591 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 2nd Floor | 3 | SF | 4 | 0-1 year | Buckled tile | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | Buckleu lile | |
| | Doors - Transom Window | 2nd Floor | 11 | SF | 4 | - | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | | | 10+ years | | |
| | Floor - Wood Doors Inclu nw | 2nd Floor 2nd Floor | 594 | EA SF | 6 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor 2nd Floor | | EA | 7 | 10+ years | | |
| | | | 18 | EA SF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,028 | 25 | 1 | 10+ years | | |
| Classroo | om #246 West (Store Room) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Ceiling - Lay-in | 2nd Floor | 490 | SF | 6 | 10+ years | | |
| | | 2nd Floor | 9 | LF | 4 | 2-5 years | | |



| Catego | ry : Classroom | | B | uildina | : Additi | on 1 | |
|----------|---------------------------------------|-----------|----------|---------|----------|-------------|----------|
| | · · · · · · · · · · · · · · · · · · · | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 2nd Floor | 11 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 490 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 955 | SF | 6 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | | | | _/ ` | • | 0.0900.0 | |
| Classroo | om #247 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 44 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | ĒA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 7 | 10+ years | |
| ~ | | | | | | | |
| Classroo | om #248 East (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 658 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 19 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 658 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,147 | SF | 6 | 10+ years | |
| Classroo | om #248 West (Special Program) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 490 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 490 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | ËA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 955 | SF | 7 | 10+ years | |
| Classro | om #249 (Regular Classroom) | | | | | | |
| 01035100 | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Casework Ceiling - Lay-in | 2nd Floor | 816 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 37 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | | SF | 4 | | |
| | | | 11 | эг | 1 | 10+ years | |



| NOR S | | | | | | | 0 N Glenwood AVENUE, Chicago, IL 60660 | | |
|----------|-----------------------------|-----------|----------|-----------------------|------|-------------|--|--|--|
| Catego | ry : Classroom | | В | Building : Addition 1 | | | | | |
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Wood | 2nd Floor | 816 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 6 | 6-10 years | | | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,100 | SF | 6 | 10+ years | | | |
| Classroo | m #336 (Art Room) | | | | | | | | |
| | Casework | 3rd Floor | 36 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,621 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | . 9 | SF | 4 | 0-1 year | Water damage | | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | 10+ years | 5 | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒA | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 1,630 | SF | 5 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 36 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | | | |
| | Storage/ Closet | 3rd Floor | 167 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,554 | SF | 6 | 10+ years | | | |
| | Work Sink | 3rd Floor | 3 | EA | 7 | 6-10 years | | | |
| | | | | | | | | | |
| Classroc | om #337 (Office) | | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 220 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 3 | SF | 4 | 0-1 year | Water damage | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 223 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 642 | SF | 7 | 10+ years | | | |
| Classroo | m #340 (Regular Classroom) | | | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | | | |
| | Casework | 3rd Floor | 28 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,050 | SF | 6 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 24 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 1,050 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 29 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 5 | LF | 6 | 6-10 years | | | |
| | Storage/ Closet | 3rd Floor | 35 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,299 | SF | 6 | 10+ years | | | |
| | | | .,200 | 2. | Ť | | | | |



| Category : Classroom | | | В | 5900 N Glenwood AVENUE, Chicago, IL 606 Building : Addition 1 | | | | |
|----------------------|-----------------------------|-----------|----------|--|-----------|-------------|--------------|--|
| | | | | anang | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | | | | | | | | |
| Classroc | m #343 East (Computer Lab) | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 982 | SF | 7 | 10+ years | | |
| | Chalk Board | 3rd Floor | 37 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 982 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,178 | SF | 7 | 10+ years | | |
| Classroc | m #343 West (Computer Lab) | | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | | |
| | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 508 | SF | 7 | 10+ years | | |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 508 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 880 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 2 | SF | 5 | 0-1 year | Water damage | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | C C | |
| lassroc | m #344 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 1,122 | SF | 6 | 10+ years | | |
| | Chalk Board | 3rd Floor | 33 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 1,122 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 33 | EA | 7 | 6-10 years | | |
| | Marker Board | 3rd Floor | 24 | LF | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,285 | SF | 6 | 10+ years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 10 | SF | 5 | 0-1 year | Water damage | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 6-10 years | - | |
| lassroc | m #345 (Special Program) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | | |
| | Casework | 3rd Floor | 10 | | 7 | 10+ years | | |
| | Casework | 51011001 | 10 | LI | ' | TOT years | | |
| | | | | | | | | |



| Category : Classroom | | | В | Building : Addition 1 | | | | |
|----------------------|----------------------------------|-----------|-----------|-----------------------|------|-------------|---------------|--|
| _ | | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Ceiling - Lay-in | 3rd Floor | 361 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 6 | SF | 4 | 0-1 year | Buckled tiles | |
| | Chalk Board | 3rd Floor | 24 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 367 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 6 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 796 | SF | 6 | 10+ years | | |
| lassroo | om #346 East (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 718 | SF | 6 | 10+ years | | |
| | Chalk Board | 3rd Floor | 22 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 718 | SF | 5 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | | EA | | 6-10 years | | |
| | | | 15 | SF | 6 | • | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,010 | SF | 6 | 10+ years | | |
| lassroo | om #346 West (Store Room) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 470 | SF | 6 | 10+ years | | |
| | Chalk Board | 3rd Floor | 24 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 470 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 9 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 812 | SF | 7 | 10+ years | | |
| Classroo | om #347 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 743 | SF | 6 | 10+ years | | |
| | Chalk Board | 3rd Floor | 38 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | ĒA | 6 | 10+ years | | |
| | Floor - Wood | 3rd Floor | 743 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,022 | SF | 7 | 10+ years | | |
| | | | 1,022 | 5 | 1 | 10+ years | | |
| lassroo | om #348 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 11 | LF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 3rd Floor | 1,200 | SF | 6 | 10+ years | | |
| | Chalk Board | 3rd Floor | 30 | LF | 4 | 2-5 years | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | | |



Category : Classroom Building : Addition 1 Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Wood 3rd Floor SF 1,200 6 10+ years Lighting - Lay-in 3rd Floor 33 ΕA 6 6-10 years Walls - Plaster/Drywall 3rd Floor 1,344 SF 7 10+ years Classroom #349 (Regular Classroom) Casework 3rd Floor 9 LF 6 10+ years Ceiling - Lay-in 3rd Floor 810 SF 7 10+ years SF 3rd Floor Ceiling - Lay-in 6 4 0-1 year Buckled tiles LF Chalk Board 47 3rd Floor 4 2-5 years SF Doors - Transom Window 3rd Floor 11 7 10+ years Doors - Wood Doors inclu hw 3rd Floor ΕA 7 10+ years 1 Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 6 10+ years Floor - Wood 3rd Floor SF 816 5 10+ years 7 Lighting - Lay-in 3rd Floor 18 ΕA 6-10 years Walls - Plaster/Drywall 3rd Floor 1,100 SF 6 10+ years

Category : Interior

Building : Addition 1

Pacammand

| | | | | | | Recommend | |
|----------|--|------------------------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Lay-in | First Floor Corridors | 5,633 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | First Floor Corridors | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | First Floor Corridors | 2,503 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | First Floor Corridors | 3,130 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | First Floor Corridors | 80 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | First Floor Corridors | 125 | EA | 7 | 10+ years | |
| | Walls - Masonry | First Floor Corridors | 2,023 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | First Floor Corridors | 6,349 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | First Floor Vestibule | 332 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | First Floor Vestibule | 2 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | First Floor Vestibule | 332 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | First Floor Vestibule | 1 | EA | 7 | 6-10 years | |
| | Walls - Masonry | First Floor Vestibule | 643 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | First Floor Vestibule | 916 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Health Clinic | 148 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | Health Clinic | 4 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Health Clinic | 148 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Health Clinic | 3 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Health Clinic | 650 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Second Floor Corridors | 39 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Second Floor Corridors | 2,831 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Second Floor Corridors | 26 | SF | 7 | 10+ years | |
| | Drinking Fountains - Single Water Cooler | Second Floor Corridors | 2 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | Second Floor Corridors | 334 | SF | 7 | 10+ years | |



| Catego | Category : Interior | | | | Building : Addition 1 | | | | |
|--------|--|-------------------------------------|-----------|-----|-----------------------|-------------|--------------|--|--|
| U | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Floor - Tile/Sheet | Second Floor Corridors | 2,582 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Second Floor Corridors | 37 | EA | 7 | 6-10 years | | | |
| | Student Lockers - One Tier | Second Floor Corridors | 140 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | Second Floor Corridors | 2,056 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | Second Floor Corridors | 2,166 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Third Floor Corridor | 2,795 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | Third Floor Corridor | 75 | SF | 4 | 0-1 year | Water damage | | |
| | Ceiling - Plaster/Drywall | Third Floor Corridor | 26 | SF | 7 | 10+ years | | | |
| | Drinking Fountains - Single Water Cooler | Third Floor Corridor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | Third Floor Corridor | 334 | SF | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | Third Floor Corridor | 2,572 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Third Floor Corridor | 42 | EA | 7 | 6-10 years | | | |
| | Student Lockers - One Tier | Third Floor Corridor | 147 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | Third Floor Corridor | 2,056 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | Third Floor Corridor | 1,657 | SF | 6 | 10+ years | | | |
| | | | | | | | | | |
| Safety | | | | | | | | | |
| | Camera Viewing Station | Office 145A | 1 | EA | 7 | 6-10 years | | | |
| | Security Cameras | Office 145A | 6 | EA | 7 | 6-10 years | | | |
| | | | | | | | | | |
| Stairs | | | | | | | | | |
| | Ceiling - Lay-in | Northeast Staircase | 136 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Northeast Staircase | 162 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | Northeast Staircase | 260 | SF | 7 | 10+ years | | | |
| | Handrails | Northeast Staircase | 123 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Northeast Staircase | 2 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | Northeast Staircase | 4 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | Northeast Staircase | 352 | LF | 7 | 10+ years | | | |
| | Walls - Masonry | Northeast Staircase | 1,004 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | Northeast Staircase | 1,507 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | Northwest Staircase | 182 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Northwest Staircase | 505 | SF | 6 | 10+ years | | | |
| | Floor - Terrazzo | Northwest Staircase | 418 | SF | 7 | 10+ years | | | |
| | Handrails | Northwest Staircase | 128 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Northwest Staircase | 7 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | Northwest Staircase | 6 | EA | 6 | 6-10 years | | | |
| | Stairs - Terrazzo | Northwest Staircase | 499 | LF | 7 | 10+ years | | | |
| | Walls - Masonry | Northwest Staircase | 1,085 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | Northwest Staircase | 1,327 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Service Stair from rm 194 to rm 336 | 136 | SF | 5 | 10+ years | | | |
| | Floor - Asphalt | Service Stair from rm 194 to rm 336 | 136 | SF | 6 | 10+ years | | | |
| | Handrails | Service Stair from rm 194 to rm 336 | 92 | LF | 5 | 10+ years | | | |
| | Lighting - Pendent/Surface | Service Stair from rm 194 to rm 336 | 1 | EA | 6 | 6-10 years | | | |
| | Stairs - Asphalt | Service Stair from rm 194 to rm 336 | 190 | LF | 6 | 10+ years | | | |



Building : Addition 1 Category : Interior Recommend Location Group Item - Type Quantity UOM Comments Rank Replacement Stairs - Asphalt Service Stair from rm 194 to rm 336 . 0-1 year Damaged 3 LF 4 Walls - Plaster/Drywall Service Stair from rm 194 to rm 336 2,107 SF 5 10+ years Vertical Conveyance Elevator - Elevator- Roped Holeless 1st Floor 1 ΕA 6 10+ years Hydraulic



Category : Exterior Building : Addition 2 Recommend Location Replacement Item - Type Quantity UOM **Comments** Group Rank Entrance 5 3 FΑ Exterior Doors - Exterior Steel Door 6 6-10 years 5 3 ΕA 6 Exterior Doors - Transom Lite 10+ years 5 LF 5 Exterior Stairs - Stone 40 10+ years Exterior Doors - Exterior Steel Door 6 3 ΕA 6 6-10 years Exterior Doors - Transom Lite 6 3 ΕA 6 10+ years Exterior Stairs - Stone 6 67 LF 5 10+ years LF Exterior Stairs - Stone 6 14 4 0-1 year Broken Stone, safety Concern Exterior Doors - Exterior Steel Door 7 2 ΕA 6 6-10 vears Exterior Doors - Transom Lite 7 2 ΕA 6 10+ years 7 LF Exterior Stairs - Stone 152 5 10+ vears 1 F Exterior Stairs - Stone 7 8 4 0-1 year Broken Stone step, safety concern Exterior Doors - Exterior Steel Door 8 2 ΕA 6 6-10 years Exterior Doors - Transom Lite 8 2 ΕA 6 10+ years 8 LF Exterior Stairs - Stone 20 5 10+ years Exterior Doors - Exterior Steel Door 9 6 ΕA 6 10+ years Exterior Doors - Transom Lite 9 4 FΑ 6 6-10 years Foundation Foundation - Concrete LF 7 Entire Building 822 10+ years SF Superstructure - Concrete Entire Building 37,798 7 10+ years Lighting Exterior Lighting - Parapet or Roof Mounted Entire Building 9 EΑ 6 6-10 years Exterior Lighting - Wall Mounted 13 ΕA 6 6-10 years Entire Building Roof System Coping - Stone Μ 47 LF 6 10+ vears Downspouts - Exterior Downspouts 70 LF 10+ years Μ 6 Parapet - Parapet < 16" Height Μ 60 LF 6 10+ years LF Parapet - Parapet > 30" Μ 47 6 10+ years Roof - Modified Bitumen SF Μ 8,128 4 1-2 years Various failures of roofing SF Roof Structure - Steel with Clay Tile Arch 7 Μ 8,128 10+ years FΑ Access Ladder - Metal Ν 4 0-1 year Obsolete ladder is not secured to the 1 building LF Coping - Terra Cotta Ν 20 6 10+ vears Coping - Terra Cotta Ν 216 LF 6 10+ years **Downspouts - Exterior Downspouts** LF 6 10+ years Ν 96 Downspouts - Interior Downspouts LF Ν 100 6 10+ years LF Parapet - Parapet < 16" Height Ν 20 6 10+ years Parapet - Parapet > 30" LF Ν 216 6 10+ years SF Roof - Modified Bitumen Ν 5 10.880 2-5 years



Category : Exterior Building : Addition 2 Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Roof Structure - Steel with Clay Tile Arch Ν 10.880 SF 10+ vears 7 0 ΕA 7 Access Ladder - Metal 2 10+ years Coping - Metal 0 87 LF 6 10+ years 0 87 LF 6 Parapet - 16" - 30" Height 10+ years 0 SF 5 Roof - Modified Bitumen 3,206 2-5 years SF 0 Roof - Modified Bitumen 500 4 1-2 years 0 ΕA 7 10+ years Roof Hatch - Metal 1 SF Roof Structure - Steel with Clay Tile Arch Ο 3.706 7 10+ years Access Ladder - Metal Ρ ΕA 7 10+ years 1 Р LF Coping - Metal 377 5 10+ years Р LF Coping - Terra Cotta 88 6 10+ vears Downspouts - Exterior Downspouts Ρ 288 LF 6 10+ years Parapet - 16" - 30" Height Ρ 465 LF 6 10+ years Р SF 15.030 5 Roof - Modified Bitumen 2-5 years Most of the grit is gone from the surface of the roofing, there are several soft spots Р 7 Roof Hatch - Metal ΕA 10+ vears 1 Roof Structure - Steel with Clay Tile Arch Р 15.030 SF 7 10+ years Walls Cheek-Wall - Stone SF Entire Building 95 6 10+ years Cornice - Metal Projecting Entire Building 852 LF 6 10+ vears SF Exterior Walls - Brick Entire Building 18.852 6 10+ years Exterior Walls - Brick SF 5 Entire Building 411 10+ vears Exterior Walls - Brick Entire Building 200 SF 5 10+ years Entire Building 3.579 SF 6 Exterior Walls - Stone-Cut 10+ years SF 5 Exterior Walls - Stone-Cut Entire Building 200 10+ years 97 SF 5 Exterior Walls - Stone-Cut Entire Building 10+ years Exterior Walls - Terra Cotta SF 5 Entire Building 8.212 10+ years SF Exterior Walls - Terra Cotta Entire Building 231 5 10+ years Windows Guard - Guards perforated Entire Building 5,097 SF 6 10+ years Guard - Guards perforated Entire Building 100 SF 5 10+ years Lintels - Steel Entire Building 1.249 LF 6 10+ vears SF Windows - Sash Aluminum Double-pane 13.194 6 10+ years Entire Building 477 SF Windows - Sash Aluminum Double-pane Entire Building 6 10+ years **Category : Electrical Building : Addition 2** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Emergency System Exit Signs - Corridors and Stairs Entire Building 22 ΕA 6 6-10 years



| Category : Electrical | | | | Building : Addition 2 | | | | | |
|---------------------------|---|-----------------|----------|-----------------------|----------|--------------------------|---------------------------------------|--|--|
| - | | Recommend | | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Exit Signs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | | | |
| | Exit Signs - Gym | Entire Building | 5 | EA | 6 | 6-10 years | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 11,294 | SF | 6 | 10+ years | | | |
| | Emergency A/C Power - Gym | Entire Building | 13,380 | SF | 6 | 10+ years | | | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,205 | SF | 6 | 10+ years | | | |
| | Security System - CCTV | Entire Building | 37,798 | SF | 6 | 6-10 years | | | |
| | Security System - Intrusion Detection | Entire Building | 37,798 | SF | 6 | 6-10 years | | | |
| | Security System - CCTV | Entire Building | 37,798 | SF | 6 | 6-10 years | Duplicate entry | | |
| | Security System - Intrusion Detection | Entire Building | 37,798 | SF | 6 | 6-10 years | Duplicate entry | | |
| Main Ser | vice | | | | | | | | |
| | PA System | Entire Building | 37,798 | SF | 5 | 6-10 years | Connected to main and north addition | | |
| Power D | istribution | | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 7 | 10+ years | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 13 | EA | 6 | 10+ years | | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | | | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 7 | 10+ years | | | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 2 | EA | 7 | 10+ years | | | |
| | Transformers - 120/240 - 120/208 | Entire Building | 1 | EA | 4 | 2-5 years | More than 50 years old, not reliable | | |
| Catego | ry : Fire Protection | | B | uilding | : Additi | on 2 | | | |
| | | | | | | Recommend | | | |
| Group Fire Alar | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Fire Alarm Strobe Lights | Entire Building | 37,798 | SF | 6 | 10+ years | | | |
| | Fire Alarm_System | Entire Building | 37,798 | SF | 6 | 10+ years | Connected to addition 1 building | | |
| Catego | ry : Mechanical | | В | uilding | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | | |
| Air Hand | ling Systems | | | | | | | | |
| | Air Handling Unit- Built Up- Multi Zone- Dual Temperature Coils - 8001 - 15000 cfm | 1st Floor | 1 | EA | 6 | 6-10 years | AHU 5, serves 2 gyms and locker rooms | | |
| | Air Intake | 1st Floor | 1 | EA | 6 | 6-10 years | | | |
| | Auxiliaries - 8001 - 15000 cfm | 1st Floor | 1 | EA | 6 | 6-10 years | | | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | 1st Floor | 150 | LF | 6 | 6-10 years | Form corridor | | |
| | Zone Dampers | 1st Floor | 5 | EA | 6 | 6-10 years | Some dampers are manually operated | | |



| Category : Mechanical | | | R | 5900 N Glenwood AVENUE, Chicago, IL 60660 Building : Addition 2 | | | | | |
|-----------------------|---|-----------------|----------|---|------------|-------------|---|--|--|
| outego | y meenamea | | | unung | . Addition | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Greater than 35000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | AHU 4, serves south addition 2 | | |
| | Air Intake | Mechanical Room | 1 | EA | 6 | 6-10 years | | | |
| | Auxiliaries - Greater than 35000 cfm | Mechanical Room | 1 | EA | 6 | 6-10 years | | | |
| | Reheat Boxes - Reheat Boxes with Hot Water Coil | Mechanical Room | 10 | EA | 6 | 6-10 years | | | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room | 100 | LF | 6 | 6-10 years | From corridor | | |
| | Zone Dampers | Mechanical Room | 39 | EA | 6 | 6-10 years | Some dampers are manually operated | | |
| | Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM | Roof | 2 | EA | 6 | 10+ years | In line style, serve air handlers | | |
| Heating I | | | | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 6 | EA | 6 | 10+ years | Behind grill | | |
| | Fin Tube - Hot Water | Entire Building | 40 | LF | 6 | 10+ years | | | |
| | Wall Heater - Electric | Entire Building | 4 | EA | 5 | 6-10 years | Serve restrooms | | |
| Mechanio | cal Plumbing | | | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 400 | LF | 6 | 10+ years | | | |
| | Dual Temperature Pump - Less than 10 | Entire Building | 1 | EA | 6 | 10+ years | Serves air handler | | |
| Tempera | ture Control | | | | | | | | |
| | DDC System | Entire Building | 37,798 | SF | 6 | 10+ years | Served from addition 1 | | |
| | Thermostats - DDC | Entire Building | 42 | EA | 6 | 10+ years | Connected to DDC system in main building | | |
| | Thermostats - DDC | Entire Building | 2 | EA | 4 | 2-5 years | Not calibrated, dampers are manually controlled | | |
| Ventilatio | | | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 10+ years | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 10+ years | | | |
| | Lab Exhaust Hood | Entire Building | 3 | EA | 6 | 10+ years | | | |
| | Roof Mounted Duct Work | Entire Building | 20 | LF | 7 | 10+ years | | | |
| Catego | ry : Plumbing | | В | uilding | : Additi | | | | |
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |



| Catarra | | | | ي منا ما ابر | . A al al 144 | | J N Glenwood AVENUE, Chicago, IL 60660 |
|----------|--|--|----------|--------------|----------------------|---|---|
| Catego | ry : Plumbing | | В | uilding | : Additi | | |
| Crown | ltem Tune | Location | Quantity | UOM | Rank | Recommend Replacement | Commonto |
| Group | Item - Type Domestic Piping-Cold Water Horizontal | Entire Building | 37,798 | SF | 6 | 10+ years | Comments There are a few pipe clamps |
| | Lines | | 57,790 | 36 | 0 | TOT years | There are a few pipe clamps |
| | Domestic Piping-Cold Water Risers | Entire Building | 37,798 | SF | 6 | 10+ years | |
| | Domestic Piping-Cold Water from Risers to | Entire Building | 37,798 | SF | 7 | 10+ years | |
| | Fixtures | Entito Ballanig | 01,100 | 0. | • | lot youro | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 37,798 | SF | 6 | 10+ years | There are a few pipe clamps |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 37,798 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 37,798 | SF | 7 | 10+ years | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 37,798 | SF | 7 | 10+ years | |
| | Fixtures | C C | | | | · | |
| | Sanitary Piping | Entire Building | 37,798 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 37,798 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 37,798 | SF | 6 | 10+ years | |
| | | | | | | | |
| Pumps | | | | | | | |
| | Pumps - Sump-Duplex | Basement | 1 | EA | 5 | 6-10 years | |
| • | _ | | _ | | | • | |
| Catego | ry : Room | | В | uilding | : Additi | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | rative Suites/Offices | Loodion | quantity | 00111 | Marin | Replacement | |
| Auminisi | AC Unit | 150 Coach's Office in Gym 1 | 1 | EA | 5 | 2-5 years | |
| | Ceiling - Plaster/Drywall | 150 Coach's Office in Gym 1 | 272 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 150 Coach's Office in Gym 1 | 20 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 150 Coach's Office in Gym 1 | 20 | EA | 6 | 10+ years | Water damage |
| | Floor - Tile | 150 Coach's Office in Gym 1 | 292 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 150 Coach's Office in Gym 1 | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | 150 Coach's Office in Gym 1 | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 150 Coach's Office in Gym 1 | 520 | SF | 6 | 10+ years | |
| | | | | | | 2 | |
| Gymnas | a | | | | | | |
| - | Ceiling - Plaster/Drywall | 151 Gym | 3,350 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 151 Gym | 36 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 151 Gym | 5 | EA | 7 | 10+ years | |
| | Floor - Sport Flooring | 151 Gym | 3,350 | SF | 7 | 6-10 years | |
| | Lighting - Metal Halide/Sodium Vapor | 151 Gym | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 151 Gym | 300 | SF | 5 | 10+ years | |
| | Walls - Masonry | 151 Gym | 1,680 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 151 Gym | 3,670 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 155 Wrestling Gym former girls | 1,380 | SF | 7 | 10+ years | |
| | Deere Weed Deere included | locker | 0 | ۲A | 7 | 10, 10, 10, 00, 00, 00, 00, 00, 00, 00, | |
| | Doors - Wood Doors inclu hw | 155 Wrestling Gym former girls locker | 2 | EA | 7 | 10+ years | |
| | | IUCKEI | | | | | |



| Catego | ategory : Room | | | Building : Addition 2 | | | | | |
|---------|--|--------------------------------|----------|-----------------------|------|---------------------------------------|----------|--|--|
| | | | | U | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| • | Doors - Wood Doors inclu hw | 155 Wrestling Gym former girls | 2 | EA | 5 | 2-5 years | | | |
| | | locker | | | | , | | | |
| | Floor - Sport Flooring | 155 Wrestling Gym former girls | 1,380 | SF | 7 | 10+ years | | | |
| | 5 | locker | , | - | | , , , , , , , , , , , , , , , , , , , | | | |
| | Lighting - Metal Halide/ High Pressure | 155 Wrestling Gym former girls | 12 | EA | 7 | 10+ years | | | |
| | Sodium | locker | | | | , | | | |
| | Storage/ Closet | 155 Wrestling Gym former girls | 120 | SF | 5 | 10+ years | | | |
| | 5 | locker | | | | , | | | |
| | Walls - Concrete Block | 155 Wrestling Gym former girls | 1,776 | SF | 7 | 10+ years | | | |
| | | locker | , | | | , | | | |
| | Bleacher Seating | Gymnasium 1 | 190 | EA | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Gymnasium 1 | 9,700 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Gymnasium 1 | 0,100 | EA | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Gymnasium 1 | 6 | EA | 7 | 10+ years | | | |
| | | , | - | SF | | | | | |
| | Floor - Epoxy/ Painted | Gymnasium 1 | 2,200 | | 7 | 6-10 years | | | |
| | Floor - Tile Ceramic/ Porcelain | Gymnasium 1 | 100 | SF | 6 | 10+ years | | | |
| | Floor - Wood | Gymnasium 1 | 7,400 | SF | 7 | 10+ years | | | |
| | Lighting - Metal Halide/Sodium Vapor | Gymnasium 1 | 34 | EA | 7 | 6-10 years | | | |
| | Scoreboards | Gymnasium 1 | 1 | EA | 5 | 6-10 years | | | |
| | Sound System | Gymnasium 1 | 1 | EA | 7 | 6-10 years | | | |
| | Storage/ Closet | Gymnasium 1 | 340 | SF | 5 | 10+ years | | | |
| | Storage/ Closet | Gymnasium 1 | 120 | SF | 5 | 10+ years | | | |
| | Walls - Masonry | Gymnasium 1 | 8,400 | SF | 7 | 10+ years | | | |
| | , | , | | | | , | | | |
| ocker/S | Shower Room | | | | | | | | |
| | Accessories | Men's Gym Locker | 1,500 | SF | 7 | 6-10 years | | | |
| | Benches, ped mounted | Men's Gym Locker | 46 | LF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Men's Gym Locker | 1,500 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | , | 1,500 | EA | 7 | | | | |
| | | Men's Gym Locker | | | | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | Men's Gym Locker | 1,500 | SF | 7 | 10+ years | | | |
| | Floor Drain | Men's Gym Locker | 3 | EA | 7 | 10+ years | | | |
| | Hand Dryer | Men's Gym Locker | 4 | EA | 7 | 6-10 years | | | |
| | Lavatory | Men's Gym Locker | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Men's Gym Locker | 20 | EA | 7 | 10+ years | | | |
| | Partitions | Men's Gym Locker | 2 | EA | 7 | 10+ years | | | |
| | Showers | Men's Gym Locker | 3 | EA | 7 | 10+ years | | | |
| | Student Lockers - One Tier | Men's Gym Locker | 48 | EA | 7 | 10+ years | | | |
| | Student Lockers - Two Tier | Men's Gym Locker | 63 | EA | 7 | 10+ years | | | |
| | Urinals | Men's Gym Locker | 2 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Men's Gym Locker | | SF | 7 | | | | |
| | | | 540 | SF | | 10+ years | | | |
| | Walls - Masonry | Men's Gym Locker | 270 | | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Men's Gym Locker | 270 | SF | 7 | 10+ years | | | |
| | Walls - Tile Ceramic/ Porcelain | Men's Gym Locker | 540 | SF | 7 | 10+ years | | | |
| | Water Closet | Men's Gym Locker | 2 | EA | 7 | 10+ years | | | |



| Catego | ry : Room | | B | uilding | : Additi | on 2 | |
|--------|---------------------------------|----------------------|----------|---------|----------|-------------|----------|
| _ | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Accessories | Unisex Locker in 155 | 97 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Unisex Locker in 155 | 97 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Locker in 155 | 97 | SF | 7 | 10+ years | |
| | Floor Drain | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Lavatory | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Unisex Locker in 155 | 2 | EA | 7 | 10+ years | |
| | Showers | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Unisex Locker in 155 | 100 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Unisex Locker in 155 | 300 | SF | 7 | 10+ years | |
| | Water Closet | Unisex Locker in 155 | 1 | EA | 7 | 10+ years | |
| | Accessories | Unisex Shower Room | 110 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | Unisex Shower Room | 4 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Unisex Shower Room | 110 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Shower Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Shower Room | 110 | SF | 7 | 10+ years | |
| | Floor Drain | Unisex Shower Room | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Unisex Shower Room | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Unisex Shower Room | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Unisex Shower Room | 2 | EA | 7 | 10+ years | |
| | Showers | Unisex Shower Room | 1 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | Unisex Shower Room | 4 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Unisex Shower Room | 378 | SF | 7 | 10+ years | |
| | Water Closet | Unisex Shower Room | 1 | EA | 7 | 10+ years | |
| | Accessories | Women's Gym Locker | 1,500 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | Women's Gym Locker | 46 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Women's Gym Locker | 1,500 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Women's Gym Locker | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Women's Gym Locker | 1,500 | SF | 7 | 10+ years | |
| | Floor Drain | Women's Gym Locker | 3 | EA | 7 | 10+ years | |
| | Hand Dryer | Women's Gym Locker | 4 | EA | 7 | 10+ years | |
| | Lavatory | Women's Gym Locker | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Women's Gym Locker | 20 | EA | 7 | 10+ years | |
| | Partitions | Women's Gym Locker | 4 | EA | 7 | 10+ years | |
| | Showers | Women's Gym Locker | 3 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | Women's Gym Locker | 48 | EA | 7 | 10+ years | |
| | Student Lockers - Two Tier | Women's Gym Locker | 63 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Women's Gym Locker | 540 | SF | 7 | 10+ years | |
| | Walls - Masonry | Women's Gym Locker | 270 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Women's Gym Locker | 270 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Women's Gym Locker | 540 | SF | 7 | 10+ years | |
| | | Women's Gym Locker | | | | | |



Nicholas Senn High School 5900 N Glenwood AVENUE, Chicago, IL 60660

| Catego | ry : Room | | Building : Addition 2 | | | | | |
|---------|-----------------------------|--------------------|-----------------------|-----|------|-------------|----------|--|
| - | - | | | 3 | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Mechani | cal/ Service Rooms | | | | | | | |
| | Janitor's Closet | 1st Floor | 90 | SF | 5 | 10+ years | | |
| | Janitor's Closet | 1st Floor | 50 | SF | 5 | 10+ years | | |
| | Mechanical/ Service Rooms | 1st Floor | 60 | SF | 7 | 10+ years | | |
| | Mechanical/ Service Rooms | 1st Floor | 712 | SF | 7 | 10+ years | | |
| | Mechanical/ Service Rooms | 1st Floor | 950 | SF | 7 | 10+ years | | |
| | Storage Room | 1st Floor | 18 | SF | 5 | 10+ years | | |
| | Janitor's Closet | 2nd Floor | 25 | SF | 5 | 10+ years | | |
| | Mechanical/ Service Rooms | 2nd Floor | 150 | SF | 7 | 10+ years | | |
| | Janitor's Closet | 3rd Floor | 62 | SF | 5 | 10+ years | | |
| | Storage Room | 3rd Floor | 56 | SF | 5 | 10+ years | | |
| | Storage Room | 3rd Floor | 178 | SF | 5 | 10+ years | | |
| | Storage Room | 3rd Floor | 390 | SF | 5 | 10+ years | | |
| | Air Tunnel | Basement | 2,730 | SF | 5 | 10+ years | | |
| | Air Tunnel | Basement | 1,300 | SF | 5 | 10+ years | | |
| | Mechanical/ Service Rooms | Basement | 350 | SF | 5 | 10+ years | | |
| | | Basement | 000 | 01 | Ŭ | Tor youro | | |
| Prep Ro | om | | | | | | | |
| | Casework | in Science Lab 100 | 40 | LF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | in Science Lab 100 | 230 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | in Science Lab 100 | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | in Science Lab 100 | 230 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | in Science Lab 100 | 3 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | in Science Lab 100 | 637 | SF | 7 | 10+ years | | |
| | Work Sink | in Science Lab 100 | 1 | EA | 7 | 10+ years | | |
| | Casework | in Science Lab 105 | 30 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | in Science Lab 105 | 326 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | in Science Lab 105 | 22 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | in Science Lab 105 | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | in Science Lab 105 | 326 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | in Science Lab 105 | 3 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | in Science Lab 105 | 693 | SF | 7 | 10+ years | | |
| | Work Sink | in Science Lab 105 | 1 | EA | 7 | 10+ years | | |
| | Casework | in Science Lab 106 | 49 | LF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | in Science Lab 106 | 230 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | in Science Lab 106 | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | in Science Lab 106 | 230 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | in Science Lab 106 | 3 | EA | 6 | 6-10 years | | |
| | Walls - Plaster/Drywall | in Science Lab 106 | 566 | SF | 7 | 10+ years | | |
| | Work Sink | in Science Lab 106 | 1 | EA | 7 | 10+ years | | |
| | Casework | in Science Lab 306 | 40 | LF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | in Science Lab 306 | 230 | SF | 7 | 10+ years | | |
| | Doors - Side-lite | in Science Lab 306 | 20 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | in Science Lab 306 | 1 | EA | 7 | 10+ years | | |



| Catego | ry : Room | | В | uilding | : Additi | on 2 | |
|------------|---------------------------------|--|----------|------------|----------|-------------|--------------|
| Ŭ | | | | U | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | in Science Lab 306 | 230 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | in Science Lab 306 | 4 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | in Science Lab 306 | 637 | SF | 7 | 10+ years | |
| | Work Sink | in Science Lab 306 | 1 | EA | 7 | 10+ years | |
| | Casework | in Science Lab 310 (east) | 48 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | in Science Lab 310 (east) | 230 | SF | 7 | 10+ years | |
| | Doors - Side-lite | in Science Lab 310 (east) | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | in Science Lab 310 (east) | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | in Science Lab 310 (east) | 230 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | in Science Lab 310 (east) | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | in Science Lab 310 (east) | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | in Science Lab 310 (east) | 543 | SF | 7 | 10+ years | |
| | Work Sink | in Science Lab 310 (east) | 1 | EA | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | in Science Lab 310 (west) | 130 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | in Science Lab 310 (west) | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | in Science Lab 310 (west) | 130 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | in Science Lab 310 (west) | 3 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | in Science Lab 310 (west) | 608 | SF | 7 | 10+ years | |
| D / | | | | | | | |
| Restroor | | 4504 Unio en Lo alcon/Tailet Da era in | 400 | 05 | 7 | 0.40 | |
| | Accessories | 150A Unisex Locker/Toilet Room in | 128 | SF | 7 | 6-10 years | |
| | | Coach's Office of Gym 1 | 400 | 05 | 0 | 10 | |
| | Ceiling - Plaster/Drywall | 150A Unisex Locker/Toilet Room in | 128 | SF | 6 | 10+ years | |
| | Deene Weed Deene in the house | Coach's Office of Gym 1 | 0 | - ^ | 7 | 10 | |
| | Doors - Wood Doors inclu hw | 150A Unisex Locker/Toilet Room in | 2 | EA | 7 | 10+ years | |
| | | Coach's Office of Gym 1 | | - ^ | | 0.4 | Design also |
| | Doors - Wood Doors inclu hw | 150A Unisex Locker/Toilet Room in | 1 | EA | 4 | 0-1 year | Broken glass |
| | | Coach's Office of Gym 1 | 00 | 05 | 0 | 10 | |
| | Floor - Tile Ceramic/ Porcelain | 150A Unisex Locker/Toilet Room in | 28 | SF | 6 | 10+ years | |
| | | Coach's Office of Gym 1 | 400 | 05 | 0 | 0.40 | |
| | Floor - Wood | 150A Unisex Locker/Toilet Room in | 100 | SF | 6 | 6-10 years | |
| | L eveter v | Coach's Office of Gym 1 | | - ^ | 0 | 10 | |
| | Lavatory | 150A Unisex Locker/Toilet Room in | 1 | EA | 6 | 10+ years | |
| | | Coach's Office of Gym 1 | 0 | - • | - | 0.40 | |
| | Lighting - Pendent/Surface | 150A Unisex Locker/Toilet Room in | 2 | EA | 7 | 6-10 years | |
| | Lindation and MARINA surfaced | Coach's Office of Gym 1 | | - ^ | - | 0.5 | |
| | Lighting - Wall Mounted | 150A Unisex Locker/Toilet Room in | 1 | EA | 5 | 2-5 years | |
| | Oh | Coach's Office of Gym 1 | | - ^ | - | 0.5 | |
| | Showers | 150A Unisex Locker/Toilet Room in | 1 | EA | 5 | 2-5 years | |
| | Otestant Lasters Ora Tian | Coach's Office of Gym 1 | 7 | – ^ | - | 0.40 | |
| | Student Lockers - One Tier | 150A Unisex Locker/Toilet Room in | 7 | EA | 5 | 6-10 years | |
| | Walls Concrete Plast | Coach's Office of Gym 1 | 70 | <u>с</u> г | 7 | 10, | |
| | Walls - Concrete Block | 150A Unisex Locker/Toilet Room in | 70 | SF | 7 | 10+ years | |
| | | Coach's Office of Gym 1 | | | | | |



| Catego | ry : Room | | В | uilding | : Additi | | |
|--------|---------------------------------|-----------------------------------|----------|----------|----------|-------------|------------------------------|
| J | • | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | 150A Unisex Locker/Toilet Room in | 350 | SF | 6 | 10+ years | |
| | | Coach's Office of Gym 1 | | | | | |
| | Walls - Plaster/Drywall | 150A Unisex Locker/Toilet Room in | 100 | SF | 4 | 0-1 year | Displaced, missing, damaged, |
| | | Coach's Office of Gym 1 | | | | | possible water damage |
| | Water Closet | 150A Unisex Locker/Toilet Room in | 1 | EA | 6 | 10+ years | |
| | | Coach's Office of Gym 1 | | | | | |
| | Accessories | 1st Floor Boys | 182 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Boys | 182 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boys | 182 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor Boys | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Boys | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor Boys | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor Boys | 150 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor Boys | 256 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Boys | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Girls | 325 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Girls | 325 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor Girls | 32 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor Girls | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Girls | 1 | ĒA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Girls | 325 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor Girls | | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Girls | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor Girls | 7 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Girls | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor Girls | 5 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor Girls | 260 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor Girls | 60 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor Girls | 430 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Girls | -30 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor Girls | 244 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girls | 244 244 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 2nd Floor Girls | 32 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor Girls | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | | | | | | |
| | | 2nd Floor Girls | 1 | EA SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Girls | 244 | - | 7 | 10+ years | |
| | Floor Drain | 2nd Floor Girls | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor Girls | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor Girls | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Girls | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor Girls | 6 | EA | 7 | 10+ years | |



| Catego | ry : Room | | B | uildina | : Additi | | Th Glerwood Avenue, Chicago, ie 60660 |
|--------|--|--|-----------|----------|------------|------------------------|---------------------------------------|
| Culogo | | | | anang | . / taanti | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Concrete Block | 2nd Floor Girls | 300 | SF | 7 | 10+ years | |
| | Walls - Masonry | 2nd Floor Girls | 60 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Girls | 280 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor Girls | 6 | EA | 7 | 10+ years | |
| | Accessories | Gym 1 Balcony Mens | 90 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Gym 1 Balcony Mens | 80 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Gym 1 Balcony Mens | 10 | SF | 3 | 0-1 year | Active leak |
| | Doors - Wood Doors inclu hw | Gym 1 Balcony Mens | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Gym 1 Balcony Mens | 90 | SF | 6 | 10+ years | |
| | Floor Drain | Gym 1 Balcony Mens | 1 | EA | 7 | 10+ years | |
| | Lavatory | Gym 1 Balcony Mens | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Gym 1 Balcony Mens | 1 | EA | 6 | 6-10 years | |
| | Partitions | Gym 1 Balcony Mens | 1 | EA | 7 | 10+ years | |
| | Urinals | Gym 1 Balcony Mens | 1 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Gym 1 Balcony Mens | 100 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Gym 1 Balcony Mens | 270 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Gym 1 Balcony Mens | 10 | SF | 5 | 10+ years | Active leak |
| | Water Closet | Gym 1 Balcony Mens | 1 | EA | 6 | 10+ years | |
| | Accessories | Gym 1 Balcony Womens | 120 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Gym 1 Balcony Womens | 115 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Gym 1 Balcony Womens | 5 | SF | 4 | 0-1 year | Significant water damage |
| | Doors - Wood Doors inclu hw | Gym 1 Balcony Womens | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Gym 1 Balcony Womens | 120 | SF | 7 | 10+ years | |
| | Lavatory | Gym 1 Balcony Womens | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Gym 1 Balcony Womens | 2 | EA | 7 | 6-10 years | |
| | Partitions | Gym 1 Balcony Womens | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Gym 1 Balcony Womens | 600 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Gym 1 Balcony Womens | 135 | SF | 4 | 0-1 year | Significant water damage |
| | Water Closet | Gym 1 Balcony Womens | 2 | EA | 7 | 10+ years | |
| | Accessories | Multi Unisex East | 244 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Multi Unisex East | 244 | SF SF | 7 7 | 10+ years | |
| | Doors - Side-lite Doors - Transom Window | Multi Unisex East | 32 | | | 10+ years | |
| | | Multi Unisex East | 44 | SF EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Multi Unisex East | 1 | EA SF | 7 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain Floor Drain | Multi Unisex East | 244 | EA | | 10+ years | |
| | | Multi Unisex East | 1 | EA | 7 7 | 10+ years | |
| | Hand Dryer | Multi Unisex East | 1 | | | 6-10 years | |
| | Lavatory Lighting - Pendent/Surface | Multi Unisex East | 2 | EA EA | 7 6 | 10+ years | |
| | Partitions | Multi Unisex East Multi Unisex East | 4 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Multi Unisex East | 300 | SF | 7 | 10+ years 10+ years | |
| | Walls - Concrete Block Walls - Masonry | Multi Unisex East | 300 60 | SF | 7 | 10+ years 10+ years | |
| | Walls - Masonry Walls - Plaster/Drywall | Multi Unisex East Multi Unisex East | 60 280 | SF | 7 | 10+ years 10+ years | |
| | Walls - Plaster/Drywall Water Closet | Multi Unisex East | | EA | 7 | | |
| | Waler CIUSEL | | 1 | EA | 1 | 10+ years | |



Building : Addition 2 Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments FΑ Water Closet Multi Unisex East 5 7 10+ vears **Category : Classroom Building : Addition 2** Recommend Location **Replacement** Comments Group Item - Type Quantity UOM Rank Classroom #100 (Science Lab Level 1) LF 7 Casework 1st Floor 83 10+ years SF Ceiling - Lay-in 1st Floor 1,314 7 10+ years Doors - Wood Doors inclu hw ΕA 7 1st Floor 2 10+ years Eve Wash Station 1st Floor 1 ΕA 7 10+ years Floor - Tile/Sheet SF 1st Floor 1,314 7 10+ years Gas Line 1st Floor 8 EΑ 7 10+ vears Lighting - Lay-in 1st Floor 36 FΑ 7 10+ years Marker Board 1st Floor 10 LF 7 6-10 vears FΑ Science Lab Fume Hood 1st Floor 1 7 10+ years Science Lab Shower ΕA 7 1st Floor 1 10+ years SF Walls - Plaster/Drywall 1st Floor 1,500 7 10+ years Work Sink ΕA 7 1st Floor 8 10+ years Classroom #101 (Regular Classroom) 1st Floor 9 LF Casework 6 10+ years SF Ceiling - Lay-in 1st Floor 796 7 10+ years Chalk Board 1st Floor 24 LF 4 2-5 years SF Doors - Transom Window 1st Floor 11 6 10+ years Doors - Wood Doors inclu hw 1st Floor 2 ΕA 6 10+ years SF Floor - Wood 1st Floor 796 6 10+ years Lighting - Lay-in 1st Floor 21 ΕA 7 10+ vears LF Marker Board 1st Floor 24 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 1.065 7 10+ years Classroom #103 (Store Room) LF Casework 1st Floor 9 6 10+ years SF Ceiling - Lay-in 750 7 10+ years 1st Floor Chalk Board LF 1st Floor 20 4 2-5 years Doors - Transom Window SF 1st Floor 22 7 10+ years Doors - Wood Doors inclu hw 1st Floor 2 ΕA 7 10+ years SF Floor - Wood 1st Floor 750 6 10+ years Lighting - Lay-in 1st Floor 21 ΕA 7 6-10 years LF Marker Board 1st Floor 24 7 6-10 years Walls - Plaster/Drywall 1st Floor 964 SF 6 10+ years Classroom #105 (Science Lab Level 2) Casework 1st Floor LF 7 88 10+ years



| Catego | ry : Classroom | | В | uilding | : Additi | on 2 | Building : Addition 2 | | | | | |
|---------|------------------------------|-----------|------------|---------|----------|-------------|-----------------------|--|--|--|--|--|
| | | | | | | Recommend | | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,124 | SF | 7 | 10+ years | | | | | | |
| | Doors - Transom Window | 1st Floor | 33 | SF | 7 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | | | | | | |
| | Eye Wash Station | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Floor - Tile | 1st Floor | 1,124 | SF | 7 | 10+ years | | | | | | |
| | Gas Line | 1st Floor | 8 | EA | 7 | 10+ years | | | | | | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | | | | | | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | | | | | | |
| | Science Lab Shower | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,174 | SF | 7 | 10+ years | | | | | | |
| | Work Sink | 1st Floor | 8 | EA | 7 | 10+ years | | | | | | |
| lassroc | m #106 (Science Lab Level 2) | | | | | | | | | | | |
| | Casework | 1st Floor | 90 | LF | 7 | 10+ years | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,232 | SF | 7 | 10+ years | | | | | | |
| | Doors - Transom Window | 1st Floor | 22 | SF | 6 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 5 | 10+ years | | | | | | |
| | Eye Wash Station | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Floor - Tile | 1st Floor | 1,232 | SF | 7 | 10+ years | | | | | | |
| | Gas Line | 1st Floor | 8 | ĒA | 7 | 10+ years | | | | | | |
| | Lighting - Lay-in | 1st Floor | 35 | EA | 7 | 6-10 years | | | | | | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | | | | | | |
| | Science Lab Shower | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,387 | SF | 7 | 10+ years | | | | | | |
| | Work Sink | 1st Floor | 8 | EA | 7 | 10+ years | | | | | | |
| lassroo | m #110 (Science Lab Level 2) | | | | | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | | | | | | |
| | Casework | 1st Floor | 90 | LF | 7 | 10+ years | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,472 | SF | 7 | 10+ years | | | | | | |
| | Doors - Transom Window | 1st Floor | 22 | SF | 7 | 10+ years | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | | | | | | |
| | Eye Wash Station | 1st Floor | - 1 | EA | 7 | 10+ years | | | | | | |
| | Floor - Tile | 1st Floor | , 1,472 | SF | 7 | 10+ years | | | | | | |
| | Gas Line | 1st Floor | ., | EA | 7 | 10+ years | | | | | | |
| | Lighting - Lay-in | 1st Floor | 21 | EA | 7 | 6-10 years | | | | | | |
| | Marker Board | 1st Floor | 16 | LF | 7 | 6-10 years | | | | | | |
| | Science Lab Shower | 1st Floor | 1 | EA | 7 | 10+ years | | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,434 | SF | 7 | 10+ years | | | | | | |
| | Work Sink | 1st Floor | 8 | EA | 7 | 10+ years | | | | | | |

Classroom #200 (Regular Classroom)



| Group Ite Ca Ce Ch Do Do Flo Lig Ma Wa Classroom #2 | Classroom m - Type asework eiling - Lay-in halk Board bors - Transom Window bors - Wood Doors inclu hw bor - Wood ghting - Lay-in arker Board alls - Plaster/Drywall | Location 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | Quantity 9 796 12 11 1 796 | UOM LF SF LF SF EA | Addition | Recommend Replacement 10+ years 10+ years 2-5 years 10+ years | Comments |
|---|---|--|--|-----------------------------------|-------------|--|------------------|
| Ca Ce Ch Do Flo Lig Ma Wa Classroom #2 | asework eiling - Lay-in nalk Board pors - Transom Window pors - Wood Doors inclu hw por - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 9 796 12 11 1 | LF SF LF SF | 6 7 4 | 10+ years 10+ years 2-5 years | Comments |
| Ce Ch Do Flo Lig Ma Wa Classroom #2 | eiling - Lay-in nalk Board pors - Transom Window pors - Wood Doors inclu hw por - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 796 12 11 1 | SF LF SF | 7 4 | 10+ years 2-5 years | |
| Ch Do Do Flo Lig Ma Wa Classroom #2 | nalk Board pors - Transom Window pors - Wood Doors inclu hw por - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 12 11 1 | LF SF | 4 | 2-5 years | |
| Do Do Flo Lig Ma Wa Classroom #2 | oors - Transom Window oors - Wood Doors inclu hw oor - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 11 1 | SF | | | |
| Do Flo Lig Ma Wa Classroom #2 | bors - Wood Doors inclu hw bor - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor 2nd Floor | 1 | | 7 | | |
| Fic Lig Ma Wa Classroom #2 | oor - Wood ghting - Lay-in arker Board | 2nd Floor 2nd Floor | | FΔ | | ior years | |
| Lig Ma Wa Classroom #2 | ghting - Lay-in arker Board | 2nd Floor | 796 | | 7 | 10+ years | |
| Ma Wa Classroom #2 | arker Board | | | SF | 7 | 10+ years | |
| Ma Wa Classroom #2 | arker Board | | 22 | EA | 7 | 6-10 years | |
| Classroom #2 | alls - Plaster/Drywall | 2nd Floor | 30 | LF | 7 | 6-10 years | |
| | | 2nd Floor | 1,237 | SF | 7 | 10+ years | |
| | 201 (Regular Classroom) | | | | | | |
| AC | C Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| - | asework | 2nd Floor | - 9 | LF | 6 | 10+ years | |
| | eiling - Lay-in | 2nd Floor | 796 | SF | 7 | 10+ years | |
| | nalk Board | 2nd Floor | 16 | LF | 4 | 2-5 years | |
| | oors - Transom Window | 2nd Floor | 11 | SF | 7 | 10+ years | |
| Do | oors - Wood Doors inclu hw | 2nd Floor | 1 | ĒA | 7 | 10+ years | |
| Flo | oor - Wood | 2nd Floor | 796 | SF | 7 | 10+ years | |
| Lic | ghting - Lay-in | 2nd Floor | 22 | ĒA | 7 | 6-10 years | |
| | arker Board | 2nd Floor | 38 | LF | 6 | 6-10 years | |
| | alls - Plaster/Drywall | 2nd Floor | 1,237 | SF | 7 | 10+ years | |
| Classroom # | 202 (Regular Classroom) | | | | | | |
| | asework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | eiling - Lay-in | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | nalk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| - | ors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | oors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | por - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | phting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | arker Board | 2nd Floor | 32 | LF | 7 | 6-10 years | |
| | alls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | |
| _Classroom #2 | 203 (Regular Classroom) | | | | | | |
| | asework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | eiling - Lay-in | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | halk Board | 2nd Floor | 12 | LF | 4 | 2-5 years | |
| - | ors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | oors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | Missing hardware |
| | por - Wood | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | ghting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | arker Board | 2nd Floor | 24 | LF | 7 | 6-10 years | |
| | alls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 7 | 10+ years | |



Building : Addition 2 Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #204 (Regular Classroom) Casework 2nd Floor 9 LF 6 10+ years 2nd Floor 726 SF 7 10+ years Ceiling - Lay-in Chalk Board 2nd Floor 22 LF 2-5 years 4 Doors - Transom Window 2nd Floor 22 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor FΑ 7 10+ years 1 Doors - Wood Doors inclu hw 2nd Floor 1 FΑ 7 10+ years SF Floor - Wood 2nd Floor 726 10+ years 6 Lighting - Lay-in 2nd Floor 21 EΑ 7 6-10 years Marker Board 2nd Floor 22 LF 7 6-10 years Walls - Plaster/Drywall 2nd Floor 1,090 SF 7 10+ years Classroom #205 (Other Instructional Use) 2nd Floor LF Casework 11 6 10+ years Ceiling - Lay-in 2nd Floor 358 SF 7 10+ years Chalk Board 2nd Floor 5 LF 2-5 years 4 Doors - Transom Window SF 7 10+ years 2nd Floor 11 FΑ 7 Doors - Wood Doors inclu hw 2nd Floor 10+ years 1 Floor - Wood 2nd Floor 358 SF 7 10+ years Lighting - Lay-in 2nd Floor 6 FΑ 7 10+ years LF Marker Board 2nd Floor 40 7 6-10 years SF Walls - Plaster/Drywall 2nd Floor 832 7 10+ years Classroom #206 (Regular Classroom) LF Casework 2nd Floor 9 7 10+ years Ceiling - Lay-in 2nd Floor SF 726 7 10+ vears LF Chalk Board 2nd Floor 22 4 2-5 years Doors - Transom Window 2nd Floor 22 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 7 EΑ 10+ years Floor - Wood SF 7 10+ years 2nd Floor 726 7 Lighting - Lay-in 2nd Floor 21 EΑ 6-10 years Marker Board 2nd Floor 22 LF 7 6-10 years Walls - Plaster/Drywall SF 2nd Floor 1.090 6 10+ years Classroom #207 (Regular Classroom) 2nd Floor LF Casework 9 7 10+ years 2nd Floor SF Ceiling - Lay-in 726 7 10+ years LF Chalk Board 2nd Floor 22 2-5 years 4 Doors - Transom Window 2nd Floor 22 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 ΕA 7 10+ years Floor - Wood 2nd Floor 726 SF 7 10+ years Lighting - Lay-in 2nd Floor 21 EΑ 7 6-10 years



| Catego | ry : Classroom | | В | uildina | : Additi | on 2 | |
|---------|---|-----------|----------|---------|------------|--------------|----------|
| | | | | anang | . / toolth | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 7 | 10+ years | |
| | | | ., | | | , see geene | |
| lassroc | om #208 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 7 | 10+ years | |
| | | | | | | | |
| lassroc | om #209 (Regular Classroom) AC Units | 2nd Floor | 4 | | 7 | C 10 via are | |
| | | | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 9 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | |
| lassroc | om #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 9 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 726 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 22 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 726 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 21 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,090 | SF | 6 | 10+ years | |
| | | | 1,090 | 0 | 0 | TOT years | |
| lassroc | om #213 (Office) | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 510 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 44 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 510 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | EA | 7 | 6-10 years | |



| Category : Classroom | | | B | Building : Addition 2 | | | | | |
|----------------------|---|---|---|--|---|--|----------|--|--|
| | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Walls - Masonry | 2nd Floor | 190 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,150 | SF | 6 | 10+ years | | | |
| | , | | , | - | - | -) | | | |
| Classroc | m #217 (Other Instructional Use) | | | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 152 | SF | 7 | 10+ years | | | |
| | Chalk Board | 2nd Floor | 4 | LF | 4 | 2-5 years | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 2nd Floor | 152 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 577 | SF | 7 | 10+ years | | | |
| lassror | m #300 (Regular Classroom) | | | | | | | | |
| 21000100 | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 825 | SF | 6 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 30 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 825 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 22 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,114 | SF | 6 | 10+ years | | | |
| 0 | | | | | | | | | |
| Jassroc | m #301 (Regular Classroom) | | | | 0 | 40 | | | |
| | Casework | 3rd Floor | 9 | LF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 825 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 10 | SF | 7 | 10+ years | | | |
| | | 3rd Floor | | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | | 11 | | | | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw Floor - Wood | 3rd Floor 3rd Floor | 1 825 | EA SF | 7 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in | 3rd Floor 3rd Floor 3rd Floor | 1 825 22 | EA SF EA | 7 6 7 | 10+ years 6-10 years | | | |
| | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 | EA SF EA LF | 7 6 7 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in | 3rd Floor 3rd Floor 3rd Floor | 1 825 22 | EA SF EA | 7 6 7 | 10+ years 6-10 years | | | |
| Classroo | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 | EA SF EA LF | 7 6 7 7 | 10+ years 6-10 years 6-10 years | | | |
| Classroo | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 | EA SF EA LF SF | 7 6 7 7 6 | 10+ years 6-10 years 6-10 years | | | |
| Classroo | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 | EA SF EA LF SF | 7 6 7 7 | 10+ years 6-10 years 6-10 years 10+ years 10+ years | | | |
| Classroo | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework Ceiling - Lay-in | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 786 | EA SF EA LF SF LF SF | 7 6 7 6 6 7 | 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years | | | |
| Classroc | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework Ceiling - Lay-in Chalk Board | 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 786 12 | EA SF LF SF LF SF LF | 7 6 7 6 6 7 4 | 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 2-5 years | | | |
| Classroc | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window | 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 786 12 11 | EA SF LF SF LF SF LF SF | 7 6 7 6 6 7 4 7 | 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years | | | |
| Classroc | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw | 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 786 12 11 1 | EA SF LF SF LF SF LF SF EA | 7 6 7 6 6 7 4 7 7 | 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years | | | |
| Classroc | Doors - Wood Doors inclu hw Floor - Wood Lighting - Lay-in Marker Board Walls - Plaster/Drywall m #302 (Science Lab Level 3) Casework Ceiling - Lay-in Chalk Board Doors - Transom Window | 3rd Floor 3rd Floor | 1 825 22 20 1,114 34 786 12 11 | EA SF LF SF LF SF LF SF | 7 6 7 6 6 7 4 7 | 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years | Chipped | | |



| Catego | ry : Classroom | | В | Building : Addition 2 | | | | | |
|----------|----------------------------------|-----------|----------|-----------------------|------|-------------|----------|--|--|
| | , | | | J | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,048 | SF | 7 | 10+ years | | | |
| | Work Sink | 3rd Floor | 1 | ĒA | 4 | 2-5 years | | | |
| Classroo | om #303 (Regular Classroom) | | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 750 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 3 | ĒA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 750 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 10+ years | | | |
| | Marker Board | 3rd Floor | 40 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 980 | SF | 6 | 10+ years | | | |
| Classroo | m #305 (Other Instructional Use) | | | | | | | | |
| | Casework | 3rd Floor | 11 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 368 | SF | 7 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 10 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 368 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 9 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 755 | SF | 7 | 10+ years | | | |
| Classroo | om #306 (Science Lab Level 2) | | | | | | | | |
| | Casework | 3rd Floor | 92 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,228 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 3rd Floor | 1,228 | SF | 7 | 10+ years | | | |
| | Gas Line | 3rd Floor | 8 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 36 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,270 | SF | 7 | 10+ years | | | |
| | Work Sink | 3rd Floor | 8 | EA | 7 | 10+ years | | | |
| Classroo | om #307 (Regular Classroom) | | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 750 | SF | 7 | 10+ years | | | |
| | | 3rd Floor | 25 | LF | 4 | 2-5 years | | | |



| Latego | ry : Classroom | B | Building : Addition 2 | | | | | | |
|----------|------------------------------|-----------|-----------------------|-----|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 750 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 25 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 980 | SF | 6 | 10+ years | | | |
| Classroc | m #309 (Regular Classroom) | | | | | | | | |
| | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor | 750 | SF | 7 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 25 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 22 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 3rd Floor | 750 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 21 | EA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 25 | LF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 980 | SF | 6 | 10+ years | | | |
| lassroc | m #310 (Science Lab Level 2) | | | | | | | | |
| | Casework | 3rd Floor | 60 | LF | 6 | 10+ years | | | |
| | Casework | 3rd Floor | 14 | LF | 5 | 2-5 years | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,136 | SF | 6 | 10+ years | | | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | | | |
| | Doors - Transom Window | 3rd Floor | 11 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 3rd Floor | 1,136 | SF | 6 | 10+ years | | | |
| | Gas Line | 3rd Floor | , 4 | EA | 6 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor | 32 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,338 | SF | 7 | 10+ years | | | |
| | Work Sink | 3rd Floor | 3 | EA | 7 | 10+ years | | | |
| | Work Sink | 3rd Floor | 1 | EA | 5 | 2-5 years | | | |
| Classroc | m #315 (Office) | | | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 490 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 3rd Floor | 44 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 3rd Floor | 490 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | ĒA | 7 | 6-10 years | | | |
| | Marker Board | 3rd Floor | 12 | LF | 7 | 6-10 years | | | |
| | Walls - Masonry | 3rd Floor | 190 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 838 | SF | 6 | 10+ years | | | |

Classroom #317 (Office)



Building : Addition 2 Category : Classroom Recommend Group Quantity UOM Rank **Replacement** Comments Item - Type Location Ceiling - Lay-in 10+ years 3rd Floor 148 SF 7 Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 7 10+ years 148 SF 10+ years Floor - Wood 3rd Floor 6 Lighting - Lay-in 3rd Floor ΕA 10+ years 3 7 Walls - Plaster/Drywall 496 SF 7 10+ years 3rd Floor

| Catego | ry : Interior | | Building : Addition 2 | | | | | | |
|----------|--|----------------------|-----------------------|-----|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Corridor | | | | | | | | | |
| | Ceiling - Lay-in | 1st Floor Corridors | 2,702 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor Corridors | 949 | SF | 6 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st Floor Corridors | 6 | EA | 7 | 10+ years | | | |
| | Doors - Transom Window | 1st Floor Corridors | 22 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 1st Floor Corridors | 8 | EA | 6 | 10+ years | | | |
| | Drinking Fountains - Single Water Cooler | 1st Floor Corridors | 2 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor Corridors | 1,257 | SF | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 1st Floor Corridors | 2,736 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor Corridors | 42 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 1st Floor Corridors | 10 | EA | 6 | 6-10 years | | | |
| | Student Lockers - One Tier | 1st Floor Corridors | 147 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | 1st Floor Corridors | 2,915 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor Corridors | 3,219 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor Vestibules | 415 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 1st Floor Vestibules | 3 | EA | 6 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor Vestibules | 415 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 1st Floor Vestibules | 8 | EA | 7 | 6-10 years | | | |
| | Walls - Masonry | 1st Floor Vestibules | 647 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor Vestibules | 384 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor Vestibules | 326 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 2ndFloor Corridors | 2,870 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 2ndFloor Corridors | 36 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 2ndFloor Corridors | 2 | EA | 6 | 10+ years | | | |
| | Drinking Fountains - Single Water Cooler | 2ndFloor Corridors | 2 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | 2ndFloor Corridors | 334 | SF | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 2ndFloor Corridors | 2,382 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 2ndFloor Corridors | 41 | EA | 7 | 10+ years | | | |
| | Student Lockers - One Tier | 2ndFloor Corridors | 143 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | 2ndFloor Corridors | 2,056 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2ndFloor Corridors | 2,166 | SF | 7 | 10+ years | | | |
| | Ceiling - Lay-in | 3rd Floor Corridors | 2,858 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor Corridors | 48 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 3rd Floor Corridors | 1 | EA | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 3rd Floor Corridors | 7 | EA | 6 | 10+ years | | | |



| Category : Interior | | | Building : Addition 2 | | | | | | |
|---------------------|--|-------------------------|-----------------------|-----|------|-------------|----------|--|--|
| Ŭ | | | | J | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| - | Drinking Fountains - Single Water Cooler | 3rd Floor Corridors | 2 | EA | 7 | 6-10 years | | | |
| | Floor - Terrazzo | 3rd Floor Corridors | 332 | SF | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 3rd Floor Corridors | 2,572 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 3rd Floor Corridors | 40 | EA | 7 | 10+ years | | | |
| | Student Lockers - One Tier | 3rd Floor Corridors | 144 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | 3rd Floor Corridors | 2,052 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 3rd Floor Corridors | 1,657 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Corridor @ Locker Rooms | 150 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Corridor @ Locker Rooms | 4 | EA | 7 | 10+ years | | | |
| | Drinking Fountains - Single Water Cooler | Corridor @ Locker Rooms | 2 | EA | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | Corridor @ Locker Rooms | 150 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Corridor @ Locker Rooms | 4 | EA | 7 | 10+ years | | | |
| | Walls - Masonry | Corridor @ Locker Rooms | 300 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Corridor @ Locker Rooms | 630 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Gym 1 Vestibule | 208 | SF | 6 | 10+ years | | | |
| | Doors - Steel Doors incl hw | Gym 1 Vestibule | 2 | EA | 6 | 10+ years | | | |
| | Floor - Terrazzo | Gym 1 Vestibule | 208 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | Gym 1 Vestibule | 2 | ĒA | 6 | 6-10 years | | | |
| | Walls - Masonry | Gym 1 Vestibule | 286 | SF | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | Gym 1 Vestibule | 250 | SF | 6 | 10+ years | | | |
| Stairs | | | | | | | | | |
| | Ceiling - Lay-in | Southeast Stairwell | 136 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Southeast Stairwell | 162 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | Southeast Stairwell | 260 | SF | 7 | 10+ years | | | |
| | Handrails | Southeast Stairwell | 123 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Southeast Stairwell | 2 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | Southeast Stairwell | 4 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | Southeast Stairwell | 352 | LF | 7 | 10+ years | | | |
| | Walls - Masonry | Southeast Stairwell | 1,004 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Southeast Stairwell | 1,507 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | Southwest Staircase | 484 | SF | 6 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Southwest Staircase | 202 | SF | 6 | 10+ years | | | |
| | Floor - Terrazzo | Southwest Staircase | 418 | SF | 7 | 10+ years | | | |
| | Handrails | Southwest Staircase | 121 | LF | 7 | 10+ years | | | |
| | Lighting - Lay-in | Southwest Staircase | 6 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | Southwest Staircase | 6 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | Southwest Staircase | 499 | LF | 7 | 10+ years | | | |
| | Walls - Masonry | Southwest Staircase | 1,085 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Southwest Staircase | 1,327 | SF | 7 | 10+ years | | | |



| Catego | Category : Site | | | uilding | | | |
|------------|-----------------------------------|-------------|----------|---------|------|--------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Civil/Drai | inage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 2 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Drain | Entire Site | 3 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 21 | EA | 6 | 10+ years | |
| Fencing | | | | | | | |
| - choing | Fencing - Chain Link | Entire Site | 115 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 79 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 6 | LF | 5 | 1-2 years | Impacted fence post |
| | Fencing - New Standard Ornamental | Entire Site | 6 | LF | 5 | 1-2 years | Impacted fence post |
| | Fencing - New Standard Ornamental | Entire Site | 6 | LF | 5 | 1-2 years | Impacted fence post |
| | Fencing - New Standard Ornamental | | 0 | LF | 5 | 1-2 years | impacted rence post |
| Landsca | pe | | | | | | |
| | Benches | Entire Site | 86 | EA | 6 | 6-10 years | |
| | Landscape - Grass | Entire Site | 132,792 | SF | 6 | 10+ years | |
| | Landscape - Grass | Entire Site | 10,000 | SF | 5 | 2-5 years | |
| | Landscape - Grass | Entire Site | 10,000 | SF | 5 | 2-5 years | |
| | Landscape - Grass | Entire Site | 10,000 | SF | 5 | 2-5 years | |
| | Landscape - Hardscape- Concrete | Entire Site | 30,747 | SF | 6 | 10+ years | |
| | Landscape - Hardscape- Concrete | Entire Site | 2,000 | SF | 4 | 1-2 years | Several walkways within the grounds are broken and require a replacement or repair |
| | Landscape - Hardscape- Concrete | Entire Site | 2,000 | SF | 4 | 1-2 years | Several walkways within the grounds are broken and require a replacemen or repair |
| | Landscape - Hardscape- Concrete | Entire Site | 2,000 | SF | 4 | 1-2 years | Several walkways within the grounds are broken and require a replacemen or repair |
| | Parkway trees | Entire Site | 52 | EA | 6 | 10+ years | • |
| | Planting Beds/ Area | Entire Site | 6,311 | SF | 4 | 1-2 years | |
| | Retaining Wall - Concrete | Entire Site | 640 | SF | 5 | 10+ years | Damage to retaining wall |
| | Trash Receptacles | Entire Site | 2 | EA | 6 | 10+ years | |
| Parking I | ot | | | | | | |
| | Concrete Curbs | Entire Site | 715 | LF | 6 | 10+ years | |
| | Surface - Asphalt | Entire Site | 12,174 | SF | 6 | 6-10 years | |
| | Surface - Asphalt | Entire Site | 1,500 | SF | 4 | 0-1 year | Several potholes throughout the asphalt areas |
| | Surface - Asphalt | Entire Site | 1,500 | SF | 4 | 0-1 year | Several potholes throughout the asphalt areas |
| | Surface - Asphalt | Entire Site | 1,500 | SF | 4 | 0-1 year | Several potholes throughout the asphalt areas |



| Catego | ry : Site | В | uilding | | | | |
|----------|--|-------------|----------|-----|------|-------------|---|
| _ | - | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Trash Compactor | Entire Site | 1 | EA | 6 | 10+ years | |
| | Trash Enclosure - Chain Links | Entire Site | 500 | SF | 5 | 1-2 years | Busted gates |
| | Trash Enclosure - Chain Links | Entire Site | 500 | SF | 5 | 1-2 years | Busted gates |
| | Trash Enclosure - Chain Links | Entire Site | 500 | SF | 5 | 1-2 years | Busted gates |
| | Trash Enclosure - Masonry | Entire Site | 486 | SF | 5 | 10+ years | |
| Sidewalk | S | | | | | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 10,924 | SF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 500 | SF | 5 | 0-1 year | Some tripping hazards in broken concrete |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 500 | SF | 5 | 0-1 year | Some tripping hazards in broken concrete |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 500 | SF | 5 | 0-1 year | Some tripping hazards in broken concrete |
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | Entire Site | 2 | EA | 7 | 10+ years | |
| | Marquee - Free Standing Back lighted w/ LED | Entire Site | 1 | EA | 7 | 10+ years | |
| | Monument - Sign | Entire Site | 3 | EA | 7 | 10+ years | Letters engraved in lime stone |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|-------------------|-------------------|---------------|---------|--------------------|---------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | • | • | | | • | | |
| Art Room | Art Room | 3rd Floor | 353/355 | 355 | 1,840 | 420 | 210 | Y | Ν |
| Art Room | Art Room | 3rd Floor | 361 | 361 | 1,584 | 108 | 54 | N | N |
| Band Room | Music Room | 4th Floor | 425 | 425 | 2,447 | 514 | 214 | Y | N |
| Band Room | Regular Classroom | 2nd Floor | 272 | 272 | 1,592 | 414 | 207 | Y | N |
| Computer Lab | Computer Lab | 3rd Floor | 326 | 326 | 1,495 | 650 | 325 | Y | N |
| Computer Lab | Computer Lab | 3rd Floor | 335 | 335 | 1,130 | 180 | 90 | Y | N |
| Computer Lab | Regular Classroom | 2nd Floor | 221 | 221 | 1,500 | 350 | 175 | Y | N |
| Computer Lab | Regular Classroom | 2nd Floor | 234 | 234 | 1,030 | 280 | 140 | Y | N |
| Computer Lab | Regular Classroom | 2nd Floor | 276 | 276 | 730 | 207 | 103 | Y | N |
| Dance Room | Regular Classroom | 1st Floor | 166 | 164/166 | 1,488 | 360 | 180 | Y | Ν |
| Faculty Lounge | Regular Classroom | 2nd Floor | 222 | 222 | 705 | 210 | 105 | Y | N |
| Music Room | Music Room | 3rd Floor | 325 | 325 | 2,395 | 550 | 150 | Y | N |
| Regular Classroom | Art Room | 3rd Floor | 351 | 351 | 920 | 210 | 105 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 162 | 162 | 730 | 207 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 172 | 172 | 678 | 120 | 60 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 174 | 174 | 528 | 120 | 60 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 176 | 176 | 730 | 207 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 219 | 1,030 | 215 | 107 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 230 | 230 | 1,145 | 280 | 140 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 233 | 233 | 1,130 | 225 | 125 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 236 | 236 | 730 | 450 | 225 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 260 | 260 | 730 | 207 | 103 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 261 | 261 | 730 | 164 | 82 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 262 | 262 | 730 | 207 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 264 | 264 | 730 | 207 | 103 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 266 | 266 | 730 | 201 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 273 | 273 | 730 | 207 | 103 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 275 | 275 | 730 | 207 | 113 | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 277 | 277 | 730 | 207 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 278 | 278 | 730 | 207 | 103 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 280 | 280 | 930 | 390 | 195 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 281 | 281 | 730 | 207 | 103 | Y | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | 319 | 1,130 | 150 | 75 | Y | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 320 | 1,050 | 140 | 35 | Y | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 322 | 730 | 210 | 105 | Y | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 328 | 328 | 730 | 210 | 105 | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 330 | 330 | 730 | 210 | 105 | Y | Ν |
| Regular Classroom | Regular Classroom | 3rd Floor | 332 | 332 | 730 | 210 | 105 | N | Ν |



Classroom Summary

| | | | Deem | Floor Plan | A | Glazed | Operable | M/indow | Creatert |
|------------------------------------|-------------------------------------|-------------------------|---------------|---------------|-------------|-------------|-------------|-----------|----------|
| Common to Upon and | | Deem Leastion | Room | Room | Area | Window | Window | Window | Smart- |
| Current Usage Regular Classroom | Intended Usage Regular Classroom | Room Location 3rd Floor | Number 334 | Number 334 | (SF) 730 | Area 300 | Area 150 | Stop Y | Board |
| | Regular Classroom | 3rd Floor | 363 | 363 | 816 | 162 | 81 | N N | N |
| Regular Classroom | | 3rd Floor 3rd Floor | 363 | 363 | 725 | 270 | 135 | N N | N N |
| Regular Classroom | Regular Classroom | 3rd Floor 3rd Floor | 367 | 367 | 725 | 126 | 63 | N N | N |
| Regular Classroom | Regular Classroom | 3rd Floor 3rd Floor | 372 | 372 | 750 | 126 | 63 | Y Y | N |
| Regular Classroom | Regular Classroom | | | | | | | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 376 | 376 | 750 | 126 | 63 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 378 | 378 | 750 | 126 | 63 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 380 | 380 | 930 | 390 | 195 | N | N |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 350 | 350 | 1,300 | 260 | 130 | Y | N |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 356 | 356 | 937 | 210 | 105 | Y | N |
| Science Lab Level 3 | Science Lab Level 3 | 3rd Floor | 352 | 352 | 990 | 280 | 140 | Y | N |
| Science Lab Level 3 | Science Lab Level 3 | 3rd Floor | 358 | 358 | 1,216 | 231 | 115 | N | N |
| Science Lab Level 3 | Science Lab Level 3 | 3rd Floor | 364 | 364 | 1,032 | 168 | 84 | N | N |
| Science Lab Level 3 | Science Lab Level 3 | 3rd Floor | 366 | 366 | 1,050 | 240 | 120 | N | N |
| Weight | Regular Classroom | 1st Floor | 158/160 | 158/160 | 1,822 | 640 | 320 | Ν | Ν |
| | | | | | | | | | |
| Building : Addition 1 | | | | 1 | | 1 | 1 | 1 | |
| Art Room | Art Room | 3rd Floor | 336 | 336 | 1,797 | 370 | 150 | N | N |
| Computer Lab | Regular Classroom | 3rd Floor | 343 East | 343 | 982 | 250 | 65 | N | N |
| Computer Lab | Regular Classroom | 3rd Floor | 343 West | 343 | 508 | 94 | 19 | N | N |
| Office | Special Program | 2nd Floor | 235 | 235 | 224 | 54 | 11 | N | N |
| Office | Special Program | 2nd Floor | 239 | 239 | 512 | 72 | 22 | N | Ν |
| Office | Special Program | 3rd Floor | 337 | 337 | 223 | 47 | 9 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 240 | 240 | 726 | 216 | 66 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 241 | 241 | 726 | 216 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 242 | 242 | 671 | 216 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 243 | 243 | 726 | 216 | 66 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 244 | 244 | 726 | 216 | 66 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 247 | 247 | 726 | 216 | 66 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 248 East | 230 (partial) | 658 | 162 | 44 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 249 | 249 | 816 | 216 | 66 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 340 | 340 | 1,085 | 250 | 65 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 344 | 344 | 1,122 | 282 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 346 East | 346 (Partial) | 718 | 188 | 56 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 347 | 347 | 743 | 188 | 56 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 348 | 348 | 1,200 | 282 | 84 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 349 | 349 | 816 | 188 | 56 | N | N |
| Special Program | Regular Classroom | 2nd Floor | 246 East | 248 | 594 | 180 | 55 | N | Ν |
| Special Program | Special Program | 2nd Floor | 245 | 245 | 367 | 108 | 33 | N | Ν |
| Special Program | Special Program | 2nd Floor | 248 West | 230 (partial) | 490 | 126 | 33 | N | N |
| Special Program | Special Program | 3rd Floor | 345 | 345 | 367 | 78 | 19 | N | Ν |



Classroom Summary

Floor Plan Glazed Operable Window Room Room Area Window Window Smart-**Current Usage** Intended Usage Room Location Number Number (SF) Area Area Stop Board Special Program Store Room 1st Floor **186 ROTC** 186 497 0 0 Ν Ν Store Room Computer Lab 2nd Floor 246 West 246 490 108 22 Ν Ν 146 214 60 Ν Store Room Special Program 1st Floor 146 596 Ν Special Program 1st Floor 149 149 1,332 384 108 Store Room Ν Ν Store Room Special Program 3rd Floor 346 West 346 (Partial) 94 28 Ν 470 Ν **Building : Addition 2** Office Other Instructional Use 2nd Floor 213 213 510 72 22 Ν Ν Office Other Instructional Use 3rd Floor 315 315 490 62 18 Ν Ν Office Other Instructional Use 3rd Floor 317 317 148 62 18 Ν Ν Other Instructional Use 2nd Floor 217 217 152 72 22 Office Ν Ν Other Instructional Use 2nd Floor 205 205 108 33 Ν Other Instructional Use 358 Ν Other Instructional Use Other Instructional Use 3rd Floor 305 305 368 94 28 Ν Ν Regular Classroom Regular Classroom 1st Floor 796 256 72 Ν 101 101 Ν Regular Classroom Regular Classroom 2nd Floor 200 200 796 216 66 Ν Ν Regular Classroom 2nd Floor **Regular Classroom** 201 201 796 216 44 Ν Ν Regular Classroom **Regular Classroom** 2nd Floor 202 726 216 66 Ν 202 Ν **Regular Classroom Regular Classroom** 2nd Floor 203 203 726 216 66 Ν Ν **Regular Classroom** Regular Classroom 2nd Floor 204 204 726 216 66 Ν Ν **Regular Classroom** Regular Classroom 2nd Floor 206 206 726 216 66 Ν Ν Regular Classroom Regular Classroom 2nd Floor 207 207 726 216 Ν Ν 66 Regular Classroom Regular Classroom 2nd Floor 208 208 726 216 66 Ν Ν Regular Classroom Regular Classroom 2nd Floor 216 55 209 209 726 Ν Ν Regular Classroom 2nd Floor 216 66 Ν Regular Classroom 210 210 726 Ν Regular Classroom 3rd Floor 300 300 825 188 56 Ν Ν **Regular Classroom** Regular Classroom Regular Classroom 3rd Floor 301 825 188 37 301 Ν Ν Regular Classroom Regular Classroom 3rd Floor 303 303 750 188 56 Ν Ν Regular Classroom Regular Classroom 3rd Floor 307 307 750 188 56 Ν Ν Regular Classroom Regular Classroom 3rd Floor 309 309 750 188 56 Ν Ν Science Lab Level 1 Regular Classroom 1st Floor 100 100 1,314 427 120 Ν Ν Ν Science Lab Level 2 Regular Classroom 1st Floor 105 105 1.124 384 108 Ν Science Lab Level 2 **Regular Classroom** 1st Floor 106 106 1.232 427 120 Ν Ν Science Lab Level 2 Regular Classroom 1st Floor 110 110 + 108 1.472 512 132 Ν Ν 3rd Floor Ν Science Lab Level 2 Regular Classroom 306 306 1.228 312 93 Ν Science Lab Level 2 Regular Classroom 3rd Floor 310 310 1,136 312 93 Ν Ν 3rd Floor Science Lab Level 3 Regular Classroom 302 302 786 188 56 Ν Ν 72 Regular Classroom 1st Floor 103 103 750 256 Ν Ν Store Room