



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1951 | 2 | 32,352 |
| Addition | 1955 | 2 | 19,885 |
| Campus Total | | | 52,237 |

| Catego | Category : Exterior | | | Building : Main | | | |
|-----------|---------------------------------------|-----------------|----------|-----------------|------|--------------------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| _Entrance | | | | | | | |
| | Entrance Control - Audio and Video | 1 - Main | 1 | EΑ | 7 | 6-10 years | |
| | Exterior Doors - Store Front | 1 - Main | 2 | EΑ | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 1 - Main | 10 | LF | 7 | 10+ years | |
| | Exterior Stairs - Stone | 1 - Main | 50 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 2 | 2 | EΑ | 7 | 10+ years | |
| | Exterior Stairs - Stone | 2 | 150 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 3.1 | 2 | EΑ | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 3.1 | 10 | LF | 7 | 10+ years | |
| | Exterior Stairs - Stone | 3.1 | 50 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 4 | 1 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 4 | 56 | LF | 7 | 10+ years | |
| | Entrance Control - Audio and Video | 5 | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 5 | 2 | EA | 7 | 10+ years | |
| | Exterior Stairs - Concrete | 5 | 72 | LF | 7 | 10+ years | |
| | Power Door Operator and Controls | 5 | 1 | EΑ | 7 | 6-10 years | |
| | Ramp Handrail - Steel_Ramp Handrail | 5 | 200 | LF | 7 | 10+ years | |
| | Ramps - Concrete | 5 | 100 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | 5 | 67 | LF | 7 | 10+ years | |
| Foundati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 585 | LF | 7 | 10+ years | |
| | Superstructure - Concrete | Entire Building | 32,352 | SF | 7 | 10+ years | |



| Category : Exterior | | | В | | | | |
|---------------------|---|-----------------|----------------|-----------|--------|-------------|------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 8 | EA | 7 | 6-10 years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 8 | EA | 6 | 2-5 years | |
| D (0 | | | | | | | |
| Roof Sys | | | | | | | |
| | Coping - Stone | A | 60 | LF . – | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | A | 4 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | A | 60 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | A | 225 | SF | 5 | 1-2 years | Bubbling, cracking, and open seams |
| | Roof Structure - Steel with Clay Tile Arch | A | 225 | SF | 7 | 10+ years | |
| | Coping - Stone | В | 278 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | В | 105 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | В | 278 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | В | 9,834 | SF | 5 | 1-2 years | Cracking. |
| | Roof Structure - Steel with Clay Tile Arch | В | 9,834 | SF | 7 | 10+ years | |
| | Coping - Stone | С | 60 | LF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts | С | 4 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | С | 60 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | С | 225 | SF | 5 | 1-2 years | Cracking. |
| | Roof Structure - Steel with Clay Tile Arch | С | 225 | SF | 7 | 10+ years | - |
| | Coping - Stone | D | 37 | LF | 5 | 10+ years | |
| | Downspouts - Interior Downspouts | D | 26 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | D | 37 | LF | 5 | 2-5 years | |
| | Roof - Modified Bitumen | D | 336 | SF | 5 | 1-2 years | Cracking. |
| | Roof Structure - Steel with Clay Tile Arch | D | 336 | SF | 7 | 10+ years | 3 |
| | Access Ladder - Metal | Ē | 1 | ĒΑ | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Ē | 40 | LF | 7 | 10+ years | |
| | Liner | _ | .0 | | • | ioi youlo | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Е | 30 | LF | 7 | 10+ years | |
| | Liner | _ | 30 | | , | 101 years | |
| | Coping - Stone | Е | 194 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Ē | 54 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | E | 194 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | E | 3,654 | SF | 5 | 1-2 years | Bubbling and cracking. |
| | Roof Structure - Steel with Clay Tile Arch | E E | 3,654 3,654 | SF SF | 5 7 | | Bubbling and cracking. |
| | Roof Structure - Steel with Clay Tile Arch | E | 3,004 | SF | , | 10+ years | |
| Walls | | | | | | | |
| | Cheek-Wall - Concrete | Entire Building | 540 | SF | 7 | 10+ years | |
| | Cheek-Wall - Stone | Entire Building | 220 | SF | 6 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 15,006 | SF | 7 | 10+ years | |
| | Exterior Walls - Prefabricated Metal Panel | Entire Building | 245 | SF | 7 | 10+ years | |
| | Wall | - | | | | • | |
| | Exterior Walls - Prefabricated Metal Panel | Entire Building | 49 | SF | 6 | 10+ years | |



| XII H | schools | | | | | | 245 W 57th STREET, Chicago, IL 606 |
|----------------|---|-----------------|----------|-------------|--------|-------------|------------------------------------|
| Catego | ry : Exterior | | В | uilding | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Wall | | | | | | |
| | Exterior Walls - Stone-Cut | Entire Building | 1,860 | SF | 7 | 10+ years | |
| | | | | | | | |
| Nindows | 3 | | | | | | |
| | Guard - Guards perforated | Entire Building | 1,663 | SF | 7 | 10+ years | |
| | Lintels - Concrete | Entire Building | 17 | LF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 260 | LF | 6 | 10+ years | |
| | Lintels - Stone | Entire Building | 187 | LF | 5 | 6-10 years | |
| | Skylite - Glass Single-Pane | Entire Building | 72 | SF | 5 | 2-5 years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 3,875 | SF | 6 | 10+ years | |
| | | 3 | -,- | | | , , , , , , | |
| Catego | ry : Electrical | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| merger | ncy System | | | | | | |
| Ū | Automatic Transfer Switch | Basement | 1 | EA | 6 | 10+ years | |
| | Emergency A/C Power - Corridors and | Entire Building | 5,020 | SF | 6 | 6-10 years | |
| | Stairs | 3 | , | | | , | |
| | Emergency A/C Power - Gym | Entire Building | 2,425 | SF | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 10 | EA | 2 | 0-1 year | No battery back-up or generator. |
| | | J | | | | • | Difficult to read. Older. |
| | Exit Signs - Gym | Entire Building | 3 | EA | 2 | 0-1 year | No battery back-up or generator. |
| | , | · · | | | | • | Difficult to read. Older. |
| | Security System - CCTV | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | | <u> </u> | , | | | • | |
| /lain Se | rvice | | | | | | |
| | Main Electrical Service - 1600 A | Basement | 1 | EA | 6 | 10+ years | Serves both buildings |
| | 120/208/3PH | | | | | · | G |
| | Independent Electrical Service for | Entire Building | 1 | EA | 6 | 10+ years | |
| | emergency power | 3 | | | | , , , , , | |
| | PA System | Entire Building | 32,352 | SF | 6 | 6-10 years | Serves both buildings |
| | • | <u> </u> | , | | | • | ŭ |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 4 | 0-1 year | Live front |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 4 | 0-1 year | Live front |
| | 5 · · · · · · · · · · · · · · · · · · · | ···········9 | Ü | - · | • | - , , | |
| | | | | | | | |



| Catego | ry : Fire Protection | | В | uilding | : Main | | 245 W 57(II STREET, Chicago, IL 6062 |
|------------|---|---------------------------|----------|---------|--------|-------------|--------------------------------------|
| | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | m | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 2-5 years | Serves both buildings |
| | Fire Alarm Strobe Lights | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| 20.10 9 0 | . , | | _ | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ir Hand | lling Systems | | | | | | |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm | Air Tunnel | 1 | EA | 5 | 6-10 years | |
| | Air Intake | Air Tunnel | 1 | EA | 6 | 6-10 years | |
| | Auxiliaries - 15001 - 25000 cfm | Air Tunnel | 1 | EA | 5 | 6-10 years | Filters missing, fan motor aged. |
| | Reheat Boxes - Reheat Boxes with Steam | Air Tunnel | 7 | EA | 5 | 6-10 years | r mers missing, fair motor agea. |
| | Coil | 7 III Turner | , | | J | o ro years | |
| | Return Duct Work - Masonry and Ducts- | Air Tunnel | 100 | LF | 5 | 6-10 years | |
| | Missing or Existing Shaft | | | | | | |
| | Zone Dampers | Air Tunnel | 19 | EA | 5 | 6-10 years | Manually controlled |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Attic | 1 | EA | 5 | 2-5 years | |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm | Mechanical Room above Gym | 1 | EA | 5 | 2-5 years | |
| | Air Intake | Mechanical Room above Gym | 1 | EA | 6 | 6-10 years | |
| Boiler Sy | votomo | | | | | | |
| oller Sy | | Doiler Doom | 2 | ГΛ | 6 | 6.10 vooro | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | 6-10 years | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Chemical Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EΑ | 6 | 6-10 years | Minor corrosion present at edges of |
| | | | _ | | • | - 1- , | blades |
| | Condensate Pump | Boiler Room | 1 | EA | 4 | 0-1 year | Significant corrosion and tank is |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | 6-10 years | leaking |
| | Non Condensing- Fire Tube- Scotch Marine- | Boiler Room Boiler Room | 2 | | 6 | 6-10 years | Sorves both buildings |
| | Steam- Low Pressure Boiler - 101 - 150 HP | Doller Kooffi | 2 | EA | 6 | 6-10 years | Serves both buildings |
| | Piping - Condensate Pipe- Steel | Boiler Room | 500 | LF | 5 | 6-10 years | Insulation at boilers damaged |
| | Piping - Steam Pipe- Steel | Boiler Room | 500 | LF | 6 | 6-10 years | 3 |
| | Steam Traps | Boiler Room | 17 | ĒA | 4 | 1-2 years | Bad traps |
| | | | | | | | |
| Heating I | Devices | | | | | | |
| -leating l | Devices Wall Heater - Electric | Entire Building | 1 | EA | 7 | 10+ years | |



| Catego | ry : Mechanical | | В | uilding | : Main | | |
|------------|--|-----------------|----------|---------|--------|--------------------------|-----------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | Radiators - Steam | Entire Building | 11 | EA | 6 | 6-10 years | |
| | Fin Tube - Steam | Entire Building | 20 | LF | 6 | 6-10 years | Enclosure in restroom missing enc |
| | Cabinet Heaters - With Steam Coil | Entire Building | 4 | EA | 5 | 6-10 years | |
| empera | nture Control | | | | | | |
| | Pneumatic System | Entire Building | 32,352 | SF | 3 | 0-1 year | Compressor is out of service |
| | Thermostats - Pneumatic | Entire Building | 20 | EA | 4 | 0-1 year | System not working |
| entilation | on | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 1 | EA | 5 | 2-5 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 3 | 0-1 year | No cover, no belt |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| | • | | | J | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| lot Wate | er | | • | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Basement | 1 | EA | 7 | 10+ years | Serves Main Building. |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water Risers | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 32,352 | SF | 3 | 0-1 year | HW piping leaks |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Sanitary Piping | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Storm Piping | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| | Vent Piping | Entire Building | 32,352 | SF | 6 | 6-10 years | |
| umps | | | | | | | |
| • | Pumps - Sump-Duplex | Basement | 1 | EA | 6 | 6-10 years | |
| Catego | ry : Room | | В | uilding | : Main | _ | |
| | | | | | | Recommend | • |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement **Comments** AC Unit 101 - Office EΑ 6-10 years 7 269 SF 7 Ceiling - Plaster/Drywall 101 - Office 10+ years Ceiling - Plaster/Drywall 101 - Office 30 SF 6 10+ years Doors - Wood Doors inclu hw 3 EΑ 7 101 - Office 10+ years SF Floor - Carpet 101 - Office 179 7 6-10 years SF Floor - Carpet 101 - Office 4 0-1 year Torn 1 Floor - Tile 101 - Office SF 7 144 10+ years Lighting - Pendent/Surface 101 - Office 6 EΑ 7 10+ years **Power Distribution** 101 - Office 6 EΑ 7 10+ years SF Storage/ Closet 101 - Office 10 7 10+ years Walls - Plaster/Drvwall SF 101 - Office 864 7 10+ years Ceiling - Plaster/Drywall 103 - Waiting Area 72 SF 7 10+ years Doors - Transom Window 103 - Waiting Area 9 SF 7 10+ years 7 Doors - Wood Doors inclu hw 103 - Waiting Area 1 EΑ 10+ years Floor - Tile 103 - Waiting Area 72 SF 7 10+ years Lighting - Pendent/Surface 103 - Waiting Area EΑ 7 1 10+ years Walls - Plaster/Drywall SF 7 103 - Waiting Area 340 10+ years SF Ceiling - Plaster/Drywall 103A - Office 126 7 10+ years Doors - Side-lite SF 103A - Office 12 7 10+ vears SF Doors - Transom Window 103A - Office 18 7 10+ years Doors - Wood Doors inclu hw 103A - Office 1 EΑ 7 10+ years SF 7 Floor - Tile 103A - Office 126 10+ years 7 Lighting - Pendent/Surface 103A - Office 2 EΑ 10+ years 2 7 Power Distribution 103A - Office FΑ 10+ years Walls - Plaster/Drywall 103A - Office 552 SF 7 10+ years Work SInk 103A - Office 1 EΑ 7 10+ years Ceiling - Plaster/Drywall SF 103B - Office 186 7 10+ years Doors - Transom Window 103B - Office 9 SF 7 10+ years 2 Doors - Wood Doors inclu hw 103B - Office EΑ 7 10+ years Floor - Tile 103B - Office 186 SF 7 10+ years Lighting - Pendent/Surface 103B - Office 3 EΑ 7 10+ years Power Distribution 103B - Office 4 EΑ 7 10+ years SF 7 Walls - Plaster/Drywall 103B - Office 795 10+ years Walls - Plaster/Drywall 103B - Office 45 SF 6 10+ years 375 SF 7 Ceiling - Plaster/Drywall 200 - Special Education 10+ years Doors - Transom Window SF 7 200 - Special Education 9 10+ years Doors - Wood Doors inclu hw 200 - Special Education 1 EΑ 7 10+ years Floor - Tile SF 200 - Special Education 367 7 10+ years SF Floor - Tile 200 - Special Education 8 4 0-1 year Chipped Lighting - Pendent/Surface 7 200 - Special Education 4 EΑ 10+ years Power Distribution 200 - Special Education 8 EΑ 7 10+ years SF 7 Storage/ Closet 200 - Special Education 4 10+ years Walls - Plaster/Drywall 200 - Special Education 984 SF 7 10+ years Ceiling - Plaster/Drywall SF 202 - Office 169 7 10+ years





| | ry : Room | | R | uilding | : Main | | 245 W 37111 STREET, CHICAGO, IL 00021 |
|----------|--------------------------------|------------------------------|----------|------------|--------|-------------|---------------------------------------|
| Julogo | ., | | | a.i.aiii.g | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _ | Doors - Transom Window | 202 - Office | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 202 - Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 202 - Office | 169 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 202 - Office | 2 | EA | 7 | 10+ years | |
| | Power Distribution | 202 - Office | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 202 - Office | 624 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Engineer's Office - Basement | 156 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Office - Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | Engineer's Office - Basement | 156 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Engineer's Office - Basement | 2 | EA | 7 | 10+ years | |
| | Power Distribution | Engineer's Office - Basement | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Engineer's Office - Basement | 500 | SF | 7 | 10+ years | |
| | AC Unit | Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Principal's Office | 154 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | Principal's Office | 154 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Principal's Office | 3 | EA | 7 | 10+ years | |
| | Power Distribution | Principal's Office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Office | 600 | SF | 7 | 10+ years | |
| _Gvmnas | ia | | | | | | |
| _Оуппаз | Ceiling - Plaster/Drywall | 1st Floor | 2,350 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 50 | SF | 5 | 1-2 years | Water damage. |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | Water damage. |
| | Doors - Wood Doors inclu hw | 1st Floor | 6 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 2,392 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 8 | SF | 4 | 0-1 year | Chipped |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 10+ years | 0pp00 |
| | Stage | 1st Floor | 600 | SF | 7 | 10+ years | |
| | Stage Curtain | 1st Floor | 10 | EΑ | 7 | 10+ years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Stage-Stairs - Asphalt | 1st Floor | 20 | LF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 3,760 | SF | 7 | 10+ years | |
| | | | | | | | |
| _MDF_ID | | | | | | 4.0 | |
| | Doors - Side-lite | Access through 202 | 1 | SF | 6 | 10+ years | |
| | Finishes | Access through 202 | 440 | SF | 7 | 10+ years | |
| | Window AC Unit | Access through 202 | 1 | EA | 7 | 6-10 years | |
| _Mechani | ical/ Service Rooms | | | | | | |
| | Air Tunnel | Sherwood Main | 1,836 | SF | 7 | 10+ years | |
| | Boiler Room | Sherwood Main | 851 | SF | 5 | 10+ years | |
| | Coal Room | Sherwood Main | 450 | SF | 7 | 10+ years | |
| | | | | | | | |



| Ja Ja M M M St St | em - Type unitor's Closet | Location | | uilding | | Decemmend | |
|-------------------------------------|--------------------------------|--------------------------|----------|----------|------|-------------|--|
| Ja Ja M M M St St | initor's Closet | Location | | | | Recommend | |
| Ja M M M St St | | | Quantity | UOM | Rank | Replacement | Comments |
| M M M St St | | Sherwood Main | 35 | SF | 7 | 10+ years | |
| M M St St | initor's Closet | Sherwood Main | 35 | SF | 7 | 10+ years | |
| M St St | echanical/ Service Rooms | Sherwood Main | 191 | SF | 7 | 10+ years | Electrical Room |
| St St | echanical/ Service Rooms | Sherwood Main | 800 | SF | 7 | 10+ years | Fan Room |
| St | echanical/ Service Rooms | Sherwood Main | 190 | SF | 5 | 10+ years | Pump Room |
| St | orage Room | Sherwood Main | 291 | SF | 7 | 10+ years | • |
| | orage Room | Sherwood Main | 78 | SF | 7 | 10+ years | |
| | orage Room | Sherwood Main | 69 | SF | 5 | 10+ years | Near Gymnasium outside entrance - large paint chipping |
| Restroom | | | | | | | |
| | ccessories | 102A (104 on floor plan) | 93 | SF | 7 | 6-10 years | |
| | eiling - Lay-in | 102A (104 on floor plan) | 93 | SF | 7 | 10+ years | |
| | oors - Wood Doors inclu hw | 102A (104 on floor plan) | 2 | EA | 7 | 10+ years | |
| FI | oor - Tile Ceramic/ Porcelain | 102A (104 on floor plan) | 93 | SF | 7 | 6-10 years | |
| FI | oor Drain | 102A (104 on floor plan) | 1 | EA | 7 | 10+ years | |
| Ha | and Dryer | 102A (104 on floor plan) | 1 | EA | 7 | 10+ years | |
| La | avatory | 102A (104 on floor plan) | 1 | EA | 7 | 10+ years | |
| Li | ghting - Lay-in | 102A (104 on floor plan) | 1 | EA | 7 | 6-10 years | |
| | alls - Plaster/Drywall | 102A (104 on floor plan) | 120 | SF | 7 | 10+ years | |
| | alls - Tile Ceramic/ Porcelain | 102A (104 on floor plan) | 200 | SF | 7 | 10+ years | |
| W | ater Closet | 102A (104 on floor plan) | 1 | EA | 7 | 10+ years | |
| | ccessories | 105 | 36 | SF | 7 | 6-10 years | |
| Ce | eiling - Plaster/Drywall | 105 | 36 | SF | 7 | 10+ years | |
| Do | oors - Wood Doors inclu hw | 105 | 1 | ĒΑ | 6 | 10+ years | |
| | oor - Tile Ceramic/ Porcelain | 105 | 36 | SF | 7 | 10+ years | |
| | avatory | 105 | 1 | EA | 7 | 10+ years | |
| | ghting - Pendent/Surface | 105 | 1 | EA | 7 | 6-10 years | |
| | alls - Plaster/Drywall | 105 | 208 | SF | 7 | 10+ years | |
| | ater Closet | 105 | 1 | EA | 7 | 10+ years | |
| | ccessories | 1st Floor | 262 | SF | 7 | 6-10 years | |
| | eiling - Plaster/Drywall | 1st Floor | 252 | SF | 7 | 10+ years | |
| | eiling - Plaster/Drywall | 1st Floor | 10 | SF | 6 | • | |
| | | | | SF SF | | 10+ years | |
| | oor - Tile Ceramic/ Porcelain | 1st Floor | 256 | | 7 | 10+ years | One alice of |
| | oor - Tile Ceramic/ Porcelain | 1st Floor | 6 | SF | 4 | 1-2 years | Cracking |
| | oor Drain | 1st Floor | 1 | EΑ | 7 | 10+ years | |
| | avatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | ghting - Pendent/Surface | 1st Floor | 4 | EΑ | 7 | 10+ years | |
| | artitions | 1st Floor | 2 | EA | 5 | 6-10 years | |
| | rinals | 1st Floor | 4 | EA | 7 | 10+ years | |
| | alls - Concrete Block | 1st Floor | 108 | SF | 7 | 10+ years | |
| | alls - Structural Glazed Tile | 1st Floor | 627 | SF | 7 | 10+ years | |
| W | ater Closet | 1st Floor | 2 | EA | 7 | 10+ years | |
| Ad | ccessories | 1st Floor | 262 | SF | 7 | 6-10 years | |

Campus Name: Sherwood Page: 8 of 28 Assessment Date: 05/12/2020







Walls - Plaster/Drywall

Category: Room **Building: Main** Recommend Location Group Item - Type Quantity **UOM** Rank Replacement **Comments** Ceiling - Plaster/Drywall 1st Floor 252 SF 10+ vears 7 Ceiling - Plaster/Drywall 1st Floor SF 0-1 year 10 4 Water damage Floor - Tile Ceramic/ Porcelain 1st Floor 262 SF 7 10+ years Floor Drain EΑ 7 1st Floor 1 10+ years 2 7 Hand Dryer 1st Floor EΑ 6-10 years 2 7 Lavatory 1st Floor EΑ 10+ years Lighting - Pendent/Surface 1st Floor 4 EΑ 7 10+ years 5 **Partitions** 1st Floor EΑ 5 6-10 years Walls - Concrete Block 1st Floor 108 SF 7 10+ years SF Walls - Plaster/Drywall 1st Floor 162 7 10+ vears SF Walls - Structural Glazed Tile 1st Floor 465 7 10+ vears Water Closet 1st Floor 5 EΑ 7 10+ years Accessories 2nd Floor 262 SF 7 6-10 years SF 7 Ceiling - Plaster/Drywall 2nd Floor 262 10+ years Floor - Tile Ceramic/ Porcelain SF 7 2nd Floor 262 10+ years Floor Drain FΑ 7 2nd Floor 1 10+ years Hand Drver 2 7 2nd Floor EΑ 6-10 years Lavatory 2nd Floor 2 EΑ 7 10+ years Lighting - Pendent/Surface 4 2nd Floor EΑ 7 10+ vears 5 **Partitions** 2nd Floor EΑ 5 6-10 years Walls - Concrete Block 2nd Floor 108 SF 7 10+ years SF 7 Walls - Plaster/Drywall 2nd Floor 162 10+ years SF Walls - Structural Glazed Tile 7 2nd Floor 465 10+ years 7 Water Closet 2nd Floor 5 FΑ 10+ years Accessories SF 7 6-10 years 2nd Floor 262 Ceiling - Plaster/Drywall SF 2nd Floor 252 7 10+ years Ceiling - Plaster/Drywall SF 2nd Floor 10 4 0-1 year Water damage SF Floor - Tile Ceramic/ Porcelain 2nd Floor 262 7 10+ years EΑ Floor Drain 2nd Floor 1 7 10+ years Lavatory 2nd Floor 2 EΑ 7 10+ years Lighting - Pendent/Surface 2nd Floor 4 EΑ 7 10+ vears **Partitions** 2nd Floor 2 EΑ 5 6-10 years 7 Urinals 2nd Floor 4 FΑ 10+ years Walls - Concrete Block 2nd Floor 108 SF 7 10+ years SF 7 Walls - Structural Glazed Tile 2nd Floor 627 10+ years 2nd Floor EΑ 7 Water Closet 2 10+ years Engineer Restroom - Basement SF Accessories 36 5 6-10 years Ceiling - Plaster/Drywall Engineer Restroom - Basement SF 7 36 10+ years Doors - Wood Doors inclu hw Engineer Restroom - Basement 1 EΑ 7 10+ years Floor - Tile SF Engineer Restroom - Basement 26 6 10+ years SF Floor - Tile Engineer Restroom - Basement 10 4 0-1 year Chipped Engineer Restroom - Basement FΑ 6 1 10+ years Lavatory Lighting - Pendent/Surface Engineer Restroom - Basement EΑ 7 10+ years

SF

10+ years

240

Engineer Restroom - Basement





| Catego | ry : Room | | Building : Main | | | | | | |
|--------|---------------------------------|------------------------------|-----------------|-----|------|--------------------------|----------|--|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | | |
| Jioup | Water Closet | Engineer Restroom - Basement | Quantity 1 | EA | 7 | 10+ years | Comments | | |
| | Accessories | In Principal's Office | 32 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | In Principal's Office | 32 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Principal's Office | 1 | ĒΑ | 7 | 10+ years | | | |
| | Floor - Carpet | In Principal's Office | 32 | SF | 7 | 6-10 years | | | |
| | Lavatory | In Principal's Office | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | In Principal's Office | 1 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | In Principal's Office | 192 | SF | 7 | 10+ years | | | |
| | Water Closet | In Principal's Office | 1 | EΑ | 7 | 10+ years | | | |
| | Accessories | In Room 103 | 32 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | In Room 103 | 32 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | In Room 103 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | In Room 103 | 32 | SF | 7 | 10+ years | | | |
| | Lavatory | In Room 103 | 1 | EA | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | In Room 103 | 1 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | In Room 103 | 192 | SF | 7 | 10+ years | | | |
| | Water Closet | In Room 103 | 1 | EA | 7 | 10+ years | | | |

Category : Classroom **Building: Main**

| | ., | | | _ | | Recommend | |
|----------|-----------------------------|-----------|----------|-----|------|-------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroc | om #102 (Pre School) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 992 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 992 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 90 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,704 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroc | om #104 (Pre School) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 750 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | |



| Catego | ory : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,320 | SF | 7 | 10+ years | |
| Classro | om #105 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 36 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,114 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | EΑ | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 1,114 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 35 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 70 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,936 | SF | 6 | 10+ years | |
| _Classro | om #106 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 750 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,320 | SF | 6 | 10+ years | |
| _Classro | om #107 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 750 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 32 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 1st Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,320 | SF | 7 | 10+ years | |
| Classro | om #201 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | | | | | | | |



| Category : Classroom Building : | | | | : Main | | | |
|---------------------------------|-----------------------------|-----------|----------|--------|------|-------------|-------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 34 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 750 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 7 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | m #202 (Science Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 50 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 745 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 5 | SF | 4 | 0-1 year | Chipped tile |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 6 | 6-10 years | - P1 |
| | Marker Board | 2nd Floor | 7 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 100 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| _Classroo | m #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 34 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 4 | 0-1 year | New window needed |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 6 | 10+ years | |
| Classroo | m #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 740 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 10 | SF | 4 | 1-2 years | Water damage |
| | Chalk Board | 2nd Floor | 34 | LF | 4 | 2-5 years | |
| | | | • | | - | , | |





| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-------------|----------|---------|--------|-------------|------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 6 | 10+ years | |
| | Trans Tractor, 21, Trans | 2110 1 1001 | 1,020 | O. | ŭ | ioi youlo | |
| Classroc | om #205 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 36 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,315 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 5 | SF | 5 | 1-2 years | Wall Crack |
| | • | | | | | , | |
| Classroc | om #206 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 34 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Wood | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 7 | 10+ years | |
| Naa | 1907 (Decules Ol | | | | | | |
| Jassroc | om #207 (Regular Classroom) | 0 - d El- | | | | 0.40 | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 30 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Wood | 2nd Floor | 750 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | 6-10 years | |







| Catego | ory : Classroom | | R | uilding | · Main | | 240 W 37th 011(E11, Officago, 1E 00021 |
|-----------|---------------------------------------|---|----------|----------|---------|--------------|--|
| Catego | i y . Olassi oom | | | ununig | . Walli | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Oroup | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | Comments |
| | Storage/ Closet | 2nd Floor | 10 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,320 | SF | 7 | 10+ years | |
| | Walls - I laster/Drywall | 2110 1 1001 | 1,320 | OI. | , | 10+ years | |
| Catego | ory : Interior | | R | uilding | · Main | | |
| Catego | i i i i i i i i i i i i i i i i i i i | | | ununig | . Walli | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | | Location | Quantity | OOM | Italiit | rtopiacoment | |
| _Corridor | | First Floor Wortibules | 050 | 0.5 | 7 | 40 | |
| | Ceiling - Plaster/Drywall | First Floor Vestibules | 252 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | First Floor Vestibules | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | First Floor Vestibules | 252 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | First Floor Vestibules | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | First Floor Vestibules | 162 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | First Floor Vestibules | 270 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | First floor corridors | 2,128 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | First floor corridors | 2 | EA | 6 | 10+ years | |
| | Doors - Wood Doors include hw | First floor corridors | 9 | EA | 7 | 10+ years | |
| | Drinking Fountains - Double Fountain | First floor corridors | 2 | EΑ | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | First floor corridors | 2 | EΑ | 7 | 10+ years | |
| | Floor - Tile/Sheet | First floor corridors | 2,128 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | First floor corridors | 25 | EΑ | 7 | 6-10 years | |
| | Student Lockers - One Tier | First floor corridors | 103 | EΑ | 6 | 10+ years | |
| | Walls - Plaster/Drywall | First floor corridors | 2,275 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | First floor corridors | 1,925 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Gym Vestibule - First Floor | 200 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Gym Vestibule - First Floor | 200 | SF | 7 | 10+ years | |
| | Doors - Wood Doors include hw | Gym Vestibule - First Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Gym Vestibule - First Floor | 200 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Gym Vestibule - First Floor | 3 | EΑ | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Gym Vestibule - First Floor | 1,400 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Second Floor Corridors | 2,128 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Second Floor Corridors | 4 | EA | 7 | 10+ years | |
| | Doors - Wood Doors include hw | Second Floor Corridors | 3 | EA | 7 | 10+ years | |
| | Drinking Fountains - Double Fountain | Second Floor Corridors | 2 | EA | 7 | 10+ years | |
| | Drinking Fountains - Single Fountain | Second Floor Corridors | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Second Floor Corridors | 2,128 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Second Floor Corridors | 2,120 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | Second Floor Corridors | 103 | EA | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Second Floor Corridors Second Floor Corridors | 2,275 | SF | 7 | | |
| | | | | SF SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Second Floor Corridors | 1,925 | SF | / | 10+ years | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 4 | ΕA | 7 | 6-10 years | |
| | | | • | | • | , | |

Campus Name: Sherwood Page : 14 of 28 Assessment Date: 05/12/2020



| atego | ry : Interior | | В | uilding | : Main | | |
|-------|--------------------------------|-----------------|----------|---------|--------|--------------------------|----------------|
| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| tairs | | | | | | | |
| | Ceiling - Plaster/Drywall | Basement Stairs | 62 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement Stairs | 10 | SF | 4 | 0-1 year | Large cracking |
| | Floor - Concrete | Basement Stairs | 20 | SF | 7 | 10+ years | |
| | Handrails | Basement Stairs | 50 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement Stairs | 1 | EA | 7 | 10+ years | |
| | Stairs - Concrete | Basement Stairs | 68 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement Stairs | 1,056 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Main entrance | 560 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Main entrance | 510 | SF | 7 | 10+ years | |
| | Handrails | Main entrance | 35 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Main entrance | 6 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Main entrance | 144 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Main entrance | 280 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Main entrance | 1,064 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | east | 560 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | east | 510 | SF | 7 | 10+ years | |
| | Handrails | east | 35 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | east | 6 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | east | 144 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | east | 280 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | east | 1,064 | SF | 7 | 10+ years | |



| Category : Exterior | | | В | uilding | on | | |
|---------------------|---|---------------------------------|----------|----------|-----------|--------------------------|----------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | Entrance Control - Audio and Video | 2 | 4 | EA | 7 | C 10 | |
| | Exterior Doors - Exterior Steel Door | 3 | 1 2 | EA EA | 7 7 | 6-10 years 10+ years | |
| | Exterior Stairs - Stone | 3 | 6 | LF | 7 | 10+ years | |
| | Exterior Stairs - Storie | 3 | U | LIT | , | 10+ years | |
| Foundati | on | | | | | | |
| | Foundation - Concrete | Entire Building | 473 | LF | 7 | 10+ years | |
| | Superstructure - Concrete | Entire Building | 19,885 | SF | 7 | 10+ years | |
| iahtina | | | | | | | |
| _ighting | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 10 | EA | 7 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 2 | EA | 7 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Littile ballaring | 2 | LA | , | 10+ years | |
| Roof Sys | stem | | | | | | |
| | Access Ladder - Metal | F | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | F | 380 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | F | 75 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | F | 380 | LF | 7 | 10+ years | |
| | Roof - Modified Bitumen | F | 8,466 | SF | 5 | 1-2 years | Cracking throughout. |
| | Roof Hatch - Metal | F | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ | F | 8,466 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 10,150 | SF | 7 | 10+ years | |
| | Exterior Walls - Stone-Cut | Entire Building | 1,700 | SF | 7 | 10+ years | |
| | | | | | | | |
| Windows | Lintels - Steel | Entire Building | 182 | LF | 7 | 10 | |
| | | Entire Building Entire Building | 172 | LF | 7 | 10+ years | |
| | Lintels - Stone | | | SF | 7 | 10+ years | |
| | Storefront Windows | Entire Building | 1,485 | SF SF | 7 7 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 3,118 | SF | , | 10+ years | |
| Catego | ry : Electrical | | В | uilding | : Additio | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| _ | ncy System | | | | | | |
| | Emergency A/C Power - Corridors and | Entire Building | 3,127 | SF | 6 | 6-10 years | |
| | Stairs | Entine Duilding | 4 740 | C.E. | 0 | C 40 | |
| | Emergency A/C Power - Multipurpose | Entire Building | 1,716 | SF | 6 | 6-10 years | |
| | Room | | | | | | |

Campus Name: Sherwood Page : 16 of 28 Assessment Date: 05/12/2020



| | | | | | A .1.1'4' | | 243 W 37(11 STREET, Chicago, IL 60621 |
|-----------|---|-----------------|----------|---------|-----------|-------------|--|
| Catego | ry : Electrical | | В | uilding | : Addıti | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exit Signs - Corridors and Stairs | Entire Building | 4 | EA | 2 | 0-1 year | No battery back-up or generator. Difficult to read. Older |
| | Exit Signs - Lunchroom | Entire Building | 3 | EA | 2 | 0-1 year | No battery back-up or generator. Difficult to read. Older |
| | Security System - CCTV | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| Main Se | | | | | | | |
| | PA System | Entire Building | 19,885 | SF | 6 | 6-10 years | Serves both buildings |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 10+ years | |
| Catego | ry : Fire Protection | | В | uilding | : Additi | | |
| | | | A | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Fire Alar | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| Catego | ry : Mechanical | | В | | | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Cond | litioning | | | | | | |
| | Chemical Pot Feeder | Site South | 1 | EA | 7 | 10+ years | |
| | Chiller-Air Cooled-Screw Type-Ground | Site South | 1 | EA | 5 | 6-10 years | Insulation on elbow at chiller |
| | Mounted - 101 - 200 tons | | | | | | damaged. |
| | Glycol Feed | Site South | 1 | EA | 6 | 6-10 years | |
| Air Hand | lling Systems | | | | | | |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | Attic | 1 | EA | 5 | 6-10 years | |
| | Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 20001-30000 cfm | Basement | 1 | EA | 5 | 2-5 years | |
| | Air Intake | Basement | 1 | EA | 6 | 6-10 years | |
| | Zone Dampers | Basement | 19 | EA | 5 | 6-10 years | Manual control |
| | Reheat Boxes - Reheat Boxes with Steam Coil | Basement | 7 | EA | 5 | 6-10 years | |
| | Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water | Entire Building | 17 | EA | 6 | 6-10 years | |
| | | | | | | | |



| Catego | ry : Mechanical | | В | uilding | : Additi | on | |
|-----------|--|----------------------|----------|----------|----------|-------------|---------------------------|
| Croun | Hom Tune | Location | Quantity | UOM | Rank | Recommend | Comments |
| Group | Item - Type | Location | Quantity | UOW | Kank | Replacement | Comments |
| Boiler S | | Decement | 400 | 1.5 | | 0.40 | |
| | Piping - Condensate Pipe- Steel | Basement | 400 | LF | 6 | 6-10 years | |
| | Piping - Steam Pipe- Steel | Basement Basement | 400 2 | LF EA | 6 6 | 6-10 years | |
| | Vacuum Pump | Dasement | 2 | EA | 6 | 6-10 years | |
| Heat Ex | changers | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell | Basement | 1 | EA | 6 | 6-10 years | Serves the Addition only. |
| | Туре | | | | | | |
| Heating | Devices | | | | | | |
| J | Radiators - Steam | Basement | 2 | EA | 6 | 6-10 years | |
| | Wall Heater - Electric | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 1 | EA | 6 | 6-10 years | |
| Mechan | ical Plumbing | | | | | | |
| | Chilled Water Pump - 10 - 20 HP | Basement | 1 | EA | 6 | 6-10 years | |
| | Chilled Water Pump - 10 - 20 HP | Basement | 1 | EA | 4 | 0-1 year | Not working |
| | Hot Water Pump - 10 - 20 HP | Basement | 2 | EA | 6 | 6-10 years | 3 |
| | Hydronic Supply and Return - Galvanized | Entire Building | 200 | LF | 6 | 6-10 years | |
| Tempera | ature Control | | | | | | |
| | Electric Thermostat | Entire Building | 17 | EA | 6 | 6-10 years | |
| | Pneumatic System | Entire Building | 19,885 | SF | 3 | 0-1 year | System not working |
| | Thermostats - Pneumatic | Entire Building | 15 | EA | 4 | 0-1 year | System not working |
| Ventilati | on | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 2 | EA | 6 | 6-10 years | |

Category: Plumbing Building: Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|--|-----------------|----------|-----|------|-----------------------|----------|
| Hot Wate | er | | | | | | |
| | Electric Heater - Less than 20 KW | 1st Floor | 1 | EA | 6 | 6-10 years | |
| Pipina | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water Risers | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 19,885 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 19,885 | SF | 6 | 6-10 years | |



| Catego | ry : Plumbing | | Building : Addition | | | | | | |
|--------|--|-----------------|---------------------|-----|------|-------------|----------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| | Fixtures | · · | | | | • | | | |
| | Sanitary Piping | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| | Storm Piping | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| | Vent Piping | Entire Building | 19,885 | SF | 6 | 6-10 years | | | |
| _Pumps | | | | | | | | | |
| | Pumps - Sump-Simplex | Basement | 1 | EA | 5 | 6-10 years | | | |

Category: Room **Building: Addition**

| Guiogi | ny : Noom | | | ununig | . Additi | Recommend | |
|---------|-----------------------------|---|----------|--------|----------|--------------|--------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | trative Suites/Offices | Location | Quantity | 00 | rtuint | rtopiacomont | Commonto |
| Aumins | Ceiling - Plaster/Drywall | 1st Floor - Teachers Lounge | 323 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor - Teachers Lounge | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor - Teachers Lounge | 323 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor - Teachers Lounge | 7 | EA | 7 | 10+ years | |
| | Power Distribution | 1st Floor - Teachers Lounge | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - Teachers Lounge | 696 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor - Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | | 1011 1001 1 0 0 0 1 0 1 0 1 0 1 0 1 0 1 | · | | • | . o · you.o | |
| Citchen | | | | | | | |
| | Ceiling - Plaster/Drywall | 113 | 671 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 113 | 5 | SF | 4 | 0-1 year | Water damage |
| | Doors - Wood Doors inclu hw | 113 | 1 | EA | 7 | 10+ years | • |
| | Floor - Tile | 113 | 676 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 113 | 7 | EA | 7 | 10+ years | |
| | Storage/ Closet | 113 | 100 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 113 | 936 | SF | 7 | 10+ years | |
| : | | | | | | | |
| brary | Casework | 2nd Floor | 50 | LF | 7 | 10+ years | |
| | Ceiling - Splined | 2nd Floor | 1,084 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 934 | SF | 7 | 6-10 years | |
| | Floor - Concrete | 2nd Floor | 150 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 28 | EA | 7 | 10+ years | |
| | Storage/ Closet | 2nd Floor | 180 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,650 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 6 | SF | 5 | 1-2 years | Cracking |

Campus Name: Sherwood Page : 19 of 28 Assessment Date: 05/12/2020



| Catego | ry : Room | | В | uilding | : Additi | on | |
|-----------|---------------------------------|---------------------------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | 113 | 1,706 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 113 | 10 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 113 | 3 | EA | 7 | 10+ years | |
| | Floor - Tile | 113 | 1,676 | SF | 7 | 10+ years | |
| | Floor - Tile | 113 | 40 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 113 | 45 | EA | 7 | 10+ years | |
| | Serving Line | 113 | 20 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 113 | 1,896 | SF | 7 | 10+ years | |
| _Mechani | cal/ Service Rooms | | | | | | |
| | Air Tunnel | Sherwood addition | 1,800 | SF | 7 | 10+ years | |
| _Restroor | n | | | | | | |
| | Accessories | 1st Floor | 140 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 125 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 15 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 140 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 2 | EΑ | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor | 4 | EA | 5 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 64 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 220 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 378 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor Teachers Lounge | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor Teachers Lounge | 45 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor Teachers Lounge | 45 | SF | 7 | 10+ years | |
| | Lavatory | 1st Floor Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | Partitions | 1st Floor Teachers Lounge | 1 | EA | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor Teachers Lounge | 280 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 140 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 140 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 140 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | 6-10 years | |



Casework

Jesse Sherwood Elementary School 245 W 57th STREET, Chicago, IL 60621

| Catego | ry : Room | | В | uilding | : Additi | on | |
|----------|--------------------------------|-----------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lavatory | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 3 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor | 4 | EA | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 220 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 374 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 4 | SF | 4 | 0-1 year | Missing |
| | Water Closet | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 45 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 45 | SF | 7 | 10+ years | |
| | Lavatory | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 224 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Catego | ry : Classroom | | В | uilding | : Additi | on | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #109 (Special Education) | | | | | | |
| | Casework | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 40 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 780 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,368 | SF | 7 | 10+ years | |
| Classroo | m #111 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 780 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,368 | SF | 7 | 10+ years | |
| Classroo | m #116 (Regular Classroom) | | | | | | |

10

LF

6

10+ years

1st Floor



| Catego | ry : Classroom | | Building : Addition | | | | | |
|----------|-----------------------------|------------------------|---------------------|----------|------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Ceiling - Plaster/Drywall | 1st Floor | 780 | SF | 7 | 10+ years | | |
| | Chalk Board | 1st Floor | 20 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 780 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,368 | SF | 6 | 10+ years | | |
| Classroo | m #118 (Regular Classroom) | | | | | | | |
| | Casework | 1st Floor | 10 | LF | 6 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 780 | SF | 7 | 10+ years | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 780 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | 6-10 years | | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 1st Floor | 20 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,368 | SF | 7 | 10+ years | | |
| Classron | m #209 (Regular Classroom) | | | | | | | |
| Classioo | , , | 2nd Floor | 10 | LF | | 10 | | |
| | Casework | 2nd Floor 2nd Floor | 10 780 | SF | 6 | 10+ years | | |
| | Ceiling - Plaster/Drywall | | | SF LF | 7 | 10+ years | | |
| | Chalk Board | 2nd Floor | 20 | | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 780 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 6 | 6-10 years | | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,344 | SF | 7 | 10+ years | | |
| Classroo | m #213 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 780 | SF | 7 | 10+ years | | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 780 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,368 | SF | 7 | 10+ years | | |
| Classroo | m #215 (Regular Classroom) | | | | | | | |

Campus Name: Sherwood Page : 22 of 28 Assessment Date: 05/12/2020



| Category : Classroom | | | В | uilding | | | |
|----------------------|-----------------------------|-------------|----------|---------|------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,368 | SF | 7 | 10+ years | |
| Classroc | om #216 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 775 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 5 | SF | 4 | 0-1 year | Chipped tile |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 6 | 6-10 years | Onipped tile |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,368 | SF | 7 | 10+ years | |
| | walls - Flaster/Drywall | 2110 1 1001 | 1,000 | Oi | , | 10+ years | |
| Classroo | om #217 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 770 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 10 | SF | 4 | 0-1 year | Chipped tile |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,368 | SF | 6 | 10+ years | |
| Classroc | om #218 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 780 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | | | | | | | |



Building: Addition Category : Classroom

Recommend Group Location Quantity UOM Rank Item - Type Replacement Comments

Walls - Plaster/Drywall 1,368 10+ years 2nd Floor SF

Category: Interior **Building: Addition**

| Category : Interior | | Building : Addition | | | | | | | |
|---------------------|--------------------------------------|-------------------------|----------|-----|------|-------------|--------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Corridor | | | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,368 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | 1st Floor | 2 | EA | 6 | 10+ years | | | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 1st Floor | 1,358 | SF | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 1st Floor | 10 | SF | 4 | 0-1 year | Chipped tile | | |
| | Lighting - Pendent/Surface | 1st Floor | 22 | EA | 7 | 6-10 years | | | |
| | Student Lockers - One Tier | 1st Floor | 79 | EA | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 1,200 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,200 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,368 | SF | 7 | 10+ years | | | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile/Sheet | 2nd Floor | 1,368 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 22 | EA | 7 | 6-10 years | | | |
| | Student Lockers - One Tier | 2nd Floor | 79 | EA | 6 | 10+ years | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,200 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 2nd Floor | 1,200 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Vestibule - First floor | 108 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors include hw | Vestibule - First floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | Vestibule - First floor | 108 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | Vestibule - First floor | 3 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | Vestibule - First floor | 7 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | Vestibule - First floor | 120 | SF | 7 | 10+ years | | | |
| Safety | | | | | | | | | |
| · | Security Cameras | 2nd Floor | 3 | EA | 7 | 10+ years | | | |
| Stairs | | | | | | | | | |
| | Ceiling - Plaster/Drywall | Addition | 348 | SF | 7 | 10+ years | | | |
| | Floor - Terrazzo | Addition | 263 | SF | 7 | 10+ years | | | |
| | Handrails | Addition | 30 | LF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Addition | 2 | EA | 7 | 6-10 years | | | |
| | Stairs - Terrazzo | Addition | 180 | LF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Addition | 1,110 | SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | Addition | 450 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | Basement | 72 | SF | 7 | 10+ years | | | |
| | Floor - Concrete | Basement | 20 | SF | 7 | 10+ years | | | |
| | 1 1001 - COlliciete | Bacomoni | | 0. | • | ioi youlo | | | |



| Category : Interior | | | Ві | | | | |
|---------------------|-------------------------|-----------|----------|-----|------|-------------|----------|
| | | Recommend | | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Wall Mounted | Basement | 1 | EA | 7 | 10+ years | |
| | Stairs - Concrete | Basement | 68 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Basement | 1,051 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Basement | 5 | SF | 5 | 0-1 year | Cracked. |

Campus Name: Sherwood Page : 25 of 28 Assessment Date: 05/12/2020



Category: Site **Building: Site**

| alego | iy. Oile | | Building . Site | | | | | | |
|-----------|--|-------------|-----------------|----------|--------|-----------------------|--------------------------------|--|--|
| | _ | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Civil/Dra | | | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 2 | EA | 7 | 10+ years | | | |
| | Civil/ Drainage - Site Manhole | Entire Site | 8 | EA | 7 | 10+ years | | | |
| | | | | | | | | | |
| Eencing | | | | | | | | | |
| | Fencing - Chain Link | Entire Site | 862 | LF | 7 | 10+ years | | | |
| | Fencing - Chain Link | Entire Site | 12 | LF | 7 | 10+ years | | | |
| | Fencing - Chain Link | Entire Site | 332 | LF | 7 | 10+ years | | | |
| | | | | | | | | | |
| _andsca | | | | | | | | | |
| | Benches | Entire Site | 3 | EA | 7 | 10+ years | | | |
| | Landscape - Grass | Entire Site | 7,166 | SF | 7 | 10+ years | | | |
| | Landscape - Hardscape- Asphalt | Entire Site | 31,400 | SF | 5 | 0-1 year | | | |
| | Landscape - Hardscape- Concrete | Entire Site | 2,175 | SF | 7 | 10+ years | | | |
| | Landscape - Hardscape- Concrete | Entire Site | 4,700 | SF | 7 | 10+ years | | | |
| | Parkway trees | Entire Site | 3 | EA | 7 | 10+ years | | | |
| | Planting Beds/ Area | Entire Site | 1,670 | SF | 7 | 10+ years | | | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 6,500 | SF | 4 | 1-2 years | Potholes throughout. | | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 14,100 | SF | 4 | 0-1 year | Cracking and holes throughout. | | |
| | Retaining Wall - Concrete | Entire Site | 168 | SF | 7 | 10+ years | | | |
| | Retaining Wall - Concrete | Entire Site | 477 | SF | 7 | 10+ years | | | |
| | Retaining Wall - Concrete | Entire Site | 84 | SF | 7 | 10+ years | | | |
| 51 | | | | | | | | | |
| Playgrou | Equipment - School Age 5-12 | Southeast | 4 | ΕΛ | 7 | 10 L VOORS | | | |
| | Surface - Square Rubber Mats | Southeast | 2,500 | EA SF | 7 4 | 10+ years 0-1 year | Tiles separating. | | |
| | Surface - Square Rubber Mais | Southeast | 2,500 | SF | 4 | 0-1 year | riles separating. | | |
| Sidewalk | 'S | | | | | | | | |
| J.GOWUII | Sidewalks - Perimeter Sidewalks | Entire Site | 2,240 | SF | 7 | 10+ years | | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 5,516 | SF | 7 | 10+ years | | | |
| | | | 3,3.3 | | - | , | | | |
| Signage | | | | | | | | | |
| 5 5 | Flag Pole - Building Mounted Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | | | |
| | Marquee - Free Standing Back Lighted | Entire Site | 1 | EA | 7 | 6-10 years | | | |
| | Monument - Building Mounted Cut Letter | Entire Site | 2 | EA | 7 | 10+ years | | | |
| | Sign | | | | | · | | | |

Campus Name: Sherwood Page : 26 of 28 Assessment Date: 05/12/2020

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.







Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Sherwood Page: 27 of 28 Assessment Date: 05/12/2020



Classroom Summary

| Classiconi Summary | | | | Floor Plan | | Glazed | Operable | | | | |
|---------------------|-------------------|---------------|--------|------------|-------|--------|----------|--------|--------|--|--|
| | | | Room | Room | Area | Window | Window | Window | Smart- | | |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board | | |
| Building : Main | | | | | | | | | | | |
| Computer Lab | Library | 2nd Floor | 201 | 201 | 750 | 101 | 37 | Υ | N | | |
| Computer Lab | Regular Classroom | 2nd Floor | 205 | 205 | 750 | 135 | 59 | Υ | Ν | | |
| Computer Lab | Regular Classroom | 2nd Floor | 206 | 206 | 750 | 135 | 59 | Υ | Υ | | |
| Kindergarten | Kindergarten | 1st Floor | 105 | 105 | 1,114 | 219 | 83 | Υ | Ν | | |
| Pre School | Regular Classroom | 1st Floor | 102 | 102 | 992 | 162 | 70 | Υ | Ν | | |
| Pre School | Regular Classroom | 1st Floor | 104 | 104 | 750 | 135 | 59 | Υ | Ν | | |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 750 | 135 | 59 | Υ | Ν | | |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 750 | 135 | 59 | Υ | Ν | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 750 | 135 | 59 | Υ | Υ | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 750 | 135 | 59 | Υ | Υ | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 750 | 135 | 59 | Υ | Υ | | |
| Science Classroom | Science Classroom | 2nd Floor | 202 | 202 | 750 | 135 | 59 | Υ | Υ | | |
| | | | | | | | | | | | |
| Building : Addition | 1 | | 1 | 1 | 1 | 1 | | T. | _ | | |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 111 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 1st Floor | 116 | 116 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 1st Floor | 118 | 118 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 215 | 215 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 217 | 780 | 168 | 68 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 218 | 780 | 168 | 68 | Υ | N | | |
| Special Education | Regular Classroom | 1st Floor | 109 | 109 | 780 | 168 | 68 | Υ | N | | |