

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|-------------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1889 | 2 | 62,370 |
| Addition | 1919 | 3 | 43,640 |
| Leased-Branch (Spry HS) | 1970 | 2 | 39,050 |
| Campus Total | | | 145,060 |

Category : Exterior Building : Main

| | | | | | | Recommend | |
|------------|---------------------------------------------|-----------------|----------|-----|------|-------------|------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Entrance | | | | | | | |
| | Entrance Control - Audio and Video | #1 E | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #1 E | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #1 E | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #1 E | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #7 W | 1 | EA | 5 | 0-1 year | Rusted/corroded. |
| | Exterior Doors - Side lite | #7 W | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #8 Exit N | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | #8 Exit N | 12 | LF | 7 | 10+ years | |
| | Ramps - Concrete | #8 Exit N | 12 | LF | 7 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | #8 Exit N | 10 | LF | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 7.1 w | 1 | EA | 6 | 10+ years | |
| Foundation | on | | | | | | |
| | Foundation - Masonry | Entire Building | 625 | LF | 7 | 10+ years | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 62,370 | SF | 7 | 10+ years | |
| Lighting | | | | | | | |
| _Lighting_ | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 6 | EA | 7 | 6-10 years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 9 | EA | 7 | 6-10 years | |
| _Roof Sys | tem | | | | | | |



| `ateno | ry : Exterior | | D | Building : Main | | | | |
|--------|-------------------------------------------------|-----------------|----------|-----------------|-----------|------------------------|--------------------------------------|--|
| alego | ry . Exterior | | В | unung | Recommend | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| ГОИР | Access Ladder - Metal | Main Roof | 2 | EA | 7 | 10+ years | Comments | |
| | Coping - Clay Tile | Main Roof | 628 | LF | 6 | 10+ years | | |
| | Downspouts - Exterior Downspouts | Main Roof | 338 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | Main Roof | 314 | LF | 6 | 10+ years | | |
| | Parapet - Parapet < 16" Height | Main Roof | 314 | LF | 6 | 10+ years | | |
| | Roof - Modified Bitumen | Main Roof | 14,096 | SF | 6 | 10+ years | | |
| | Roof Hatch - Metal | Main Roof | 14,090 | EA | 7 | • | | |
| | Roof Structure - Steel with Clay Tile Arch | Main Roof | 14,096 | SF | 7 | 10+ years | | |
| | | | | | | 10+ years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | West Low Roof | 5 | LF | 6 | 10+ years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | West Low Roof | 16 | LF | 6 | 10+ years | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | West Low Roof | 43 | LF | 6 | 10+ years | | |
| | Coping - Clay Tile | West Low Roof | 154 | LF | 6 | 10+ years | | |
| | Downspouts - Exterior Downspouts | West Low Roof | 60 | LF | 6 | 10+ years | | |
| | Parapet - 16" - 30" Height | West Low Roof | 154 | LF | 6 | 10+ years | | |
| | Roof - Modified Bitumen | West Low Roof | 3,840 | SF | 6 | 10+ years | | |
| | Roof Structure - Steel with Clay Tile Arch | West Low Roof | 3,840 | SF | 7 | 10+ years | | |
| alls | | | | | | | | |
| | Cornice - Masonry Projecting Limestone | Entire Building | 610 | LF | 6 | 10+ years | | |
| | Cornice - Terra Cotta | Entire Building | 550 | LF | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 21,590 | SF | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 5,040 | SF | 6 | 10+ years | | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 252 | SF | 6 | 10+ years | | |
| | Exterior Walls - Stone-Cast | Entire Building | 2,855 | SF | 6 | 10+ years | | |
| indows | 3 | | | | | | | |
| | Guard - Guards perforated | Entire Building | 2,770 | SF | 6 | 10+ years | | |
| | Lintels - Brick | Entire Building | 460 | LF | 6 | 10+ years | | |
| | Lintels - Steel | Entire Building | 202 | LF | 6 | 10+ years | | |
| | Lintels - Stone | Entire Building | 150 | LF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 640 | SF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 5,760 | SF | 6 | 10+ years | | |
| atego | ry : Electrical | | В | uilding | : Main | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| | ncy System | | | | | | | |
| nerger | Automatic Transfer Switch | Electrical Boom | 4 | EA | 6 | 10+ years | | |
| | | Electrical Room | 1 | EA EA | 6 6 | 10+ years 10+ years | Serves the part of the building that | |
| | Automatic Transfer Switch | Electrical Room | 1 | EΑ | n | TO+ VEATS | serves the part of the building that | |



| Category : Electrical | | | Building : Main | | | | | |
|-----------------------|----------------------------------------------------------|-------------------|-----------------|---------|--------|-----------------------------------------|-----------------------------------------------|--|
| | | 1 | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments used to be a clinic and has reverted | |
| | | | | | | | back to being part of the school | |
| | Emergency A/C Power - Corridors and | Entire Building | 11,119 | SF | 6 | 10+ years | back to being part of the school | |
| | Stairs | Zittire Ballaning | 11,110 | O. | ŭ | 10. youro | | |
| | Security System - CCTV | Entire Building | 62,370 | SF | 6 | 6-10 years | | |
| | Security System - Intrusion Detection | Entire Building | 62,370 | SF | 6 | 6-10 years | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 11 | EA | 6 | 6-10 years | | |
| | Emergency Battery Packs - Corridors and | Entire Building | 13 | EA | 6 | 6-10 years | | |
| | Stairs | | _ | | | | | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | | |
| ∕lain Ser | vice | | | | | | | |
| | Independent Electrical Service for | Electrical Room | 1 | EA | 7 | 10+ years | | |
| | emergency power Main Electrical Service - 2001 to 3000 A | Electrical Room | 1 | EA | 7 | 10 L VOORO | | |
| | 120/208/3PH | Electrical Room | ı | EA | , | 10+ years | | |
| | PA System | Entire Building | 62,370 | SF | 6 | 6-10 years | Serves entire school | |
| | 1 / Gyotom | Little Ballanig | 02,070 | O. | Ü | o to youro | Corvos criaro coricor | |
| ower Di | stribution | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 7 | 10+ years | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 4 | 2-5 years | EM fuse panel older than 40 years. | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 8 | EA | 7 | 10+ years | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 17 | EA | 6 | 2-5 years | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 7 | 10+ years | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 6 | 2-5 years | Older disconnect panel | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 7 | 10+ years | | |
| | Main Distribution Panels - Greater than 600 | Entire Building | 3 | EA | 7 | 10+ years | | |
| | amp | g | _ | | | , , , , , , , , , , , , , , , , , , , , | | |
| | Main Distribution Panels - Less than 400 | Entire Building | 1 | EA | 7 | 10+ years | | |
| | amp | | | | | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 6-10 years | | |
| ategoi | ry : Fire Protection | | В | uilding | : Main | | | |
| Proup | Itom Tuno | Location | Quantity | UOM | Pont | Recommend | Comments | |
| Group | Item - Type | Location | Quantity | UUIVI | Rank | Replacement | Comments | |
| ire Aları | n Fire Alarm Panel | Entire Building | 1 | EA | 3 | 0-1 year | More than 40 years of service and | |
| | 1 no / nami i anoi | Lital Dulluling | | L/ \ | J | o i youi | obsolete. Also serves Addition. | |
| | Fire Alarm_System | Entire Building | 62,370 | SF | 4 | 0-1 year | More than 40 years of service and | |
| | • | S | , | | | · | cannot support strobes or additional | |
| | | | | | | | pulls | |



| Catego | ry : Fire Protection | | В | uilding | : Main | | |
|----------|------------------------------------------------------------------------------------------------|------------------|----------|---------|--------|--------------------------|--------------------------------------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| atego | ry : Mechanical | | В | uilding | : Main | | |
| | , · ···· | | _ | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ir Cond | itioning | | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | NW Exterior Wall | 1 | EA | 6 | 6-10 years | Not fully accessible in a safe manuat the time of assessment |
| ir Hand | ling Systems | | | | | | |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | Serves auditorium and gym in Addition |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Auxiliaries - 15001 - 25000 cfm | Mechanical Room | 1 | EA | 4 | 1-2 years | Older equipment, dampers propper open, motor aged. |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room | 100 | LF | 7 | 10+ years | |
| | Zone Dampers | Mechanical Room | 2 | EA | 5 | 6-10 years | |
| | Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Auxiliaries - 30001 - 45000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room | 100 | LF | 7 | 10+ years | |
| | Zone Dampers | Mechanical Room | 35 | EA | 5 | 6-10 years | Manually controlled per the building engineer. |
| oiler Sy | stems | | | | | | |
| • | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | 10+ years | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Chemical Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 7 | 10+ years | Replaced since last assessment |
| | Condensate Pump | Boiler Room | 1 | EΑ | 6 | 10+ years | B |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | 6-10 years | Pipe insulation below tank needs repair. |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 5 | 10+ years | Two leaks presents in boiler tube |
| | Piping - Condensate Pipe- Steel | Boiler Room | 600 | LF | 5 | 6-10 years | |
| | Piping - Steam Pipe- Steel | Boiler Room | 600 | LF | 5 | 6-10 years | |
| | Steam Traps | Boiler Room | 36 | EA | 5 | 10+ years | |



Category : Mechanical

John Spry Elementary Community School 2400 S Marshall BOULEVARD, Chicago, IL 60623

Recommend

Building: Main

| | | | | | | Recommend | |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-----------------|---------|--------|-------------|--------------------------------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Wall Heater - Electric | Entire Building | 7 | EA | 6 | 6-10 years | |
| | Wall Heater - Electric | Entire Building | 1 | EA | 5 | 2-5 years | |
| | Fin Tube - Steam | Entire Building | 30 | LF | 6 | 10+ years | |
| | Unit Heater - Electric | Entire Building | 2 | ĒΑ | 6 | 10+ years | |
| | Unit Heater - Gas | Entire Building | 1 | EA | 6 | 10+ years | |
| | Office reactions of the control of t | Little Ballaling | ' | LA | O | 10+ years | |
| Tempera | ature Control | | | | | | |
| | Electric Thermostat | Entire Building | 3 | EA | 6 | 10+ years | |
| | Pneumatic System | Entire Building | 62,370 | SF | 4 | 1-2 years | System has many leaks which has |
| | i neumatic System | Little Ballaling | 02,370 | Si | 7 | 1-2 years | disabled most zone actuators |
| | Thermostats - Pneumatic | Entire Building | 37 | EA | 4 | 1 2 voore | Contaminated with oil |
| | memosiais - Friedmatic | Entire Building | 37 | EA | 4 | 1-2 years | Contaminated with oil |
| Ventilation | nn | | | | | | |
| Verman | Exhaust Fans- Roof Mounted - 500 - 1500 | Roof | 1 | EA | 6 | 2-5 years | Dented motor housing |
| | CFM | | | | | , | |
| | Exhaust Fans- Roof Mounted - Less than | Roof | 2 | EA | 6 | 2-5 years | Dented motor housing |
| | 500 CFM | | | | | • | · |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| | ., | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | er | | - | | | · | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 7 | 10+ years | Installed 2019, Serves the main and addition. |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 4 | 1-2 years | Older deteriorated unit, signs of leaks and corrosion. |
| Piping | | | | | | | |
| riping | Domestic Piping-Cold Water Horizontal | Entire Building | 62,370 | SF | 4 | 1.2 voore | Original piping with numerous pipe |
| | Lines | Entire Building | 02,370 | SI | 4 | 1-2 years | |
| | | Catina Duildina | 60.070 | SF | 4 | 4.0 | clamps. |
| | Domestic Piping-Cold Water Risers | Entire Building | 62,370 | | 4 | 1-2 years | |
| | Domestic Piping-Cold Water from Risers to | Entire Building | 62,370 | SF | 4 | 1-2 years | |
| | Fixtures | F (| 00.070 | 0.5 | | 4.0 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 62,370 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 62,370 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 62,370 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 62,370 | SF | 4 | 1-2 years | |
| | Fixtures | | | | | | |
| | Sanitary Piping | Entire Building | 62,370 | SF | 5 | 10+ years | |
| | Storm Piping | Entire Building | 62,370 | SF | 5 | 10+ years | With heavy rains, one of the |
| | - | - | | | | - | downspouts presents water to enter the boiler room |
| | Vent Piping | Entire Building | 62,370 | SF | 5 | 10+ years | the polici room |
| | | 5 5 4 1 4 1 1 5 | 32,070 | O. | Ŭ | .0. ,00.0 | |
| Campus | Name: Spry Community Links High School | | Page : 5 of 52 | | | | Assessment Date: 11/19/2020 |
| Jampus I | tamo. Opry Community Links ringin School | | 1 ago . 0 01 02 | | | | 7000001116111 Date. 11/19/2020 |



Building: Main Category: Plumbing

Recommend Quantity UOM Rank Replacement Comments Group Item - Type Location

Pumps

Pumps - Domestic Booster Pump-Simplex 2-5 years No leaks; old but in good condition. Mechanical Room 1 EΑ 6

Duilding . Main

| Categor | ry : Room | Building : Main | | | | | | | |
|----------|---------------------------------|----------------------------|----------|-----|------|-------------|-------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Administ | rative Suites/Offices | | | | | | | | |
| | AC Unit | 105 Literary Office | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 105 Literary Office | 510 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 105 Literary Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 105 Literary Office | 510 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 105 Literary Office | 6 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 105 Literary Office | 10 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 105 Literary Office | 448 | SF | 7 | 10+ years | | | |
| | AC Unit | 106 counseling Office | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 106 counseling Office | 542 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 106 counseling Office | 70 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 106 counseling Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Tile | 106 counseling Office | 542 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 106 counseling Office | 6 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 106 counseling Office | 4 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 106 counseling Office | 655 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor Staff Workroom | 95 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor Staff Workroom | 1 | EA | 7 | 10+ years | | | |
| | Floor - Concrete | 1st Floor Staff Workroom | 95 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | 1st Floor Staff Workroom | 1 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 1st Floor Staff Workroom | 2 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st Floor Staff Workroom | 538 | SF | 7 | 10+ years | | | |
| | AC Unit | 204A Office | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 204A Office | 96 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 204A Office | 1 | EA | 7 | 10+ years | | | |
| | Floor - Concrete Epoxy/ Painted | 204A Office | 96 | SF | 7 | 10+ years | Asphalt flooring. | | |
| | Lighting - Pendent/Surface | 204A Office | 2 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 204A Office | 2 | EA | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 204A Office | 412 | SF | 7 | 10+ years | | | |
| | AC Unit | 205 Teachers Resource Room | 2 | EA | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 205 Teachers Resource Room | 609 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 205 Teachers Resource Room | 80 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 205 Teachers Resource Room | 12 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 205 Teachers Resource Room | 2 | EA | 7 | 10+ years | | | |
| | Floor - Wood | 205 Teachers Resource Room | 609 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 205 Teachers Resource Room | 8 | EA | 7 | 6-10 years | | | |
| | Power Distribution | 205 Teachers Resource Room | 11 | EA | 7 | 10+ years | | | |



| Catego | ory : Room | | В | uilding | : Main | | |
|--------|--------------------------------------|--------------------------------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Plaster/Drywall | 205 Teachers Resource Room | 850 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 2nd Floor Staff Workroom | 95 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Staff Workroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor Staff Workroom | 95 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor Staff Workroom | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | 2nd Floor Staff Workroom | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor Staff Workroom | 538 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | B2 A | 100 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | B2 A | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | B2 A | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | B2 A | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | B2 A | 320 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | B2 B | 100 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 B | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | B2 B | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | B2 B | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | B2 B | 2 | EA | 7 | 10+ years | |
| | Storage/ Closet | B2 B | 6 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | B2 B | 320 | SF | 7 | 10+ years | |
| | Work SInk | B2 B | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | B2 C | 100 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 C | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | B2 C | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | B2 C | 2 | ĒΑ | 7 | 6-10 years | |
| | Power Distribution | B2 C | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | B2 C | 320 | SF | 7 | 10+ years | |
| | Work SInk | B2 C | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | B2 D | 100 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 D | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | B2 D | 100 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | B2 D | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | B2 D | 2 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | B2 D | 320 | SF | 7 | 10+ years | |
| | Work Sink | B2 D | 1 | EA | 7 | 10+ years | |
| | Ceiling - Lay-in | B2 special ed | 480 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 special ed B2 special ed | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | B2 special ed B2 special ed | 480 | SF | 7 | • | |
| | | B2 special ed B2 special ed | 400 | EA | 7 | 10+ years | |
| | Lighting - Lay-in Power Distribution | B2 special ed B2 special ed | 12 | EA | 7 | 6-10 years | |
| | | B2 special ed B2 special ed | | SF | 7 7 | 10+ years | |
| | Walls - Plaster/Drywall | | 704 | SF SF | | 10+ years | |
| | Ceiling - Exposed | Basement Teachers Lounge | 600 | | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement Teachers Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Basement Teachers Lounge | 600 | SF | 7 | 10+ years | |



| Category : Room | | | Building : Main | | | | | |
|-----------------|-----------------------------|--------------------------|-----------------|-----|------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Lighting - Pendent/Surface | Basement Teachers Lounge | 10 | EΑ | 7 | 6-10 years | | |
| | Power Distribution | Basement Teachers Lounge | 6 | EΑ | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Basement Teachers Lounge | 1,283 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | Community Links 2 | 435 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Community Links 2 | 1 | EA | 7 | 10+ years | | |
| | Floor - Terrazzo | Community Links 2 | 200 | SF | 7 | 10+ years | | |
| | Floor - Wood | Community Links 2 | 235 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Community Links 2 | 8 | EA | 7 | 6-10 years | | |
| | Power Distribution | Community Links 2 | 12 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | Community Links 2 | 273 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Community Links 2 | 612 | SF | 7 | 10+ years | | |
| | Ceiling - Exposed | Community Links Office | 364 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Community Links Office | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | Community Links Office | 364 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | Community Links Office | 3 | EA | 7 | 10+ years | | |
| | Power Distribution | Community Links Office | 10 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | Community Links Office | 273 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Community Links Office | 532 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Engineering office | 213 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Engineering office | 1 | EΑ | 7 | 10+ years | | |
| | Floor - Wood | Engineering office | 213 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | Engineering office | 3 | EA | 7 | 6-10 years | | |
| | Power Distribution | Engineering office | 6 | EΑ | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Engineering office | 450 | SF | 7 | 10+ years | | |
| | AC Unit | Main Office | 1 | EA | 7 | 6-10 years | | |
| | Ceiling - Lay-in | Main Office | 650 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | Main Office | 18 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Main Office | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | Main Office | 650 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Main Office | 7 | EA | 7 | 6-10 years | | |
| | Power Distribution | Main Office | 16 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Main Office | 1,150 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Principals Office | 198 | SF | 7 | 10+ years | | |
| | Doors - Transom Window | Principals Office | 18 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | Principals Office | 2 | EA | 7 | 10+ years | | |
| | Floor - Tile | Principals Office | 198 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Principals Office | 2 | EA | 7 | 6-10 years | | |
| | Power Distribution | Principals Office | 8 | EA | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | Principals Office | 548 | SF | 7 | 10+ years | | |
| | • | | | | | • | | |
| Library | | | | | | | | |
| • | AC Unit | 206 & 208 | 4 | EA | 7 | 6-10 years | | |
| | Casework | 206 & 208 | 18 | LF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 206 & 208 | 2,010 | SF | 7 | 10+ years | | |
| | - | | • | | | • | | |



| Catego | ry : Room | | В | uilding | : Main | | - |
|----------|--------------------------------------------------------|------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 206 & 208 | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 206 & 208 | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 206 & 208 | 875 | SF | 7 | 6-10 years | |
| | Floor - Wood | 206 & 208 | 1,135 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 206 & 208 | 28 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 206 & 208 | 78 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 206 & 208 | 2,175 | SF | 7 | 10+ years | |
| _Lunch & | Multipurpose Room | | | | | | |
| | Ceiling - Exposed | B2 lunchroom | 216 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 lunchroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | B2 lunchroom | 216 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | B2 lunchroom | 4 | EA | 7 | 6-10 years | |
| | Walls - Masonry | B2 lunchroom | 72 | SF | 7 | 10+ years | |
| | Walls - Masorry Walls - Plaster/Drywall | B2 lunchroom | 384 | SF | 7 | • | |
| | walls - Plaster/Drywall | B2 IUIICIIIOOIII | 304 | SF | , | 10+ years | |
| _Mechani | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 24 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 24 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 39 | SF | 5 | 10+ years | |
| | Storage Room | 3rd Floor | 64 | SF | 5 | 10+ years | |
| | Air Intake Plenums | Basement | 2,000 | SF | 7 | 10+ years | |
| | Air Tunnel | Basement | 1,500 | SF | 7 | 10+ years | |
| | Boiler Room | Basement | 1,756 | SF | 7 | 10+ years | |
| | Loading Docks | Basement | 200 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 3.707 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 1,684 | SF | 7 | 10+ years | |
| | Vaults | Basement | 200 | SF | 7 | 10+ years | |
| Restroor | m | | | | | | |
| | Accessories | 1st FL. Boys | 260 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st FL. Boys | 260 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st FL. Boys | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st FL. Boys | 260 | SF | 7 | 10+ years | |
| | Floor Drain | 1st FL. Boys | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st FL. Boys | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st FL. Boys | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st FL. Boys | 6 | EA | 7 | 6-10 years | |
| | Partitions | 1st FL. Boys | 2 | ΕA | 7 | 10+ years | |
| | Urinals | 1st FL. Boys | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st FL. Boys | 111 | SF | 7 | 10+ years | |
| | Walls - Traster/Drywaii Walls - Structural Glazed Tile | 1st FL. Boys | 637 | SF | 7 | 10+ years | |
| | Water Closet | 1st FL. Boys | 2 | EA | 7 | 10+ years | |
| | vvalel Clusel | 151 FL. DUYS | 2 | EA | , | TOT YEARS | |



| Second S | Catego | Category : Room | | Building : Main | | | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------------------------------|---------------|-----------------|----|---|------------|----------------|--|--|
| Accessories Ceiling - Plaster/Dywall Ist FI. Men Ceiling - Plaster/Dywall Ist FI. Men Ceiling - Plaster/Dywall Ist FI. Men S SF 7 10- years Ceiling - Plaster/Dywall Ist FI. Men S SF 5 1-2 years Floor - Wood Doors inclu hw Ist FI. Men | | | | Recommend | | | | | | |
| Ceiling - Plaster/Drywall | Group | • • | | | | | | Comments | | |
| Ceiling - Plaster/Drywall | | | | | | | | | | |
| Doors - Wood Doors inclu hw | | | | | | | • | | | |
| Floor - Tile | | | | | | | | Broken plaster | | |
| Lavatory | | | | | | | | | | |
| Lighting - Pendent/Surface | | | | | | | • | | | |
| Lighting - Vall Mounted 1st Fl. Men 520 SF 7 10+ years | | • | | | | | | | | |
| Walls - Plaster/Drywall 1st Fl. Men 520 SF 7 10+ years Water Closet 1st Fl. Men 1 EA 7 10+ years Accessories 2nd Fir Boys 260 SF 7 6-10 years Celling - Plaster/Drywall 2nd Fir Boys 260 SF 7 10+ years Doors - Side-Ilte 2nd Fir Boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Fir Boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 2nd Fir Boys 260 SF 7 10+ years Floor Drain 2nd Fir Boys 260 SF 7 10+ years Floor Drain 2nd Fir Boys 2 EA 7 6-10 years Hand Dryer 2nd Fir Boys 2 EA 7 6-10 years Layatory 2nd Fir Boys 6 EA 7 6-10 years Lighting - Pendent/Surface 2nd Fir Boys 4 EA 7 10+ years < | | | | = = | | | | | | |
| Water Closet | | | | | | | | | | |
| Accessories | | | | 520 | | | 10+ years | | | |
| Ceiling - Plaster/Dywall 2nd Fir Boys 260 SF 7 10+ years | | | | | | | | | | |
| Doors - Side-lite | | | | | | | | | | |
| Doors - Transom Window | | | | | | | 10+ years | | | |
| Doors - Wood Doors inclu hw | | | | | | | 10+ years | | | |
| Floor - Tile Ceramic/ Porcelain | | Doors - Transom Window | | 12 | SF | | 10+ years | | | |
| Floor Drain | | Doors - Wood Doors inclu hw | | | | 7 | 10+ years | | | |
| Hand Dryer | | Floor - Tile Ceramic/ Porcelain | | 260 | SF | | 10+ years | | | |
| Lavatory 2nd Fir Boys 3 EA 7 10+ ýears Lighting - Pendent/Surface 2nd Fir Boys 6 EA 7 6-10 years Partitions 2nd Fir Boys 2 EA 7 10+ years Walls - Plaster/Drywall 2nd Fir Boys 4 EA 7 10+ years Walls - Structural Glazed Tile 2nd Fir Boys 637 SF 7 10+ years Water Closet 2nd Fir Boys 2 EA 7 10+ years Water Closet 2nd Fir Women 78 SF 7 10+ years Ceiling - Plaster/Drywall 2nd Fir Women 78 SF 7 10+ years Ceiling - Plaster/Drywall 2nd Fir Women 1 EA 7 10+ years Lavatory 2nd Fir Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd Fir Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Fir Women 1 EA 7 6-10 | | | | | EA | | 10+ years | | | |
| Lighting - Pendent/Surface 2nd Flr Boys 6 EA 7 6-10 years Partitions 2nd Flr Boys 2 EA 7 10+ years Walls - Plaster/Drywall 2nd Flr Boys 111 SF 7 10+ years Walls - Structural Glazed Tile 2nd Flr Boys 637 SF 7 10+ years Walls - Structural Glazed Tile 2nd Flr Boys 637 SF 7 10+ years Water Closet 2nd Flr Women 78 SF 7 10+ years Accessories 2nd Flr Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Flr Women 78 SF 7 10+ years Floor - Tile 2nd Flr Women 78 SF 6 10+ years Lavatory 2nd Flr Women 1 EA 7 6-10 years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 | | Hand Dryer | 2nd Flr Boys | 2 | EA | 7 | 6-10 years | | | |
| Partitions 2nd Fir Boys 2 EA 7 10+ years Urinals 2nd Fir Boys 4 EA 7 10+ years Walls - Plaster/Drywall 2nd Fir Boys 111 SF 7 10+ years Walls - Structural Glazed Tile 2nd Fir Boys 637 SF 7 10+ years Water Closet 2nd Fir Boys 2 EA 7 10+ years Accessories 2nd Fir Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Fir Women 78 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Fir Women 1 EA 7 10+ years Floor - Tile 2nd Fir Women 78 SF 6 10+ years Lavatory 2nd Fir Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd Fir Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Fir Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Fir Women 1 EA 7 6-10 years Water Closet 2nd Fir Women 1 EA 7 10+ years Accessories | | Lavatory | 2nd Flr Boys | 3 | EΑ | 7 | 10+ years | | | |
| Urinals 2nd FIr Boys 4 EA 7 10+ years Walls - Plaster/Drywall 2nd FIr Boys 111 SF 7 10+ years Walls - Structural Glazed Tile 2nd FIr Boys 637 SF 7 10+ years Water Closet 2nd FIr Boys 2 EA 7 10+ years Accessories 2nd FIr Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd FIr Women 78 SF 7 10+ years Doors - Wood Doors inclu hw 2nd FIr Women 1 EA 7 10+ years Floor - Tile 2nd FIr Women 78 SF 6 10+ years Floor - Tile 2nd FIr Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd FIr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd FIr Women 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Fir Women 1 EA 7 | | Lighting - Pendent/Surface | 2nd Flr Boys | 6 | EA | 7 | 6-10 years | | | |
| Walls - Plaster/Drywall 2nd Flr Boys 111 SF 7 10+ years Walls - Structural Glazed Tile 2nd Flr Boys 637 SF 7 10+ years Water Closet 2nd Flr Boys 2 EA 7 10+ years Accessories 2nd Flr Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Flr Women 78 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Flr Women 1 EA 7 10+ years Floor - Tile 2nd Flr Women 78 SF 6 10+ years Lavatory 2nd Flr Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Pendent/Surface 2nd Flr Women 1 EA | | Partitions | 2nd Flr Boys | 2 | EA | 7 | 10+ years | | | |
| Walls - Structural Glazed Tile2nd Flr Boys637SF710+ yearsWater Closet2nd Flr Boys2EA710+ yearsAccessories2nd Flr Women78SF76-10 yearsCeiling - Plaster/Drywall2nd Flr Women78SF710+ yearsDoors - Wood Doors inclu hw2nd Flr Women1EA710+ yearsFloor - Tile2nd Flr Women78SF610+ yearsLavatory2nd Flr Women1EA710+ yearsLighting - Pendent/Surface2nd Flr Women1EA76-10 yearsLighting - Wall Mounted2nd Flr Women1EA76-10 yearsWalls - Plaster/Drywall2nd Flr Women519SF710+ yearsWater Closet2nd Flr Women1EA710+ yearsAccessories3rd Flr boys260SF76-10 yearsCeiling - Plaster/Drywall3rd Flr boys260SF710+ yearsDoors - Side-lite3rd Flr boys1EA710+ yearsDoors - Transom Window3rd Flr boys1EA710+ yearsFloor Drain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years <td></td> <td>Urinals</td> <td>2nd Flr Boys</td> <td>4</td> <td>EΑ</td> <td>7</td> <td>10+ years</td> <td></td> | | Urinals | 2nd Flr Boys | 4 | EΑ | 7 | 10+ years | | | |
| Water Closet 2nd Flr Boys 2 EA 7 10+ years Accessories 2nd Flr Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Flr Women 78 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Flr Women 1 EA 7 10+ years Floor - Tile 2nd Flr Women 1 EA 7 10+ years Lavatory 2nd Flr Women 1 EA 7 6-10 years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Flr Women 519 SF 7 10+ years Water Closet 2nd Flr Women 1 EA 7 10+ years Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 1 EA 7 10+ years Floor Porain | | Walls - Plaster/Drywall | 2nd Flr Boys | 111 | SF | 7 | 10+ years | | | |
| Water Closet2nd Flr Boys2EA710+ yearsAccessories2nd Flr Women78SF76-10 yearsCeiling - Plaster/Drywall2nd Flr Women78SF710+ yearsDoors - Wood Doors inclu hw2nd Flr Women1EA710+ yearsFloor - Tile2nd Flr Women78SF610+ yearsLavatory2nd Flr Women1EA76-10 yearsLighting - Pendent/Surface2nd Flr Women1EA76-10 yearsLighting - Wall Mounted2nd Flr Women1EA76-10 yearsWalls - Plaster/Drywall2nd Flr Women519SF710+ yearsWater Closet2nd Flr Women1EA710+ yearsAccessories3rd Flr boys260SF76-10 yearsCeiling - Plaster/Drywall3rd Flr boys260SF710+ yearsDoors - Side-lite3rd Flr boys9SF710+ yearsDoors - Transom Window3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys1EA710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | | 2nd Flr Boys | 637 | SF | 7 | 10+ years | | | |
| Accessories 2nd Flr Women 78 SF 7 6-10 years Ceiling - Plaster/Drywall 2nd Flr Women 78 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Flr Women 1 EA 7 10+ years Floor - Tile 2nd Flr Women 78 SF 6 10+ years Lavatory 2nd Flr Women 1 EA 7 10+ years Lavatory 2nd Flr Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Ster/Drywall 2nd Flr Women 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Flr Women 519 SF 7 10+ years Accessories 2nd Flr Women 1 EA 7 10+ years Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Side-lite 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 12 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 1 EA 7 10+ years Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Fir boys 3 EA 7 10+ years | | Water Closet | 2nd Flr Boys | 2 | EA | 7 | | | | |
| Doors - Wood Doors inclu hw2nd Flr Women1EA710+ yearsFloor - Tile2nd Flr Women78SF610+ yearsLavatory2nd Flr Women1EA710+ yearsLighting - Pendent/Surface2nd Flr Women1EA76-10 yearsLighting - Wall Mounted2nd Flr Women1EA76-10 yearsWalls - Plaster/Drywall2nd Flr Women519SF710+ yearsWater Closet2nd Flr Women1EA710+ yearsAccessories3rd Flr boys260SF76-10 yearsCeiling - Plaster/Drywall3rd Flr boys260SF710+ yearsDoors - Side-lite3rd Flr boys9SF710+ yearsDoors - Transom Window3rd Flr boys9SF710+ yearsDoors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor Drain3rd Flr boys260SF710+ yearsHand Dryer3rd Flr boys1EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | Accessories | | | SF | 7 | | | | |
| Doors - Wood Doors inclu hw2nd FIr Women1EA710+ yearsFloor - Tile2nd FIr Women78SF610+ yearsLavatory2nd FIr Women1EA710+ yearsLighting - Pendent/Surface2nd FIr Women1EA76-10 yearsLighting - Wall Mounted2nd FIr Women1EA76-10 yearsWalls - Plaster/Drywall2nd FIr Women519SF710+ yearsWater Closet2nd FIr Women1EA710+ yearsAccessories3rd FIr boys260SF76-10 yearsCeiling - Plaster/Drywall3rd FIr boys260SF710+ yearsDoors - Side-lite3rd FIr boys9SF710+ yearsDoors - Transom Window3rd FIr boys12SF710+ yearsDoors - Wood Doors inclu hw3rd FIr boys1EA710+ yearsFloor Drain3rd FIr boys260SF710+ yearsHand Dryer3rd FIr boys1EA76-10 yearsLavatory3rd FIr boys3EA710+ years | | Ceiling - Plaster/Drywall | | | SF | | 10+ years | | | |
| Floor - Tile 2nd Flr Women 78 SF 6 10+ years Lavatory 2nd Flr Women 1 EA 7 10+ years Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Flr Women 519 SF 7 10+ years Water Closet 2nd Flr Women 1 EA 7 10+ years Water Closet 2nd Flr Women 1 EA 7 10+ years Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 12 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor Drain 3rd Flr boys 260 SF 7 10+ years Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | 2nd Flr Women | 1 | EA | 7 | 10+ years | | | |
| Lavatory Lighting - Pendent/Surface Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 519 SF 7 10+ years Water Closet Accessories 2nd Flr Women 1 EA 7 10+ years Water Closet Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | 2nd Flr Women | 78 | | | | | | |
| Lighting - Pendent/Surface 2nd Flr Women 1 EA 7 6-10 years Lighting - Wall Mounted 2nd Flr Women 1 EA 7 6-10 years Walls - Plaster/Drywall 2nd Flr Women 519 SF 7 10+ years Water Closet 2nd Flr Women 1 EA 7 10+ years Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 12 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Floor Drain 3rd Flr boys 260 SF 7 10+ years Hand Dryer 3rd Flr boys 1 EA 7 10+ years Lavatory 3rd Flr boys 3 EA 7 6-10 years Lavatory | | | | | | | | | | |
| Lighting - Wall Mounted 2nd Flr Women 519 SF 7 10+ years Water Closet Accessories Ceiling - Plaster/Drywall 3rd Flr boys Doors - Side-lite Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Floor Prain Floor Drain Hand Dryer Lavatory 2nd Flr Women 2nd Flr boys 260 SF 7 260 | | | | 1 | | | , | | | |
| Walls - Plaster/Drywall2nd Flr Women519SF710+ yearsWater Closet2nd Flr Women1EA710+ yearsAccessories3rd Flr boys260SF76-10 yearsCeiling - Plaster/Drywall3rd Flr boys260SF710+ yearsDoors - Side-lite3rd Flr boys9SF710+ yearsDoors - Transom Window3rd Flr boys12SF710+ yearsDoors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | | 2nd Flr Women | 1 | EΑ | | | | | |
| Water Closet 2nd Flr Women 1 EA 7 10+ years Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Hand Dryer 3rd Flr boys 1 EA 7 10+ years Lavatory 3rd Flr boys 3 EA 7 6-10 years Lavatory | | | 2nd Flr Women | 519 | SF | | • | | | |
| Accessories 3rd Flr boys 260 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd Flr boys 260 SF 7 10+ years Doors - Side-lite 3rd Flr boys 9 SF 7 10+ years Doors - Transom Window 3rd Flr boys 12 SF 7 10+ years Doors - Wood Doors inclu hw 3rd Flr boys 1 EA 7 10+ years Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | | | | | • | | | |
| Ceiling - Plaster/Drywall3rd Flr boys260SF710+ yearsDoors - Side-lite3rd Flr boys9SF710+ yearsDoors - Transom Window3rd Flr boys12SF710+ yearsDoors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | | | 260 | | | | | | |
| Doors - Side-lite3rd Flr boys9SF710+ yearsDoors - Transom Window3rd Flr boys12SF710+ yearsDoors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | | | | | | | | | |
| Doors - Transom Window3rd Flr boys12SF710+ yearsDoors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | • | | | | | | | | |
| Doors - Wood Doors inclu hw3rd Flr boys1EA710+ yearsFloor - Tile Ceramic/ Porcelain3rd Flr boys260SF710+ yearsFloor Drain3rd Flr boys1EA710+ yearsHand Dryer3rd Flr boys2EA76-10 yearsLavatory3rd Flr boys3EA710+ years | | | | | | | • | | | |
| Floor - Tile Ceramic/ Porcelain 3rd Flr boys 260 SF 7 10+ years Floor Drain 3rd Flr boys 1 EA 7 10+ years Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | | | | | | | | |
| Floor Drain 3rd Flr boys 1 EA 7 10+ years Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | | | | | • | | | |
| Hand Dryer 3rd Flr boys 2 EA 7 6-10 years Lavatory 3rd Flr boys 3 EA 7 10+ years | | | | | | | | | | |
| Lavatory 3 rd Flr boys 3 EA 7 10+ years | | | | | | | | | | |
| | | | | | | | | | | |
| Eighting 1 ondone outland of the boys | | | | | | | | | | |
| | | Lighting - Feliaent/Outlace | Sid i ii boys | U | LA | , | 0-10 years | | | |



Category : Room

John Spry Elementary Community School 2400 S Marshall BOULEVARD, Chicago, IL 60623

| | | | | | | Recommend | |
|--------|---------------------------------|--------------------|------------|---------|--------|-------------|-----------------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Partitions | 3rd Flr boys | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Flr boys | 4 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Flr boys | 111 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Flr boys | 637 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Flr boys | 2 | EA | 7 | 10+ years | |
| | Accessories | B2 | 64 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | B2 | 64 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | B2 | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | B2 | 64 | SF | 7 | 10+ years | |
| | Floor Drain | B2 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | B2 | 1 | EA | 7 | 10+ years | |
| | Lavatory | B2 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | B2 | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | B2 | 128 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | B2 | 128 | SF | 7 | 10+ years | |
| | Water Closet | B2 | 1 | ĒΑ | 7 | 10+ years | |
| | Accessories | Engineering Office | 102 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineering Office | 102 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineering Office | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Engineering Office | 102 | SF | 7 | 10+ years | |
| | Floor Drain | Engineering Office | 1 | ĒΑ | 7 | 10+ years | |
| | Lavatory | Engineering Office | 1 | EA | 4 | 0-1 year | Broken in half. |
| | Lighting - Pendent/Surface | Engineering Office | 2 | EA | 7 | 6-10 years | 2.0 |
| | Partitions | Engineering Office | 1 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Engineering Office | 430 | SF | 5 | 1-2 years | Patching and painting throughout. |
| | Water Closet | Engineering Office | 1 | EA | 7 | 10+ years | r atoming and painting amoughout |
| | Accessories | Principal's Toilet | 45 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Principal's Toilet | 45 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Principal's Toilet | 45 | SF | 7 | 10+ years | |
| | Lavatory | Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Principal's Toilet | 1 | EΑ | 7 | 6-10 years | |
| | Walls - Masonry | Principal's Toilet | 50 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Toilet | 263 | SF | 7 | 10+ years | |
| | Water Closet | Principal's Toilet | 1 | EA | 7 | 10+ years | |
| | | · | _ | | | • | |
| Catego | ry : Classroom | | В | uilding | : Main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | om #101 (Regular Classroom) | | - Luaining | | | | 5 |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Casework Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Oriain Dualu | 13(1100) | 10 | LF | 4 | 2-5 years | |

Building: Main



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|----------|--------|-------------|---------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EΑ | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EΑ | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 156 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| Classroc | m #102 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 870 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 10 | SF | 4 | | Missing tiles |
| | | 1st Floor | 12 | EA | 7 | 1-2 years | wissing tiles |
| | Lighting - Lay-in | | | | | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF SF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| Classroc | m #103 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EΑ | 7 | 6-10 years | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EΑ | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 36 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 156 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| Classroc | m #104 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| | Walls Tlastel/Dlywall | 13111001 | 1,210 | O. | , | 101 years | |
| lassroc | m #108 (Regular Classroom) | | | | | | |

Page : 12 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | |
|-----------|-----------------------------|-------------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 27 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 156 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| Classroo | om #109 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 156 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| | · | 1001 | 1,210 | O. | • | io: youro | |
| _Classroo | om #110 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 156 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,218 | SF | 7 | 10+ years | |
| _Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 37 | SF | 7 | 10+ years | |
| | 200.0 Halloom William | 2110 1 1001 | 31 | 0. | , | ioi youis | |

Page : 13 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | - |
|-----------|-----------------------------|------------------------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 10+ years | |
| | Storage/ Closet | 2nd Floor | 178 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| Classroo | m #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor 2nd Floor | 25 | SF | 7 | • | |
| | | | | SF SF | | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 6 | 10+ years | |
| Classroo | m #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 188 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| _Classroo | m #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 45 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| | viano i laster/brywan | 2110 1 1001 | 1,210 | Oi. | , | 101 yours | |
| Classroo | m #207 (Regular Classroom) | | | | | | |

Page : 14 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | · |
|-----------|-----------------------------|------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 2 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 21 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 14 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 184 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| Classroo | om #209 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 4 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor 2nd Floor | 36 | SF | 7 | • | |
| | | | | _ | | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 7 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 182 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,218 | SF | 7 | 10+ years | |
| Classroo | om #301 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 27 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 200 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,218 | SF | 6 | 10+ years | |
| _Classroo | om #302 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | 1 1001 - 99000 | 314 1 1001 | 300 | OI. | , | 10+ years | |

Page : 15 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | |
|-----------|-----------------------------|------------|----------|---------|--------|-------------|-----------------------------------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 31 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,218 | SF | 6 | 10+ years | |
| _Classroo | om #303 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 9 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 10 | ĹF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 880 | SF | 4 | 0-1 year | Cracking and chipping throughout. |
| | Lighting - Lay-in | 3rd Floor | 12 | ĒΑ | 7 | 6-10 years | Graciumy and compping among roun |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 145 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,218 | SF | 7 | 10+ years | |
| | walle Tideten 21, wall | 0.0.1.00. | 1,210 | 0. | • | io. youro | |
| Classroo | om #304 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 49 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,216 | SF | 6 | 10+ years | |
| Classro | om #305 (Faculty Lounge) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 470 | SF | 6 | 6-10 years | |
| | Chalk Board | 3rd Floor | 4 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 470 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 7 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 3 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 117 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,039 | SF | 7 | 10+ years | |
| Classro | om #306 (Regular Classroom) | | | | | | |
| <u> </u> | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | AO Office | 314 1 1001 | 2 | LA | , | o- io yeais | |

Page : 16 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------|----------|---------|--------|-------------|----------|
| | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Casework | 3rd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 40 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 179 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,216 | SF | 7 | 10+ years | |
| Classroo | om #307 (Faculty Lounge) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 15 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 880 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 119 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,218 | SF | 6 | 10+ years | |
| Classroo | om #308 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 5 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 6 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 182 | SF | 5 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,216 | SF | 6 | 10+ years | |
| Classroo | om #309 (Science) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 36 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | 200.0 Wood 20010 IIIold IIW | 014 1 1001 | ' | _/ \ | , | ioi youis | |

Page : 17 of 52



| Catego | ry : Classroom | | В | uilding | : Main | | Widishan Booke Vitto, Omoago, le 66620 |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|----------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 18 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 880 | SF | 7 | 10+ years | |
| | Storage/ Closet | 3rd Floor | 148 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,215 | SF | 7 | 10+ years | |
| Classroo | om #B-9 (Regular Classroom) | | | | | | |
| | AC Units | Basement | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 835 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | Basement | 835 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 19 | EΑ | 7 | 6-10 years | |
| | Marker Board | Basement | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | Basement | 120 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 1,260 | SF | 7 | 10+ years | |
| _Classroo | om #B3 (Computer Lab) | | | | | | |
| | AC Units | Basement | 1 | EA | 7 | 6-10 years | |
| | Casework | Basement | 48 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 1,208 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | Basement | 1,208 | SF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Basement | 13 | EΑ | 7 | 6-10 years | |
| | Marker Board | Basement | 18 | LF | 7 | 6-10 years | |
| | Storage/ Closet | Basement | 150 | SF | 7 | 10+ years | |
| | Walls - Masonry | Basement | 357 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 1,285 | SF | 7 | 10+ years | |
| | Work Sink | Basement | 1 | EA | 7 | 10+ years | |
| Classroo | om #B6 (Special Program) | | | | | | |
| | AC Units | Basement | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 858 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EΑ | 7 | 10+ years | |
| | Floor - Wood | Basement | 858 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 21 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | Basement | 16 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 1,134 | SF | 7 | 10+ years | |
| | | | | | | | |

Page : 18 of 52



| Catego | ry : Interior | | В | uilding | : Main | | - |
|-----------|--------------------------------------|-----------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Corridor | | | | | | | |
| | Ceiling - Exposed | 1st Floor | 3,170 | SF | 7 | 10+ years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 1st Floor | 3,170 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 3,835 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 3,170 | SF | 7 | 10+ years | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 2nd Floor | 3,170 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 2nd Floor | 30 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 4,055 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 3,170 | SF | 7 | 10+ years | |
| | Drinking Fountains - Double Fountain | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 3rd Floor | 3,170 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 3rd Floor | 252 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 4,053 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 925 | SF | 7 | 10+ years | |
| | Floor - Asphalt Floor | Basement | 925 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 5 | EA | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 872 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 352 | SF | 7 | 10+ years | |
| | Walls - Vinyl Coated Gypsum Panel | Basement | 320 | SF | 7 | 10+ years | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 5 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 4 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| _Otono | Ceiling - Lay-in | North Stair | 342 | SF | 7 | 10+ years | |
| | Floor - Asphalt | North Stair | 342 | SF | 7 | 10+ years | |
| | Handrails | North Stair | 158 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | North Stair | 5 | EA | 7 | 6-10 years | |
| | Stairs - Asphalt | North Stair | 79 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | North Stair | 4,320 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Stairs by main office | 342 | SF | 7 | 10+ years | |
| | Floor - Asphalt | Stairs by main office | 342 | SF | 7 | 10+ years | |
| | Handrails | Stairs by main office | 54 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Stairs by main office | 4 | EA | 7 | 6-10 years | |
| | Stairs - Asphalt | Stairs by main office | 27 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Stairs by main office | 1,584 | SF | 7 | 10+ years | |
| | | | | | | | |

Page : 19 of 52



Building: Main Category: Interior

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments

Campus Name: Spry Community Links High School Page : 20 of 52 Assessment Date: 11/19/2020





Category : Exterior **Building: Addition**

| · | ALC: IOI | | | _ | . Additi | Recommend | |
|-------|-----------------------------------------|-----------------|----------|-----|----------|-------------|------------------|
| Item | - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
|) | | | | | | | |
| Exte | rior Doors - Exterior FRP Door | #2 E | 4 | EA | 6 | 10+ years | |
| Exte | rior Stairs - Concrete | #2 E | 12 | LF | 5 | 1-2 years | Spalling |
| Exte | rior Doors - Exterior Steel Door | #3 S | 4 | EA | 5 | 1-2 years | Dented/corrdoed. |
| Exter | rior Stairs - Concrete | #3 S | 12 | LF | 5 | 1-2 years | Spalling |
| Exter | rior Doors - Exterior Steel Door | #4 Exit W | 3 | EA | 5 | 1-2 years | Corroded. |
| Exte | rior Stairs - Concrete | #4 Exit W | 40 | LF | 5 | 2-5 years | Minor cracking. |
| Exte | rior Doors - Exterior Steel Door | #5 Exit W | 3 | EA | 6 | 10+ years | - |
| Exte | rior Stairs - Concrete | #5 Exit W | 40 | LF | 5 | 2-5 years | Minor cracking. |
| Exte | rior Doors - Exterior Steel Door | #6 W | 4 | EA | 5 | 1-2 years | Rusted/corroded. |
| Exte | rior Stairs - Concrete | #6 W | 12 | LF | 7 | 10+ years | |
| tion | | | | | | | |
| Foun | ndation - Masonry | Entire Building | 561 | LF | 7 | 10+ years | |
| Supe | erstructure - Steel with Clay Tile Arch | Entire Building | 43,640 | SF | 7 | 10+ years | |
| g | | | | | | | |
| | rior Lighting - Parapet or Roof Mounted | Entire Building | 4 | EA | 6 | 6-10 years | |
| Exte | rior Lighting - Wall Mounted | Entire Building | 7 | EA | 6 | 6-10 years | |
| /stem | | | | | | | |
| | ess Ladder - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| Copii | ng - Clay Tile | Main Roof | 474 | LF | 6 | 10+ years | |
| Dow | nspouts - Interior Downspouts | Main Roof | 240 | LF | 6 | 10+ years | |
| | pet - 16" - 30" Height | Main Roof | 119 | LF | 6 | 10+ years | |
| Para | pet - Parapet > 30" | Main Roof | 356 | LF | 6 | 10+ years | |
| Roof | - Modified Bitumen | Main Roof | 7,191 | SF | 6 | 10+ years | |
| Roof | Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| Roof | Structure - Steel with Clay Tile Arch | Main Roof | 7,191 | SF | 7 | 10+ years | |
| | ess Ladder - Metal | Middle Roof | 1 | EA | 7 | 10+ years | |
| Copii | ng - Clay Tile | Middle Roof | 148 | LF | 6 | 10+ years | |
| | nspouts - Interior Downspouts | Middle Roof | 30 | LF | 6 | 10+ years | |
| | pet - Parapet > 30" | Middle Roof | 148 | LF | 6 | 10+ years | |
| | - Modified Bitumen | Middle Roof | 4,597 | SF | 6 | 10+ years | |
| | Hatch - Metal | Middle Roof | . 1 | EA | 7 | 10+ years | |
| Roof | Structure - Steel with Clay Tile Arch | Middle Roof | 4,597 | SF | 7 | 10+ years | |
| | ng - Clay Tile | West Low Roof | 149 | LF | 6 | 10+ years | |
| | nspouts - Interior Downspouts | West Low Roof | 40 | LF | 6 | 10+ years | |
| DOW | pet - Parapet > 30" | West Low Roof | 149 | LF | 6 | 10+ years | |
| | | | | | _ | | |
| Para | - Modified Bitumen | West Low Roof | 4,517 | SF | 6 | 10+ years | |

Page : 21 of 52



| Category : Exterior | | | В | Building : Addition | | | | |
|---------------------|----------------------------------------|-----------------|----------|---------------------|-----------|-------------|----------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Walls | | | | | | | | |
| | Cornice - Masonry Projecting Limestone | Entire Building | 775 | LF | 6 | 10+ years | | |
| | Cornice - Terra Cotta | Entire Building | 360 | LF | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 3,100 | SF | 6 | 10+ years | | |
| | Exterior Walls - Brick | Entire Building | 14,530 | SF | 6 | 10+ years | | |
| | Exterior Walls - Stone-Cast | Entire Building | 420 | SF | 6 | 10+ years | | |
| | Exterior Walls - Stone-Cast | Entire Building | 2,135 | SF | 6 | 10+ years | | |
| Windows | 3 | | | | | | | |
| | Guard - Guards perforated | Entire Building | 2,210 | SF | 7 | 10+ years | | |
| | Lintels - Brick | Entire Building | 135 | LF | 6 | 10+ years | | |
| | Lintels - Steel | Entire Building | 360 | LF | 6 | 10+ years | | |
| | Lintels - Stone | Entire Building | 115 | LF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 4,392 | SF | 6 | 10+ years | | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 488 | SF | 6 | 10+ years | | |
| Catego | rv : Electrical | | R | uildina | : Additio | n . | | |

Category : Electrical Building : Addition

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|--------------------------------------------------------|-----------------|----------|-------|------|-----------------------|------------------------------------|
| • | ncy System | | Quantity | 00141 | Num | . topiacomont | - Commonto |
| mangon | Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building | 6,272 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 8,912 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 4,535 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,800 | SF | 6 | 10+ years | Upgraded since last assessment |
| | Security System - CCTV | Entire Building | 43,640 | SF | 6 | 6-10 years | . • |
| | Security System - Intrusion Detection | Entire Building | 43,640 | SF | 6 | 2-5 years | |
| | Exit Signs - Auditoium | Entire Building | 12 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 17 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Auditoium and Aisle Lighting | Entire Building | 14 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Auditoium and Aisle Lighting | Entire Building | 6 | EA | 4 | 0-1 year | Old and substantially deteriorated |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 19 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Gym | Entire Building | 1 | EA | 6 | 6-10 years | One provided |
| | Emergency Battery Packs - Students Toilets | Entire Building | 5 | EA | 6 | 6-10 years | · |
| Main Sei | vice | | | | | | |
| | PA System | Entire Building | 43,640 | SF | 6 | 6-10 years | Served by Main |

Page : 22 of 52



| Catego | ry : Electrical | | Building : Addition | | | | | |
|-----------|------------------------------------------------------------------------|------------------|---------------------|------------|----------|-------------|-------------------------------------------------------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | | | | | | | | |
| _Power D | vistribution | Father Delibling | | Ε.Δ | | 40 | | |
| | Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A | Entire Building | 2 2 | EA EA | 7 4 | 10+ years | Deterioreted topo utilized to sever | |
| | Lighting and Power Pariets - 100 A | Entire Building | 2 | EA | 4 | 1-2 years | Deteriorated, tape utilized to cover unused breakers. | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 4 | 0-1 year | Live front and unlocked | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 5 | EA | 7 | 10+ years | Live from and amounted | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 6 | 2-5 years | | |
| | | S . | | | | , | | |
| Catego | ry : Fire Protection | | В | uilding | : Additi | on | | |
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Fire Alar | | | | | | | | |
| | Fire Alarm_System | Entire Building | 43,640 | SF | 4 | 0-1 year | More than 40 years of service and | |
| | | | | | | | cannot support strobes or additional | |
| | | | | | | | pulls | |
| Catego | ry : Mechanical | | R | uildina | : Additi | on | | |
| Outogo | . Medianida | | | unung | . Additi | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Air Hand | lling Systems | | Ž | | | • | | |
| | Air Handling Unit- Built Up-Multi Zone- | Mechanical Room | 1 | EA | 5 | 6-10 years | | |
| | Steam Coils - 15001 - 25000 cfm | | | | | , | | |
| | Air Intake | Mechanical Room | 1 | EA | 5 | 6-10 years | | |
| | Auxiliaries - 15001 - 25000 cfm | Mechanical Room | 1 | EA | 4 | 1-2 years | Older components, dampers held | |
| | | | | | | | open, motor aged. Damaged and | |
| | B . B . W . B | | 400 | . – | _ | 40 | potentially abandoned piping at coil. | |
| | Return Duct Work - Masonry and Ducts- | Mechanical Room | 100 | LF | 5 | 10+ years | | |
| | Missing or Existing Shaft Zone Dampers | Mechanical Room | 14 | EA | 5 | 2-5 years | Manually adjusted | |
| | Zone Dampers | Mechanical Room | 17 | LA | 3 | 2-5 years | Manually adjusted | |
| Boiler Sy | /stems | | | | | | | |
| | Condensate Pump | Entire Building | 1 | EA | 6 | 2-5 years | Surface corrosion present. | |
| | Piping - Condensate Pipe- Steel | Entire Building | 400 | LF | 5 | 2-5 years | , | |
| | Piping - Steam Pipe- Steel | Entire Building | 400 | LF | 5 | 2-5 years | | |
| | Steam Traps | Entire Building | 25 | EA | 5 | 2-5 years | | |
| | | | | | | | | |
| _Heating_ | | | | | | | | |
| | Unit Heater - Steam | 2nd Floor | 1 | EA | 5 | 2-5 years | | |
| | Radiators - Steam | 3rd Floor | 1 | EA EA | 5 | 10+ years | No temperature control | |
| | | | α | ⊢ Λ | 6 | 1() ± VA2rc | | |
| | Wall Heater - Electric | Entire Building | 9 | | | 10+ years | | |
| | Wall Heater - Electric Wall Heater - Electric | Entire Building | 3 | EA | 5 | 2-5 years | | |

Page : 23 of 52



| Catego | ry : Mechanical | | В | uildina | : Additi | on | |
|-----------|-----------------------------------------------------|------------------------------------|-----------|----------|----------|-----------------------|---------------------------------------------------------------|
| | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| · | Fin Tube - Steam | Entire Building | 84 | LF | 6 | 6-10 years | Covers in gym missing joint piece between covers. |
| Temper: | ature Control | | | | | | |
| · | Pneumatic System | Entire Building | 43,640 | SF | 4 | 1-2 years | Numerous leaks prevent zone actuators from operating |
| | Thermostats - Pneumatic | Entire Building | 16 | EA | 4 | 1-2 years | Contaminated with oil |
| /entilati | on | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 6 | 6-10 years | Missing rain hood at discharge of far |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 7 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 2 | EA | 7 | 10+ years | Both installed in 10/2020 |
| | Roof Mounted Duct Work Type I Exhaust Hood- Kitchen | Entire Building Entire Building | 100 1 | LF EA | 6 2 | 10+ years 0-1 year | Mostly up the side of the building. Missing fire suppression. |
| Catego | ry : Plumbing | | В | uilding | : Additi | on | |
| | | | | Ŭ | | Recommend | |
| ∃roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| piping_ | | | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 43,640 | SF | 4 | 1-2 years | Original piping with numerous pipe clamps. |
| | Domestic Piping-Cold Water Risers | Entire Building | 43,640 | SF | 4 | 1-2 years | · |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 43,640 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 43,640 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 43,640 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 43,640 | SF | 4 | 1-2 years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 43,640 | SF | 4 | 1-2 years | |
| | Sanitary Piping | Entire Building | 43,640 | SF | 6 | 10+ years | |
| | Storm Piping | Entire Building | 43,640 | SF | 6 | 10+ years | |
| | Vent Piping | Entire Building | 43,640 | SF | 6 | 10+ years | |
| Catego | ry : Room | | В | uilding | : Additi | on | |
| | | Laadaa | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Group | Item - Tyne | I OCATION | | | | | |
| Group | Item - Type trative Suites/Offices | Location | Qualitity | OCIVI | Italik | Replacement | |

Page : 24 of 52



| Catego | ry : Room | | В | uilding | : Additi | on | |
|------------|-----------------------------|-----------------------------------------------------|----------|----------|----------|------------------------|-----------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | 0 ''' | storage) office/MDF rm | 60= | 05 | _ | 40 | |
| | Ceiling - Lay-in | 1st fl next to womens rm (FP | 235 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | storage) office/MDF rm | 4 | EA | 7 | 10 | |
| | Doors - Wood Doors Inclu nw | 1st fl next to womens rm (FP storage) office/MDF rm | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st fl next to womens rm (FP | 235 | SF | 7 | 10+ years | |
| | Floor - Wood | storage) office/MDF rm | 233 | SF | , | 10+ years | |
| | Lighting - Lay-in | 1st fl next to womens rm (FP | 2 | EA | 7 | 6-10 years | |
| | Lighting Lay in | storage) office/MDF rm | _ | L/\ | , | o io years | |
| | Power Distribution | 1st fl next to womens rm (FP | 4 | EA | 7 | 10+ years | |
| | 1 GWGI BIGUIBAUGII | storage) office/MDF rm | • | _, 、 | • | io. youro | |
| | Walls - Plaster/Drywall | 1st fl next to womens rm (FP | 715 | SF | 7 | 10+ years | |
| | , | storage) office/MDF rm | | | | , | |
| | Ceiling - Lay-in | 3rd fl Assistant principals office | 164 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd fl Assistant principals office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd fl Assistant principals office | 164 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd fl Assistant principals office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd fl Assistant principals office | 4 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd fl Assistant principals office | 535 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Room 110A (FP reading rm) | 180 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Room 110A (FP reading rm) | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | Room 110A (FP reading rm) | 180 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Room 110A (FP reading rm) | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Room 110A (FP reading rm) | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Room 110A (FP reading rm) | 681 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | rm 112A (FP work rm) | 180 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | rm 112A (FP work rm) | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | rm 112A (FP work rm) | 180 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | rm 112A (FP work rm) | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | rm 112A (FP work rm) | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | rm 112A (FP work rm) | 610 | SF | 7 | 10+ years | |
| Auditoriu | m & Theater | | | | | | |
| _Auditoriu | Ceiling - Plaster/Drywall | Basement | 6,272 | SF | 6 | 10+ years | Paint chipping and peeling. |
| | Doors - Wood Doors inclu hw | Basement | 8 | SF EA | 7 | 10+ years 10+ years | r and onlyping and peeling. |
| | Floor - Carpet | Basement | 1,217 | SF | 7 | 6-10 years | |
| | Floor - Concrete | Basement | 3,632 | SF | 7 | 10+ years | |
| | Floor - Wood | Basement | 1,423 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 1,423 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Basement | 14 | EA | 7 | 6-10 years | |
| | Main Floor Seating | Basement | 470 | EA | 7 | 10+ years | |
| | Sound System | Basement | 470 | EA | 7 | 6-10 years | |
| | Stage | Basement | 765 | SF | 7 | 10+ years | |
| | Stage Curtain | Basement | 765 6 | EA | 7 | 10+ years | |
| | Olago Oditalii | Dasement | 0 | LA | , | 10+ years | |

Page : 25 of 52



| Catego | ry : Room | | В | uilding | : Addition | | |
|----------|--------------------------------------|------------------------------------|----------|---------|------------|-------------|-----------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Stage Lighting System | Basement | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 5,770 | SF | 6 | 10+ years | Paint chipping and peeling. |
| Gymnas | ia | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 4,535 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 36 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 6 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 4,535 | SF | 7 | 10+ years | |
| | Lighting - Metal Halide/Sodium Vapor | 2nd Floor | 20 | EΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 5,320 | SF | 7 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 280 | SF | 6 | 10+ years | |
| | Floor - Concrete Epoxy/ Painted | Basement | 280 | SF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 5 | ĒΑ | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 725 | SF | 7 | 10+ years | |
| unch & | Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 1,800 | SF | 7 | 10+ years | |
| | Doors - Transom Window | Basement | 36 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | Basement | 1,800 | SF | 6 | 10+ years | |
| | | Basement | 34 | EA | 7 | • | |
| | Lighting - Pendent/Surface | | | | | 6-10 years | |
| | Serving Line | Basement | 36 | LF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement | 1,750 | SF | 7 | 10+ years | |
| /lechani | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 3rd Floor | 18 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 770 | SF | 7 | 10+ years | |
| Prep Ro | | | | | | | |
| | Casework | Prep room shared between 310 & 313 | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | Prep room shared between 310 & 313 | 275 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Prep room shared between 310 & 313 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Prep room shared between 310 & 313 | 275 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Prep room shared between 310 & 313 | 3 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Prep room shared between 310 & 313 | 570 | SF | 7 | 10+ years | |

Page : 26 of 52



| Catego | ory : Room | | В | uilding | : Addition | | |
|--------|---------------------------------|--------------------------------|----------|---------|------------|-------------|----------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Work Sink | Prep room shared between 310 & | 1 | EA | 7 | 6-10 years | |
| | | 313 | | | | | |
| estroo | m | | | | | | |
| | Accessories | 1st fl-girls | 275 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st fl-girls | 275 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st fl-girls | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st fl-girls | 275 | SF | 7 | 10+ years | |
| | Floor Drain | 1st fl-girls | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st fl-girls | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st fl-girls | 3 | EA | 7 | 10+ years | |
| | Lavatory | 1st fl-girls | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st fl-girls | 8 | EA | 7 | 6-10 years | |
| | Partitions | 1st fl-girls | 5 | ĒΑ | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st fl-girls | 132 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st fl-girls | 528 | SF | 7 | 10+ years | |
| | Water Closet | 1st fl-girls | 5 | EA | 7 | 10+ years | |
| | Accessories | 2nd flr Girl's next to 210 | 275 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd fir Girl's next to 210 | 275 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd fir Girl's next to 210 | 9 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 2nd fir Girl's next to 210 | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd fir Girl's next to 210 | 12 | EA | 7 | 10+ years | |
| | | | | SF | 7 | - | |
| | Floor - Tile Ceramic/ Porcelain | 2nd flr Girl's next to 210 | 275 | | | 10+ years | |
| | Floor Drain | 2nd flr Girl's next to 210 | 1 | EΑ | 7 | 10+ years | |
| | Hand Dryer | 2nd flr Girl's next to 210 | 2 | EΑ | 7 | 6-10 years | |
| | Lavatory | 2nd flr Girl's next to 210 | 2 | EΑ | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd flr Girl's next to 210 | 8 | EA | 7 | 6-10 years | |
| | Partitions | 2nd flr Girl's next to 210 | 5 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd flr Girl's next to 210 | 132 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd flr Girl's next to 210 | 528 | SF | 7 | 10+ years | |
| | Water Closet | 2nd flr Girl's next to 210 | 5 | EA | 7 | 10+ years | |
| | Accessories | 3rd flr Girl's next to 310 | 275 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd flr Girl's next to 310 | 275 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd flr Girl's next to 310 | 9 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 3rd flr Girl's next to 310 | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd flr Girl's next to 310 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd flr Girl's next to 310 | 275 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd flr Girl's next to 310 | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd flr Girl's next to 310 | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd flr Girl's next to 310 | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd flr Girl's next to 310 | 8 | EA | 7 | 6-10 years | |
| | Partitions | 3rd flr Girl's next to 310 | 5 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd flr Girl's next to 310 | 132 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd flr Girl's next to 310 | 528 | SF | 7 | 10+ years | |

Page : 27 of 52



| Catego | ry : Room | | В | uilding | : Additi | on | |
|--------|---------------------------------|------------------------------------------|----------|---------|----------|-------------|---------------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | 3rd flr Girl's next to 310 | 5 | EA | 7 | 10+ years | |
| | Accessories | 3rd flr toilet in asst principals office | 44 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd flr toilet in asst principals office | 44 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd flr toilet in asst principals office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd flr toilet in asst principals office | 44 | SF | 6 | 10+ years | |
| | Lavatory | 3rd flr toilet in asst principals office | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd flr toilet in asst principals office | 1 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd flr toilet in asst principals office | 190 | SF | 7 | 10+ years | |
| | Water Closet | 3rd flr toilet in asst principals office | 1 | EA | 7 | 10+ years | |
| | Accessories | Basement | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement | 25 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete | Basement | 25 | SF | 5 | 10+ years | |
| | Lavatory | Basement | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 1 | EA | 7 | 6-10 years | |
| | Walls - Masonry | Basement | 260 | SF | 6 | 10+ years | Concrete - paint chipping and peeling throughout. |
| | Water Closet | Basement | 1 | EA | 7 | 10+ years | 3 |
| | Accessories | Next to girls unisex | 90 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Next to girls unisex | 90 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Next to girls unisex | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Next to girls unisex | 90 | SF | 7 | 10+ years | |
| | Floor Drain | Next to girls unisex | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | Next to girls unisex | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Next to girls unisex | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Next to girls unisex | 2 | EA | 7 | 6-10 years | |
| | Partitions | Next to girls unisex | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Next to girls unisex | 152 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Next to girls unisex | 266 | SF | 7 | 10+ years | |
| | Water Closet | Next to girls unisex | 1 | ĒΑ | 7 | 10+ years | |
| | Accessories | boys- basement | 560 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | boys- basement | 560 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | boys- basement | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | boys- basement | 560 | SF | 7 | 10+ years | |
| | Floor Drain | boys- basement | 1 | ĒΑ | 7 | 10+ years | |
| | Hand Dryer | boys- basement | 2 | EA | 7 | 6-10 years | |
| | Lavatory | boys- basement | 3 | EA | 7 | 10+ years | |
| | Lavatory | boys- basement | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | boys- basement | 8 | EΑ | 7 | 6-10 years | |
| | Partitions | boys- basement | 3 | EA | 7 | 10+ years | |
| | Urinals | boys- basement | 7 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | boys- basement | 267 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | boys- basement | 712 | SF | 7 | 10+ years | |
| | Water Closet | boys- basement | 3 | EA | 7 | 10+ years | |
| | | boyo bacomont | 9 | _, \ | • | io. youro | |

Page : 28 of 52



| Catego | ry : Room | | В | uilding | : Additi | on | |
|---------|---------------------------------|------------------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Accessories | girls - basement | 222 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | girls - basement | 222 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | girls - basement | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | girls - basement | 222 | SF | 7 | 10+ years | |
| | Floor Drain | girls - basement | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | girls - basement | 2 | EA | 7 | 6-10 years | |
| | Lavatory | girls - basement | 1 | EA | 7 | 10+ years | |
| | Lavatory | girls - basement | 3 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | girls - basement | 7 | EA | 7 | 6-10 years | |
| | Partitions | girls - basement | 7 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | girls - basement | 177 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | girls - basement | 472 | SF | 7 | 10+ years | |
| | Water Closet | girls - basement | 7 | ĒΑ | 7 | 10+ years | |
| | Accessories | in rm 114 | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | in rm 114 | 30 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | in rm 114 | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | in rm 114 | 30 | SF | 7 | 10+ years | |
| | Floor Drain | in rm 114 | 1 | ĒΑ | 7 | 10+ years | |
| | Lavatory | in rm 114 | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | in rm 114 | 1 | ΕA | 7 | 6-10 years | |
| | Walls - Tile Ceramic/ Porcelain | in rm 114 | 170 | SF | 7 | 10+ years | |
| | Water Closet | in rm 114 | 1 | EA | 7 | 10+ years | |
| | Accessories | womens - 1st fl | 50 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | womens - 1st fl | 210 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | womens - 1st fl | 50 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | womens - 1st fl | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | womens - 1st fl | 260 | SF | 7 | 10+ years | |
| | Lavatory | womens - 1st fl | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | womens - 1st fl | 2 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | womens - 1st fl | 1 | EA | 7 | 6-10 years | |
| | Partitions | womens - 1st fl | 2 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | womens - 1st fl | 600 | SF | 7 | 10+ years | |
| | Water Closet | womens - 1st fl | 2 | EA | 7 | 10+ years | |
| | vvaldi Olusci | MOHIGHS - 19f II | 2 | ĽA | , | TOT YEARS | |
| atego | ry : Classroom | | В | uilding | : Additi | on | |
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classro | om #111 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 768 | SF | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 8 | SF | 7 | 10+ years | |
| | Deers Weed Deers in deal law | 4-4-Fl | 4 | _ ^ _ ^ | | 10 | |

Page : 29 of 52

1st Floor

1st Floor

1st Floor

EΑ

SF

SF

7

6

7

1

300

468

10+ years

2-5 years

10+ years

Floor - Carpet

Floor - Wood

Doors - Wood Doors inclu hw



| Catego | ry : Classroom | | В | uilding | : Additi | | |
|----------|--------------------------------|------------------------|----------|----------|----------|------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 1st Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 14 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 936 | SF | 7 | 10+ years | |
| lassroc | om #112 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 690 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 250 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 320 | SF | 6 | 2-5 years | |
| | Floor - Wood | 1st Floor | 620 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,102 | SF | 7 | 10+ years | |
| | · | 1001 | 1,102 | O. | , | 101 youro | |
| lassroc | om #113 (Pre School) AC Units | 1st Floor | 2 | EA | 7 | 6.40 years | |
| | | 1st Floor | | LF | 7 | 6-10 years | |
| | Casework | | 11 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 768 | | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 768 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 14 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 936 | SF | 7 | 10+ years | |
| Classroc | om #114 (Pre School) | | | | | | |
| | AC Units | 1st Floor | 1 | EΑ | 7 | 6-10 years | |
| | Casework | 1st Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 940 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Wood | 1st Floor | 940 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 1,102 | SF | 7 | 10+ years | |
| Classroo | om #210 (Special Education) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 420 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor 2nd Floor | 1 | SF EA | 7 | - | |
| | DOOLS - MOOD DOOLS LLICIN LIM | 2110 11001 | 1 | EA | ′ | 10+ years | |

Page : 30 of 52



| Catego | ry : Classroom | | В | uilding | : Additi | on | |
|----------|-----------------------------|-----------|----------|---------|----------|-------------|------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Carpet | 2nd Floor | 420 | SF | 4 | 0-1 year | Carpet torn and repaired with duct tape. |
| | Lighting - Lay-in | 2nd Floor | 6 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 7 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 844 | SF | 6 | 10+ years | |
| Classroo | om #211 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 6 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 768 | SF | 4 | 0-1 year | Old and bubbling. |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 936 | SF | 7 | 10+ years | |
| Classroo | om #212 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 768 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 22 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 936 | SF | 7 | 10+ years | |
| Classroo | nm #213 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 936 | SF | 7 | 10+ years | |
| Classroc | nm #214 (Regular Classroom) | | | | | | |

Page : 31 of 52



| Catego | ry : Classroom | | В | uilding | : Additi | | Warshall Booke VAIND, Officago, IE 00023 |
|-----------|--------------------------------------------|------------------------|------------|----------|----------|-------------|------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 26 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 2nd Floor | 6 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 2nd Floor | 768 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EΑ | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 936 | SF | 7 | 10+ years | |
| Classroo | om #310 (Science Lab Level 1) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 72 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | - 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 14 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 25 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Science Lab Fume Hood | 3rd Floor | 1,002 | EA | 7 | 10+ years | |
| | Science Lab Fully Flood Science Lab Shower | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,100 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 8 | EA | 7 | 6-10 years | |
| | WORKSHIK | Sid Flooi | 0 | LA | 1 | 0-10 years | |
| _Classroo | om #311/313 (Science Lab Level 2) | 0.15 | | - | | 0.40 | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 72 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EΑ | 7 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | 14 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Science Lab Elements | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor 3rd Floor | 1,073 8 | SF EA | 7 7 | 10+ years | |
| | Work Sink | | | | | 6-10 years | |

Page : 32 of 52



| Catego | ry : Classroom | | В | uildina | : Addition | on | |
|----------|------------------------------------------|-----------|----------|----------|------------|-------------|----------|
| | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | m #314 (Regular Classroom) | | • | | | • | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 768 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Wood | 3rd Floor | 768 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 43 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 936 | SF | 7 | • | |
| | walls - Plaster/Drywall | 310 F1001 | 930 | SF | 1 | 10+ years | |
| Catego | ry : Interior | | В | uildina | : Additio | on | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | _ | |
| | Ceiling - Lay-in | 1st Floor | 1,965 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 1st Floor | 2 | ĒΑ | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 1st Floor | 1,965 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 10 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 2,650 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,965 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 2nd Floor | 1,965 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 10 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,650 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,965 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 55 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Fountain | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | 3rd Floor | 1,965 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 55 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 10 | EA | 5 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 3rd Floor | 2,650 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Basement | 2,413 | SF | 6 | 10+ years | |
| | Drinking Fountains - Double Water Cooler | Basement | 2,413 | SF EA | 7 | 6-10 years | |
| | Floor - Asphalt Floor | Basement | 2,325 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | | | SF SF | | | |
| | | Basement | 88 | SF EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Basement | 9 | SF | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | Basement | 2,650 | 5F | 6 | 10+ years | |
| | | | | | | | |
| Safety | | | | | | | |

Page : 33 of 52



| Catego | ry : Interior | | В | uilding | : Additi | on | |
|--------|----------------------------|-----------------|----------|---------|----------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Security Cameras | Entire Building | 5 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| | Ceiling - Lay-in | South Stairs | 342 | SF | 6 | 10+ years | |
| | Floor - Asphalt | South Stairs | 342 | SF | 6 | 10+ years | |
| | Handrails | South Stairs | 158 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | South Stairs | 6 | EΑ | 6 | 6-10 years | |
| | Stairs - Asphalt | South Stairs | 79 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | South Stairs | 4,320 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Southwest Stair | 342 | SF | 6 | 10+ years | |
| | Floor - Asphalt | Southwest Stair | 342 | SF | 6 | 10+ years | |
| | Handrails . | Southwest Stair | 158 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Southwest Stair | 6 | EA | 6 | 6-10 years | |
| | Stairs - Asphalt | Southwest Stair | 79 | LF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Southwest Stair | 4,320 | SF | 6 | 10+ years | |

Page : 34 of 52





Category : Exterior **Building: Leased-Branch (Spry HS)**

| | | | | | Recommend | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-------------------------------------|----------------------|------------------|--------------------------------------------------|---------------------------|
| oup Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ance | | 4.00 | | | | |
| Exterior Doors - Exterior Steel Door | Courtyard North | 1 | EA | 6 | 10+ years | |
| Exterior Doors - Exterior Wood Door | Courtyard West | 1 | EA | 5 | 0-1 year | Corroded. |
| Exterior Doors - Transom Lite | Courtyard West | 1 | EA | 6 | 6-10 years | Corroded. |
| Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door | East | 2 | EA | 6 | 10+ years | |
| Exterior Doors - Exterior Steel Door | Main South | 2 | EA | 7 | • | |
| Exterior Doors - Store Front | Main South | | EA | 6 | 10+ years | |
| Exterior Doors - Store Front Exterior Doors - Transom Lite | Main South | 2 | EA EA | 7 | 10+ years 10+ years | |
| Ramp Handrail - Steel_Ramp Handrail | Main South | 55 | LF | 6 | • | |
| | | 35 35 | LF LF | | 10+ years | Cracking throughout |
| Ramps - Concrete | Main South | 35 | | 5 | 0-1 year | Cracking throughout. |
| Exterior Doors - Exterior Steel Door | North - east | 1 | EΑ | 5 | 1-2 years | Door dented throughout. |
| Exterior Doors - Exterior Steel Door | North - west | 1 | EΑ | 6 | 10+ years | |
| Exterior Doors - Exterior Wood Door | Southeast | 2 | EA | 6 | 10+ years | |
| Exterior Stairs - Concrete | Southeast | 12 | LF | 7 | 10+ years | |
| undation | | | | | | |
| Foundation - Concrete | Entire Building | 235 | LF | 7 | 10+ years | No exposed foundation |
| Superstructure - Metal Deck/ Concrete | Entire Building | 44,252 | SF | 7 | 10+ years | · |
| Topping | 3 | , | | | , | |
| | | | | | | |
| ghting | | | | | | |
| Exterior Lighting - Lighting | Entire Building | 28 | EA | 4 | 2-5 years | Soffit, may not be in use |
| Exterior Lighting - Parapet or Roof Mounted | Entire Building | 13 | EA | 7 | 10+ years | Newer LED |
| of System | | | | | | |
| Coping - Metal | Roof 1 | 323 | LF | 7 | 10+ years | |
| Downspouts - Interior Downspouts | Roof 1 | 100 | LF | 7 | 10+ years | |
| Roof - PVC Membrane | Roof 1 | 6,235 | SF | 7 | 10+ years | Covered in snow |
| Roof Structure - Steel / Metal Deck/ | Roof 1 | 6,235 | SF | 7 | 10+ years | |
| Concrete Topping | | 0,200 | • | • | .o. youro | |
| Chimney - Brick Chimney- Concrete/ Mortar | Roof 2 | 30 | LF | 7 | 10+ years | |
| Liner | 11001 2 | | | • | ioi youro | |
| | Roof 2 | 210 | LF | 7 | 10+ years | |
| | | | | | 10+ years | |
| Coping - Metal | | | IF | 7 | IU+ VEAIS | |
| Coping - Metal Downspouts - Interior Downspouts | Roof 2 | 100 | LF SF | 7 7 | | Covered in snow |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane | Roof 2 Roof 2 | 100 5,690 | SF | 7 | 10+ years | Covered in snow |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane Roof Structure - Steel / Metal Deck/ | Roof 2 | 100 | | | | Covered in snow |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof 2 Roof 2 Roof 2 | 100 5,690 5,690 | SF SF | 7 7 | 10+ years 10+ years | Covered in snow |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane Roof Structure - Steel / Metal Deck/ Concrete Topping Coping - Metal | Roof 2 Roof 2 Roof 3 | 100 5,690 5,690 | SF SF LF | 7 7 7 | 10+ years 10+ years 10+ years | Covered in snow |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane Roof Structure - Steel / Metal Deck/ Concrete Topping Coping - Metal Downspouts - Exterior Downspouts | Roof 2 Roof 2 Roof 3 Roof 3 | 100 5,690 5,690 120 100 | SF SF LF LF | 7 7 7 6 | 10+ years 10+ years 10+ years 10+ years | |
| Coping - Metal Downspouts - Interior Downspouts Roof - PVC Membrane Roof Structure - Steel / Metal Deck/ Concrete Topping Coping - Metal | Roof 2 Roof 2 Roof 3 | 100 5,690 5,690 | SF SF LF | 7 7 7 | 10+ years 10+ years 10+ years | Covered in snow |

Page : 35 of 52



| Category : Exterior | | | | Building : Leased-Branch (Spry HS) | | | |
|---------------------|----------------------------------------------------------|------------------|------------------------------------|------------------------------------|--------|------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Access Ladder - Metal | Roof 4 | 1 | EΑ | 7 | 10+ years | |
| | Chimney - Brick Chimney- Concrete/ Mortar | Roof 4 | 60 | LF | 6 | 10+ years | |
| | Liner | | | | | | |
| | Chimney - Metal Flue | Roof 4 | 5 | LF | 7 | 10+ years | |
| | Coping - Metal | Roof 4 | 390 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof 4 | 100 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Roof 4 | 7,090 | SF | 5 | 10+ years | Covered in snow |
| | Roof Structure - Steel / Metal Deck/ | Roof 4 | 7,090 | SF | 7 | 10+ years | |
| | Concrete Topping | Doof E | 140 | | 7 | 10 | |
| | Coping - Metal | Roof 5 Roof 5 | 140 | LF LF | 7 | 10+ years | |
| | Downspouts - Exterior Downspouts Roof - Modified Bitumen | Roof 5 | 20 7,090 | SF | 6 6 | 10+ years 10+ years | Covered in snow |
| | Roof Structure - Steel / Metal Deck/ | Roof 5 | 7,090 | SF | 7 | 10+ years | Covered III Show |
| | Concrete Topping | 10013 | 7,090 | OI. | , | TOT years | |
| | Concrete Topping | | | | | | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 10,850 | SF | 7 | 10+ years | |
| | Exterior Walls - Concrete Block | Entire Building | 1,200 | SF | 7 | 10+ years | Poured in place concrete |
| \ | | | | | | | |
| Windows | Curtain wall - Glazed Single Pane | Entire Building | 3,615 | SF | 4 | 0-1 year | Poor insulation, leaking windows, |
| | ourtain num olu_ou olligio i ulio | 9 | 3,0.0 | ٠. | • | o . you. | corrosion |
| | Curtain wall - Insulated Panel | Entire Building | 963 | SF | 4 | 1-2 years | Obsolete system, likely not insulated |
| | | • | | | | | corrosion |
| | Lintels - Steel | Entire Building | 6 | LF | 6 | 10+ years | |
| | Skylite - Lexan | Entire Building | 575 | SF | 6 | 10+ years | |
| | Windows - Louver | Entire Building | 25 | SF | 7 | 10+ years | |
| Catego | ry : Electrical | | Building : Leased-Branch (Spry HS) | | | | |
| | , | | | | | Recommend | , |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerger | ncy System | | | | | | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 15 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Gym | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 39,050 | SF | 7 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 39,050 | SF | 5 | 2-5 years | The motion sensors are outdated but functional however any malfunction would require replacement, the parts are no longer available. |
| | Exit Signs - Auditoium | Entire Building | 2 | EA | 4 | 1-2 years | Lettering worn and difficult to read. |
| | EXIL SIGHS - AUGICOLONI | | | | | | |
| | Exit Signs - Addition Exit Signs - Corridors and Stairs | Entire Building | 12 | ΕA | 4 | 1-2 years | Lettering worn and difficult to read. |

Page : 36 of 52



| Catego | ry : Electrical | | В | uilding | : Lease | d-Branch (Spry | / HS) |
|----------|-----------------------------------------------------------|-----------------|----------|---------|---------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | |
| | Exit Signs - Pool | Entire Building | 3 | EA | 4 | 1-2 years | Lettering worn and difficult to read. |
| /lain Se | rvice | | | | | | |
| | Main Electrical Service - 800 A and Less than 120/208/3PH | Basement | 1 | EA | 4 | 2-5 years | Functional but very old. |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 6 | 2-5 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | 0-1 year | Serves the pool. Heavily corroded, might pose risks for operators. The building engineer uses the breakers to switch on/off the lights in the poor room. |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 2-5 years | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 2-5 years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 4 | 0-1 year | Exposed wiring |
| Catego | ry : Fire Protection | | В | uilding | : Lease | d-Branch (Spry | / HS) |
| | | | | | | Recommend | • |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ire Alar | m | | | | | | |
| | Fire Alarm Panel | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Fire Alarm Strobe Lights | 1st Floor | 39,050 | SF | 7 | 6-10 years | |
| | Fire Alarm_System | 1st Floor | 39,050 | SF | 7 | 6-10 years | |
| Catego | ry : Mechanical | | В | uilding | : Lease | d-Branch (Spry | / HS) |
| | | | | | | Recommend | |
| ≩roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Cond | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | 6-10 years | Roof was inaccessible at time of assessment due to heavy snow fall Condition based on conversation w building engineer and condition of interior fan coil unit section. |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 5 | 2-5 years | Roof was inaccessible at time of assessment due to heavy snow fal Condition based on conversation while building engineer and condition of interior fan coil unit section. |

Page : 37 of 52



| Catego | ry : Mechanical | | В | uilding | : Lease | d-Branch (Spr | / HS) |
|----------|----------------------------------------------------------------------------------------------|------------------------|----------|----------|---------|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | 0 | 11014 | | Recommend | • |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | lling Systems | | | | | | |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm | 2nd Floor | 1 | EA | 4 | 1-2 years | Unit is corroded and old. |
| | Air Intake | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm | 2nd Floor | 1 | EA | 5 | 2-5 years | |
| | Air Intake | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM | 2nd Floor | 1 | EA | 5 | 6-10 years | Serves the pool |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm | 2nd Floor | 1 | EA | 5 | 2-5 years | Serves the 2nd floor IT room. Some of the steam valves are leaking. Overall the maintenance is poor, the building relies more and more on the rooftop units, the older systems being kept as reserve capacity. Ball bearings might need replacement and proper lubrication. The motors appear to be functional. The transmission belts seem functional however there is no evidence available about the date of last replacement. Some of the pulleys need verification and proper maintenance |
| | Air Intake Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM | 2nd Floor 2nd Floor | 1 1 | EA EA | 6 5 | 6-10 years 6-10 years | Motor is very old. |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | 2nd Floor | 1 | EA | 5 | 6-10 years | Motor is very old. |
| | Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM | 2nd Floor | 2 | EA | 5 | 6-10 years | Serve men and women locker rooms |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm | 2nd Floor | 1 | EA | 5 | 2-5 years | |
| | Air Intake | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | 2nd Floor | 1 | EA | 5 | 6-10 years | Motor is very old. |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - Less than 4000 cfm | Basement | 1 | EA | 4 | 1-2 years | Unit is corroded and not meant for pool service. Ductwork insulation deteriorated and missing. |
| | Air Intake | Basement | 1 | EA | 6 | 6-10 years | |
| | Fan Coil Unit- Celing Mounted - Electric | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Fan Coil Unit- Celing Mounted - Electric | Entire Building | 1 | EA | 5 | 2-5 years | |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons | Roof | 1 | EA | 7 | 10+ years | Installed October 2020. Roof was inaccessible at time of assessment due to heavy snow fall. |

Page : 38 of 52



| Catego | ry : Mechanical | | В | uilding | : Lease | d-Branch (Spry | / HS) |
|-------------|---------------------------------------------------------------------------------------------|-----------------|----------|---------|---------|----------------|----------------------------------------------------------------------------------------------------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 5 - 10 tons | Roof | 1 | EA | 7 | 10+ years | Installed October 2020. Roof was inaccessible at time of assessment due to heavy snow fall. |
| Boiler Sy | vstems | | | | | | |
| , | Boiler Auxiliary- Steam Boiler - 101 - 150 HP | Boiler Room | 1 | EA | 7 | 10+ years | |
| | Boiler Auxiliary- Steam Boiler - 101 - 150 HP | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 2 | EA | 5 | 2-5 years | The dampers are functional however they are not properly maintained. One of the units is permanently open, no control available. |
| | Condensate Pump | Boiler Room | 2 | EA | 5 | 6-10 years | |
| | Non Condensing- Cast Iron- Atmospheric- Steam Boiler - 101 - 150 HP | Boiler Room | 1 | EA | 7 | 10+ years | Installed in 2020 |
| | Non Condensing- Cast Iron- Atmospheric- Steam Boiler - 101 - 150 HP | Boiler Room | 1 | EA | 6 | 2-5 years | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 350 | LF | 6 | 6-10 years | |
| | Piping - Steam Pipe- Steel | Boiler Room | 350 | LF | 6 | 6-10 years | |
| _Heating_ | | | | | | | |
| | Fin Tube - Steam | Entire Building | 520 | LF | 5 | 6-10 years | |
| _Tempera | ature Control | | | | | | |
| | Electric Thermostat | Entire Building | 2 | EA | 7 | 10+ years | These thermostats serve the gymnasium only |
| | Pneumatic System | Entire Building | 39,050 | SF | 7 | 10+ years | Installed recently |
| | Thermostats - Pneumatic | Entire Building | 20 | EA | 7 | 10+ years | New thermostats, most of them installed last year |
| _Ventilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Roof | 1 | EA | 5 | 2-5 years | Toilet exhaust fan |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 2 | EA | 6 | 6-10 years | Roof was inaccessible at time of assessment due to heavy snow fall. Condition based on conversation with building engineer. |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 1 | EA | 6 | 6-10 years | Roof was inaccessible at time of assessment due to heavy snow fall. Condition based on conversation with building engineer. |
| | Roof Mounted Duct Work | Roof | 100 | LF | 6 | 10+ years | 5 5 |
| | Type II Exhaust Hood- Warming Kitchen | Roof | 1 | EA | 5 | 6-10 years | |

Page : 39 of 52



| Catego | ry : Plumbing | | В | Building : Leased-Branch (Spry HS) | | | | | |
|----------|----------------------------------------------------|-------------------|----------|------------------------------------|---------|----------------|----------|--|--|
| | _ | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Hot Wat | | | | | | | | | |
| | Electric Heater - Less than 20 KW | Basement | 1 | EA | 6 | 6-10 years | | | |
| | Gas Heater - Greater than 600000 BTU/HR | Boiler Room | 1 | EA | 6 | 10+ years | | | |
| | Hot Water Storage Tank_Gas - 501 - 1000 | Boiler Room | 1 | EA | 6 | 6-10 years | | | |
| | Gallons | | | | | | | | |
| Piping | | | | | | | | | |
| | Domestic Piping-Cold Water Horizontal | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Lines | | 00.050 | 0.5 | _ | 40 | | | |
| | Domestic Piping-Cold Water Risers | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Fixtures | | | | | | | | |
| | Sanitary Piping | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Storm Piping | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| | Vent Piping | Entire Building | 39,050 | SF | 6 | 10+ years | | | |
| Pool Sys | stems | | | | | | | | |
| | Pool Drain Piping | Basement | 100 | LF | 6 | 10+ years | | | |
| | Pool Filtration System including Pump | Basement | 1 | EA | 6 | 6-10 years | | | |
| | Pool Hot Water Heater - Gas Fired | Basement | 1 | EA | 6 | 10+ years | | | |
| | Pool Supply and Return Piping | Basement | 250 | LF | 6 | 10+ years | | | |
| Pumps | | | | | | | | | |
| | Pumps - Sump-Simplex | Basement | 2 | EA | 6 | 6-10 years | | | |
| Catego | ry : Room | | В | uilding | : Lease | d-Branch (Spry | (HS) | | |
| | | | | | | Recommend | • | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Administ | rative Suites/Offices | | | | | | | | |
| | Ceiling - Exposed | 21 Century Office | 108 | SF | 7 | 10+ years | | | |
| | Doors - Side-lite | 21 Century Office | 32 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | 21 Century Office | 6 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 21 Century Office | 2 | ĒΑ | 7 | 6-10 years | | | |
| | | 04.0 | 400 | | | 40 | | | |

21 Century Office

Walls - Concrete Block

Lighting - Pendent/Surface Power Distribution

Floor - Tile

Storage/ Closet

10+ years

6-10 years

10+ years

10+ years

10+ years

SF

EΑ

EΑ

SF

SF

7

7

7

7

108

1

6

30

310



| Catego | ry : Room | | В | uilding | : Lease | d-Branch (Spry | / HS) |
|--------|-----------------------------|------------------|----------|----------|---------|----------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Splined | 2nd Floor office | 121 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor office | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor office | 121 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor office | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | 2nd Floor office | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor office | 220 | SF | 7 | 10+ years | |
| | AC Unit | CLHS Office 206A | 1 | EA | 7 | 2-5 years | |
| | Ceiling - Splined | CLHS Office 206A | 240 | SF | 6 | 2-5 years | |
| | Doors - Wood Doors inclu hw | CLHS Office 206A | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | CLHS Office 206A | 240 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | CLHS Office 206A | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | CLHS Office 206A | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | CLHS Office 206A | 500 | SF | 7 | 10+ years | |
| | Ceiling - Exposed | Conference Room | 206 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Conference Room | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Carpet | Conference Room | 206 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Conference Room | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Conference Room | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Conference Room | 300 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Conference Room | 120 | SF | 7 | 10+ years | |
| | AC Unit | Directors Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | Directors Office | 270 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Directors Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Directors Office | 270 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Directors Office | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | Directors Office | 6 | EA | 6 | 6-10 years | |
| | Storage/ Closet | Directors Office | 30 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Directors Office | 1,200 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Exercise Room | 500 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Exercise Room | 2 | EA | 6 | • | |
| | Floor - Wood | Exercise Room | 500 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Exercise Room | 6 | EA | 6 | 10+ years | |
| | Power Distribution | Exercise Room | 4 | EA | 6 | 6-10 years | |
| | | | | | _ | 6-10 years | |
| | Storage/ Closet | Exercise Room | 80 | SF SF | 5 | 10+ years | |
| | Walls - Concrete Block | Exercise Room | 240 | SF SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Exercise Room | 400 | | 6 | 10+ years | |
| | Work Sink | Exercise Room | 1 | EA | 7 | 10+ years | |
| | Ceiling - Splined | Game Room | 920 | SF | 6 | 10+ years | |
| | Doors - Transom Window | Game Room | 300 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Game Room | 3 | EA | 6 | 10+ years | |
| | Floor - Tile | Game Room | 916 | SF | 6 | 10+ years | 0 11 |
| | Floor - Tile | Game Room | 4 | SF | 4 | 0-1 year | Cracking |
| | Lighting - Lay-in | Game Room | 15 | EA | 6 | 6-10 years | |
| | Power Distribution | Game Room | 8 | EA | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | Building : Leased-Branch (Spry HS) | | | | | | |
|------------|-----------------------------|---------------------|------------------------------------|-----|------|-------------|----------|--|--|
| _ | | | | _ | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Walls - Masonry | Game Room | 2,000 | SF | 6 | 10+ years | | | |
| | Ceiling - Lay-in | Main Office | 102 | SF | 6 | 10+ years | | | |
| | Doors - Transom Window | Main Office | 115 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Main Office | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | Main Office | 102 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | Main Office | 2 | EA | 6 | 6-10 years | | | |
| | Power Distribution | Main Office | 2 | EA | 6 | 6-10 years | | | |
| | Storage/ Closet | Main Office | 40 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | Main Office | 115 | SF | 6 | 10+ years | | | |
| | AC Unit | Teen Center | 1 | EA | 7 | 6-10 years | | | |
| | Ceiling - Splined | Teen Center | 518 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Teen Center | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile | Teen Center | 518 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | Teen Center | 10 | EA | 6 | 6-10 years | | | |
| | Power Distribution | Teen Center | 6 | EA | 6 | 6-10 years | | | |
| | Walls - Masonry | Teen Center | 1,600 | SF | 6 | 10+ years | | | |
| _Auditoriu | ım & Theater | | | | | | | | |
| | Ceiling - Splined | Theater / lunchroom | 2,720 | SF | 6 | 10+ years | | | |
| | Doors - Side-lite | Theater / lunchroom | 20 | SF | 7 | 10+ years | | | |
| | Doors - Transom Window | Theater / lunchroom | 110 | SF | 7 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | Theater / lunchroom | 5 | EA | 7 | 10+ years | | | |
| | Floor - Tile | Theater / lunchroom | 2,720 | SF | 7 | 10+ years | | | |
| | Lighting - Pendent/Surface | Theater / lunchroom | 8 | EA | 7 | 6-10 years | | | |
| | Sound System | Theater / lunchroom | 1 | EA | 7 | 6-10 years | | | |
| | Stage | Theater / lunchroom | 950 | SF | 7 | 6-10 years | | | |
| | Stage Lighting System | Theater / lunchroom | 2 | EA | 7 | 6-10 years | | | |
| | Stage-Stairs - Wood | Theater / lunchroom | 1 | LF | 7 | 10+ years | | | |
| | Stairs - Wood | Theater / lunchroom | 5 | LF | 7 | 10+ years | | | |
| | Storage/ Closet | Theater / lunchroom | 240 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Theater / lunchroom | 3,200 | SF | 7 | 10+ years | | | |
| _Gymnas | ia | | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 4,600 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EΑ | 7 | 10+ years | | | |
| | Floor - Wood | 1st Floor | 4,600 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | [′] 18 | EA | 7 | 6-10 years | | | |
| | Scoreboards | 1st Floor | 1 | EA | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 115 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 10,200 | SF | 7 | 10+ years | | | |
| _Kitchen_ | | | | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 321 | SF | 7 | 10+ years | | | |
| | | | | | | | | | |



| Catego | ry : Room | В | uildina | : Lease | d-Branch (Spr | / HS) | |
|-----------|---------------------------------|--------------------------|------------|----------|---------------|-------------|-----------------------------------------------|
| | ., | | _ | | | Recommend | , |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 321 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EΑ | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 15 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 550 | SF | 7 | 10+ years | |
| | | | | | | , | |
| _Locker/S | Shower Room | | | | | | |
| | Accessories | 1st Floor Boys Lockeroom | 550 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1st Floor Boys Lockeroom | 20 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor Boys Lockeroom | 550 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor Boys Lockeroom | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boys Lockeroom | 550 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor Boys Lockeroom | 3 | ĒΑ | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Boys Lockeroom | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor Boys Lockeroom | 1 | ΕA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Boys Lockeroom | 8 | EΑ | 6 | 6-10 years | |
| | Partitions | 1st Floor Boys Lockeroom | 2 | EA | 7 | 10+ years | |
| | Showers | 1st Floor Boys Lockeroom | 11 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | 1st Floor Boys Lockeroom | 52 | EA | 6 | 10+ years | |
| | Urinals | 1st Floor Boys Lockeroom | 2 | EA | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor Boys Lockeroom | 2,000 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor Boys Lockeroom | 2,000 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor Girls | 550 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1st Floor Girls | 30 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor Girls | 550 550 | SF | 6 | | |
| | Doors - Wood Doors inclu hw | | | | | 10+ years | |
| | | 1st Floor Girls | 2 | EA SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Girls | 550 | | 6 | 10+ years | |
| | Floor Drain | 1st Floor Girls | 5 | EΑ | 7 | 10+ years | |
| | Hand Dryer | 1st Floor Girls | 1 | EΑ | 7 | 6-10 years | |
| | Lavatory | 1st Floor Girls | 2 | EΑ | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor Girls | 12 | EA | 6 | 6-10 years | |
| | Partitions | 1st Floor Girls | 1 | EA | 7 | 10+ years | |
| | Showers | 1st Floor Girls | 8 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | 1st Floor Girls | 60 | EA | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor Girls | 2,000 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor Girls | 2 | EA | 6 | 10+ years | |
| Mechan | ical/ Service Rooms | | | | | | |
| _wecnan | Boiler Room | 1st Floor | 900 | SF | 7 | 10+ years | |
| | | | 35 | SF SF | 7 | - | |
| | Janitor's Closet | 1st Floor | | | | 10+ years | |
| | Storage Room | 1st Floor | 40 | SF | 7 | 10+ years | Head to be a vesture on 15 miles of |
| | Janitor's Closet | 2nd Floor | 16 | SF | 7 | 10+ years | Used to be a restroom / inside dance room 209 |
| | Storage Room | 2nd Floor | 237 | SF | 7 | 10+ years | 133.11.200 |
| | - | | | | | - | |



| Catego | ry : Room | | Building : Leased-Branch (Spry HS) | | | | | | |
|----------|-------------------------------------------------------|---------------------------------|------------------------------------|----------|------|-------------|----------|--|--|
| _ | | | | | | Recommend | _ | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Pool & N | atatorium | | | | | | | | |
| | Accessories | 1st Floor | 4,300 | SF | 7 | 6-10 years | | | |
| | Bleachers Seating/Plank Seating | 1st Floor | 30 | EA | 6 | 10+ years | | | |
| | Ceiling - Lay-in | 1st Floor | 4,300 | SF | 6 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 4,300 | SF | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 36 | EA | 6 | 6-10 years | | | |
| | Pool Basin | 1st Floor | 1 | SF | 6 | 10+ years | | | |
| | Pool Deck Drains | 1st Floor | 16 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | 1st Floor | 35 | SF | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 1st Floor | 3,500 | SF | 6 | 10+ years | | | |
| | Walls - Haster/Brywall Walls - Structural Glazed Tile | 1st Floor | 3,500 | SF | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 151 F1001 | 3,300 | SF | O | 10+ years | | | |
| Restroor | n | | | | | | | | |
| | Accessories | 1st Floor | 275 | SF | 7 | 6-10 years | | | |
| | Ceiling - Lay-in | 1st Floor | 275 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor | 275 | SF | 6 | 10+ years | | | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | | | |
| | Lavatory | 1st Floor | 4 | EA | 6 | 10+ years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 4 | EA | 6 | 6-10 years | | | |
| | Partitions | 1st Floor | 3 | EA | 7 | 10+ years | | | |
| | Urinals | 1st Floor | 5 | EA | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,200 | SF | 6 | 10+ years | | | |
| | Water Closet | 1st Floor | 3 | EA | 6 | 10+ years | | | |
| | Accessories | 1st Floor Across Game Room | 150 | SF | 7 | 6-10 years | | | |
| | Ceiling - Splined | 1st Floor Across Game Room | 150 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor Across Game Room | 130 | EA | 6 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor Across Game Room | 150 | SF | 6 | 10+ years | | | |
| | Hand Dryer | 1st Floor Across Game Room | 150 | EA | 7 | 6-10 years | | | |
| | Lavatory | 1st Floor Across Game Room | 2 | EA | 6 | 10+ years | | | |
| | | | 2 | EA | 6 | | | | |
| | Lighting - Lay-in | 1st Floor Across Game Room | | | | 6-10 years | | | |
| | Partitions | 1st Floor Across Game Room | 2 | EA SF | 7 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor Across Game Room | 1,270 | | 6 | 10+ years | | | |
| | Water Closet | 1st Floor Across Game Room | 2 | EA | 6 | 10+ years | | | |
| | Accessories | 1st Floor Mens Across Game Room | 75 | SF | 7 | 6-10 years | | | |
| | Ceiling - Splined | 1st Floor Mens Across Game Room | 75 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor Mens Across Game Room | 1 | EA | 6 | 10+ years | | | |
| | Floor - Terrazzo | 1st Floor Mens Across Game Room | 75 | SF | 6 | 10+ years | | | |
| | Hand Dryer | 1st Floor Mens Across Game Room | 1 | EA | 7 | 6-10 years | | | |
| | Lavatory | 1st Floor Mens Across Game Room | 1 | EA | 6 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor Mens Across Game Room | 1 | EA | 6 | 6-10 years | | | |
| | Partitions | 1st Floor Mens Across Game Room | 1 | EA | 7 | 10+ years | | | |



| Catego | ry : Room | Building : Leased-Branch (Spry HS) | | | | | |
|-----------|---------------------------------|------------------------------------|----------|---------|---------|----------------|----------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Structural Glazed Tile | 1st Floor Mens Across Game Room | 215 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor Mens Across Game Room | 1 | EA | 6 | 10+ years | |
| | Accessories | Girls Restroom | 190 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Girls Restroom | 190 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Girls Restroom | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Girls Restroom | 190 | SF | 6 | 10+ years | |
| | Hand Dryer | Girls Restroom | 1 | EΑ | 7 | 6-10 years | |
| | Lavatory | Girls Restroom | 3 | EΑ | 6 | 10+ years | |
| | Lighting - Lay-in | Girls Restroom | 2 | EA | 6 | 6-10 years | |
| | Partitions | Girls Restroom | 3 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Girls Restroom | 1,200 | SF | 6 | 10+ years | |
| | Water Closet | Girls Restroom | 3 | EA | 6 | 10+ years | |
| Catego | ry : Classroom | | В | uilding | : Lease | d-Branch (Spry | / HS) |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EΑ | 7 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 340 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 350 | SF | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 10+ years | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 350 | SF | 7 | 10+ years | |
| Classroo | om #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 350 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 350 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 500 | SF | 7 | 10+ years | |
| _Classroo | om #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 731 | SF | 6 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 731 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 11 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | | | _ | | | , | |
| | | | | | | | |



| Category : Classroom | | | Building : Leased-Branch (Spry HS) | | | | | |
|----------------------|-----------------------------|-------------|------------------------------------|----------|------|------------|----------|--|
| | | | | _ | | Recommend | , | |
| Group | Item - Type | Location | Quantity | UOM | Rank | | Comments | |
| | Walls - Concrete Block | 2nd Floor | 700 | SF | 7 | 10+ years | | |
| Classro | om #204 (Regular Classroom) | | | | | | | |
| Classio | AC Units | 2nd Floor | 4 | ΓΛ | 7 | 0.40 | | |
| | | | 1 | EA | 7 | 6-10 years | | |
| | Ceiling - Splined | 2nd Floor | 230 | SF SF | 6 | 10+ years | | |
| | Doors - Transom Window | 2nd Floor | 40 | | 7 | 6-10 years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 230 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 4 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd Floor | 450 | SF | 7 | 10+ years | | |
| _Classroo | om #205 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Ceiling - Splined | 2nd Floor | 600 | SF | 6 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 600 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 6 | EA | 7 | 6-10 years | | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | | |
| | Walls - Masonry | 2nd Floor | 280 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 500 | SF | 7 | 10+ years | | |
| Classra | om #206 (Science Classroom) | | | | | | | |
| Classio | , | 0-15 | | Ε, | 7 | 0.40 | | |
| | AC Units | 2nd Floor | 3 | EA | 7 | 6-10 years | | |
| | Casework | 2nd Floor | 40 | LF | 7 | 10+ years | | |
| | Ceiling - Splined | 2nd Floor | 1,000 | SF | 7 | 10+ years | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 3 | EA | 7 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 1,000 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd Floor | 300 | SF | 7 | 10+ years | | |
| | Walls - Masonry | 2nd Floor | 220 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 250 | SF | 7 | 10+ years | | |
| | Work Sink | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| Classroo | om #207 (Computer Lab) | | | | | | | |
| | Ceiling - Exposed | 2nd Floor | 2,220 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EΑ | 7 | 10+ years | | |
| | Floor - Tile | 2nd Floor | 2,220 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 49 | EΑ | 7 | 6-10 years | | |
| | Walls - Masonry | 2nd Floor | 1,140 | SF | 7 | 10+ years | | |
| | Walls - Plaster/Drywall | 2nd Floor | 200 | SF | 7 | 10+ years | | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | | |
| | The close Cyclem | 2110 1 1001 | ' | _/ \ | , | o io youis | | |

Page : 46 of 52



| | ry Classroom | | | 2400 S Marshall BOULEVARD, Chicago, IL 60623 Building: Leased-Branch (Spry HS) | | | | | | |
|----------|--------------------------------------|------------|------------|---------------------------------------------------------------------------------|---------|-----------------------------|------------------------------|--|--|--|
| Catego | ry : Classroom | | В | unung | . Lease | u-Branch (Spry Recommend | y noj | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| • | om #208 (Regular Classroom) | | - Quantity | | - Carin | . topicomont | | | | |
| Ciassion | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Splined | 2nd Floor | 950 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 3 | EA | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 950 | SF | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | 6-10 years | | | | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | | | | |
| | Storage/ Closet | 2nd Floor | 112 | SF | 7 | 10+ years | | | | |
| | Walls - Concrete Block | 2nd Floor | 1,200 | SF | 7 | 10+ years | | | | |
| | Walls - Coliciete block | 2110 F1001 | 1,200 | SF | , | 10+ years | | | | |
| Classroo | om #209 (Dance Room) | | | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | | | | |
| | Ceiling - Splined | 2nd Floor | 900 | SF | 6 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 3 | EA | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 900 | SF | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 17 | EA | 7 | 6-10 years | | | | |
| | Marker Board | 2nd Floor | 6 | LF | 7 | 6-10 years | | | | |
| | Storage/ Closet | 2nd Floor | 65 | SF | 7 | 10+ years | | | | |
| | Wall Mirrors | 2nd Floor | 20 | SF | 7 | 2-5 years | | | | |
| | Walls - Concrete Block | 2nd Floor | 1,200 | SF | 7 | 10+ years | | | | |
| Classroo | om #210 (Regular Classroom) | | | | | | | | | |
| Oldoorox | Ceiling - Exposed | 2nd Floor | 720 | SF | 7 | 10+ years | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 7 | 10+ years | | | | |
| | Floor - Tile | 2nd Floor | 720 | SF | 7 | 10+ years | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | 6-10 years | | | | |
| | Marker Board | 2nd Floor | 2 | LF | 7 | 6-10 years | | | | |
| | Walls - Concrete Block | 2nd Floor | 136 | SF | 7 | 10+ years | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 440 | SF | 7 | 10+ years | | | | |
| | | | • | . | • | .o. you.o | | | | |
| Catego | ry : Interior | | В | uilding | : Lease | d-Branch (Spr | y HS) | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Commonts | | | |
| Corridor | , i | Location | Quantity | OCIVI | Italik | Replacement | Comments | | | |
| | Ceiling - Splined | 1st Floor | 2,500 | SF | 6 | 10+ years | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | ĒΑ | 6 | 10+ years | | | | |
| | Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | 10+ years | | | | |
| | Floor - Terrazzo | 1st Floor | 900 | SF | 6 | 10+ years | | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 470 | SF | 6 | 10+ years | | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 2 | SF | 4 | 0-1 year | Missing Tiles | | | |
| | Floor - Tile/Sheet | 1st Floor | 1,130 | SF | 4 | 0-1 year | Cracking/chipped throughout. | | | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EΑ | 6 | 6-10 years | 5 11 | | | |
| | Stairs - Concrete Stairs | 1st Floor | 6 | LF | 6 | 10+ years | | | | |
| | ·· · · · | | • | | - | , | | | | |
| | | | | | | | | | | |



| Catego | ategory : Interior | | | Building : Leased-Branch (Spry HS) | | | | |
|--------|--------------------------------------|------------------------|----------|------------------------------------|------|-------------|----------|--|
| _ | | | | _ | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Stairs - Terrazzo | 1st Floor | 40 | LF | 6 | 10+ years | | |
| | Walls - Concrete Block | 1st Floor | 5,600 | SF | 6 | 10+ years | | |
| | Ceiling - Splined | 2nd Floor | 1,350 | SF | 6 | 10+ years | | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 2 | EA | 7 | 6-10 years | | |
| | Floor - Tile/Sheet | 2nd Floor | 1,350 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | 2nd Floor | 17 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd Floor | 2,240 | SF | 7 | 10+ years | | |
| Safety | | | | | | | | |
| - | Camera Viewing Station | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Metal Dedector | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Security Cameras | 1st Floor | 19 | EA | 7 | 6-10 years | | |
| Stairs | | | | | | | | |
| | Ceiling - Exposed | South | 100 | SF | 7 | 10+ years | | |
| | Floor - Concrete | South | 100 | SF | 7 | 10+ years | | |
| | Handrails | South | 30 | LF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | South | 1 | EA | 7 | 10+ years | | |
| | Stairs - Concrete | South | 16 | LF | 7 | 10+ years | | |
| | Walls - Concrete Block | South | 600 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Stairs Near Main Entry | 40 | SF | 6 | 10+ years | | |
| | Floor - Terrazzo | Stairs Near Main Entry | 40 | SF | 6 | 10+ years | | |
| | Handrails | Stairs Near Main Entry | 55 | LF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Stairs Near Main Entry | 1 | EA | 6 | 6-10 years | | |
| | Stairs - Terrazzo | Stairs Near Main Entry | 120 | LF | 6 | 10+ years | | |
| | Walls - Masonry | Stairs Near Main Entry | 180 | SF | 6 | 10+ years | | |
| | Ceiling - Splined | Stairs Near Pool | 40 | SF | 6 | 10+ years | | |
| | Floor - Tile | Stairs Near Pool | 40 | SF | 6 | 10+ years | | |
| | Handrails | Stairs Near Pool | 55 | LF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Stairs Near Pool | 1 | EA | 6 | 6-10 years | | |
| | Stairs - Tile | Stairs Near Pool | 120 | LF | 6 | 10+ years | | |
| | Walls - Concrete Block | Stairs Near Pool | 180 | SF | 6 | 10+ years | | |



Category: Site

Sidewalks

Signage

| aicgo | iy. Oilo | | | unung | . Oite | | |
|-----------|-----------------------------------|-------------------|----------|-------|----------|-------------|----------------------|
| | | | 0 | | . | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Civil/Dra | O | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 5 | EA | 6 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 11 | EA | 6 | 10+ years | |
| encina | | | | | | | |
| <u>-</u> | Fencing - Chain Link | Entire Site | 200 | LF | 6 | 10+ years | |
| | Fencing - Guard Rail | Entire Site | 155 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 730 | LF | 6 | 10+ years | |
| andsca | pe | | | | | | |
| | Landscape - Hardscape- Concrete | Entire Site | 2,160 | SF | 6 | 10+ years | |
| | Parkway trees | Entire Site | 11 | EA | 6 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 600 | SF | 6 | 10+ years | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 22,500 | SF | 4 | 0-1 year | Cracking throughout. |
| arking | Lot | | | | | | |
| Ü | Surface - Asphalt | Parking Lot- East | 15,447 | SF | 6 | 10+ years | |
| | Surface - Asphalt | Parking Lot- East | 200 | SF | 4 | 0-1 year | Potholes |
| | Surface - Asphalt | Parking Lot- East | 200 | SF | 4 | 0-1 year | Potholes |
| | Surface - Asphalt | Parking Lot- East | 200 | SF | 4 | 0-1 year | Potholes |
| | Surface - Asphalt | Parking Lot- West | 3,982 | SF | 6 | 10+ years | |
| | Surface - Asphalt | Parking Lot- West | 500 | SF | 4 | 0-1 year | Potholes |
| | Surface - Asphalt | Parking Lot- West | 500 | SF | 4 | 0-1 year | Potholes |
| | Surface - Asphalt | Parking Lot- West | 500 | SF | 4 | 0-1 year | Potholes |
| | Surface - Concrete | Parking Lot- West | 2,745 | SF | 6 | 10+ years | |
| | Trash Enclosure - Chain Links | Parking Lot- West | 2,745 | SF | 6 | 10+ years | |
| laygrou | ınd | | | | | | |
| - | Equipment - School Age 5-12 | East Courtyard | 1 | EA | 6 | 10+ years | |
| | Surface - Poured Surface | East Courtyard | 1,809 | SF | 6 | 10+ years | |
| | | | | | | | |

Page: 49 of 52

17,775

SF

EΑ

EΑ

6

6

10+ years

10+ years

10+ years

Building: Site

Sidewalks - Perimeter Sidewalks

Flag Pole - Building Mounted Flag Pole

Marquee - Free Standing Back Lighted

Entire Site

East Facade, Northeast

East Facade, Northeast



John Spry Elementary Community School


2400 S Marshall BOULEVARD, Chicago, IL 60623

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Spry Community Links High School Page: 50 of 52 Assessment Date: 11/19/2020





Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart- Board |
|----------------------------|-------------------|---------------|----------------|------------------------------|--------------|--------------------------|----------------------------|----------------|-----------------|
| Building : Main | | | | | (-) | | | | |
| Computer Lab | Computer Lab | Basement | B3 | В3 | 1,208 | 60 | 29 | N | N |
| Faculty Lounge | Regular Classroom | 3rd Floor | 307 | 307 | 880 | 69 | 6 | N | N |
| Faculty Lounge | Special Program | 3rd Floor | 305 | 305 | 470 | 44 | 4 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 101 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 880 | 78 | 39 | N | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 880 | 72 | 33 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 880 | 78 | 39 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 880 | 6,272 | 33 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 880 | 62 | 5 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 880 | 69 | 6 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 880 | 69 | 6 | N | N |
| Regular Classroom | Regular Classroom | Basement | B-9 | B-9 | 835 | 60 | 29 | N | N |
| Science | Regular Classroom | 3rd Floor | 309 | 309 | 880 | 69 | 6 | N | N |
| Special Program | Special Program | Basement | B6 | B6 | 858 | 60 | 29 | N | N |
| Building : Leased-Branch (| (Spry HS) | | | | | | | | |
| Computer Lab | Computer Lab | 2nd Floor | 207 | 207 | 2,220 | 370 | 60 | | |
| Dance Room | Dance Room | 2nd Floor | 209 | 209 | 900 | 0 | 0 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 340 | 350 | 100 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 350 | 200 | 50 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 731 | 400 | 80 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 230 | 140 | 40 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 600 | 220 | 60 | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 950 | 0 | 0 | | |
| Danielan Olasanaana | Daniela Olasana | On d Flagr | 040 | 040 | 700 | | | 1 | |

210

206

Page : 51 of 52

210

206

720

1,000

0

360

0

80

Regular Classroom

Science Classroom

2nd Floor

2nd Floor

Regular Classroom

Science Classroom



Classroom Summary

| Oldoor Com Cammary | | | D | Floor Plan | A | Glazed | Operable | \A(! | 0 |
|---------------------|-------------------|---------------|----------------|----------------|--------------|----------------|----------------|----------------|-----------------|
| Current Usage | Intended Usage | Room Location | Room Number | Room Number | Area (SF) | Window Area | Window Area | Window Stop | Smart- Board |
| Building : Addition | <u>-</u> | · | | | | | | | |
| Computer Lab | Regular Classroom | 2nd Floor | 211 | 211 | 768 | 90 | 8 | N | N |
| Kindergarten | Kindergarten | 1st Floor | 112 | 112 | 940 | 122 | 50 | Y | N |
| Pre School | Kindergarten | 1st Floor | 114 | 114 | 940 | 175 | 75 | Y | N |
| Pre School | Regular Classroom | 1st Floor | 113 | 113 | 768 | 108 | 12 | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 111 | 768 | 108 | 12 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 768 | 99 | 10 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 768 | 99 | 10 | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 214 | 214 | 768 | 108 | 12 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 314 | 314 | 768 | 108 | 12 | N | N |
| Science Lab Level 1 | Regular Classroom | 3rd Floor | 310 | 310 | 1,062 | 125 | 14 | N | N |
| Science Lab Level 2 | Regular Classroom | 3rd Floor | 311/313 | 313/311 | 1,062 | 144 | 16 | N | N |
| Special Education | Office | 2nd Floor | 210 | 210 | 420 | 17 | 4 | N | N |

Page : 52 of 52