

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1895	3	22,440
Addition 1	1904	3	50,650
Addition 2	1996	3	32,830
Campus Total			105,920

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	3	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	3	2	EA	5	2-5 years	
	Ramp Handrail - Steel_Ramp Handrail	3	21	LF	6	6-10 years	
	Ramps - Concrete	3	11	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	3.1 Girls	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	3.1 Girls	1	EA	4	0-1 year	Plywood worn.
	Exterior Doors - Exterior Steel Door	Boiler to Courtyard	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Boiler to Courtyard	1	EA	5	2-5 years	Plywood.
	Ramp Handrail - Steel_Ramp Handrail	Boiler to Courtyard	15	LF	6	6-10 years	
	Ramps - Concrete	Boiler to Courtyard	15	LF	6	10+ years	
Foundati	on						
	Foundation - Masonry	Entire Building	580	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	20,160	SF	7	10+ years	
		· ·				•	
Liahtina							
_ 0	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	2-5 years	
	g	59	-			,	
_Roof Sys	stem						
	Coping - Clay Tile	G	260	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	G	150	LF	6	6-10 years	
	•					·	

Campus Name: Linne Page : 1 of 41 Assessment Date: 07/31/2019



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet > 30"	G	260	LF	6	6-10 years	
	Roof - Modified Bitumen	G	5,862	SF	5	1-2 years	Worn cracked surface.
	Roof Hatch - Metal	G	1	EΑ	3	2-5 years	No Ladder access, hatch not used.
	Roof Structure - Heavy Timber	G	5,862	SF	7	10+ years	
	Coping - Stone	Н	55	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Н	30	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Н	55	LF	6	10+ years	
	Roof - Modified Bitumen	Н	340	SF	5	1-2 years	Worn and cracked surface.
	Roof Structure - Heavy Timber	Н	340	SF	7	10+ years	
	Coping - Clay Tile	1	96	LF	6	10+ years	
	Downspouts - Interior Downspouts	1	14	LF	6	6-10 years	
	Parapet - 16" - 30" Height	1	96	LF	6	10+ years	
	Roof - Modified Bitumen	1	1,620	SF	5	1-2 years	Worn and cracked.
	Roof Structure - Heavy Timber	1	1,620	SF	7	10+ years	
	Coping - Clay Tile	Ĵ	59	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Ĵ	20	LF	6	6-10 years	
	Parapet - 16" - 30" Height	.J	59	LF	6	10+ years	
	Roof - Modified Bitumen	.l	740	SF	5	1-2 years	Worn cracked surface
	Roof Structure - Heavy Timber	J	740	SF	7	10+ years	Wolff Gracked Saliace
/alls	Cheek-Wall - Concrete Cornice - Metal Projecting Exterior Walls - Brick Exterior Walls - Stone-Cast	Entire Building Entire Building Entire Building Entire Building	60 675 9,500 1,720	SF LF SF SF	5 6 6	0-1 year 6-10 years 10+ years 10+ years	Large crack at Entrance 3 observed Painting.
/indows		g	.,		-	, , , , , , , , , , , , , , , , , , ,	
	Guard - Guards wire guard	Entire Building	425	SF	6	6-10 years	
	Lintels - Brick	Entire Building	115	LF	6	10+ years	
	Lintels - Stone	Entire Building	238	LF	6	6-10 years	
	Skylite - Glass Single-Pane	Entire Building	24	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,520	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	cy System						
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	10+ years	
	Exit Signs - Lunchroom	Entire Building	1	EA	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	1,482	SF	6	10+ years	Recently upgraded



Catego	ry : Electrical		R	uilding	· Main		N Sacramento AVENUE, Chicago, IL 60618
Catego	ry . Electrical			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. ор	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	Served from addition 1
	gg	g	_			, , , , , , , , , , , , , , , , , , , ,	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	22,440	SF	6	10+ years	
	ŭ	Ç				·	
Sprinkler	System						
•	Dry Sprinkler System	Entire Building	22,440	SF	5	10+ years	Served from addition 1
		-				-	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	vstems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	10+ years	
	Pressure Boiler - 101 - 150 HP						
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	5	2-5 years	Minor corrosion.
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Duplex with recessed receiver.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	Evidence of leaks present. 4 pumps.
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	5	10+ years	
	Steam- Low Pressure Boiler - 101 - 150 HP				-	, , , , , ,	
	Piping - Condensate Pipe- Steel	Boiler Room	150	LF	6	10+ years	Appears piping insulation was tested
	i iping - Condensate i ipe- Steel	Bollet Room	150	LI	O	10+ years	or abated and replaced.
	Piping - Steam Pipe- Steel	Boiler Room	150	LF	6	10 L Vooro	Appears piping insulation was tested
	Piping - Steam Pipe- Steel	Bollet Room	150	LF	О	10+ years	
	O	5 " 5			_	0.40	or abated and replaced.
	Steam Traps	Boiler Room	1	EA	5	6-10 years	Many leak
Heating I	Davisas						
пеашу	Unit Heater - Steam	Basement	1	EA	5	6-10 years	
	Unit Heater - Steam	Basement	1	EA	5	6-10 years	
	Wall Heater - Electric		6	EA	6		
		Entire Building			_	10+ years	Describe a contra
	Wall Heater - Electric	Entire Building	5	EA	4	1-2 years	Rusting units
	Cabinet Heaters - With Steam Coil	Entire Building	1	EA	4	0-1 year	Needs painting and maintenance. Ol
							and rusing
Tempera	ature Control						
	Electric Thermostat	Entire Building	11	EA	6	10+ years	Electric thermostats for wall heaters
	Pneumatic System	Entire Building	22,440	SF	4	1-2 years	Mostly manual control. Difficult to
	· · · · · · · · · · · · · · · · · · ·	· · · - · · · · · · · · · · · · · · · ·	==,		-	. = ,	control. Main equipment in Addition 1
							Control. Main Equipment in Addition i
	Thermostats - Pneumatic	Entire Building	11	EA	4	1-2 years	Many do not work.

Campus Name: Linne Page : 3 of 41 Assessment Date: 07/31/2019



XIII S	Schools					3221 I	N Sacramento AVENUE, Chicago, IL 60618
Catego	ry : Mechanical		E	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ventilatio	an an						
_venillalii	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Kitchen
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	10+ years	rationion
	CFM	Ŭ				,	
•	D		_				
Catego	ry : Plumbing		E	Building	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping	.,,,,,						
- ping	Domestic Piping-Cold Water Horizontal	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old.
	Lines	3	, -			,	Many pipe clamps.
	Domestic Piping-Cold Water Risers	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old.
	Developing Cold Meter from Discuss to	Forting Desirations	00.440	05	4	4.0	Many pipe clamps.
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old. Many pipe clamps.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old.
		g	,	О.	•	you.o	Many pipe clamps.
	Domestic Piping-Hot Water Return Lines	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old.
	B	E (00.440	05		4.0	Many pipe clamps.
	Domestic Piping-Hot Water Return Risers	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old. Many pipe clamps.
	Domestic Piping-Hot Water from Risers to	Entire Building	22,440	SF	4	1-2 years	Piping is more than 60 years old.
	Fixtures	9	,		•	,	Many pipe clamps.
	Sanitary Piping	Entire Building	22,440	SF	6	10+ years	
	Storm Piping	Entire Building	22,440	SF	6	10+ years	
	Vent Piping	Entire Building	22,440	SF	6	10+ years	
Dumna							
Pumps	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	6-10 years	Frequent maintenance required
	Pumps - Sump-Duplex	Basement	1	ĒΑ	4	2-5 years	Pump does not work
•	01		_				
Catego	ry : Classroom		<u> </u>	Building	: wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	om #104 - Art Room (Art Room)		4		- 101111		
Oldssioc	AC Units	Basement	2	EA	7	10+ years	
	Casework	Basement	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,030	SF	7	10+ years	
				EA			
	Doors - Wood Doors inclu hw	Basement	2		6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,030	SF	4	0-1 year	Flooring chipping and cracking throughout.
	Lighting - Pendent/Surface	Basement	14	EA	6	6-10 years	anoughout.
	<u> </u>		• •		-	- ,	

Campus Name: Linne Page : 4 of 41 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	Basement	11	LF	6	6-10 years	
	Walls - Masonry	Basement	1,083	SF	6	10+ years	
	Work Sink	Basement	4	EA	7	6-10 years	
Classroo	om #105 (Music Room)						
	AC Units	Basement	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,017	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	Basement	16	ĒΑ	6	6-10 years	
	Marker Board	Basement	33	LF	6	6-10 years	
	Storage/ Closet	Basement	189	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	1,200	SF	6	10+ years	
Classro	om #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	
	Casework	2nd Floor	_ 5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	828	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	828	SF	5	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	7	10+ years	
	•	2110 1 1001	1,000	O1	•	ror youro	
_Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,017	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	189	SF	5	2-5 years	
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,017	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	975	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	6	10+ years	
Classroo	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	10+ years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	928	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	2nd Floor	928	SF	7	•	
	Lighting - Pendent/Surface					10+ years	
	Marker Board	2nd Floor	17	EA	6	6-10 years	
		2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,000	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	350	SF	7	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	5	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,017	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	['] 16	EA	6	6-10 years	
	Marker Board	3rd Floor	17	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	4	0-1 year	Wall cracking from ceiling down wa
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	350	SF	6	10+ years	
Classroo	om #310 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1,017	SF	6	10+ years	
	Doors - Hallsolli William	SIU FIOOI	0	SI-	U	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	30	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	350	SF	6	10+ years	
Classics	m #244 (Dogular Classroom)						
Classion	om #311 (Regular Classroom) AC Units	Oud Flags	4		7	0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,017	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,000	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	350	SF	6	10+ years	
Classroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	30	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	950	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	350	SF	6	10+ years	
			300	٥.	•	,	
Classroo	om #Ceramics Room (Art Room)						
	Ceiling - Lay-in	Basement	1,030	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	1,030	SF	7	10+ years	
	Kiln	Basement	1	EA	6	10+ years	Kiln is located in the connected Home
	Lighting - Lay-in	Basement	15	EA	6	6-10 years	Economics Room.
	Walls - Concrete Block	Basement	600	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	628	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #Home Ec (Other Instructional Use)						
	Ceiling - Lay-in	Basement	1,051	SF	6	10+ years	
	Ceiling - Lay-in	Basement	3	SF	4	0-1 year	Tile missing.
	Floor - Concrete	Basement	500	SF	7	10+ years	-
	Floor - Tile	Basement	554	SF	6	10+ years	
	Lighting - Lay-in	Basement	11	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,100	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	100	SF	4	0-1 year	Extensive water damage observed
	Work Sink	Basement	3	EA	5	6-10 years	around where the Kiln is located.
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal/ Service Rooms						
	Boiler Room	Boiler Room	181	SF	5	10+ years	
D = = t = = = =	_						
Restroor		040		0.5		0.40	
	Accessories	212 212	55 55	SF SF	5	6-10 years	
	Ceiling - Plaster/Drywall			_	6	10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	212	1	EA SF	6	6-10 years	
		212	26 29	SF SF	6 4	6-10 years	Tile missing congreting and chinne
	Floor - Tile	212	29	-	·	0-1 year	Tile missing, separating, and chippe near lavatory.
	Lavatory	212	1	EA	6	10+ years	
	Lighting - Pendent/Surface	212	1	EA	7	10+ years	
	Partitions	212	1	EA	7	10+ years	
	Walls - Plaster/Drywall	212	200	SF	6	10+ years	
	Walls - Plaster/Drywall	212	100	SF	6	10+ years	
	Water Closet	212	1	EA	6	6-10 years	
	Accessories	Basement	350	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement	350	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	350	SF	5	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Lavatory	Basement	3	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement	5	EA	6	10+ years	
	Partitions	Basement	13	EA	5	10+ years	
	Walls - Plaster/Drywall	Basement	337	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	600	SF	7	10+ years	
	Water Closet	Basement	13	EA	6	10+ years	
	Accessories	Boiler Room	28	SF SF	5	6-10 years	

Campus Name: Linne Page : 8 of 41 Assessment Date: 07/31/2019



Category : Room

Carl von Linne Elementary School 3221 N Sacramento AVENUE, Chicago, IL 60618

roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Boiler Room	1	EΑ	6	10+ years	
	Floor - Concrete	Boiler Room	28	SF	5	10+ years	
	Lavatory	Boiler Room	1	EA	5	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	5	10+ years	
	Walls - Masonry	Boiler Room	191	SF	6	10+ years	
	Water Closet	Boiler Room	1	EA	6	10+ years	
itegoi	ry : Interior		В	uilding	: Main		
_				_		Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
rridor							
	Ceiling - Exposed	1st Floor	432	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	400	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Floor - Epoxy/ Painted	1st Floor	832	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	700	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	675	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	675	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,332	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	675	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	5	10+ years	
	Floor - Tile/Sheet	3rd Floor	675	SF	5	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,332	SF	6	10+ years	
irs							
	Ceiling - Lay-in	South	360	SF	6	10+ years	
	Floor - Asphalt	South	288	SF	6	10+ years	
	Handrails	South	128	LF	5	10+ years	
	Lighting - Pendent/Surface	South	2	EA	7	10+ years	
	Lighting - Wall Mounted	South	2	EA	7	10+ years	
	Stairs - Asphalt	South	360	LF	7	10+ years	
	Walls - Plaster/Drywall	South	3,240	SF	6	10+ years	
tical (Conveyance						
	Wheelchair Lift - Chair Lift		1	EA	4	0-1 year	The wheelchait lift is non-operati

Building: Main



Category : Exterior Building : Addition 1

tem - Type	Location	Quantity	LIONA	_	Recommend	
tem - Type	Location	Quantity				A
		Quantity	UOM	Rank	Replacement	Comments
Exterior Doors - Exterior Steel Door	1	2	EA	6	6-10 years	
Exterior Doors - Transom Lite	1	2	EA	6	6-10 years	
Exterior Stairs - Stone	1	30	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	2	2	EA	6	6-10 years	
Exterior Doors - Transom Lite	2	2		6	6-10 years	
Exterior Stairs - Stone	2	30	LF	6	10+ years	
Exterior Doors - Exterior Steel Door	9	3	EA	6	6-10 years	
Exterior Doors - Transom Lite	9	3	EA	6	6-10 years	
Exterior Stairs - Stone	9	9	LF	5	6-10 years	Minor cracking.
Exterior Doors - Exterior Steel Door	NE 1 story boys	1	EΑ	6	6-10 years	<u>-</u>
Exterior Doors - Side lite	NE 1 story boys	1	EΑ	5	2-5 years	Rusted base.
					•	
	Factor Destroyer	700		7	40	
	•					0
						Seepage in crawl space.
Superstructure - Heavy Timber	Entire Building	40,130	5F	7	10+ years	
Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	2-5 years	
Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	2-5 years	
m						
	Δ	230	I F	6	10+ vears	
						Roof is worn.
					•	No access ladder to hatch, roof hatch
NOOI Hatch - Metal	A	ı	LA	3	2-5 years	is not used.
Roof Structure - Heavy Timber	Α	5.600	SF	7	10+ vears	
		1			,	Not OSHA
iner	_	00		•	.c. jouro	
	В	10	LF	5	0-1 vear	Cracking face brick.
iner			_,	-	- , ,	
	В	404	LF	6	10+ vears	
		_				
					•	
		-				Roof is worn.
		1				
		•				
	Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Stone Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Stairs - Stone Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Foundation - Masonry Foundation - Masonry Foundation - Heavy Timber Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Height Foomspouts - Exterior Downspouts Forapet - 16" - 30" Height Foof - Modified Bitumen Foof Structure - Heavy Timber Foccess Ladder - Metal Chimney - Brick Chimney- Concrete/ Mortar Liner Chimney - Brick Chimney- Concrete/ Mortar	Exterior Doors - Exterior Steel Door Exterior Doors - Transom Lite Exterior Stairs - Stone Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Stairs - Stone Exterior Stairs - Stone Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Lighting - Masonry Entire Building Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Parapet or Roof Mounted Exterior Lighting Exterior Lighting Exterior Downspouts A Parapet - 16" - 30" Height Book - Parapet - 16" - 30" Height Boof - Modified Bitumen Boof	Exterior Doors - Exterior Steel Door 2 2 2 2 2 2 2 2 2	Exterior Doors - Exterior Steel Door 2	Exterior Doors - Exterior Steel Door 2	Exterior Doors - Exterior Steel Door 2

Campus Name: Linne Page : 10 of 41 Assessment Date: 07/31/2019



Catego	ry : Exterior		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	C	25	LF	6	10+ years	
	Downspouts - Exterior Downspouts	С	31	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	С	50	LF	6	10+ years	
	Roof - Modified Bitumen	С	108	SF	5	1-2 years	Roof is worn.
	Roof Structure - Heavy Timber	С	108	SF	7	10+ years	
	Coping - Stone	D	25	LF	6	10+ years	
	Parapet - 16" - 30" Height	D	25	LF	6	10+ years	
	Roof - Modified Bitumen	D	168	SF	5	1-2 years	Roof is worn.
	Roof Structure - Heavy Timber	D	168	SF	7	10+ years	
	Coping - Clay Tile	E	25	LF	6	10+ years	
	Coping - Stone	Ē	25	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Ē	31	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Ē	50	LF	6	10+ years	
	Roof - Modified Bitumen	Ē	108	SF	5	1-2 years	Roof is worn.
	Roof Structure - Heavy Timber	E	108	SF	7	10+ years	ROOF IS WOITI.
	Coping - Clay Tile	F	116	LF	6	10+ years	
	Downspouts - Exterior Downspouts	F	18	LF	6	6-10 years	
	Parapet - 16" - 30" Height	r F		LF	6		
		•	116		-	10+ years	Deatie
	Roof - Modified Bitumen	F	710	SF	5	1-2 years	Roof is worn.
	Roof Structure - Heavy Timber	F	710	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	24	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	77	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,330	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	19,050	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	200	SF	5	1-2 years	Efflorescence
	Exterior Walls - Stone-Cut	Entire Building	4,500	SF	6	10+ years	
Windows							
v v II IGGVVS	Guard - Guards wire guard	Entire Building	880	SF	6	6-10 years	
	Lintels - Brick	Entire Building	270	LF	7	10+ years	
	Lintels - Steel	Entire Building	15	LF	6	6-10 years	
	Lintels - Stone	Entire Building	340	LF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	4,925	SF	6	6-10 years	
Catana	ru - Flootrical		D	uildine	. A alaliti	on 1	
atego	ry : Electrical		В	unuing	: Additi	on 1 Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
-	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves the main and addition 1.
	Exit Signs - Auditoium	Entire Building	3	EA	6	6-10 years	
		9					

Campus Name: Linne Page : 11 of 41 Assessment Date: 07/31/2019



Catego	ry : Electrical		Building : Addition 1					
_			_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exit Signs - Corridors and Stairs	Entire Building	1	EΑ	2	0-1 year	Does not work.	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years		
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years		
	Security System - CCTV	Entire Building	50,650	SF	6	10+ years		
	Security System - Intrusion Detection	Entire Building	50,650	SF	6	10+ years		
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,061	SF	4	2-5 years	Not all lights work	
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,448	SF	4	2-5 years	Not all lights work	
Main Se								
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves the main and addition 1.	
	Independent Electrical Service for emergency power	Entire Building	2	EA	6	10+ years	Building has ATS and a separate feed for the fire pump.	
Power D	istribution							
	Lighting and Power Panels - 100 A	Entire Building	13	EA	6	10+ years		
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years		
Catego	ry : Fire Protection		В					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar								
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	Serves entire school	
	Fire Alarm Strobe Lights	Entire Building	50,650	SF	6	10+ years		
	Fire Alarm_System	Entire Building	50,650	SF	6	10+ years		
	Fire Pump Controller	Entire Building	1	EA	6	10+ years		
Pump Ro	oom Assembly							
	Fire Pump - 25-50 hp	Basement	1	EA	5	10+ years	Serves all buildings	
	Jockey Pump	Basement	1	EA	5	6-10 years	Serves all buildings	
3prinkle:	r System							
	Dry Sprinkler System	Entire Building	50,650	SF	5	10+ years	Older system	
	Sprinkler Heads	Entire Building	50,650	SF	7	10+ years		
	Sprinkler Piping	Entire Building	50,650	SF	6	10+ years		
_	ry : Mechanical		В	uilding	: Additio	on 1		
Catego	Item - Type							



73237 00110013						in Sacramento Avenue, Chicago, il 606 ro
					Replacement	
Air Handling Systems						
Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Mechanical Room	1	EA	5	6-10 years	Serves the Main Building and Addition 1.
Air Intake	Mechanical Room	1	EA	5	2-5 years	Rusted, painting needed.
Auxiliaries - 30001 - 45000 cfm	Mechanical Room	1	EA	5	6-10 years	Frequent repairs needed.
Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	10+ years	Return is from adjacent corridors.
Zone Dampers	Mechanical Room	32	EA	5	6-10 years	16 in north air chamber and 16 in the south air chamber. Mostly manually controlled but the dampers are functional.
Boiler Systems						
Piping - Condensate Pipe- Steel	Entire Building	250	LF	6	6-10 years	
Piping - Steam Pipe- Steel	Entire Building	250	LF	6	6-10 years	
Steam Traps	Entire Building	8	EA	6	6-10 years	
Heating Devices						
Cabinet Heaters - With Steam Coil	Basement	1	EA	4	2-5 years	Older corroding cabinet heater
Wall Heater - Electric	Entire Building	6	EA	6	10+ years	_
Wall Heater - Electric	Entire Building	2	EA	5	6-10 years	Cleaning required
Wall Heater - Electric	Entire Building	3	EA	4	1-2 years	Older, corroding
Fin Tube - Steam	Main Office	17	LF	7	10+ years	
Temperature Control						
Pneumatic System	Entire Building	50,650	SF	4	1-2 years	Mostly manual control. Difficult to control
Thermostats - Pneumatic	Entire Building	21	EA	4	1-2 years	Many old thermostats do not work.
_Ventilation						
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	

Category: Plumbing

Building: Addition 1

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Older, requires frequent maintenance.
_Pipina							
	Domestic Piping-Cold Water Horizontal	Entire Building	50,650	SF	4	1-2 years	Pipes are more than 60 years old.



Catego	Category : Plumbing			Building : Addition 1						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
	Lines Domestic Piping-Cold Water Risers	Entire Building	50,650	SF	4	1-2 years	There are many pipe clamps. Pipes are more than 60 years old.			
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	50,650	SF	4	1-2 years	There are many pipe clamps Pipes are more than 60 years old. There are many pipe clamps			
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	50,650	SF	4	1-2 years	Pipes are more than 60 years old. There are many pipe clamps			
	Domestic Piping-Hot Water Return Lines	Entire Building	50,650	SF	4	1-2 years	Pipes are more than 60 years old. There are many pipe clamps			
	Domestic Piping-Hot Water Return Risers	Entire Building	50,650	SF	4	1-2 years	Pipes are more than 60 years old. There are many pipe clamps			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	50,650	SF	4	1-2 years	Pipes are more than 60 years old. There are many pipe clamps			
	Sanitary Piping	Entire Building	50,650	SF	6	10+ years				
	Storm Piping	Entire Building	50,650	SF	6	10+ years				
	Vent Piping	Entire Building	50,650	SF	6	10+ years				

Building · Addition 1 Category : Room

Jatego	ry: Room	Building : Addition 1							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Adminis	rative Suites/Offices								
	AC Unit	205 Conference Room	1	EA	5	6-10 years			
	Ceiling - Plaster/Drywall	205 Conference Room	365	SF	6	10+ years			
	Doors - Transom Window	205 Conference Room	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	205 Conference Room	1	EA	6	10+ years			
	Floor - Tile	205 Conference Room	365	SF	5	10+ years			
	Lighting - Pendent/Surface	205 Conference Room	6	EA	6	10+ years			
	Power Distribution	205 Conference Room	8	EA	6	10+ years			
	Walls - Plaster/Drywall	205 Conference Room	858	SF	6	10+ years			
	AC Unit	207 Office	1	EA	5	6-10 years			
	Ceiling - Plaster/Drywall	207 Office	365	SF	7	10+ years			
	Doors - Transom Window	207 Office	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	207 Office	1	EA	6	10+ years			
	Floor - Tile	207 Office	365	SF	7	10+ years			
	Lighting - Pendent/Surface	207 Office	3	EA	6	10+ years			
	Power Distribution	207 Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	207 Office	897	SF	6	10+ years			
	AC Unit	ESL Parent Room	2	EA	7	10+ years			
	Ceiling - Plaster/Drywall	ESL Parent Room	600	SF	6	10+ years			
	Doors - Wood Doors inclu hw	ESL Parent Room	1	EA	6	6-10 years			
	Floor - Tile	ESL Parent Room	600	SF	6	6-10 years			
	Lighting - Pendent/Surface	ESL Parent Room	8	EA	6	6-10 years			
	Walls - Masonry	ESL Parent Room	540	SF	6	10+ years			
	Walls - Plaster/Drywall	ESL Parent Room	250	SF	6	10+ years			

Campus Name: Linne Page : 14 of 41 Assessment Date: 07/31/2019



Catego	ategory : Room Building : Addition 1						
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Engineer's Office	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	100	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EA	7	10+ years	
	Power Distribution	Engineer's Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	329	SF	6	10+ years	
	AC Unit	Main Office 206	1	EA	5	6-10 years	
	Ceiling - Lay-in	Main Office 206	398	SF	6	10+ years	
	Doors - Transom Window	Main Office 206	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office 206	1	EA	6	10+ years	
	Floor - Wood	Main Office 206	398	SF	6	10+ years	
	Lighting - Pendent/Surface	Main Office 206	4	EA	7	10+ years	
	Power Distribution	Main Office 206	8	EA	6	10+ years	
	Storage/ Closet	Main Office 206	189	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office 206	944	SF	6	10+ years	
	Ceiling - Lay-in	Principal's Conference Rm 206B	161	SF	6	10+ years	
	Doors - Transom Window	Principal's Conference Rm 206B	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Conference Rm 206B	1	EA	6	10+ years	
	Floor - Carpet	Principal's Conference Rm 206B	161	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Conference Rm 206B	3	EA	6	10+ years	
	Power Distribution	Principal's Conference Rm 206B	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal's Conference Rm 206B	678	SF	6	10+ years	
	AC Unit	Principal's Office (206A)	1	EA	5	6-10 years	
	Ceiling - Lay-in	Principal's Office (206A)	267	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office (206A)	1	EA	6	10+ years	
	Floor - Carpet	Principal's Office (206A)	267	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office (206A)	3	EA	6	10+ years	
	Power Distribution	Principal's Office (206A)	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office (206A)	779	SF	6	10+ years	
	Ceiling - Plaster/Drywall	in 102 (Office/Speech Therapy)	200	SF	6	10+ years	
	Doors - Wood Doors inclu hw	in 102 (Office/Speech Therapy)	1	EA	6	10+ years	
	Floor - Wood	in 102 (Office/Speech Therapy)	200	SF	6	10+ years	
	Lighting - Pendent/Surface	in 102 (Office/Speech Therapy)	3	EA	7	10+ years	
	Power Distribution	in 102 (Office/Speech Therapy)	4	EA	6	10+ years	
	Walls - Plaster/Drywall	in 102 (Office/Speech Therapy)	590	SF	6	10+ years	
_Gvmnas	ia						
_ Суппа	Ceiling - Splined	4th Floor	2,011	SF	6	6-10 years	
	Doors - Steel Doors incl hw	4th Floor	2,011	EA	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	4	EA	6	10+ years	
	Floor - Tile	4th Floor	1,050	SF	6	6-10 years	
	Floor - Wood	4th Floor	3,061	SF	7	6-10 years	
	Lighting - Pendent/Surface	4th Floor	16	EA	6	10+ years	
	Sound System	4th Floor	10	EA	5	6-10 years	
	Journa Dystern	1 011 1001	1	LA	J	U- IU years	

Campus Name: Linne Page : 15 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		В	uilding	: Addition	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage	4th Floor	1,040	SF	6	6-10 years	
	Stage Curtain	4th Floor	8	EA	5	6-10 years	
	Stage Lighting System	4th Floor	1	EA	5	10+ years	
	Storage/ Closet	4th Floor	200	SF	5	10+ years	
	Walls - Plaster/Drywall	4th Floor	3,142	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	306A	1	EA	6	10+ years	
	Finishes	306A	200	SF	5	10+ years	
	Window AC Unit	306A	1	EA	5	6-10 years	
	Wildow Ac Offic	300/1			J	o ro years	
<u> ⁄lechani</u>	cal/ Service Rooms						
	Storage Room	2nd FI Storage (2) Outside 205	43	SF	5	10+ years	
	Storage Room	2nd Fl Storage (3) Outside Rm 207	43	SF	5	10+ years	
	Storage Room	2nd Fl Storage (4) Outside Rm 207	43	SF	5	10+ years	
	Storage Room	2nd FI storage (1) Outside Rm 205	43	SF	5	10+ years	
	Janitor's Closet	2nd Floor	20	SF	5	10+ years	
	Air Intake Plenums	Basement (1st Flr) - Middle & South	310	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - Middle & South	93	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - Middle & South	930	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - Middle & South	125	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - Middle & South	253	SF	5	10+ years	
	Storage Room	Basement (1st Flr) - Middle & South	365	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - north	308	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement (1st Flr) - north	220	SF	5	10+ years	
Restroor	n						
<u>XCSHOOL</u>	Accessories	2nd Flr Staff Toilet	189	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Flr Staff Toilet	189	SF	5	10+ years	
	Doors - Wood Doors inclu hw	2nd Flr Staff Toilet	1	ĒA	5	10+ years	
	Floor - Tile	2nd Flr Staff Toilet	89	SF	6	10+ years	
	Floor - Wood	2nd Flr Staff Toilet	100	SF	5	2-5 years	
	Lavatory	2nd Flr Staff Toilet	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Flr Staff Toilet	2	EA	7	10+ years	
	Partitions	2nd Flr Staff Toilet	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Flr Staff Toilet	850	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Fir Staff Toilet	120	SF	7	10+ years	
	Water Closet	2nd Fir Staff Toilet	120	EA	7	10+ years	
	Accessories	3rd Floor Boys Toilet Room	83	SF	5	6-10 years	
	Ceiling - Lay-in	3rd Floor Boys Toilet Room	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Boys Tollet Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys Tollet Room	83	SF	6	-	
				Sr EA	7	10+ years	
	Floor Drain	3rd Floor Boys Toilet Room	1	ĽΑ	1	10+ years	

Campus Name: Linne Page : 16 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		Building : Addition 1							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lavatory	3rd Floor Boys Toilet Room	1	EA	6	10+ years				
	Lighting - Lay-in	3rd Floor Boys Toilet Room	2	EA	6	10+ years				
	Partitions	3rd Floor Boys Toilet Room	1	EA	5	2-5 years	Need to be repainted.			
	Urinals	3rd Floor Boys Toilet Room	3	EA	6	10+ years				
	Walls - Concrete Block	3rd Floor Boys Toilet Room	170	SF	6	10+ years				
	Walls - Plaster/Drywall	3rd Floor Boys Toilet Room	50	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	3rd Floor Boys Toilet Room	120	SF	6	10+ years				
	Water Closet	3rd Floor Boys Toilet Room	1	EA	6	10+ years				
	Accessories	3rd Floor Girls Toilet Room	83	SF	5	6-10 years				
	Ceiling - Lay-in	3rd Floor Girls Toilet Room	83	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Girls Toilet Room	1	ĒΑ	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls Toilet Room	83	SF	6	10+ years				
	Floor Drain	3rd Floor Girls Toilet Room	1	ĒΑ	7	10+ years				
	Lavatory	3rd Floor Girls Toilet Room	1	EA	6	10+ years				
	Lighting - Lay-in	3rd Floor Girls Toilet Room	2	EA	6	10+ years				
	Partitions	3rd Floor Girls Toilet Room	3	EA	7	10+ years				
	Walls - Concrete Block	3rd Floor Girls Toilet Room	170	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor Girls Toilet Room	50	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	3rd Floor Girls Toilet Room	120	SF	6	10+ years				
	Water Closet	3rd Floor Girls Toilet Room	3	EA	6	10+ years				
	Accessories	3rd Floor Teachers' Toilet Room	294	SF	5	6-10 years				
	Ceiling - Lay-in	3rd Floor Teachers' Toilet Room	294	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Teachers' Toilet Room	1	EA	6	10+ years				
	Floor - Tile	3rd Floor Teachers' Toilet Room	270	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd Floor Teachers' Toilet Room	24	SF	6	10+ years				
		3rd Floor Teachers' Toilet Room	2	EA	6					
	Lavatory Lighting - Pendent/Surface	3rd Floor Teachers' Toilet Room	4	EA	7	10+ years 10+ years				
	Partitions	3rd Floor Teachers' Toilet Room	2	EA	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor Teachers' Toilet Room	1,036	SF	6	,				
			1,036	Sr EA	-	10+ years				
	Water Closet	3rd Floor Teachers' Toilet Room	250	SF	6 5	10+ years				
	Accessories	Basement (1st Flr)	250	SF SF	5 6	6-10 years				
	Ceiling - Plaster/Drywall	Basement (1st Flr)		EA		10+ years				
	Doors - Steel Doors incl hw	Basement (1st Flr)	1		6	10+ years				
	Floor - Concrete Epoxy/ Painted	Basement (1st Flr)	250	SF EA	5	2-5 years				
	Floor Drain	Basement (1st Flr)	1		7	10+ years				
	Lavatory	Basement (1st Flr)	4	EΑ	6	10+ years				
	Lighting - Pendent/Surface	Basement (1st Flr)	6	EA	6	10+ years				
	Partitions	Basement (1st Flr)	5	EA	5	10+ years				
	Walls - Concrete Block	Basement (1st Flr)	468	SF	6	10+ years				
	Walls - Masonry	Basement (1st Flr)	446	SF	6	10+ years				
	Water Closet	Basement (1st Flr)	5	EA	6	10+ years				
	Accessories	Basement (1st Flr)	200	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Basement (1st Flr)	200	SF	6	10+ years				
	Doors - Steel Doors incl hw	Basement (1st Flr)	1	EA	6	10+ years				

Campus Name: Linne Page : 17 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		В	uilding	: Addition	on 1				
_			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Concrete Epoxy/ Painted	Basement (1st Flr)	200	SF	5	2-5 years				
	Floor Drain	Basement (1st Flr)	1	EA	7	10+ years				
	Lavatory	Basement (1st Flr)	2	EA	6	10+ years				
	Lighting - Pendent/Surface	Basement (1st Flr)	4	EA	6	10+ years				
	Partitions	Basement (1st Flr)	2	EA	7	10+ years				
	Urinals	Basement (1st Flr)	4	EA	6	10+ years				
	Walls - Concrete Block	Basement (1st Flr)	435	SF	6	10+ years				
	Walls - Masonry	Basement (1st Flr)	376	SF	6	10+ years				
	Water Closet	Basement (1st Flr)	2	EA	6	10+ years				
	Accessories	Basement (1st Flr) Mens	100	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Basement (1st Flr) Mens	100	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Basement (1st Flr) Mens	1	EA	6	10+ years				
	Floor - Tile	Basement (1st Flr) Mens	100	SF	6	10+ years				
	Lavatory	Basement (1st Flr) Mens	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Basement (1st Flr) Mens	2	EA	6	10+ years				
	Partitions	Basement (1st Flr) Mens	2	EA	5	10+ years				
	Urinals	Basement (1st Flr) Mens	2	EA	6	10+ years				
	Walls - Plaster/Drywall	Basement (1st Flr) Mens	236	SF	6	10+ years				
	Walls - Structural Glazed Tile	Basement (1st Flr) Mens	84	SF	6	10+ years				
	Water Closet	Basement (1st FIr) Mens	2	EA	6	10+ years				
					_	•				

Building : Addition 1

Recommend Category: Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #102 (Regular Classroom)						
	AC Units	Basement	1	EA	7	10+ years	
	Casework	Basement	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	816	SF	6	10+ years	
	Chalk Board	Basement	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	816	SF	5	2-5 years	
	Lighting - Pendent/Surface	Basement	18	EA	6	6-10 years	
	Marker Board	Basement	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	900	SF	6	6-10 years	Paint chipping and peeling throughout.
Classroo	om #103 (on lock) (Counseling Room)						
	AC Units	Basement	2	EA	7	10+ years	
	Casework	Basement	33	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	640	SF	6	10+ years	
	Chalk Board	Basement	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	640	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	6	6-10 years	

Campus Name: Linne Page : 18 of 41 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	Building : Addition 1					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Walls - Masonry	Basement	250	SF	6	10+ years			
	Walls - Masonry	Basement	100	SF	5	0-1 year	Chipped and cracking masonry or		
	, , , , , , , , , , , , , , , , , , , ,			-	-	· , , · · · ·	lower portion of wall throughout		
							classroom.		
	Walls - Plaster/Drywall	Basement	535	SF	6	10+ years	Cidosi dom.		
	Walls - Flaster/Drywall	Dasement	333	OI	U	10+ years			
Classros	om #201 (Regular Classroom)								
Classiuu	,	0-15	0			40			
	AC Units	2nd Floor	2	EA	7	10+ years			
	Casework	2nd Floor	6	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	1,017	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	1,017	SF	5	2-5 years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	38	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	189	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,316	SF	6	10+ years			
	,		,			,			
Classroo	m #202 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	10+ years			
	Casework	2nd Floor	6	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	1,017	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
			•	SF	-	•			
	Floor - Wood	2nd Floor	1,017		5	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	38	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	189	SF	5	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,289	SF	6	10+ years			
	Work Sink	2nd Floor	1	EA	5	6-10 years			
Olasaus a	#202 (Parular Classes)								
CIASSI00	om #203 (Regular Classroom) AC Units	2nd Floor	2	EA	7	10+ years			
	Casework	2nd Floor 2nd Floor		LF		-			
			6	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	982		6	10+ years	NA		
	Ceiling - Lay-in	2nd Floor	35	SF	4	0-1 year	Water damage observed.		
	Chalk Board	2nd Floor	30	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Wood	2nd Floor	1,017	SF	5	2-5 years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	37	LF	6	6-10 years			
	Storage/ Closet	2nd Floor	189	SF	5	10+ years			

Campus Name: Linne Page : 19 of 41 Assessment Date: 07/31/2019



y : Classroom	Building : Addition 1					
					Recommend	
						Comments
Walls - Plaster/Drywall	2nd Floor	1,442	SF	6	10+ years	
m #204 (Regular Classroom)						
AC Units		1	EA	7	10+ years	
Casework	2nd Floor	6		6	10+ years	
Ceiling - Lay-in	2nd Floor	1,017		6	10+ years	
Chalk Board	2nd Floor	12		4	2-5 years	
Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
Floor - Wood	2nd Floor	1,017	SF	5	2-5 years	
Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
Marker Board	2nd Floor	24	LF	6	6-10 years	
Storage/ Closet	2nd Floor	189	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,376	SF	6	10+ years	
m #208 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	10+ years	
		700		6	•	
Chalk Board		15	LF	4		
Doors - Transom Window		9	SF	6	10+ years	
Doors - Wood Doors inclu hw		1	EΑ		10+ vears	
Floor - Wood	2nd Floor	700				
Lighting - Pendent/Surface	2nd Floor	13				
Marker Board	2nd Floor	10		6	•	
Walls - Plaster/Drywall	2nd Floor	1,481	SF	6	10+ years	
m #301 (Regular Classroom)						
	2nd Floor	1	EA	7	10+ vears	
			SF		•	
	2nd Floor			6		
Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	-	
	2nd Floor	1,017	SF	5	2-5 years	
	2nd Floor	16			,	
Marker Board		20	LF		6-10 years	
					,	
Walls - Plaster/Drywall	2nd Floor	1,332	SF	6	10+ years	
m #302 (Science Classroom)						
AC Units	3rd Floor	1	EA	7	10+ vears	
	3rd Floor	5	LF	6		
		_		-		
				4		
Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Item - Type Walls - Plaster/Drywall m #204 (Regular Classroom) AC Units Casework Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #208 (Regular Classroom) AC Units Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall m #301 (Regular Classroom) AC Units Ceiling - Lay-in Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall m #301 (Regular Classroom) AC Units Ceiling - Lay-in Doors - Wood Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall m #302 (Science Classroom) AC Units Casework Ceiling - Lay-in Chalk Board	Location Walls - Plaster/Drywall 2nd Floor		Location Quantity UOM		

Campus Name: Linne Page : 20 of 41 Assessment Date: 07/31/2019



	y : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	6-10 years	
Classroor	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	17	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,288	SF	6	10+ years	
lassroor	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,017	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,017	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	6	6-10 years	
	Marker Board	3rd Floor	18	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	189	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,288	SF	6	10+ years	
Classroor	m #306 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	838	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	838	SF	5	2-5 years	
		3rd Floor		SF EA			
	Lighting - Pendent/Surface Walls - Plaster/Drywall	3rd Floor 3rd Floor	16 1,400	SF	6 6	6-10 years 10+ years	
				>-	n	HIT VESTS	

Campus Name: Linne Page : 21 of 41 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	10+ years	
	Ceiling - Lay-in	3rd Floor	700	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	5	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	700	SF	5	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,442	SF	6	10+ years	

Category: Interior **Building: Addition 1**

Category : Interior		Building : Addition 1							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	2nd Floor	2,113	SF	6	10+ years	Minor paint chipping.		
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	5	10+ years			
	Floor - Tile/Sheet	2nd Floor	2,113	SF	5	10+ years			
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	3,800	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	1,855	SF	6	10+ years			
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	5	10+ years			
	Floor - Tile/Sheet	3rd Floor	1,855	SF	5	10+ years			
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	3,723	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement (1st Flr) - NE Vestibule	128	SF	6	10+ years			
	Floor - Concrete	Basement (1st Flr) - NE Vestibule	128	SF	5	10+ years			
	Lighting - Pendent/Surface	Basement (1st Flr) - NE Vestibule	1	EA	7	10+ years			
	Stairs - Concrete Stairs	Basement (1st Flr) - NE Vestibule	1	LF	6	10+ years			
	Walls - Masonry	Basement (1st FIr) - NE Vestibule	350	SF	6	10+ years			
	Ceiling - Lay-in	Basement (1st Flr) - north (Boy's Plan Space)	2,320	SF	6	10+ years			
	Doors - Steel Doors incl hw	Basement (1st Flr) - north (Boy's Plan Space)	2	EA	6	10+ years			
	Doors - Steel Doors incl hw	Basement (1st Flr) - north (Boy's Plan Space)	1	EA	5	10+ years			
	Drinking Fountains - Double Fountain	Basement (1st Flr) - north (Boy's Plan Space)	1	EA	5	10+ years			
	Floor - Tile/Sheet	Basement (1st Flr) - north (Boy's Plan Space)	2,320	SF	7	10+ years			
	Lighting - Lay-in	Basement (1st Flr) - north (Boy's Plan Space)	20	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement (1st Flr) - north (Boy's Plan Space)	2,100	SF	6	10+ years			
	Ceiling - Lay-in	Basement (1st Flr) Corridor	350	SF	6	10+ years			
	Doors - Wood Doors include hw	Basement (1st Flr) Corridor	2	EA	6	10+ years			

Campus Name: Linne Page : 22 of 41 Assessment Date: 07/31/2019



Catego	ry : Interior		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete Epoxy/ Painted	Basement (1st Flr) Corridor	350	SF	5	10+ years	
	Lighting - Lay-in	Basement (1st Flr) Corridor	5	EA	6	10+ years	
	Stairs - Concrete Stairs	Basement (1st Flr) Corridor	60	LF	6	10+ years	
	Student Lockers - One Tier	Basement (1st Flr) Corridor	24	EΑ	6	10+ years	
	Walls - Masonry	Basement (1st Flr) Corridor	500	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement (1st Flr) Corridor	600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Southwest Stair Vestibule	84	SF	5	10+ years	
	Doors - Steel Doors incl hw	Southwest Stair Vestibule	4	EA	5	10+ years	
	Doors - Wood Doors include hw	Southwest Stair Vestibule	4	EA	5	10+ years	
	Floor - Tile Ceramic/ Porcelain	Southwest Stair Vestibule	84	SF	6	10+ years	
	Lighting - Pendent/Surface	Southwest Stair Vestibule	1	EA	6	10+ years	
	Walls - Structural Glazed Tile	Southwest Stair Vestibule	208	SF	6	10+ years	
Stairs							
	Ceiling - Lay-in	North	360	SF	6	10+ years	
	Floor - Asphalt	North	288	SF	7	10+ years	
	Handrails	North	136	LF	7	10+ years	
	Lighting - Pendent/Surface	North	1	EA	7	10+ years	
	Lighting - Wall Mounted	North	2	EA	6	10+ years	
	Stairs - Asphalt	North	360	LF	7	10+ years	
	Walls - Plaster/Drywall	North	3,240	SF	6	10+ years	
	Ceiling - Lay-in	North West	420	SF	6	10+ years	
	Floor - Asphalt	North West	580	SF	6	6-10 years	
	Handrails	North West	216	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	8	EA	6	10+ years	
	Lighting - Wall Mounted	North West	3	EA	7	10+ years	
	Stairs - Asphalt	North West	540	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	4,175	SF	6	10+ years	
	Ceiling - Lay-in	South West	420	SF	6	10+ years	
	Floor - Asphalt	South West	580	SF	6	10+ years	
	Handrails	South West	216	LF	5	10+ years	
	Lighting - Pendent/Surface	South West	8	EA	6	10+ years	
	Lighting - Wall Mounted	South West	3	EA	7	10+ years	
	Stairs - Asphalt	South West	540	LF	6	10+ years	
	Walls - Plaster/Drywall	South West	4,230	SF	6	10+ years	

Campus Name: Linne Page : 23 of 41 Assessment Date: 07/31/2019



Category : Exterior				Building : Addition 2				
Ū						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
trance								
	Exterior Doors - Side lite	4	2	EA	7	6-10 years		
	Exterior Doors - Store Front	4	2	EA	7	6-10 years		
	Exterior Doors - Transom Lite	4	2	EA	7	6-10 years		
	Power Door Operator and Controls	4	1	EA	4	0-1 year	Does not operate.	
	Exterior Doors - Side lite	5	2	EA	7	6-10 years	•	
	Exterior Doors - Store Front	5	2	EA	7	6-10 years		
	Exterior Doors - Transom Lite	5	2	EA	7	6-10 years		
	Entrance Control - Audio	6	1	EA	6	2-5 years		
	Exterior Doors - Side lite	6	2	EA	7	6-10 years		
	Exterior Doors - Store Front	6	2	EA	7	6-10 years		
	Exterior Doors - Transom Lite	6	2	EA	7	6-10 years		
	Power Door Operator and Controls	6	1	EA	4	0-1 year	Not operating.	
	Exterior Doors - Side lite	7	2	EA	7	6-10 years	g.	
	Exterior Doors - Store Front	7	2	EΑ	7	6-10 years		
	Exterior Doors - Transom Lite	7	2	EΑ	7	6-10 years		
	Exterior Doors - Store Front	8	2	EΑ	7	6-10 years		
	Exterior Doors - Transom Lite	8	2	EΑ	7	6-10 years		
	Power Door Operator and Controls	8	1	EΑ	7	2-5 years		
	Exterior Doors - Store Front	Courtyard A	1	EΑ	7	6-10 years		
	Exterior Doors - Transom Lite	Courtyard A	1	EΑ	7	6-10 years		
	Exterior Doors - Store Front	Courtyard B	1	EΑ	7	6-10 years		
	Exterior Doors - Transom Lite	Courtyard B	1	EΑ	7	6-10 years		
	Exterior Doors - Store Front	Courtyard C	1	EΑ	7	10+ years		
	Exterior Doors - Transom Lite	Courtyard C	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	Courtyard Gate	1	EA	6	6-10 years		
	Exterior Doors - Store Front	Courtyard at Building Link	2	EA	7	6-10 years		
	Exterior Doors - Transom Lite	Courtyard at Building Link	2	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	Electrical Room	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	Kitchen	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	Roof	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	Stair Tower Exit	1	EA	7	6-10 years		
	Exterior Doors Exterior Oteci Door	Stall Tower Exit	•	L/\	•	o to years		
undati	on							
unuall	Foundation - Concrete	Entire Building	700	LF	7	10+ years		
	Superstructure - Metal Deck/ Concrete	Entire Building Entire Building	32,355	SF	7	10+ years 10+ years		
	Topping	Little building	32,333	ЭГ	1	10+ years		
	1.0bbii.iA							
hting								
3	Exterior Lighting - Wall Mounted	Entire Building	18	EA	6	2-5 years		
		-				•		
of Sys	tem							

Campus Name: Linne Page : 24 of 41 Assessment Date: 07/31/2019



Catego	ry : Exterior		В	uilding	: Additi	on 2	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	K - East	1	EA	7	10+ years	
	Coping - Stone	K - East	365	LF	7	10+ years	
	Downspouts - Interior Downspouts	K - East	270	LF	6	6-10 years	
	Parapet - 16" - 30" Height	K - East	365	LF	7	10+ years	
	Roof - Modified Bitumen	K - East	9,698	SF	4	1-2 years	Cracks, bubbling throughout, leak at
			2,223	-		,	library.
	Roof Structure - Steel / Metal Deck/	K - East	9,698	SF	7	10+ years	
	Concrete Topping	11 2461	0,000	٥.	•	io. youro	
	Access Ladder - Metal	L	1	EA	7	6-10 years	
	Coping - Stone	Ĺ	72	LF	7	10+ years	
	Downspouts - Interior Downspouts	ī	35	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Ī	72	LF	7	10+ years	
	Roof - Modified Bitumen	Ī	260	SF	4	1-2 years	Cracking & bubbling.
	Roof Hatch - Metal	<u> </u>	1	EA			· ·
		L		SF	3	2-5 years	Not used, no access.
	Roof Structure - Steel / Metal Deck/	L	260	21	7	10+ years	
	Concrete Topping		0.40	. –	-	40	
	Coping - Stone	M	240	LF . –	7	10+ years	
	Downspouts - Interior Downspouts	M	117	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	M	240	LF	7	10+ years	
	Roof - Modified Bitumen	M	3,456	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	M	3,456	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	N	1	EA	7	10+ years	
	Chimney - Metal Flue	N	10	LF	7	6-10 years	
	Coping - Stone	N	75	LF	7	10+ years	
	Downspouts - Interior Downspouts	N	37	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	N	75	LF	7	10+ years	
	Roof - Modified Bitumen	N	987	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	N	987	SF	7	10+ years	
	Concrete Topping					, , , , , ,	
	Coping - Stone	0	52	LF	7	10+ years	
	Downspouts - Interior Downspouts	Ö	13	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Ö	52	LF	7	10+ years	
	Roof - Modified Bitumen	Ö	176	SF	5	1-2 years	Roof is cracking.
	Roof Structure - Steel / Metal Deck/	Ö	176	SF	7	10+ years	rtoor is ordoning.
	Concrete Topping	G	170	Oi	,	101 years	
	Access Ladder - Metal	Р	1	EA	7	10+ years	
	Coping - Stone	P	60	LF	7	10+ years	
	Downspouts - Interior Downspouts	P	19	LF	6	6-10 years	
	Parapet - 16" - 30" Height	P	60	LF	7	10+ years	
		P		SF			
	Roof - Modified Bitumen	· · · · · · · · · · · · · · · · · · ·	480		5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Р	480	SF	7	10+ years	
	Concrete Topping			- ^	-	0.40	
	Access Ladder - Metal	Q	1	EA	7	6-10 years	

Campus Name: Linne Page : 25 of 41 Assessment Date: 07/31/2019



Galego	ry : Exterior		В	uilding	: Addition		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	Q	98	LF	7	10+ years	
	Downspouts - Interior Downspouts	Q	61	LF · –	6	6-10 years	
	Parapet - 16" - 30" Height	Q	98	LF	6	10+ years	
	Roof - Modified Bitumen	Q	560	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Q	560	SF	7	10+ years	
	Concrete Topping						
Valls							
	Canopy - Metal	Entire Building	50	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	16,100	SF	7	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	5,000	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	910	SF	7	10+ years	
	Wall Exterior Walls - Stone-Cut	Entire Building	1,400	SF	7	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	1,180	SF	7	6-10 years	
	Lintels - Brick	Entire Building	36	LF	7	10+ years	
	Lintels - Concrete	Entire Building	50	LF	7	10+ years	
	Lintels - Steel	Entire Building	315	LF	7	6-10 years	
	Windows - Decorative	Entire Building	15	SF	7	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,900	SF	7	6-10 years	
Catego	ry : Electrical		В	uilding	: Additio	on 2	
						Recommend	
		Location	Quantity	UOM	Rank	Replacement	Comments
Group	Item - Type	Location	Quantity	00			
	Item - Type ncy System	Location	Quantity	00			
	ncy System		Quantity 1		6	10+ vears	Serves Addition 2 only.
	ncy System Automatic Transfer Switch	Electrical Room	1	EA	6 2	10+ years 0-1 year	Serves Addition 2 only. No generator and no battery back-u
	ncy System Automatic Transfer Switch Exit Signs - Corridors and Stairs	Electrical Room Entire Building	1 19	EA EA	2	0-1 year	No generator and no battery back-u
	ncy System Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym	Electrical Room Entire Building Entire Building	1 19 3	EA EA EA	2 2	0-1 year 0-1 year	No generator and no battery back-u No generator and no battery back-u
	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and	Electrical Room Entire Building	1 19	EA EA	2	0-1 year	No generator and no battery back-u No generator and no battery back-u
	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs	Electrical Room Entire Building Entire Building Entire Building Entire Building	1 19 3 4 1	EA EA EA EA	2 2 2 6	0-1 year 0-1 year 0-1 year 6-10 years	No generator and no battery back-u No generator and no battery back-u
	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency A/C Power - Corridors and	Electrical Room Entire Building Entire Building Entire Building	1 19 3	EA EA EA	2 2 2	0-1 year 0-1 year 0-1 year	No generator and no battery back-u No generator and no battery back-u
	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency A/C Power - Corridors and Stairs	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 19 3 4 1 3 6,922	EA EA EA EA EA SF	2 2 2 6	0-1 year 0-1 year 0-1 year 6-10 years	No generator and no battery back-up No generator and no battery back-up
•	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency A/C Power - Corridors and	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	1 19 3 4 1	EA EA EA EA	2 2 2 6 6	0-1 year 0-1 year 0-1 year 6-10 years 6-10 years 10+ years	Serves Addition 2 only. No generator and no battery back-up No generator and no battery back-up No generator and no battery back-up
Emerger	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Electrical Room Entire Building	1 19 3 4 1 3 6,922 2,900	EA EA EA EA EA SF	2 2 2 6 6 6	0-1 year 0-1 year 0-1 year 6-10 years 6-10 years 10+ years	No generator and no battery back-up No generator and no battery back-up
Group Emerger Main Se	Automatic Transfer Switch Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Lunchroom Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Electrical Room Entire Building	1 19 3 4 1 3 6,922 2,900	EA EA EA EA EA SF	2 2 2 6 6 6	0-1 year 0-1 year 0-1 year 6-10 years 6-10 years 10+ years	No generator and no battery back-up No generator and no battery back-up

Campus Name: Linne Page : 26 of 41 Assessment Date: 07/31/2019



Catego	ry : Electrical		В	uilding	: Additi		V Sacramento AVENOE, Officago, IE 60010
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	emergency power PA System	Entire Building	92,645	SF	6	6-10 years	only. Served from main.
_Power D	istribution						
	Lighting and Power Panels - 100 A Main Distribution Panels - 400 - 600 amp	Entire Building Entire Building	9 1	EA EA	6 6	10+ years 10+ years	
Catego	ry : Fire Protection		В	uilding	: Additi	on 2	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	32,830	SF	6	10+ years	
	Fire Alarm_System	Entire Building	32,830	SF	6	10+ years	
Sprinkle	Custom						
_эрппке	Sprinkler Heads	Entire Building	32,830	SF	7	10+ years	
	Sprinkler Piping	Entire Building	32,830	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	32,830	SF	6	10+ years	
		, and the second				-	
Catego	ry : Mechanical		В	uilding	: Additi		
0	Hans T	Laadian	0	11014	D I-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	Condensing Unit- Roof Mounted - Less	Roof	1	EA	5	2.5.4227	Francisco de la constitución de
	than 5 tons	ROOI	ı	EA	5	2-5 years	Frequent maintenance is required. Part of ductless split system.
	Chemical Pot Feeder	Roof	1	EA	6	10+ years	Tart of adoless spin system.
	Chiller-Air Cooled-Screw Type-Roof	Roof	1	EA	2	0-1 year	Chiller compressors have failed and
	Mounted - 101 - 200 tons					-	unit has exceeded its standard life
	01 15 1	5 (- ^	•	0.40	span
	Glycol Feed	Roof	1	EA	6	6-10 years	
Air Hand	ling Systems						
All Hand	Fan Coil Unit- Celing Mounted - Electric	2nd Floor	1	EA	6	10+ years	Part of ductless split system.
	Fan Power Box - Fan Power Box with Hot	Entire Building	20	EΑ	6	10+ years	Tart of adolious spin system.
	Water Coil	<u> </u>				,	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	AHU-1
	Indoor- Hot Water and Chilled Water Coils -						
	12001-20000 cfm Air Intake	Mechanical Room	4	⊏∧	e	10± voore	
	VAV Box	Mechanical Room	1 7	EA EA	6 6	10+ years 6-10 years	
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	AHU-2
	Indoor- Hot Water and Chilled Water Coils -			_/ \	J	.o. youro	

Campus Name: Linne Page : 27 of 41 Assessment Date: 07/31/2019



Catego	Category : Mechanical			Building : Addition 2					
	_					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	8001-12000 cfm	Machaniaal Daam	4	_^	0	40			
	Air Intake	Mechanical Room	1	EΑ	6	10+ years			
	VAV Box	Mechanical Room	2	EΑ	6	6-10 years	Constant consider a condent		
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	5	2-5 years	Frequent repairs needed		
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	5	2-5 years	Frequent repairs needed		
Boiler Sy									
	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Mechanical Room	2	EA	5	6-10 years			
	Chemical Pot Feeder	Mechanical Room	2	EA	5	6-10 years			
	Combustion Dampers	Mechanical Room	2	EA	6	10+ years			
	Non Condensing- Flexible Tube-	Mechanical Room	2	ΕA	5	6-10 years			
	Atmospheric- Hot Water Boiler - 1001 - 2000 MBH					,			
	Water Fill System	Mechanical Room	1	EA	6	6-10 years			
Heating	Devices								
	Cabinet Heaters - With Hot Water Coil	1st Floor	5	EA	6	10+ years	Painting required		
	Fin Tube - Hot Water	2nd Floor	12	LF	6	10+ years			
	Unit Heater - Hot Water	2nd Floor	3	EA	6	6-10 years	2 units concealed above ceiling in corridor. 3rd unit in mechanical room		
Mechani	cal Plumbing								
	Hydronic Supply and Return - Steel	Entire Building	1,200	LF	6	10+ years			
	Chilled Water Pump - Less than 10	Mechanical Room	2	EA	5	6-10 years	Packing needs to be replaced		
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	6-10 years	Motor being replaced on 1 of the pumps at the time of assessment.		
Tempera	ature Control								
	DDC System	Entire Building	32,830	SF	5	6-10 years	Software upgrade needed.		
	Electric Thermostat	Entire Building	3	EA	6	10+ years	Serve the unit heaters.		
	Thermostats - DDC	Entire Building	29	EA	6	10+ years	20 Fan powered boxes and 9 VAV boxes.		
Ventilation	on								
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	Concealed above ceiling. Condition based on age and conversation with Building Engineer.		
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years			
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years			

Campus Name: Linne Page : 28 of 41 Assessment Date: 07/31/2019



Catego	ry : Mechanical		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	3	0-1 year	Fan is missing. Roof curb and electrical connections remain.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	5	6-10 years	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Cold Water Risers	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Hot Water Return Lines	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	32,830	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	32,830	SF	6	10+ years	
	Sanitary Piping	Entire Building	32,830	SF	6	10+ years	
	Storm Piping	Entire Building	32,830	SF	6	10+ years	
	Vent Piping	Entire Building	32,830	SF	6	10+ years	
Catego	ry : Room		В	uildina	: Additi	on 2	
32.1290	· y · · · · · · · · · · · · · · · · · · ·		_			Recommend	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	trative Suites/Offices		,,				
	Ceiling - Lay-in	126 Main Office + Clinic	328	SF	7	10+ years	
	Doors - Side-lite	126 Main Office + Clinic	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	126 Main Office + Clinic	1	EA	6	10+ years	
	Floor - Carpet	126 Main Office + Clinic	328	SF	6	10+ years	
	Lighting - Lay-in	126 Main Office + Clinic	5	EΑ	7	10+ years	
	Power Distribution	126 Main Office + Clinic	16	EΑ	7	10+ years	
	Walls - Concrete Block	126 Main Office + Clinic	300	SF	7	10+ years	
	Walls - Masonry	126 Main Office + Clinic	275	SF	7	10+ years	
	Walls - Plaster/Drywall	126 Main Office + Clinic	228	SF	7	10+ years	
	Ceiling - Lay-in	127 Inner Office (Teacher's Lounge)	382	SF	7	10+ years	
	Doors - Wood Doors inclu hw	127 Inner Office (Teacher's Lounge)	2	EA	7	10+ years	
	Floor - Carpet	127 Inner Office (Teacher's Lounge)	382	SF	6	10+ years	
	Lighting - Lay-in	127 Inner Office (Teacher's Lounge)	6	EA	7	10+ years	

Campus Name: Linne Page : 29 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		Building : Addition 2					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	127 Inner Office (Teacher's Lounge)	16	EA	7	10+ years		
	Storage/ Closet	127 Inner Office (Teacher's Lounge)	38	SF	5	10+ years		
	Walls - Concrete Block	127 Inner Office (Teacher's Lounge)	93	SF	7	10+ years		
	Walls - Plaster/Drywall	127 Inner Office (Teacher's Lounge)	500	SF	7	10+ years		
	Work SInk	127 Inner Office (Teacher's Lounge)	1	EA	5	6-10 years		
	Ceiling - Lay-in	2nd Floor Office (Teacher's Lounge)	124	SF	7	10+ years		
	Doors - Side-lite	2nd Floor Office (Teacher's Lounge)	14	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Office (Teacher's Lounge)	1	EA	7	10+ years		
	Floor - Carpet	2nd Floor Office (Teacher's Lounge)	124	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor Office (Teacher's Lounge)	2	EA	7	10+ years		
	Power Distribution	2nd Floor Office (Teacher's Lounge)	6	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor Office (Teacher's Lounge)	346	SF	6	10+ years		
	Ceiling - Exposed	S-2 Lunchroom Office (formerly	122	SF	7	10+ years		
	3	storage)				,		
	Doors - Wood Doors inclu hw	S-2 Lunchroom Office (formerly	2	EA	7	10+ years		
		storage)				, , , , ,		
	Floor - Tile	S-2 Lunchroom Office (formerly	122	SF	7	10+ years		
		storage)		_		, , , , ,		
	Lighting - Pendent/Surface	S-2 Lunchroom Office (formerly	2	EA	7	10+ years		
	gg	storage)	_		•	, , , , , , , , , , , , , , , , , , , ,		
	Power Distribution	S-2 Lunchroom Office (formerly	2	EA	7	10+ years		
	. 6.16. 2.66	storage)	_		•	. o . y ca. c		
	Walls - Concrete Block	S-2 Lunchroom Office (formerly	550	SF	7	10+ years		
	Traile Control Diock	storage)	000	O.	•	ioi youlo		
	Ceiling - Exposed	S-4 Gym Office/Storage	392	SF	7	10+ years		
	Doors - Steel Doors incl hw	S-4 Gym Office/Storage	1	EA	6	10+ years		
	Floor - Tile	S-4 Gym Office/Storage	392	SF	6	10+ years		
	Lighting - Pendent/Surface	S-4 Gym Office/Storage	6	EA	7	10+ years		
	Power Distribution	S-4 Gym Office/Storage	2	EΑ	7	10+ years		
	Walls - Concrete Block	S-4 Gym Office/Storage	1,120	SF	7	10+ years		
	Walls Condicte Block	0 + Gym Gmoc/Glorage	1,120	O.	,	101 years		
Gymnas	io							
_Оуппаѕ	Bleacher Seating	2nd Floor	42	EA	6	10+ years		
	Ceiling - Exposed	2nd Floor	2,900	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2,900	EA	6	10+ years		
		2nd Floor	-	SF	7			
	Floor - Sport Flooring Lighting - Pendent/Surface	2nd Floor	2,900	SF EA	6	10+ years		
	Scoreboards		20			10+ years		
		2nd Floor	1	EΑ	5	10+ years		
	Sound System	2nd Floor	1	EΑ	7	10+ years		
	Stage Lighting System	2nd Floor	1	EA	5	10+ years		
	Walls - Concrete Block	2nd Floor	4,800	SF	6	10+ years		
12:0-1								
Kitchen	Coiling Louin	1et Floor	055			10		
	Ceiling - Lay-in	1st Floor	955	SF	6	10+ years		

Campus Name: Linne Page : 30 of 41 Assessment Date: 07/31/2019



Room em - Type pors - Steel Doors incl hw pors - Wood Doors inclu hw por - Concrete Epoxy/ Painted por - Tile ghting - Lay-in erving Line alls - Concrete Block	Location 1st Floor	Quantity 1 4 835 120 14 17 1,450	UOM EA EA SF SF EA LF SF	Rank 6 6 5 6 6 7	Recommend Replacement 10+ years 10+ years 6-10 years 10+ years 10+ years	Comments
pors - Steel Doors incl hw pors - Wood Doors inclu hw poor - Concrete Epoxy/ Painted poor - Tile ghting - Lay-in erving Line alls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 4 835 120 14 17	EA EA SF SF EA LF	6 6 5 6	10+ years 10+ years 6-10 years 10+ years	Comments
pors - Wood Doors inclu hw poor - Concrete Epoxy/ Painted poor - Tile ghting - Lay-in erving Line alls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	4 835 120 14 17	EA SF SF EA LF	6 5 6 6	10+ years 6-10 years 10+ years	
oor - Concrete Epoxy/ Painted oor - Tile ghting - Lay-in erving Line alls - Concrete Block	1st Floor 1st Floor 1st Floor 1st Floor	835 120 14 17	SF SF EA LF	5 6 6	6-10 years 10+ years	
oor - Tile ghting - Lay-in erving Line alls - Concrete Block	1st Floor 1st Floor 1st Floor	120 14 17	SF EA LF	6 6	10+ years	
oor - Tile ghting - Lay-in erving Line alls - Concrete Block	1st Floor 1st Floor	14 17	EA LF	6	10+ years	
erving Line alls - Concrete Block	1st Floor	17	EA LF	_		
erving Line alls - Concrete Block	1st Floor	17	LF	_		
alls - Concrete Block					10+ years	
asework			SF	6	10+ years	
asework						
	228	50	LF	7	10+ years	
asework	228	12	LF	7	10+ years	
asework	228	60	LF	7		
					10+ years	
eiling - Lay-in						
				_		
				_	•	
				_	•	
					•	
		700			10+ years	
		180	SF	7	10+ years	
alls - Plaster/Drywall	228	250	SF	7	10+ years	
tipurpose Room						
	1st Floor	2.700	SF	6	10+ vears	
oors - Wood Doors inclu hw						
				_	-	
		· · · · · · · · · · · · · · · · · · ·				
alls - Concrete Block	1st Floor	1,330	SF	6	10+ years	
oors - Steel Doors incl hw	2nd Floor	2	FΔ	7	10± vears	
ther Cooling Unit	2nd Floor	1	EA	7	10+ years	
Service Rooms						
	1st Floor	3/	SF	5	10± veare	
					•	
					•	
· ·					•	
					•	
orage Room	2nd Floor	146	SF	5	10+ years	
	pelling - Lay-in pors - Wood Doors inclu hw por - Tile phting - Lay-in alls - Concrete Block pors - Steel Doors incl hw pishes	asework 228 biling - Lay-in 228 bors - Side-lite 228 bors - Wood Doors inclu hw 228 bor - Carpet 228 ghting - Lay-in 228 galls - Concrete Block 228 alls - Masonry 228 alls - Plaster/Drywall 228 tipurpose Room bors - Wood Doors inclu hw 1st Floor bors - Wood Doors inclu hw 1st Floor bors - Wood Doors inclu hw 1st Floor bors - Tile 1st Floor ghting - Lay-in 1st Floor alls - Concrete Block 1st Floor bors - Steel Doors incl hw 2nd Floor borage Rooms 1st Floor borage Room 1st Floor borage Room 1st Floor borage Room 2nd Floor borage Room 2nd Floor borage Room 2nd Floor borage Rooms 2nd Floor borage Rooms 2nd Floor borage Rooms 2nd Floor borage Rooms 2nd Floor	18 18 18 18 18 18 18 18	18	18	18

Campus Name: Linne Page : 31 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		Building : Addition 2					
_			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
estroor								
	Accessories	124/120	44	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	124/120	44	SF	7	10+ years		
	Doors - Wood Doors inclu hw	124/120	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	124/120	44	SF	6	10+ years		
	Floor Drain	124/120	1	EA	7	10+ years		
	Lavatory	124/120	1	EA	7	10+ years		
	Lighting - Lay-in	124/120	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	124/120	192	SF	7	10+ years		
	Water Closet	124/120	1	EA	6	10+ years		
	Accessories	130/128	40	SF	7	10+ years		
	Ceiling - Plaster/Drywall	130/128	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	130/128	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	130/128	40	SF	7	10+ years		
	Floor Drain	130/128	1	EA	7	10+ years		
	Lavatory	130/128	1	EA	7	10+ years		
	Lighting - Lay-in	130/128	1	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	130/128	188	SF	7	10+ years		
	Water Closet	130/128	1	ĒΑ	7	10+ years		
	Accessories	1st Floor	276	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	276	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	276	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	2	EΑ	6	10+ years		
	Lighting - Lay-in	1st Floor	3	EA	7	10+ years		
	Partitions	1st Floor	5	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	100	SF	6	10+ years		
	Walls - Concrete Block Walls - Tile Ceramic/ Porcelain	1st Floor	620	SF	7	10+ years		
	Water Closet	1st Floor	5	EA	7	-		
	Accessories	1st Floor	250	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	250	SF	7	10+ years		
			250	SF SF	7 7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor				10+ years		
	Floor Drain	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	2	EΑ	7	10+ years		
	Lighting - Lay-in	1st Floor	3	EΑ	7	10+ years		
	Partitions	1st Floor	2	EΑ	7	10+ years		
	Urinals	1st Floor	3	EA	7	10+ years		
	Walls - Concrete Block	1st Floor	100	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor	600	SF	7	10+ years		
	Water Closet	1st Floor	2	EA	7	10+ years		
	Accessories	1st Floor Mens	44	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor Mens	44	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Mens	1	EA	7	10+ years		

Campus Name: Linne Page : 32 of 41 Assessment Date: 07/31/2019



Catego	ry : Room		В	uilding	: Additi		V dacramento AVEIVOE, Onicago, le 00010
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st Floor Mens	44	SF	7	10+ years	
	Floor Drain	1st Floor Mens	1	EA	7	10+ years	
	Lavatory	1st Floor Mens	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Mens	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Mens	214	SF	7	10+ years	
	Water Closet	1st Floor Mens	1	EA	7	10+ years	
	Accessories	1st Floor Womens	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Womens	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Womens	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Womens	40	SF	7	10+ years	
	Floor Drain	1st Floor Womens	1	EA	7	10+ years	
	Lavatory	1st Floor Womens	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Womens	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Womens	205	SF	7	10+ years	
	Water Closet	1st Floor Womens	1	ĒΑ	7	10+ years	
	Accessories	2nd Floor	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	250	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	250	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EΑ	7	10+ years	
	Partitions	2nd Floor	2	EΑ	7	10+ years	
	Urinals	2nd Floor	3	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	100	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	600	SF	7	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	
	Accessories	2nd Floor	276	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	276	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	276	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	10+ years	
	Partitions	2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	100	SF	6	10+ years	
	Walls - Concrete Block Walls - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	620	SF	7	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	vvaldi Olusci	2110 1 1001	5	LA	O	TOT YEARS	
Catego	ry : Classroom		В	uildina	: Additi	on 2	
				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #120 (Kindergarten)						
	Casework	1st Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	890	SF	6	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
			· ·		•	_ 0 /00.0	



Catego	ry : Classroom		Building : Addition 2							
	•			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Side-lite	1st Floor	14	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	890	SF	6	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years				
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years				
	Work Sink	1st Floor	2	ĒΑ	5	6-10 years				
Classroo	om #122 (Pre School)									
	Casework	1st Floor	64	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	1,200	SF	6	10+ years				
	Chalk Board	1st Floor	22	LF	4	2-5 years				
	Doors - Side-lite	1st Floor	42	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	1,200	SF	6	10+ years				
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years				
	Walls - Concrete Block	1st Floor	788	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	6	10+ years				
	Work Sink	1st Floor	1	EA	5	6-10 years				
01	"404 (D. O.L. I)					·				
Classroo	om #124 (Pre School)									
	Casework	1st Floor	64	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	1,200	SF	6	10+ years				
	Chalk Board	1st Floor	22	LF	4	2-5 years				
	Doors - Side-lite	1st Floor	42	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	1,200	SF	6	10+ years				
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years				
	Walls - Concrete Block	1st Floor	788	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	6	10+ years				
	Work Sink	1st Floor	2	EA	5	6-10 years				
_Classroo	om #128 (Pre School)									
	Casework	1st Floor	64	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	1,154	SF	6	10+ years				
	Chalk Board	1st Floor	18	LF	4	2-5 years				
	Doors - Side-lite	1st Floor	14	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years				
	Floor - Tile	1st Floor	1,154	SF	6	10+ years				
	Lighting - Lay-in	1st Floor	16	ĒΑ	6	6-10 years				
	Walls - Concrete Block	1st Floor	524	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years				
	Work Sink	1st Floor	2	EA	7	6-10 years				
	-		_		-	,				

Page : 34 of 41 Campus Name: Linne Assessment Date: 07/31/2019



Catego	ry : Classroom		Building : Addition 2						
			• "			Recommend	•		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classroo	m #130 (Pre School)								
	Casework	1st Floor	64	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	1,154	SF	6	10+ years			
	Chalk Board	1st Floor	18	LF	4	2-5 years			
	Doors - Side-lite	1st Floor	14	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	1,154	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	16	EA	6	6-10 years			
	Walls - Concrete Block	1st Floor	790	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years			
	Work Sink	1st Floor	2	EA	7	6-10 years			
_Classroo	m #222 (Regular Classroom)								
	Casework	2nd Floor	60	LF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	814	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	814	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years			
	Walls - Concrete Block	2nd Floor	660	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	232	SF	6	10+ years			
Classroo	m #224 (Regular Classroom)								
	Casework	2nd Floor	60	LF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	872	SF	7	10+ years			
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	872	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years			
	Marker Board	2nd Floor	16	LF	7	10+ years			
	Walls - Concrete Block	2nd Floor	696	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	232	SF	7	10+ years			
Classroo	m #226 (Computer Lab)								
	Ceiling - Lay-in	2nd Floor	920	SF	6	10+ years			
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	2nd Floor	920	SF	6	10+ years			
	Lighting - Lay-in	2nd Floor	16	ĒΑ	6	6-10 years			
	Marker Board	2nd Floor	10	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	710	SF	6	10+ years			
	Walls - Masonry	2nd Floor	174	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
	,					,			

Campus Name: Linne Page : 35 of 41 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	#200 (D I. Ol)						
_Classroo	m #230 (Regular Classroom)	0- d El				40	
	Casework	2nd Floor	55	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	860	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	452	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	474	SF	6	10+ years	
Classroo	m #232 (Regular Classroom)						
	Casework	2nd Floor	55	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	2nd Floor	860	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	6	6-10 years	
	Walls - Concrete Block	2nd Floor	690	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	236	SF	6	10+ years	
•			_		A 1 1141		
Catego	ry : Interior		В	ullaing	: Additi	on 2 Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	.,,,,,					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	Ceiling - Lay-in	1st Floor	2,672	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	7	ĒΑ	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	ΕA	5	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,672	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	24	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years	
		1301 1001	10			•	
		1st Floor	3 600	SF	6	TO+ vears	
	Walls - Concrete Block	1st Floor 1st Floor	3,600 360	SF SF	6 7	10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry	1st Floor	360	SF	7	10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall	1st Floor 1st Floor - 2 Entrance Vestibules	360 150	SF SF	7 7	10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front	1st Floor 1st Floor - 2 Entrance Vestibules 1st Floor - 2 Entrance Vestibules	360 150 4	SF SF EA	7 7 6	10+ years 10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front Floor - Tile Ceramic/ Porcelain	1st Floor 1st Floor - 2 Entrance Vestibules 1st Floor - 2 Entrance Vestibules 1st Floor - 2 Entrance Vestibules	360 150 4 150	SF SF EA SF	7 7 6 6	10+ years 10+ years 10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front Floor - Tile Ceramic/ Porcelain Lighting - Lay-in	1st Floor 1st Floor - 2 Entrance Vestibules	360 150 4 150 2	SF SF EA SF EA	7 7 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front Floor - Tile Ceramic/ Porcelain Lighting - Lay-in Walls - Masonry	1st Floor 1st Floor - 2 Entrance Vestibules	360 150 4 150 2 244	SF SF EA SF EA SF	7 7 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front Floor - Tile Ceramic/ Porcelain Lighting - Lay-in Walls - Masonry Ceiling - Lay-in	1st Floor 1st Floor - 2 Entrance Vestibules 2nd Floor	360 150 4 150 2 244 2,740	SF SF EA SF EA SF SF	7 7 6 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Walls - Concrete Block Walls - Masonry Ceiling - Plaster/Drywall Doors - Store Front Floor - Tile Ceramic/ Porcelain Lighting - Lay-in Walls - Masonry	1st Floor 1st Floor - 2 Entrance Vestibules	360 150 4 150 2 244	SF SF EA SF EA SF	7 7 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	

Campus Name: Linne Page : 36 of 41 Assessment Date: 07/31/2019



Catego	ry : Interior		В	Building : Addition 2					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors include hw	2nd Floor	8	EA	6	10+ years			
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	2,740	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	24	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	3,800	SF	6	10+ years			
	Walls - Masonry	2nd Floor	360	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	245	SF	6	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	10+ years			
	Doors - Wood Doors include hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile/Sheet	3rd Floor	245	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	650	SF	6	10+ years			
	Ceiling - Lay-in	4th Floor	245	SF	5	10+ years			
	Doors - Steel Doors incl hw	4th Floor	4	EA	6	10+ years			
	Doors - Wood Doors include hw	4th Floor	1	EA	6	10+ years			
	Floor - Tile/Sheet	4th Floor	245	SF	7	10+ years			
	Lighting - Lay-in	4th Floor	4	EA	7	10+ years			
	Walls - Concrete Block	4th Floor	674	SF	6	10+ years			
Stairs									
	Ceiling - Plaster/Drywall	East	320	SF	7	10+ years			
	Floor - Tile	East	224	SF	7	10+ years			
	Handrails	East	78	LF	5	10+ years	Minor paint chipping.		
	Lighting - Lay-in	East	3	EA	7	10+ years			
	Stairs - Rubber	East	92	LF	7	10+ years			
	Walls - Masonry	East	1,200	SF	7	10+ years			
	Walls - Plaster/Drywall	East	30	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South	300	SF	7	10+ years			
	Floor - Tile	South	200	SF	7	10+ years			
	Handrails	South	78	LF	5	10+ years			
	Lighting - Lay-in	South	3	EA	7	10+ years			
	Stairs - Rubber	South	92	LF	7	10+ years			
	Walls - Concrete Block	South	1,100	SF	6	10+ years			
	Ceiling - Plaster/Drywall	West	848	SF	7	10+ years			
	Floor - Tile	West	446	SF	6	10+ years			
	Handrails	West	176	LF	7	10+ years			
	Lighting - Lay-in	West	7	EA	7	10+ years			
	Stairs - Rubber	West	288	LF	7	10+ years			
	Walls - Concrete Block	West	3,500	SF	6	10+ years			
_Vertical (Conveyance								
	Elevator - Hydraulic Elevator		1	EA	6	10+ years			
	•				-	,			

Campus Name: Linne Page : 37 of 41 Assessment Date: 07/31/2019



Category : Site	Building : Site

Calego	ry . Oile		٥	unung	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	6-10 years	
	OWII/ Brainage - Oite Marinole	Littile Oile	10	LA	O	0-10 years	
Fencing							
_	Fencing - Chain Link	Entire Site	492	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	672	LF	6	6-10 years	Minor paint chipping throughout.
Landsca	pe						
	Benches	Entire Site	5	EA	7	6-10 years	
	Irrigation	Entire Site	4,020	SF	7	6-10 years	
	Landscape - Grass	Entire Site	4,020	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	6,960	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	2,280	SF	6	6-10 years	
	Parkway trees	Entire Site	9	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	2,870	SF	6	6-10 years	
	Play Area - Asphalt/ Hardscape	Entire Site	9,115	SF	6	6-10 years	
	Trash Receptacles	Entire Site	2	EA	7	6-10 years	
Parking	Lot						
T arking	Surface - Asphalt	Entire Site	5,280	SF	4	0-1 year	Cracking observed and striping to be
	•		,			,	done.
	Surface - Concrete	Entire Site	1,500	SF	7	6-10 years	
	Trash Compactor	Entire Site	1	EA	6	6-10 years	
Playgrou	ınd						
, g	Equipment - Combo 3-12	North East	1	EA	7	6-10 years	
	Surface - Poured Surface	North East	3,200	SF	7	6-10 years	
	Sanass T sarsa Sanass	TTOTAL EGGL	0,200	O.	•	o io youro	
Sidewall							
	Sidewalks - Perimeter Sidewalks	Entire Site	10,316	SF	7	10+ years	
Signage							
	Flag Pole - Flag Pole	West	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	West	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter	West	3	EA	7	10+ years	
	Sign		· ·	_, .	•	,	



Carl von Linne Elementary School

3221 N Sacramento AVENUE, Chicago, IL 60618

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Linne Page : 39 of 41 Assessment Date: 07/31/2019



Classroom Summary

Classroom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		•	•	•		•	•	•	
Art Room	Lunch Room	Basement	104 - Art Room	Lunchroom	1,030	96	48	Y	Y
Art Room	Play Room	Basement	Ceramics Room	Girls Play Room	1,030	96	48	N	N
Music Room	Kindergarten	Basement	105	Classroom	1,017	100	50	N	Υ
Other Instructional Use	Play Room	Basement	Home Ec	Girls Play Rm	1,054	100	50	N	N
Regular Classroom	Art Room	2nd Floor	210	110	1,017	175	88	Y	Υ
Regular Classroom	Kindergarten	2nd Floor	211	111	1,017	175	87	N	Y
Regular Classroom	Kindergarten	2nd Floor	212	112	928	175	87	Y	N
Regular Classroom	Library	3rd Floor	311	Library	1,017	158	79	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	109	1,017	154	77	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	209	1,017	140	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	212	1,017	175	87	N	Υ
Science Classroom	Regular Classroom	3rd Floor	310	210	1,017	140	70	N	Υ
	<u> </u>	•	•				•	•	
Building : Addition 2									
Computer Lab	Computer Lab	2nd Floor	226	207	920	144	20	N	Υ
Kindergarten	Kindergarten	1st Floor	120	108	890	115	13	N	Υ
Pre School	Pre School	1st Floor	122	104	1,200	140	18	N	Υ
Pre School	Pre School	1st Floor	124	106	1,200	140	18	N	Υ
Pre School	Pre School	1st Floor	128	122	1,154	140	18	N	N
Pre School	Pre School	1st Floor	130	124	1,154	140	21	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	205	814	72	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	224	206	872	72	10	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	230	216	860	108	15	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	232	217	860	108	15	N	Υ
Building : Addition 1						•	T	T	
Computer Lab	Regular Classroom	3rd Floor	306	206	838	136	68	Y	Υ
Counseling Room	Regular Classroom	Basement	103 (on lock)	B2	640	60	15	N	N
Regular Classroom	Multi Purpose Room	2nd Floor	202	102	1,017	245	122	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	101	1,017	175	88	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	103	1,017	152	76	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	104	1,017	140	70	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	108	700	68	34	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	301	201	1,017	140	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	203	1,017	140	70	N	Υ



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	304	204	1,017	140	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	208	700	70	35	N	Y
Regular Classroom	Regular Classroom	Basement	102	Classroom	816	140	36	N	N
Science Classroom	Regular Classroom	3rd Floor	302	202	1,017	240	120	N	Υ

Campus Name: Linne Page : 41 of 41 Assessment Date: 07/31/2019