Project Type: Exterior/Masonry Renovation Priorities Department: Facilities Status: Construction Unit Number: 24771

Budget Amount: \$2,500,000 Budget Year: 2013 Estimated Project Start: July 2012 Estimated Project Complete: December 2013

Existing modified bitumen roof is in poor condition and needs to be replacement. Water infiltration exists which is damaging the interior finishes. There are open joints throughout the masonry and spalling limestone.

| Financial Details | | | |
|-------------------|-----------------|----------------------|---------------|
| Project Phase | Original Budget | Current Estimate: | \$2,500,000 |
| Design: | \$155,418 | Expenditure to Date: | \$92,368 |
| Construction: | \$2,168,381 | • | |
| Environmental: | \$35,256 | Percent Complete: | 4% |
| Management: | \$140,945 | Funding Source: | CPS Resources |
| Project Total: | \$2,500,000 | Operating Impact: | \$0 |



Details

Ideal Program Enrollment: 390 2011/2012 Enrollment: 652 Space Utilization Index / Status: 67% (overcrowded) Performance Level: Level 1 Building Age: 70 Years Network: O'Hare ES

Scope

Provide new modified roof system including new roof hatches, flashing, terminations, gravel stops etc per CPS standards. Provide masonry repairs at select first floor window heads. Provide masonry repairs at select locations from second floor window head to parapet. Rebuild parapets and replace steel lintels where section loss is greater than 25%. Remove and reset limestone copings - provide new thru wall flashing. Provide repairs to limestone band above window and entry. Provide masonry repairs to chimney. Replace lexan windows. Provide all required site landscaping to comply with Chicago Landscape Ordinance.



