Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Phillip D Armour Elementary School 22061 2070 School: **Oracle Unit: Building ID:** 950 W. 33rd Place Address: Region: Mail Room: Asbestos Surveyor: James, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/9/2019 Email Address: A copy of the2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Other Each child's backpack Notice printed in school's calendar Material Description HA No Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES SF 0 X NO Plaster 10000 Throughout Building Surface Yes None 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

2	9" x 9" Green Floor Tile			Room 305		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:					 							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					1							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
3	9" x 9" Gray Floor Tile			Room 305		Miscellaneous		None			YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

2016 - Fall:	No Change										
Comments:											
2017 - Fall:											
Comments:											
2017 - Sprir	ng: No Change										
Comments:					_						
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

4

5

Comments:

Comments:

Comments:

Comments:

Material Description

9" x 9" Tan Floor Tile

12" x 12" Tan with Beige

Streaks Floor Tile

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material

Quantity

1800

250

Material

Units

SF

SF

Room 004B

Material Location

First Floor Corridor Areas

Page 3

Change in Assessment Category

X NO

X NO

YES

YES

		Quantity	Units		Туре	Category		Type	Quantity	Units		
6	9" x 9" Gray Floor Tile Mastic	100	SF	Room 305		Miscellaneous	No	None	0		YES	X NO
2016 - F	all: No Change											
Commer	nts:											
2017 - F	all: No Change											
Commer	nts:											

Material

Friable

Damage

Damage

Asbestos

2017 - Spring: No Change Comments:

Material

Material Location

2018 - Fall: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Tan Floor Tile with Beige Streaks Mastic	300	SF	Room 002		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

2016 - Fall:	No Change										
Comments:											
2017 - Fall:											
Comments:											
2017 - Sprir	ng: No Change										
Comments:					_						
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

8

9

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

9" x 9" Green Floor Tile

Drywall

Material

Quantity

2000

500

Material

Units

SF

SF

Room 305

Material Location

Throughout Building

Change in Assessment Category

X NO

X NO

YES

YES

10	9" x 9" Tan Floor Tile Mastic	1800	SF	First Floor Corridor Areas		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change]							
Commer												
2017 - Fa	all: No Change											
Commer	nts:											
2017 - S	pring: No Change											
Commer	nts:											
2018 - Fa	all: No Change											
Commer	nts:											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	Burlap Material			Room 304 Behind Blackboard by Entrance, Room 206 Wardrobe by		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Blackboard, Room 105

Wardrobe

Change in Assessment Category

Damage

Units

											1	
12	Exhaust Caulk Material			Throughout Building		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					<u> </u>							
2017 - Fall:	No Change											
Comments:												
	ıg: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	Drywall Joint Compound	500	SF	Boy's Bathroom by 202 West Wall, Teacher's Lounge by 204 South		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Wall, Principal's Office

14	Wall and Floor Joiner Compound			Boy's Bathroom by 202, Girl's Bathroom by 201		Miscellaneous					YES	X NO
2016 - Fa	ıll: No Change											
Commen												
2017 - Fa	ıll: No Change											
Commen												
2017 - Sp	oring: No Change											
Commen												
2018 - Fa	III: No Change											
Commen	ts:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Black Vinyl Baseboard	300	LF	Women's Teachers Lounge Across From		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

201, Men's Teachers Lounge Across From 205

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Black Vinyl Baseboard Adhesive	300	LF	Women's Teachers Lounge Across From 201, Men's Teacher's Lounge Across From 205		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	lo Chango										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12"Light Yellow Mix w/Beige & Brown Specs FT			Teacher's Lounge Across From Room 205		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

18	12"x12"Lt Yellow Mix w/Beige/Brown Specs FT Mastic			Teacher's Lounge Across From Room 205		Miscellaneous					YES	X NO
2016 - Fall: I	No Change]						•	
Comments:	10 Onango											
2017 - Fall: I	No Change				-							
Comments:	- to onango											
2017 - Sprin	g: No Change				_							
Comments:												
2018 - Fall: I	No Change				-							
Comments:	<u> </u>											
					j							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	9"x9' Light Brown w/Beige & Dark Brown Streaks FT			Room 101		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

20	9"x9" Lt. Brown w/Beige/Dark Brown Streaks Mastic			Room 101		Miscellaneous		None			YES	X NO
		•	·	•	7							
2016 - Fall:	No Change											
Comments:												
					1							
2017 - Fall:	No Change				1							
Comments:	•				1							
2017 - Spri	ng: No Change											
Comments:	:				1							
2018 - Fall:	No Change											
Comments:	•				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

Room 101

HA No

21

Material Description

9"x9" Dark Brown w/Beige

& Cream Streaks

9"x9" Lt. Brown

Change in Assessment Category

X NO

YES

22		9"x9" Dark Brown w/Beige & Cream Streaks FT Mastic			Room 101		Miscellaneous		None			YES	X NO
2010	6 - Fall: N	o Change				7							
	nments:	5 5 1 a											
201	7 - Fall· N	o Change				1							
	nments:	o onango											
201	7 - Spring	: No Change											
	nments:												
2018	8 - Fall: N	o Change				1							
	nments:												
1 AH	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
23		Beige Linoleum Circle			Room 101		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

Patch

24	Beige Linoleum Circle Patch Mastic			Room 101		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	10 Change				-							
2017 - Fall: N	No Change											
Comments:												
					4							
	g: No Change											
Comments:					_							
2018 - Fall: N	No Change				1							
Comments:												
		1	T	T	T	T = -		T =	T _	Т _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25	12" x 12" Light Pink and Gray Floor Tile			Principal's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

Material

Quantity

Material

Units

26	12" x 12" Light Pink & Gray Floor Tile Mastic			Principal's Office, Engineer's washroom		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	·											
2017 - Spri	ng: No Change											
Comments	:											
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
27	9"x9"Dark Chocolate Brown w/Beige & Red Streaks FT			Main office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Material Description

12" x 12" Light Pink & Gray

Material

Quantity

Material

Units

28	9"x"9 Dk. Choc. Brown w/Beige & Red Streaks Mastic			Main office		Miscellaneous		None			YES	X NO
204C Fall	· No Change											
	: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	::											
2017 - Spr	ing: No Change											
Comments	::											
2018 - Fall	: No Change											
Comments	::											
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Type

None

Damage

Quantity

Damage

Units

HA No

29

Material Description

9"x"9 Dk. Choc. Brown

9" x 9" Black w/Beige & Red Streaks Floor Tile

Material

Units

Material

Quantity

Material Location

Public Office Areas, main

office

YES

X NO

30	9"x9"Black Floor Tile w/Beige & Red Streaks Mastic	Public Office Areas; main office		Miscellaneous		None			YES	X NO
2016 - Fa	ıll: No Change	•	1	•	•	•	•	•		
Commen			1							
COMMITTEE			†							
2017 - Fa	ıll: No Change									
Commen										
	oring: No Change									
Commen	ts:									
2018 - Fa	ıll: No Change		_							
Commen										
]							
	1		1	1			1 -			

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
31	Interior Brick	100000	SF	Fan Area #1, Engine Room Across From Engineer's Office, Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

9"x9"Black Floor Tile

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
32	Interior Brick Mortar	100000	SF	Fan Area #1, Engine Room Across From Engineer's Office, Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
0047 5 11	N. Observe											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Brown Vinyl Baseboard	100	LF	Corridor to Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
34	Brown Vinyl Baseboard Adhesive	100	LF	Corridor to Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change]							
Commen	ts:				1							
2017 - Fa	III: No Change											
Commen	ts:		•									

Material

Friable

Damage

Damage

Asbestos

2017 - Spring: No Change

Material Material Location

Comments:

Material Description

2018 - Fall: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Boiler Door's Interior Insulation	12	SF	Boiler Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

2016 - Fall:	No Change										
Comments:											
2017 - Fall:											
Comments:											
2017 - Sprir	ng: No Change										
Comments:					_						
2018 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

36

37

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Incinerator Lining Insulation

Incinerator Brick

Material

Quantity

50

Material

Units

SF

SF

Material Location

Boiler Room

Boiler Room

Change in Assessment Category

X NO

X NO

YES

YES

38	9" x 9" Green Floor Tile w/Beige Streaks			Bathroom of Engine Room		Miscellaneous					YES	X NO
2016 - Fa	II: No Change				\neg							
Comment												
2017 - Fa	II: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	is:											
2018 - Fa	II: No Change											
Comment	ts:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
39	9" x 9" Green Floor Tile			Bathroom of Engine		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material Quantity Material Location

Room

HA No

Material Description

w/Beige Streaks Mastic

40	Beaver Board			Dentist's Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	.											
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	g: No Change]							
Comments:					1							
2018 - Fall: N	lo Change											
Comments:					_							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	12" x 12" Beige Floor Tile w/Chocolate Streaks			Dentist's Office		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

42	w/Chocolate Streaks Mastic			Dentist's Office		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
43	9" x 9" Dark Green Floor Tile w/Beige Streaks			Lunch Storage Room		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

12"x12"Beige Floor Tile

Material

Quantity

Material

Units

Material Location

44	9"x9" Dark Green Floor Tile w/Beige Streaks Mastic			Lunch Storage Room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	10 Onango											
2017 - Fall: N	No Change				-							
Comments:	go											
2017 - Spring	g: No Change				+							
Comments:												
2018 - Fall: N	No Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
45	12" x 12" Beige Floor Tile	500	SF	Lunchroom Areas		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

46	12" x 12" Beige Floor Tile			Lunchroom Areas		Miscellaneous					YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
2018 - Fall	: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
47	9" x 9" Light Green Floor			Lunchroom Areas		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

Comments:

Material Description

48	Tile Mastic			Lunchroom Areas		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Spring	j: No Change											
Comments:					-							
2018 - Fall: N	lo Change											
Comments:					_							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
49	9" x 9" Dark Chocolate w/Beige Streaks			Lunchroom Storage Areas		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

9" x 9" Light Green Floor

Material

Quantity

Material

Units

Material Location

50	9" x 9" Dark Chocolate w/Beige Streaks Mastic -			Lunchroom Storage Areas		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:					_							
2018 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
51	Exterior Window Caulk - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

52	Interior Window Glazing			Rooms 305, 104 and 203		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	V											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
53	Exterior Window Glazing Compound - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Units

Material

Quantity

Material Location

54	Exterior Brick - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	•]							
2018 - Fall: N	lo Change				-							
Comments:	Ţ.											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Asses	sment Category
	Fotorios Driels Marten Non	Quantity	UTIILS		Туре	Category		Туре	Quantity	UTIKS		
55	Exterior Brick Mortar - Non AHERA			Exterior of Building		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Comments:

Comments:

Comments:

Comments:

Material Description

Material

Units

Material

Quantity

Material Location

56	Black Border Tile	90	SF	Public Office Space by Room 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Chango]							
	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					1							
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					<u>-</u> '							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
	•	Quantity	Units		Туре	Category		Туре	Quantity	Units	Ŭ	0 ,
			1	I			1	* * *		1		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

90

HA No

57

Material Description

Black Border Tile Mastic

Material

Quantity

Material

Units

SF

Material Location

Public Office Space by

Public Office Space by

Room 102 and Main

Change in Assessment Category

YES

YES

X NO

58	Fire Door Insulation	400	SF	Throughout the Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
2018 - Fall: I	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
59	Roofing Material - Non- AHERA			Roof		Miscellaneous					YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
60	12" x 12" Brown Floor Tile w/Brown Specks	50	SF	Lunchroom Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	S:											
2017 - Fall	l: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
2018 - Fall	l: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12" x 12" Brown Floor Tile w/Brown Specks Mastic	50	SF	Lunchroom Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
62	Chalk Board/Poster Board Adhesive	150	SF	Rooms 101-105, 201-206 & 301-306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12" x 12" Dk. Beige w/Brown Floor Tile	124	SF	Office (Room 104)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 32

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12" x 12" Dk. Beige w/Brown Floor Tile Mastic	124	SF	Office (Room 104)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	12" x 12" Black w/White Floor Tile	462	SF	Room 002 Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	12" x 12" Black w/White Floor Tile Mastic	462	SF	Room 002 Teacher's Lounge		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12" x 12" Lt. Beige Floor Tile	108	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12" x 12" Lt. Beige Floor Tile Mastic	108	SF	Engineer's Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
0047 0 : N 01	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Blue Ceramic Tile Wall Grout	100	SF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HAN	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70		Blue Ceramic Tile Wall Adhesive	100	SF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES X NO
2016	6 - Fall: N	o Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Gray Ceramic Tile Floor Grout	120	SF	2nd Floor Boy's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Page 36

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	/
72	White Ceramic Wall Tile Grout	100	SF	2nd Floor Unisex Washroom		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
73	Pink Ceramic Wall Tile Adhesive	100	SF	2nd Floor Unisex Washroom		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	Brown Brick Ceramic Floor tile Grout	40	SF	2nd Floor Unisex Washroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change Comments:											
					1						

Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
75	Ceramic Floor Tile Grout	100	SF	2nd Floor Unisex Washroom		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

76	Pink Baseboard Grout	20	LF	2nd Floor Unisex Washroom	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:	-									
2017 - Fall: N	lo Change									
Comments:	<u> </u>									
2017 - Spring	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	<u> </u>									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Pink Baseboard Adhesive	20	LF	2nd Floor Unisex Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
78	Yellow Ceramic Tile Wall Grout	350	SF	2nd Floor Girls Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change	
9	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	Yellow Ceramic Wall Tile Adhesive	350	SF	2nd Floor Girls Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

80	Grout	1134	SF	Girl's Washrooms		Miscellaneous	NO	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:]							
2017 - Fall: N	o Change											
Comments:]							
2017 - Spring	: No Change											
Comments:					-							
2018 - Fall: N	o Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

80

81

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

White Ceramic Floor Tile

12" x 12" light blue floor tile with dark blue and white

Material

Quantity

1134

Material

Units

SF

Material Location

Basement Boy's and

101

Change in Assessment Category

X NO

X NO

YES

82	Mastic associated with 12" x 12" light blue floor tile with dark blue and white	ı		101		Miscellaneous		None			YES	X NO
2016 Falls N	No Changa		<u> </u>		¬							
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:	-											
			•	_								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units	1	Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

83	with dark brown and white streaks	Second floor unisex washroom
	·	
2016 - Fa	all: No Change	
Commer	nts:	
2017 - Fa	all: No Change	
Commer	nts:	
2017 - S	pring: No Change	
Commer	nts:	
2018 - Fa	all: No Change	
Commer	nts:	

Material

Quantity

Material

Units

Material Location

Second floor unisex

HA No

Material Description

Mastic associated with 12"

12" x 12" Brown floor tile

YES

X NO

84	and white streaks			washroom		Miscellaneous					L_YES	<u>X</u> NO
2016 - Fall:	No Change				\exists							
Comments:												
2017 - Fall:	No Change				_							
Comments:	Ţ											
2017 - Sprir	ng: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Damage

Туре

Damage

Quantity

0

None

Damage

Units

85	4" black basecove	40	LF	washroom						
	•			·						
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	j: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:	Comments:									
		•	•	_						

40

Material

Units

LF

Material

Quantity

Material Location

Second floor unisex

Second floor unisex

HA No

84

85

Material Description

Mastic for 12" x 12" brown

floor tile with dark brown

4" black basecove

Change in Assessment Category

X NO

X NO

YES

86	4" black basecove adhesive	40	LF	second floor unisex washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												
2017 - Fall	l: No Change											
Comments	s:											
	ing: No Change											
Comments	3:				1							
2018 - Fall	: No Change				Ī							
Comments	S:				-							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•	•	

Quantity

2250

Units

305,306

SF

Material

Units

Material Quantity Material Location

HA No

87

Material Description

Adhesive of multi colored

blue carpet

88	Green carpet adhesive	750	SF	306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	U											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

18000

Material

Quantity

Material

Units

SF

Material Location

Basement Halls and

Supply Rooms,

HA No

89

Material Description

12"x12" Blue Mottled Vinyl

Floor Tile

Change in Assessment Category

X NO

90	12"x12" Blue Mottled Vinyl Floor Tile Mastic	18000	SF	Basement Halls and Supply Rooms, Lunchrooms,		Miscellaneous	No	None	0		YES	X NO
0040 5-11	N. Olasas				_							
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2018 - Fall: I	No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

		Offices
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2018 - Fall: No Change		
Comments:		
		•

6010

Material

Quantity

Material

Units

SF

Material Location

Basement Halls and

Ground Elevator and

Vestibules, Rooms and

HA No

91

Material Description

4" Brown Vinyl Baseboard

Change in Assessment Category

X NO

92	4" Brown Vinyl Baseboard Adhesive	6010	SF	Ground Elevator and Vestibules, Rooms and Offices		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			·]			·			
Comments:											
2017 - Fall: N	lo Change]						
Comments:					-						
2017 - Spring	g: No Change				-						
Comments:											
2018 - Fall: N	lo Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
93	12"x12" Tan Streaked Floor Tile	25	SF	Bathroom in Tank Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	Comments:											
2017 - Fall: No Change					1							
Comments:	Comments:											

2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Ground Elevator and

94	12"x12" Tan Streaked Floor Tile Mastic	25	SF	Bathroom in Tank Room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: No Change											
Comments:	<u> </u>										
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	12"x12" Grey Mottled Floor Tile	60	SF	Ground Floor Elevator Lobby		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

96	12"x12" Grey Mottled Floor Tile Mastic	60	SF	Ground Floor Elevator Lobby		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change				1						
Comments:	io onange										
					1						
2017 - Fall: N	lo Change										
Comments:											
0017 0	N. O.				1						
2017 - Spring	g: No Change										
Comments:											
2018 - Fall: N	lo Change				-						
Comments:	- - -				1						
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Ground Floor Elevator

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12"x12" Light Green Mottled VFT	1700	SF	1st-3rd Floor Elevator Foyer, Office 101A,101B, 107,108, 201B		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

12"x12" Grey Mottled Floor

Material

Quantity

Material

Units

98	12"x12" Light Green Mottled VFT Mastic	1700	SF	1st-3rd Floor Elevator Foyer, Office 101A,101B, 107,108, 201B		Miscellaneous	No	None	0		YES X	NO
0040 5-1	II N. Olassa				1							
2016 - Fa	II: No Change											
Comment	S:											
2017 - Fal	II: No Change				-							
Comment	<u> </u>				1							
2017 - Sp	ring: No Change				-							
Comment												
2018 - Fal	II: No Change				1							
Comment												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment	Category

Type

Type

Material

Category

Category

Surface

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

99	Off-white Spray-on Fireproofing	75	SF	Elevator Room 004									
2016 - Fall: No Change													
Comments:													
2017 - Fall: No Change													
Comments:													
2017 - Spring	: No Change												
Comments:													
2018 - Fall: N	o Change												
Comments:													

Quantity

Units

Material

Units

Material

Quantity

Material Location

1st-3rd Floor Elevator

HA No

Material Description

Α	Boiler Insulation			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	Comments:											
2018 - Fall: N	lo Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
В	Boiler Breeching Insulation			Boiler Room		TSI					YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
С	Aircell Pipe Insulation	353	LF	Lunchroom Areas, Engine Room Areas, Pump Room Areas, Basement Fan Room Areas		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Fall: No Change												

2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	

Comments:

]						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessme
		Quantity	Units		Type	Category		Type	Quantity	Units	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Joint Compound of Aircell Pipe Insulation	52	LF	Lunchroom Areas, Engine Room Areas, Pump Room Areas, Basement Fan Room Areas		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Page 52

E	Joint Compound off Fiberglass Pipe Insulation			Basement		Miscellaneous					YES	X NO
2016 - Fall:	: No Change				7							
Comments												
2017 - Spri	ng: No Change											
Comments	:				_							
	: No Change											
Comments	:				_							
	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
_				Boiler Room, Pump Room, Janitor's Office							YES	X NO

TSI

Asbestos

Type

Material

Category

Friable

Yes

Loc

5

Damage

Type

Damage

Quantity

856

LF

HA No

F

Material Description

Cardboard Pipe Insulation

Material

Quantity

Material

Units

Material Location

Areas, Pipe Chases, Common Basement

Areas

Change in Assessment Category

Damage

Units

G	Joint Compound off (Cardboard) Pipe Insulation	20	LF	Boiler Room, Pump Room, Janitor's Office Areas		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change]						
Comments:	_										
2017 - Fall: N	o Change										
Comments:					1						
2017 - Spring	: No Change										
Comments:					-						
2018 - Fall: No Change											
Comments:											
]						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	Mag Pipe Insulation	100	LF	Mechanical Room Areas		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Joint Compound of Mag Pipe Insulation			Mechanical Rooms		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22061

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Phillip D Armour Elementary School
Date: 9/3/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.