Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Alice L Barnard Computer Math & Science Ctr ES 22131 2150 School: **Oracle Unit:** Building ID: Address: 10354 S. Charles Region: 06 Mail Room: Asbestos Surveyor: Dunne, Michael X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12x12 Brown w/ Tan Floor YES 01 X NO Miscellaneous Tile (Removed 2010) 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 Caria	ay No Changa										
	ng: No Change				_						
Comments:											
2018 - Fall:	No Change										
	Ţ				_						
Comments:					_						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

350

Material

Quantity

Material

Units

SF

Material Location

Basement, Teacher's

Lounge, 004

203

HA No

01A

01B

Material Description

9x9 Green Floor Tile

ABATED

9x9 Red & Black Floor Tile-

Change in Assessment Category

X NO

X NO

YES

2016 - Fall: N	lo Change				7						
Comments:											
2017 - Spring	g: No Change				_						
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2018 - Fall: No Change					_						
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

Damage

Quantity

0

None

Damage

Units

HA No

01C

01D

Comments:

Comments:

Comments:

Comments:

Material Description

9x9 Dark & Light Green Floor Tile- ABATED

9x9 Dark Brown& Red

Floor Tile

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material

Quantity

Material

Units

SF

140

Material Location

Stair Landing Outside

Change in Assessment Category

X NO

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
01E	12x12 Dark Blue & Light Blue Floor Tile	704	SF	Main office, 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments	:											
2017 - Spri	ing: Damaged											
Comments:cracked tiles												
2017 - Fall: No Change					=							
Comments	:											
2018 - Fall	2018 - Fall: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12x12 Tan Floor Tile	2675	SF	Basement Corridor, Pre- Kindergarten Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 4

											1
0046 Falls N	Na Obasana										
2016 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change				+						
	g. No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ll .	11	CAUAMIIIV	T URBIS	1	I IVDE		1	1 1 V DE	L CALLADIIIV	T CHIHIS	1

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

None

Damage

Quantity

0

0

671

HA No

02A

02B

Material Description

12x12 Off White Floor Tile

12x12 Red & Brown/Cream Floor Tile (Marble Pattern)

Material

Units

SF

SF

Room 400

Material

Quantity

800

Material Location

Basement Room 002

Page 5

Change in Assessment Category

YES

YES

X NO

X NO

Damage

Units

02C	12x12 Light Brown & Cream Floor Tile	700	SF	Room 108	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	-									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2018 - Fall: N	o Change									

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02D	12x12 Red & Black Floor Tile	2378	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
02E	9"x9" Red and Black Floor Tile	350	SF	Asst. Principals Office, 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:	•											
2017 - Spring: No Change												
Comments:												

2017 - Fall: No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	Tile Mastic (Not Observed)	4907	SF	1st and 2nd fl. corridors, and lunch rm office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

lo Chongo				\neg						
io Change										
g: No Change										
lo Change										
lo Change										
				<u>—</u>						
Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	Quantity	Units		Type	Category		Туре	Quantity	Units	
Ovo Croon Floor Tilo Mostio	250	oe.	Teacher's Lounge-		Missellaneous	No	None			Dyso I Vivo
`	No Change So Change No Change No Change Material Description	g: No Change No Change Material Description Material Quantity	g: No Change No Change No Change Material Description Material Quantity Units	g: No Change No Change No Change Material Description Material Material Location Units Tacabara Laures	g: No Change No Change No Change Material Description Material Quantity Units Material Location Asbestos Type	g: No Change No Change No Change Material Description Material Quantity Units Material Location Asbestos Type Category Taceber's Laures	g: No Change No Change No Change Material Description Material Quantity Units Material Location Asbestos Type Category Friable Category	g: No Change No Change No Change Material Description Material Material Location Asbestos Type Category Type Taggherial Jungs	g: No Change No Change No Change Material Description Material Material Material Location Asbestos Type Category Type Quantity Tagglerial purgs	g: No Change No Change No Change No Change No Change No Change Tope Category Material Damage Type Quantity Units Tope Category Tope Category Tope Quantity Tope Quantity

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

350

SF

HA No

06A

06B

Material Description

Mastic- ABATED

9x9 Red & Black Floor Tile

9x9 Green Floor Tile Mastic

Material

Quantity

Material

Units

Material Location

Room 203

Basement

Change in Assessment Category

X NO

X NO

YES

06C	9x9 Dark & Light Green Floor Tile Mastic- ABATED			Main Office							YES	X NO
2016 - Fall: I	No Change				1							
Comments:	into onango											
2017 - Sprin	g: No Change											
Comments:	g											
2017 - Fall: I	No Change				1							
Comments:												
2018 - Fall: I	No Change											
Comments:	<u> </u>											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

				1
2016 - Fall: N	lo Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2017 - Spring	: No Change	<u>-</u>	<u>.</u>	
Comments:				
				·
2018 - Fall: N	lo Change			
Comments:				

140

Material

Quantity

Material

Units

SF

Material Location

Stair Landing Outside

HA No

06D

Material Description

9x9 Dark Brown & Red

Floor Tile Mastic

Change in Assessment Category

X NO

		Quantity	Units		Type	Category		Type	Quantity	Units		
06E	12x12 Dark Blue & Light Blue Floor Tile Mastic	704	SF	Main Office, 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					-							
2017 - Sprin	g: Damaged				1							
Comments:												

Material

Friable

Damage

Damage

Asbestos

Comments:cracked tile

2017 - Fall: No Change
Comments:

Material

Material Material Location

2018 - Fall: No Change

Material Description

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12x12 Tan Floor Tile Mastic	2756	SF	Basement Corridor, Pre- Kindergarten		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

07A	12x12 Off White Floor Tile Mastic	800	SF	Basement Rm. 002		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	. to onango				-							
2017 - Sprin	g: No Change]							
Comments:	g. No Onlange											
2017 - Fall:	No Change											
Comments:	J											
2018 - Fall:	No Change				-							
Comments:	•											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Туре

None

0

Damage

Quantity

Damage

Units

07.5	Pattern)	07.1	O1	TROOM TOO
2016 - Fall: No	o Change			
Comments:				
2017 - Spring:	: No Change			
Comments:				
2017 - Fall: No	o Change			
Comments:				
2018 - Fall: No	o Change			
Comments:	·			·

671

SF

Room 400

Material

Quantity

Material

Units

Material Location

HA No

07B

Material Description

12x12 Red & Brown/Cream

Floor Tile Mastic (Marble

YES

X NO

07C	12"x12" Light Brown & Cream Floor (Mastic)	700	SF	Room 108	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:	<u> </u>									
2017 - Sprin	ng: No Change									
2017 - Fall: Comments:	•									
2018 - Fall: Comments:	No Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07D	12x12 Red & Black Floor Tile Mastic	2376	SF	Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
07E	9x9 Red and Black Floor Tile Mastic	350	SF	Asst. Principals Office, 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Light Green Carpet Mastic (Not Observed)	0	SF	Room 208		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
09	Carpet Mastic (NOT OBSERVED)	800	SF	Room 302		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	II: No Change											
Comments	S:											
2017 - Fall	II: No Change											
Comments	s:				_							
2017 - Spr	ring: Abated											
Comments	s:removed											
2018 - Fall	II: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12x12 Brown Floor Tile	100	SF	3rd Floor Warming Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

HA No	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asse	essment Category
10A	12x12 Brown, Beige, Tan floor tile Mastic	300	SF	3rd Floor Warming Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10B	12x12 Beige Floor Tile	100	SF	3rd Floor Warming Kitchen		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

10C	12x12 Tan Floor Tile	100	SF	3rd Floor Warming Kitchen		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change										
Comments	:				1						
2017 - Spr	ing: No Change										
Comments	: -				-						
	: No Change				1						
Comments) <u>.</u>				-						
2018 - Fall	: No Change]						
Comments).										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Blue Carpet Mastic	936	SF	Room 204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:	1										
2017 - Spri	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:											
					<u> </u>						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
	·	Quantity	Units		Type	Category		Type	Quantity	Units	

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

HA No

12

13

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Green Carpet Mastic

9"X9" Brown Floor Tile

Material

Quantity

108

200

Material

Units

SF

SF

Material Location

Principal's Office

Engineer's Office

Change in Assessment Category

X NO

X NO

YES

	masus										
2016 - Fall:	No Change				7						
Comments:	<u> </u>]						
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change				-						
Comments:											
2018 - Fall:	No Change				-						
Comments:											
					J						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change	 <u>.</u>	
Comments:			
2017 - Spring	: No Change	 <u>.</u>	
Comments:			
2018 - Fall: N	o Change		
Comments:			

Quantity

200

Units

SF

Material

Units

SF

Material

Quantity

200

Material Location

Engineer's Office

Engineer's Office

HA No

14

15

Material Description

9"X9" Brown Floor Tile

9"X9" Tan Floor Tile

Mastic

Change in Assessment Category

X NO

X NO

YES

0040 Falls	No Observe				_						
2016 - Fall:											
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprir	ng: No Change										
Comments:											
2018 - Fall:	No Change										
Comments:	-										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

350

HA No

16

17

Comments:

2016 - Fall: No Change

Material Description

9"X9" Tan Floor Tile Mastic

12"X12" Green Floor Tile

Material

Units

SF

SF

Material Quantity

200

Material Location

Engineer's Office

Basement Room 001

Change in Assessment Category

YES

YES

X NO

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
18	12"X12" Green Floor Tile Mastic	350	SF	Basement Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments	S:											
2017 - Fall	l: No Change											
Comments	3:				_							
2017 - Spr	ring: No Change											
Comments	3:				_							
2018 - Fall	l: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Terrazo Flooring - Gray and White Speckled	1138	SF	South Stairwell		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

20	Plaster	42500	SF	Throughout Walls and Ceilings		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	J											
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change				-							
Comments:	.											
2018 - Fall: N	o Change				1							
Comments:	•											
					J							
HA No	Material Description	Material Quantity	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

Damage

Quantity

0

Damage

Units

2092

Material

Quantity

Material

Units

SF

Material Location

Throughout Walls and

North Stairwell

HA No

21

Material Description

Terrazzo Flooring - Green

with White and Black

Change in Assessment Category

X NO

22	Green with Dark Green specles	460	SF	Elevator Hall		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change		<u> </u>	<u> </u>]						
Comments:	<u> </u>				1						
2017 - Fall: N	lo Change										
Comments:											
	g: No Change										
Comments:					1						
2018 - Fall: N	lo Change										
Comments:					-						
					J						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
23	Terrazo Flooring - Light Grey with Pearl Specles	200	SF	Elevator Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											

Comments: 2017 - Spring: No Change Comments:

HA No

Material Description

Terrazzo Flooring - Light

Material

Units

Material Quantity Material Location

2018 - Fall: No Change Comments:

24	Terrazo Flooring - Mint Green with White Speckles	600	SF	North Corridor Border	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Fall: N	No Change									
Comments:	<u> </u>									
2017 - Spring	g: No Change									
Comments:	J									
2018 - Fall: N	No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Vibration Gasket (Tan)	4	LF	Attic		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 23

26	Vibration Gasket (Red)	4	LF	Attic	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
2017 - Fall: N	lo Change									
2017 - Spring Comments:	g: No Change									
2018 - Fall: I	lo Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 18" Black Border Tile	350	SF	Engineer's Office, Gym Stairs, and Auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

28	12"x 18" Black Border Tile Mastic	350	SF	Engineer's Office, Auditorium, and Gym Stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			•]							
Comments:	io chango											
0047 5.11 1	I. Ol											
2017 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					1							
,					•							
LIA NI-	Marketal Basedaria	NA-r-d-1	Marta dal	NA-restallander	A -11	Markadal	Estable.	D	D	D	Ol ' - A	

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	2' x 2' White Ceiling Tile	200	SF	West Entrance		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

30	12x12 Maroon VFT (ABATED)			1st and 2nd floor corridor, Lunchroom office 211, outside room 400 landing		Miscellaneous					YES	X NO
204C Falls	No Change				1							
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	-											
		·										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

Damage

Туре

Damage

Quantity

Damage

Units

31	12x12 Maroon VFT Mastic (ABATED)	Lunchroom office 211, outside room 400 landing
	-	
2016 - Fal	II: No Change	
Comment	s:	
2017 - Fal	II: No Change	
Comment	s:	
2017 - Sp	ring: No Change	
Comment	s:	
2018 - Fal	II: No Change	
Comment	s:	

Material

Units

Material

Quantity

Material Location

1st and 2nd floor corridor,

HA No

Material Description

12x12 Maroon VFT Mastic

YES

X NO

32	12x12 Tan Floor Tile VFT	5000	SF	1st and 2nd floor cooridors, lunchroom office (211), Landing outside Room 400	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	: No Change									
Comments	<u> </u>									
2017 - Fall:	: No Change									
Comments	·									
2017 - Spri	ng: No Change									
Comments										
2018 - Fall:	: No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12x12 Tan Floor Tile VFT (Mastic)	5000	SF	1st and 2nd floor cooridors, Lunchroom office (211), Landing outside of Rm 400		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Comments:

Material Description

Material

Quantity

Material

Units

34	1x1 ceiling tile white with wormhole and ceiling tile	500	SF	Room 204, Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	J											
2017 - Fall: N	o Change				<u> </u>							
Comments:												
2017 - Spring	: No Change				-							
Comments:	<u> </u>											
2018 - Fall: N	o Change				-							
Comments:	Ü											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

Yes

Miscellaneous

None

0

Damage

Туре

Damage

Quantity

Damage

Units

35	wormhole and ceiling tile (Mastic Glue Pucks)	500	SF	Room 204, Library
2016 - Fall: N	No Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				

HA No

Material Description

1x1 Ceiling tile white with

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12x12 cream with Gray specs VFT	1500	SF	Room 208		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37	12x12 Cream with Gray specs VFT(Mastic)	1500	SF	Room 208		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
38	12x12 Creamy Brown Specs VFT	250	SF	IB office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12x12 creamy brown specs VFT(Mastic)	250	SF	IB office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	·
<u> </u>	

В	MJP E/F/V on Fiberglass	350	LF	Mechanical Areas, Boiler Rooms	TSI	Yes	Loc	10	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2018 - Fall: N	o Change									
Comments:										

Type

Asbestos

Type

Material

Category

Material

TSI

Category

Friable

Friable

Yes

Damage

Damage

Туре

None

Туре

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

Material Location

Material Location

С	Aircell Pipe Insulation	450	LF	Attic		
2016 - Fall: No Change						
Comments:						
2017 - Fall: No Change						
Comments:						
2017 - Spring: No Change						
Comments:						
2018 - Fall: No Change						
Comments:						

Material

Quantity

Material

Quantity

Material

Material

Units

Units

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Aircell Pipe Insulation	25	LF	Attic		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Alice L Barnard Computer Math & Science Ctr ES				
Date:1/11/2019				
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.				
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.				
CHECK ONE				
A copy of this notice was sent home in each child's backpack.				
A copy of this notice was printed in the school's newsletter and sent home with each child				
A copy of this notice was printed in the school's calendar and sent home with each child				
Other.				
A COPY OF THIS NOTICE MUST BE PLACED IN THE				

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.