Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

22141

Oracle Unit:

2828 N. Kilbourn Ave. Address: Region: 02 Mail Room: Asbestos Surveyor: Cooke, Kevin X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/27/2018 Email Address: kcooke1@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12"x12" Beige w/ Red & 1st and 2nd Floor YES 2A SF X NO 8000 Miscellaneous No None 0 Brown Spots Floor Tile Corridor - 1927 Building 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2018 - Spring : No Change Comments:

John Barry Elementary School

School:

2160

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
2B	12"x12" Beige w/ Red & Brown Spots Floor Tile Mastic	8000	SF	1st and 2nd Floor Corridor - 1927 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2C	12"x12" Orange Floor Tile	350	SF	Room 103 - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2D	12"x12" Orange Floor Tile Mastic	350	SF	Room 103 - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2E	12"x12" White w/ Tan Spots VFT	200	SF	Room 113 Gym Office - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:	2F	12"x12" White w/ Tan Spots VFT Mastic	200	SF	Room 113 Gym Office - 1927 Building		Miscellaneous	No	None	0	YES	X NO
Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change	2016 - Fall: N	lo Change]						
2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change		io Change				-						
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:											
Comments: 2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change												
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring	յ։ No Change										
2017 - Fall: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:											
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change												
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: N	lo Change]						
2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:											
Comments: 2018 - Fall: No Change												
2018 - Fall: No Change	2018 - Spring	g : No Change]						
2018 - Fall: No Change	Comments:											
Comments:	2018 - Fall: N	lo Change]						
	Comments:]						
]						

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2G	12"x12" White w/ Gray Streaks Floor Tile	2000	SF	Engineers Office & Toilet, Room 100, 101, 105 (Lunchroom), 111 - 1927 Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2H	12"x12" White w/ Gray Streaks Floor Tile Mastic	2000	SF	Engineers Office & Toilet, Room 100, 101, 105 (Lunchroom), 111 - 1927 Building		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 Light Blue w/ streaks VFT	1000	SF	Rms 113, 102, and Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 5

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
2J	12x12 Light Blue w/ Streaks VFT Mastic	1000	SF	Rms 113, 102, and Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												

Material

Friable

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Hardcoat Plaster			Throughout - 1927 Building		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

2018 - Spring : No Change

Comments:

Material

Material Location

Damage Change in Assessment Category

40	Textured Plaster			Auditorium, Auditorium Vestibule, Auditorium Stage - 1927 Building		Miscellaneous	No				YES	X NO
2016 - Fall: N	No Change			•	7							
Comments:	10 Ondrige											
2017 Caria	a. No Chongo											
Comments:	g: No Change											
Comments.												
2017 - Fall: N	No Change											
Comments:												
2018 - Spring	g : No Change				-							
Comments:												
2018 - Fall: N	No Change				+							
Comments:	· ·											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

None

0

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

		- Carantiny	0	
95-1	12"x12" Gray w/ Black Specks Floor Tile	Room # 1 through # 10, Office, Corridor, Boys & Girls Toilets, Men & Womens Toilets - 1995 Annex		
2016 - Fall: N	lo Change			
Comments:	io enange			
Comments.				
2017 - Fall: N	lo Change			
Comments:	<u> </u>			
2017 - Spring	j: No Change			
Comments:	-			
2018 - Spring	ı : No Change			
Comments:				
2018 - Fall: N	lo Change			
Comments:				

HA No

Material Description

Material

Quantity

Material

Units

Material Location

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95-2	12"x12" Gray w/ Black Specks Floor Tile Mastic	2500	SF	Room # 1 through # 10, Office, Corridor, Boys & Girls Toilets, Men & Womens Toilets - 1995 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
95-3	2'x4' White w/ Grooves Ceiling Tile	2500	SF	Room # 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, Office, Corridor-1995 Annex		Miscellaneous	No	None	0		YES	X NO
		•	•	•	1	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2018 - S	pring : No Change
Commer	nts:

Material Description

2018 - Fall: No Change

Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95-4	Gray Vinyl Baseboard	2500	SF	Throughout 1995 Annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
95-5	Gray Vinyl Baseboard Mastic			Throughout 1995 Annex		Miscellaneous	No				YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				-							
Comments:	,											
2017 - Fall: N	lo Change											
Comments:					1							
2018 - Spring	g : No Change											
Comments:					1							
2018 - Fall: N	lo Change											
Comments:	•				1							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95-6	Drywall			Throughout 1995 Annex		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 10

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
95-7	Drywall Compound			Throughout 1995 Annex		Miscellaneous	No				YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	V											
2018 - Spring	g : No Change				-							
Comments:	, , , , , , , , , , , , , , , , , , ,											
2018 - Fall: N	lo Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ВВ	Mag Block Pipe Insulation	360	LF	1st Floor Girl's Washrooms (hidden by steel enclosure); Boiler Room; Engine Room - 1927 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

С	Boiler Gaskets	4	LF	Boiler # 1 and # 2, Boiler Room - 1927 Building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Sprine	g: No Change											
Comments:	, ,											
2017 - Fall: N	No Change											
Comments:	J											
2018 - Spring	g : No Change				1							
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Asses	sment Category
		Quantity	Units	Throughout (Hidden by	Туре	Category		Туре	Quantity	Units		
CC	Aircell Pipe Insulation	4500	LF	drop-ceiling) - 1927 Building		TSI	Yes	None	0		YES	X NO

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	Cardboard Pipe Insulation	1500	LF	Tunnel Connecting to Boiler Room, North and South Basement Storage Rooms - 1927 Building		TSI	Yes	Dist	90		YES X NO
2016 - Fall: N	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Boiler Packing	450	SF	Boiler Room - 1927 Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	MJP E/F/V on Mag Block Pipe Insulation (Jacket of both boilers)	450	SF	Boiler Room, Engine Room (Jacket of both boilers) - 1927 Building		TSI	Yes	Dist	62		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Boiler Packing, Pipe Insulation	10	LF	Boiler Room - 1927 Building		TSI	Yes	Dist	5		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FF	Air Cell Duct Insulation NOT OBSERVED			Unfinished Crawl Spaces - 1927 Building NOT OBSERVED		TSI					YES	X NO
2016 - Fall: N Comments:	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GG	Repaired Plaster	4	SF	North Side Air Tunnel - 1927 Building		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
НН	MJP E/F/V on Aircell Pipe Insulation (Hidden by drop- ceiling)	310	LF	Throughout (See Hatching Maps) - 1927 Building (Hidden by drop-ceiling)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2040 Fall No Olassa
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
II	MJP E/F/V on Cardboard Pipe Insulation	85	LF	Tunnel Connecting to Boiler Room, North and South Basement Storage Rooms - 1927 Building		TSI	Yes	Loc	8		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

IK	12"x12" Light Blue VFT	200	SF	Main Office - 1927 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	.											
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall:	No Change				=							
Comments:												
2018 - Sprin	ıg : No Change											
Comments:												
2018 - Fall: No Change												
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
IL	12"x12" Light Blue VFT	200	SF	Main Office - 1927 Building		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
JJ	Interior Window Caulk			Interior Windows- 1927 Building		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change]							
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2018 - Fall: N	o Change											
Comments:												
2018 - Spring	: No Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
KK	Exterior Window Caulk			Exterior Windows- 1927 Building		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	12" x 12" Blue VFT	200	SF	Office 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Oracle Unit: 22141

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John Barry Elementary School
Date: 9/11/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 22141

SCHOOL'S ASBESTOS MANAGEMENT PLAN.